The University of Alabama

| UNIT NO: | 241366 2 | 015 TOYO | TA HIG | HLANDEI | २ | | WORK ORDE | R NO: | 20470 | |
|--------------------|---------------------|--------------|------------|----------|--------------|-------------------|----------------|----------------|-------------------|------------|
| USING DEPT NO: | 208185 | (| OPENED | DATE: | 06/04/201 | 15 07:31:16 | LOCATION: GA | ARAGE - Unive | ersity Automotive | Services |
| WO STATUS: | CLOSED | (| COMPLET | ED DATE: | 06/04/201 | 5 14:59:45 | METER 1 - M: 2 | 21 | METER 2 - N: | 0 |
| WO VISIT REASON: | SCHEDULED | (| CLOSED | DATE: | 06/04/201 | 15 14:59:46 | IN-SERVICE DAT | TE: 06/02 | 2/2015 | |
| TECH SPEC NO: | 15TOYHIGHLAND | 2015 To | oyota High | lander | | | UNIT SERIAL NO |): 5TD2 | KRFH6FS08358 | 6 |
| JOB CODE | JOB DESCRIPTION | 1 | STAT R | SN WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | COMMERCIAL | TOTAL COST |
| PS-00-001 PREP SE | ERVICE NEW UNIT IN | I-SERVICE | DON | C N | GARAGE | 0.50 | \$28.75 \$ | 60.00 | \$0.00 | \$28.75 |
| JOB COUNT: 1 | | | | WORK OR | DER TOTAL: | 0.50 | 28.75 | 0.00 | 0.00 | 28.75 |
| Job Code | Job Descriptio | <u>n</u> | | Employee | <u>e No.</u> | <u>Start</u> | Finis | <u>h</u> | Quantity | Total Cost |
| PS-00-001 PREP SER | ICE NEW UNIT IN-SER | VICE INSPECT | TION 1133 | 8644 | 06/ | /04/2015 07:31:56 | 06/04/2015 08: | 01:56 | 0.50 | \$28.75 |
| | | | | | | | | | LABOR | |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 20470 |
|--------------------|----------|------------------------|----------------|-------|
| Work Order Note | <u>s</u> | | | |
| (LPATE) DO PDI | | | | |
| Job Notes | | | | |
| PS-00-001 - PREP S | | IN-SERVICE INSPECTION | | |
| (LPATE) PDI COMPL | ETED | | | |
| | | | | |
| | | | | |

The University of Alabama

| UNIT NO: | | 241366 2 | 015 TOYOTA H | IGHLANDER | R | | WORK ORDE | ER NO: | 22169 | |
|---|---------------|--|----------------------|---|-------------------|--|-------------------------------------|--------------------------|---|--------------------------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | COMPI | ED DATE: LETED DATE: ED DATE: łighlander | 12/10/201 | 5 10:10:30 5 08:08:35 5 08:08:36 | | 2226 TE: 06/02 | ersity Automotive S METER 2 - N: //2015 KRFH6FS083586 | 0 |
| JOB CODE 66-PM-PMA | | JOB DESCRIPTION | <u>N</u> STAT DON | <u>RSN</u> <u>WRTY</u> P N | JOB LOC GARAGE | LABOR HRS 0.31 | LABOR \$17.83 | MATERIAL \$40.03 | COMMERCIAL \$0.00 | TOTAL COST \$57.86 |
| JOB COUN | IT: 1 | | | WORK OR | DER TOTAL: | 0.31 | 17.83 | 40.03 | 0.00 | 57.86 |
| Job Code 66-PM-PMA | PERFORM | Job Description | _ | Employee 0260422 | | <u>Start</u> 09/2015 06:00:00 | <mark>Finis</mark> 12/09/2015 06 | | Quantity 0.31 | <u>Total Cost</u> \$17.83 |
| Job Code 66-PM-PMA | PERFORM | Job Description | _ | <u>Part No</u> 04152-YZZA1 | | Des TER-OIL | cription | <u>Unit Pri</u> | LABOR ice Quantity 3.19 1 | 17.83 <u>Total Cost</u> \$6.19 |
| 66-PM-PMA | | OIL CHANGE | |)W20S | | | YNTHETIC OIL QT | | 5.64 6 PARTS | \$33.84 40.03 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 22169 |
|---------------------|--------------|------------------------|----------------|-------|
| Work Order Notes | | | | |
| (LISAPATE) PM | | | | |
| Job Notes | | | | |
| 66-PM-PMA - PERFORM | I OIL CHANGE | | | |
| (LISAPATE) PM BY GM | | | | |

The University of Alabama

| UNIT NO: | | 241366 2 | 2015 TOYOTA H | IGHLANDER | | | | DER NO: | 23428 | |
|---|---------------|--|---------------|---|--------------------------|--|--|----------------------------|--|--------------------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | COMP | ED DATE: LETED DATE: ED DATE: Highlander | 05/23/201 | 6 11:18:55 6 09:17:36 6 09:17:37 | LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL | 3659 DATE: 06/0 | versity Automotive METER 2 - N: 12/2015 ZKRFH6FS08358 | 0 |
| JOB CODE 66-PM-PMA | _ | JOB DESCRIPTION | N STAT DON | <u>RSN</u> <u>WRTY</u> P N | <u>JOB LOC</u> GARAGE | LABOR HRS 0.65 | LABOR \$37.25 | MATERIAL \$40.77 | COMMERCIAL \$0.00 | TOTAL COST \$78.02 |
| JOB COUN | IT: 1 | | | WORK ORI | DER TOTAL: | 0.65 | 37.2 | 5 40.7 | 7 0.00 | 78.02 |
| Job Code 66-PM-PMA | PERFORM | Job Descriptio DIL CHANGE | | <u>Employee</u> 1074414 | | <u>Start</u> 18/2016 14:22:17 | | hish 15:01:09 | Quantity 0.65 LABOR | Total Cost \$37.25 37.25 |
| Job Code | | Job Descriptio | <u>n</u> | Part No | <u>.</u> | Des | cription | <u>Unit P</u> | rice Quantity | Total Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | C | 04152-YZZA1 | FIL | TER-OIL | | | 6.93 1 | \$6.93 |
| 66-PM-PMA | PERFORM | OIL CHANGE | C | W20S | HA | VOLINE OW20 S | YNTHETIC OIL Q | Т | 5.64 6 PARTS | \$33.84 40.77 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 23428 | |
|----------|--------|------------------------|----------------|-------|--|
| | | | | | |

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/CS-USED 1/2QT OF OL ALREADY CHARGED OUT

The University of Alabama

| UNIT NO: | | 241366 2 | 015 TOYO | | GHLA | NDER | | | WORK OF | RDER NO | D : | 25830 | |
|---|--------------------------|----------------------|-----------------------|-------------|------------|---------|---|--|--------------|--------------|------------|-----------------|--------------|
| USING DEPT NO:208185WO STATUS:CLOSEDWO VISIT REASON:SCHEDULEDTECH SPEC NO:15TOYHIGHLAND20 | | | COMPLETED DATE: 03/02 | | | | 17 09:43:31 17 14:22:10 17 14:22:12 | LOCATION: GARAGE METER 1 - M: 5504 IN-SERVICE DATE: UNIT SERIAL NO: | | | 0 | | |
| JOB CODE | <u>I</u> | JOB DESCRIPTION | <u>l</u> | <u>STAT</u> | <u>RSN</u> | WRTY | JOB LOC | LABOR HRS | LABOR | MAT | ERIAL | COMMERCIAL | TOTAL COST |
| 03-51-038 | REPLAC | E NEW WIPER BLAD | ES | DON | Р | Ν | GARAGE | 0.09 | \$5.35 | \$38.36 | | \$0.00 | \$43.71 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.48 | \$27.60 | \$46.52 | | \$0.00 | \$74.12 |
| 66-PM-PMC | PERFOR | M CABIN FILTER RE | PLACEMEI | DON | Ρ | Ν | GARAGE | 0.67 | \$38.64 | \$7.33 | | \$0.00 | \$45.97 |
| JOB COUN | T: 3 | | | | wo | RK ORI | DER TOTAL | : 1.25 | 71. | 59 | 92.21 | 0.00 | 163.80 |
| Job Code | | Job Description | <u>n</u> | | <u>Em</u> | ployee | <u>No.</u> | <u>Start</u> | Ē | <u>inish</u> | | <u>Quantity</u> | Total Cost |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1170580 | | 02 | 2/23/2017 11:09:38 | 02/24/201 | 7 13:38:40 | | 26.48 | \$1,522.82 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1170580 | | 02 | 2/23/2017 11:09:38 | 02/24/201 | 7 13:38:40 | | (26.48) | (\$1,522.82) |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLACI | EMENT | 1 | 1170580 | | 02 | 2/24/2017 14:10:49 | 02/24/201 | 7 14:51:08 | | 0.67 | \$38.64 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1170580 | | 02 | 2/23/2017 11:09:38 | 02/23/201 | 7 11:38:26 | | 0.48 | \$27.60 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1 | 1074414 | | 02 | 2/23/2017 06:48:41 | 02/23/201 | 7 06:54:16 | | 0.09 | \$5.35 |
| | | | | | | | | | | | | LABOR | 71.59 |
| Job Code | | Job Description | <u>n</u> | | | Part No | • | Des | cription | | Unit Pric | e Quantity | Total Cost |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1 | 61 | | W | IPERS 16" | | | 12. | 78 1 | \$12.78 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | V | /W-2600 | -PC | W | IPER BLADE 26" | | | 12. | 79 1 | \$12.79 |
| 03-51-038 | REPLACE NEW WIPER BLADES | | V | /W-2000 | -PC | W | IPER BLADE 20" | | | 12. | 79 1 | \$12.79 | |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLACI | EMENT | 8 | 00012C | | С | ABIN AIR FILTER F | REPL 4483 | | 7. | 33 1 | \$7.33 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0 | 4152-YZ | ZA1 | F | LTER-OIL | | | 6. | 93 1 | \$6.93 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0 | W20S | | Н | AVOLINE OW20 S | YNTHETIC OIL | QT | 5. | 66 7 | \$39.59 |
| | | | | | | | PARTS | 92.21 | | | | | |

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 25830 |
|-------------------|------------------|--------------------------------|----------------|-------|
| Work Order Note | <u>es</u> | | | |
| (LISAPATE) PM-REI | PLACE ALL WIPERS | - RESET TIRE LIGHT-CHECK SPARE | | |
| Job Notes | | | | |
| 03-51-038 - REPLA | CE NEW WIPER BL | ADES | | |
| (LISAPATE) REPLA | CED ALL 3 WIPERS | | | |

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) PM BY AB COOLANT CHECKED GOOD TO -37

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

The University of Alabama

| UNIT NO: | | 241366 | 2015 TOYO | | IGHLA | NDER | | | WORK ORDER NO: | | | 27883 | | |
|---|-----------|--|-----------------|----------------|---------|---|-------------------------|---|----------------|-------------|------------|-----------------|----------|------------|
| USING DEPT NO:208185WO STATUS:CLOSEDWO VISIT REASON:SCHEDULEDTECH SPEC NO:15TOYHIGHLAND2015 | | COMPL CLOSE | COMPLETED DATE: | | | 17 08:53:56 17 07:51:44 17 07:51:46 | METER 1 - IN-SERVICI | LOCATION:GARAGE - University Automotive SetMETER 1 - M:7244METER 2 - N:IN-SERVICE DATE:06/02/2015UNIT SERIAL NO:5TDZKRFH6FS083586 | | | 0 | | | |
| JOB CODE | L | JOB DESCRIP | TION | STAT | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MAT | ERIAL (| COMMERCIAL | TOTAL C | OST |
| 66-17-028 | PERFOR | M MOUNT AND I | BALANCE TIRE | DON | 0 | Ν | GARAGE | 0.20 | \$11.50 | \$3.18 | \$ | 0.00 | \$14.68 | |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.22 | \$12.65 | \$39.25 | S | 217.72 | \$269.62 | |
| PU-17 | PURCHA | SED TIRES, TUE | BES, LINERS & | DON | 0 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | S | 60.00 | \$0.00 | |
| JOB COUN | IT: 3 | | | | WO | RK ORI | DER TOTAL | : 0.42 | 2 24 | .15 | 42.43 | 217.72 | 2 | 284.30 |
| Job Code | | Job Descri | ption | | V | endor N | <u>o.</u> | Invoice No. | Purcha | se Order N | <u>lo.</u> | | Total Co | ost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1122732 | | 23 | 34738 | 0040860 | | | | \$ | 6217.72 |
| | | | | | | | | | | | | COMML | 2 | 217.72 |
| Job Code | | Job Descri | ption | | Em | ployee | <u>No.</u> | <u>Start</u> | | Finish | | Quantity | Total Co | <u>ost</u> |
| 66-17-028 | PERFORM I | MOUNT AND BALA | NCE TIRES | 1 | 1213180 | | 10 | 0/23/2017 07:00:0 | 0 10/23/20 | 17 07:12:00 | | 0.20 | | \$11.50 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1074414 | | 1(| 0/19/2017 10:46:4 | 2 10/19/20 | 17 14:59:41 | | (4.22 |) (\$2 | 242.44) |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1074414 | | 10 | 0/19/2017 10:46:4 | 2 10/19/20 | 17 10:59:54 | | 0.22 | : | \$12.65 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1074414 | | 1(| 0/19/2017 10:46:4 | 2 10/19/20 | 17 14:59:41 | | 4.22 | \$ | 5242.44 |
| | | | | | | | | | | | | LABOR | | 24.15 |
| Job Code | | Job Descri | ption | | | Part No | <u>.</u> | De | scription | | Unit Price | <u>Quantity</u> | Total Co | <u>ost</u> |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | W20T | | 01 | N20 SYN OIL THO | DMAS CAM2 QT | - | 4.1 | 7 7 | | \$29.19 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | С | :111 | | R | ED BRAKE CLEA | NER | | 3.1 | 7 1 | | \$3.17 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | 4152-YZ | ZA1 | F | LTER-OIL | | | 6.8 | 9 1 | | \$6.89 |
| 66-17-028 | PERFORM I | MOUNT AND BALA | NCE TIRES | V | VHEEL W | /EIGHT | W | HEEL WEIGHT K | NOCK ON | | 0.3 | 6 1 | | \$0.36 |
| 66-17-028 | PERFORM I | MOUNT AND BALA | NCE TIRES | 6 | 3001 | | 1/ | 4 OZ STICK ON T | APE WEIGHT | | 0.0 | 5 10 | | \$0.45 |
| 66-17-028 | PERFORM I | M MOUNT AND BALANCE TIRES 6-111 TPMS SERVICE | | PMS SERVICE KI | T 6-111 | | 2.3 | 71 | | \$2.37 | | | | |
| | | | | | | | | | | | | PARTS | | 42.43 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 27883 |
|---------------------|-------------------|------------------------|----------------|-------|
| Work Order Note | es | | | |
| (LISAPATE) PM | | | | |
| Job Notes | | | | |
| 66-17-028 - PERFOR | RM MOUNT AND BA | ALANCE TIRES | | |
| (LISAPATE) MOUNT | ED AND BALANCE | D 1 NEW TIRE | | |
| 66-PM-PMA - PERF | ORM OIL CHANGE | | | |
| (LISAPATE) PM BY \$ | SH-FOUND A CUT I | N RR TIRE SIDEWALL | | |
| PU-17 - PURCHASE | D TIRES, TUBES, I | LINERS & VALVES | | |
| (LISAPATE) PURCH | ASED 1 TIRE FROM | I FIRESTONE. PD BY CC | | |

The University of Alabama

| UNIT NO: | | 241366 | 2015 TOYC | TA H | GHL | NDER | 2 | | | WORK OF | |): | 30706 | | |
|---|---------------|---|------------|-------------------------|------------|-------------|------------|--|-----------|---------------------------|---|-----------|------------|--------------|-----------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAN | | OPENE COMPL CLOSE | ETED | DATE: E: | 09/05/201 | 18 14:40:3 18 07:01:0 18 07:01:0 | 1 | METER 1 - N IN-SERVICE | LOCATION: GARAGE - Univ METER 1 - M: 9960 IN-SERVICE DATE: 06/0 UNIT SERIAL NO: 5TD | | | 0 | |
| JOB CODE | <u> </u> | JOB DESCRIPT | ION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR | HRS | LABOR | MATE | RIAL | COMMERCIAL | <u>TOTAL</u> | COST |
| 03-51-038 | REPLAC | E NEW WIPER BL | ADES | DON | 0 | Ν | GARAGE | | 0.25 | \$14.38 | \$34.79 | : | \$0.00 | \$49.17 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | Ν | GARAGE | | 0.13 | \$7.38 | \$46.73 | | \$0.00 | \$54.11 | |
| 66-PM-PMC | PERFOR | RM CABIN FILTER | REPLACEMEI | DON | 0 | Ν | GARAGE | | 0.41 | \$23.77 | \$7.33 | : | \$0.00 | \$31.10 | |
| JOB COUN | IT: 3 | | | | WC | RK ORI | DER TOTAL: | | 0.79 | 45. | 53 | 88.85 | 0.00 |) | 134.38 |
| Job Code | | Job Descrip | tion | | En | nployee | No. | <u>Sta</u> | <u>rt</u> | E | <u>inish</u> | | Quantity | Total | Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | 5 | 08 | /30/2018 14 | 4:18:05 | 08/30/201 | 3 14:18:05 | | 0.00 | | \$0.00 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | i | 08 | /30/2018 14 | 1:30:00 | 08/30/201 | 3 14:45:41 | | 0.26 | | \$15.03 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | i | 08 | /30/2018 14 | 1:30:00 | 08/30/201 | 3 14:45:41 | | (0.26 |) | (\$15.03) |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | ; | 08 | /30/2018 14 | 4:30:00 | 08/30/201 | 3 14:45:41 | | 0.26 | | \$15.03 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | ; | 08 | /30/2018 14 | 4:30:00 | 08/30/201 | 3 14:45:41 | | (0.26 |) | (\$15.03) |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | ; | 08 | /30/2018 14 | 4:18:05 | 08/30/201 | 3 14:18:05 | | 0.00 | | \$0.00 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1758845 | i | 08 | /30/2018 11 | :45:01 | 08/30/201 | 3 11:52:43 | | 0.13 | | \$7.38 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | 8 | 1 | 1758845 | ; | 08 | /30/2018 11 | :44:45 | 08/30/201 | 3 11:59:45 | | 0.25 | | \$14.38 |
| 66-PM-PMC | PERFORM | CABIN FILTER REPL | ACEMENT | 1 | 1758845 | 5 | 08 | /30/2018 11 | :19:57 | 08/30/201 | 3 11:44:45 | | 0.41 | | \$23.77 |
| | | | | | | | | | | | | | LABOR | | 45.53 |
| Job Code | | Job Descrip | tion | | | Part No | <u>.</u> | | Des | cription | | Unit Pric | e Quantity | Total | Cost |
| 03-51-038 | REPLACE N | | 3 | v | /W-2000 |)-PC | W | IPER BLAD | E 20" | | | 12. | 79 1 | | \$12.79 |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | 6 | v | /W-2600 |)-PC | W | IPER BLAD | E 26" | | | 12. | 79 1 | | \$12.79 |
| 66-PM-PMC | PERFORM | CABIN FILTER REPL | ACEMENT | 8 | 00012C | | CA | ABIN AIR FI | LTER F | REPL 4483 | | 7.3 | 33 1 | | \$7.33 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | W20T | | 0V | V20 SYN OI | IL THO | MAS CAM2 QT | | 5. | 74 7 | | \$40.21 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | 4152-YZ | ZA1 | FII | FILTER-OIL | | | 6. | 52 1 | | \$6.52 | |
| 03-51-038 | REPLACE N | IEW WIPER BLADES | 6 | 6 | 012A | | RE | EAR WIPER | R BLAD | E | | 9.2 | | | \$9.21 |
| | | | | | | | | | | | | | PARTS | | 88.85 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 30706 |
|-------------------|-----------------|------------------------|----------------|-------|
| Work Order Not | es | | | |
| (LISAPATE) PM-RE | PLACE FRONT AND | REAR WIPERS | | |
| Job Notes | | | | |
| 03-51-038 - REPLA | CE NEW WIPER BL | ADES | | |
| | | N | | |

(LISAPATE) REPLACED ALL 3 WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS/SH COOLANT -32' 66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

The University of Alabama

| UNIT NO: | | 241366 | 2015 TOYO | DTA HI | GHLA | NDER | | WORK ORDER NO | | | NO: | 33456 | | |
|---|---------------|--|------------|-------------------------|---------|-------------|------------|--|------|--|-----------------|-------------------|------|------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED UNSCHEDULED 15TOYHIGHLANE | | OPENE COMPL CLOSE | ETED I | DATE: E: | 07/18/20 | 019 13:23:38 019 07:09:55 019 07:09:56 | | LOCATION: GAR, METER 1 - M: 15 ⁻ IN-SERVICE DATE UNIT SERIAL NO: | 156 : 06/02 | METER 2 - N | 0 | rices |
| JOB CODE | L | JOB DESCRIPTI | <u>ON</u> | <u>STAT</u> | RSN | WRTY | JOB LOO | LABOR H | RS | LABOR M | IATERIAL | | | OTAL COST |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0 | .31 | \$22.48 \$47 | .24 | \$0.00 | \$69 | 9.72 |
| 66-PM-PMC | PERFOR | M CABIN FILTER F | REPLACEMEI | DON | 0 | Ν | GARAGE | 0 | .30 | \$21.75 \$7.3 | 33 | \$0.00 | \$29 | 9.08 |
| JOB COUN | IT: 2 | | | | wo | RK ORI | DER TOTAI | _: (| 0.61 | 44.23 | 54.57 | 0. | 00 | 98.80 |
| Job Code | | Job Descript | ion | | Em | ployee | <u>No.</u> | <u>Start</u> | | <u>Finish</u> | | <u>Quantit</u> | Z | Total Cost |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLA | ACEMENT | 1 | 1901357 | | 0 | 7/17/2019 07:1 | 8:36 | 07/17/2019 07:36 | :36 | 0. | 30 | \$21.75 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1901357 | | 0 | 7/17/2019 07:0 | 0:00 | 07/17/2019 07:18 | :36 | 0. | 31 | \$22.48 |
| | | | | | | | | | | | | LABOR | ! | 44.23 |
| Job Code | | Job Descript | ion | | | Part No | <u>.</u> | | Des | cription | <u>Unit Pri</u> | <u>ce Quantit</u> | Z | Total Cost |
| 03-32-002 | REPLACE N | EW BATTERY | | 7 | 40245 | | E | ATTERY TERM | 1 PR | OTECTOR WASHER | 0 | .96 | (2) | (\$1.92) |
| 03-32-002 | REPLACE N | EW BATTERY | | 7 | 40245 | | E | ATTERY TERM | 1 PR | OTECTOR WASHER | C | .96 | 2 | \$1.92 |
| 66-PM-PMC | PERFORM (| ABIN FILTER REPLA | ACEMENT | 8 | 00012C | | C | ABIN AIR FILT | ER R | REPL 4483 | 7 | .33 | 1 | \$7.33 |
| 03-32-002 | REPLACE N | EW BATTERY | | 2 | 4F2 | | E | ATTERY BCI 2 | 4F 5 | 50CCA | 113 | .55 | 1 | \$113.55 |
| 03-32-002 | REPLACE N | EW BATTERY | | 2 | 4F2 | | E | ATTERY BCI 2 | 4F 5 | 50CCA | 113 | .55 | (1) | (\$113.55) |
| 66-PM-PMA | PERFORM (| DIL CHANGE | | 0 | 4152-YZ | ZA1 | F | ILTER-OIL | | | 6 | .50 | 1 | \$6.50 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0 | W20T | | 0 | W20 SYN OIL | ТНОМ | MAS CAM2 QT | 5 | .82 | 7 | \$40.74 |
| | | | | | | | | | | | | PARTS | | 54.57 |

UNIT NO:2413662015 TOYOTA HIGHLANDERWORK ORDER NO:33456

Work Order Notes

(EKIMBREL) PM and rotate tires

Job Notes

03-32-002 - REPLACE NEW BATTERY

09-15 - ALIGN STEERING

31-17-015 - ROTATE TIRE ROTATION

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) AG/AG, coolant -35. Condition of front tires is satisfactory, the better tires are already on the back.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) AG replaced cabin filter 4483.

The University of Alabama

| UNIT NO: | | 241366 20 | 015 ΤΟΥΟΤΑ Η | IGHLA | NDER | | | WORK ORD | ER NO |): 3 | 35958 | | |
|---|---------------|--|--------------|------------|-------------|------------|---|--|----------------------|--------------|--|---------|-----------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | COMPI | D DATI | DATE: E: | 03/24/202 | 20 10:07:06 20 10:39:06 20 13:23:41 | LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL I | 18789 ATE: | N 06/02/2 | ity Automotive S /ETER 2 - N: 015 RFH6FS083586 | 0 | |
| JOB CODE | | JOB DESCRIPTION | | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | RIAL | COMMERCIAL | TOTAL C | COST |
| 14-52-021 | INSTALL | GPS SYSTEM | DON | 0 | Ν | GARAGE | 1.13 | \$82.23 | \$0.00 | 9 | 50.00 | \$82.23 | |
| 66-PM-PMA | PERFOR | M OIL CHANGE | DON | Ρ | Ν | GARAGE | 0.61 | \$44.25 | \$47.95 | \$ | 50.00 | \$92.20 | |
| JOB COUN | IT: 2 | | | wo | | DER TOTAL: | 1.74 | 126.48 | | 47.95 | 0.00 | | 174.43 |
| Job Code | | Job Description | <u>.</u> | <u>Em</u> | nployee | <u>No.</u> | <u>Start</u> | <u>Fin</u> | <u>ish</u> | | <u>Quantity</u> | Total C | :ost |
| 14-52-021 | INSTALL GP | S SYSTEM | 1 | 2052187 | , | 03 | /10/2020 07:44:55 | 03/10/2020 0 | 8:22:58 | | 0.63 | | \$45.98 |
| 14-52-021 | INSTALL GP | S SYSTEM | 1 | 2052187 | , | 03 | /10/2020 07:44:55 | 03/10/2020 0 | 8:14:55 | | 0.50 | | \$36.25 |
| 66-PM-PMA | PERFORM | DIL CHANGE | 1 | 2052187 | 7 | 03 | /10/2020 07:08:18 | 03/10/2020 0 | 7:44:55 | | 0.61 | | \$44.25 |
| | | | | | | | | | | | LABOR | | 126.48 |
| Job Code | | Job Description | <u>l</u> | | Part No | <u>.</u> | Des | cription | | Unit Price | <u>e</u> <u>Quantity</u> | Total C | :ost |
| 66-PM-PMA | PERFORM | DIL CHANGE | C | W20T | | 0V | 0W20 SYN OIL THOMAS CAM2 QT | | | 5.8 | 34 7 | | \$40.85 |
| 66-PM-PMA | PERFORM | DIL CHANGE | C | 4152-YZ | ZA1 | FIL | TER-OIL | | | 6.5 | i0 1 | | \$6.50 |
| 66-PM-PMA | PERFORM | DIL CHANGE | C | 5089 | | BF | AKE CLEAN NON | J-FLAMMABLE 14 | OZ | 6.4 | 4 1 | | \$6.44 |
| 66-PM-PMA | PERFORM | DIL CHANGE | C | W20T | | 00 | 20 SYN OIL THO | MAS CAM2 QT | | 5.8 | 34 (7) | | (\$40.85) |
| 66-PM-PMA | PERFORM | DIL CHANGE | C | W20T | | 00 | 20 SYN OIL THO | MAS CAM2 QT | | 5.8 | | | \$35.01 |
| | | | | | | | | | | | PARTS | | 47.95 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 35958 |
|--------------------|---------------------|------------------------|----------------|-------|
| Work Order Not | es | | | |
| (LISAPATE) PM-Inst | tall 4G GPS system | | | |
| Job Notes | | | | |
| 14-52-021 - INSTAL | L GPS SYSTEM | | | |
| EKIMBREL) JW ins | stalled GPS#5040096 | 600 | | |
| 6-PM-PMA - PERF | ORM OIL CHANGE | | | |
| (EKIMBREL) JW/AG | coolant -25 | | | |

The University of Alabama

| UNIT NO: | | 241366 | 2015 TOYO | DTA H | GHLA | NDEF | 2 | WORK ORDER NO | | | 376 | 617 | | |
|---|---------------|--|-----------|----------------|-----------------------------------|-------------|------------|---|------------------------------|----------------------|--------------|-----------------|--------------|------------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | | COMPL CLOSE | D DATI ETED I D DATE | DATE: E: | 09/18/202 | 20 14:59:27 20 11:38:37 20 15:50:16 | METER 1 - M: IN-SERVICE I | SERVICE DATE: 06/02/ | | TER 2 - N: | 0 | |
| JOB CODE | <u>E</u> | JOB DESCRIPTIO | <u>N</u> | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATERIA | <u>L CO</u> | MMERCIAL | <u>TOTAL</u> | COST |
| 03-51-038 | REPLAC | E NEW WIPER BLAD | DES | DON | 0 | Ν | GARAGE | 0.17 | \$12.43 | \$24.58 | \$0.0 | 0 | \$37.01 | |
| 06-15 | INSPEC | T STEERING | | DON | 0 | Ν | GARAGE | 0.19 | \$13.49 | \$0.00 | \$0.0 | 0 | \$13.49 | |
| 09-15 | ALIGN S | TEERING | | DON | 0 | Ν | GARAGE | 0.68 | \$49.18 | \$0.00 | \$0.0 | 0 | \$49.18 | |
| 24-02-061 | REPAIR | WINDSHIELD | | DON | 0 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$57. | 50 | \$57.50 | |
| 66-17-028 | PERFOR | RM MOUNT AND BAL | ANCE TIRE | DON | 0 | Ν | GARAGE | 0.84 | \$61.22 | \$443.31 | \$0.0 | 0 | \$504.53 | |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | | DON | Р | Ν | GARAGE | 0.27 | \$19.29 | \$59.33 | \$0.0 | 0 | \$78.62 | |
| 66-PM-PMC | PERFOR | RM CABIN FILTER RE | EPLACEMEI | DON | 0 | Ν | GARAGE | 0.09 | \$6.75 | \$7.33 | \$0.0 | 0 | \$14.08 | |
| JOB COUN | JOB COUNT: 7 | | | | wo | RK OR | DER TOTAL: | 2.24 | | | .55 | 57.50 | | 754.41 |
| | | | | | | | | | | | | | | |
| <u>Job Code</u> 24-02-061 | REPAIR WI | Job Descriptio | <u>on</u> | 1 | <u>v</u> 1078716 | endor N | | Invoice No. 392 | Purchase | e Order No. | | | <u>Total</u> | <u>Cost</u> \$57.50 |
| 2102001 | | | | | 1010110 | | | | | | | COMML | · | 57.50 |
| Job Code | | Job Descriptio | on | | Em | ployee | No. | <u>Start</u> | Fi | nish_ | | Quantity | Total | Cost |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLAC | | 1 | 2052187 | | | /16/2020 13:10:43 | | | | 0.09 | | \$6.75 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 2052187 | | 09 | /16/2020 08:28:18 | 09/16/2020 | 08:44:16 | | 0.27 | | \$19.29 |
| 03-51-038 | REPLACE N | NEW WIPER BLADES | | 1 | 2052187 | , | 09 | /16/2020 08:44:30 | 09/16/2020 | 08:54:47 | | 0.17 | | \$12.43 |
| 06-15 | INSPECT S | TEERING | | 1 | 2052187 | | 09 | /16/2020 08:59:16 | 09/16/2020 | 09:10:26 | | 0.19 | | \$13.49 |
| 66-17-028 | PERFORM | MOUNT AND BALANCE | E TIRES | 1 | 2052187 | | 09 | /16/2020 12:19:56 | 09/16/2020 | 13:10:36 | | 0.84 | | \$61.22 |
| 09-15 | ALIGN STEI | ERING | | 1 | 1170580 | | 09 | /16/2020 15:14:49 | 09/16/2020 | 15:55:31 | | 0.68 | | \$49.18 |
| | | | | | | | | | | | · | LABOR | | 162.36 |
| Job Code | | Job Descriptic | <u>on</u> | | | Part No | <u>.</u> | Des | cription | Unit | Price | <u>Quantity</u> | Total | Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | W20T | | 00 | /20 SYN OIL THO | MAS CAM2 QT | | 5.82 | 7 | | \$40.74 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | 4152-YZ | ZA1 | FIL | TER-OIL | | | 6.50 | 1 | | \$6.50 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 4 | 9430 | | All | R FILTER | | | 12.09 | 1 | | \$12.09 |
| 03-51-038 | REPLACE N | NEW WIPER BLADES | | V | /W-2000 | -PC | WI | PER BLADE 20" | | | 11.79 | 1 | | \$11.79 |
| FleetFocus M5 | - WODETAIL | - Work Order Detail v20 |).0 | | | | | | | | | | | Page:1 |

The University of Alabama

| Job Code | Job Description |
|-----------|----------------------------------|
| 03-51-038 | REPLACE NEW WIPER BLADES |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES |
| 66-PM-PMC | PERFORM CABIN FILTER REPLACEMENT |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES |
| 66-17-028 | PERFORM MOUNT AND BALANCE TIRES |

| Part No. |
|--------------|
| WW-2600-PC |
| 52168 |
| 21030 |
| 800012C |
| WHEEL WEIGHT |
| 63001 |

| <u>).</u> | Description | Unit Price | Quantity | Total Cost |
|-----------|-----------------------------|------------|----------|------------|
| | WIPER BLADE 26" | 12.79 | 1 | \$12.79 |
| | TIRE 245/60R18 MICH DEF LTX | 217.86 | 2 | \$435.72 |
| | TPMS SERVICE KIT 6-116 | 3.32 | 2 | \$6.63 |
| | CABIN AIR FILTER REPL 4483 | 7.33 | 1 | \$7.33 |
| | WHEEL WEIGHT KNOCK ON | 0.42 | 1 | \$0.42 |
| | 1/4 OZ STICK ON TAPE WEIGHT | 0.06 | 9 | \$0.54 |
| | | | PARTS | 534.55 |

241366 2015 TOYOTA HIGHLANDER UNIT NO:

WORK ORDER NO:

37617

Work Order Notes

(LISAPATE) PM-Replace wipers and air filter

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

06-15 - INSPECT STEERING

(JWRIGHT) Checked front end and brakes. Found no issues. AMG, JAW

09-15 - ALIGN STEERING

(ABLACK) AB performed alignment

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr came to the shop and repaired the ding in the windshield. Pd by CC

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced both front tires and balanced. Aired and torqued to spec.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service and found damage on the rear lift gate and rear trim. Also scratch on left side and small sent on rr panel. coolant -34° also found it needs front tires replaced. SH, JAW/JAW

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) Replaced air filter

The University of Alabama

| UNIT NO: | | 241366 2015 | 5 ΤΟΥΟΤΑ ΗΙ | GHLA | ANDER | | | WORK OF | DER NO: | 39 | 9118 | |
|---|---------------|--|--|-----------|-------------|------------|--|--|------------------|------------------------|--|------------|
| USING DEF WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | OPENE COMPL CLOSE 2015 Toyota H | ETED | DATE: E: | 02/19/202 | 1 13:27:16 1 11:34:49 1 14:04:56 | LOCATION: METER 1 - N IN-SERVICE UNIT SERIA | : 23180 DATE: | M I 06/02/20 | y Automotive S E TER 2 - N: 15 FH6FS083586 | 0 |
| JOB CODE | <u>E</u> | JOB DESCRIPTION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATER | IAL C | OMMERCIAL | TOTAL COST |
| 66-79-003 | PERFOR | M SAFETY INSPECTION | DON | Y | Ν | GARAGE | 0.78 | \$91.61 | \$0.00 | \$0 | .00 | \$91.61 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | DON | Ρ | Ν | GARAGE | 0.79 | \$93.55 | \$0.00 | \$0 | .00 | \$93.55 |
| JOB COUN | NT: 2 | | | WC | | DER TOTAL: | 1.57 | 185. | 16 | 0.00 | 0.00 | 185.16 |
| Job Code | | Job Description | | <u>En</u> | nployee | <u>No.</u> | <u>Start</u> | E | <u>inish</u> | | <u>Quantity</u> | Total Cost |
| 66-79-003 | PERFORM | SAFETY INSPECTION | 1 | 1901357 | , | 02/ | 18/2021 13:09:45 | 02/18/202 | 1 13:53:04 | | 0.72 | \$85.19 |
| 66-79-003 | PERFORM | SAFETY INSPECTION | 1 | 1901357 | , | 02/ | 18/2021 15:24:10 | 02/18/202 | 1 15:27:26 | | 0.05 | \$6.42 |
| 66-PM-PMA | PERFORM | OIL CHANGE | 1 | 1901357 | 7 | 02/ | 18/2021 12:21:44 | 02/18/202 | 1 13:09:18 | | 0.79 | \$93.55 |
| | | | | | | | | | | | LABOR | 185.16 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

241366 **2015 TOYOTA HIGHLANDER** UNIT NO:

WORK ORDER NO:

39118

Work Order Notes

(LISAPATE) PM-Do annual safety inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) miles: 23180 completed safety inspection and safety inspection checklist, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 23180 Vehicle has been 1139 miles, oil was changed at last PM, checked fluids, battery and tires, updated oil change sticker. Completed checklist and vacuumed out vehicle AMG

The University of Alabama

| UNIT NO: | 241366 | 2015 TOYC | DTA HIG | HLAN | NDER | 1 | | WORK OR | | : : | 39466 | |
|---------------|--------------------------|--------------|-------------|------------|-------------|------------|------------------|-------------|----------|-----------|--------------------|------------|
| USING DEPT N | IO: 208185 | | OPENED | DATE: | 1 | 03/23/202 | 1 07:07:07 | LOCATION: | GARAGE | - Univers | sity Automotive \$ | Services |
| WO STATUS: | CLOSED | (| COMPLE | TED D | ATE: | 03/23/202 | 1 15:06:38 | METER 1 - M | : 23532 | I | METER 2 - N: | 0 |
| WO VISIT REAS | SON: SCHEDULED | | CLOSED | DATE: | | 03/30/202 | 1 15:14:52 | IN-SERVICE | DATE: | 06/02/2 | 2015 | |
| TECH SPEC NO | O: 15TOYHIGHLAN | D 2015 T | oyota Hig | ghlandei | r | | | UNIT SERIA | NO: | 5TDZK | RFH6FS083586 | 6 |
| JOB CODE | JOB DESCRIPT | ION | <u>STAT</u> | RSN \ | <u>NRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | RIAL | COMMERCIAL | TOTAL COST |
| PD-00-999 F | PREP DISPOSE PREPARE | UNIT FOR DI | DON | D | Ν | GARAGE | 0.05 | \$5.34 | \$0.00 | : | \$0.00 | \$5.34 |
| JOB COUNT: | 1 | | | WOR | K ORI | DER TOTAL: | 0.05 | 5. | 34 | 0.00 | 0.00 | 5.3 |
| Job Code | Job Descrip | <u>tion</u> | | <u>Emp</u> | loyee | <u>No.</u> | <u>Start</u> | E | inish | | <u>Quantity</u> | Total Cost |
| PD-00-999 PR | REP DISPOSE PREPARE UNIT | FOR DISPOSAL | . 119 | 915538 | | 03/2 | 23/2021 10:40:26 | 03/23/202 | 10:43:09 | | 0.05 | \$5. |
| | | | | | | | | | | | LABOR | 5.3 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

UNIT NO: 241366 2015 TOYOTA HIGHLANDER WORK ORDER NO: 39466

Work Order Notes

(LISAPATE) Per Mario prep unit for surplus

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks tag\ RC (AJONES) Fleet decided to keep vehicle

The University of Alabama

| UNIT NO: | | 241366 | 2015 ТОҮОТА Н | GHLA | NDER | R | | WORK OR | DER NO: | 397 | ' 02 | |
|---|---------------|--|--|----------------------|------------------|--------------------------|---|---|----------------------------|--------------------------|---------------------------|--|
| USING DEF WO STATU WO VISIT F TECH SPE | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | OPENE COMPI CLOSE 2015 Toyota H | ETED | DATE: E: | 04/16/202 | 21 15:16:42 21 13:55:37 21 09:16:42 | LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL | DATE: 0 | MET 6/02/2015 | ER 2 - N: | 0 |
| JOB CODE | | JOB DESCRIPTIO E NEW BATTERY | <u>N</u> STAT DON | <u>RSN</u> O | <u>WRTY</u> N | <u>JOB LOC</u> GARAGE | LABOR HRS 0.18 | | MATERIA \$113.55 | <u>L COI</u> \$0.0 | MMERCIAL 0 | TOTAL COST \$134.76 |
| JOB COUN | NT: 1 | | | WC | RK ORI | DER TOTAL | 0.18 | 3 21.2 | :1 11; | 8.55 | 0.00 | 134.76 |
| <u>Job Code</u> 03-32-002 | REPLACE N | Job Descriptic IEW BATTERY | | <u>En</u> 2052187 | nployee | | <u>Start</u> /15/2021 15:32:47 | | <u>nish</u> 15:43:34 | - | Quantity 0.18 LABOR | <u>Total Cost</u> \$21.21 21.21 |
| Job Code 03-32-002 | REPLACE N | Job Description | | 4F2 | <u>Part No</u> | _ | Des TTERY BCI 24F \$ | scription 550CCA | <u>Uni</u> | t Price 113.55 | Quantity 1 PARTS | <u>Total Cost</u> \$113.55 113.55 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

UNIT NO: 241366 2015 TOYOTA HIGHLANDER WORK ORDER NO: 39702

Work Order Notes

(EKIMBREL) replace battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. Charging at 13.9 volts. JAW

The University of Alabama

| UNIT NO: 241366 2015 TOY | | | DTA HI | GHLA | NDER | 2 | | WORK | | D: 4 | 0173 | | |
|--------------------------|------------|---------------------|-----------|--|----------|--------|-----------------|---|------------|---|------------|---|------------|
| WO STATUS WO VISIT R | | | | OPENED DATE: COMPLETED DATE: CLOSED DATE: Toyota Highlander | | | 06/23/202 | 06/15/2021 07:59:03 06/23/2021 14:17:41 06/23/2021 14:17:44 | | LOCATION: GARAGE METER 1 - M: 27634 IN-SERVICE DATE: UNIT SERIAL NO: | | ty Automotive : I ETER 2 - N: 015 RFH6FS08358 | 0 |
| JOB CODE | <u>.</u> | JOB DESCRIPTION | | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABC | <u>R MATI</u> | ERIAL C | OMMERCIAL | TOTAL COST |
| 03-17-028 | REPLAC | E NEW MOUNT AND | BALANCE | DON | 0 | Ν | GARAGE | 0.50 | \$58.64 | \$443.78 | s \$(| 0.00 | \$502.42 |
| 06-15 | INSPECT | STEERING | | DON | 0 | Ν | GARAGE | 0.25 | \$29.50 | \$0.00 | \$0 | 0.00 | \$29.50 |
| 09-15 | ALIGN S | TEERING | | DON | 0 | Ν | GARAGE | 0.58 | \$67.95 | \$0.00 | \$0 | 0.00 | \$67.95 |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.88 | \$103.35 | \$40.43 | \$0 | 0.00 | \$143.78 |
| JOB COUNT: 4 | | | | | WOF | | | 2.20 |) 2 | 59.44 | 484.21 | 0.00 | 743.65 |
| Job Code | | Job Description | <u>1</u> | | Emp | oloyee | <u>No.</u> | <u>Start</u> | | <u>Finish</u> | | Quantity | Total Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1901357 | | 06 | /15/2021 08:44:3 | 6 06/15/2 | 2021 09:15:00 | | 0.51 | \$59.79 |
| 06-15 | INSPECT ST | TEERING | | 1 | 1901357 | | 06 | /23/2021 07:00:0 | 06/23/2 | 2021 07:15:00 | | 0.25 | \$29.50 |
| 06-15 | INSPECT ST | TEERING | | 1 | 1310047 | | 06 | /15/2021 14:23:5 | 2 06/15/2 | 2021 14:23:52 | | 0.00 | \$0.00 |
| 09-15 | ALIGN STEE | ERING | | 1 | 1310047 | | 06 | /15/2021 13:30:5 | 7 06/15/2 | 2021 14:05:30 | | 0.58 | \$67.95 |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | 1 | 1901357 | | 06 | /15/2021 13:00:0 | 06/15/2 | 2021 13:29:49 | | 0.50 | \$58.64 |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | 1 | 1901357 | | 06 | /15/2021 12:22:2 | 3 06/15/2 | 2021 12:22:23 | | 0.00 | \$0.00 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 1 | 1074414 | | 06 | /15/2021 08:25:4 | 3 06/15/2 | 2021 08:47:52 | | 0.37 | \$43.56 |
| | | | | | | | | | | | | LABOR | 259.44 |
| Job Code | | Job Description | <u>1</u> | | E | art No | <u>.</u> | De | scription | | Unit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 04 | 4152-YZZ | A1 | FII | LTER-OIL | | | 6.96 | 6 1 | \$6.96 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | W20BT | | BL | JLK OIL 0W20 FS | ; | | 4.49 |) 7 | \$31.40 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 05089 | | | BF | RAKE CLEAN NO | N-FLAMMAB | LE 14OZ | 6.56 | 3 1 | \$6.56 |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | 21030 | | | TF | MS SERVICE KI | T 6-116 | | 3.30 | | |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0W20BT | | | BL | JLK OIL 0W20 FS | i | | 4.49 |) (7 |) (\$31.40 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0W20BT | | | BL | JLK OIL 0W20 FS | i | | 4.49 | 9 6 | \$26.91 |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | V | VHEEL WI | EIGHT | W | HEEL WEIGHT K | NOCK ON | | 0.50 |) 1 | \$0.50 |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | 63001 1/4 OZ S | | | 4 OZ STICK ON 1 | APE WEIGH | Т | 0.06 | 6 16 | \$0.96 | |
| 03-17-028 | REPLACE N | IEW MOUNT AND BALAN | NCE TIRES | 5 | 2168 | | TII | RE 245/60R18 M | CH DEF LTX | | 217.86 | 6 2 | \$435.72 |

| 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 40173 |
|-----------------|--|--|---|
| | | | |
| | | | |
| | | | |
| EW MOUNT AI | ID BALANCE TIRES | | |
| nd balanced rea | r tires. AMG | | |
| ING | | | |
| necked good. Al | ИG | | |
| G | | | |
| lignment. EH | | | |
| OIL CHANGE | | | |
| 5 Completed PN | I topside, Scott assisted, Josh was bottomside. Complete | ed checklist. AMG SH/JW | |
| | nd balanced rea RING necked good. AN G Alignment. EH I OIL CHANGE | The formation of the fo | IEW MOUNT AND BALANCE TIRES Ind balanced rear tires. AMG RING hecked good. AMG G Alignment. EH |

The University of Alabama

| UNIT NO: | | | | IGHLA | NDER | 2 | | WORK OR | DER NO: | 41 | 499 | | | |
|---|---------------|---|----------------|-------------|---------------------------------------|-------------|------------|--|--|----------------|-----------------|------------|--------------|-----------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED PREVENTIVE I 15TOYHIGHLA | MAINT | COMP | ED DAT LETED ED DAT lighland | DATE: E: | 11/08/202 | 1 10:27:34 1 15:17:23 1 07:59:54 | LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL | 31215 DATE: | ME 06/02/201 | TER 2 - N: | 0 | |
| JOB CODE | L | JOB DESCRIP | TION | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATER | RIAL CO | MMERCIAL | <u>TOTAL</u> | COST |
| 03-17-016 | REPLAC | E NEW TIRE PR | ESSURE MONI | DON | 0 | Ν | GARAGE | 2.42 | \$285.89 | \$205.89 | \$0. | 00 | \$491.78 | |
| 03-51-038 | REPLAC | E NEW WIPER E | BLADES | DON | Р | Ν | GARAGE | 0.04 | \$4.69 | \$31.82 | \$0. | 00 | \$36.51 | |
| 66-17-033 | PERFOR | M TIRE ROTATI | ON AND BRAKE | DON | 0 | Ν | GARAGE | 0.22 | \$25.96 | \$0.00 | \$0. | 00 | \$25.96 | |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.67 | \$79.03 | \$38.89 | \$0. | 00 | \$117.92 | |
| 66-PM-PMC | PERFOR | M CABIN FILTE | R REPLACEMEI | DON | Р | Ν | GARAGE | 0.03 | \$4.00 | \$0.00 | \$0. | 00 | \$4.00 | |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$2. | 00 | \$2.00 | |
| JOB COUN | IT: 6 | | | | WC | | DER TOTAL: | 3.39 | 399.5 | 7 2 | 276.60 | 2.00 | | 678.17 |
| Job Code | | Job Descr | iption | | | endor N | | Invoice No. | Purchase | e Order No. | <u>.</u> | | <u>Total</u> | |
| CH-SP | CHARGE Sh | op Supplies | | t | 503163 | | 1 | | | | | COMML | | \$2.00 2.00 |
| Job Code | | Job Descr | ption | | En | nployee | <u>No.</u> | <u>Start</u> | Fii | nish | | Quantity | Total | Cost |
| 03-17-016 | REPLACE N | EW TIRE PRESSU | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 03/2021 13:55:40 | 11/03/2021 | 14:06:41 | | 0.18 | | \$21.67 |
| 66-17-033 | PERFORM | TIRE ROTATION A | ND BRAKE INSPE | CTION 1 | 1074414 | Ļ | 11/ | 03/2021 11:36:16 | 11/03/2021 | 11:49:28 | | 0.22 | | \$25.96 |
| 03-51-038 | REPLACE N | EW WIPER BLADI | ES | 1 | 1074414 | Ļ | 11/ | 03/2021 11:31:42 | 11/03/2021 | 11:34:05 | | 0.04 | | \$4.69 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1074414 | Ļ | 11/ | 03/2021 10:51:19 | 11/03/2021 | 11:31:30 | | 0.67 | | \$79.03 |
| 03-17-016 | REPLACE N | EW TIRE PRESSL | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 03/2021 14:32:33 | 11/03/2021 | 15:39:10 | | 1.11 | | \$131.01 |
| 66-PM-PMC | PERFORM | CABIN FILTER REF | PLACEMENT | 1 | 1074414 | Ļ | 11/ | 04/2021 07:02:17 | 11/04/2021 | 07:04:19 | | 0.03 | | \$4.00 |
| 03-17-016 | REPLACE N | EW TIRE PRESSU | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 04/2021 07:05:24 | 11/04/2021 | 07:24:47 | | 0.32 | | \$38.12 |
| 03-17-016 | REPLACE N | EW TIRE PRESSU | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 04/2021 08:10:21 | 11/04/2021 | 08:21:14 | | 0.18 | | \$21.40 |
| 03-17-016 | REPLACE N | EW TIRE PRESSU | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 04/2021 11:20:43 | 11/04/2021 | 11:54:45 | | 0.57 | | \$66.93 |
| 03-17-016 | REPLACE N | EW TIRE PRESSU | JRE MONITOR/SE | NSOR 1 | 1074414 | Ļ | 11/ | 04/2021 13:06:30 | 11/04/2021 | 13:09:56 | | 0.06 | | \$6.75 |
| | | | | | | | | | | | | LABOR | | 399.56 |
| Job Code | | Job Descri | intion | | | Part No | | Dee | cription | | nit Price | Quantity | Total | Cost |

The University of Alabama

| Job Code | Job Description | Part No. | Description | Unit Price | Quantity | Total Cost |
|-----------|--|-------------|--------------------------------|------------|----------|------------|
| 03-51-038 | REPLACE NEW WIPER BLADES | 19260 | WIPER BLADE 26 IN OE BEAM | 12.43 | 1 | \$12.43 |
| 66-PM-PMA | PERFORM OIL CHANGE | 05089 | BRAKE CLEAN NON-FLAMMABLE 140Z | 6.56 | 1 | \$6.56 |
| 66-PM-PMA | PERFORM OIL CHANGE | 0W20BT | BULK OIL 0W20 FS | 4.50 | 6 | \$27.00 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 12A | 12" WIPER BLADE | 9.20 | 1 | \$9.20 |
| 66-PM-PMA | PERFORM OIL CHANGE | 04152-YZZA1 | FILTER-OIL | 5.33 | 1 | \$5.33 |
| 03-17-016 | REPLACE NEW TIRE PRESSURE MONITOR/SENSOR | 426070R020 | TPMS KIT | 102.95 | 2 | \$205.89 |
| 03-17-016 | REPLACE NEW TIRE PRESSURE MONITOR/SENSOR | 21360 | TPMS DUAL FREQ UNIV STEM | 46.10 | (2) | (\$92.19) |
| 03-17-016 | REPLACE NEW TIRE PRESSURE MONITOR/SENSOR | 21360 | TPMS DUAL FREQ UNIV STEM | 46.10 | 2 | \$92.19 |
| 03-51-038 | REPLACE NEW WIPER BLADES | 19200 | WIPER BLADE OE BEAM STYLE 20IN | 10.19 | 1 | \$10.19 |
| | | | | - | PARTS | 276.60 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

241366 2015 TOYOTA HIGHLANDER WORK ORDER NO: UNIT NO:

41499

Work Order Notes

(IFALLS) PM

Job Notes

03-17-016 - REPLACE NEW TIRE PRESSURE MONITOR/SENSOR

(SHARBIN) Left front and right front TPMS sensors were not reading replaced both sensors and test drove flashing light would not go out. Used the tire tool to relearn tire positions through the ECU but this did not work either. Ordered 2 sensors from Toyota and installed them tire light is out. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

The University of Alabama

| UNIT NO: | | | 15 TOYOTA HIGHLANDER | | | | | | DER NC |): 4 | 2025 | | |
|---|---------------|--|----------------------|---------------------|-------------|------------|---|--|----------------|--------------|--|--------------|------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | COMP | ED DAT | DATE: E: | 03/29/202 | 22 11:14:05 22 15:28:09 22 08:13:55 | LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL | 33024 DATE: | N 06/02/2 | ity Automotive S IETER 2 - N: 015 RFH6FS083586 | 0 | |
| JOB CODE | <u> </u> | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | <u>ERIAL</u> | COMMERCIAL | <u>TOTAI</u> | COST |
| 16-71 | TRANSF | PORT BODY | DON | 0 | Ν | GARAGE | 0.50 | \$59.00 | \$0.00 | \$ | 0.00 | \$59.00 | |
| 20-00 | TOWING | COMPLETE VEHICLE | DON | В | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 798.10 | \$798.10 | |
| 24-71 | REPAIR | BODY | DON | А | N | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 4,299.33 | \$4,299.3 | 3 |
| 35-42 | DIAGNO | SE COOLING SYSTEM | DON | 0 | N | GARAGE | 0.25 | \$29.50 | \$0.00 | \$ | 0.00 | \$29.50 | |
| 66-PM-PMA | PERFOF | RM OIL CHANGE | DON | Р | N | GARAGE | 0.14 | \$17.04 | \$39.52 | \$ | 0.00 | \$56.56 | |
| CH-SP | CHARGE | E Shop Supplies | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 2.00 | \$2.00 | |
| JOB COUN | IT: 6 | | | wo | | DER TOTAL: | 0.89 | 105.54 | 4 | 39.52 | 5,099.43 | | 5,244.49 |
| Job Code | | Job Description | | V | endor N | <u>o.</u> | Invoice No. | Purchase | Order N | <u>o.</u> | | Tota | l Cost |
| 20-00 | TOWING CO | OMPLETE VEHICLE | | 1076249 |) | 222 | 2778 | | | | | | \$798.10 |
| 24-71 | REPAIR BO | DY | | 1150605 | 5 | 169 | 9068056 | | | | | | \$2,300.00 |
| 24-71 | REPAIR BO | DY | | 1150605 | 5 | 169 | 9068057 | | | | | | \$1,999.33 |
| CH-SP | CHARGE SI | hop Supplies | Ę | 03163 | | 1 | | | | | | | \$2.00 |
| | | | | | | | | | | | COMML | | 5099.43 |
| Job Code | | Job Description | | Er | nployee | <u>No.</u> | <u>Start</u> | <u>Fir</u> | nish | | <u>Quantity</u> | Tota | l Cost |
| 35-42 | DIAGNOSE | COOLING SYSTEM | | 121318 |) | 03/ | 29/2022 07:00:00 | 03/29/2022 | 07:15:00 | | 0.25 | | \$29.50 |
| 16-71 | TRANSPOR | RT BODY | | 139974 | 5 | 03/ | 29/2022 07:00:00 | 03/29/2022 | 07:30:00 | | 0.50 | | \$59.00 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 205218 | 7 | 03/ | 21/2022 13:00:00 | 03/21/2022 | 13:08:40 | | 0.14 | | \$17.04 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 205218 ⁻ | 7 | 03/ | 21/2022 12:58:01 | 03/21/2022 | 12:58:01 | | 0.00 | | \$0.00 |
| | | | | | | | | | | | LABOR | | 105.54 |
| Job Code | | Job Description | | | Part No | <u>.</u> | Des | cription | | Unit Price | <u>Quantity</u> | Tota | l Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | (| 4152-Y2 | ZZA1 | FIL | TER-OIL | | | 6.0 | 5 1 | | \$6.05 |
| 66-PM-PMA | PERFORM | OIL CHANGE | (| W20BT | | BU | LK OIL 0W20 FS | | | 4.4 | 9 6 | | \$26.91 |
| 66-PM-PMA | PERFORM | OIL CHANGE | (| 5089 | | BR | AKE CLEAN NON | I-FLAMMABLE 14 | 4OZ | 6.5 | | | \$6.56 |
| | | | | | | | | | | | PARTS | | 39.52 |

241366 2015 TOYOTA HIGHLANDER UNIT NO:

WORK ORDER NO:

42025

Work Order Notes

(IFALLS) Driver requested unit be towed in ran over something in the road and loosing coolant. Bambarger will take a loaner unit to Georgia state line and swap and pick up disabled unit and bring to the shop.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Picked up from Andrews by RC/CW

20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Bambarger towed unit to the shop. per notes above. Pd by CC

24-71 - REPAIR BODY

(IFALLS) Andrews repaired Body Damage to rear lift gate (department pay) and rear bumper was not part of accident. Pd by CC State Auto Pd Andrews for frontend damage Ck# 1000984997 3-21-22 \$534.17 UA pd \$2000.00 DED and they also paid a supplement of CK# 1001012819 3-21-22 \$138.01. All repairs have been completed

35-42 - DIAGNOSE COOLING SYSTEM

(LISAPATE) IF verified radiator is busted is why its loosing coolant. Repair will be done by the Body Shop

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH drained oil, reinstalled plug and removed oil filter. JAW installed oil filter and filled with oil. JAW, SH/SH, JAW MILEAGE-33183

CH-SP - CHARGE Shop Supplies

The University of Alabama

| UNIT NO: | | 241366 201 | 5 ΤΟΥΟΤΑ Η | GHL | NDER | 2 | | WORK OR | DER NO: | 44465 | |
|---|---------------|---|--|------------|-------------|------------|--|---|----------------------------|--|-------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED PREVENTIVE MAINT 15TOYHIGHLAND | OPENE COMPI CLOSE 2015 Toyota H | ETED | DATE: E: | 08/26/202 | 2 11:18:25 2 09:43:01 2 13:51:20 | LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI | : 35178 DATE: 06 | niversity Automotive METER 2 - N: 6/02/2015 TDZKRFH6FS08358 | 0 |
| JOB CODE | L | JOB DESCRIPTION | <u>STAT</u> | <u>RSN</u> | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIA | | TOTAL COST |
| 66-PM-PMA | PERFOR | RM OIL CHANGE | DON | Ρ | Ν | GARAGE | 0.17 | \$20.26 | \$0.00 | \$0.00 | \$20.26 |
| CH-SP | CHARGE | E Shop Supplies | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5.00 | \$5.00 |
| JOB COUN | IT: 2 | | | WC | RK ORI | DER TOTAL: | 0.17 | 20.2 | 26 (|).00 5.00 |) 25.26 |
| Job Code | | Job Description | | <u>v</u> | endor N | <u>lo.</u> | Invoice No. | <u>Purchas</u> | <u>e Order No.</u> | | Total Cost |
| CH-SP | CHARGE SH | nop Supplies | 5 | 03163 | | 1 | | | | | \$5.00 |
| | | | | | | | | | | COMML | 5.00 |
| Job Code | | Job Description | | En | nployee | No. | <u>Start</u> | F | inish | <u>Quantity</u> | <u>Total Cost</u> |
| 66-PM-PMA | PERFORM | OIL CHANGE | 1 | 1901357 | 7 | 08/ | 25/2022 14:04:42 | 08/25/2022 | 2 14:15:00 | 0.17 | \$20.26 |
| | | | | | | | | | | LABOR | 20.26 |

241366 2015 TOYOTA HIGHLANDER UNIT NO:

WORK ORDER NO: 44465

Work Order Notes

(IFALLS) Herb Robertson dropped off for pm brewer porch

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 35178 Vehicle has been 995 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

CH-SP - CHARGE Shop Supplies

The University of Alabama

| UNIT NO: | NO: 241366 2015 TOYOTA HIGHLANDI | | | | NDER | ł | | WORK OF | RDER NO | : 4 | 5416 | | | |
|---|----------------------------------|---|---------------------|-------------------------|---------|-------------|------------|---|--|-------------------|-----------------------|--|--------------|----------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAN | D 2015 ⁻ | OPENE COMPL CLOSE | ETED | DATE: E: | 12/06/202 | 22 15:08:24 22 07:54:12 22 10:32:31 | LOCATION: METER 1 - N IN-SERVICE UNIT SERIA | I: 36871 DATE: | MI 06/02/20 | y Automotive S E TER 2 - N: 15 FH6FS083586 | 0 | |
| JOB CODE | Ē | JOB DESCRIPT | ON | <u>STAT</u> | RSN | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | RIAL C | OMMERCIAL | TOTAL | COST |
| 03-17-016 | REPLAC | E NEW TIRE PRE | SSURE MONI | DON | 0 | Ν | GARAGE | 0.90 | \$106.40 | \$50.10 | \$0 | .00 | \$156.50 | |
| CH-SP | CHARGE | E Shop Supplies | | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$5 | .00 | \$5.00 | |
| SO-05 | SCAN O | UT ELECTRONIC | ENGINE EEC | DON | 0 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$0 | .00 | \$0.00 | |
| JOB COUN | IT: 3 | | | | wo | RK ORI | DER TOTAL | . 0.90 | 106. | 40 | 50.10 | 5.00 | | 161.50 |
| Job Code | | Job Descrip | tion | | v | endor N | <u>o.</u> | Invoice No. | Purchas | e Order No | <u>).</u> | | Total | Cost |
| CH-SP | CHARGE SI | nop Supplies | | 5 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Descrip | tion | | Em | nployee | <u>No.</u> | <u>Start</u> | <u> </u> | <u>inish</u> | | Quantity | Total | Cost |
| 03-17-016 | REPLACE N | IEW TIRE PRESSUR | E MONITOR/SE | NSOR 1 | 1310047 | , | 12 | /02/2022 13:13:43 | 12/02/202 | 2 14:07:49 | | 0.90 | | \$106.40 |
| | | | | | | | | | | | | LABOR | | 106.40 |
| Job Code | | Job Descrip | <u>tion</u> | | | Part No | <u>.</u> | Des | cription | <u>।</u> | Jnit Price | Quantity | <u>Total</u> | Cost |
| 03-17-016 | REPLACE N | IEW TIRE PRESSUR | E MONITOR/SE | NSOR 2 | 1360 | | TF | MS DUAL FREQ | UNIV STEM | | 50.10 | 1 | | \$50.10 |
| | | | | | | | | | | | | PARTS | | 50.10 |

241366 **2015 TOYOTA HIGHLANDER** UNIT NO:

WORK ORDER NO: 45416

Work Order Notes

(LISAPATE) Check engine light on, running fine. Going out of Town Tuesday.

Job Notes

03-17-016 - REPLACE NEW TIRE PRESSURE MONITOR/SENSOR

(EHOWELL) The low tire light was on, and the battery was low in the right front tire pressure sensor. Replaced RF tire pressure sensor and programmed the sensor to the vehicle. AMG drove vehicle and the light went out. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Did not scan out. The check engine light was not on. EH

The University of Alabama

| UNIT NO: | | | 5 ΤΟΥΟ | TA HI | GHLA | NDER | ł | | WORK OF | |): 4 | 5728 | | |
|---|---------------|--|--------|-------------|----------------------------|-------------|------------|---|--|----------------------------------|--------------|--|----------|-------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | C | OMPL | D DATE ETED I D DATE | DATE: E: | 01/10/20 | 23 07:22:09 23 14:15:58 23 15:42:51 | LOCATION: METER 1 - M IN-SERVICE UNIT SERIA | 1 : 37852 DATE: | N 06/02/2 | ity Automotive S IETER 2 - N: 015 RFH6FS083586 | 0 | |
| JOB CODE | L | JOB DESCRIPTION | 5 | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | MATE | ERIAL (| COMMERCIAL | TOTAL (| COST |
| 03-51-038 | REPLAC | E NEW WIPER BLADES | I | DON | Ρ | Ν | GARAGE | 0.08 | \$9.28 | \$32.73 | \$ | 0.00 | \$42.01 | |
| 66-PM-PMA | PERFOR | M OIL CHANGE | I | DON | Р | Ν | GARAGE | 0.62 | \$73.36 | \$55.44 | \$ | 0.00 | \$128.80 | |
| CH-SP | CHARGE | Shop Supplies | I | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 5.00 | \$5.00 | |
| JOB COUN | IT: 3 | | | | WO | RK ORI | DER TOTAL | : 0.70 | 82. | 64 | 88.17 | 5.00 | | 175.81 |
| Job Code | | Job Description | | | V | endor N | <u>o.</u> | Invoice No. | Purchas | se Order N | <u>o.</u> | | Total (| <u>Cost</u> |
| CH-SP | CHARGE Sh | nop Supplies | | 5 | 03163 | | 1 | | | | | | | \$5.00 |
| | | | | | | | | | | | | COMML | | 5.00 |
| Job Code | | Job Description | | | Em | ployee | <u>No.</u> | <u>Start</u> | <u>F</u> | <u>inish</u> | | <u>Quantity</u> | Total (| Cost |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1074414 | | 0 | /10/2023 08:15:57 | 01/10/202 | 3 08:53:15 | | 0.62 | | \$73.36 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1 | 1074414 | | 0 | /10/2023 08:11:01 | 01/10/202 | 3 08:15:44 | | 0.08 | | \$9.28 |
| | | | | | | | | | | | | LABOR | | 82.64 |
| Job Code | | Job Description | | | | Part No | <u>.</u> | Des | cription | | Unit Price | <u>Quantity</u> | Total (| Cost |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1 | 9260 | | V | IPER BLADE 26 IN | N OE BEAM | | 12.7 | 9 1 | | \$12.79 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1 | 9200 | | V | IPER BLADE OE E | BEAM STYLE 20 | NIC | 10.4 | 7 1 | | \$10.47 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0 | 5089 | | В | RAKE CLEAN NON | N-FLAMMABLE | 140Z | 7.8 | 6 1 | | \$7.86 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 0' | W20BT | | В | JLK OIL 0W20 FS | | | 6.0 | 9 6 | | \$36.54 |
| 03-51-038 | REPLACE N | EW WIPER BLADES | | 1: | 2A | | 1: | " WIPER BLADE | | | 9.4 | 7 1 | | \$9.47 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 04 | 4152-YZ | ZA1 | F | LTER-OIL | | | 11.0 | 41 | | \$11.04 |
| | | | | | | | | | | | | PARTS | | 88.17 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 45728 |
|-------------------|-------------------|------------------------|----------------|-------|
| Work Order Not | tes | | | |
| (EHANNAH) pm- re | place wipers | | | |
| Job Notes | | | | |
| 03-51-038 - REPLA | CE NEW WIPER BL | ADES | | |
| (SHARBIN) Replace | ed the wipers. SH | | | |
| 66-PM-PMA - PERF | FORM OIL CHANGE | | | |
| (SHARBIN) SH/GC | Performed PM. | | | |
| CH-SP - CHARGE | Shop Supplies | | | |
| | | | | |

The University of Alabama

| UNIT NO: | | 241366 20 | 15 TOYO ⁻ | TA HI | GHLA | NDER | | | WORK C | RDER NO: | : 4 | 47086 | |
|---|--------------|--|----------------------|-------------|---------------------------------------|-------------|------------------|---|---|---------------------|--------------|--|----------------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: EASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | C | OMPL | D DATE ETED I D DATE ghlande | DATE: E: | 05/17/202 | 23 15:21:58 23 15:31:50 23 07:14:41 | LOCATION METER 1 - IN-SERVIC UNIT SERI | M: 39520 E DATE: | N 06/02/2 | ity Automotive S /ETER 2 - N: 015 RFH6FS083586 | 0 |
| JOB CODE | | JOB DESCRIPTION | Ś | <u>STAT</u> | <u>RSN</u> | <u>WRTY</u> | JOB LOC | LABOR HRS | LABOR | <u>MATER</u> | RIAL (| COMMERCIAL | TOTAL COST |
| 66-PM-PMA | PERFOF | RM OIL CHANGE | I | DON | Ρ | Ν | GARAGE | 0.17 | \$20.36 | \$0.00 | \$ | 60.00 | \$20.36 |
| CH-SP | CHARGE | E Shop Supplies | I | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$ | 5.00 | \$5.00 |
| WA-00 | WASH C | OMPLETE VEHICLE | I | DON | Ρ | Ν | GARAGE | 0.36 | \$41.96 | \$0.00 | \$ | 60.00 | \$41.96 |
| JOB COUN | Т: 3 | | | | WO | RK ORI | DER TOTAL: | 0.53 | 6 | 2.32 | 0.00 | 5.00 | 67.3 |
| Job Code CH-SP | CHARGE SI | Job Description | | 50 | <u>Ve</u> 03163 | endor N | l o. 1 | <u>Invoice No.</u> | Purch | ase Order No | <u>.</u> | | <u>Total Cost</u> \$5.0 |
| | | | | | | | | | | | | COMML | 5.0 |
| Job Code | | Job Description | | | Em | ployee | <u>No.</u> | <u>Start</u> | | <u>Finish</u> | | <u>Quantity</u> | Total Cost |
| WA-00 | WASH COM | IPLETE VEHICLE | | 11 | 074414 | | 05/ | 17/2023 10:36:22 | 05/17/20 | 023 10:57:42 | | 0.36 | \$41.9 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 11 | 074414 | | 05/ | 17/2023 10:25:49 | 05/17/20 | 023 10:36:10 | | 0.17 | \$20.3 |
| | | | | | | | | | | | | LABOR | 62.3 |

241366 2015 TOYOTA HIGHLANDER UNIT NO:

WORK ORDER NO:

47086

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1668 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

The University of Alabama

| UNIT NO: | | 241366 | 2015 TOYO | | GHLA | NDER | | | WORK O | |): 4 | 8636 | |
|---|---------------|--|-----------|-------------------------|------------------|-------------|------------|---|--|---------------------|----------------------|--|------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: REASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | | OPENE COMPL CLOSE | ETED I D DATI | DATE: E: | 10/25/20 | 23 14:20:06 23 07:26:50 23 09:08:43 | LOCATION: METER 1 - I IN-SERVICE UNIT SERIA | M: 41989 E DATE: | M 06/02/20 | ty Automotive S ETER 2 - N: 015 RFH6FS083586 | |
| JOB CODE | | JOB DESCRIPTIO | N | <u>STAT</u> | RSN | WRTY | JOB LOC | LABOR HRS | LABOR | MATE | RIAL C | OMMERCIAL | TOTAL COST |
| 66-PM-PMA | PERFOR | M OIL CHANGE | | DON | Р | Ν | GARAGE | 0.37 | \$43.59 | \$98.26 | \$0 |).00 | \$141.85 |
| 66-PM-PMC | PERFOR | M CABIN FILTER R | EPLACEMEI | DON | Р | Ν | GARAGE | 0.13 | \$14.78 | \$13.17 | \$0 |).00 | \$27.95 |
| CH-SP | CHARGE | Shop Supplies | | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$: | 5.00 | \$5.00 |
| JOB COUN | IT: 3 | | | | wo | RK ORI | DER TOTAL | .: 0.49 | 58 | .37 | 111.43 | 5.00 | 174.80 |
| Job Code | | Job Descriptio | on | | V | endor N | <u>0.</u> | Invoice No. | Purcha | se Order N | <u>o.</u> | | Total Cost |
| CH-SP | CHARGE Sh | nop Supplies | | 5 | 03163 | | 1 | | | | | | \$5.0 |
| | | | | | | | | | | | | COMML | 5.0 |
| Job Code | | Job Description | on | | Em | ployee | <u>No.</u> | <u>Start</u> | ļ | Finish | | Quantity | Total Cost |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLA | CEMENT | 1 | 1074414 | | 1(| 0/20/2023 09:45:59 | 10/20/202 | 23 09:53:30 | | 0.13 | \$14.7 |
| 66-PM-PMA | PERFORM | DIL CHANGE | | 1 | 1074414 | | 1(| 0/19/2023 14:53:25 | 5 10/19/202 | 23 15:15:35 | | 0.37 | \$43.5 |
| | | | | | | | | | | | | LABOR | 58.3 |
| Job Code | | Job Description | on | | | Part No | <u>.</u> | Des | scription | | Unit Price | Quantity | Total Cost |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | 5089 | | В | RAKE CLEAN NOI | N-FLAMMABLE | 140Z | 10.82 | 2 1 | \$10.8 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | W20BT | | В | ULK OIL 0W20 FS | | | 6.30 |) 6 | \$37.8 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | 0 | 4152-YZ | ZA1 | FI | ILTER-OIL | | | 18.72 | 2 1 | \$18.7 |
| 66-PM-PMC | PERFORM | CABIN FILTER REPLA | CEMENT | Р | C5667 | | C | ABIN FILTER | | | 13.17 | ' 1 | \$13.1 |
| 66-PM-PMA | PERFORM | OIL CHANGE | | Р | A6116F | | D | ODGE DURANGO | AIR FILTER | | 30.92 | 2 1 | \$30.9 |
| | | | | | | | | | | | | PARTS | 111.43 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 48636 |
|---------------------|-------------------------|------------------------|----------------|-------|
| Work Order Note | <u>s</u> | | | |
| (CWIGLEY) PM | | | | |
| Job Notes | | | | |
| 66-PM-PMA - PERFC | ORM OIL CHANGE | | | |
| (SHARBIN) SH/FC Pe | erformed PM. SH | | | |
| 66-PM-PMC - PERFC | | R REPLACEMENT | | |
| (LISAPATE) Replaced | d the cabin & air filte | er. SH | | |
| CH-SP - CHARGE SI | hop Supplies | | | |

The University of Alabama

| UNIT NO: | | 241366 20 | 15 TOYO | | GHLA | NDER | | | WORK ORI | DER NO: | 50969 | |
|---|--------------|--|------------|-------------------------|------------------|-------------|------------|--|--|---------------------|---|-------------------|
| USING DEP WO STATUS WO VISIT R TECH SPEC | S: EASON: | 208185 CLOSED SCHEDULED 15TOYHIGHLAND | | OPENE COMPL CLOSE | ETED I D DATI | DATE: E: | 06/04/202 | 4 09:57:11 4 07:42:33 4 07:42:36 | LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL | 44755 DATE: 06/0 | versity Automotive S METER 2 - N: 02/2015 0ZKRFH6FS083586 | 0 |
| JOB CODE | <u> </u> | JOB DESCRIPTION | | <u>STAT</u> | <u>RSN</u> | WRTY | JOB LOC | LABOR HRS | LABOR | MATERIAL | <u>COMMERCIAL</u> | TOTAL COST |
| CH-SP | CHARGE | E Shop Supplies | | DON | 2 | Ν | GARAGE | 0.00 | \$0.00 | \$0.00 | \$1.97 | \$1.97 |
| PD-00-999 | PREP DI | SPOSE PREPARE UNI | IT FOR DI | DON | D | Ν | GARAGE | 0.02 | \$1.97 | \$0.00 | \$0.00 | \$1.97 |
| JOB COUN | T: 2 | | | | WO | | DER TOTAL: | 0.02 | 1.97 | 7 0.0 | 0 1.97 | 3.94 |
| Job Code | | Job Description | | | V | endor N | 0. | Invoice No. | Purchase | Order No. | | Total Cost |
| CH-SP | CHARGE SH | hop Supplies | | 5 | 03163 | | 1 | | | | | \$1.97 |
| | | | | | | | | | | | COMML | 1.97 |
| Job Code | | Job Description | | | Em | nployee | <u>No.</u> | <u>Start</u> | Fir | <u>nish</u> | <u>Quantity</u> | <u>Total Cost</u> |
| PD-00-999 | PREP DISP | OSE PREPARE UNIT FOR | R DISPOSAI | L 1: | 2395904 | Ļ | 05/ | 31/2024 08:34:40 | 05/31/2024 | 08:35:40 | 0.02 | \$1.97 |
| | | | | | | | | | | | LABOR | 1.97 |

The University of Alabama Report Printed: 06/20/2024 15:06:00 By User: GLOBETTI

| UNIT NO: | 241366 | 2015 TOYOTA HIGHLANDER | WORK ORDER NO: | 50969 |
|------------------|--------|------------------------|----------------|-------|
| Work Order Notes | | | | |

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) perform prepare unit disposal fc

| Report Title: Report Author: | WODETAIL - Work Order Detail v20.0 FleetFocus M5 |
|---------------------------------|--|
| File Path: | E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1 |
| Data Extracted: | Thu Jun 20 2024 15:06:00 Report User: GLOBETTI |
| TZ: | Central Standard Time |
| DLL Version: | 2021.02.23 |
| Report Comments: | 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 Parameters and Selection Filters |
| First Grouping: | VIEW_WO_WORKSHEET.WO_NO |
| Second Grouping: | VIEW JOB WORKSHEET.JOB |
| Third Grouping: | |
| Sorted By: | |
| From Date: | |
| To Date: | |
| Option 1: | |
| Option 2: | |
| Selection Filters: | isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '241366') //Q= |