Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

**LABOR** 

**UNIT NO:** 243854 **2020 TOYOTA CAMRY WORK ORDER NO:** 37787

**USING DEPT NO:** 507143 **OPENED DATE:** 09/28/2020 08:13:07 **LOCATION:** GARAGE - University Automotive Services

**CLOSED** 09/28/2020 08:14:10 **WO STATUS: COMPLETED DATE: METER 2 - N**: 0 **METER 1 - M**: 54

**WO VISIT REASON: SCHEDULED CLOSED DATE: IN-SERVICE DATE:** 09/25/2020

2020 Toyota Camry **UNIT SERIAL NO: TECH SPEC NO:** 20TOYOTACAMRY 4T1C11AK9LU986363

JOB CODE	JOB DESCRIPTION	STAT	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<u>MATERIAL</u>	COMMERCIAL	TOTAL COST
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	С	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUN	T: 1		WO	RK ORI	DER TOTAL:	0.50	0.0	0.00	0.00	0.00
Job Code	Job Description		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPEC	CTION 1	0208562	2	09/	28/2020 08:13:33	09/28/2020	08:43:33	0.50	\$0.00

09/28/2020 10:11:27

0.00

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 37787

**Work Order Notes** 

(LISAPATE) New unit do PDI

**Job Notes** 

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

**UNIT NO:** 243854 **2020 TOYOTA CAMRY WORK ORDER NO:** 38642 **USING DEPT NO:** 507143 **OPENED DATE:** 12/14/2020 08:14:18 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 12/14/2020 15:48:39 **WO STATUS:** COMPLETED DATE: **METER 1 - M**: 187 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 12/15/2020 07:56:14 **IN-SERVICE DATE:** 09/25/2020 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK9LU986363 COMMERCIAL TOTAL COST JOB CODE STAT RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION 66-PM-PMA PERFORM OIL CHANGE DON Ρ **GARAGE** 0.17 \$19.47 \$0.00 \$0.00 \$19.47 JOB COUNT: 1 WORK ORDER TOTAL: 0.17 19.47 0.00 0.00 19.47 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 12/14/2020 14:42:41 12/14/2020 14:52:35 0.17 \$19.47 LABOR 19.47

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 38642

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 187 miles. Updated pm sticker. Checked all fluids and tires. Coolant-34°. JAW MILEAGE-187

UNIT NO:		243854	2020 TOYOTA C	AMRY				WORK ORI	DER NO:	393	335	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	COMPI CLOSE	ED DATE ETED DE ED DATE Camry	DATE:	03/10/202	1 10:22:43 1 07:46:26 1 08:38:11	LOCATION: METER 1 - M: IN-SERVICE DUNIT SERIAL	1403 <b>DATE:</b> 0	ME1 09/25/2020	ΓER 2 - N:	ervices 0
JOB CODE	<del>_</del> '	JOB DESCRIPTIO	N STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.02	<b>LABOR</b> \$1.80	<b>MATERIA</b> \$35.68	AL <u>CO</u> \$0.0	MMERCIAL 0	<b>TOTAL COST</b> \$37.48
JOB COUN	IT: 1			WO	RK ORI	DER TOTAL:	0.02	1.80	0 3	5.68	0.00	37.48
Job Code 66-PM-PMA	PERFORM (	<u>Job Descriptio</u> OIL CHANGE	<del></del>	<u>Em</u> 2052187	ployee		<u><b>Start</b></u> 08/2021 15:27:39		<b>nish</b> 15:28:34		Quantity 0.02 LABOR	Total Cost \$1.80
Job Code		Job Description	<u>on</u>	<u> </u>	Part No	<u>.</u>	Des	cription	<u>Un</u>	it Price	Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE	V	VIX51394		OIL	FILTER			6.50	1	\$6.50
66-PM-PMA	PERFORM (	OIL CHANGE	C	W16T		OIL	. 0W16 CAM2 LSF	PI SN4+ QT		5.84	PARTS 5	\$29.18 <b>35.68</b>

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 39335

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH MILEAGE-1403

UNIT NO:		243854	2020 TOY	OTA C	AMRY	•			WORK O	RDER NO	:	39904		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	Y 2020	OPENE COMPL CLOSE Toyota C	ETED   D DATI	DATE:	05/12/202	1 11:49:32 1 09:35:33 1 07:27:46	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 2468 E DATE:	09/25	rsity Automotive ( <b>METER 2 - N:</b> /2020 11AK9LU986363	0	
JOB CODE		JOB DESCRIPTION	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
03-02-024	REPLAC	E NEW GLASS		DON	0	Ν	GARAGE	0.01	\$1.38	\$0.00		\$264.50	\$265.88	
35-31	DIAGNO	SE CHARGING SYS	STEM	DON	0	Ν	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00	
CH-32-002	CHARGE	BATTERY		DON	0	N	GARAGE	0.15	\$17.70	\$0.00		\$0.00	\$17.70	
JOB COUN	T: 3				wo	RK ORI	DER TOTAL:	0.66	78	3.08	0.00	264.50	١	342.58
Job Code		Job Descripti	<u>on</u>		<u>V</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		<u>Total</u>	Cost
03-02-024	REPLACE N	EW GLASS		1′	078716		288	3042						\$264.50
												COMML		264.50
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	,	<u>Finish</u>		Quantity	<u>Total</u>	Cost
35-31	DIAGNOSE	CHARGING SYSTEM		1′	213180		05/	13/2021 07:00:00	05/13/20	21 07:30:00		0.50		\$59.00
03-02-024	REPLACE N	EW GLASS		12	2052187	•	05/	11/2021 07:32:43	05/11/202	21 07:33:25		0.01		\$1.38
CH-32-002	CHARGE BA	TTERY		12	2052187	•	05/	11/2021 07:32:14	05/11/202	21 07:32:32		(0.01	)	(\$0.59)
CH-32-002	CHARGE BA	TTERY		12	2052187	•	05/	11/2021 07:32:14	05/11/202	21 07:32:32		0.01		\$0.59
CH-32-002	CHARGE BA	TTERY		12	2052187	•	05/	11/2021 07:32:14	05/11/202	21 07:41:14		0.15		\$17.70
												LABOR		78.08

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 39904

### **Work Order Notes**

(LISAPATE) Back glass got broken out by a tree limb during storms. Also battery was dead had to jump off to bring to us

#### **Job Notes**

#### 03-02-024 - REPLACE NEW GLASS

(JWRIGHT) Vacuumed all interior to remove any broken glass after the new glass was installed. (LISAPATE) Glass Dr installed new back glass. Pd by CC

#### 35-31 - DIAGNOSE CHARGING SYSTEM

(LISAPATE) Found dead battery to be caused by light bar randomly coming on. Kevin with UAPD said it likely was the controller having caused this issue. MS

#### CH-32-002 - CHARGE BATTERY

(JWRIGHT) Charged battery. Tested good (LISAPATE)

UNIT NO:	243854 2020	0 TOYOTA CAMRY		WORK ORDER NO:	40060	
USING DEPT NO:	507143	OPENED DATE:	06/01/2021 08:38:23	LOCATION: GARAGE -	University Automotive S	ervices
WO STATUS:	CLOSED	COMPLETED DATE:	06/01/2021 14:35:18	METER 1 - M: 2860	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2021 07:26:08	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK9LU986363	
JOB CODE	JOB DESCRIPTION	STAT RSN WRTY	JOB LOC LABOR HRS	LABOR MATER	IAL COMMERCIAL	TOTAL COST
66-PM-PMA PERF	FORM OIL CHANGE	DON P N	GARAGE 0.22	\$26.12 \$0.00	\$0.00	\$26.12
JOB COUNT: 1		WORK ORD	ER TOTAL: 0.22	26.12	0.00 0.00	26.12
Job Code	Job Description	Employee I	No. Start	<u>Finish</u>	<u>Quantity</u>	Total Cost
66-PM-PMA PERFOR	RM OIL CHANGE	12052187	06/01/2021 08:56:32	06/01/2021 09:09:49	0.22	\$26.12
					LABOR	26.12

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 40060

**Work Order Notes** 

(LISAPATE) PM-check all tires pressures driver added air

**Job Notes** 

### 66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) Unit has only been 1400 miles since last pm. Updated sticker. Checked all fluids and tires. Adjusted tire pressures, they were 15psi over inflated. Coolant -34° JAW MILEAGE-2870

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

243854 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 40388 **USING DEPT NO:** 507143 OPENED DATE: 07/08/2021 09:28:40 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 07/12/2021 14:38:42 COMPLETED DATE: METER 1 - M: 3833 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 07/13/2021 07:19:32 **IN-SERVICE DATE:** 09/25/2020 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK9LU986363 JOB CODE STAT WRTY JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION RSN LABOR 66-17-030 PERFORM TIRE PATCH DON 0 **GARAGE** 0.81 \$95.22 \$103.66 \$8.44 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.81 95.22 8.44 0.00 103.66 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-17-030 PERFORM TIRE PATCH 11901357 07/08/2021 09:36:44 07/08/2021 10:25:09 0.81 \$95.22 **LABOR** 95.22 **Job Code Job Description** Part No. **Unit Price** Quantity Description **Total Cost** 1 66-17-030 23131 3.92 \$3.92 PERFORM TIRE PATCH TPMS SNAP IN VALVE 21060 66-17-030 WHEEL WEIGHT 0.51 \$0.51 PERFORM TIRE PATCH WHEEL WEIGHT KNOCK ON PATCH 1/4 PILOT WIRE 66-17-030 PERFORM TIRE PATCH 14041 4.01 \$4.01 **PARTS** 8.44

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 40388

**Work Order Notes** 

(LISAPATE) Low tire light is on. Found a nail in LR tire

**Job Notes** 

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 3833 Repaired L/R tire, balanced and rechecked for leak, all good. AMG

UNIT NO:		243854	2020 TOY	OTA C	AMRY				WORK (	ORDER NO	): 4	40908		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	⁄ 2020 <sup>-</sup>	OPENE COMPL CLOSE Toyota C	ETED I	DATE:	09/03/20	21 11:48:21 21 08:00:11 21 08:32:23		- M: 5502 CE DATE:	09/25/2	sity Automotive S METER 2 - N: 2020 IAK9LU986363	Services 0	
JOB CODE	Ī	JOB DESCRIPTIO	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL (	COMMERCIAL	TOTAL (	COST
03-51-038	REPLAC	E NEW WIPER BLAI	DES	DON	Р	Ν	GARAGE	0.13	\$15.80	\$17.90	9	80.00	\$33.70	
66-17-015	PERFOR	M TIRE ROTATION		DON	0	Ν	GARAGE	0.06	\$7.01	\$0.00	9	80.00	\$7.01	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.44	\$52.12	\$39.65	\$	80.00	\$91.77	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	\$2.00	\$2.00	
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	.: 0.64	. 7	4.93	57.55	2.00		134.48
Job Code CH-SP	CHARGE St	Job Description op Supplies	<u>on</u>	50	<b>V</b> 03163	endor N	l <b>o.</b> 1	Invoice No.	<u>Purch</u>	ase Order N	<u>o.</u>	COMML	<u>Total (</u>	\$2.00 <b>2.00</b>
Job Code		Job Description	on		Em	ployee	No.	<u>Start</u>		Finish		Quantity	Total 0	Cost
66-17-015	PERFORM	TIRE ROTATION		1	1074414		0:	9/02/2021 07:34:38	09/02/2	021 07:38:12		0.06		\$7.01
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		0	9/01/2021 15:16:42	09/01/2	021 15:21:06		0.07		\$8.65
03-51-038	REPLACE N	EW WIPER BLADES		1	1901357		0	9/01/2021 15:09:01	09/01/2	021 15:17:03		0.13		\$15.80
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		0	9/01/2021 13:45:58	09/01/2	021 14:08:04		0.37		\$43.46
												LABOR		74.92
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	e Quantity	Total C	<u>Cost</u>
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		0	IL 0W16 CAM2 LS	PI SN4+ QT		6.0	08 5		\$30.38
03-51-038	REPLACE N	EW WIPER BLADES		20	6-1		V	/IPER BLADE			10.3	31 1		\$10.31
03-51-038	REPLACE N	EW WIPER BLADES		Т	WB20-1		W	/IPER BLADE 20"			7.5	59 1		\$7.59
66-PM-PMA	PERFORM (	OIL CHANGE		W	/IX51394	1	О	IL FILTER			9.2			\$9.27
												PARTS		57.55

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 40908

**Work Order Notes** 

(LISAPATE) PM-replace wipers

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-015 - PERFORM TIRE ROTATION

(SHARBIN) JW AMG SH Rotated tires and inspected brakes.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5502. SH AMG / SH Performed PM.

UNIT NO:		243854 20	020 TOYOTA C	AMRY	•			WORK OF	DER NO	: 41	743		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED PREVENTIVE MAINT 20TOYOTACAMRY	OPENI COMP T CLOSE 2020 Toyota (	ETED	DATE:	12/02/202	1 14:35:18 1 12:09:04 1 12:09:07	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	l: 7410 <b>DATE</b> :	ME 09/25/202	TER 2 - N:	0	
JOB CODE 66-PM-PMA CH-SP	PERFOR	JOB DESCRIPTION M OIL CHANGE Shop Supplies	<u>STAT</u> DON DON	RSN P 2	WRTY N N	JOB LOC GARAGE GARAGE	0.24 0.00	•	<b>MATE</b> \$38.42 \$0.00	<b>RIAL CC</b> \$0.		<b>TOTAL</b> \$66.41 \$2.00	COST
JOB COUN	IT: 2			wc	RK ORI	DER TOTAL:	0.24	27.	99	38.42	2.00		68.41
Job Code CH-SP	CHARGE Sh	Job Description nop Supplies	-	<u>V</u> 03163	<u>endor N</u>	<b>lo.</b> 1	Invoice No.	<u>Purchas</u>	se Order No	<u>).</u>	COMML	<u>Total</u>	\$2.00
Job Code 66-PM-PMA	PERFORM (	Job Description	-	<u>En</u> 205218	nployee		<u><b>Start</b></u> 01/2021 15:17:25		<u>inish</u> 1 15:31:39		Quantity 0.24	<u>Total</u>	
Job Code 66-PM-PMA	DEDECOPM (	Job Description	=	W16T	Part No	<del>_</del>	<u>Des</u> 0W16 CAM2 LS	scription	<u>l</u>	Jnit Price 5.84	LABOR Quantity 5	<u>Total</u>	27.99 Cost \$29.18
66-PM-PMA		DIL CHANGE		VIX5139	4		_ FILTER	FI 3114† QI		9.24	PARTS		\$9.24 <b>38.42</b>

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 41743

**Work Order Notes** 

(IFALLS) pm

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW MILEAGE-7470

UNIT NO:		243854 20	020 TOYOTA	CAN	ИRY				WORK O	RDER NO	): 4	12521		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	COM	SED	TED D	DATE:	03/02/202	22 07:51:00 22 14:49:29 22 08:07:34	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 9530 E DATE:	<b>N</b> 09/25/2	ity Automotive S IETER 2 - N: 020 AK9LU986363		
JOB CODE		JOB DESCRIPTION	ST.	<u> </u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLAD	ES DC	N	Р	Ν	GARAGE	0.04	\$4.69	\$17.90	\$	60.00	\$22.59	
66-PM-PMA	PERFOR	M OIL CHANGE	DC	N	Р	Ν	GARAGE	0.38	\$45.23	\$39.78	\$	60.00	\$85.01	
CH-SP	CHARGE	Shop Supplies	DC	N	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00	
JOB COUN	IT: 3				WOI	RK ORI	DER TOTAL:	0.42	49	0.92	57.68	2.00		109.60
Job Code		Job Description	<u>1</u>		Ve	endor N	<u>o.</u>	Invoice No.	Purcha	se Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		503	163		1							\$2.00
												COMML		2.00
Job Code		Job Description	<u>1</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1190	01357		03/	/02/2022 08:25:56	03/02/20	22 08:48:56		0.38		\$45.23
03-51-038	REPLACE N	IEW WIPER BLADES		1190	01357		03/	/02/2022 08:23:17	03/02/20	22 08:25:40		0.04		\$4.69
												LABOR		49.92
Job Code		Job Description	<u>1</u>		į	Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0W1	16T		OII	L 0W16 CAM2 LSF	PI SN4+ QT		6.7	2 5		\$33.60
03-51-038	REPLACE N	IEW WIPER BLADES		26-1			WI	PER BLADE			10.3	1 1		\$10.31
03-51-038	REPLACE N	IEW WIPER BLADES		TWE	320-1		WI	PER BLADE 20"			7.5	9 1		\$7.59
66-PM-PMA	PERFORM (	OIL CHANGE		WIX	51394		OII	L FILTER			6.1	81		\$6.18
												PARTS		57.68

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 42521

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 9530 Completed PM topside, Josh was bottomside. Completed checklist. AMG/JW

UNIT NO:		243854	2020 TOY	OTA C	AMRY	•			WORK (	ORDER NO	): 42	2864		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR	Y 2020	OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	04/08/202	22 07:14:01 22 14:06:29 22 07:27:23			ME 09/25/202	TER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL CO	OMMERCIAL	TOTAL	COST
66-17-030	PERFOR	M TIRE PATCH		DON	0	N	GARAGE	0.38	\$44.25	\$7.68	\$0.	.00	\$51.93	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.	.00	\$2.00	
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	: 0.38	4	14.25	7.68	2.00	l	53.93
Job Code		Job Descripti	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purch</u>	nase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descripti	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-030	PERFORM 1	TIRE PATCH		1:	2052187	7	04	/08/2022 08:37:10	04/08/2	022 08:59:40		0.38		\$44.25
												LABOR		44.25
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	<u>Total</u>	Cost
66-17-030	PERFORM 1	TIRE PATCH		14	4041		PA	TCH 1/4 PILOT W	/IRE		3.86	1		\$3.86
66-17-030	PERFORM 1	TIRE PATCH		2	3131		TF	MS SNAP IN VAL	VE 21060		3.82	1		\$3.82
												PARTS		7.68

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 42864

**Work Order Notes** 

(CHANNELL) nail in front passenger side tire

**Job Notes** 

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired right front tire. Aired to spec and reused old weights. JAW

UNIT NO:		243854	2020 TOY	OTA C	AMRY	•			WORK O	RDER NO	): 4	3423		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAM	RY 2020 <sup>-</sup>	OPENE COMPL CLOSE Toyota C	ETED	DATE:	06/01/20	22 08:09:55 22 14:44:51 22 14:59:19	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 11054 E <b>DATE</b> :	<b>M</b> 09/25/20		Services 0	
JOB CODE		JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	ERIAL C	OMMERCIAL	TOTAL C	OST
03-34-004	REPLAC	E NEW CLEARAN	CE/MARKER	DON	0	Ν	GARAGE	0.20	\$23.60	\$0.75	\$0	0.00	\$24.35	
35-34-004	DIAGNO	SE CLEARANCE/I	MARKER	DON	0	N	GARAGE	1.05	\$123.34	\$0.00	\$0	0.00	\$123.34	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.09	\$11.11	\$46.70	\$0	0.00	\$57.81	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	: 1.34	158	.05	47.45	2.00	2	207.50
Job Code CH-SP	CHARGE SI	Job Descrip	<u>tion</u>	5	<u>V</u> 03163	<u>endor N</u>	<b>lo.</b> 1	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total C</u>	ost \$2.00
												COMML	-	2.00
<b>Job Code</b> 03-34-004	REPLACE N	Job Descrip		1	<u>En</u> 1213180	nployee		<u><b>Start</b></u> 5/01/2022 07:00:00	•	Finish 22 07:12:00		Quantity 0.20	<u>Total C</u>	ost \$23.60
66-PM-PMA		OIL CHANGE	, <u>.</u>		2052187			6/01/2022 07:13:16		22 07:18:55		0.09		\$11.11
35-34-004		CLEARANCE/MARK	ER		1213180			5/31/2022 14:30:00		22 14:52:57		0.38		\$45.14
35-34-004	DIAGNOSE	CLEARANCE/MARK	ER	1	1213180	)	05	5/31/2022 13:35:14	05/31/202	22 14:15:00		0.66		\$78.21
												LABOR		158.06
Job Code		Job Descrip	tion			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total C	ost
03-34-004	REPLACE N	IEW CLEARANCE/M	ARKER	1	94		В	JLB-TAG/MARKEF	₹		0.38	3 2		\$0.75
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		O	L 0W16 CAM2 LS	PI SN4+ QT		7.47	7 5		\$37.35
66-PM-PMA	PERFORM (	OIL CHANGE		٧	VIX5139	4	O	L FILTER			9.35	51		\$9.35
												PARTS		47.45

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 43423

**Work Order Notes** 

(EKIMBREL) PM--per driver left front and rear marker lights are out

**Job Notes** 

03-34-004 - REPLACE NEW CLEARANCE/MARKER

(LISAPATE) Found both marker bulbs on driver side of vehicle to be blown. replaced bulbs MS

03-51-038 - REPLACE NEW WIPER BLADES

35-34-004 - DIAGNOSE CLEARANCE/MARKER

(MSIDES) Found both marker bulbs on driver side of vehicle to be blown. MS

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG

MILEAGE-11054

UNIT NO:		243854	2020 TOYO	OTA C	AMRY	7			WORK C	RDER NO	): 4	4306		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	08/19/202	22 14:03:04 22 14:25:01 22 09:06:26		M: 12653 E DATE:	<b>M</b> 09/25/20	ty Automotive ( ETER 2 - N: 020 AK9LU986363		
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL C	OMMERCIAL	TOTAL	COST
06-17	INSPECT	TIRES, TUBES, L	INERS & VAL	DON	0	N	GARAGE	0.10	\$12.13	\$0.00	\$0	0.00	\$12.13	
66-17-013	PERFOR	M ALIGNMENT		DON	0	N	GARAGE	0.51	\$59.69	\$0.00	\$0	0.00	\$59.69	
66-17-028	PERFOR	M MOUNT AND B	ALANCE TIRE	DON	0	N	GARAGE	1.16	\$136.88	\$51.12	\$0	0.00	\$188.00	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	T: 4				WC	RK ORI	DER TOTAL	: 1.77	20	8.70	51.12	2.00		261.82
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purch</u>	ase Order N	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-013	PERFORM A	ALIGNMENT		1	1310047	,	08	/18/2022 09:10:56	08/18/20	)22 09:41:17		0.51		\$59.69
06-17	INSPECT TI	RES, TUBES, LINER	S & VALVES	1	2052187	7	08	/17/2022 09:45:09	08/17/20	022 09:51:19		0.10		\$12.13
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	1	2052187	7	08	/17/2022 08:35:33	08/17/20	022 09:45:09		1.16		\$136.88
												LABOR		208.70
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	6	3001		1/4	4 OZ STICK ON TA	APE WEIGHT		0.17	20		\$3.30
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	2	1372		HA	AMATON VALVE S	STEM TOYOTA	١	11.96	4		\$47.82
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	В	110772	4	21	5/55R17 MICH SU	JRVEY TIRES		0.00	4		\$0.00
												PARTS		51.12

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 44306

**Work Order Notes** 

(CWIGLEY) Check all 4 tires, per driver.

**Job Notes** 

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) found all tires worn

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed 4wheel alignment. Relearned steering angle sensor. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) replaced all 4 tires and balanced. aired to spec and torqued lug nuts to spec. installed survey tires in order of LF-9 RF-10 LR-11 RR-12 JAW

UNIT NO:		243854 20	020 TOYOTA C	AMRY	,			WORK ORDER	NO:	44419	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	СОМР	ED DAT LETED ED DAT Camry	DATE:	08/23/202	2 15:48:55 2 15:12:55 2 07:28:48	LOCATION: GAR METER 1 - M: 12 IN-SERVICE DATE UNIT SERIAL NO:	726 : 09/25	ersity Automotive S <b>METER 2 - N:</b> 5/2020 C11AK9LU986363	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u> <u>N</u>	<u>IATERIAL</u>	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.21	\$24.55 \$0.	00	\$0.00	\$24.55
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00 \$0.	00	\$5.00	\$5.00
JOB COUN	T: 2			wc	RK ORI	DER TOTAL:	0.21	24.55	0.00	5.00	29.55
Job Code		Job Description	<u>!</u>	<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchase Ord	er No.		Total Cost
CH-SP	CHARGE Sh	nop Supplies		503163		1					\$5.00
										COMML	5.00
Job Code		Job Description	1	<u>En</u>	nployee	No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1205218	7	08/2	23/2022 07:24:07	08/23/2022 07:36	:36	0.21	\$24.55
										LABOR	24.55

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 44419

**Work Order Notes** 

(CWIGLEY) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1300 miles. Checked fluids and tires. Coolant -34°. JAW MILEAGE-12726

UNIT NO:		243854	2020 TOY	OTA C	<b>AMRY</b>	•			WORK O	RDER NO	): 4	<b>45162</b>		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR		OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	11/08/20	22 09:20:25 22 07:12:10 22 11:24:05	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 13454 E DATE:	N 09/25/2	sity Automotive s METER 2 - N: 2020 1AK9LU986363	Services 0	
JOB CODE	1	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.40	\$46.81	\$41.45	\$	00.00	\$88.26	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.42	\$49.82	\$20.52	\$	00.00	\$70.34	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	9	\$5.00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL	: 0.82	96	5.63	61.97	5.00		163.60
Job Code		Job Descript	ion_		V	endor N	<u>o.</u>	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	1	1074414		11	/03/2022 10:26:59	11/03/20	22 10:52:19		0.42		\$49.82
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		11	/03/2022 10:02:59	11/03/20	22 10:26:47		0.40		\$46.81
												LABOR		96.63
Job Code		Job Descript	<u>ion</u>			Part No		Des	cription		Unit Price	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		0	IL 0W16 CAM2 LSI	PI SN4+ QT		7.0	)2 5		\$35.10
66-PM-PMA	PERFORM (	OIL CHANGE		W	/IX5139	4	0	IL FILTER			6.3	35 1		\$6.35
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	Р	C99237	С	C	ABIN FILTER 2020	CAMRY		20.5	521		\$20.52
												PARTS		61.97

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 45162

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

UNIT NO:		243854	2020 TOYO	OTA C	AMRY	•			WORK OR	DER NO	: 46	022	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE oyota C	ETED	DATE:	02/03/20	23 13:04:14 23 11:18:55 23 09:02:03	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 14629 <b>DATE</b> :	ME 09/25/202	TER 2 - N:	Services 0
JOB CODE		JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	N	GARAGE	0.02	\$2.39	\$23.26	\$0.	00	\$25.65
66-17-033	PERFOR	M TIRE ROTATION	N AND BRAKE	DON	Р	Ν	GARAGE	0.12	\$13.67	\$0.00	\$0.	00	\$13.67
66-79-003	PERFOR	M SAFETY INSPE	CTION	DON	Υ	Ν	GARAGE	0.33	\$38.87	\$0.00	\$0.	00	\$38.87
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.16	\$19.31	\$13.11	\$0.	00	\$32.42
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00
JOB COUN	JOB COUNT: 5			WORK ORDE			ER TOTAL	: 0.63	74.24		36.37	5.00	115.61
Job Code		Job Descript	tion		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order No	<u>o.</u>		Total Cost
CH-SP	CHARGE SI	op Supplies		5	03163		1						\$5.00
												COMML	5.00
Job Code		Job Descript	tion_		<u>En</u>	ployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		<b>Quantity</b>	Total Cost
66-17-033	PERFORM	TRE ROTATION AND	BRAKE INSPE	CTION 1	1074414		02	/01/2023 13:50:07	02/01/2023	3 13:57:04		0.12	\$13.67
66-79-003	PERFORM	SAFETY INSPECTION	N	1	1074414		02	/01/2023 13:30:11	02/01/2023	3 13:49:57		0.33	\$38.87
03-51-038	REPLACE N	EW WIPER BLADES		1	1074414		02	/01/2023 13:28:47	02/01/2023	3 13:30:00		0.02	\$2.39
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		02	/01/2023 13:18:47	02/01/2023	3 13:28:36		0.16	\$19.3
												LABOR	74.24
Job Code		Job Descript	tion			Part No		Des	cription	<u>!</u>	Unit Price	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	9260		W	IPER BLADE 26 IN	OE BEAM		12.79	1	\$12.79
03-51-038	REPLACE N	EW WIPER BLADES		1	9200		W	IPER BLADE OE E	BEAM STYLE 20	IN	10.47	1	\$10.4
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		SI	EA FOAM 16OZ			13.11	1	\$13.1
												PARTS	36.37

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 46022

### **Work Order Notes**

(EHANNAH) pm- replacer wipers - perform safety inspections.

#### **Job Notes**

#### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

#### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected the brakes. Found no issues at this time. SH

### 66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

(SHARBIN) Front pads 9MM thick and the rear pads are 7 MM thick. SH

#### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1223 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

UNIT NO:		243854	2020 TOY	OTA C	AMRY	•			WORK OF	RDER NO:	46	6954		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR	Y 2020 1	OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	05/05/20	23 12:59:51 23 13:43:20 23 15:39:44	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 16579 E DATE:	<b>ME</b> 09/25/20	y Automotive S ETER 2 - N: 20 AK9LU986363	Services 0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CO	OMMERCIAL	TOTAL	COST
66-17-033	PERFOR	M TIRE ROTATION	AND BRAKE	DON	Р	N	GARAGE	0.28	\$32.97	\$0.00	\$0	0.00	\$32.97	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.15	\$17.21	\$41.36	\$0	0.00	\$58.57	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	T: 3				wo	RK ORI	DER TOTAL	: 0.43	50	.18	41.36	5.00		96.54
Job Code		Job Descripti	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchas	se Order No	<u>.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	nployee	No.	<u>Start</u>	<u> </u>	- - - - -		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		05	5/04/2023 14:13:04	05/04/202	23 14:15:00		0.03		\$3.80
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		05	5/04/2023 14:30:00	05/04/202	23 14:36:49		0.11		\$13.41
66-17-033	PERFORM 1	TIRE ROTATION AND	BRAKE INSPE	CTION 1	1074414	ļ	05	5/04/2023 14:37:00	05/04/202	23 14:53:46		0.28		\$32.97
												LABOR		50.18
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	scription	<u>u</u>	Init Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		0	L 0W16 CAM2 LS	PI SN4+ QT		7.11	5		\$35.55
66-PM-PMA	PERFORM (	OIL CHANGE		٧	VIX51394	4	0	IL FILTER			5.81	1		\$5.81
												PARTS		41.36

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 46954

**Work Order Notes** 

(EHANNAH) pm- replace wipers-

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

**CH-SP - CHARGE Shop Supplies** 

**WA-00 - WASH COMPLETE VEHICLE** 

UNIT NO:		243854 20	20 TOY	OTA C	AMRY	7			WORK OR	DER NO	47	697		
USING DEP WO STATUS WO VISIT R TECH SPEC	507143 CLOSED SCHEDULED 20TOYOTACAMRY	OPENED DATE: COMPLETED DAT CLOSED DATE: 2020 Toyota Camry			DATE:	07/25/20	23 12:31:39 23 14:36:29 23 14:36:32	LOCATION: GARAGE METER 1 - M: 18285 IN-SERVICE DATE: UNIT SERIAL NO:		<b>ME</b> 09/25/202	TER 2 - N:			
JOB CODE		JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		DON	N	N	GARAGE	0.41	\$48.45	\$146.72	\$0.0	00	\$195.17	
03-51-038	REPLAC	E NEW WIPER BLADE	S	DON	Р	Ν	GARAGE	0.05	\$6.26	\$24.08	\$0.0	00	\$30.34	
35-32	DIAGNO	SE CRANKING SYSTE	М	DON	0	Ν	GARAGE	0.23	\$27.47	\$0.00	\$0.0	00	\$27.47	
66-17-033	PERFOR	M TIRE ROTATION AN	D BRAKE	DON	Р	Ν	GARAGE	0.28	\$33.01	\$0.00	\$0.0	00	\$33.01	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.38	\$44.74	\$49.73	\$0.0	00	\$94.47	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00	
JOB COUN	IT: 6				WC	RK ORI	DER TOTAL	: 1.36	159.9	93	220.53	5.00		385.46
Job Code CH-SP	CHARGE SI	Job Description		5	<u>\</u> 03163	<u>endor N</u>	l <b>o.</b> 1	Invoice No.	<u>Purchas</u>	e Order No	<u>.</u>		<u>Total</u>	\$5.00
												COMML		5.00
Job Code		Job Description				<u>nployee</u>		<u>Start</u>		<u>inish</u>		Quantity	<u>Total</u>	
66-17-033		FIRE ROTATION AND BRA	KE INSPE					7/24/2023 11:35:39				0.28		\$33.01
03-32-002		IEW BATTERY			205218			7/24/2023 08:49:58				0.41		\$48.45
35-32	DIAGNOSE	CRANKING SYSTEM		1	205218	7	07	7/24/2023 07:39:39	07/24/2023	3 07:53:37		0.23		\$27.47
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414	ļ.	07	7/24/2023 11:09:43	07/24/2023	3 11:32:28		0.38		\$44.74
03-51-038	REPLACE N	IEW WIPER BLADES		1	1074414	ļ	07	7/24/2023 11:32:28	07/24/2023	3 11:35:39		0.05		\$6.26
												LABOR		159.93
Job Code		<b>Job Description</b>				Part No	<u>.</u>	Des	cription	<u>L</u>	<u> Init Price</u>	Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	IEW BATTERY		4	7H5		В	ATTERY			146.72	1		\$146.72
03-51-038	REPLACE N	IEW WIPER BLADES		1	9260		W	IPER BLADE 26 IN	N OE BEAM		13.23	1		\$13.23
66-PM-PMA	PERFORM	OIL CHANGE		C	W16T		0	L 0W16 CAM2 LS	PI SN4+ QT		8.79	5		\$43.95
03-51-038	REPLACE N	IEW WIPER BLADES		1	9200		W	IPER BLADE OE E	BEAM STYLE 20	IN	10.85	1		\$10.85
66-PM-PMA	PERFORM	OIL CHANGE		V	VIX5139	4	0	IL FILTER			5.78	1		\$5.78
												PARTS		220.53

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 47697

### **Work Order Notes**

(EHANNAH) Diagnose cranking system

#### **Job Notes**

#### 03-32-002 - REPLACE NEW BATTERY

(GARAGE) Replaced battery with new. Alternator charging at 13.8 volts. JAW

#### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

#### 35-32 - DIAGNOSE CRANKING SYSTEM

(GARAGE) checked and unit was starting no issues after sitting over the weekend. Tested battery and it tested full charge but a weak cell. Battery is 3 years old needs replaced. JAW

#### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Cross rotated the tires and inspected the brakes. Found no issues at this time. SH

#### 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) The job was restored for Work Order# 47697. By User ID EKIMBREL on 7/24/2023 9:13 AM. (GARAGE) Performed PM. SH

UNIT NO:		243854	2020 TOYO	OTA C	AMRY	7			WORK	ORDER NO:		47804	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPI CLOSE Toyota C	LETED ED DAT	DATE:	08/23/202	23 09:20:15 23 10:03:02 23 12:15:46	METER IN-SER\	ON: GARAGE - 1 - M: 18652 /ICE DATE: ERIAL NO:	09/25/	METER 2 - N:	Services 0
JOB CODE	<u>.</u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LAB	OR MATER	RIAL	COMMERCIAL	TOTAL COST
15-05	WARRAN	ITY ELECTRONIC	ENGINE EEC	DON	W	J	GARAGE	0.00	\$0.00	\$0.00		\$0.00	\$0.00
16-05	TRANSP	ORT ELECTRONIC	C ENGINE EE	DON	0	N	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00
35-32	DIAGNO	SE CRANKING SY	STEM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00		\$0.00	\$0.00
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00
JOB COUN	T: 4				WC	RK ORI	DER TOTAL:	0.50	ı	59.00	0.00	5.00	64.00
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Pur</u>	chase Order No	<u>.</u>		Total Cost
15-05	WARRANTY	ELECTRONIC ENG	INE EEC SYSTE	EM 1	1076422	2	62	14289					\$0.00
CH-SP	CHARGE Sh	op Supplies		5	03163		1						\$5.00
												COMML	5.00
Job Code		Job Descrip	tion		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
16-05	TRANSPOR	T ELECTRONIC EN	GINE EEC SYSTI	EM 1	1399745	5	08/	/23/2023 07:00:00	08/23	3/2023 07:30:00		0.50	\$59.00
												LABOR	59.00

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 47804

**Work Order Notes** 

(LISAPATE) Per driver unit is hesitating to start. Battery was just replaced in July

**Job Notes** 

15-05 - WARRANTY ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Toyota found poor programming in software. Update software. rechecked ok

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Taken to Toyota by CW

35-32 - DIAGNOSE CRANKING SYSTEM

(LISAPATE) Unit has charging issue take to Toyota for warranty repair

UNIT NO:		243854 2	020 TOY	OTA C	AMRY	7			WORK	ORDER NO	:	48010		
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	08/31/202	3 12:57:17 3 13:44:58 3 14:50:32	METER IN-SER	ON: GARAGE 1-M: 18652 VICE DATE: ERIAL NO:	09/25/2	METER 2 - N:	0	
JOB CODE	<u>E</u>	JOB DESCRIPTION	<u></u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LAB	OR MATE	RIAL	COMMERCIAL	TOTAL	COST
06-13	INSPECT	BRAKES		DON	0	N	GARAGE	0.48	\$56.74	\$0.00		\$0.00	\$56.74	
06-17	INSPECT	TIRES, TUBES, LINI	ERS & VAL	DON	0	N	GARAGE	0.20	\$23.60	\$0.00		\$0.00	\$23.60	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
JOB COUN	NT: 3				WC	RK ORI	DER TOTAL:	0.68		80.34	0.00	5.00		85.34
Job Code		Job Description	<u>1</u>		<u>v</u>	endor N	lo.	Invoice No.	<u>Pur</u>	chase Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>1</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
06-13	INSPECT BE	RAKES		1:	2201267	7	08/	31/2023 08:50:37	08/3	1/2023 09:15:00		0.41		\$47.95
06-13	INSPECT BE	RAKES		1:	2201267	7	08/	31/2023 09:30:00	08/3	1/2023 09:34:28		0.07		\$8.78
06-17	INSPECT TI	RES, TUBES, LINERS &	VALVES	1:	2201267	7	08/	31/2023 09:15:00	08/3	1/2023 09:27:00		0.20		\$23.60
														80.33

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 48010

**Work Order Notes** 

(EHANNAH) nail is DR tire- inspect brakes

### **Job Notes**

#### 06-13 - INSPECT BRAKES

(GRCOOK) Inspected brakes-GC, found no issues, also had JW look at brake also for a second opinion, found no issues.

Took on a test drive and test drove fine with no issues with brakes.-GC

Brake pads are all 10mm on front and rear wheels.-GC

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) GC checked tire. Nail did not puncture tire

UNIT NO:		243854	2020 TOYO	OTA C	AMRY	•			WORK OF	RDER NO	: 48	8079		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR		OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	09/07/202	23 08:23:26 23 15:21:43 23 11:05:17	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 18840 DATE:	<b>ME</b> 09/25/202		Services 0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
06-17	INSPECT	TIRES, TUBES, L	INERS & VAL	DON	0	Ν	GARAGE	0.17	\$20.36	\$0.00	\$0.	.00	\$20.36	
66-17-028	PERFOR	M MOUNT AND BA	ALANCE TIRE	DON	N	Ν	GARAGE	0.30	\$35.14	\$260.27	\$0.	.00	\$295.41	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.47	55.	50	260.27	5.00		320.77
Job Code CH-SP	CHARGE SI	Job Descript	<u>ion</u>	5	<u>V</u> 03163	endor N	<b>o.</b> 1	Invoice No.	Purchas	se Order No	<u>o.</u>		<u>Total</u>	Cost \$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	1	1310047	•	09	/06/2023 07:01:33	09/06/202	3 07:19:25		0.30		\$35.14
06-17	INSPECT TI	RES, TUBES, LINERS	S & VALVES	1	1074414		09	/05/2023 08:31:15	09/05/202	3 08:41:36		0.17		\$20.36
												LABOR		55.50
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u> </u>	Unit Price	Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	6	3001		1/4	4 OZ STICK ON TA	APE WEIGHT		0.26	9		\$2.30
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	2	3131		TF	MS SNAP IN VAL	VE 21060		3.87	1		\$3.87
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	2	6370		TII	RE 215/55R17 MIC	CH PRIMACY		254.10	1		\$254.10
												PARTS		260.27

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 48079

**Work Order Notes** 

(LISAPATE) screw in tire

### **Job Notes**

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Inspected the tire. Found a screw next to the sidewall. Can not be patched. SH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced one new tire. Placed the new tire on the left front. EH

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

243854 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 48767 **USING DEPT NO:** 507143 **OPENED DATE:** 10/31/2023 07:29:21 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 11/01/2023 10:21:20 **WO STATUS:** COMPLETED DATE: METER 1 - M: 20440 METER 2 - N: WO VISIT REASON: **SCHEDULED CLOSED DATE:** 11/01/2023 13:12:38 **IN-SERVICE DATE:** 09/25/2020 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK9LU986363 JOB CODE WRTY **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT RSN **JOB LOC** LABOR HRS **LABOR** 06-17 DON Ν **GARAGE** 0.02 \$2.88 \$0.00 \$2.88 INSPECT TIRES, TUBES, LINERS & VAL' \$0.00 CH-SP CHARGE Shop Supplies DON Ν **GARAGE** 0.00 \$0.00 \$0.00 \$3.32 \$3.32 JOB COUNT: 2 WORK ORDER TOTAL: 0.02 2.88 0.00 3.32 6.20 **Job Code Job Description** Vendor No. Invoice No. Purchase Order No. **Total Cost** 503163 CH-SP **CHARGE Shop Supplies** 1 \$3.32 CH-SP 1 **CHARGE Shop Supplies** 503163 (\$3.32)CH-SP **CHARGE Shop Supplies** 503163 1 \$3.32 CH-SP **CHARGE Shop Supplies** 503163 (\$3.32)1 CH-SP \$3.32 **CHARGE Shop Supplies** 503163 CH-SP **CHARGE Shop Supplies** 503163 (\$2.88)1 CH-SP \$2.88 **CHARGE Shop Supplies** 503163 1 COMML 3.32 **Job Code** Job Description Employee No. **Total Cost** Start Finish Quantity 06-17 INSPECT TIRES, TUBES, LINERS & VALVES 12395904 10/31/2023 07:45:49 10/31/2023 07:47:17 0.02 \$2.88 06-17 12395904 10/31/2023 07:45:49 0.02 \$2.88 INSPECT TIRES, TUBES, LINERS & VALVES 10/31/2023 07:47:17 06-17 12395904 INSPECT TIRES, TUBES, LINERS & VALVES 10/31/2023 07:45:49 10/31/2023 07:47:17 (0.02)(\$2.88)LABOR 2.88

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

243854 **2020 TOYOTA CAMRY WORK ORDER NO: UNIT NO:** 48767

### **Work Order Notes**

(EHANNAH) low pressure light is on, they just want it check out to see if it's the weather or something else.

#### **Job Notes**

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(FCONTRER) Low pressure fc (LISAPATE) checked. reset ok FC (LRUSHING) Visit Reason Changed On 11/1/2023 3:46 PM By LRUSHING

### **CH-SP - CHARGE Shop Supplies**

(LRUSHING) Visit Reason Changed On 11/1/2023 3:46 PM By LRUSHING (LRUSHING) Visit Reason Changed On 11/1/2023 3:47 PM By LRUSHING (LRUSHING) Visit Reason Changed On 11/1/2023 3:48 PM By LRUSHING

UNIT NO:		243854	2020 TOY	OTA C	AMRY	7			WORK OR	DER NO	: 48	8861		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR	Y 2020	OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	11/10/20	23 07:42:22 23 11:40:48 23 13:23:27	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 20737 <b>DATE</b> :	<b>MI</b> 09/25/20	y Automotive S ETER 2 - N: 20 AK9LU986363	Services 0	
JOB CODE	<del>_</del>	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.33	\$38.94	\$49.88	\$0	0.00	\$88.82	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	: 0.33	38.9	94	49.88	5.00		93.82
Job Code		Job Descripti	<u>ion</u>		<u>v</u>	<u>endor N</u>	<u>lo.</u>	Invoice No.	<u>Purchas</u>	e Order No	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>ion</u>		En	nployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1:	2395904	4	11	/10/2023 07:00:00	11/10/2023	3 07:19:48		0.33		\$38.94
												LABOR		38.94
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u> </u>	Unit Price	Quantity	Total	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		0	L 0W16 CAM2 LS	PI SN4+ QT		8.49	5		\$42.45
66-PM-PMA	PERFORM (	OIL CHANGE		W	/IX5139	4	0	IL FILTER			7.43	1		\$7.43
												PARTS		49.88

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 48861

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

UNIT NO:		243854 2	020 TOYOTA C	AMRY	•			WORK ORDER N	<b>O</b> :	49247	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	COMP	ED DAT LETED ED DAT Camry	DATE:	12/18/202	3 11:30:25 3 10:00:52 3 11:17:31	METER 1 - M: 2164 IN-SERVICE DATE: UNIT SERIAL NO:	8 09/25	rsity Automotive S <b>METER 2 - N:</b> /2020 11AK9LU986363	Services 0
JOB CODE		JOB DESCRIPTION	STAT	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR MA	<u> </u>	COMMERCIAL	TOTAL COST
14-17-030	INSTALL	TIRE PATCH	DON	В	N	GARAGE	0.12	\$13.80 \$0.00		\$0.00	\$13.80
CH-SP	CHARGE	E Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00 \$0.00		\$5.00	\$5.00
JOB COUN	T: 2			wc	RK ORI	DER TOTAL:	0.12	13.80	0.00	5.00	18.80
Job Code		Job Description	<u>1</u>	<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchase Order	No.		Total Cost
CH-SP	CHARGE S	hop Supplies		503163		1					\$5.00
										COMML	5.00
Job Code		Job Description	<u> </u>	<u>En</u>	nployee	No.	<u>Start</u>	<u>Finish</u>		<u>Quantity</u>	Total Cost
14-17-030	INSTALL TIE	RE PATCH		11310047	7	12/	13/2023 15:00:46	12/13/2023 15:07:47		0.12	\$13.80
										LABOR	13.80

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 49247

**Work Order Notes** 

(LRUSHING) nail in tire please repair

**Job Notes** 

14-17-030 - INSTALL TIRE PATCH

(EHOWELL) The left rear tire pressure was low. Removed the tire from the vehicle, sprayed it down with red thunder, and checked it for leaks. No leaks and no nails were found. EH/SH/FC

UNIT NO:		243854	2020 TOY	OTA C	AMRY	7			WORK O	RDER NO	): 4	19438		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR	Y 2020	OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	01/11/2	024 10:44:23 024 08:22:15 024 08:42:45	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 22297 E DATE:	<b>N</b> 09/25/2	ity Automotive 9 METER 2 - N: 1020 IAK9LU986363	Services 0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LO	C LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL	COST
66-17-030	PERFOR	M TIRE PATCH		DON	N	N	GARAGE	0.50	\$58.61	\$18.06	\$	60.00	\$76.67	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00	
JOB COUN	T: 2				WC	RK ORI	DER TOTA	L: 0.50	0 58	3.61	18.06	5.00		81.67
Job Code		Job Descripti	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		•	1						\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>on</u>		En	nployee	No.	<u>Start</u>		Finish		Quantity	<u>Total</u>	Cost
66-17-030	PERFORM	TIRE PATCH		1	1074414	ļ	(	01/10/2024 10:48:34	4 01/10/20	24 11:18:22		0.50		\$58.61
												LABOR		58.61
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	<u>De</u> :	scription_		Unit Price	e Quantity	<u>Total</u>	Cost
66-17-030	PERFORM	TIRE PATCH		6	3001			1/4 OZ STICK ON T	APE WEIGHT		0.2	20 4		\$0.78
66-17-030	PERFORM	TIRE PATCH		1	4041		F	PATCH 1/4 PILOT V	VIRE		5.4	6 1		\$5.46
66-17-030	PERFORM	TIRE PATCH		2	1372		ŀ	HAMATON VALVE	STEM TOYOTA		11.8	321		\$11.82
												PARTS		18.06

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 49438

**Work Order Notes** 

(EHANNAH) tire patch

**Job Notes** 

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched the left rear tire. SH

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

7.43

0.20

3.62

194.25

21

**PARTS** 

UNIT NO:		243854 2	020 TOY	OTA C	AMRY	•			WORK O	RDER NO	): 4	9537		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	01/31/202	24 09:42:33 24 10:55:30 24 14:33:12	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 22592 E DATE:	<b>M</b> 09/25/20	ty Automotive S ETER 2 - N: 020 AK9LU986363	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	•	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	ERIAL C	OMMERCIAL	TOTAL	COST
06-15	INSPECT	STEERING		DON	Ν	N	GARAGE	0.25	\$29.50	\$0.00	\$0	0.00	\$29.50	
66-17-013	PERFOR	M ALIGNMENT		DON	Ν	Ν	GARAGE	0.44	\$51.76	\$0.00	\$0	0.00	\$51.76	
66-17-028	PERFOR	M MOUNT AND BALA	NCE TIRE	DON	N	N	GARAGE	0.58	\$68.44	\$795.56	\$0	0.00	\$864.00	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.30	\$34.88	\$44.63	\$0	0.00	\$79.51	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 5				wo	RK ORI	DER TOTAL:	1.56	184	4.58	840.19	5.00	,	1,029.77
Job Code CH-SP	CHARGE Sh	Job Description op Supplies	<u>1</u>	50	<u>V</u> 03163	endor N	l <b>o.</b> 1	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	<u>Cost</u> \$5.00
												COMML		5.00
Job Code		Job Description	<u>1</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM C	OIL CHANGE		12	2395904	ļ	01	/23/2024 11:20:00	01/23/20	24 11:37:44		0.30		\$34.88
06-15	INSPECT ST	EERING		12	2395904	ļ	01	/31/2024 07:00:00	01/31/20	24 07:15:00		0.25		\$29.50
66-17-013	PERFORM A	LIGNMENT		12	2052187	,	01	/25/2024 07:41:58	01/25/20	24 08:08:17		0.44		\$51.76
66-17-028	PERFORM N	OUNT AND BALANCE	TIRES	12	2395904	ļ	01	/24/2024 15:36:39	01/24/20	24 15:38:32		(0.03)	)	(\$3.70)
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	12	2395904	ļ.	01/	/24/2024 15:36:39	01/24/20	24 15:38:32		0.03		\$3.70
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	12	2395904	ļ.	01/	/24/2024 15:36:39	01/24/20	24 16:11:27		0.58		\$68.44
												LABOR		184.58
Job Code		Job Description	1			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total	Cost
66-PM-PMA	PERFORM C	OIL CHANGE		0/	N16T		OII	L 0W16 CAM2 LS	PI SN4+ QT		7.44	ļ 5		\$37.20

OIL FILTER

1/4 OZ STICK ON TAPE WEIGHT

TIRE 215/55R17 UNIROYAL TPAW

TPMS SNAP IN VALVE 21060

PG4476F

63001

23131

28075

PERFORM OIL CHANGE

PERFORM MOUNT AND BALANCE TIRES

PERFORM MOUNT AND BALANCE TIRES

PERFORM MOUNT AND BALANCE TIRES

66-PM-PMA

66-17-028

66-17-028

66-17-028

\$7.43

\$4.10

\$14.46

\$777.00

840.19

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 49537

**Work Order Notes** 

(LISAPATE) PM

### **Job Notes**

06-15 - INSPECT STEERING

(EKIMBREL) fc checked front end

66-17-013 - PERFORM ALIGNMENT

(JWRIGHT) performed alignment. Adjusted toe on all 4 tires and reset steer ahead sensor. Test drove and found no issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) perform replaced 4 new tires and balanced FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Preform oil changes fc

UNIT NO:		243854 20	20 TOY	OTA C	AMRY	•			WORK OR	DER NO:	49894			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	02/23/202	4 08:16:22 4 09:31:29 4 07:10:15	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	DATE: 0	Iniversity Auto <b>METER</b> 9/25/2020 T1C11AK9LU	2 - N:	ervices 0	
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIA	AL COMMI	ERCIAL	TOTAL	COST
14-52-021	INSTALL	GPS SYSTEM		DON	0	Ν	GARAGE	0.14	\$16.55	\$0.00	\$0.00		\$16.55	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00		\$5.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	0.14	16.5	55	0.00	5.00		21.55
Job Code		Job Description			<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order No.			<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
											C	DMML		5.00
Job Code		Job Description			Em	ployee	No.	<u>Start</u>	<u>Fi</u>	inish	<u>Q</u> ı	uantity	Total	Cost
14-52-021	INSTALL GF	S SYSTEM		11	1074414		02/	22/2024 08:37:27	02/22/2024	08:45:52		0.14		\$16.55
											L	ABOR		16.55

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 49894

**Work Order Notes** 

(EHANNAH) install GPS

**Job Notes** 

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U0302240154

UNIT NO:		243854	2020 TOY	OTA C	AMRY	7			WORK C	RDER NO	: 5	0347		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	′ 2020 <sup>-</sup>	OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	03/29/202	24 13:30:41 24 07:32:36 24 08:58:47		<b>M</b> : 24510	<b>M</b> 09/25/20	ity Automotive S IETER 2 - N: D20 AK9LU986363	Services 0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOF</u>	R MATE	RIAL C	OMMERCIAL	TOTAL C	OST
03-51-042	REPLAC	E NEW KEY FOB BA	ATTERY	DON	5	Ν	GARAGE	0.08	\$9.24	\$6.75	\$0	0.00	\$15.99	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$:	5.00	\$5.00	
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL:	0.08		9.24	6.75	5.00		20.99
Job Code		Job Description	<u>on</u>		<u>v</u>	<u>endor N</u>	lo.	Invoice No.	Purch	ase Order No	<u>).</u>		Total C	ost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		<b>Quantity</b>	Total C	ost
03-51-042	REPLACE N	IEW KEY FOB BATTER	RY	1	1074414	1	03/	28/2024 13:39:56	03/28/20	024 13:44:38		0.08		\$9.24
												LABOR		9.24
Job Code		Job Description	on_			Part No	<u>.</u>	Des	cription	<u>.</u>	Unit Price	Quantity	Total C	ost
03-51-042	REPLACE N	IEW KEY FOB BATTER	RY	С	R2032		BU	TTON CELL BAT	TERY 3V		6.75	51		\$6.75
												PARTS		6.75

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 50347

**Work Order Notes** 

(EHANNAH) new key fob battery

**Job Notes** 

03-51-042 - REPLACE NEW KEY FOB BATTERY

(GARAGE) Replaced the key fob battery per customer request. Operating properly. SH

UNIT NO:		243854	2020 TOYO	OTA C	<b>AMRY</b>	•			WORK C	RDER NO	): 5	0430		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR		OPENE COMPL CLOSE oyota C	ETED D DATI	DATE:	04/05/202	24 14:38:08 24 13:34:04 24 14:09:49		M: 24744 E DATE:	<b>N</b> 09/25/20	ity Automotive 9 IETER 2 - N: 020 AK9LU986363	0	
JOB CODE	Ī	JOB DESCRIPTION	<u>NC</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL C	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.01	\$1.44	\$48.68	\$	0.00	\$50.12	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.04	\$4.36	\$22.73	\$	0.00	\$27.09	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL	: 0.05	;	5.80	71.41	5.00		82.21
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purch	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	1:	2395904	ļ	04	/04/2024 15:18:08	04/04/20	)24 15:20:21		0.04		\$4.36
66-PM-PMA	PERFORM (	OIL CHANGE		1:	2395904	ļ	04	/04/2024 15:16:57	04/04/20	)24 15:17:41		0.01		\$1.44
												LABOR		5.80
Job Code		Job Descript	<u>ion</u>			Part No	_	<u>Des</u>	cription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		Р	G4476F		OI	L FILTER			7.4	3 1		\$7.43
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	Р	C99237	С	CA	ABIN FILTER 2020	CAMRY		22.7	3 1		\$22.73
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		OI	L 0W16 CAM2 LS	PI SN4+ QT		8.2	55		\$41.25
												PARTS		71.41

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 50430

**Work Order Notes** 

(LRUSHING) pm

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter EH

UNIT NO:		243854	2020 TOYOT	A CA	MRY	7			WORK OR	DER NO	: 51	1241		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	CC	MPL OSEI	D DAT	DATE:	07/15/20	024 08:54:33 024 08:12:23 024 11:54:32	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	1: 26296 <b>DATE</b> :	<b>ME</b> 09/25/202	y Automotive S ETER 2 - N: 20 AK9LU986363	Services 0	
JOB CODE	<del>_</del> '	JOB DESCRIPTION OIL CHANGE	<del>_</del>	<u>TAT</u> ON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.01	<b>LABOR</b> \$1.02	<b>MATE</b> \$43.79		OMMERCIAL .00	<b>TOTAL</b> \$44.81	COST
CH-SP	CHARGE	Shop Supplies	D	ON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	.: 0.01	1.0	02	43.79	5.00		49.81
Job Code CH-SP	CHARGE SI	Job Description	<u>on</u>	50	<u>V</u> 3163	<u>endor N</u>	<b>lo.</b> 1	Invoice No.	<u>Purchas</u>	e Order No	<u>).</u>		<u>Total</u>	<b>Cost</b> \$5.00
												COMML		5.00
Job Code 66-PM-PMA	PERFORM (	Job Description	<u>on</u>	11	<u>Em</u> 074414	nployee		<u><b>Start</b></u> 6/20/2024 13:23:44		<u>inish</u> 4 13:24:15		Quantity 0.01	<u>Total</u>	\$1.02
Job Code	DEDECOMA	Job Description	<u>on</u>	0)/	MACT	Part No	_		scription	<u>l</u>	Jnit Price	Quantity	<u>Total</u>	1.02 Cost
66-PM-PMA 66-PM-PMA		OIL CHANGE OIL CHANGE			V16T G4476F	:		OIL 0W16 CAM2 LS OIL FILTER	PI SN4+ QT		7.38 6.89	5 1		\$36.90 \$6.89
												PARTS		43.79

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 51241

**Work Order Notes** 

(EHANNAH) pm

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

UNIT NO:	2	243854	2020 TOY	OTA C	AMRY	,			WORK (	ORDER NO:	5192	7	
USING DEPT	'NO: 5	07143		OPENE	ED DAT	E:	08/23/202	4 14:49:07	LOCATIO	N: GARAGE	- University Au	utomotive Se	rvices
WO STATUS:		CLOSED		COMPL	LETED	DATE:	08/28/202	4 14:53:54	METER 1	- <b>м</b> : 26781	METE	R 2 - N:	)
WO VISIT RE	ASON:	SCHEDULED		CLOSE	D DAT	E:	08/29/202	4 08:21:54	IN-SERVI	CE DATE:	09/25/2020		
TECH SPEC	NO: 2	20TOYOTACAMRY	2020	Toyota C	Camry				UNIT SER	IAL NO:	4T1C11AK9I	_U986363	
JOB CODE	<u>,</u>	IOB DESCRIPTIO	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL COMI	MERCIAL	TOTAL COST
25-52-021	REMOVE (	SPS SYSTEM		DON	5	Ν	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0	0.00
PD-00-999	PREP DISF	POSE PREPARE L	NIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0	0.00
JOB COUNT	: 2				WC	RK ORI	DER TOTAL:	0.00		0.00	0.00	0.00	0.0

The University of Alabama

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

UNIT NO: 243854 2020 TOYOTA CAMRY WORK ORDER NO: 51927

**Work Order Notes** 

(EHANNAH) PREP FOR SALE

**Job Notes** 

25-52-021 - REMOVE GPS SYSTEM

(EKIMBREL) rmoved GPS 387u030240154 \

Removed GPS# 87u030240154\RC

(EHOWELL) Visit Reason Changed On 8/28/2024 2:53 PM By EHOWELL

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) rc prepped unit for sale

Report Printed: 09/09/2024 13:51:27 By User: GLOBETTI

### Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Mon Sep 09 2024 13:51:27 Report User: GLOBETTI

TZ: Central Standard Time

**DLL Version:** 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

#### **Parameters and Selection Filters**

First Grouping: VIEW\_WO\_WORKSHEET.WO\_NO
Second Grouping: VIEW\_JOB\_WORKSHEET.JOB

**Third Grouping:** 

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'243854') //Q=