#### The University of Alabama

### Work Order Charge Detail

JOB COUNT: 1

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

11/27/2019

0.00

**IN-SERVICE DATE:** 

0.00

0.50

**UNIT NO:** 243577 **2020 TOYOTA CAMRY WORK ORDER NO:** 35011

**USING DEPT NO:** 507143 **OPENED DATE:** 11/27/2019 10:46:26 **LOCATION:** GARAGE - University Automotive Services

**CLOSED WO STATUS:** 12/02/2019 13:05:27 COMPLETED DATE: **METER 1 - M**: 54 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 12/02/2019 13:05:29

WORK ORDER TOTAL:

**TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149

COMMERCIAL TOTAL COST JOB CODE STAT RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE DON С **GARAGE** 0.50 \$0.00 \$0.00 \$0.00 \$0.00

**Job Code Job Description** Employee No. **Start Finish** Quantity **Total Cost** PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE INSPECTION 11170580 11/27/2019 10:47:12 11/27/2019 11:17:12 0.50 \$0.00

> LABOR 0.00

0.00

0.00

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 35011

**Work Order Notes** 

(LISAPATE) New unit do PDI

**Job Notes** 

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

**LABOR** 

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 36293

USING DEPT NO: 507143 OPENED DATE: 05/04/2020 08:00:23 LOCATION: GARAGE - University Automotive Services

**WO STATUS:** CLOSED **COMPLETED DATE:** 05/05/2020 13:39:00 **METER 1 - M:** 1140 **METER 2 - N:** 0

WO VISIT REASON: SCHEDULED CLOSED DATE: 05/06/2020 15:54:19 IN-SERVICE DATE: 11/27/2019

TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry UNIT SERIAL NO: 4T1C11AK2LU893149

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
CL-71-032	CLEANED WATER LEAK INTERIOR/EXT	DON	0	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUN	Т: 1		wo	RK ORI	DER TOTAL:	1.00	0.0	0.00	0.00	0.00
Job Code	Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fii</u>	nish	Quantity	Total Cost
CL-71-032	CLEANED WATER LEAK INTERIOR/EXTERIOR	1	1074414		05/	05/2020 06:00:00	05/05/2020	07:00:00	1.00	\$0.00

0.00

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 36293

**Work Order Notes** 

(IFALLS) Window was left down and water got into the cabin area, dry out inside of car

**Job Notes** 

**CL-71-032 - CLEANED WATER LEAK INTERIOR/EXTERIOR** 

(IFALLS) SH opened all windows and doors, put a fan in the car to dry out water in passenger seat.

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 37124

**USING DEPT NO:** 507143 **OPENED DATE:** 07/15/2020 13:42:08 **LOCATION:** GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 07/15/2020 14:22:30
 METER 1 - M:
 2332
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 07/16/2020 12:53:41
 IN-SERVICE DATE:
 11/27/2019

TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry UNIT SERIAL NO: 4T1C11AK2LU893149

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<u>MATERIAI</u>	L COMMERCIA	L TOTAL COST	
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00	
JOB COUNT	: 1		wo	RK ORI	DER TOTAL:	0.33	0.	.00 0	.00 0.0	0.0	)0

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11915538	07/15/2020 13:54:53	07/15/2020 13:56:04	(0.02)	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11915538	07/15/2020 13:54:53	07/15/2020 13:56:04	0.02	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11915538	07/15/2020 13:54:53	07/15/2020 14:14:41	0.33	\$0.00
					LABOR	0.00

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 37124

**Work Order Notes** 

(LISAPATE) Perform safety check

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Safety check was completed. We did not drop oil at this time. We checked fluids, battery and tire pressures. Updated sticker Coolant -34'

EK/RC

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

243577 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 37775 **USING DEPT NO:** 507143 OPENED DATE: 09/28/2020 07:23:39 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 09/28/2020 09:29:03 COMPLETED DATE: METER 1 - M: 4248 METER 2 - N: **WO VISIT REASON: SCHEDULED** 09/28/2020 09:58:10 **CLOSED DATE: IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 COMMERCIAL TOTAL COST JOB CODE WRTY **MATERIAL** JOB DESCRIPTION STAT RSN JOB LOC LABOR HRS LABOR 31-17 ROTATE TIRES, TUBES, LINERS & VALV DON 0 **GARAGE** 0.36 \$0.00 \$0.00 \$0.00 \$0.00 Ρ 66-PM-PMA PERFORM OIL CHANGE DON **GARAGE** 0.75 \$0.00 \$23.83 \$0.00 \$23.83 JOB COUNT: 2 **WORK ORDER TOTAL:** 1.11 0.00 23.83 0.00 23.83 **Job Code Job Description** Employee No. Start **Finish** Quantity **Total Cost** 31-17 ROTATE TIRES, TUBES, LINERS & VALVES 11074414 09/28/2020 08:34:10 09/28/2020 08:55:49 0.36 \$0.00 66-PM-PMA PERFORM OIL CHANGE 11074414 09/28/2020 08:22:13 09/28/2020 08:33:58 0.20 \$0.00 66-PM-PMA PERFORM OIL CHANGE 11074414 09/28/2020 07:37:19 09/28/2020 08:10:45 0.56 \$0.00 **LABOR** 0.00 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE WIX51394 OIL FILTER 4.33 \$4.33 66-PM-PMA PERFORM OIL CHANGE 0W16T OIL 0W16 CAM2 LSPI SN4+ QT 3.90 \$19.50 **PARTS** 23.83

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 37775

**Work Order Notes** 

(LISAPATE) PM

#### **Job Notes**

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(SHARBIN) SH ROTATED TIRES.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH PERFORMED PM

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

243577 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 38694 **USING DEPT NO:** 507143 OPENED DATE: 12/17/2020 13:01:36 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 12/18/2020 07:33:32 COMPLETED DATE: **METER 1 - M:** 7128 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 12/18/2020 11:21:22 **IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 JOB CODE STAT WRTY JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION RSN LABOR 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 0.22 \$26.29 \$61.97 \$35.68 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.22 26.29 35.68 0.00 61.97 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 12/17/2020 15:06:10 12/17/2020 15:19:32 0.22 \$26.29 66-PM-PMA PERFORM OIL CHANGE 12052187 0.00 \$0.00 12/17/2020 14:14:25 12/17/2020 14:14:25 **LABOR** 26.29 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** OIL FILTER 1 \$6.50 66-PM-PMA PERFORM OIL CHANGE WIX51394 6.50 66-PM-PMA OIL 0W16 CAM2 LSPI SN4+ QT 5.84 \$29.18 PERFORM OIL CHANGE 0W16T **PARTS** 35.68

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 38694

**Work Order Notes** 

(EKIMBREL) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW MILEAGE-7128

UNIT NO:		243577 2	2020 TOYOTA	CA	MRY				WORK (	ORDER NO	D: 3	38884	
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	CO	MPLE DSED	DATE TED I DATE mry	DATE:	01/25/202	21 07:08:11 1 12:20:32 21 07:27:49		- M: 8129 CE DATE:	<b>N</b> 11/27/2		0
JOB CODI	<u>E</u>	JOB DESCRIPTION	<u>N</u> ST	<u>AT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MAT	ERIAL (	COMMERCIAL	TOTAL COST
66-17-030	PERFOR	RM TIRE PATCH	DC	N	Ο	Ν	GARAGE	0.35	\$41.17	\$3.51	\$	60.00	\$44.68
66-79-002	PERFOR	RM SERVICE CALL	DC	N	В	N	GARAGE	0.50	\$59.00	\$0.00	\$	60.00	\$59.00
JOB COUN	NT: 2				wo	RK ORI	DER TOTAL:	0.85	10	0.17	3.51	0.00	103.68
Job Code		Job Descriptio	<u>n</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-79-002	PERFORM	SERVICE CALL		102	208562		01/	25/2021 12:19:21	01/25/2	021 12:49:21		0.50	\$59.0
66-17-030	PERFORM	TIRE PATCH		112	213180		01/	25/2021 09:30:00	01/25/2	021 09:50:56		0.35	\$41.1
66-17-030	PERFORM	TIRE PATCH		112	213180		01/	25/2021 09:28:50	01/25/2	021 09:28:50		0.00	\$0.0
												LABOR	100.1
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	e Quantity	Total Cost
66-17-030	PERFORM	TIRE PATCH		140	041		PA <sup>°</sup>	TCH 1/4 PILOT W	'IRE		3.5	511	\$3.5
												PARTS	3.5

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 38884

**Work Order Notes** 

(LISAPATE) Per Sam Camry 10 RF tire is flat and will not hold air.

Parked in lot at the back of Bryce Lawn Apts closest to Campus Dr

#### **Job Notes**

#### 66-17-030 - PERFORM TIRE PATCH

(MSIDES) Repaired tire and rebalanced used one Part# 14041 tire patch, did not use any inventory weights or valve stems. MS

#### 66-79-002 - PERFORM SERVICE CALL

(EKIMBREL) EK/RC installed spare tire on RF and drove to shop

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

243577 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 39250 **USING DEPT NO:** 507143 OPENED DATE: 03/01/2021 14:57:42 **LOCATION:** GARAGE - University Automotive Services **CLOSED** WO STATUS: 03/02/2021 13:46:16 COMPLETED DATE: **METER 1 - M:** 8816 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 03/02/2021 15:41:54 **IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 JOB CODE STAT WRTY **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION RSN JOB LOC LABOR HRS LABOR 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 0.25 \$29.47 \$49.84 \$79.31 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.25 29.47 49.84 0.00 79.31 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 11074414 03/02/2021 09:00:01 03/02/2021 09:15:00 0.25 \$29.47 **LABOR** 29.47 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 1 ANTIFREEZE AP 14.16 \$14.16 66-PM-PMA PERFORM OIL CHANGE ANTIFREEZE-ALL PURPOSE 66-PM-PMA 0W16T OIL 0W16 CAM2 LSPI SN4+ QT 5.84 5 \$29.18 PERFORM OIL CHANGE WIX51394 66-PM-PMA PERFORM OIL CHANGE OIL FILTER 6.50 \$6.50 **PARTS** 49.84

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 39250

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 8816. SH/AMG Performed PM. Did not rotate tires this time tires on the rear wear worn more on the outer edge than the front.SH

UNIT NO:		243577	2020 TOYO	OTA C	AMRY	•			WORK C	RDER NO	D: 4	40026		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE oyota C	ETED D DATI	DATE:	05/28/20	21 07:51:16 21 14:34:40 21 07:55:01		M: 11701 E DATE:	11/27/2	sity Automotive : <b>METER 2 - N:</b> 1019 1AK2LU893149	0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL	COMMERCIAL	TOTAL	COST
06-15	INSPEC <sup>-</sup>	Γ STEERING		DON	0	N	GARAGE	0.43	\$50.22	\$0.00	9	\$0.00	\$50.22	
66-17-013	PERFOR	M ALIGNMENT		DON	0	N	GARAGE	0.66	\$77.75	\$0.00	9	\$0.00	\$77.75	
66-17-028	PERFOR	M MOUNT AND BAL	ANCE TIRE	DON	0	N	GARAGE	0.75	\$88.21	\$643.92	2 9	80.00	\$732.13	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE		\$39.10	\$46.32		80.00	\$85.42	
JOB COUN	T: 4				wo	RK ORI	DER TOTAL	: 2.16	25	5.28	690.24	0.00	ı	945.52
Job Code		Job Description	<u>on</u>		<u>Em</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
06-15	INSPECT S	TEERING		1	1170580		05	5/27/2021 13:46:07	05/27/20	21 14:11:39		0.43		\$50.22
66-17-013	PERFORM A	ALIGNMENT		1	1170580		05	5/27/2021 13:45:44	05/27/20	21 13:46:01		0.00		\$0.56
66-17-013	PERFORM A	ALIGNMENT		1	1170580		05	5/27/2021 11:17:39	05/27/20	21 11:56:54		0.65		\$77.19
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	1	1170580		05	5/27/2021 10:54:33	05/27/20	21 11:17:16		0.38		\$44.68
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	1	1170580		05	5/27/2021 07:55:53	05/27/20	21 08:18:01		0.37		\$43.53
66-PM-PMA	PERFORM	OIL CHANGE		1	1901357	•	05	5/26/2021 12:44:26	05/26/20	21 13:04:19		0.33		\$39.10
												LABOR		255.28
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	Des	cription		Unit Pric	e Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	1	1711		TI	RE 215/55R17 MIC	CH DEFEND T	+H	156.5	57 4		\$626.28
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	2	3131		TF	PMS SNAP IN VAL	VE 21060		3.9	92 4		\$15.66
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	6	3001		1/-	4 OZ STICK ON TA	APE WEIGHT		0.0	9		\$0.54
66-17-028	PERFORM I	MOUNT AND BALANCI	E TIRES	٧	VHEEL V	VEIGHT	W	HEEL WEIGHT KN	IOCK ON		0.4	18 3		\$1.44
66-PM-PMA	PERFORM	OIL CHANGE		0	W16T		O	L 0W16 CAM2 LSI	PI SN4+ QT		5.8	32 5		\$29.10
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		SI	EA FOAM 16OZ			10.7	71 1		\$10.71
66-PM-PMA	PERFORM	OIL CHANGE		٧	VIX51394	4	O	IL FILTER			6.5	511		\$6.51
												PARTS		690.24

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 40026

**Work Order Notes** 

(LISAPATE) PM

#### **Job Notes**

06-15 - INSPECT STEERING

(ABLACK) AB inspected steering. Checked ok.

66-17-013 - PERFORM ALIGNMENT

(ABLACK) AB performed alignment.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(ABLACK) AB mounted and balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 11701 Completed PM top and bottom side. Completed checklist and vacuumed out vehicle. AMG/AMG

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 40162

USING DEPT NO: 507143 OPENED DATE: 06/14/2021 08:27:04 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 06/15/2021 13:50:09
 METER 1 - M:
 12404
 METER 2 - N:
 0

 WO VISIT REASON:
 UNSCHEDULED
 CLOSED DATE:
 06/17/2021 11:33:46
 IN-SERVICE DATE:
 11/27/2019

TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry UNIT SERIAL NO: 4T1C11AK2LU893149

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<b>MATERIAL</b>	COMMERCIAL	<b>TOTAL COST</b>
01-02-031	ADJUST EXTERIOR BODY MOLDINGS	DON	0	N	GARAGE	0.57	\$67.72	\$0.00	\$0.00	\$67.72
JOB COUNT	: 1		WC	RK ORI	DER TOTAL:	0.57	67.7	72 0.00	0.00	67.72
Job Code	Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>F</u> i	<u>nish</u>	Quantity	Total Cost

Job Code	<b>Job Description</b>	Employee No.	<u>Start</u>	<u>Finish</u>	<b>Quantity</b>	<b>Total Cost</b>
01-02-031	ADJUST EXTERIOR BODY MOLDINGS	11310047	06/14/2021 10:34:59	06/14/2021 10:35:11	0.00	\$0.39
01-02-031	ADJUST EXTERIOR BODY MOLDINGS	11310047	06/14/2021 09:30:00	06/14/2021 09:45:22	0.26	\$30.22
01-02-031	ADJUST EXTERIOR BODY MOLDINGS	11310047	06/14/2021 08:56:08	06/14/2021 09:15:00	0.31	\$37.10
					LABOR	67.71

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

The University of Alabama

243577 **2020 TOYOTA CAMRY WORK ORDER NO: UNIT NO:** 40162

#### **Work Order Notes**

(CHANNELL) adjust exterior molding

(CHANNELL) right lower rocker at front fender

#### **Job Notes**

#### 01-02-031 - ADJUST EXTERIOR BODY MOLDINGS

(EHOWELL) Removed right front tire and fender liner to inspect for damage. The right front fender is not flush with the front facia and right front door. Something has previously damaged the front facia due to impact. This is likely the cause of the customer's concern. EH (IFALLS) Andrew quoted price to repair waiting on department to approve.

UNIT NO:		243577	2020 TOYO	OTA C	AMRY				WORK (	ORDER NO	): 4	40646	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMI		COMPL	ED DATI ETED I ED DATI Camry	DATE:	08/09/20	021 09:06:02 021 11:40:25 021 15:16:30		- M: 14442 CE DATE:	11/27/2		0
JOB CODE	<u> </u>	JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MAT	ERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	Ν	GARAGE	0.15	\$17.70	\$17.77	5	80.00	\$35.47
66-17-033	PERFOR	RM TIRE ROTATIO	N AND BRAKE	DON	0	N	GARAGE	0.28	\$32.48	\$0.00	9	\$0.00	\$32.48
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.63	\$74.14	\$50.54	9	\$0.00	\$124.68
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	9	\$2.00	\$2.00
JOB COUN	IT: 4				WO	RK ORI	DER TOTAL	_: 1.05	12	24.32	68.31	2.00	194.6
Job Code CH-SP	CHARGE SI	Job Descrip	<u>vtion</u>	5	<b>V</b> 03163	endor N	l <u>o.</u> 1	Invoice No.	<u>Purch</u>	nase Order N	lo.		Total Cost \$2.0
Lab Cada		lah Danasis	4:		F		NI-	Otherst		Finish		COMML	Z.0
<b>Job Code</b> 66-17-033	PEREORM.	Job Descrip TIRE ROTATION ANI		CTION 1		ployee		<u>Start</u> 8/06/2021 07:48:12	08/06/2	Finish 021 08:04:43		Quantity 0.28	Total Cost \$32.4
03-51-038		IEW WIPER BLADES			1074414			8/09/2021 07:00:00		021 07:09:00		0.15	\$17.7
66-PM-PMA		OIL CHANGE	,	·	1074414			8/05/2021 13:08:03		021 07:05:00		0.63	\$74.1
OO-I WI-I WIA	T LIVI OTVIVI	OIL OHAIVOL		•	1074414		O	0/00/2021 10:00:00	00/03/2	021 10.40.40		LABOR	124.3
Job Code		Job Descrip	tion			Part No		Des	cription		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE		٧	VIX51394		_	DIL FILTER			9.4		\$9.4
66-PM-PMA	PERFORM	OIL CHANGE		S	F16		S	EA FOAM 16OZ			10.7	71 1	\$10.7
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		C	OIL 0W16 CAM2 LS	PI SN4+ QT		6.0	)8 5	\$30.3
03-51-038	REPLACE N	IEW WIPER BLADES	3	Т	WB20-1		V	VIPER BLADE 20"			7.4	16 1	\$7.4
03-51-038	REPLACE N	IEW WIPER BLADES	3	2	6-1		٧	VIPER BLADE			10.3	311	\$10.3
												PARTS	68.3

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 40646

**Work Order Notes** 

(LISAPATE) PM-replace wipers

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH/JW Rotated tires and inspected brakes.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 14442. SH Performed PM.

UNIT NO:		243577 202	O TOYOTA	CAMR	Y			WORK O	RDER NO	): 4	1285		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	СОМ	SED DA	DATE:	10/12/20	21 11:46:22 21 15:03:56 21 09:17:00	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 16609 E DATE:	<b>M</b> 11/27/20	ty Automotive S ETER 2 - N: 119 AK2LU893149	Services 0	
JOB CODE		JOB DESCRIPTION	STA	T RSI	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADES	DOI	N P	N	GARAGE	0.04	\$4.75	\$17.90	\$0	0.00	\$22.65	
66-PM-PMA	PERFOR	RM OIL CHANGE	DOI	N P	N	GARAGE	0.27	\$31.76	\$55.60	\$0	0.00	\$87.36	
CH-SP	CHARGE	Shop Supplies	DOI	1 2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3			W	ORK OR	DER TOTAL	: 0.31	36	6.51	73.50	2.00		112.01
Job Code	CHARGE SI	Job Description		503163	<u>Vendor N</u>	<b>lo.</b>	Invoice No.	Purcha	se Order N	<u>o.</u>		<u>Total</u>	Cost \$2.00
011-01	OF IAROL OF	iop oupplies		300100		'					COMML		2.00
Job Code		Job Description		<u> </u>	mployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		110744	14	10	0/12/2021 10:25:59	10/12/20	21 10:28:24		0.04		\$4.75
66-PM-PMA	PERFORM (	OIL CHANGE		110744	14	10	0/12/2021 10:09:41	10/12/20	21 10:25:50		0.27		\$31.76
											LABOR		36.51
Job Code		Job Description			Part No	<u>).</u>	Des	cription		Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		WIX513	94	0	IL FILTER			9.26	, 1		\$9.26
66-PM-PMA	PERFORM (	OIL CHANGE		SF16		SI	EA FOAM 16OZ			10.71	1		\$10.71
03-51-038	REPLACE N	IEW WIPER BLADES		TWB20	-1	W	IPER BLADE 20"			7.59	) 1		\$7.59
03-51-038	REPLACE N	IEW WIPER BLADES		26-1		W	IPER BLADE			10.31	1		\$10.31
66-PM-PMA	PERFORM (	OIL CHANGE		0W16T		0	IL 0W16 CAM2 LS	PI SN4+ QT		7.13	5		\$35.63
											PARTS		73.50

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 41285

**Work Order Notes** 

(LISAPATE) PM-replace wipers

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 16609. SH/JW Performed PM.

UNIT NO:		243577 2020	O TOYOTA C	AMRY	,			WORK	ORDER NO	): 4	41935		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	COMP	ED DAT LETED ED DAT Camry	DATE:	12/21/20	21 09:54:41 21 08:32:42 21 08:51:31	METER 1	- M: 18957 CE DATE:	11/27/2	sity Automotive S METER 2 - N: 2019 1AK2LU893149		
JOB CODE		JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABC	<u>NATE</u>	RIAL	COMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY	DON	0	N	GARAGE	0.17	\$20.58	\$146.72	9	80.00	\$167.30	
35-32	DIAGNO	SE CRANKING SYSTEM	DON	0	Ν	GARAGE	0.18	\$21.21	\$0.00	9	80.00	\$21.21	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	9	\$2.00	\$2.00	
JOB COUN	IT: 3			WC	RK ORI	DER TOTAL	0.35		41.79	146.72	2.00		190.51
Job Code	CHARGE SI	Job Description	ı	<u>\</u> 503163	endor N	<u>lo.</u> 1	Invoice No.	Purc	hase Order N	<u>o.</u>		<u>Total</u>	Cost \$2.00
OH-OI	OF PARCE OF	юр оцрыкоз	·	303103		•					COMML		2.00
<b>Job Code</b> 03-32-002	REPLACE N	Job Description IEW BATTERY		<u>Er</u> 11074414	nployee 1		<u>Start</u> :/20/2021 15:11:14	12/20/	<u>Finish</u> 2021 15:19:09		Quantity 0.13	Total	Cost \$15.57
03-32-002	REPLACE N	IEW BATTERY		11074414	1	12	/20/2021 15:05:05	12/20/	2021 15:07:38		0.04		\$5.02
35-32	DIAGNOSE	CRANKING SYSTEM		11074414	1	12	/20/2021 11:22:28	12/20/	2021 11:33:15		0.18		\$21.21
											LABOR		41.80
Job Code		Job Description			Part No	<u>.</u>	Des	cription		Unit Pric	e Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	IEW BATTERY	:	24F2		В	ATTERY BCI 24F 5	50CCA		113.5	55 (1)		(\$113.55)
03-32-002	REPLACE N	IEW BATTERY	:	24F2		В	ATTERY BCI 24F 5	50CCA		113.5	55 1		\$113.55
03-32-002	REPLACE N	IEW BATTERY	•	47H5		В	ATTERY			146.7	721		\$146.72
											PARTS		146.72

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 41935

**Work Order Notes** 

(LISAPATE) Per driver check battery had to jump off this morning.

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Installed a new battery. SH

35-32 - DIAGNOSE CRANKING SYSTEM

(SHARBIN) ALT Charging at 13.90. Battery tested bad. SH

Page:1

# Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		243577 2020 1	ΓΟΥ	OTA C	AMRY	,			WORK O	RDER NO	: 42	2048	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY 2		OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	01/13/2	022 11:47:49 022 11:17:17 022 07:43:40	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 19539 EDATE:	<b>ME</b> 11/27/20	y Automotive S ETER 2 - N: 19 AK2LU893149	Services 0
JOB CODE	<u>E</u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LO	C LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES		DON	Р	N	GARAGE	0.03	\$3.11	\$17.90	\$0	.00	\$21.01
06-15	INSPEC <sup>*</sup>	T STEERING		DON	0	Ν	GARAGE	0.08	\$8.95	\$0.00	\$0	.00	\$8.95
66-17-013	PERFOR	RM ALIGNMENT		DON	0	N	GARAGE	0.49	\$57.43	\$0.00	\$0	.00	\$57.43
66-17-028	PERFOR	RM MOUNT AND BALANCE	TIRE	DON	0	N	GARAGE	0.79	\$93.55	\$646.79	\$0	.00	\$740.34
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.77	\$91.38	\$85.05	\$0	.00	\$176.43
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00
JOB COUN	IT: 6				WC	RK ORI	DER TOTA	L: 2.16	254	.42	749.74	2.00	1,006.16
Job Code		Job Description			<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>o.</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		•	1					\$2.00
												COMML	2.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>	<u>!</u>	<u>Finish</u>		Quantity	Total Cost
66-17-013	PERFORM	ALIGNMENT		1	1310047	•	(	01/12/2022 14:58:42	01/12/202	22 15:27:54		0.49	\$57.43
06-15	INSPECT S	TEERING		1	2052187	,	(	01/12/2022 14:53:02	01/12/202	22 14:57:35		0.08	\$8.95
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		1	2052187	,	(	01/12/2022 14:30:00	01/12/202	22 14:52:43		0.38	\$44.68
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		1	2052187	,	(	01/12/2022 13:50:09	01/12/202	22 14:15:00		0.41	\$48.87
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187	,	(	01/12/2022 08:15:38	01/12/202	22 08:17:13		0.03	\$3.11
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	7	(	01/12/2022 07:28:59	01/12/202	22 08:15:27		0.77	\$91.38
												LABOR	254.42
Job Code		Job Description				Part No	<u>).</u>	<u>Des</u>	cription	<u>!</u>	Unit Price	<b>Quantity</b>	Total Cost
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		1	549788		-	TIRE GEN ALTIMAX	215/55R17		157.52	4	\$630.06
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		C	OATED	15G	(	COATED 15G WHEE	EL WEIGHT		0.11	1	\$0.11
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		2	3131		-	TPMS SNAP IN VAL	VE 21060		3.83	4	\$15.30
66-17-028	PERFORM	MOUNT AND BALANCE TIRES		6	3001		•	1/4 OZ STICK ON TA	APE WEIGHT		0.17	8	\$1.32
66-PM-PMA	PERFORM	OIL CHANGE		V	/IX5139	4	(	OIL FILTER			9.24	1	\$9.24

#### The University of Alabama

# Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 160Z	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.02	5	\$65.10
					PARTS	749.74

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 42048

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

06-15 - INSPECT STEERING

(JWRIGHT) Steering good

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all 4 tires and balanced.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-19539

UNIT NO:		243577	2020 TOYOTA CAMRY						WORK O	RDER NO	): 4	12877		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED UNSCHEDULED 20TOYOTACAMR		OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	04/11/202	22 10:57:48 22 14:27:08 22 07:41:26	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 21467 E <b>DATE</b> :	<b>N</b> 11/27/2	ity Automotive 9 <b>IETER 2 - N:</b> 019 AK2LU893149	Services 0	
JOB CODE	1	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.87	\$102.10	\$49.71	\$	0.00	\$151.81	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.07	\$8.65	\$18.57	\$	0.00	\$27.22	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00	
JOB COUN	T: 3				wo	RK ORI	DER TOTAL:	0.94	110	.75	68.28	2.00		181.03
Job Code		Job Descript	ion_		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		Finish		Quantity	<u>Total</u>	Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	1	1901357		04	/11/2022 13:08:26	04/11/202	22 13:12:50		0.07		\$8.65
66-PM-PMA	PERFORM (	OIL CHANGE		1	1901357		04	/11/2022 12:16:15	04/11/202	22 13:08:10		0.87		\$102.10
												LABOR		110.75
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>	,	Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	Р	C99237	С	CA	BIN FILTER 2020	CAMRY		18.5	7 1		\$18.57
66-PM-PMA	PERFORM (	OIL CHANGE		WIX51394			OI	L FILTER			5.4	0 1		\$5.40
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		SE	A FOAM 16OZ			10.7	1 1		\$10.71
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		OI	L 0W16 CAM2 LSF	PI SN4+ QT		6.7			\$33.60
												PARTS		68.28

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 42877

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 21467 Completed PM top and bottom side. Completed checklist. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

UNIT NO:		243577	2020 TOYO	OTA C	AMRY	•			WORK C	ORDER NO	): 43	3817		
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		507143 CLOSED SCHEDULED 20TOYOTACAMR		OPENED DATE: COMPLETED DATE: CLOSED DATE: 20 Toyota Camry			07/05/2022 08:03:13 07/07/2022 13:59:53 07/11/2022 09:59:23		LOCATION: GARAGE METER 1 - M: 23553 IN-SERVICE DATE: UNIT SERIAL NO:		E - University Automotive <b>METER 2 - N:</b> 11/27/2019 4T1C11AK2LU89314		Services 0	
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-17-033	PERFOR	M TIRE ROTATION	AND BRAKE	DON	0	Ν	GARAGE	0.59	\$69.46	\$0.00	\$0	.00	\$69.46	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.59	\$70.11	\$43.52	\$0	.00	\$113.63	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	N	GARAGE	0.05	\$5.83	\$20.52	\$0	.00	\$26.35	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00	
JOB COUN	T: 4				wo	RK ORI	DER TOTAL:	1.23	14	5.40	64.04	2.00		211.44
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purch	ase Order No	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-033	PERFORM 1	TIRE ROTATION AND	BRAKE INSPEC	CTION 1	2052187	,	07	/05/2022 13:31:08	07/05/2	022 14:06:27		0.59		\$69.46
66-PM-PMA	PERFORM (	OIL CHANGE		1	2052187	,	07	/05/2022 09:26:11	07/05/20	022 10:01:50		0.59		\$70.11
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	1	2052187	,	07	/05/2022 09:23:03	07/05/20	022 09:26:01		0.05		\$5.83
												LABOR		145.40
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		٧	VIX5139	4	OI	L FILTER			6.17	1		\$6.17
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	Р	C99237	С	CA	ABIN FILTER 2020	CAMRY		20.52	1		\$20.52
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LSI	PI SN4+ QT		7.47	5		\$37.35
												PARTS		64.04

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 43817

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Brakes are at 8mm all around. Torqued all lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW MILEAGE-23553

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) Replaced cabin filter

UNIT NO: 243577		243577	2020 TOYOTA CAMRY							DER NO	3981		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR		OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	07/15/20	022 08:34:35 022 10:49:20 022 11:56:33	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 23760 <b>DATE</b> :	<b>M</b> 11/27/20		Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL COST
66-17-030	PERFOR	M TIRE PATCH		DON	0	N	GARAGE	0.54	\$64.15	\$16.70	\$0	0.00	\$80.85
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00
JOB COUN	T: 2				WO	RK ORI	DER TOTAL	.: 0.54	64.	15	16.70	2.00	82.85
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purchas</u>	e Order No	<u>).</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1						\$2.00
												COMML	2.00
Job Code		Job Descripti	<u>ion</u>		Em	nployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	Total Cost
66-17-030	PERFORM <sup>7</sup>	TIRE PATCH		1	1074414	ļ	0	7/15/2022 08:37:24	07/15/2022	2 09:10:01		0.54	\$64.15
												LABOR	64.15
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	Des	scription	<u>!</u>	Unit Price	Quantity	Total Cost
66-17-030	PERFORM <sup>7</sup>	TIRE PATCH		14	4041		F	ATCH 1/4 PILOT W	/IRE		4.31	1	\$4.31
66-17-030	PERFORM	TIRE PATCH		2	1372		F	IAMATON VALVE S	STEM TOYOTA		11.96	1	\$11.96
66-17-030	PERFORM 7	TIRE PATCH		5	8121			0 OZ WHEEL WEI	GHT		0.43	1	\$0.43
												PARTS	16.70

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 43981

**Work Order Notes** 

(CHANNELL) tire patch

**Job Notes** 

66-17-030 - PERFORM TIRE PATCH

(HHARBIN) Patched left front tire. SH

		243577 2	2020 TOYOTA CAMRY							DER NO	44601		
				OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	09/09/20	022 07:20:55 022 11:04:24 022 12:11:50	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	: 25066 <b>DATE</b> :	11/27/	rsity Automotive S <b>METER 2 - N:</b> 2019 11AK2LU893149	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>1</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.27	\$32.19	\$86.07		\$0.00	\$118.26
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	.: 0.27	7 32.	19	86.07	5.00	123.20
Job Code		Job Description	<u>n</u>		_	endor N		Invoice No.	<u>Purchas</u>	e Order N	l <u>o.</u>		Total Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1					COMML	\$5.0 <b>5.0</b>
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>E</u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		0	9/08/2022 09:30:00	09/08/2022	2 09:46:22		0.27	\$32.1
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		0	9/08/2022 09:24:12	2 09/08/2022	2 09:24:12		0.00	\$0.0
												LABOR	32.1
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	Des	scription_		Unit Pric	ce Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		V	VA10859	)	Д	IR FILTER CAMRY	(		33.	.12 1	\$33.1
66-PM-PMA	PERFORM (	OIL CHANGE		0	5089		В	BRAKE CLEAN NON-FLAMMABLE			7.	64 1	\$7.6
66-PM-PMA	PERFORM (	OIL CHANGE		V	VIX5139	4	C	OIL FILTER			10.	28 1	\$10.2
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		C	DIL 0W16 CAM2 LS	SPI SN4+ QT		7.	.015	\$35.0
												PARTS	86.0

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 44601

**Work Order Notes** 

(CWIGLEY) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

UNIT NO: 243577 20  USING DEPT NO: 507143  WO STATUS: CLOSED  WO VISIT REASON: SCHEDULED  TECH SPEC NO: 20TOYOTACAMRY		2020 TOYOTA CAMRY						RDER NO	: 4	14821			
		CLOSED SCHEDULED	COMP	NED DATE: IPLETED DATE: SED DATE: a Camry		10/03/2022 09:19:30 10/06/2022 08:49:39 10/06/2022 09:31:01		LOCATION: GARAGE METER 1 - M: 25506 IN-SERVICE DATE: UNIT SERIAL NO:		11/27/2	METER 2 - N:	Services 0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>n</u> <u>stat</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL (	COST
66-79-002	PERFOR	M SERVICE CALL	DON	В	N	GARAGE	0.03	\$3.74	\$0.00	\$	60.00	\$3.74	
CH-32-002	CHARGE	BATTERY	DON	0	N	GARAGE	0.01	\$1.54	\$0.00	\$	60.00	\$1.54	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00	
JOB COUN	IT: 3			WC	RK ORI	DER TOTAL:	0.04		5.28	0.00	5.00		10.28
Job Code CH-SP	Job Description CHARGE Shop Supplies		<del></del>	<u>\</u> 503163	<u>endor N</u>	lo. 1	o. Invoice No.		Purchase Order N			<u>Total (</u>	<u>Cost</u> \$5.00
											COMML		5.00
Job Code		Job Descriptio	o <u>n</u>	<u>E</u> r	nployee	No.	<u>Start</u>	<u>Finish</u>			Quantity	Total (	Cost
CH-32-002	CHARGE BA	ATTERY		11074414	1	10/	05/2022 11:45:44	10/05/20	22 11:46:31		0.01		\$1.54
66-79-002	PERFORM S	SERVICE CALL		11074414		10/	05/2022 11:43:37	10/05/20	22 11:45:31		0.03		\$3.74
66-PM-PMA	PERFORM (	OIL CHANGE		11901357		10/03/2022 13:59		10/03/20	10/03/2022 14:01:13		(0.03)		(\$4.10)
66-PM-PMA	PERFORM (	PERFORM OIL CHANGE		11901357		10/03/2022 13		10/03/20	22 14:01:13		0.03		\$4.10
											LABOR		5.28

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 44821

**Work Order Notes** 

(LISAPATE)

(LISAPATE) Security resources requested a service call for a dead battery

**Job Notes** 

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) SH AMG Performed a service call to sec rec for a dead battery. Jumped off and drove back to the shop. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Not due service meter needed resetting. AMG

CH-32-002 - CHARGE BATTERY

(SHARBIN) Charged battery rechecked good. ALT Charging at 14 volts. SH

UNIT NO:		020 TOYOT	A C	AMRY				WORK OR	DER NO	: 4	5459			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	CC	OMPL LOSE	D DATE ETED I D DATE amry	DATE:	12/08/202	22 13:17:52 22 09:37:17 22 14:17:22	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 26673 <b>DATE</b> :	<b>M</b> 11/27/20	ty Automotive S ETER 2 - N: 019 AK2LU893149		
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>s</u>	TAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADI	ES D	OON	Р	Ν	GARAGE	0.03	\$3.44	\$18.41	\$0	0.00	\$21.85	
66-PM-PMA	PERFOR	RM OIL CHANGE	D	OON	Р	Ν	GARAGE	0.25	\$29.24	\$41.45	\$0	0.00	\$70.69	
CH-SP	CHARGE	Shop Supplies	D	OON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3	5.00	\$5.00	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.28	32.0	88	59.86	5.00		97.54
Job Code		Job Description	<u>1</u>		V	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>1</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u>F</u>	inish_		Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		12	2052187		12/	06/2022 15:10:11	12/06/2022	2 15:11:56		0.03		\$3.44
66-PM-PMA	PERFORM (	OIL CHANGE		12	2052187		12/	06/2022 14:19:11	12/06/2022	2 14:34:03		0.25		\$29.24
												LABOR		32.68
Job Code		Job Description	<u>1</u>		ı	Part No	<u>.</u>	<u>Des</u>	<u>cription</u>	ļ	Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		W	/IX51394	ļ.	OII	FILTER			6.35	5 1		\$6.35
03-51-038	REPLACE N	IEW WIPER BLADES		T	WB20-1		WI	PER BLADE 20"			7.82	2 1		\$7.82
03-51-038	REPLACE N	IEW WIPER BLADES		26	<b>6-1</b>		WI	PER BLADE			10.59	) 1		\$10.59
66-PM-PMA	PERFORM (	OIL CHANGE		0\	W16T		OII	0W16 CAM2 LSF	PI SN4+ QT		7.02	2 5		\$35.10
												PARTS		59.86

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 45459

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW MILEAGE-26673
Will need new tires at next pm

UNIT NO:	NIT NO: 243577 2020 T SING DEPT NO: 507143				AMRY	•			WORK O	RDER NO	: 45	635		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE Toyota C	ETED	DATE:	01/25/202	22 15:52:47 23 08:24:47 23 11:00:45	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 26926 EDATE:	ME 11/27/201	y Automotive E <b>TER 2 - N:</b> 19 .K2LU893149	0	
JOB CODE	Ī	JOB DESCRIPTI	<u>ION</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
06-15	INSPECT	STEERING		DON	0	Ν	GARAGE	0.03	\$3.38	\$0.00	\$0.	.00	\$3.38	
66-17-013	PERFOR	M ALIGNMENT		DON	0	N	GARAGE	0.43	\$50.38	\$0.00	\$0.	.00	\$50.38	
66-17-028	PERFOR	M MOUNT AND B	ALANCE TIRE	DON	0	N	GARAGE	1.62	\$191.26	\$14.42	\$0.	.00	\$205.68	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00	
JOB COUN	IT: 4				WO	RK ORI	DER TOTAL	2.08	245	.02	14.42	5.00	)	264.44
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>	ļ	Finish		Quantity	<u>Total</u>	Cost
66-17-013	PERFORM A	ALIGNMENT		1	1310047	•	01	/23/2023 14:30:00	01/23/202	23 14:44:57		0.25		\$29.40
66-17-013	PERFORM A	ALIGNMENT		1	1310047	,	01	/23/2023 14:04:20	01/23/202	23 14:15:00		0.18		\$20.98
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	1	2201267	7	01	/23/2023 09:52:30	01/23/202	23 11:29:45		1.62		\$191.26
06-15	INSPECT S	ΓEERING		1	2201267	7	01	/23/2023 09:50:47	01/23/202	23 09:52:30		0.03		\$3.38
												LABOR		245.02
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u>!</u>	Unit Price	Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	В	110772	A	21	5/55R17 MICH SU	JRVEY TIRES		0.00	4		\$0.00
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	2	3131		TF	MS SNAP IN VAL	VE 21060		2.16	4		\$8.64
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	6	3001		1/4	4 OZ STICK ON TA	APE WEIGHT		0.17	35		\$5.78
												PARTS		14.42

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 45635

**Work Order Notes** 

(EHANNAH) tire light is on, please inspect

(GARAGE) nail in right front tire, cant be patched, all tires need to be replaced due to low tread depth-GC

**Job Notes** 

06-15 - INSPECT STEERING

(GARAGE) inspected steering-EH-GC

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. EH .5 Reset steering using code link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) performed mounted and balanced tires-GC

UNIT NO:		243577	2020 TOYO	OTA C	AMRY	•			WORK C	RDER NO	): 4	46379		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE Toyota C	ETED	DATE:	03/07/202	23 11:14:08 23 11:50:16 23 13:18:17		M: 28812 E DATE:	<b>N</b> 11/27/2		Services 0	
JOB CODE	<u>:</u>	JOB DESCRIPTIO	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL (	COMMERCIAL	TOTAL	COST
66-17-033	PERFOR	M TIRE ROTATION	AND BRAKE	DON	Р	Ν	GARAGE	0.19	\$21.90	\$0.00	\$	00.00	\$21.90	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.10	\$12.32	\$55.89	\$	00.00	\$68.21	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	\$5.00	\$5.00	
JOB COUN	Т: 3				wo	RK ORI	DER TOTAL	: 0.29	3	4.22	55.89	5.00		95.11
Job Code		Job Description	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purch</u>	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-033	PERFORM 1	TIRE ROTATION AND E	BRAKE INSPE	CTION 1	1074414		03	/06/2023 14:30:00	03/06/20	023 14:41:08		0.19		\$21.90
66-17-033	PERFORM 1	TIRE ROTATION AND E	BRAKE INSPE	CTION 1	1074414		03	/06/2023 14:25:00	03/06/20	023 14:25:00		0.00		\$0.00
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		03	/06/2023 14:08:44	03/06/20	023 14:15:00		0.10		\$12.32
												LABOR		34.22
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		٧	VIX5139	4	OI	L FILTER			6.0	)3 1		\$6.03
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		SE	EA FOAM 16OZ			13.1	11 1		\$13.11
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LS	PI SN4+ QT		7.3			\$36.75
												PARTS		55.89

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 46379

**Work Order Notes** 

(EHANNAH) pm- replace wipers

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires and inspected brakes found no issues at this time. SH Right side GC Left side.

21to the RR

22 to the LR

23 to the RF

24 to the LF

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

UNIT NO:					AMRY				WORK OF	DER NO	): 4	7082	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE Toyota C	ETED	DATE:	05/18/202	23 14:28:57 23 09:57:18 23 13:40:01	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 30555 <b>DATE</b> :	<b>M</b> 11/27/20		Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	COMMERCIAL	TOTAL COST
66-79-003	PERFOR	M SAFETY INSPE	CTION	DON	Υ	Ν	GARAGE	0.40	\$47.72	\$0.00	\$	0.00	\$47.72
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.11	\$12.39	\$41.34	\$	0.00	\$53.73
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.10	\$11.80	\$22.73	\$	0.00	\$34.53
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL:	0.61	71.	91	64.07	5.00	140.98
Job Code CH-SP	CHARGE Sh	Job Descript	<u>tion</u>	5	<u>V</u> 03163	endor N	l <u>o.</u> 1	Invoice No.	Purchas	e Order N	<u>o.</u>		Total Cost \$5.00
												COMML	5.00
Job Code		Job Descript	tion		<u>En</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	1	1074414		05	/18/2023 07:00:00	05/18/202	3 07:06:00		0.10	\$11.80
66-79-003	PERFORM S	SAFETY INSPECTION	N	1	1074414		05	/17/2023 09:34:31	05/17/202	3 09:58:47		0.40	\$47.72
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		05	/17/2023 09:26:01	05/17/202	3 09:26:01		0.00	\$0.00
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		05	/17/2023 09:08:42	05/17/202	3 09:15:00		0.11	\$12.39
												LABOR	71.91
Job Code		Job Descript	tion_			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	P	C99237	С	CA	ABIN FILTER 2020	CAMRY		22.73	3 1	\$22.73
66-PM-PMA	PERFORM (	OIL CHANGE		٧	VIX51394	1	OI	L FILTER			5.79	9 1	\$5.79
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LS	PI SN4+ QT		7.1		\$35.55
												PARTS	64.07

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 47082

**Work Order Notes** 

(EHANNAH) pm- replace wipers- do SI

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Did not find any issues at this time. Rotated tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH CW/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) SH replaced cabin filter

UNIT NO:		243577 2020 TC	OYOTA C	AMRY	•			WORK O	RDER NO	: 47	'384	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY 202	OPENE COMPI CLOSE 20 Toyota C	ETED	DATE:	06/21/202	23 08:36:50 23 14:58:43 23 14:58:45	LOCATION METER 1 - IN-SERVICE UNIT SERIA	M: 31394 E <b>DATE</b> :	ME 11/27/201	y Automotive ( ETER 2 - N: 19 .K2LU893149	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-51-042	REPLAC	E NEW KEY FOB BATTERY	DON	0	N	GARAGE	0.10	\$12.26	\$6.72	\$0.	.00	\$18.98
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00
JOB COUN	IT: 2			WC	RK ORI	DER TOTAL:	0.10	12	2.26	6.72	5.00	23.98
Job Code		Job Description		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies	5	03163		1						\$5.00
											COMML	5.00
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>	,	<u>Finish</u>		Quantity	Total Cost
03-51-042	REPLACE N	IEW KEY FOB BATTERY	1	220126	7	06	/20/2023 08:40:33	06/20/20	23 08:46:47		0.10	\$12.26
											LABOR	12.26
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>!</u>	Jnit Price	Quantity	Total Cost
03-51-042	REPLACE N	IEW KEY FOB BATTERY	C	R2032		BL	JTTON CELL BAT	ΓERY 3V		6.72	1	\$6.72
											PARTS	6.72

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 47384

**Work Order Notes** 

(LISAPATE) key fob is dead

**Job Notes** 

03-51-042 - REPLACE NEW KEY FOB BATTERY

(GRCOOK) Replaced key fob battery-GC

UNIT NO:		020 TOYO	TA C	AMRY	7			WORK OF	RDER NO	): 4	47832			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	Ċ	OPENE COMPL CLOSE Oyota C	ETED D DAT	DATE:	08/08/20	023 11:15:26 023 13:43:08 023 07:50:26	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 32883 DATE:	<b>N</b> 11/27/2		Services 0	
JOB CODE	Ī.	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL COS	ST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.23	\$26.85	\$78.74	\$	00.00	\$105.59	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	\$5.00	\$5.00	
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	.: 0.23	3 26	.85	78.74	5.00	110	10.59
Job Code		Job Description	<u>1</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchas	se Order N	<u>0.</u>		Total Cos	<u>st</u>
CH-SP	CHARGE SI	nop Supplies		50	03163		1						\$	\$5.00
												COMML	,	5.00
Job Code		Job Description	1		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	inish		Quantity	Total Cos	<u>st</u>
66-PM-PMA	PERFORM (	OIL CHANGE		1:	2201267	7	0	8/07/2023 07:05:53	3 08/07/202	3 07:19:32		0.23	\$2	26.85
												LABOR	20	26.85
Job Code		Job Description	1			Part No	<u>.</u>	Des	scription		Unit Price	e Quantity	Total Cos	<u>st</u>
66-PM-PMA	PERFORM (	OIL CHANGE		V	/IX5139	4	C	IL FILTER			5.7	78 1	\$	\$5.78
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		S	EA FOAM 16OZ			13.1	11 1	\$1	313.11
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		C	IL 0W16 CAM2 LS	SPI SN4+ QT		11.9	975	\$5	59.85
												PARTS	78	78.74

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 47832

**Work Order Notes** 

(LRUSHING) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filters good, added seafoam to fuel, tires and tire pressure. Miles, 32,883

UNIT NO:				OTA C	AMRY	•			WORK O	RDER NO:	47	933		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR		СОМР	ED DAT LETED ED DAT Camry	DATE:	08/31/20	023 07:18:09 023 13:39:02 023 15:05:12	LOCATION METER 1 - I IN-SERVICE UNIT SERIA	M: 33252 E DATE:	ME 11/27/201		Services 0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	<u>RSN</u>	WRTY	JOB LO	LABOR HRS	LABOR	MATER	RIAL CO	MMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		DON	Ν	Ν	GARAGE	0.21	\$24.29	\$221.08	\$0.	00	\$245.37	
03-44-082	REPLAC	E NEW FUEL DOO	R HOUSING/	DON	5	Ν	GARAGE	0.28	\$33.37	\$134.13	\$27	70.25	\$437.75	
06-32-002	INSPECT	ΓBATTERY		DON	0	Ν	GARAGE	0.03	\$3.70	\$0.00	\$0.	00	\$3.70	
16-44	TRANSP	ORT FUEL SYSTE	М	DON	0	Ν	GARAGE	0.50	\$59.00	\$0.00	\$0.	00	\$59.00	
66-79-002	PERFOR	RM SERVICE CALL		DON	В	N	GARAGE	0.04	\$5.11	\$0.00	\$0.	00	\$5.11	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
PA-44-082	PAINTED	FUEL DOOR HOU	JSING/HINGE	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$0.	00	\$0.00	
JOB COUN	IT: 7				wo	RK OR	DER TOTA	L: 1.06	125	5.47	355.21	275.25		755.93
<b>Job Code</b> 03-44-082	REPLACE N	Job Descript		ASSY 1	_	endor N		<u>Invoice No.</u> 1697655	<u>Purcha</u>	se Order No	<u>-</u>		<u>Total</u>	<b>Cost</b> \$270.25
CH-SP	CHARGE SI	nop Supplies		5	03163		1	1						\$5.00
												COMML		275.25
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee		<u>Start</u>	•	<u>Finish</u>		Quantity	<u>Total</u>	Cost
16-44	TRANSPOR	T FUEL SYSTEM		1	1915538	}	(	08/31/2023 07:00:00	08/31/202	23 07:30:00		0.50		\$59.00
03-44-082	REPLACE N	IEW FUEL DOOR HO	USING/HINGE A	ASSY 1	1074414	ļ	(	08/28/2023 13:33:17	08/28/202	23 13:50:15		0.28		\$33.37
06-32-002	INSPECT BA	ATTERY		1	1074414		(	08/22/2023 07:32:44	08/22/202	23 07:34:37		0.03		\$3.70
03-32-002	REPLACE N	IEW BATTERY		1	1074414		(	08/22/2023 07:20:12	08/22/202	23 07:32:33		0.21		\$24.29
66-79-002	PERFORM	SERVICE CALL		1	1915538	}	(	08/21/2023 08:32:50	08/21/202	23 08:35:26		0.04		\$5.11
												LABOR		125.47
Job Code		Job Descript	<u>ion</u>			Part No	<u>).</u>	<u>Des</u>	cription	<u>u</u>	Init Price	Quantity	<u>Total</u>	Cost
03-44-082	REPLACE N	IEW FUEL DOOR HO	USING/HINGE A	ASSY 7	7379060	10	F	FUEL LID SPACER			2.60	1		\$2.60
03-44-082	REPLACE N	IEW FUEL DOOR HO	USING/HINGE A	ASSY 7	7360350	)40	5	SPRING ASSEMBLY	1		7.41	1		\$7.41
03-44-082	REPLACE N	IEW FUEL DOOR HO	USING/HINGE A	ASSY 9	0269A00	005	F	RIVET			3.08	2		\$6.15
03-44-082	REPLACE N	IEW FUEL DOOR HO	USING/HINGE A	ASSY 7	7350061	80	F	FUEL DOOR			110.35	1		\$110.35
FleetFocus M5	- WODETAIL	- Work Order Detail v2	20.0											Page:1

# Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-44-082	REPLACE NEW FUEL DOOR HOUSING/HINGE ASSY	9054106069	FUEL DOOR CUSHION	3.81	2	\$7.62
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	221.08	1	\$221.08
				·	PARTS	355.21

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 47933

**Work Order Notes** 

(EHANNAH) service call for a dead battery

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Installed a new battery ALT charging at 13.8 volts. SH

03-44-082 - REPLACE NEW FUEL DOOR HOUSING/HINGE ASSY

(LISAPATE) SH installed new fuel door housing assy

**06-32-002 - INSPECT BATTERY** 

(SHARBIN) GC Put the battery on charge. Battery retested bad. SH

16-44 - TRANSPORT FUEL SYSTEM

(LISAPATE) Taken to Andrews by RC

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped off brought back to shop\RC CW

**CH-SP - CHARGE Shop Supplies** 

PA-44-082 - PAINTED FUEL DOOR HOUSING/HINGE ASSY

(LISAPATE) Andrews's painted fuel door . Pd by PO

UNIT NO:		243577	2020 TOYO	TA C	AMRY	•			WORK O	RDER NO	): 48	8677		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	C	OMPL LOSE	<b>D DAT ETED D DAT</b> amry	DATE:	10/24/20	023 10:53:38 023 14:52:28 023 07:09:54		M: 34952 E DATE:	<b>M</b> 11/27/20		Services 0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u> </u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE	I	DON	Р	Ν	GARAGE	0.45	\$53.33	\$65.01	\$0	0.00	\$118.34	
CH-SP	CHARGE	Shop Supplies	]	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	.: 0.4	5 5	3.33	65.01	5.00		123.34
Job Code		Job Description	<u>on</u>		V	endor N	l <u>o.</u>	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		Em	ployee	No.	<u>Start</u>		Finish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		11	1074414		1	0/23/2023 13:41:5	5 10/23/20	23 14:09:02		0.45		\$53.33
												LABOR		53.33
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	<u>De</u>	scription		Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		W	/IX5139	4	C	IL FILTER			11.55	5 1		\$11.55
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		S	EA FOAM 16OZ			13.11	1		\$13.11
66-PM-PMA	PERFORM (	OIL CHANGE		0\	N16T		C	OIL 0W16 CAM2 LS	SPI SN4+ QT		8.07	5		\$40.35
												PARTS		65.01

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 48677

**Work Order Notes** 

(LISAPATE) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

UNIT NO:				OTA C	AMRY	•			WORK C	RDER NO	): 49	9012	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAN	MRY 2020 <sup>-</sup>	OPENE COMPL CLOSE Toyota C	ETED D DAT	DATE:	11/29/20	23 08:59:37 23 08:21:34 23 09:45:51		M: 35825 E DATE:	<b>M</b> 11/27/20	ty Automotive S ETER 2 - N: 19 AK2LU893149	0
JOB CODE	<u> </u>	JOB DESCRIP	TION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL C	OMMERCIAL	TOTAL COST
03-05-019	REPLAC	E NEW OXYGEN	N SENSOR	DON	N	N	GARAGE	0.26	\$30.22	\$275.61	\$0	0.00	\$305.83
03-41	REPLAC	E NEW AIR INTA	AKE SYSTEM	DON	N	N	GARAGE	0.26	\$30.32	\$154.68	\$0	0.00	\$185.00
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00
SO-00	SCAN O	UT COMPLETE \	VEHICLE	DON	0	N	GARAGE	3.74	\$440.83	\$0.00	\$0	0.00	\$440.83
JOB COUN	IT: 4				WC	RK ORI	DER TOTAL	.: 4.25	5 50	1.37	430.29	5.00	936.66
Job Code CH-SP	CHARGE SI	Job Descr	<u>iption</u>	5	<u>V</u> 03163	endor N	<b>lo.</b> 1	Invoice No.	Purch	ase Order N	<u>o.</u>		<u>Total Cost</u> \$5.00
												COMML	5.00
<b>Job Code</b> 03-41	REPLACE N	Job Descr IEW AIR INTAKE S		1	<u>En</u> 1310047	nployee ,		<u>Start</u> 1/29/2023 07:41:31	11/29/20	Finish 23 07:56:56		Quantity 0.26	Total Cost \$30.32
03-05-019		IEW OXYGEN SEN			1310047			1/29/2023 07:26:09		23 07:41:31		0.26	•
SO-00		COMPLETE VEHIC			1310047			1/21/2023 13:06:01		23 13:52:06		0.77	•
SO-00	SCAN OUT	COMPLETE VEHIC	CLE	1	1310047	,	1	1/21/2023 11:04:56	11/21/20	23 11:52:22		0.79	\$93.29
SO-00	SCAN OUT	COMPLETE VEHIC	CLE	1	1310047	7	1	1/21/2023 09:00:00	11/21/20	23 09:41:28		0.69	\$81.55
SO-00	SCAN OUT	COMPLETE VEHIC	CLE	1	1310047	,	1	1/20/2023 13:04:48	11/20/20	23 14:33:58		1.49	\$175.36
												LABOR	501.37
Job Code		Job Descr	<u>iption</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	Quantity	Total Cost
03-41	REPLACE N	IEW AIR INTAKE S	SYSTEM	Α	NTIFRE	EZE PINI	K T	OYOTA ANTIFREE	ZE		26.94	. 1	\$26.94
03-05-019	REPLACE N	IEW OXYGEN SEN	NSOR	8	9467332	210	0	XYGEN SENSOR			275.61	1	\$275.61
03-41	REPLACE N	IEW AIR INTAKE S	SYSTEM	1	6260F00	010	Н	OSE ASSEMBLY			127.74		
												PARTS	430.29

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 49012

**Work Order Notes** 

(EHANNAH) check engine light is on

### Job Notes

#### 03-05-019 - REPLACE NEW OXYGEN SENSOR

(EHOWELL) Replaced B1S2 oxygen sensor. Observed the O2 data after the repair. The readings changed after the new sensor was installed. EH 1.0 HR

### 03-41 - REPLACE NEW AIR INTAKE SYSTEM

(EHOWELL) Verified that the coolant water route switching valve was receiving power and ground. Replaced the coolant water route switching valve and added coolant to the vehicle. EH .7 HR

**CH-SP - CHARGE Shop Supplies** 

#### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(EHOWELL) DTC: P227118 O2 Sensor Signal Biased/Stuck Rich B1S2 Circuit Current Below Threshold.

DTC: P268115 Engine Coolant Bypass Valve Circuit Short to Battery or Open.

Called the dealer and they informed me that this concern fell under the 3 years/36,000-mile warranty, therefore the repair was not covered. EH

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

243577 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 49106 **USING DEPT NO:** 507143 **OPENED DATE:** 11/30/2023 13:40:42 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 12/18/2023 09:55:35 **METER 1 - M:** 35979 COMPLETED DATE: METER 2 - N: WO VISIT REASON: **SCHEDULED** 12/18/2023 11:26:24 CLOSED DATE: **IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 **COMMERCIAL TOTAL COST** JOB CODE WRTY **MATERIAL** JOB DESCRIPTION STAT RSN **JOB LOC** LABOR HRS **LABOR** 03-02-013 REPLACE NEW FLOOR COVERINGS DON Ν **GARAGE** 0.25 \$29.50 \$217.39 \$0.00 \$246.89 CH-SP **CHARGE Shop Supplies** DON 2 **GARAGE** 0.00 \$0.00 \$0.00 \$5.00 \$5.00 JOB COUNT: 2 **WORK ORDER TOTAL:** 0.25 29.50 217.39 5.00 251.89 **Job Code Job Description** Vendor No. Invoice No. Purchase Order No. **Total Cost** CH-SP **CHARGE Shop Supplies** 503163 1 \$5.00 COMML 5.00 **Job Code Job Description** Employee No. Finish **Total Cost** Start Quantity 03-02-013 REPLACE NEW FLOOR COVERINGS 11074414 12/14/2023 14:15:50 12/14/2023 14:30:50 0.25 \$29.50 03-02-013 REPLACE NEW FLOOR COVERINGS 11074414 12/14/2023 14:15:50 12/14/2023 14:15:50 0.00 \$0.00 03-02-013 REPLACE NEW FLOOR COVERINGS 11074414 12/14/2023 14:15:50 12/14/2023 14:15:50 0.00 \$0.00 **LABOR** 29.50 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 03-02-013 REPLACE NEW FLOOR COVERINGS PT9080318020 201.38 1 \$201.38 FLOOR MAT SET 03-02-013 5869433010 FLOOR MAT CLIP UPPER 6.24 \$6.24 REPLACE NEW FLOOR COVERINGS 9.77 03-02-013 REPLACE NEW FLOOR COVERINGS 5869833010 FLOOR MAT CLIP LOWER \$9.77 **PARTS** 217.39

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 49106

**Work Order Notes** 

(EKIMBREL) replace floor mats

**Job Notes** 

03-02-013 - REPLACE NEW FLOOR COVERINGS

(SHARBIN) Installed a new floor mat retainer clip on the drivers side and installed 4 new floor mats. SH

UNIT NO:		243577	2020 TOY	OTA C	AMRY	•			WORK O	RDER NO:	49	324		
USING DEPT WO STATUS: WO VISIT RE TECH SPEC	: EASON:	507143 CLOSED SCHEDULED 20TOYOTACAMR	Y 2020	OPENE COMPL CLOSE Toyota C	ETED D DATI	DATE:	01/04/202	4 07:56:38 4 09:01:37 4 11:55:05	LOCATION METER 1 - IN-SERVIC UNIT SERI	E DATE:	<b>ME</b> 11/27/201	TER 2 - N:	Services 0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	IAL CO	MMERCIAL	TOTAL	COST
06-32-002	INSPECT	BATTERY		DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00	\$0.0	00	\$0.00	
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.15	\$17.70	\$0.00	\$0.0	00	\$17.70	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00	
JOB COUNT	: 3				wo	RK ORE	ER TOTAL:	0.15	1	7.70	0.00	5.00		22.70
Job Code		Job Descripti	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcha	ase Order No.			<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
CH-32-002	CHARGE BA	TTERY		1:	2395904	ļ	01/	04/2024 07:00:00	01/04/20	24 07:09:00		0.15		\$17.70
												LABOR		17.70

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 49324

**Work Order Notes** 

(LISAPATE) Per driver unit has been jumped off a few times. Check battery

**Job Notes** 

**06-32-002 - INSPECT BATTERY** 

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery. FC

Page:1

# Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		243577 2020	TOY	OTA C	AMRY	7			WORK OF	RDER NO	: 49	413	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY		OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	01/17/2	024 14:06:01 024 10:33:12 024 07:54:54	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 36534 EDATE:	<b>ME</b> 11/27/201	/ Automotive \$ ETER 2 - N: 19 K2LU893149	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LO	C LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL COST
06-15	INSPEC <sup>*</sup>	T STEERING		DON	N	Ν	GARAGE	2.21	\$260.78	\$0.00	\$0.	00	\$260.78
66-17-013	PERFOR	RM ALIGNMENT		DON	N	Ν	GARAGE	1.28	\$150.65	\$0.00	\$0.	00	\$150.65
66-17-028	PERFOR	RM MOUNT AND BALANC	E TIRE	DON	N	Ν	GARAGE	0.04	\$4.26	\$728.90	\$0.	00	\$733.16
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.46	\$54.38	\$75.67	\$0.	00	\$130.05
66-PM-PMC	PERFOR	RM CABIN FILTER REPLA	CEMEI	DON	Р	N	GARAGE	0.01	\$1.74	\$22.73	\$0.	00	\$24.47
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00
JOB COUN	IT: 6				WC	RK ORI	DER TOTA	L: 4.00	471.	.81	827.30	5.00	1,304.11
Job Code		Job Description			<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purchas</u>	se Order No	<u>).</u>		<u>Total Cost</u>
CH-SP	CHARGE SI	nop Supplies		5	03163			1					\$5.00
												COMML	5.00
Job Code		<b>Job Description</b>			<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMC	PERFORM	CABIN FILTER REPLACEME	NT	1	2395904	1	(	01/11/2024 15:37:21	01/11/202	4 15:38:14		0.01	\$1.74
06-15	INSPECT S	TEERING		1	1310047	7	(	01/11/2024 14:30:00	01/11/202	4 15:31:00		1.02	\$119.97
06-15	INSPECT S	TEERING		1	1310047	,	(	01/11/2024 13:03:24	01/11/202	4 14:15:00		1.19	\$140.8
66-17-013	PERFORM	ALIGNMENT		1	1310047	,	(	01/11/2024 07:36:35	01/11/202	4 08:53:11		1.28	\$150.65
66-17-028	PERFORM	MOUNT AND BALANCE TIRI	ES	1	2395904	1	(	01/10/2024 15:39:36	01/10/202	24 15:41:46		0.04	\$4.26
66-PM-PMA	PERFORM	OIL CHANGE		1	2395904	1	(	01/10/2024 08:36:58	01/10/202	24 09:04:37		0.46	\$54.38
												LABOR	471.81
Job Code		<b>Job Description</b>				Part No	<u>.</u>	<u>Des</u>	scription	<u>L</u>	Jnit Price	<b>Quantity</b>	<u>Total Cost</u>
66-PM-PMA	PERFORM	OIL CHANGE		0	W16T		(	OIL 0W16 CAM2 LS	PI SN4+ QT		11.03	5	\$55.13
66-PM-PMA	PERFORM	OIL CHANGE		S	F16		:	SEA FOAM 16OZ			13.11	1	\$13.1
66-PM-PMC	PERFORM	CABIN FILTER REPLACEME	NT	P	C99237	С	(	CABIN FILTER 2020	) CAMRY		22.73	1	\$22.73
66-PM-PMA		OIL CHANGE			G4476F			OIL FILTER			7.43	1	\$7.43
66-17-028	PERFORM	MOUNT AND BALANCE TIRI	ES	6	3001		•	1/4 OZ STICK ON TA	APE WEIGHT		0.20	25	\$4.8

The University of Alabama

Job Code	Job Description	<u>Part No.</u>	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	4	\$14.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557737	TIRE 215/55R17 GEN ALTIMAX	177.39	4	\$709.56
					PARTS	827.30

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 49413

**Work Order Notes** 

(EHANNAH) pm

**Job Notes** 

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH/FC

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) perform mounted and balanced fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter fc

UNIT NO:		243577	2020 TOYO	OTA C	AMRY	•			WORK O	RDER NO	:	49507		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	03/06/202	24 07:25:28 24 10:43:20 24 10:43:23	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 36749 E DATE:	11/27/2		Services 0	
JOB CODE	Ī	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
03-01-054	REPLAC	CE NEW BYPASS H	EATER HOSE	DON	5	N	GARAGE	0.00	\$0.00	\$0.00		\$538.92	\$538.92	
14-52-021	INSTALI	GPS SYSTEM		DON	5	Ν	GARAGE	0.08	\$10.00	\$0.00		\$0.00	\$10.00	
16-01	TRANSI	PORT AIR CONDITI	ONING, HEAT	DON	5	Ν	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00	
CH-SP	CHARG	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
SO-05	SCAN C	OUT ELECTRONIC E	ENGINE EEC	DON	5	N	GARAGE	3.83	\$451.42	\$13.11		\$0.00	\$464.53	
JOB COUN	IT: 5				WC	RK ORI	DER TOTAL:	: 4.41	520	).42	13.11	543.92		1,077.45
Job Code		Job Descript	<u>tion</u>		V	endor N	l <u>o.</u>	Invoice No.	Purcha	se Order No	<u>).</u>		Total	Cost
03-01-054	REPLACE I	NEW BYPASS HEATE	R HOSE	1	1076422	2	62	35205						(\$538.92)
03-01-054	REPLACE I	NEW BYPASS HEATE	R HOSE	1	1076422	2	62	35205						\$538.92
03-01-054	REPLACE I	NEW BYPASS HEATE	R HOSE	1	1076422	2	62	35205						\$538.92
CH-SP	CHARGE S	hop Supplies		5	03163		1							\$5.00
												COMML	,	543.92
Job Code		Job Descript	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>Finish</u>			Quantity	<u>Total</u>	Cost
16-01	TRANSPOR	RT AIR CONDITIONIN	G, HEAT, VENT	1	1399745	5	02	/27/2024 07:00:00	02/27/20	24 07:30:00		0.50		\$59.00
						_			00/0=/00			(0.50)		(4=0.00)

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	Total Cost
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11399745	02/27/2024 07:00:00	02/27/2024 07:30:00	0.50	\$59.00
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11399745	02/27/2024 07:00:00	02/27/2024 07:30:00	(0.50)	(\$59.00)
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11399745	02/27/2024 07:00:00	02/27/2024 07:30:00	0.50	\$59.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 13:05:32	02/23/2024 13:08:51	0.06	\$6.52
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 13:05:32	02/23/2024 13:08:51	(0.06)	(\$6.52)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 13:05:32	02/23/2024 13:08:51	0.06	\$6.52
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 09:56:32	02/23/2024 10:51:08	0.91	\$107.38
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 09:56:32	02/23/2024 10:51:08	(0.91)	(\$107.38)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/23/2024 09:56:32	02/23/2024 10:51:08	0.91	\$107.38
14-52-021	INSTALL GPS SYSTEM	12201267	02/22/2024 08:53:01	02/22/2024 08:58:06	0.08	\$10.00
14-52-021	INSTALL GPS SYSTEM	12201267	02/22/2024 08:53:01	02/22/2024 08:58:06	(0.08)	(\$10.00)

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>		<b>Quantity</b>	<b>Total Cost</b>
14-52-021	INSTALL GPS SYSTEM	12201267	02/22/2024 08:53:01	02/22/2024 08:58:06		0.08	\$10.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 09:30:00	01/22/2024 10:52:30		1.38	\$162.25
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 07:45:53	01/22/2024 09:15:00		1.49	\$175.26
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 09:30:00	01/22/2024 10:52:30		1.38	\$162.25
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 07:45:53	01/22/2024 09:15:00		1.49	\$175.26
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 09:30:00	01/22/2024 10:52:30		(1.38)	(\$162.25)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	01/22/2024 07:45:53	01/22/2024 09:15:00		(1.49)	(\$175.26)
						LABOR	520.41
Job Code	Job Description	Part No.	Descr	ription <u>L</u>	Jnit Price	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	SF16	SEA FOAM 16OZ		13.11	1	\$13.11
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	SF16	SEA FOAM 16OZ		13.11	(1)	(\$13.11)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	SF16	SEA FOAM 16OZ		13.11	1	\$13.11
						PARTS	13.11

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 49507

### **Work Order Notes**

(EHANNAH) scan out (EHANNAH) install GPS

(EHANNAH) inspect GPS- driver reports wires hanging down next to driver.

### **Job Notes**

#### 03-01-054 - REPLACE NEW BYPASS HEATER HOSE

(LISAPATE) Tuscaloosa Toyota installed coolant flow bypass valve. Pd by CC Toyota is sending a check to reimburse for tax charged. (IFALLS) Visit Reason Changed On 3/6/2024 10:42 AM By IFALLS

06-52-021 - INSPECT GPS SYSTEM

### 14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS # 87U030240050 in unit 2843C-GC (IFALLS) Visit Reason Changed On 3/6/2024 10:43 AM By IFALLS

### 16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Toyota by CW (IFALLS) Visit Reason Changed On 3/6/2024 10:43 AM By IFALLS

**CH-SP - CHARGE Shop Supplies** 

#### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(EHOWELL) Found DTCs: P268111 Engine Coolant Bypass Valve Circuit Short to Ground-Confirmed.

P26AC15 Engine Coolant Bypass Valve "B" Circuit Short to Battery or Open-Confirmed/Pending

P11EE00 Cylinder #3 Air Fuel Ratio Imbalance (Port)-Unknown

Followed diagnostic test procedure for DTC P268111. The coolant bypass valve (water switch valve) is receiving 12 volts, the resistance of the bypass valve ohms within specification, the wire between the valve and the engine control module is 0.5 ohms, and the wire is not shorted to ground. Also, commanded the valve on/off with a scan tool while monitoring the voltage sent to the bypass valve. The voltage ranged from 11.9 volts to 12.4 volts. This proves that the ECM is shorted to ground internally. Consulted a diagnostic chart in ProDemand and found the ECM as a possible cause for DTC P11EE. EH/JW

(JWRIGHT) already been scanned out previously and fixed. Rescanned and has no light on or codes stored. Ran for over an hour and test drove. Found no issues. Went ahead and added seafoam in case of bad fuel. JAW

(IFALLS) Visit Reason Changed On 3/6/2024 10:41 AM By IFALLS

UNIT NO: 243577 202		2020 TOY	OTA C	AMRY	•			WORK O	RDER NO:		50149			
WO STATUS: CL WO VISIT REASON: SO		507143 CLOSED SCHEDULED 20TOYOTACAMR	CLOSED CC SCHEDULED CL		OPENED DATE: COMPLETED DATE: CLOSED DATE: Byota Camry		03/26/202	03/26/2024 09:54:58 03/26/2024 12:41:56		LOCATION: GARAGE - METER 1 - M: 38562 IN-SERVICE DATE: UNIT SERIAL NO:		University Automotive S <b>METER 2 - N:</b> 11/27/2019 4T1C11AK2LU893149		
JOB CODE	_	JOB DESCRIPTION	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL	COMMERCIAL	TOTAL	COST
03-05-019	REPLAC	E NEW OXYGEN S	ENSOR	DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00		\$564.52	\$564.52	
16-05	TRANSP	ORT ELECTRONIC	ENGINE EE	DON	0	N	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
SO-00	SCAN O	UT COMPLETE VEI	HICLE	DON	0	N	GARAGE	0.08	\$9.74	\$0.00		\$0.00	\$9.74	
JOB COUN	IT: 4				WC	RK ORI	DER TOTAL:	0.58	68	3.74	0.00	569.52		638.26
Job Code		Job Descripti	<u>ion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	Purcha	ase Order No	<u>.</u>		<u>Total</u>	Cost
03-05-019	REPLACE N	IEW OXYGEN SENSO	OR	1	1076422	2	624	42369						\$564.52
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		569.52
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	<u>Total</u>	Cost
16-05	TRANSPOR	T ELECTRONIC ENG	INE EEC SYSTI	EM 1	1399745	5	03/	/26/2024 07:00:00	03/26/20	24 07:30:00		0.50		\$59.00
SO-00	SCAN OUT	COMPLETE VEHICLE	<u> </u>	1	1074414	ļ	03/	/19/2024 08:08:11	03/19/20	24 08:13:08		0.08		\$9.74
												LABOR		68.74

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 50149

**Work Order Notes** 

(EHANNAH) scan- out check engine light on

Job Notes

03-05-019 - REPLACE NEW OXYGEN SENSOR

(LISAPATE) Tuscaloosa Toyota scanned out installed new oxygen sensor air fuel ratio. Pd by CC

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Taken to Toyota by CW

**CH-SP - CHARGE Shop Supplies** 

### **SO-00 - SCAN OUT COMPLETE VEHICLE**

(SHARBIN) Scanned vehicle. P0420 code was stored. Possible catalytic convertor failure and a list of other possibilities. Sending to Toyota. SH

UNIT NO:		243577	2020 TOYO	TA C	AMRY	•			WORK O	RDER NO	): 5	50435		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAMRY	(	OPENE COMPL CLOSE oyota C	ETED D DAT	DATE:	04/05/20	24 07:13:45 24 13:32:29 24 14:20:12	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 39174 E <b>DATE</b> :	11/27/2	ity Automotive S <b>IETER 2 - N:</b> 019 AK2LU893149	Services 0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.41	\$47.82	\$61.79	\$	60.00	\$109.61	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00	
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	: 0.41	47	.82	61.79	5.00		114.61
Job Code		Job Descripti	<u>on</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	op Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	<u>on</u>		<u>En</u>	nployee	No.	<u>Start</u>	ļ	Finish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1:	2395904	1	04	1/05/2024 07:34:00	04/05/202	24 07:58:19		0.41		\$47.82
												LABOR		47.82
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0'	W16T		0	IL 0W16 CAM2 LS	PI SN4+ QT		8.2	5 5		\$41.25
66-PM-PMA	PERFORM (	OIL CHANGE		Р	G4476F		0	IL FILTER			7.4	3 1		\$7.43
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		s	EA FOAM 16OZ			13.1	11		\$13.11
												PARTS		61.79

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 50435

**Work Order Notes** 

(EHANNAH) pm

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

**CH-SP - CHARGE Shop Supplies** 

WA-00 - WASH COMPLETE VEHICLE

UNIT NO:		243577	2020 TOYO	OTA C	AMRY	•			WORK OR	DER NO	): 51	473		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTACAME		OPENE COMPL CLOSE oyota C	ETED	DATE:	07/22/202	24 07:29:00 24 08:02:34 24 08:02:40	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 41387 <b>DATE</b> :	<b>ME</b> 11/27/20	y Automotive ( E <b>TER 2 - N:</b> 19 .K2LU893149	Services 0	
JOB CODE	1	JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
66-17-028	PERFOR	M MOUNT AND B	ALANCE TIRE	DON	Ν	Ν	GARAGE	0.01	\$0.95	\$240.44	\$0	.00	\$241.39	
66-17-033	PERFOR	M TIRE ROTATIO	N AND BRAKE	DON	Р	N	GARAGE	0.00	\$0.00	\$0.00	\$0	.00	\$0.00	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.00	\$0.00	\$56.48	\$0	.00	\$56.48	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00	
JOB COUNT: 4		WORK ORDER TO			DER TOTAL:	0.01	0.0	95	296.92	5.00		302.87		
Job Code		Job Descrip	<u>tion</u>		V	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	tion		<u>En</u>	nployee	No.	Start Finish		<u>inish</u>		Quantity	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALAN	ICE TIRES	1	2395904	ļ.	07	/16/2024 10:24:57	07/16/2024	10:25:26		0.01		\$0.95
												LABOR		0.95
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LSI	PI SN4+ QT		7.31	5		\$36.53
66-PM-PMA	PERFORM (	OIL CHANGE		Р	G4476F		OI	L FILTER			6.84	1		\$6.84
66-PM-PMA	PERFORM (	OIL CHANGE		S	F16		SE	A FOAM 16OZ			13.11	1		\$13.11
66-17-028	PERFORM I	MOUNT AND BALAN	ICE TIRES	1	5576270	0000	TIF	RE 215/55R17 GE	N ALTIMAX		237.74	1		\$237.74
66-17-028	PERFORM I	MOUNT AND BALAN	ICE TIRES	6	3001		1/4	OZ STICK ON TA	APE WEIGHT		0.23	12		\$2.70
												PARTS	<del>-</del>	296.92

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 51473

**Work Order Notes** 

(EHANNAH) inspect tire- pm (EKIMBREL) FC

### **Job Notes**

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

#### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and Balanced 1 new tire on unit 2843C-GC (EKIMBREL) reused tpms kit

66-17-030 - PERFORM TIRE PATCH

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(EKIMBREL) FC ROTATED TIRES

### 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) perform oil changes FC

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

243577 **UNIT NO:** 2020 TOYOTA CAMRY **WORK ORDER NO:** 51912 **USING DEPT NO:** 507143 OPENED DATE: 08/23/2024 07:02:58 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 08/23/2024 13:51:30 COMPLETED DATE: **METER 1 - M:** 41789 METER 2 - N: **WO VISIT REASON: SCHEDULED CLOSED DATE:** 08/26/2024 15:35:18 **IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 COMMERCIAL TOTAL COST JOB CODE WRTY **MATERIAL** JOB DESCRIPTION STAT RSN JOB LOC LABOR HRS LABOR 66-17-028 PERFORM MOUNT AND BALANCE TIRE DON Ν **GARAGE** 0.00 \$0.00 \$182.28 \$182.28 \$0.00 CH-SP CHARGE Shop Supplies DON 2 **GARAGE** 0.00 \$0.00 \$0.00 \$5.00 \$5.00 JOB COUNT: 2 **WORK ORDER TOTAL:** 182.28 0.00 0.00 5.00 187.28 **Job Code Job Description** Vendor No. Invoice No. Purchase Order No. **Total Cost** CH-SP **CHARGE Shop Supplies** 503163 1 \$5.00 COMML 5.00 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 63001 0.20 8 \$1.56 66-17-028 PERFORM MOUNT AND BALANCE TIRES 1/4 OZ STICK ON TAPE WEIGHT 23131 3.33 66-17-028 PERFORM MOUNT AND BALANCE TIRES TPMS SNAP IN VALVE 21060 \$3.33 177.39 \$177.39 66-17-028 PERFORM MOUNT AND BALANCE TIRES 1557737 TIRE 215/55R17 GEN ALTIMAX **PARTS** 182.28

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 51912

**Work Order Notes** 

(EHANNAH) tire patch on RP tire

**Job Notes** 

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and Balanced 1 new tire on unit 2843C, Unit had small screw in tire to close to the side wall to be patched-GC Miles, 41,793

66-17-030 - PERFORM TIRE PATCH

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

**UNIT NO:** 243577 **2020 TOYOTA CAMRY WORK ORDER NO:** 51922 **USING DEPT NO:** 507143 **OPENED DATE:** 08/23/2024 14:24:38 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 08/30/2024 08:00:51 **WO STATUS: COMPLETED DATE: METER 1 - M**: 41793 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED CLOSED DATE:** 08/30/2024 10:11:17 **IN-SERVICE DATE:** 11/27/2019 **TECH SPEC NO:** 20TOYOTACAMRY 2020 Toyota Camry **UNIT SERIAL NO:** 4T1C11AK2LU893149 COMMERCIAL TOTAL COST JOB CODE **JOB DESCRIPTION** <u>STAT</u> RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** 25-52-021 REMOVE GPS SYSTEM DON 5 **GARAGE** 0.00 \$0.00 \$0.00 \$0.00 \$0.00 PD-00-999 GARAGE PREP DISPOSE PREPARE UNIT FOR DI DON D 0.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 2 **WORK ORDER TOTAL:** 0.00 0.00 0.00 0.00 0.00

The University of Alabama

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

UNIT NO: 243577 2020 TOYOTA CAMRY WORK ORDER NO: 51922

**Work Order Notes** 

(EHANNAH) PREP FOR SALE

**Job Notes** 

**25-52-021 - REMOVE GPS SYSTEM** 

(EHOWELL) GPS# 87U030240050 was removed.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) REMOVED ALL STROBE LIGHTS, UA EQUIPMENT AND LOGOS UNIT CHECKED OK,

Report Printed: 09/09/2024 13:42:56 By User: GLOBETTI

### Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Mon Sep 09 2024 13:42:56 Report User: GLOBETTI

TZ: Central Standard Time

**DLL Version:** 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### **Parameters and Selection Filters**

First Grouping: VIEW\_WO\_WORKSHEET.WO\_NO
Second Grouping: VIEW\_JOB\_WORKSHEET.JOB

**Third Grouping:** 

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'243577') //Q=