The University of Alabama

Work Order Charge Detail

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 27351

USING DEPT NO: 507203 OPENED DATE: 09/06/2017 09:55:15 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 09/07/2017 13:08:52
 METER 1 - M:
 992
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 09/07/2017 13:08:55
 IN-SERVICE DATE:
 09/01/2017

TECH SPEC NO: 17FORDF550 2017 Ford F550 **UNIT SERIAL NO**: 1FDAF5GY6HED32871

COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION STAT PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE DON С **GARAGE** 0.50 \$28.75 \$0.00 \$0.00 \$28.75 JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost**

PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE INSPECTION 11213180 09/06/2017 09:56:00 09/06/2017 10:26:00 0.50 \$28.75

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 27351

Work Order Notes

(LISAPATE) DO PDI NEW UNIT

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

(LISAPATE) DAMAGE TO REAR DRIVER QUARTER PANEL, REAR OF BUS ALSO HAS A DENT IN ROOF AND SMALL HOLE IN CEILING INSIDE

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

242430 **UNIT NO:** 2017 FORD F550 **WORK ORDER NO:** 27915 **USING DEPT NO:** 507203 OPENED DATE: 10/23/2017 09:09:01 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 10/24/2017 08:03:12 COMPLETED DATE: **METER 1 - M**: 1701 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 10/24/2017 08:03:14 **CLOSED DATE: IN-SERVICE DATE:** 09/01/2017 **TECH SPEC NO:** 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871 JOB CODE RSN WRTY JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT LABOR 14-02-010 **INSTALL MIRRORS** DON 0 **GARAGE** 0.70 \$40.25 \$198.17 \$238.42 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.70 40.25 198.17 0.00 238.42 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 14-02-010 **INSTALL MIRRORS** 11074414 10/23/2017 09:09:48 10/23/2017 09:51:48 0.70 \$40.25 **LABOR** 40.25 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 14-02-010 7C2Z17682BA 198.17 \$198.17 **INSTALL MIRRORS** MIRROR ASY **PARTS** 198.17

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 27915

Work Order Notes

(LISAPATE) THIS BUS HIT COMMUNITY SERVICE VAN 6274B WHILE TURNING AND BROKE THE MIRROR ON THE PASSENGER SIDE. NO OTHER DAMAGES. PER ANDRE TUCKER BILL MIRROR TO THIS VAN

Job Notes

14-02-010 - INSTALL MIRRORS

(LISAPATE) REMOVED AND REPLACED PASSENGER MIRROR. RECHECKED OK

The University of Alabama

Work Order Charge Detail

242430

2017 FORD F550

UNIT NO:

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

28349

WORK ORDER NO:

507203 **USING DEPT NO: OPENED DATE:** 12/06/2017 09:15:01 **LOCATION:** GARAGE - University Automotive Services **WO STATUS:** CLOSED 02/20/2018 14:34:43 **METER 2 - N:** 0 **COMPLETED DATE: METER 1 - M**: 2574 SCHEDULED **WO VISIT REASON: CLOSED DATE:** 02/20/2018 14:34:47 **IN-SERVICE DATE:** 09/01/2017 17FORDF550 **TECH SPEC NO:** 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	<u>MATERIAI</u>	L COI	MMERCIAL PROPERTY NAMED IN COLUMN 1	TOTAL COST
15-71-032	WARRANTY WATER LEAK INTERIOR/E>	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.0	0	\$0.00
JOB COUN	Т: 1		wo	RK ORI	DER TOTAL:	0.00	0.0	00 0.	.00	0.00	0.00
Job Code	Job Description		V	endor N	lo.	Invoice No.	Purchas	e Order No.			Total Cost
15-71-032	WARRANTY WATER LEAK INTERIOR/EXTERIOR	R 1	11269864		228	12504	0042348				\$0.00
									-	COMML	0.00

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 28349

Work Order Notes

(LISAPATE) ROOF HAS MULTIPLE LEAKS-FIRST 3 SEATS BY WINDOW ON PASSNGER SIDE-DRIVER SIDE AND EMERGENCY HATCH-DELAER WILL SEND A TECH TO THE GARAGE TO REPAIR ONSITE

Job Notes

15-71-032 - WARRANTY WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) LEAK REPAIRED UNDER WARRANTY, GAPS IN SEALANT AROUND THE ESCAPE HATCH AND ROOF RAILS, CLEANED AND SEALED MOLDINGS AND ROOF RAILS

UNIT NO:		242430	2017 FORI	D F550)				WORK C	RDER NO	D: 2	9063	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DATI	DATE:	03/19/201	18 10:37:32 18 14:43:39 18 14:43:41	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 3473 E DATE:	N 09/01/2	ity Automotive S 1ETER 2 - N: 017 5GY6HED3287	0
JOB CODE	_	JOB DESCRIPTION M OIL CHANGE	<u>ON</u>	STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.31	LABOF \$17.83	<u>MATI</u> \$22.11		COMMERCIAL 0.00	TOTAL COST \$39.94
JOB COUN					WO	RK ORI	DER TOTAL:			7.83	22.11	0.00	•
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	1758845	;	03	/07/2018 07:00:00	03/07/20	018 07:18:36		0.31	\$17.83
												LABOR	17.83
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	Des	cription		Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5	W20P		5V	V20 FS QRT OIL			2.5	9 7	\$18.13
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			3.9	8 1	\$3.98
												PARTS	22.11

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 29063

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS COOLANT -27'

UNIT NO:		242430	2017 FOR) F550)				WORK O	RDER N	0: 2	29627		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED	DATE:	06/29/20	018 15:47:23 018 07:41:13 018 07:41:15	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 4253 E DATE:	N 09/01/2		0	
JOB CODE	<u> </u>	JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL (COMMERCIAL	TOTAL	COST
03-01-056	REPLAC	E NEW A/C ORFIC	CE VALVE/FILT	DON	0	Ν	GARAGE	2.00	\$115.00	\$80.22	\$	0.00	\$195.22	
35-01	DIAGNO	SE AIR CONDITIC	NING, HEAT, '	DON	0	Ν	GARAGE	0.50	\$28.75	\$0.00	\$	0.00	\$28.75	
66-01-058	PERFOR	M EVAC AND REG	CHARGE FRE	DON	0	N	GARAGE	1.00	\$57.50	\$8.95	\$	60.00	\$66.45	
JOB COUN	T: 3				wo	RK ORI	DER TOTAL	_: 3.50	201	1.25	89.17	0.00		290.42
Job Code		Job Descrip	tion		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-01-058	PERFORM E	EVAC AND RECHAR	GE FREON	1	1268671		C	6/28/2018 09:30:00	06/28/20	18 10:30:00		1.00		\$57.50
35-01	DIAGNOSE	AIR CONDITIONING	6, HEAT, VENT	1	1268671		C	6/28/2018 07:00:00	06/28/20	18 07:30:00		0.50		\$28.75
03-01-056	REPLACE N	EW A/C ORFICE VA	LVE/FILTER	1	1268671		C	6/28/2018 07:30:00	06/28/20	18 09:30:00		2.00		\$115.00
												LABOR	-	201.25
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	cription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
03-01-056	REPLACE N	EW A/C ORFICE VA	LVE/FILTER	F	OR3863	9	C	ORFICE TUBE			1.1	3 1		\$1.13
03-01-056	REPLACE N	EW A/C ORFICE VA	LVE/FILTER	F.	A1928		P	IR FILTER			53.1	5 1		\$53.15
03-01-056	REPLACE N	EW A/C ORFICE VA	LVE/FILTER	V	СЗВ		F	ORD ORANGE AN	TIFREEZE		25.9	4 1		\$25.94
66-01-058	PERFORM E	EVAC AND RECHAR	GE FREON	Е	STER O	IL	A	/C ESTER OIL OU	NCE		0.9	8 2		\$1.96
66-01-058	PERFORM E	EVAC AND RECHAR	GE FREON	R	ECYCLE	ED FREO	N LB F	RECLAIMED FREO	N LB		1.5	0 4		\$6.00
66-01-058	PERFORM E	EVAC AND RECHAR	GE FREON	R	ECYCLE	ED FREO	N OZ F	RECLAIMED FREO	N OZ		0.0	9 11		\$0.99
												PARTS		89.17

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 29627

Work Order Notes

(LISAPATE) FRONT A/C NOT COOLING AT TIMES

Job Notes

03-01-056 - REPLACE NEW A/C ORFICE VALVE/FILTER

(LISAPATE) REPLACED ORFICE AND CLEANED FILTER AT CONDENSER. REPLACED AIR FILTER
TOPPED OFF ANTIFREEZE

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(RWINTERS) IF FOLLOWED ACC REPAIR PROCEDURE REMOVED ORIFICE AND FILTER AT CONDENSER TOOK PICTURES AND SENT TO SHAWN LARSON 1-574-264-2190

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) EVAC AND RECHARGED. RECHECKED COOLING GOOD RECOVERED 4.68LBS
RECYCLED 4.11 ADDED 2 OZ OF OIL W/DYE

UNIT NO:		242430	2017 FORI	D F550)				WORK	ORDER NO	D: 3	0705	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED D DATI	DATE:	09/28/201	18 14:13:38 18 10:37:35 18 10:37:37	METER '		N 09/01/20	ity Automotive S IETER 2 - N: 017 5GY6HED3287	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LAB	OR MAT	ERIAL C	COMMERCIAL	TOTAL COST
15-71-032	WARRAN	NTY WATER LEAK	NTERIOR/E	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$	0.00	\$0.00
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.47	\$0.00	\$45.37	\$	0.00	\$45.37
JOB COUN	IT: 2				wo	RK ORE	DER TOTAL:	0.47		0.00	45.37	0.00	45.37
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total Cost</u>
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357		08	/30/2018 09:59:08	08/30	/2018 10:27:06		0.47	\$0.00
												LABOR	0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			3.98	8 1	\$3.98
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		BU	ILK OIL 5W20 SY	NTHETIC T	HOMAS	3.2	7 7	\$22.89
66-PM-PMA	PERFORM (OIL CHANGE		V	СЗВ		FC	ORD ORANGE AN	TIFREEZE		18.50	0 1	\$18.50
												PARTS	45.37

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 30705

Work Order Notes

(LISAPATE) PM

(LISAPATE) Bus was picked up by Creative Bus sales and taken to Georgia

Job Notes

15-71-032 - WARRANTY WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) WO closed for fiscal Year End vehicle is not repaired it is still in Georgia

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,EK/AG Coolant -35'

The University of Alabama

Work Order Charge Detail

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 31001

USING DEPT NO: 507203 OPENED DATE: 10/02/2018 09:25:01 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 10/11/2018 07:15:31
 METER 1 - M: 5830
 METER 2 - N: 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 10/11/2018 07:15:33
 IN-SERVICE DATE: 09/01/2017

TECH SPEC NO: 17FORDF550 2017 Ford F550 **UNIT SERIAL NO**: 1FDAF5GY6HED32871

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMER	CIAL TOTAL	COST
15-71-032	WARRANTY WATER LEAK INTERIOR/E>	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00	
JOB COUNT	: 1		wo	RK ORI	DER TOTAL:	0.00	0	.00 0.	00	0.00	0.00

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 31001

Work Order Notes

(LISAPATE) Previous WO closed due to end of fiscal year. Bus is at Creative Bus sales having water leaks fixed

Job Notes

15-71-032 - WARRANTY WATER LEAK INTERIOR/EXTERIOR

(LISAPATE) Creative Bus Sales picked the bus up and took it to Georgia they resealed the roof and all the windows to repair the water leak. No invoice of the repair was provided.

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 **WORK ORDER NO:** 31210 **USING DEPT NO:** 507203 **OPENED DATE:** 10/18/2018 10:49:37 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 10/23/2018 08:11:18 COMPLETED DATE: **METER 1 - M**: 6436 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 10/23/2018 08:11:19 **CLOSED DATE: IN-SERVICE DATE:** 09/01/2017 **TECH SPEC NO:** 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871 COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION STAT 66-79-002 PERFORM SERVICE CALL DON В **GARAGE** 1.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 1 WORK ORDER TOTAL: 1.00 0.00 0.00 0.00 0.00 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 66-79-002 PERFORM SERVICE CALL 11213180 10/18/2018 10:50:12 10/18/2018 11:50:12 1.00 \$0.00 **LABOR** 0.00

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 31210

Work Order Notes

(IFALLS) Debbie requested a service call to Ridgecrest South something smells like burning from vents and smell is coming from under the hood.

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) MS/EH completed service call found leaves on top of exhaust manifold. Drove bus to the shop blew out engine bay. rechecked ok

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

242430 **UNIT NO:** 2017 FORD F550 **WORK ORDER NO:** 31931 **USING DEPT NO:** 507203 OPENED DATE: 01/15/2019 10:00:53 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 01/17/2019 07:09:08 COMPLETED DATE: **METER 1 - M:** 6990 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 01/17/2019 07:09:09 **CLOSED DATE: IN-SERVICE DATE:** 09/01/2017 **TECH SPEC NO:** 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871 COMMERCIAL TOTAL COST JOB CODE JOB LOC LABOR HRS **MATERIAL** JOB DESCRIPTION STAT RSN WRTY LABOR 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 1.24 \$0.00 \$78.76 \$78.76 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 1.24 0.00 78.76 0.00 78.76 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 11074414 01/15/2019 14:15:00 01/15/2019 14:30:14 0.25 \$0.00 66-PM-PMA PERFORM OIL CHANGE 0.99 \$0.00 11074414 01/15/2019 13:00:37 01/15/2019 14:00:00 **LABOR** 0.00 **Job Description** Part No. Description **Unit Price** Quantity **Total Cost** Job Code 7 **BULK OIL 5W20 SYNTHETIC THOMAS** 3.09 \$21.63 66-PM-PMA PERFORM OIL CHANGE 5W20BT 53.15 \$53.15 66-PM-PMA PERFORM OIL CHANGE FA1928 AIR FILTER 66-PM-PMA PERFORM OIL CHANGE BALB329 OIL FILTER 3.98 \$3.98 **PARTS** 78.76

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 31931

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC,SH/SH,EK Replaced air filter Coolant -35'

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 32769

USING DEPT NO: 507203 OPENED DATE: 04/30/2019 08:36:25 LOCATION: GARAGE - University Automotive Services

WO STATUS: CLOSED **COMPLETED DATE:** 05/24/2019 07:17:41 **METER 1 - M:** 8517 **METER 2 - N:** 0

WO VISIT REASON: SCHEDULED **CLOSED DATE:** 05/24/2019 07:17:43 **IN-SERVICE DATE**: 09/01/2017

TECH SPEC NO: 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILT	DON	0	Ν	GARAGE	2.50	\$0.00	\$1.29	\$0.00	\$1.29
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	DON	Р	N	GARAGE	2.00	\$0.00	\$180.15	\$0.00	\$180.15
03-15-009	REPLACE NEW TIE ROD	DON	0	N	GARAGE	1.50	\$0.00	\$64.36	\$0.00	\$64.36
03-15-020	REPLACE NEW DRAG LINK	DON	0	N	GARAGE	1.50	\$0.00	\$73.23	\$0.00	\$73.23
09-15	ALIGN STEERING	DON	0	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT,	DON	0	N	GARAGE	6.00	\$0.00	\$0.00	\$0.00	\$0.00
36-01	FLUSH AIR CONDITIONING, HEAT, VEN	DON	0	N	GARAGE	1.50	\$0.00	\$55.20	\$0.00	\$55.20
66-01-058	PERFORM EVAC AND RECHARGE FREE	DON	0	N	GARAGE	7.00	\$0.00	\$39.65	\$0.00	\$39.65
66-79-003	PERFORM SAFETY INSPECTION	DON	0	N	GARAGE	2.57	\$0.00	\$5.89	\$0.00	\$5.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	0	N	GARAGE	2.00	\$0.00	\$15.37	\$0.00	\$15.37

JOB COUNT: 10	WORK ORDER TOTAL:	27.57	0.00	435.14	0.00	435.14
	 	0.1			0	-

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11213180	05/23/2019 07:00:00	05/23/2019 09:00:00	2.00	\$0.00
36-01	FLUSH AIR CONDITIONING, HEAT, VENT	11213180	05/23/2019 09:00:00	05/23/2019 10:30:00	1.50	\$0.00
09-15	ALIGN STEERING	11213180	05/23/2019 10:30:00	05/23/2019 11:30:00	1.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11213180	05/23/2019 07:00:00	05/23/2019 14:00:00	7.00	\$0.00
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	11213180	05/23/2019 09:30:00	05/23/2019 11:30:00	2.00	\$0.00
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	11213180	05/23/2019 07:00:00	05/23/2019 09:30:00	2.50	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	05/23/2019 07:00:00	05/23/2019 13:00:00	6.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	05/01/2019 11:15:53	05/01/2019 13:49:57	2.57	\$0.00
03-15-009	REPLACE NEW TIE ROD	11213180	05/23/2019 07:00:00	05/23/2019 08:30:00	1.50	\$0.00
03-15-020	REPLACE NEW DRAG LINK	11213180	05/23/2019 08:30:00	05/23/2019 10:00:00	1.50	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	SHIPPING	SHIPPING AND HANDLING	18.23	1	\$18.23
36-01	FLUSH AIR CONDITIONING, HEAT, VENT	A/C FLUSH	A/C FLUSH DURA II 32OZ	27.60	2	\$55.20
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	207316	ORIFICE TUBE	1.29	1	\$1.29
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.20	12	\$2.40
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	16	\$16.16
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON LB	RECLAIMED FREON LB	1.50	9	\$13.50
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	16	\$1.44
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	218349	DESSICANT KIT, CONDENSER SVC	20.63	(1)	(\$20.63)
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	217517	EXPANSION VALVE	31.71	(1)	(\$31.71)
03-15-009	REPLACE NEW TIE ROD	ES800880	TIE ROD END	123.57	(1)	(\$123.57)
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	218349	DESSICANT KIT, CONDENSER SVC	20.63	1	\$20.63
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	217517	EXPANSION VALVE	31.71	1	\$31.71
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	11132871A	A/C ACCUM/FILTER/ORIFICE KIT	80.96	2	\$161.92
03-15-009	REPLACE NEW TIE ROD	ES3420S	ADJUSTING SLEEVE	18.49	1	\$18.49
03-15-009	REPLACE NEW TIE ROD	ES800880	TIE ROD END	123.57	1	\$123.57
03-15-009	REPLACE NEW TIE ROD	DS300008	TIE ROD, RH CONNECTING	45.87	1	\$45.87
03-15-020	REPLACE NEW DRAG LINK	2696128	INNER TIE ROD / DRAG LINK ASSY	73.23	1	\$73.23
66-79-003	PERFORM SAFETY INSPECTION	40032	DOT 4 BRAKE FLUID 32OZ	5.89	1	\$5.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	15.37	1	\$15.37
66-01-058	PERFORM EVAC AND RECHARGE FREON	FJC2468	A/C PAG OIL	6.15	1	\$6.15
					PARTS	435.14

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 32769

Work Order Notes

(LISAPATE) Check A/C front unit not cooling

Job Notes

03-01-056 - REPLACE NEW A/C ORFICE VALVE/FILTER

(LISAPATE) Replaced the front and rear orifice valve . *** see evac and recharge for additional notes ***

03-01-063 - REPLACE NEW ACCUMULATOR/DRIER

(LISAPATE) Replaced the front and rear units accumulator *** see evac and recharge for additional notes ***

03-15-009 - REPLACE NEW TIE ROD

(LISAPATE) Replaced tie rod and adjusting sleeve

03-15-020 - REPLACE NEW DRAG LINK

(LISAPATE) Replaced drag link

09-15 - ALIGN STEERING

(LISAPATE) MS Performed alignment

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) Found A/C unit to be icing over

36-01 - FLUSH AIR CONDITIONING, HEAT, VENT

(LISAPATE) Flushed lines, condenser and evaporator.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) ** FRONT UNIT** Found unit to be icing over. Recovered freon and replaced accumulator and orifice. Performed vacuum check and leak test, passed both. Recharged to spec of 4lbs 12oz and added 2 oz of oil. Also replaced cabin filter.

REAR UNIT Recovered system and replaced accumulator and orifice. Found orifice to have lots of debris(dust) on it. Flushed lines, condenser and evaporator. Recharged system to spec of 5lbs and added 9oz of oil. Noticed low pressure going almost into a vacuum. Pulled back down and replaced orifice again. Recharged system to 5.5lbs system still had low pressures. Called ACC they advised adding 0.5 lbs until pressures were within spec according to ambient temp. Pulled system down again inspected orifice, appeared clean, reinstalled new orifice and charge to spec 5.0 lbs ended up having to add 5oz more of oil due to recovering and recharging system so many times. Performed evac and recharge a total of 6 times. Vehicle is cooling and operating normally at this time. Advise customer to bring bus back in hotter weather (June,July) to recheck and verify pressures are still within spec

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SH/AG/MS Performed Safety inspection. See attached

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

UNIT NO:		242430	2017 FOR	D F550					WORK	ORDER N	0:	33527	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550	2017	OPENE COMPL CLOSE Ford F55	ETED I	DATE:	07/25/20	019 08:32:04 019 20:00:00 019 20:00:00	METER 1	- M: 9528 CE DATE:	09/01/2	sity Automotive S METER 2 - N: 2017 F5GY6HED3287	0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION M OIL CHANGE	<u>ON</u>	STAT DON	RSN P	WRTY N	JOB LOG GARAGE	LABOR HRS 1.38		<u>MAT</u> \$27.44		COMMERCIAL \$0.00	TOTAL COST \$27.44
JOB COUN	IT: 1				wo	RK ORI	DER TOTA	_: 1.3	8	0.00	27.44	0.00	27.44
Job Code 66-PM-PMA	PERFORM (Job Descript	<u>ion</u>	11	<u>Em</u> 074414	ployee		<u>Start</u> 7/25/2019 09:40:2	9 07/25/2	<u>Finish</u> 2019 09:54:48		Quantity 0.24	Total Cost \$0.00
66-PM-PMA	PERFORM (OIL CHANGE		11	901357		(7/25/2019 08:54:0	7 07/25/2	2019 10:02:47		1.14 LABOR	\$0.00 0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>De</u>	scription_		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		CI	MP		N	OBILE CM-P TUE	BE GREASE		2.8	81 1	\$2.81
66-PM-PMA	PERFORM (OIL CHANGE		5\	W20BT		E	BULK OIL 5W20 S	NTHETIC TH	IOMAS	2.9	95 7	\$20.65
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		(OIL FILTER			3.9	98 1	\$3.98
												PARTS	27.44

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 33527

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG Coolant -35'

UNIT NO:		242430	2017 FORI	D F550)				WORK O	RDER NO	D: 3	35021		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	12/05/20	019 15:07:20 019 07:25:25 019 07:25:26	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 11007 E DATE:	M 09/01/20	ity Automotive S 1ETER 2 - N: 017 5GY6HED3287	0	
JOB CODE	- '	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY		<u> </u>	LABOR		_	COMMERCIAL	TOTAL COS	I
31-17	ROTATE	TIRES, TUBES, LII	NERS & VALV	DON	0	N	GARAGE	0.57	\$0.00	\$0.00	\$	0.00	\$0.00	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	2.15	\$0.00	\$64.25	\$	0.00	\$64.25	
JOB COUN	T: 2				wo	RK OR	DER TOTAL	.: 2.72	2 (0.00	64.25	0.00	64.	.25
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost	
31-17	ROTATE TIR	ES, TUBES, LINERS	& VALVES	1:	2052187	7	1.	2/03/2019 08:38:11	12/03/20	019 09:12:40		0.57	\$0	0.00
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357	,	1	2/03/2019 06:26:26	12/03/20	019 08:35:15		2.15	\$0	0.00
												LABOR	0	.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>).</u>	Des	scription		Unit Price	Quantity	Total Cost	
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		C	IL FILTER			3.98	8 1	\$3	3.98
66-PM-PMA	PERFORM (OIL CHANGE		2	00697		А	IR FILTER			33.02	2 1	\$33	3.02
66-PM-PMA	PERFORM (OIL CHANGE		0	5089		В	RAKE CLEAN NOI	N-FLAMMABLE	E 140Z	4.29	9 1	\$4	1.29
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		В	ULK OIL 5W20 SY	NTHETIC THO	DMAS	2.8	7 8	\$22	2.96

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 35021

Work Order Notes

(EKIMBREL) pm

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires, adjusted tire pressures and torqued lugs to 165lbs

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,AG/AG Coolant -35' Replaced air filter Syn 3.1

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO:	242430	2017 FORD F550		WORK ORDER NO: 36070	
USING DEPT NO:	507203	OPENED DATE:	03/26/2020 13:44:47	LOCATION: GARAGE - University Automotive Services	

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 05/08/2020 09:00:46
 METER 1 - M:
 12199
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 05/08/2020 11:30:23
 IN-SERVICE DATE:
 09/01/2017

TECH SPEC NO: 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-79-045	ADJUST WHEELCHAIR HYD CYLINDER	DON	Р	Ν	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00
03-14-002	REPLACE NEW BUMPERS & ATTACHIN	DON	0	N	GARAGE	1.22	\$0.00	\$507.93	\$0.00	\$507.93
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	0	N	GARAGE	3.28	\$0.00	\$0.00	\$0.00	\$0.00
06-71-032	INSPECT WATER LEAK INTERIOR/EXTE	DON	0	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREG	DON	0	N	GARAGE	1.00	\$0.00	\$8.38	\$0.00	\$8.38
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	0	N	GARAGE	0.85	\$0.00	\$300.93	\$0.00	\$300.93
66-79-003	PERFORM SAFETY INSPECTION	DON	0	N	GARAGE	1.20	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.89	\$0.00	\$50.41	\$0.00	\$50.41

JOB COUNT: 8	WORK ORDER TOTAL:	10.94	0.00	867.65	0.00	867.65
--------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/04/2020 13:29:52	05/04/2020 14:00:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/04/2020 14:15:00	05/04/2020 14:38:00	0.38	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	05/04/2020 14:38:44	05/04/2020 15:50:54	1.20	\$0.00
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11213180	05/05/2020 06:58:53	05/05/2020 09:15:00	2.27	\$0.00
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11213180	05/05/2020 09:30:00	05/05/2020 10:30:44	1.01	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11213180	05/08/2020 07:00:00	05/08/2020 08:00:00	1.00	\$0.00
06-71-032	INSPECT WATER LEAK INTERIOR/EXTERIOR	11213180	05/08/2020 07:00:00	05/08/2020 07:30:00	0.50	\$0.00
01-79-045	ADJUST WHEELCHAIR HYD CYLINDER	11213180	05/08/2020 07:00:00	05/08/2020 09:00:00	2.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	05/06/2020 13:02:44	05/06/2020 13:53:33	0.85	\$0.00
03-14-002	REPLACE NEW BUMPERS & ATTACHING PARTS	11074414	05/04/2020 14:38:00	05/04/2020 15:51:19	1.22	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	<u>Description</u>	<u>Unit Price</u>	Quantity	Total Cost
03-14-002	REPLACE NEW BUMPERS & ATTACHING PARTS	BS021047	BUMPER REAR STD 7X97"	287.00	1	\$287.00

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-14-002	REPLACE NEW BUMPERS & ATTACHING PARTS	BX050511	BUMPER BRACKET	28.50	1	\$28.50
03-14-002	REPLACE NEW BUMPERS & ATTACHING PARTS	BS021669	BUMPER ANTI-RIDE PLATE	192.43	1	\$192.43
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	7	\$27.16
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	19.27	1	\$19.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05125520000	TIRE CONTI 225/70R19.5 HSR LRG	298.53	1	\$298.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.06	1	\$1.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	LT1	19.5 WHEEL WEIGHT	0.67	2	\$1.34
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.19	8	\$1.52
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	0.74	1	\$0.74
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	68	\$6.12
					PARTS	867.65

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 36070

Work Order Notes

(RTUNAITI) Replace rear bumper, apply new DOT tape (EKIMBREL) PM

Job Notes

01-55-038 - ADJUST CARGO DOOR LIFT SPRINGS

(EKIMBREL) MS had to adjust spring tension on wheelchair lift loading ramp. Would not travel all the way down. 2.0 hrs

01-79-045 - ADJUST WHEELCHAIR HYD CYLINDER

(IFALLS) MS inspected wheel chair lift and found bottom kick plate not letting down properly, IF manually let lift down and kick plate started working normally. MS had to adjust tension spring for kick plate.

03-14 - REPLACE NEW FRAME

03-14-002 - REPLACE NEW BUMPERS & ATTACHING PARTS

(EKIMBREL) SH/AG removed and replaced rear bumper.

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(GARAGE) Job 06-01 was added on-the-fly by 11213180 on 05/05/2020 07:00:42.

(EKIMBREL) MS recovered system and found it to be 8oz undercharged. Inspected orifice tube, looked fine. Found high side service point leaking.

06-71-032 - INSPECT WATER LEAK INTERIOR/EXTERIOR

(EKIMBREL) AG found left side emergency window wire harness caught between window seal. Moved wire and rechecked. No leaks.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EKIMBREL) MS replaced service valve. Performed vacuum and leak test, passed both. Recharged to spec of 4.75lbs and added 1oz of oil with dye. A/C cooling. Front a/c was only system not working, rear still works fine.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) MS/AG replaced and balanced RF tire.

66-79-003 - PERFORM SAFETY INSPECTION

(EKIMBREL) EK/AG performed safety inspection.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/SH performed pm. Coolant -35

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 **WORK ORDER NO:** 37852 **USING DEPT NO:** 507203 OPENED DATE: 10/02/2020 08:08:00 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 10/02/2020 09:14:45 COMPLETED DATE: **METER 1 - M**: 12274 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 10/02/2020 11:53:37 **CLOSED DATE: IN-SERVICE DATE:** 09/01/2017 **TECH SPEC NO:** 17FORDF550 2017 Ford F550 **UNIT SERIAL NO:** 1FDAF5GY6HED32871 JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 0.32 \$38.32 \$0.00 \$0.00 \$38.32 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.32 38.32 0.00 0.00 38.32 **Job Code Job Description** Employee No. **Start Finish** Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 10/02/2020 08:17:26 10/02/2020 08:35:04 0.29 \$34.68 66-PM-PMA PERFORM OIL CHANGE 0.03 \$3.64 11901357 10/02/2020 08:14:32 10/02/2020 08:16:23 LABOR 38.32

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 37852

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 75 miles. Updated sticker and checked all fluids and tires. Coolant -34° AB,MS,JAW

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO:	242430	2017 FORD F550	WORK ORDER NO:	39255

USING DEPT NO: 507203 OPENED DATE: 03/01/2021 15:52:12 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 03/29/2021 11:17:20
 METER 1 - M:
 13565
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 03/29/2021 15:09:00
 IN-SERVICE DATE:
 09/01/2017

WORK ORDER TOTAL:

TECH SPEC NO: 17FORDF550 2017 Ford F550 **UNIT SERIAL NO**: 1FDAF5GY6HED32871

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
03-01-006	REPLACE NEW CONDENSER	DON	0	Ν	GARAGE	3.70	\$436.83	\$253.13	\$0.00	\$689.96
03-01-077	REPLACE NEW EXPANSION VALVE	DON	0	N	GARAGE	0.41	\$48.58	\$58.80	\$0.00	\$107.38
06-42	INSPECT COOLING SYSTEM	DON	0	N	GARAGE	0.03	\$3.44	\$0.00	\$0.00	\$3.44
66-01-058	PERFORM EVAC AND RECHARGE FRE	DON	0	N	GARAGE	0.47	\$55.98	\$12.12	\$0.00	\$68.10
66-79-003	PERFORM SAFETY INSPECTION	DON	Υ	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	1.05	\$124.23	\$45.83	\$0.00	\$170.06

5.77

680.86

369.88

						-
Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
06-42	INSPECT COOLING SYSTEM	11170580	03/22/2021 15:03:47	03/22/2021 15:05:32	0.03	\$3.44
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/25/2021 07:00:00	03/25/2021 07:06:00	0.10	\$11.80
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	03/22/2021 10:02:21	03/22/2021 10:30:49	0.47	\$55.98
03-01-077	REPLACE NEW EXPANSION VALVE	11170580	03/22/2021 09:37:31	03/22/2021 10:02:13	0.41	\$48.58
03-01-006	REPLACE NEW CONDENSER	11170580	03/22/2021 09:30:00	03/22/2021 09:37:18	0.12	\$14.36
03-01-006	REPLACE NEW CONDENSER	11170580	03/22/2021 08:23:30	03/22/2021 09:15:00	0.86	\$101.28
03-01-006	REPLACE NEW CONDENSER	11170580	03/16/2021 10:37:46	03/16/2021 13:21:05	2.72	\$321.19
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/02/2021 08:43:02	03/02/2021 09:46:12	1.05	\$124.23
					LABOR	680.86

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	1072	BATTERY CLEANER SPRAY 13 OZ	5.09	1	\$5.09
66-PM-PMA	PERFORM OIL CHANGE	1072	BATTERY CLEANER SPRAY 13 OZ	5.09	(1)	(\$5.09)
66-PM-PMA	PERFORM OIL CHANGE	1072	BATTERY CLEANER SPRAY 13 OZ	5.09	1	\$5.09
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
03-01-006	REPLACE NEW CONDENSER	CC30089C	CONDENSER	164.25	1	\$164.25
03-01-077	REPLACE NEW EXPANSION VALVE	FOR39517	EXPANSION VALVE	43.88	1	\$43.88

JOB COUNT: 6

1,050.74

0.00

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
03-01-077	REPLACE NEW EXPANSION VALVE	FOR39517	EXPANSION VALVE	43.88	(1)	(\$43.88)
03-01-006	REPLACE NEW CONDENSER	CC30089C	CONDENSER	164.25	(1)	(\$164.25)
03-01-006	REPLACE NEW CONDENSER	HC3Z19712C	CONDENSER	253.13	1	\$253.13
03-01-077	REPLACE NEW EXPANSION VALVE	HL3Z19849D	EXPANSION VALVE	58.80	1	\$58.80
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.10	1	\$1.10
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	5	\$1.43
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	71	\$9.59
					PARTS	369.88

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 39255

Work Order Notes

(LISAPATE) PM-Front A/C will not get cold

Job Notes

03-01-006 - REPLACE NEW CONDENSER

(ABLACK) AB installed a new condenser. AC is cooling better now.

03-01-077 - REPLACE NEW EXPANSION VALVE

(ABLACK) AB installed a new expansion valve and seals. Rechecked ok.

06-42 - INSPECT COOLING SYSTEM

(ABLACK) AB inspected AC system. Found it needed a new expansion valve and a condenser.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(ABLACK) AB performed evac and recharge on front ac unit.

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SI done by JW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW MILEAGE-13565

UNIT NO:		242430	2017 FORI	D F550)				WORK OR	DER NO:	40514	
USING DEP WO STATUS WO VISIT RI TECH SPEC	EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	08/04/202	1 08:35:58 1 14:23:42 1 07:50:59	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	: 15111 DATE: 09/	iversity Automotive METER 2 - N: 01/2017 DAF5GY6HED3287	0
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLAC	E NEW BATTERY		DON	0	N	GARAGE	0.12	\$14.03	\$123.60	\$0.00	\$137.63
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	N	GARAGE	0.10	\$11.80	\$14.67	\$0.00	\$26.47
35-01	DIAGNO	SE AIR CONDITION	NING, HEAT, '	DON	0	N	GARAGE	0.61	\$71.98	\$0.00	\$0.00	\$71.98
66-01-058	PERFOR	RM EVAC AND REC	HARGE FRE	DON	Ο	N	GARAGE	1.00	\$118.00	\$27.70	\$0.00	\$145.70
66-79-003	PERFOR	RM SAFETY INSPE	CTION	DON	Υ	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	2.68	\$315.95	\$35.60	\$0.00	\$351.55
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
JOB COUN	Т: 7				WC	RK ORE	DER TOTAL:	4.61	543.5	66 201.	57 2.00	747.13
Job Code		Job Descript	ion		V	endor N	<u>o.</u>	Invoice No.	Purchase	e Order No.		Total Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1					\$2.00

					COMML	2.00
Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/30/2021 11:12:36	07/30/2021 11:12:36	0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/30/2021 11:12:36	07/30/2021 11:12:36	0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/30/2021 11:12:36	07/30/2021 12:12:36	1.00	\$118.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/22/2021 12:17:50	07/22/2021 13:44:29	1.44	\$170.41
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/22/2021 12:32:43	07/22/2021 13:46:43	1.23	\$145.53
03-32-002	REPLACE NEW BATTERY	12052187	07/22/2021 13:44:42	07/22/2021 13:51:50	0.12	\$14.03
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/30/2021 11:12:36	07/30/2021 11:18:36	0.10	\$11.80
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/30/2021 11:12:36	07/30/2021 11:18:36	(0.10)	(\$11.80)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	07/30/2021 13:11:25	07/30/2021 13:48:01	0.61	\$71.98
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/02/2021 07:00:00	08/02/2021 07:06:00	0.10	\$11.80
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/02/2021 07:00:00	08/02/2021 07:06:00	0.10	\$11.80

The University of Alabama

					LABOR	543.55
Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	651	BATTERY BCI 65 750CCA	123.60	1	\$123.60
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.62	1	\$4.62
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.34	2	\$14.67
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	60	\$17.10
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	1	\$1.01
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	71	\$9.59
					PARTS	201.57

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

242430 2017 FORD F550 WORK ORDER NO: 40514 **UNIT NO:**

Work Order Notes

(LISAPATE) PM-Do a safety inspection

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. Alt charging at 13.9 volts. JAW

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(ABLACK) AB found the front ac system was overcharged and building very high head pressure. Needs to have freon level adjusted in system.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(ABLACK) AB performed evac and recharge. Pulled out 4lbs 7oz of freon. Vacuumed system and added 3lbs 8oz to system and was cooling much better since the head pressure was much lower. Added another 4 oz to the system for a total of 3lbs 12oz of freon. System was overcharged. Rechecked ok.

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) JW performed safety inspection

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service and bus checklist. Coolant -34°. JAW/AMG MILEAGE-15111

UNIT NO:		242430	2017 FOR	D F550)				WORK OF	RDER NO:	: 40	981		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED D DAT	DATE:	09/14/202	1 08:47:32 1 13:12:34 1 13:23:44	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 15585 DATE:	ME 09/01/20	y Automotive S ETER 2 - N: 17 GY6HED3287	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
03-15-045	REPLAC	E NEW STEERING	ANGLE SEN	DON	0	Ν	GARAGE	1.97	\$232.95	\$220.82	\$0.	.00	\$453.77	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.	.00	\$2.00	
SO-05	SCAN O	JT ELECTRONIC E	ENGINE EEC	DON	0	N	GARAGE	0.43	\$50.38	\$0.00	\$0.	.00	\$50.38	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	2.40	283.	33 :	220.82	2.00		506.15
Job Code		Job Descript	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	tion_		<u>En</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	/ 1 ⁻	1310047	•	09/	14/2021 12:20:53	09/14/202	1 12:46:30		0.43		\$50.38
03-15-045	REPLACE N	IEW STEERING ANG	LE SENSOR	1	1310047		09/	14/2021 09:01:58	09/14/202	1 11:00:25		1.97		\$232.95
												LABOR		283.33
Job Code		Job Descript	tion			Part No	<u> </u>	Des	<u>cription</u>	U	Jnit Price	Quantity	<u>Total</u>	Cost
03-15-045	REPLACE N	IEW STEERING ANG	LE SENSOR	Н	C3Z3F8	18A	ST	EERING WHEEL	ROTATION SEN	ISOR	220.82	1		\$220.82
												PARTS		220.82

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 40981

Work Order Notes

(LISAPATE) Per driver service advance trac and hill start assist not available are lit up on driver display.

Job Notes

03-15-045 - REPLACE NEW STEERING ANGLE SENSOR

(EHOWELL) Replaced the steering wheel rotation sensor. Observed data on the scan tool after repairs and the position of the steering wheel changed while moving the steering wheel. A road test was performed and the advance trac light never came back on. EH 1.6 Hours

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC C0051:64-48 Steering Wheel Position Sensor. 1.0 Hour

UNIT NO:		242430	2017 FOR	F550)				WORK	ORDER NO	D: 4	11113	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DATI	DATE:	09/28/20	021 11:40:53 021 09:16:38 021 14:00:51	METER 1	ON: GARAGI I - M: 15738 ICE DATE: RIAL NO:	N 09/01/2	ity Automotive 9 IETER 2 - N: 017 5GY6HED3287	0
JOB CODE		JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	OR MAT	ERIAL (COMMERCIAL	TOTAL COST
03-42-024	REPLAC	E NEW 90" FITTIN	GS, COOLING	DON	0	Ν	GARAGE	0.61	\$72.18	\$12.65	\$	60.00	\$84.83
35-42	DIAGNO	SE COOLING SYS	TEM	DON	0	Ν	GARAGE	0.61	\$72.05	\$0.00	\$	60.00	\$72.05
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00
SO-05	SCAN O	JT ELECTRONIC E	ENGINE EEC	DON	0	N	GARAGE	2.57	\$303.72	\$0.00	\$	60.00	\$303.72
JOB COUN	T: 4				wo	RK ORI	DER TOTAL	.: 3.80) 4	147.95	12.65	2.00	462.
Job Code CH-SP	CHARGE Sh	Job Descript	<u>tion</u>	5	V 03163	endor N	l <mark>o.</mark> 1	Invoice No.	Purc	hase Order N	<u>lo.</u>	COMML	*22.
Job Code		Job Descript	<u>tion</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	1 1	1310047		0	9/23/2021 14:30:00	09/23/	2021 15:49:26		1.32	\$156.
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	1 1	1310047		0	9/23/2021 13:00:00	09/23/	2021 14:15:00		1.25	\$147.
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	1 1	1310047		0	9/23/2021 12:52:0	7 09/23/	2021 12:52:07		0.00	\$0.
35-42	DIAGNOSE	COOLING SYSTEM		1	1310047		0	9/24/2021 09:34:5	1 09/24/	2021 10:11:29		0.61	\$72.
03-42-024	REPLACE N	EW 90" FITTINGS, C	COOLING SYSTE	EM 1	1310047		0	9/27/2021 07:41:20	09/27/	2021 08:18:02		0.61	\$72.
												LABOR	447.
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	<u>De</u>	scription		Unit Price	<u>Quantity</u>	Total Cost
03-42-024	REPLACE N	EW 90" FITTINGS, C	COOLING SYSTE	M F	OR8475	7	Н	EATER FITTING			11.4	8 1	\$11
03-42-024	REPLACE N	EW 90" FITTINGS, C	COOLING SYSTE	M V	C3B		F	ORD ORANGE AN	ITIFREEZE		28.3	1 1	\$28
03-42-024	REPLACE N	REPLACE NEW 90" FITTINGS, COOLING SYSTEM		M V	C3B		F	ORD ORANGE AN	ITIFREEZE		28.3	1 (1)	(\$28.5
03-42-024	REPLACE N	EPLACE NEW 90" FITTINGS, COOLING SYSTEM			0 CLAMI	P	C	LAMP 9/16-1 1/16			0.3	9 <u>3</u>	. \$1 12.

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 41113

Work Order Notes

(LISAPATE) Service stabilitrak light back on also hill start assist and abs light

Job Notes

03-42-024 - REPLACE NEW 90" FITTINGS, COOLING SYSTEM

(EHOWELL) Replaced the Y fitting that connects the cooling system hoses. Installed 3 new hose clamps. Filled vehicle with coolant and pressure tested system to verify repair. EH .5 HR

35-42 - DIAGNOSE COOLING SYSTEM

(EHOWELL) The vehicle was leaking coolant at the Y fitting near the heater core hoses. EH .5 HR

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTCs: P193C:00-28 Steering Angle Sensor and C0051:64-48 Steering Wheel Position Sensor.

Observed data on scan tool while turning the steering wheel. The Steering Angle Sensor jumps from about 800 degrees to over 5000 degrees when turned near the stop. Yaw rate sensor should read near 0.05, but it reads .2. Examined ABS Module connector, Steering Column Control Module connector, and Restraint Control Module connectors, but did not see any bent pins or other issues. It was necessary to remove cupholders and floor hardware to gain access the Restraint Control Module. Cleared codes and performed a road test while driving over bumps. No warning lights came on. We are releasing the vehicle to the customer and they may return the vehicle to us if needed. EH/AB

UNIT NO:		242430 2017 FORD		F550)				WORK OR	DER NO:	417	798		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	12/13/202	21 08:39:20 21 13:35:12 21 07:32:50	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 16868 DATE :	ME 09/01/201	ΓER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERI	IAL CO	MMERCIAL	TOTAL	COST
03-01-054	REPLACI	E NEW BYPASS H	EATER HOSE	DON	0	N	GARAGE	1.50	\$177.00	\$79.58	\$0.0	0	\$256.58	
03-50-100	REPLAC	E NEW BELT, SER	PENTINE OR	DON	0	N	GARAGE	0.05	\$6.29	\$99.03	\$0.0	0	\$105.32	
03-50-102	REPLACI	E NEW IDLER PUL	LEY	DON	0	Ν	GARAGE	0.03	\$4.10	\$38.24	\$0.0	0	\$42.34	
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	N	GARAGE	0.15	\$17.70	\$15.18	\$0.0	0	\$32.88	
66-79-002	PERFOR	M SERVICE CALL		DON	В	N	GARAGE	0.23	\$26.88	\$0.00	\$0.0	0	\$26.88	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.76	\$89.98	\$100.14	\$0.0	0	\$190.12	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.0	0	\$2.00	
SO-05	SCAN O	JT ELECTRONIC E	ENGINE EEC	DON	0	N	GARAGE	0.21	\$24.39	\$0.00	\$0.0	0	\$24.39	
JOB COUN	T: 8				WC	RK ORI	DER TOTAL:	2.94	346.	34 3:	32.17	2.00		680.51
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order No.			<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code	DEDI AGE N	Job Descript				<u>iployee</u>		Start		<u>inish</u>		Quantity	<u>Total</u>	Cost
03-01-054		EW BYPASS HEATE	RHUSE		1213180			/13/2021 07:00:00	12/13/2021			1.50		\$177.00
66-PM-PMA 66-PM-PMA	PERFORM (1074414 1074414			/06/2021 14:30:00 /06/2021 14:08:52				0.66 0.10		\$77.91
66-79-002		SERVICE CALL			1213180			/06/2021 14:08:52 /06/2021 10:24:56				0.10		\$12.06 \$26.88
SO-05		ELECTRONIC ENGIN	IE EEC SYSTEM		1213180			/06/2021 10:24:30 /06/2021 10:38:47				0.23		\$24.39
03-50-102		EW IDLER PULLEY	IL LLO OTOTLI		1213180			06/2021 10:50:47				0.03		\$4.10
03-50-100		EW BELT, SERPENT	INE OR MISC		1213180			06/2021 10:53:31	12/06/2021			0.05		\$6.29
03-51-038		EW WIPER BLADES			1074414			07/2021 07:00:00	12/07/2021			0.15		\$17.70
												LABOR		346.33
Job Code		Job Description				Part No	<u>.</u>	<u>Des</u>	cription	<u>Ur</u>	nit Price	Quantity	<u>Total</u>	Cost

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
66-PM-PMA	PERFORM OIL CHANGE	VC3B	FORD ORANGE ANTIFREEZE	28.31	1	\$28.31
03-50-102	REPLACE NEW IDLER PULLEY	DAY89007	IDLER/TENSION PULLEY	38.24	1	\$38.24
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK061420	SERPENTINE BELT	99.03	1	\$99.03
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	36.02	1	\$36.02
03-01-054	REPLACE NEW BYPASS HEATER HOSE	FOR84757	HEATER FITTING	11.87	1	\$11.87
03-01-054	REPLACE NEW BYPASS HEATER HOSE	HC3Z18472C	HEATER HOSE	67.71	1	\$67.71
					PARTS	332.17

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 41798

Work Order Notes

(LISAPATE) Driver requested a service call bus is broken down on Helen Keller Dr

(LISAPATE) PM-replace wipers

Job Notes

03-01-054 - REPLACE NEW BYPASS HEATER HOSE

(LISAPATE) MS replaced heater hose and T fitting for rear heater

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(MSIDES) Replaced serpentine belt. MS

03-50-102 - REPLACE NEW IDLER PULLEY

(MSIDES) Replaced idler pulley. MS

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-79-002 - PERFORM SERVICE CALL

(MSIDES) Performed service call. Reset emergency shutdown module and drove vehicle back to shop for repair. MS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) JW AMG/SH Performed PM. Found thermostat by pass hose leaking.

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(MSIDES) Scanned vehicle and found codes: P0217 - Engine coolant overtemp condition, P0625 - Generator field/F terminal circuit low, P065B - Generator control circuit range/performance, P1285 - Cylinder head overtemp condition, P1299 - Cylinder head overtemp protection active. All of these codes were due to the drive belt being throw due to a failed pulley bearing. MS

UNIT NO:		242430	2017 FOR	D F550)				WORK OF	RDER NO): 4:	3183		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550	2017	OPENE COMPL CLOSE Ford F55	ETED D DAT	DATE:	05/11/202	22 12:08:16 22 14:27:43 22 14:04:23	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 18229 EDATE:	M 09/01/20	ty Automotive S ETER 2 - N: 017 GY6HED3287	0	
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	Ν	GARAGE	0.04	\$4.72	\$20.37	\$0	0.00	\$25.09	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.80	\$94.73	\$47.85	\$0	0.00	\$142.58	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3				WC	RK ORI	DER TOTAL	: 0.84	99.	.45	68.22	2.00		169.67
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	Purchas	se Order No	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	ion		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	inish		Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	2052187	7	05	5/10/2022 13:18:04	05/10/202	2 14:06:14		0.80		\$94.73
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187	7	05	5/10/2022 14:06:23	05/10/202	2 14:08:47		0.04		\$4.72
												LABOR		99.45
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u>!</u>	Unit Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	9220		W	IPER 22 IN OE BE	AM		10.19	2		\$20.37
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		ВІ	JLK OIL 5W20 SYI	NTHETIC THOM	MAS	5.64	7		\$39.48
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			8.37			\$8.37
												PARTS		68.22

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 43183

Work Order Notes

(CWIGLEY) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW MILEAGE-18229

UNIT NO:		242430	2017 FOR) F550)					WORK C	RDER NO):	43589		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED	DATE:	06/17/2	2022 14:3 ² 2022 14:1 ² 2022 15:3 ²	4:22		M: 18230 E DATE:	09/01/2	sity Automotive METER 2 - N: 2017 5GY6HED3287	0	
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LO	C LABO	OR HRS	LABOR	MATI	ERIAL	COMMERCIAL	TOTAL	COST
03-01-055	REPLAC	E NEW A/C LINE(S)	DON	0	N	GARAGE	≣	0.82	\$97.22	\$194.16	;	\$0.00	\$291.38	
35-01	DIAGNO	SE AIR CONDITION	NING, HEAT, '	DON	0	N	GARAGE	≣	3.62	\$426.80	\$0.00		\$0.00	\$426.80	
66-01-058	PERFOR	RM EVAC AND REC	HARGE FRE	DON	0	N	GARAGE	≣	0.51	\$60.11	\$65.10		\$0.00	\$125.21	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	≣	0.00	\$0.00	\$0.00	;	\$2.00	\$2.00	
JOB COUN	T: 4				wo	RK ORI	DER TOTA	AL:	4.95	58	4.13	259.26	2.00		845.39
Job Code		Job Descript	i <u>on</u>		<u>v</u>	endor N	lo.	Invo	ice No.	Purch	ase Order N	<u>lo.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163			1							\$2.00
													COMML		2.00
Job Code		Job Descripti	<u>ion</u>		<u>En</u>	ployee	No.	<u>s</u>	Start .		<u>Finish</u>		Quantity	<u>Total</u>	Cost
03-01-055	REPLACE N	IEW A/C LINE(S)		1	1213180)		06/16/2022	2 07:41:40	06/16/20	022 08:31:06		0.82		\$97.22
35-01	DIAGNOSE	AIR CONDITIONING,	HEAT, VENT	1	1213180)		06/10/2022	2 12:16:36	06/10/20)22 15:45:11		3.48		\$410.21
35-01	DIAGNOSE	AIR CONDITIONING,	HEAT, VENT	1	1310047	•		06/10/2022	2 09:33:35	06/10/20	022 09:42:01		0.14		\$16.59
66-01-058	PERFORM	EVAC AND RECHARG	E FREON	1	1213180)		06/16/2022	2 08:31:14	06/16/20	022 09:01:48		0.51		\$60.11
													LABOR		584.13
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>		Des	<u>cription</u>		Unit Pric	e Quantity	<u>Total</u>	Cost
66-01-058	PERFORM	EVAC AND RECHARG	SE FREON	F	134AOZ	<u>, </u>		R134A FRE	EON-OUN	CE		0.9	98 64		\$62.40
66-01-058	PERFORM	EVAC AND RECHARG	SE FREON	E	STER C	IL		A/C ESTER	R OIL OUN	NCE		1.0	08 12		\$12.96
66-01-058	PERFORM	EVAC AND RECHARG	SE FREON	E	STER C	IL		A/C ESTER	R OIL OUN	NCE		1.0	08 (12)	(\$12.96
66-01-058	PERFORM	EVAC AND RECHARG	SE FREON	E	STER C	IL		A/C ESTER	R OIL OUN	NCE		1.0	08 1		\$1.08
66-01-058	PERFORM	EVAC AND RECHARG	SE FREON	F	ECYCLI	ED FREC	N OZ	RECLAIME	ED FREON	N OZ		0.	14 12		\$1.62
03-01-055	REPLACE N	IEW A/C LINE(S)		M	1OTYF38	3059		A/C LINE				194.	161	<u>-</u>	\$194.16
													PARTS		259.26

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 43589

Work Order Notes

(LISAPATE) Front A/C is blowing hot

Job Notes

03-01-055 - REPLACE NEW A/C LINE(S)

(MSIDES) Found high pressure line to be leaking. Replaced high pressure line that runs from compressor to condenser. MS 1.0 hrs

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Found high side pressure line to be leaking. MS

(IFALLS) Looked entire system over for leaks and high pressure line was only line found to be leaking. 1HRS MS

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(MSIDES) Recovered 12 OZ of freon from system. Replaced leaking pressure line and perform vacuum and leak test unit passed both. Charged to spec of 4LBS and 12OZ also added 1.0OZ of ester oil with dye. MS

Billed Parts

Recycled Freon: 12OZ Inventory Freon: 64OZ

Ester oil: 1.00Z

Page:1

Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

242430

2017 FORD F550

UNIT NO:

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

44455

WORK ORDER NO:

USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550 2017 F	OPENE COMPL CLOSE Ford F55	ETED D DAT	DATE:	09/14/202	22 15:28:54 22 14:28:43 22 07:27:17	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 19022 DATE :	09/01/2	sity Automotive S METER 2 - N: 2017 5GY6HED3287	0
JOB CODE	<u>:</u>	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL (COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.12	\$14.06	\$15.60	\$	\$0.00	\$29.66
03-79-009	REPLAC	CE NEW SEAT BELT(S)	DON	0	N	GARAGE	0.46	\$54.08	\$162.75	\$	\$0.00	\$216.83
06-02-006	INSPEC	T ROOF PANEL & REINFORCEN	DON	0	N	GARAGE	0.02	\$2.33	\$0.00	\$	\$0.00	\$2.33
24-02-006	REPAIR	ROOF PANEL & REINFORCEME	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$	\$1,150.00	\$1,150.00
66-79-003	PERFOR	RM SAFETY INSPECTION	DON	Υ	N	GARAGE	0.99	\$117.38	\$0.00	\$	\$0.00	\$117.38
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	1.00	\$118.00	\$0.00	\$	\$0.00	\$118.00
CH-SP	_	E Shop Supplies	DON	2	N	GARAGE		\$0.00	\$0.00		\$5.00	\$5.00
		_ опор оцрыюз	DON					• • • • • • • • • • • • • • • • • • • •		•		•••
JOB COUN	DB COUNT: 7			WC	ORK ORI	DER TOTAL:	2.59	305.8	35	178.35	1,155.00	1,639.20
Job Code		Job Description		<u>v</u>	/endor N	lo.	Invoice No.	<u>Purchase</u>	e Order No	<u>).</u>		Total Cost
06-02-006	INSPECT R	OOF PANEL & REINFORCEMENTS	1	1177989	9	10	105					\$1,150.0
06-02-006	INSPECT R	OOF PANEL & REINFORCEMENTS	1	1177989	9	10	105					(\$1,150.00
CH-SP	CHARGE S	hop Supplies	5	03163		1						\$5.0
24-02-006	REPAIR RO	OF PANEL & REINFORCEMENTS	1	1177989	9	10	105					\$1,150.0
											COMML	1155.00
Job Code		Job Description		<u>E</u> r	nployee	No.	<u>Start</u>	<u>Fi</u>	nish		Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	1	229627	7	09	/14/2022 07:00:00	09/14/2022	08:00:00		1.00	\$118.00
03-79-009	REPLACE N	NEW SEAT BELT(S)	1	229627	7	09	/13/2022 14:07:59	09/13/2022	14:35:29		0.46	\$54.0
66-79-003	PERFORM	SAFETY INSPECTION	1	229627	7	09	/08/2022 08:15:19	09/08/2022	09:15:00		0.99	\$117.3
03-51-038	REPLACE N	NEW WIPER BLADES	1	229627	7	09	/08/2022 07:40:31	09/08/2022	07:47:40		0.12	\$14.00
06-02-006	INSPECT R	OOF PANEL & REINFORCEMENTS	1	229627	7	09	/08/2022 07:39:20	09/08/2022	07:40:31		0.02	\$2.3
											LABOR	305.8
Job Code		Job Description			Part No) <u>.</u>	Des	scription	<u>.</u>	Unit Price	e Quantity	Total Cost
03-51-038	REPLACE N	NEW WIPER BLADES	22-1		WI	PER BLADE 22"	TRICO EXACT		7.8	30 2	\$15.6	
03-79-009	REPLACE N	REPLACE NEW SEAT BELT(S) 3157KS				SE	AT BELT RETRA	CTOR/BUCKLE		162.7	75 1	\$162.7
												_

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

PARTS

178.35

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

242430 **UNIT NO:** 2017 FORD F550 WORK ORDER NO: 44455

Work Order Notes

(CHANNELL) roof leaking (GARAGE)

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blades JDM

03-79-009 - REPLACE NEW SEAT BELT(S)

(GARAGE) replaced buckle on handi cap lift JDM

(LISAPATE) rechecked ok

06-02-006 - INSPECT ROOF PANEL & REINFORCEMENTS

(LISAPATE) Found roof seals dryrotted and starting to rust

24-02-006 - REPAIR ROOF PANEL & REINFORCEMENTS

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) seat belt buckle on handi cap lift JDM (LISAPATE) Safety inspection completed. See attached

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) checker Jdm

(LISAPATE) Vehicle had been 793 miles. checked fluids battery and tires

UNIT NO:		242430	2017 FORD	F550)				WORK OR	DER NO:	45	324		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	12/08/202	22 14:50:22 22 15:27:41 22 15:48:53	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 19880 DATE : (ME 09/01/201	TER 2 - N:	0	
JOB CODE		JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERI	AL CC	MMERCIAL	TOTAL	COST
03-02-077	REPLAC	E NEW WASHER FL	_UID PUMP	DON	0	N	GARAGE	0.34	\$40.05	\$54.98	\$0.	00	\$95.03	
03-02-092	REPLAC	E NEW HOOD SHO	CKS/TRUNK	DON	0	Ν	GARAGE	1.00	\$118.00	\$110.02	\$0.	00	\$228.02	
03-13-001	REPLAC	E NEW FRONT BRA	KES & ROT	DON	0	N	GARAGE	2.59	\$305.78	\$189.83	\$0.	00	\$495.61	
03-33-003	REPLAC	E NEW COIL		DON	0	N	GARAGE	0.34	\$40.19	\$90.53	\$0.	00	\$130.72	
03-33-004	REPLAC	E NEW SPARK PLU	GS	DON	0	N	GARAGE	1.29	\$151.89	\$183.60	\$0.	00	\$335.49	
03-40-405	REPLAC	E NEW VALVE COV	ERS/GASKE	DON	0	N	GARAGE	1.00	\$118.00	\$78.39	\$0.	00	\$196.39	
03-40-442	REPLAC	E NEW VALVE SPR	INGS	DON	0	N	GARAGE	10.11	\$1,193.24	\$26.86	\$0.	00	\$1,220.10)
03-50-100	REPLAC	E NEW BELT, SERF	PENTINE OR	DON	0	N	GARAGE	0.20	\$23.60	\$108.90	\$0.	00	\$132.50	
03-50-102	REPLAC	E NEW IDLER PULL	-EY	DON	0	N	GARAGE	1.39	\$163.66	\$39.24	\$0.	00	\$202.90	
03-50-103	REPLAC	E NEW BELT TENSI	IONER	DON	0	N	GARAGE	3.98	\$469.90	\$273.24	\$0.	00	\$743.14	
66-13-130	PERFOR	RM Burnish Brakes		DON	0	N	GARAGE	0.35	\$41.37	\$0.00	\$0.	00	\$41.37	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.16	\$18.85	\$56.78	\$0.	00	\$75.63	
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
SO-05	SCAN O	UT ELECTRONIC E	NGINE EEC	DON	0	N	GARAGE	0.43	\$51.20	\$0.00	\$0.	00	\$51.20	
JOB COUN	T: 14				WC	RK ORI	DER TOTAL:	23.18	2,735.7	3 1,21	12.37	5.00		3,953.10
Job Code CH-SP	CHARGE SI	Job Description	on_	5	<u>V</u> 03163	endor N	l <u>o.</u> 1	Invoice No.	Purchase	e Order No.			<u>Total</u>	Cost \$5.00
												COMML		5.00
Job Code		Job Description	<u>on</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>nish</u>		Quantity	Total	Cost
03-40-405		IEW VALVE COVERS/0		1	1310047	,	12	/08/2022 07:00:00	12/08/2022	08:00:00		1.00		\$118.00
03-50-100		IEW BELT, SERPENTII			1310047	,	12	/08/2022 07:00:00	12/08/2022	07:12:00		0.20		\$23.60
SO-05		ELECTRONIC ENGINE	E EEC SYSTEM	l 1	1310047	7	12	/02/2022 07:01:36	12/02/2022	07:27:38		0.43		\$51.20
03-33-003	REPLACE N			1	1310047	,	12	/01/2022 10:34:10	12/01/2022	10:54:36		0.34		\$40.19
FleetFocus M5	- WODETAIL	- Work Order Detail v20	0.0											Page:1

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	11/30/2022 13:01:37	11/30/2022 14:15:00		1.22	\$144.32
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	11/30/2022 14:30:00	11/30/2022 15:52:06		1.37	\$161.46
03-50-103	REPLACE NEW BELT TENSIONER	11310047	11/30/2022 09:30:00	11/30/2022 11:53:12		2.39	\$281.63
03-50-103	REPLACE NEW BELT TENSIONER	11310047	11/30/2022 09:13:57	11/30/2022 09:15:00		0.02	\$2.07
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/23/2022 13:01:48	11/23/2022 13:17:51		0.27	\$31.57
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/23/2022 08:20:25	11/23/2022 11:30:25		3.17	\$373.67
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/21/2022 14:37:33	11/21/2022 15:55:29		1.30	\$153.27
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/28/2022 07:43:39	11/28/2022 08:28:44		0.75	\$88.66
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/28/2022 08:32:21	11/28/2022 09:15:00		0.71	\$83.88
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/28/2022 09:30:00	11/28/2022 11:55:05		2.42	\$285.33
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/28/2022 13:03:44	11/28/2022 13:20:17		0.28	\$32.55
03-40-442	REPLACE NEW VALVE SPRINGS	11310047	11/29/2022 07:33:17	11/29/2022 08:46:40		1.22	\$144.32
03-50-102	REPLACE NEW IDLER PULLEY	11310047	12/01/2022 08:21:23	12/01/2022 09:15:00		0.89	\$105.45
03-50-102	REPLACE NEW IDLER PULLEY	11310047	12/01/2022 09:30:00	12/01/2022 09:59:36		0.49	\$58.21
66-PM-PMA	PERFORM OIL CHANGE	11310047	12/01/2022 12:19:59	12/01/2022 12:19:59		0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	11310047	12/01/2022 12:57:45	12/01/2022 12:57:45		0.00	\$0.00
66-13-130	PERFORM Burnish Brakes	11310047	12/01/2022 13:00:00	12/01/2022 13:03:47		0.06	\$7.44
03-02-077	REPLACE NEW WASHER FLUID PUMP	11310047	12/01/2022 13:03:47	12/01/2022 13:24:09		0.34	\$40.05
03-50-103	REPLACE NEW BELT TENSIONER	11310047	12/01/2022 13:24:09	12/01/2022 14:15:00		0.85	\$100.01
03-50-103	REPLACE NEW BELT TENSIONER	11310047	12/01/2022 14:30:00	12/01/2022 15:07:50		0.63	\$74.41
03-33-004	REPLACE NEW SPARK PLUGS	11310047	12/01/2022 15:07:50	12/01/2022 15:55:04		0.79	\$92.89
66-PM-PMA	PERFORM OIL CHANGE	11310047	12/02/2022 07:29:14	12/02/2022 07:38:49		0.16	\$18.85
03-33-004	REPLACE NEW SPARK PLUGS	11310047	12/08/2022 08:00:00	12/08/2022 08:30:00		0.50	\$59.00
03-50-103	REPLACE NEW BELT TENSIONER	11310047	12/08/2022 08:30:00	12/08/2022 08:36:00		0.10	\$11.80
03-02-092	REPLACE NEW HOOD SHOCKS/TRUNK SHOCKS	11310047	12/08/2022 07:00:00	12/08/2022 08:00:00		1.00	\$118.00
66-13-130	PERFORM Burnish Brakes	11310047	12/02/2022 07:38:49	12/02/2022 07:56:04		0.29	\$33.93
						LABOR	2735.76
Job Code	Job Description	Part No.	Descr	iption	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNT	HETIC THOMAS	6.24	7	\$43.68
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER		5.87	1	\$5.87
FleetFocus M5	5 - WODETAIL - Work Order Detail v20.0						Page:2

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	7.23	1	\$7.23
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-33-004	REPLACE NEW SPARK PLUGS	MOTSP509	SPARK PLUGS	18.36	10	\$183.60
03-33-003	REPLACE NEW COIL	STIFD509	COIL	52.19	1	\$52.19
03-40-442	REPLACE NEW VALVE SPRINGS	RV3574S	VALVE SPRING	10.43	1	\$10.43
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584A	VALVE COVER GASKET	39.12	1	\$39.12
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584A	VALVE COVER GASKET	39.12	(1)	(\$39.12)
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584A	VALVE COVER GASKET	39.12	1	\$39.12
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584B	GASKET	39.12	1	\$39.12
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK061420	SERPENTINE BELT	108.90	1	\$108.90
03-02-092	REPLACE NEW HOOD SHOCKS/TRUNK SHOCKS	LC3Z16C826A	HOOD SHOCK	55.01	1	\$55.01
03-02-092	REPLACE NEW HOOD SHOCKS/TRUNK SHOCKS	LC3Z16C826B	HOOD SHOCK	55.01	1	\$55.01
03-33-003	REPLACE NEW COIL	STWSPP113E	COIL ON PLUG BOOT	4.26	1	\$4.26
03-50-103	REPLACE NEW BELT TENSIONER	CTL49314	TENSIONER ASSEMBLY	71.73	1	\$71.73
03-50-102	REPLACE NEW IDLER PULLEY	GAT38001	IDLER PULLEY	39.24	1	\$39.24
03-40-442	REPLACE NEW VALVE SPRINGS	F5RZ6518B	RETAINER KEEPER	1.08	2	\$2.16
03-40-442	REPLACE NEW VALVE SPRINGS	3L3Z6564A	ROCKER ARM	14.27	1	\$14.27
03-02-077	REPLACE NEW WASHER FLUID PUMP	JL3Z17664A	WASHER PUMP	54.98	1	\$54.98
03-50-103	REPLACE NEW BELT TENSIONER	SKF5106WCC	BEARING	60.72	2	\$121.44
03-50-103	REPLACE NEW BELT TENSIONER	GAT38041	PULLEY	83.07	1	\$83.07
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	HC3Z2001B	FRONT BRAKE PADS	183.90	1	\$183.90
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584B	GASKET	39.12	(1)	(\$39.12)
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	DL1Z6584B	GASKET	39.27	1	\$39.27
03-50-103	REPLACE NEW BELT TENSIONER	GAT38041	PULLEY	83.07	(1)	(\$83.07)
03-50-103	REPLACE NEW BELT TENSIONER	GAT38041	PULLEY	80.07	1	\$80.07
03-33-003	REPLACE NEW COIL	STWSPP113E	COIL ON PLUG BOOT	4.26	(1)	(\$4.26)
03-33-003	REPLACE NEW COIL	STWSPP113E	COIL ON PLUG BOOT	4.26	9	\$38.34
					PARTS	1212.37

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 45324

Work Order Notes

(LISAPATE) Check engine light is on and flashing-unit is running rough-belt is squealing

Job Notes

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

03-02-077 - REPLACE NEW WASHER FLUID PUMP

(EHOWELL) The washer was not spraying. Verified that the pump was receiving power and ground. Replaced windshield washer fluid pump. The washer is now spraying properly. EH Add .2 HR diag.

03-02-092 - REPLACE NEW HOOD SHOCKS/TRUNK SHOCKS

(EKIMBREL) eh replaced both hood shocks

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EHOWELL) Installed new front brake pads. EH

03-33-003 - REPLACE NEW COIL

(EHOWELL) Replaced one ignition coil. EH

03-33-004 - REPLACE NEW SPARK PLUGS

(EHOWELL) Replaced all spark plugs. EH

03-40-405 - REPLACE NEW VALVE COVERS/GASKETS

(EKIMBREL) eh replaced valve cover gaskets

03-40-442 - REPLACE NEW VALVE SPRINGS

(EHOWELL) Replaced a broken valve spring on the right side of the vehicle. Installed a new roller follower and valve cover gasket. The vehicle is no longer misfiring. EH 17.6 HRS

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(EKIMBREL) eh replaced belt

03-50-102 - REPLACE NEW IDLER PULLEY

(EHOWELL) Replaced two idler pulleys. Removed two other pulleys and sent them to Northport Auto Supply. They replaced the bearings in the two other pulleys. A squealing noise is no longer coming from the belt area. EH 1.3 HRS to replace all pulleys and diagnose.

03-50-103 - REPLACE NEW BELT TENSIONER

(EHOWELL) Replaced belt tensioner and installed a new serpentine belt. EH No extra labor.

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Changed oil and filter, greased front end, topped of rear differential fluid, checked battery, tire pressures, and fluids. The vehicle will need a complete set of tires next PM. The axle fluid was dark and needs to be changed next PM. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found the vehicle with a misfire using the scan tool misfire graph. EH

UNIT NO:		242430	2017 FORI) F550	ı				WORK	ORDER NO	D :	46412		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED D DATI	DATE:	03/10/20	023 12:05:28 023 13:13:44 023 08:54:21	METER 1 IN-SERV	ON: GARAGE - M: 20327 ICE DATE: RIAL NO:	09/01/2	sity Automotive METER 2 - N: 2017 F5GY6HED3287	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	OR MAT	ERIAL	COMMERCIAL	TOTAL COS	<u>ST</u>
03-01-077	REPLAC	E NEW EXPANSIO	N VALVE	DON	0	Ν	GARAGE	0.60	\$70.80	\$45.69		\$0.00	\$116.49	
06-01-001	INSPEC	AIR CONDITION	NG ASSEMBL	DON	0	N	GARAGE	2.87	\$339.18	\$0.00		\$0.00	\$339.18	
66-01-058	PERFOR	M EVAC AND REC	HARGE FRE	DON	0	N	GARAGE	1.91	\$224.92	\$16.98		\$0.00	\$241.90	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	.: 5.3	8 6	34.90	62.67	5.00	702	2.57
Job Code CH-SP	CHARGE SI	Job Descript	<u>tion</u>	50	V 03163	endor N	lo. 1	Invoice No.	<u>Puro</u>	hase Order N	lo.	COMML		<u>t</u> 55.00 5.00
Job Code		Job Descript	<u>tion</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost	<u>t</u>
03-01-077	REPLACE N	IEW EXPANSION VAI	LVE	1′	1310047		0	3/10/2023 09:16:5	6 03/10/	2023 09:16:56		0.00	\$0	0.00
03-01-077	REPLACE N	IEW EXPANSION VAI	LVE	1′	1310047		0	3/10/2023 09:16:5	6 03/10/	2023 09:16:56		0.00	\$0	0.00
03-01-077	REPLACE N	IEW EXPANSION VAI	LVE	1	1310047		0	3/10/2023 09:16:5	6 03/10/	2023 09:52:56		0.60	\$70	0.80
66-01-058	PERFORM I	EVAC AND RECHAR	GE FREON	1	1310047		0	3/09/2023 13:00:0	0 03/09/	2023 13:27:22		0.46	\$5	3.82
66-01-058	PERFORM I	EVAC AND RECHAR	GE FREON	1	1310047		0	3/09/2023 10:33:0	0 03/09/	2023 12:00:00		1.45	\$17	1.10
06-01-001	INSPECT AI	R CONDITIONING AS	SSEMBLY	1	1310047		0	3/09/2023 09:30:0	0 03/09/	2023 10:33:00		1.05	\$123	3.90
06-01-001	INSPECT AI	R CONDITIONING AS	SSEMBLY	1	1310047		0	3/09/2023 07:25:3	2 03/09/	2023 09:15:00		1.82	\$21	5.28
												LABOR	634	4.90
Job Code		Job Descript	<u>tion</u>			Part No	<u>).</u>	<u>De</u>	scription		Unit Pric	e Quantity	Total Cost	<u>t</u>
03-01-077	REPLACE N	IEW EXPANSION VAI	LVE	F	OR3951	7	E	XPANSION VALVE	≣		45.	69 1	\$4	15.69
66-01-058	PERFORM I	EVAC AND RECHAR	GE FREON	R	134AOZ	•	F	134A FREON-OU	NCE		0.9	98 8	\$	57.80
66-01-058	PERFORM I	EVAC AND RECHAR	GE FREON	R	ECYCLE	ED FREC	ON OZ F	ECLAIMED FREC	N OZ		0.			9.18
												PARTS	62	2.67

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 46412

Work Order Notes

(EHANNAH) replace wipers- inspect AC. Back AC is working fine, the front is not cooling off.

Job Notes

03-01-077 - REPLACE NEW EXPANSION VALVE

(EHOWELL) Blew oil out of the evaporator core using a blow gun. Replaced expansion valve. EH

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Wipers were not replaced. EH

06-01-001 - INSPECT AIR CONDITIONING ASSEMBLY

(EHOWELL) The low side of the AC system was freezing up. The low side pressure was near 0 psi and the compressor continued to run. The high pressure side of the expansion valve was not frozen, but the low side of the valve was. EH

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered 4.26 lb. of Freon. Leak test passed. Charged vehicle with 4.75 lb. of Freon. EH

UNIT NO:		242430	2017 FOR	D F550)				WORK	ORDER NO:	46	784		
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550	2017	OPENE COMPL CLOSE Ford F55	ETED D DAT	DATE:	04/24/202	3 14:14:51 3 11:05:58 3 13:09:45			ME 09/01/201	TER 2 - N:	0	
JOB CODE	E	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATERI	AL CC	MMERCIAL	TOTAL (COST
14-71-024	INSTALL	.BUMPER(S)		DON	0	N	GARAGE	0.37	\$44.02	\$0.00	\$0.	00	\$44.02	
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
JOB COUN	NT: 2				WO	RK ORI	DER TOTAL:	0.37	4	44.02	0.00	5.00		49.02
Job Code		Job Descript	ion_		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purch</u>	nase Order No.			Total C	<u>Cost</u>
CH-SP	CHARGE S	hop Supplies		50	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total C</u>	Cost
14-71-024	INSTALL BU	JMPER(S)		1:	2052187	,	04/	20/2023 14:30:00	04/20/2	2023 14:52:23		0.37		\$44.02
14-71-024	INSTALL BU	JMPER(S)		1:	2052187	,	04/	20/2023 14:21:10	04/20/2	2023 14:21:10		0.00		\$0.00
												LABOR		44.02

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 46784

Work Order Notes

(EHANNAH) install bumper

Job Notes

14-71-024 - INSTALL BUMPER(S)

(JWRIGHT) Removed bumper from old bus with blowed motor and installed on this bus. JAW

UNIT NO:		242430	2017 FOR	F550)				WORK O	RDER NO:	469	23		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED	DATE:	05/03/202	3 11:47:15 3 14:06:41 3 11:41:33	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	DATE : 0	MET 9/01/2017		0	
JOB CODE	<u>.</u>	JOB DESCRIPTI	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATERIA</u>	AL COM	IMERCIAL	TOTAL	COST
05-17	REPLAC	E USED TIRES, T	UBES, LINERS	DON	0	Ν	GARAGE	1.18	\$138.95	\$0.00	\$0.00		\$138.95	
06-01	INSPEC ⁻	TAIR CONDITIONI	ING, HEAT, VE	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00		\$0.00	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00		\$5.00	
JOB COUN	T: 3				wo	RK ORI	DER TOTAL:	1.18	138	.95	0.00	5.00		143.95
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcha	se Order No.			<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1				_			\$5.00
												COMML		5.00
Job Code		Job Descrip	tion		En	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
05-17	REPLACE U	ISED TIRES, TUBES	, LINERS & VALV	'ES 1	2052187	,	05/	02/2023 14:30:37	05/02/202	23 15:41:16		1.18		\$138.95
											_	LABOR		138.95

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 46923

Work Order Notes

(LRUSHING) Needs Freon checked for front a/c vents - a/c is not cold

Job Notes

05-17 - REPLACE USED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Swapped all 6 tires and wheels from surplus unit 9051B to this unit. Adjusted all pressures. Torqued all lug nuts to spec. JAW

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Issac checked unit will need an evaporator freezes up after sitting. Dept needed will bring back on the 15th

242430

507203

2017 FORD F550

OPENED DATE:

UNIT NO:

USING DEPT NO:

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

47076

LOCATION: GARAGE - University Automotive Services

WORK ORDER NO:

WO STATUS WO VISIT R TECH SPEC	EASON:	CLOSED SCHEDULED 17FORDF550 201		ETED DAT			3 08:48:44 3 09:43:16	METER 1 - M IN-SERVICE UNIT SERIAL	DATE: 09/0	METER 2 - N: 01/2017 0AF5GY6HED3287	
JOB CODE	<u>.</u>	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-010	REPLAC	E NEW EVAPORATOR	DON	0	Ν	GARAGE	13.01	\$1,534.89	\$868.64	\$0.00	\$2,403.53
03-01-011	REPLAC	E NEW HEATER CORE	DON	Ο	N	GARAGE	1.00	\$118.00	\$179.07	\$0.00	\$297.07
03-15-045	REPLAC	E NEW STEERING ANGLE SE	N DON	0	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.15	\$17.70	\$16.65	\$0.00	\$34.35
10-22-003	SERVICI	E DIFFERENTIAL CARRIER	DON	0	N	GARAGE	0.81	\$95.88	\$62.70	\$0.00	\$158.58
66-01-058	PERFOR	RM EVAC AND RECHARGE FR	E(DON	0	N	GARAGE	0.41	\$47.95	\$19.35	\$0.00	\$67.30
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.68	\$80.24	\$31.42	\$0.00	\$111.66
CH-SP	CHARGE	E Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-15	SCAN O	UT STEERING	DON	0	N	GARAGE	0.03	\$4.06	\$0.00	\$0.00	\$4.06
JOB COUN	Т: 9			wo	RK ORI	DER TOTAL:	17.09	2,016.7	72 1,177.8	3 5.00	3,199.55
Job Code		Job Description		<u>v</u>	endor N	lo.	Invoice No.	Purchas	e Order No.		Total Cost
CH-SP	CHARGE S	hop Supplies	5	03163		1					\$5.00
										COMML	5.00
Job Code		Job Description			nployee		<u>Start</u>		<u>inish</u>	Quantity	Total Cost
03-01-011	REPLACE N	NEW HEATER CORE	1	1310047	,	06/	26/2023 08:00:00	06/26/2023	3 09:00:00	1.00	\$118.00
03-51-038	REPLACE N	NEW WIPER BLADES	1	1074414	ļ	05/	24/2023 14:23:02	05/24/2023	3 14:23:02	0.00	\$0.00
03-51-038	REPLACE N	NEW WIPER BLADES	1	1074414	ļ	05/	24/2023 14:23:02	05/24/2023	3 14:23:02	0.00	\$0.00
66-PM-PMA	PERFORM	OIL CHANGE	1	1074414	ļ	05/	24/2023 13:34:12	05/24/2023	3 14:15:00	0.68	\$80.24
03-01-010	REPLACE N	NEW EVAPORATOR	1	1310047	•	05/	18/2023 09:30:00	05/18/2023	3 10:14:42	0.75	\$87.91
03-01-010	REPLACE N	NEW EVAPORATOR	1	1310047	,	05/	18/2023 09:06:07	05/18/2023	3 09:15:00	0.15	\$17.47
03-01-010	REPLACE N	NEW EVAPORATOR	1	1310047	•	05/	18/2023 07:27:12	05/18/2023	3 08:48:54	1.36	\$160.68
03-01-010	REPLACE N	NEW EVAPORATOR	1	1310047	,	05/	18/2023 10:20:16	05/18/2023	3 11:53:17	1.55	\$182.93
03-01-010	REPLACE N	NEW EVAPORATOR	1	1310047	•	05/	18/2023 13:00:32	05/18/2023	3 13:46:00	0.76	\$89.42
FleetFocus M5	- WODETAIL	- Work Order Detail v20.0									Page:1

05/16/2023 11:41:02

Job Code 03-01-010	<u>Job Description</u> REPLACE NEW EVAPORATOR	Employee No. 11310047	<u>Start</u> 05/18/2023 14:38:59	<u>Finish</u> 05/18/2023 15:50:29		Quantity 1.19	<u>Total Cost</u> \$140.62
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/19/2023 07:07:08	05/19/2023 09:15:00		2.13	\$251.47
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/19/2023 09:30:00	05/19/2023 09:57:43		0.46	\$54.51
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/19/2023 10:06:13	05/19/2023 11:00:00		0.90	\$105.77
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/19/2023 13:01:00	05/19/2023 14:15:00		1.23	\$145.53
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/19/2023 14:30:00	05/19/2023 15:52:02		1.37	\$161.33
03-01-010	REPLACE NEW EVAPORATOR	11310047	05/22/2023 07:01:19	05/22/2023 08:11:06		1.16	\$137.24
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/24/2023 14:23:02	05/24/2023 14:32:02		0.15	\$17.70
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	05/25/2023 07:02:33	05/25/2023 07:26:56		0.41	\$47.95
10-22-003	SERVICE DIFFERENTIAL CARRIER	11310047	05/25/2023 07:26:56	05/25/2023 08:15:41		0.81	\$95.88
SO-15	SCAN OUT STEERING	11310047	05/25/2023 08:15:41	05/25/2023 08:17:45		0.03	\$4.06
03-15-045	REPLACE NEW STEERING ANGLE SENSOR	11310047	06/26/2023 07:00:00	06/26/2023 08:00:00		1.00	\$118.00
						LABOR	2016.71
Job Code	Job Description	Part No.	Donor	1.41.			
JOD COUE	Job Description	<u>rail No.</u>	Descr	<u>ription</u>	Unit Price	Quantity	Total Cost
03-01-010	REPLACE NEW EVAPORATOR	18476	<u>Descr</u> HEATER CORE	<u>iption</u>	0.00	Quantity 1	<u>Total Cost</u> \$0.00
<u> </u>		·					
03-01-010	REPLACE NEW EVAPORATOR	18476	HEATER CORE		0.00	1	\$0.00
03-01-010 66-PM-PMA	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE	18476 5W20TQT	HEATER CORE QUART CAM2 SYN 5W	/20 32OZ	0.00	1	\$0.00 \$10.70
03-01-010 66-PM-PMA 66-PM-PMA	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE	18476 5W20TQT ANTIFREEZE DEXCOOL	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM	/20 32OZ	0.00 10.70 20.72	1 1 1	\$0.00 \$10.70 \$20.72
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI	V20 32OZ ICO EXACT	0.00 10.70 20.72 8.33	1 1 1 2	\$0.00 \$10.70 \$20.72 \$16.65
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV	ICO EXACT	0.00 10.70 20.72 8.33 8.97	1 1 1 2 1	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE	ICO EXACT	0.00 10.70 20.72 8.33 8.97 0.99	1 1 1 2 1 10	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON PERFORM EVAC AND RECHARGE FREON	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ RECYCLED FREON OZ	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE RECLAIMED FREON C	ICO EXACT	0.00 10.70 20.72 8.33 8.97 0.99	1 1 1 2 1 10 70	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90 \$9.45
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058 66-01-058 03-01-011	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON PERFORM EVAC AND RECHARGE FREON REPLACE NEW HEATER CORE	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ RECYCLED FREON OZ FL3Z18476B	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE RECLAIMED FREON CO HEATER CORE	ICO EXACT	0.00 10.70 20.72 8.33 8.97 0.99 0.14 179.07	1 1 1 2 1 10 70	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90 \$9.45 \$179.07
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058 66-01-058 03-01-011	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON PERFORM EVAC AND RECHARGE FREON REPLACE NEW HEATER CORE REPLACE NEW EVAPORATOR	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ RECYCLED FREON OZ FL3Z18476B 18476	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE RECLAIMED FREON CO HEATER CORE HEATER CORE	ICO EXACT	0.00 10.70 20.72 8.33 8.97 0.99 0.14 179.07 0.00	1 1 1 2 1 10 70 1 (1)	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90 \$9.45 \$179.07 \$0.00
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058 66-01-058 03-01-011 03-01-010	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON PERFORM EVAC AND RECHARGE FREON REPLACE NEW HEATER CORE REPLACE NEW EVAPORATOR REPLACE NEW EVAPORATOR	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ RECYCLED FREON OZ FL3Z18476B 18476 HL3Z19850AB	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE RECLAIMED FREON CO HEATER CORE HEATER CORE EVAPORATOR	ICO EXACT	0.00 10.70 20.72 8.33 8.97 0.99 0.14 179.07 0.00 803.25	1 1 1 2 1 10 70 1 (1)	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90 \$9.45 \$179.07 \$0.00 \$803.25
03-01-010 66-PM-PMA 66-PM-PMA 03-51-038 03-01-010 66-01-058 66-01-058 03-01-011 03-01-010	REPLACE NEW EVAPORATOR PERFORM OIL CHANGE PERFORM OIL CHANGE REPLACE NEW WIPER BLADES REPLACE NEW EVAPORATOR PERFORM EVAC AND RECHARGE FREON PERFORM EVAC AND RECHARGE FREON REPLACE NEW HEATER CORE REPLACE NEW EVAPORATOR REPLACE NEW EVAPORATOR REPLACE NEW EVAPORATOR	18476 5W20TQT ANTIFREEZE DEXCOOL 22-1 82180 R134AOZ RECYCLED FREON OZ FL3Z18476B 18476 HL3Z19850AB FR3Z19C734A	HEATER CORE QUART CAM2 SYN 5W ANTIFREEZE-GM WIPER BLADE 22" TRI ULTRA BLACK RTV R134A FREON-OUNCE RECLAIMED FREON CO HEATER CORE HEATER CORE EVAPORATOR SENSOR	V20 32OZ ICO EXACT E DZ	0.00 10.70 20.72 8.33 8.97 0.99 0.14 179.07 0.00 803.25 37.80	1 1 1 2 1 10 70 1 (1) 1	\$0.00 \$10.70 \$20.72 \$16.65 \$8.97 \$9.90 \$9.45 \$179.07 \$0.00 \$803.25 \$37.80

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 47076

Work Order Notes

(LISAPATE) A/C not working

Job Notes

03-01-010 - REPLACE NEW EVAPORATOR

(EHOWELL) Removed plastic trim panel, hand rail, center cup holder, fire extinguisher, etc. Disconnected various wires for accessories. Removed dash and instrument panel. Replaced evaporator core, evaporator temperature sensor, and heater core. Assembled vehicle and filled cooling system with coolant. Observed evaporator temperature sensor with the AC operating and it was approximately 39 degrees F. Additional 2.0 HRS for removing aftermarket/up-fitter items. EH

03-01-011 - REPLACE NEW HEATER CORE

(LISAPATE) Replaced heater core EH

03-15-045 - REPLACE NEW STEERING ANGLE SENSOR

(EHOWELL) The customer needs to bring the vehicle back so we can replace the steering angle sensor. The part should be delivered on 5/25/23. EH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

10-22-003 - SERVICE DIFFERENTIAL CARRIER

(EHOWELL) Found the differential fluid dark during the last PM inspection and recommended a service. Drained rear differential fluid. Added 4 quarts of 75W140W. EH .5 HR

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered 4.36 lb. and drained 0.0 oz. of oil. Pulled a vacuum. Leak test passed. Charged vehicle with 4.75 lb. of refrigerant. Added additional .25 lb. EH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been 1200 miles since the last PM. Checked fluids(added 1/2 QT of oil) battery tire pressure and updated the oil change sticker. Needs a transmission service soon. SH

CH-SP - CHARGE Shop Supplies

SO-15 - SCAN OUT STEERING

(EHOWELL) While test driving the vehicle, the hill start assist not available message was displayed on the driver information center. Found DTCs: C0051:64-48 Steering Wheel Position Sensor and P193C:00-6C Steering Wheel Angle Signal. The steering angle sensor PID was reading 379 degrees when it should have been reading 0 degrees. EH

Page:1

Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		242430	2017 FOR	D F550)				WORK OR	DER NO	: 48	925		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	11/17/20	23 10:08:54 23 13:10:02 23 09:57:39	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 22870 DATE :	ME 09/01/20	y Automotive S E TER 2 - N: 17 GY6HED3287	0	
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	N	GARAGE	0.01	\$1.34	\$16.65	\$0.	.00	\$17.99	
24-01-001	REPAIR	AIR CONDITIONIN	G ASSEMBLY	DON	N	Ν	GARAGE	0.25	\$29.50	\$0.00	\$0.	.00	\$29.50	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.68	\$79.85	\$70.83	\$0.	.00	\$150.68	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00	
SO-00	SCAN O	UT COMPLETE VE	HICLE	DON	N	N	GARAGE	0.02	\$2.62	\$0.00	\$0.	.00	\$2.62	
WA-00	WASH C	OMPLETE VEHICL	.E	DON	Р	N	GARAGE	0.36	\$42.91	\$0.00	\$0.	.00	\$42.91	
JOB COUN	IT: 6				WC	RK ORI	DER TOTAL	.: 1.32	156.2	22	87.48	5.00		248.70
Job Code CH-SP	CHARGE SI	Job Descript	<u>tion</u>	5	<u>∨</u> 03163	<u>'endor N</u>	lo. 1	Invoice No.	<u>Purchas</u>	e Order No	<u>).</u>		<u>Total</u>	\$5.00
												COMML		5.00
<u>Job Code</u> 24-01-001		Job Descript CONDITIONING ASS		1	<u>En</u> 2052187	<u>iployee</u>		<u>Start</u> 1/17/2023 07:00:00	_	i <u>nish</u> : 07:15:00		Quantity 0.25	<u>Total</u>	<u>Cost</u> \$29.50
SO-00		COMPLETE VEHICLI			2052187			1/17/2023 07:00:00 1/17/2023 12:10:45				0.23		\$2.62
WA-00		PLETE VEHICLE	_		2395904			1/17/2023 12:10:43 1/10/2023 13:00:00				0.36		\$42.91
WA-00		PLETE VEHICLE			2395904			1/10/2023 13:58:57				0.00		\$0.00
03-51-038		IEW WIPER BLADES			2395904			1/10/2023 11:45:25				0.01		\$1.34
03-51-038		IEW WIPER BLADES			2395904			1/10/2023 11:45:25				(0.01)		(\$1.34)
03-51-038	REPLACE N	IEW WIPER BLADES		1	2395904	1	1	1/10/2023 11:45:25	11/10/2023	11:46:06		0.01		\$1.34
66-PM-PMA	PERFORM (OIL CHANGE		1	2395904	1	1	1/10/2023 10:57:41	11/10/2023	11:38:17		0.68		\$79.85
												LABOR		156.22
Job Code		Job Descript	tion			Part No	<u>.</u>	Des	scription	<u></u>	Jnit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE		5	W20TQ	Г	C	UART CAM2 SYN	5W20 32OZ		9.27	7		\$64.89
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		C	IL FILTER			5.94	1		\$5.94
03-51-038	REPLACE N	IEW WIPER BLADES		2	2-1		٧	/IPER BLADE 22"	TRICO EXACT		8.33	2		\$16.65

The University of Alabama Work Order Charge Detail

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	(2)	(\$16.65)
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
					PARTS	87.48

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 48925

Work Order Notes

(LRUSHING) pm-wash - a/c is not working again.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc (IFALLS) Visit Reason Changed On 11/20/2023 9:56 AM By IFALLS

24-01-001 - REPAIR AIR CONDITIONING ASSEMBLY

(GARAGE) During test drive on hill assist issues, did not find any issues with a/c. It was blowing cold both days of test driving. JAW

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(GARAGE) Scanned unit for hill assist problem. Had no stored codes in system. Test drove and test on hills and the hill assist is operating correctly. No issues found. JAW

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

UNIT NO:		242430	2017 FOR) F550)				WORK (ORDER NO): 4	19615	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED	DATE:	02/07/20	24 08:52:17 24 12:59:29 24 15:15:26		M: 23064 CE DATE:	N 09/01/2		0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATI	ERIAL (COMMERCIAL	TOTAL COST
03-35-005	REPLAC	E NEW DOOR SW	TTCH	DON	Ν	Ν	GARAGE	1.21	\$142.19	\$86.07	\$	60.00	\$228.26
06-02-006	INSPEC	ΓROOF PANEL & F	REINFORCEN	DON	N	N	GARAGE	0.33	\$38.78	\$0.00	\$	60.00	\$38.78
06-02-018	INSPECT	Γ DOOR MECHANI	SM	DON	N	Ν	GARAGE	0.23	\$26.81	\$0.00	\$	60.00	\$26.81
24-79-016	REPAIR	EMERGENCY ROO	OF HATCH	DON	N	N	GARAGE	1.20	\$141.90	\$44.96	\$	60.00	\$186.86
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00
JOB COUN	IT: 5				wo	RK ORI	DER TOTAL	: 2.96	34	9.68	131.03	5.00	485.71
Job Code CH-SP	CHARGE SI	Job Descript	<u>tion</u>	5	V 03163	endor N	l o. 1	Invoice No.	Purch	ase Order N	l <u>o.</u>	COMML	Total Cost \$5.00
Job Code		Job Descript	tion		Em	ployee	No	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
06-02-018	INSPECT D	OOR MECHANISM	<u>lion</u>	1	<u>تت</u> 2052187	-		<u>Start</u> 1/30/2024 08:24:31	01/30/2	024 08:38:09		0.23	\$26.81
03-35-005	REPLACE N	IEW DOOR SWITCH		1	2052187		0:	2/01/2024 09:39:30	02/01/2	024 10:51:48		1.21	\$142.19
24-79-016	REPAIR EM	ERGENCY ROOF HA	ATCH	1	2052187		0:	2/01/2024 08:27:09	02/01/2	024 09:39:18		1.20	\$141.90
06-02-018	INSPECT D	OOR MECHANISM		1	2052187		0	1/30/2024 08:24:31	01/30/2	024 08:38:09		0.23	\$26.81
06-02-018	INSPECT D	OOR MECHANISM		1	2052187		0	1/30/2024 08:24:31	01/30/2	024 08:38:09		(0.23)	(\$26.81)
06-02-006	INSPECT R	OOF PANEL & REINF	FORCEMENTS	1	2052187	•	0	1/30/2024 08:04:34	01/30/2	024 08:24:17		0.33	\$38.78
06-02-006	INSPECT R	OOF PANEL & REINF	ORCEMENTS	1	2052187	•	0	1/30/2024 08:04:34	01/30/2	024 08:24:17		(0.33)	(\$38.78)
06-02-006	INSPECT R	OOF PANEL & REINF	ORCEMENTS	1	2052187		0	1/30/2024 08:04:34	01/30/2	024 08:24:17		0.33	\$38.78
												LABOR	349.68
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	<u>Quantity</u>	Total Cost
03-35-005	REPLACE N	IEW DOOR SWITCH		0	8011003		S	WITCH, AUTOMAT	TIC DOOR BU	S	86.0	7 1	\$86.07
24-79-016	REPAIR EM	ERGENCY ROOF HA	ATCH	L	SB27034	1145	R	V CAULK SELF-LE	EVELING WHI	TE	14.9		\$44.96
												PARTS	131.03

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 49615

Work Order Notes

(EHANNAH) roof is leaking- door will not open, passenger side door.

Job Notes

03-35-005 - REPLACE NEW DOOR SWITCH

(JWRIGHT) Replaced auto door switch. 1/2 he labor. JAW

06-02-006 - INSPECT ROOF PANEL & REINFORCEMENTS

(JWRIGHT) Inspected roof and found cracks and gaps in the caulking along the roof panels. Need to reseal roof. JAW (IFALLS) Visit Reason Changed On 2/7/2024 3:14 PM By IFALLS

06-02-018 - INSPECT DOOR MECHANISM

(JWRIGHT) Inspected and found switch has a short in it and needs replaced. JAW (IFALLS) Visit Reason Changed On 2/7/2024 3:14 PM By IFALLS

24-79-016 - REPAIR EMERGENCY ROOF HATCH

(JWRIGHT) sealed roof panels and around the seal of emergency hatch. JAW 1 hr

UNIT NO:		242430	2017 FORI	D F550)				WORK ORD	ER NO:	50666	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED D DAT	DATE:	06/18/202	24 10:45:17 24 07:52:27 24 07:33:49	LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL I	24016 ATE : 09/0	ersity Automotive METER 2 - N: 1/2017 AF5GY6HED3287	0
JOB CODE	E	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
03-01-055	REPLAC	E NEW A/C LINE(S	5)	DON	N	N	GARAGE	2.69	\$317.03	\$98.12	\$0.00	\$415.15
03-01-056	REPLAC	E NEW A/C ORFIC	E VALVE/FILT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
03-03-016	REPLAC	E NEW TEMPERAT	TURE SENDII	DON	Ν	N	GARAGE	0.00	\$0.00	\$48.87	\$0.00	\$48.87
03-13-002	REPLAC	E NEW REAR BRA	KES & DRUN	DON	N	N	GARAGE	0.00	\$0.00	\$138.73	\$0.00	\$138.73
03-15-029	REPLAC	E NEW STEERING	STABILIZER	DON	N	N	GARAGE	0.00	\$0.00	\$95.01	\$0.00	\$95.01
03-15-047	REPLAC	E NEW STEER SW	/ITCH	DON	Ν	N	GARAGE	0.00	\$0.00	\$495.26	\$0.00	\$495.26
03-32-002	REPLAC	E NEW BATTERY		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFOR	RM MOUNT AND BA	ALANCE TIRE	DON	N	N	GARAGE	0.01	\$1.44	\$1,893.48	\$0.00	\$1,894.92
66-79-003	PERFOR	RM SAFETY INSPE	CTION	DON	Υ	N	GARAGE	2.74	\$323.88	\$0.00	\$0.00	\$323.88
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.54	\$63.56	\$0.00	\$0.00	\$63.56
66-PM-PMC	PERFOR	RM CABIN FILTER F	REPLACEMEI	DON	Р	N	GARAGE	0.00	\$0.00	\$30.65	\$0.00	\$30.65
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-15	SCAN O	UT STEERING		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUN	IT: 13				WC	RK ORI	DER TOTAL	: 5.98	705.91	2,800.12	2 5.00	3,511.03
Job Code		Job Descript	ion		v	endor N	О.	Invoice No.	Purchase	Order No.		Total Cost
CH-SP	CHARGE SI			5	03163		<u> </u>					\$5.00
											COMML	5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fin</u>	<u>ish</u>	Quantity	Total Cost
03-01-055	REPLACE N	IEW A/C LINE(S)		1	1310047	7	05	5/08/2024 09:08:58	05/08/2024 1	1:50:10	2.69	\$317.03
66-17-028	PERFORM	MOUNT AND BALANC	CE TIRES	1	1074414	ļ	05	5/06/2024 11:49:45	05/06/2024 1	1:50:29	0.01	\$1.44
66-PM-PMA	PERFORM	OIL CHANGE		1	2395904	1	04	/23/2024 13:19:27	04/23/2024 1	3:51:46	0.54	\$63.56
35-01	DIAGNOSE	AIR CONDITIONING,	HEAT, VENT	1	1310047	7	04	/24/2024 07:03:26	04/24/2024 1	1:28:07	4.41	\$520.54
35-01	DIAGNOSE	AIR CONDITIONING,	HEAT, VENT	1	1310047	,	04	/24/2024 07:03:26	04/24/2024 1	1:28:07	(4.41	(\$520.54)
FleetFocus M5	- WODETAIL	- Work Order Detail v2	20.0									Page:1

Total Cost

Work Order Charge Detail

Job Description

Job Code

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

Quantity

<u>Finish</u>

<u>Start</u>

66-79-003	PERFORM SAFETY INSPECTION	11310047	04/24/2024 12:59:50	04/24/2024 15:44:31		2.74	\$323.88
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/10/2024 08:08:36	05/10/2024 15:51:18		7.71	\$909.98
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/10/2024 08:08:36	05/10/2024 15:51:18		(7.71)	(\$909.98)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 08:31:14	05/30/2024 09:15:00		0.73	\$86.07
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 09:30:00	05/30/2024 11:47:58		2.30	\$271.33
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 09:30:00	05/30/2024 11:47:58		(2.30)	(\$271.33)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 08:31:14	05/30/2024 09:15:00		(0.73)	(\$86.07)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 13:02:45	05/30/2024 14:15:00		1.20	\$142.09
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 14:30:00	05/30/2024 15:48:35		1.31	\$154.55
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 14:30:00	05/30/2024 15:48:35		(1.31)	(\$154.55)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	05/30/2024 13:02:45	05/30/2024 14:15:00		(1.20)	(\$142.09)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	12395904	06/11/2024 09:15:25	06/11/2024 09:15:25		0.00	\$0.00
						LABOR	705.91
Job Code	Job Description	Part No.	Descri	iption_	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	₹	6.44	1	\$6.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGH	Т	0.84	2	\$1.68
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58124	1.25 OZ WHEEL WEIGI	HT	0.60	4	\$2.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	009121	TIRE 225/70R19.5 BRD)G R238 LRG	464.46	4	\$1,857.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME	E LOW BOLT IN	7.89	4	\$31.56
03-03-016	REPLACE NEW TEMPERATURE SENDING UNIT	NL3Z19C734	SENSOR		48.87	1	\$48.87
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER		30.65	1	\$30.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22200	TR412 VALVE STEM SI	HORT STYLE	0.56	(4)	(\$2.22)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22200	TR412 VALVE STEM SI	HORT STYLE	0.56	4	\$2.22
03-15-029	REPLACE NEW STEERING STABILIZER	KYBSS10202	STEERING DAMPER		95.01	1	\$95.01
03-01-055	REPLACE NEW A/C LINE(S)	HC3Z19867B	A/C LINE		98.12	1	\$98.12
03-15-047	REPLACE NEW STEER SWITCH	HC3Z3F791AC	STEERING COLUMN S	SWITCH	495.26	1	\$495.26
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	07480	ROLOC DISC 2 IN COA	ARSE	1.88	6	\$11.25
03-13-002							0404.04
	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWRZ362018A	REAR BRAKE PADS		121.04	1	\$121.04

Employee No.

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 50666

Work Order Notes

(LISAPATE) PM-Do SI-Check front A/C blows hot-replaced hill assist sensor

Job Notes

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

03-01-055 - REPLACE NEW A/C LINE(S)

(EHOWELL) Replaced the AC compressor suction line due to a possible restriction. (Per Ford Service Information) EH .8HR

03-01-056 - REPLACE NEW A/C ORFICE VALVE/FILTER

(EHOWELL) Replaced the orifice tube in the auxiliary AC system behind the driver's seat. No obvious changes were noticed in the AC performance. EH .4 HR

03-03-016 - REPLACE NEW TEMPERATURE SENDING UNIT

(EHOWELL) Drilled a hole in the side of the HVAC case and installed a new Evaporator Temperature Sensor. Soldered a wire into the violet-colored wire coming from the Front Controls Interface Module. Connected the wire to the new sensor. Ran another wire to ground and connected to the sensor. 1.0 HR

We will not be able to get a parts warranty on this sensor because it would have been necessary to remove the dash to retrieve the old sensor. EH

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Replaced rear brake pads. Scuffed rotors using multiple Roloc discs. EH 1.4 HRS

RR Rotor Thickness- 38.7mm LR Rotor Thickness- 38.7mm

03-15-029 - REPLACE NEW STEERING STABILIZER

(EHOWELL) Replaced steering stabilizer. EH .5 HR

03-15-047 - REPLACE NEW STEER SWITCH

(EHOWELL) Installed a new Steering Column Switch Housing Assembly. (Includes: Clock Spring and Multifunction Switch.) DTCs: U2100 and U2101 set due to configuration not being completed. Performed Programmable Module Installation "PMI" for the Steering Column Control Module. Entered As Built data. Cleared DTCs and performed a SCCM self-test. The self-test passed. EH 1.5 HRS

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) FC replaced the two batteries in the compartment on the right side of the vehicle and the battery under the hood. EH

03-79-009 - REPLACE NEW SEAT BELT(S)

09-15 - ALIGN STEERING

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

(EHOWELL) The vehicle's factory AC system is freezing up because the compressor is not cycling off. There is an aftermarket auxiliary system tied into the factory AC system. The compressor cycles on/off based on the readings given from the Evaporator temperature sensor. This sensor appears to be reading properly when compared to multiple sensors on the vehicle. (After vehicle sits overnight.)

The Powertrain Control Module is responsible for engaging and disengaging the AC compressor. Reprogrammed the PCM. Calibration has been loaded and checked.

The Front Controls Interface Module reads the temperature of the evaporator temperature sensor. The sensor is a thermistor. Resistance decreases as temperature increases and vice versa. Installed a resistor switch board in place of the evaporator temperature sensor and observed the readings through the data on the Ford scan tool. The degrees read by the sensor corresponded to the resistance change when the dial was turned to increase or decrease resistance. This proves that the FCIM is receiving the correct temperature, however it may not be communicating the proper message to the PCM via serial data.

Placed the evaporator temperature sensor in water and froze the sensor in the freezer. Plugged the wires into the sensor and examined the reading via scan tool, while heating/melting the ice. According to Ford, the compressor should come on when the sensor reads 33.8 degrees F. The compressor did not engage until the evaporator temperature sensor read 39.2 degrees F. It appears the FCIM may have delayed sending the message to the PCM.

When attempting to command the AC compressor on with the scan tool, there is an exclamation point beside the output control button. This means that there is a communication error. The Front Blower Relay also had the same issue when attempting to command it through the FCIM. Disconnected both FCIM connectors and was able to command the AC clutch using the scan tool.

The AC is still freezing up and we should probably look at replacing the Front Controls Interface Module. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) SH Mounted FC balanced 4 tires. SH

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed Safety Inspection. EH/FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check FC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EHOWELL) Installed a new cabin filter. EH

CH-SP - CHARGE Shop Supplies

SO-15 - SCAN OUT STEERING

(EHOWELL) In May of last year, the "hill start assist not available" message was displayed on the driver information center. Found DTCs: C0051:64-48 Steering Wheel Position Sensor and P193C:00-6C Steering Wheel Angle Signal. The steering angle sensor PID was reading 379 degrees when it should have been reading 0 degrees. The vehicle was released without the installation of a new part. EH *No Charge for Scan Out*

UNIT NO:		242430 2	017 FORI	D F550)				WORK C	RDER NO:	51	231	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE ord F55	ETED	DATE:	09/04/202	24 07:53:18 24 08:12:52 24 15:46:01			ME 09/01/201	TER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>1</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATER</u>	RIAL CO	MMERCIAL	TOTAL COST
03-32-002	REPLAC	E NEW BATTERY		DON	N	N	GARAGE	0.00	\$0.00	\$399.96	\$0.0	00	\$399.96
03-79-009	REPLAC	E NEW SEAT BELT(S	S)	DON	N	N	GARAGE	0.00	\$0.00	\$172.17	\$31	.40	\$203.57
09-15	ALIGN S	TEERING		DON	N	N	GARAGE	0.03	\$3.11	\$0.00	\$0.0	00	\$3.11
24-52-003	REPAIR	RADIO		DON	N	N	GARAGE	0.00	\$0.00	\$581.25	\$0.0	00	\$581.25
66-01-058	PERFOR	M EVAC AND RECH	ARGE FRE	DON	N	N	GARAGE	0.03	\$3.41	\$0.00	\$0.0	00	\$3.41
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0		\$5.00
JOB COUN	IT: 6				WO	RK ORI	DER TOTAL:	0.06		6.52 1, ²	153.38	36.40	1,196.30
Job Code		Job Descriptio	n		v	endor N	lo.	Invoice No.	Purch	ase Order No			Total Cost
03-79-009	REPLACE N	IEW SEAT BELT(S)	_	6	632287		<u>-</u>	326P			_		\$31.40
CH-SP	CHARGE SI	nop Supplies		5	03163		1						\$5.00
												COMML	36.40
Job Code		Job Descriptio	<u>n</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-01-058	PERFORM I	EVAC AND RECHARGE	FREON	1:	2052187	,	07	/22/2024 09:49:22	07/22/20	024 09:51:06		0.03	\$3.41
09-15	ALIGN STEE	ERING		1	1310047	•	08	/12/2024 14:24:36	08/12/20)24 14:26:11		0.03	\$3.11
												LABOR	6.52
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>	Des	cription	<u>U</u>	Init Price	Quantity	Total Cost
03-79-009	REPLACE N	IEW SEAT BELT(S)		8	0657302	200AB	SE	AT BELT			172.17	1	\$172.17
24-52-003	REPAIR RAI	OIO		Н	C3Z188	42AAE	FC	IM			581.25	1	\$581.25
03-32-002	REPLACE N	IEW BATTERY		6	51		ВА	TTERY BCI 65 75	0CCA		199.98	2	\$399.96
												PARTS	1153.38

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 51231

Work Order Notes

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EKIMBREL) Should have been billed om WO#50666

03-79-009 - REPLACE NEW SEAT BELT(S)

09-15 - ALIGN STEERING

24-52-003 - REPAIR RADIO

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(GARAGE) Evac and recharge. Repaired leak at the expansion valve. Recovered 5.17lbs and recharged 5.17lbs with 1oz oil. JAW

66-13-130 - PERFORM Burnish Brakes

UNIT NO:		242430	2017 FOR) F550)				WORK O	RDER NO	: 52	011	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507203 CLOSED SCHEDULED 17FORDF550		OPENE COMPL CLOSE Ford F55	ETED D DAT	DATE:	09/28/202	4 08:16:40 4 08:19:54 4 08:26:03	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 24021 E DATE:	ME 09/01/201	Automotive S TER 2 - N: 7 Y6HED3287	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	MMERCIAL	TOTAL COST
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00
PD-00-999	PREP DI	SPOSE PREPARE	UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$35.00	\$0.0	00	\$35.00
JOB COUN	T: 2				wo	RK ORD	DER TOTAL:	0.00	C).00	35.00	5.00	40.00
Job Code		Job Descripti	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1						\$5.00
												COMML	5.00
Job Code		Job Descripti	ion			Part No	<u>.</u>	Des	cription	<u></u>	Jnit Price	Quantity	Total Cost
PD-00-999	PREP DISPO	OSE PREPARE UNIT	FOR DISPOSAL	_ 0	8984		AD	HESIVE REMOVE	ER		35.00	1	\$35.00
												PARTS	35.00

The University of Alabama

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

UNIT NO: 242430 2017 FORD F550 WORK ORDER NO: 52011

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) closed due to year end.

(EHOWELL) We did not need to reopen this work order. We charged for the prep for sale when we closed this work order. We just added the prep for sale notes to this work order after completing it today. CW/RC removed work marks, removed tag # 1395C, checked inside of vehicle. The vehicle did not have a GPS.

Report Printed: 10/25/2024 11:53:14 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Fri Oct 25 2024 11:53:14 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'242430') //Q=