

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 10100

USING DEPT NO:	504302	OPENED DATE:	01/19/2012 10:22:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2012 13:58:35	METER 1 - M:	28018	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2012 13:58:37	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-016	REPAIR TAIL&LIFT GATE	DON	O	N	GARAGE	0.50	\$28.75	\$8.59	\$0.00	\$37.34

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	8.59	0.00	37.34
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	11268671	01/19/2012 16:00:00	01/19/2012 16:30:00	0.50	\$28.75
					LABOR	28.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	DEXRON III	TRANSMISSION FLUID	3.68	1	\$3.68
24-02-016	REPAIR TAIL&LIFT GATE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
					PARTS	8.59

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **10100**

---

## Work Order Notes

(LPATE) PER SHANE HYD LIFT IS LEAKING FLUID AND SQUEALING WHEN GOING UP AND DOWN.

---

## Job Notes

### **24-02-016 - REPAIR TAIL&LIFT GATE**

(LPATE) TIGHTENED HYD HOSES TO LIFT, CLEANED UP FLUID FROM AREA DRIVER WILL WATCH AND ADVISE IF ANY MORE LEAKAGE. ADDED A QT OF FLUID. RECHECKED LIFT IS OPERATING PROPERLY.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 10220

USING DEPT NO:	504302	OPENED DATE:	02/02/2012 09:17:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2012 07:17:51	METER 1 - M:	28204	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2012 07:17:52	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.58	\$148.25	\$128.40	\$0.00	\$276.65

JOB COUNT: 2	WORK ORDER TOTAL:	3.08	177.00	128.40	0.00	305.40
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	02/03/2012 07:00:00	02/03/2012 07:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/02/2012 11:33:26	02/02/2012 12:59:41	1.44	\$82.66
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/02/2012 10:35:07	02/02/2012 11:43:34	1.14	\$65.60
					LABOR	177.01

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	240	\$25.20
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.74	1	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	65A	BATTERY TOP POST FORD	83.52	1	\$83.52
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	5.31	1	\$5.31
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	9.63	1	\$9.63
					PARTS	128.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 10220

## Work Order Notes

(LPATE) PM-BATTERY FAILED, REPLACE BATTERY

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LPATE) REPLACED BATTERY

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY SH-REPLACED OIL DRAIN PLUG

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 10911

USING DEPT NO:	504302	OPENED DATE:	05/01/2012 11:32:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2012 14:14:35	METER 1 - M:	29165	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2012 14:14:36	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$385.56	\$385.56

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	385.56	385.56
--------------	-------------------	------	------	------	--------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D225236	0015676	\$385.56
				COMML	385.56

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 10911

## Work Order Notes

(LPATE) SHANE DAMAGED RIGHT FRONT TIRE, TAKING TO GOODYEAR TO BE REPLACED.

## Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR REPLACED RIGHT FRONT TIRE. P0039720

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 1115

USING DEPT NO:	504302	OPENED DATE:	04/11/2008 13:51:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2008 10:09:03	METER 1 - M:	10990	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/15/2008 10:09:04	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01	REPLACE NEW AIR CONDITIONING, HE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.00	\$45.00	\$0.00	\$0.00	\$45.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$43.59	\$0.00	\$57.54

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	58.95	43.59	0.00	102.54
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-01	REPLACE NEW AIR CONDITIONING, HEAT, VENT	11112000	MRCS109454	01326	\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11088474	04/15/2008 07:00:00	04/15/2008 07:18:36	0.31	\$13.95
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11088474	04/15/2008 07:18:36	04/15/2008 08:18:36	1.00	\$45.00
				LABOR		58.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	8.94	1	\$8.94
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.40	1	\$7.40
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	3.74	1	\$3.74
				PARTS		43.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 1115

## Work Order Notes

(LOBRIEN) PM AND BLOWER INOPERABLE AGAIN ON SPEEDS, 1, 2 & 3-WARRANTY

## Job Notes

**03-01 - REPLACE NEW AIR CONDITIONING, HEAT, VENT**

(LOBRIEN) REPLACED BLOWER MOTOR RESISTOR.

**16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT**

(LOBRIEN) TAKEN TO MADDEN-WARRANTY.

**66-PM-PMA - PERFORM OIL CHANGE**

(LOBRIEN) PM BY JASON ELMORE.



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 11701

USING DEPT NO:	504302	OPENED DATE:	08/17/2012 13:42:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2012 14:09:48	METER 1 - M:	30971	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/21/2012 14:09:49	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$46.14	\$66.41	\$0.00	\$112.55

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.80</b>	<b>46.14</b>	<b>66.41</b>	<b>0.00</b>	<b>112.55</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	08/17/2012 13:42:40	08/17/2012 14:30:49	0.80	\$46.14
					<b>LABOR</b>	<b>46.14</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	16.43	1	\$16.43
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	8	\$45.24
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.74	1	\$4.74
					<b>PARTS</b>	<b>66.41</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 11701

## Work Order Notes

(GMANNING) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20 OIL BOTTLE Qty 224 Cost 0

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY BG/RT-REPLACED AIR FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 11829

USING DEPT NO:	504302	OPENED DATE:	09/05/2012 13:31:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2012 13:51:56	METER 1 - M:	31172	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2012 13:51:57	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$482.62	\$0.00	\$482.62

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	482.62	0.00	482.62
--------------	-------------------	------	------	--------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-55-012	PURCHASED CARGO RESTRAINTS	BOX98208R2PLY	TOW STRAP	32.52	1	\$32.52
PU-55-012	PURCHASED CARGO RESTRAINTS	ASL557WHK	27X2 RATCHET	22.47	1	\$22.47
PU-55-012	PURCHASED CARGO RESTRAINTS	BOXFH40638	GRAB HOOK 3/8	5.81	2	\$11.61
PU-55-012	PURCHASED CARGO RESTRAINTS	FWS70413	3/8 CHAIN	3.88	3	\$11.65
PU-55-012	PURCHASED CARGO RESTRAINTS	BOX98320R	TOW STRAP HD 3X20 60K	67.40	6	\$404.37
<b>PARTS</b>						<b>482.62</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 11829

## Work Order Notes

(LPATE) DEPT REQUESTED EQUIPMENT TO HELP INSTALL TENTS FOR FOOTBALL GAMES.

## Job Notes

### **PU-55-012 - PURCHASED CARGO RESTRAINTS**

(LPATE) RW PURCHASED TOW STRAPS, CHAINS AND RATCHETS FOR INSTALLING TENTS AT PRESIDENTS MANSION.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 1207

USING DEPT NO:	504302	OPENED DATE:	04/28/2008 10:00:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2008 10:01:24	METER 1 - M:	11202	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/28/2008 10:01:24	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$11.25	\$29.82	\$0.00	\$41.07

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.25</b>	<b>11.25</b>	<b>29.82</b>	<b>0.00</b>	<b>41.07</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11088858	04/28/2008 10:02:00	04/28/2008 10:17:00	0.25	\$11.25
					<b>LABOR</b>	<b>11.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	14.91	2	\$29.82
					<b>PARTS</b>	<b>29.82</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 1207

## Work Order Notes

(LOBRIEN) NEED NEW WIPER BLADES.

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LOBRIEN) REPLACED WIPER BLADES.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 12346

USING DEPT NO:	504302	OPENED DATE:	11/07/2012 15:25:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2012 06:54:04	METER 1 - M:	31714	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/08/2012 06:54:06	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-55-009	INSPECT LIFT ASSEMBLY - LIFT TRUCK	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-01	REPAIR AIR CONDITIONING, HEAT, VEN	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$215.60	\$215.60
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 4	WORK ORDER TOTAL:	2.00	115.00	0.00	215.60	330.60
--------------	-------------------	------	--------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-01	REPAIR AIR CONDITIONING, HEAT, VENT	11122732	156153	0017927	\$215.60
				COMML	215.60

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11397026	11/07/2012 15:30:04	11/07/2012 16:00:04	0.50	\$28.75
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11397026	11/07/2012 15:30:15	11/07/2012 16:30:15	1.00	\$57.50
06-55-009	INSPECT LIFT ASSEMBLY - LIFT TRUCKS	11397026	11/07/2012 15:30:10	11/07/2012 16:00:10	0.50	\$28.75
				LABOR		115.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 12346

## Work Order Notes

(LPATE) CHECK A/C IS NOT GETTING COLD/CHECK LIFT GATE FOR LEAK

## Job Notes

### **06-55-009 - INSPECT LIFT ASSEMBLY - LIFT TRUCKS**

(LPATE) CHECKED LIFT FOR LEAK COULD NOT FIND ONE.

### **16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT**

(LPATE) TAKEN TO FIRESTONE BY BG

### **24-01 - REPAIR AIR CONDITIONING, HEAT, VENT**

(LPATE) FIRESTONE REPLACED SCRADER VALVES AND RECHARGED A/C. PD BY CC

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(LPATE) CHECKED A/C LEAKING AT SERVICE PORT SENT TO FIRESTONE TO REPAIR



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 12904

USING DEPT NO:	504302	OPENED DATE:	01/29/2013 08:15:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/07/2013 13:35:19	METER 1 - M:	32736	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/07/2013 13:35:21	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-017	REPLACE NEW MASS AIR FLOW SENS	DON	O	N	GARAGE	0.80	\$46.00	\$242.40	\$0.00	\$288.40
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	5.30	\$304.88	\$434.68	\$0.00	\$739.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$2.67	\$141.42	\$0.00	\$144.09
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.60	\$34.50	\$17.79	\$0.00	\$52.29
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	24.51	\$1,409.29	\$0.00	\$0.00	\$1,409.29

JOB COUNT: 5	WORK ORDER TOTAL:	31.26	1,797.34	836.29	0.00	2,633.63
--------------	-------------------	-------	----------	--------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	01/29/2013 14:12:32	01/29/2013 14:15:00	0.04	\$2.36
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	01/29/2013 14:30:00	01/30/2013 09:15:00	18.75	\$1,078.13
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	01/30/2013 09:30:00	01/30/2013 14:15:00	4.75	\$273.13
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	01/30/2013 14:30:00	01/30/2013 15:28:06	0.97	\$55.68
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/30/2013 11:43:23	01/30/2013 11:46:10	0.05	\$2.67
03-33-004	REPLACE NEW SPARK PLUGS	11397026	02/05/2013 13:00:00	02/05/2013 13:51:02	0.85	\$48.91
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11397026	02/07/2013 07:00:00	02/07/2013 07:36:00	0.60	\$34.50
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	11397026	02/07/2013 07:00:00	02/07/2013 07:48:00	0.80	\$46.00
03-33-004	REPLACE NEW SPARK PLUGS	11397026	02/05/2013 09:30:00	02/05/2013 12:00:00	2.50	\$143.75
03-33-004	REPLACE NEW SPARK PLUGS	11397026	02/05/2013 07:17:54	02/05/2013 09:15:00	1.95	\$112.22
					LABOR	1797.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE GOLD	ANTIFREEZE-FORD	5.40	5	\$27.00
66-PM-PMA	PERFORM OIL CHANGE	WIX49136	AIR FILTER	27.90	1	\$27.90
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	3L3Z12B579BA	MASS AIRFLOW SENSOR	242.40	1	\$242.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5C3Z3A006AA	POWER STEER RESERVOIR CAP	17.61	1	\$17.61
03-33-004	REPLACE NEW SPARK PLUGS	RADDV310	CLEAR VACUUM LINE	1.17	3	\$3.51
03-33-004	REPLACE NEW SPARK PLUGS	LIS65600	SPARK PLUG REMOVER TOOL	139.35	1	\$139.35
03-33-004	REPLACE NEW SPARK PLUGS	STWSPP87	COIL BOOTS	7.10	3	\$21.29
03-33-004	REPLACE NEW SPARK PLUGS	STWSPP87	COIL BOOTS	7.10	7	\$49.67
03-33-004	REPLACE NEW SPARK PLUGS	CSP7989	SPARK PLUGS PLATINUM	20.81	10	\$208.05
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	17.79	1	\$17.79
03-33-004	REPLACE NEW SPARK PLUGS	SEESF16	SEAFOAM	12.81	1	\$12.81
					<b>PARTS</b>	<b>836.29</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 12904

## Work Order Notes

(LPATE) SCAN OUT CHECK ENGINE LIGHT, PM-REPLACE FUEL FILTER

## Job Notes

### **03-05-017 - REPLACE NEW MASS AIR FLOW SENSOR**

(LPATE) REPLACED MASS AIRFLOW SENSOR

### **03-33-004 - REPLACE NEW SPARK PLUGS**

(RWINTERS) REPLACED SPARK PLUS AND COIL BOOTS 6 OUT OF 10 PLUS BROKE OFF (DUE TO BAD DESIGN) HAD TO USE A SPECIAL TOOL TO REMOVE BROKEN PLUGS, ADDED SEA FOAM, ADDED 2 BOTTLES OF TECHRON FUEL TREATMENT. TEST DROVE LIGHT NEVER CAME ON

### **66-PM-PMA - PERFORM OIL CHANGE**

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.7675

(LPATE) PM BY RS/BG-REPLACED AIR FILTER

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LPATE) REPLACED FUEL FILTER WAS STOPPED UP

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LPATE) SCAN OUT CHECK ENGINE LIGHT P0171 SYSTEM LEAN BANK 1

(RWINTERS) AFTER REPAIRS, COULDN'T GET ALL MONITORS TO CLICK OFF/RESET-ADVISED DRIVER TO BRING BACK ASAP IF CHECK ENGINE LIGHT CAME BACK ON IF NOT, COME BACK AFTER 2 DAYS OF DRIVING TO SEE IF MONITORS RESET.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 13146

USING DEPT NO:	504302	OPENED DATE:	02/25/2013 15:45:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2013 07:42:12	METER 1 - M:	32984	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2013 07:42:14	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CL-44-014	CLEANED INJECTORS - ELECTRONIC	DON	O	N	GARAGE	1.50	\$86.25	\$74.22	\$0.00	\$160.47

JOB COUNT: 1	WORK ORDER TOTAL:	1.50	86.25	74.22	0.00	160.47
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-44-014	CLEANED INJECTORS - ELECTRONIC	11397026	02/26/2013 07:00:00	02/26/2013 08:30:00	1.50	\$86.25
					<b>LABOR</b>	<b>86.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-44-014	CLEANED INJECTORS - ELECTRONIC	MMM08955	3M FUEL SYSTEM CLEANER	37.11	2	\$74.22
					<b>PARTS</b>	<b>74.22</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 13146

## Work Order Notes

(LPATE) CHECK ENGINE LIGHT IS ON SINCE FRIDAY

## Job Notes

### **CL-44-014 - CLEANED INJECTORS - ELECTRONIC**

(LPATE) SCAN OUT CODE P0171 BANK 1 SYSTEM LEAN-LOOKED AT SCAN DATA FUEL TRIM LONG TERM (BANK1-16% BANK 2 49%) SHORT TERM IS NORMAL SWITCHING FROM (+-5% TO +-0%) CLEANED FUEL INJECTORS RAN 2 CANS THROUGH SYSTEM CLEARED CODES RECHECKED SCAN DATA AND TEST DROVE. LONG TERM FUEL TRIM DROPPED TO 6% ON BANK 1 STAYED SAME ON BANK 2 TEST DROVE ALL MONITORS CLICKED OFF AND PASSED TEST.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 13219

USING DEPT NO:	504302	OPENED DATE:	03/06/2013 08:12:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2013 08:02:35	METER 1 - M:	33124	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2013 08:02:37	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-016	REPAIR TAIL&LIFT GATE	DON	O	N	GARAGE	0.50	\$28.75	\$108.48	\$0.00	\$137.23

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	108.48	0.00	137.23
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	11074414	03/06/2013 08:13:42	03/06/2013 08:43:42	0.50	\$28.75
					LABOR	28.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	SHIPPING	SHIPPING AND HANDLING	24.39	1	\$24.39
24-02-016	REPAIR TAIL&LIFT GATE	255072	12 RUBBER DOCK BUMPER	42.05	2	\$84.09
					PARTS	108.48

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 13219

## Work Order Notes

(LPATE) SHANE REQUESTED NEW RUBBER BUMPERS FOR THE LIFTGATE ON HIS TRUCK

## Job Notes

24-02-016 - REPAIR TAIL&LIFT GATE

(LPATE) RT INSTALLED RUBBER BUMPERS ON LIFTGATE OF TRUCK

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14281

USING DEPT NO:	504302	OPENED DATE:	07/08/2013 10:40:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/10/2013 09:15:02	METER 1 - M:	34400	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/10/2013 09:15:05	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$488.12	\$0.00	\$603.12
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.65	\$122.13	\$0.00	\$157.78
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.75	\$17.79	\$0.00	\$46.54
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	1.50	\$86.25	\$95.26	\$0.00	\$181.51

JOB COUNT: 5	WORK ORDER TOTAL:	4.62	265.65	723.30	0.00	988.95
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11413680	07/09/2013 07:00:00	07/09/2013 07:30:00	0.50	\$28.75
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	07/09/2013 07:00:00	07/09/2013 09:00:00	2.00	\$115.00
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11413680	07/09/2013 07:00:00	07/09/2013 08:30:00	1.50	\$86.25
66-PM-PMA	PERFORM OIL CHANGE	11413680	07/09/2013 07:00:00	07/09/2013 07:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	10260422	07/09/2013 06:00:00	07/09/2013 06:18:36	0.31	\$17.83
					LABOR	265.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7B155BA	IN-LINE TRANSMISSION FILTER	48.29	1	\$48.29
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7B155BA	IN-LINE TRANSMISSION FILTER	46.79	(1)	(\$46.79)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD1066M	FRONT PADS	148.67	1	\$148.67
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7B155BA	IN-LINE TRANSMISSION FILTER	46.79	1	\$46.79
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7A098AA	TRANSMISSION FILTER KIT	46.97	1	\$46.97
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	7.20	9	\$64.80
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB680305	ROTOR	169.73	2	\$339.45
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.53	1	\$5.53
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	17.79	1	\$17.79



# Work Order Charge Detail

PARTS	723.30
-------	--------

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14281

## Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER-SERVICE TRANSMISSION-CHECK BRAKES

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(GMANNING) REPLACED FRONT PADS AND ROTORS. TEST DROVE OK.

### **06-13 - INSPECT BRAKES**

(GMANNING) BG INSPECTED BRAKES. FRONT NEED REPLACEMENT, BACK BRAKES STILL LOOK GOOD.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.7675

(GMANNING) PM BY GM/RT

(GMANNING) TRUCK HELD 7.5 QTS OF OIL. BILLED 7 QTS. .5 QT WAS ALREADY CHARGED OUT FROM CABINET.

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(GMANNING) RT REPLACED FUEL FILTER

### **66-PM-PMT - PERFORM TRANSMISSION SERVICE**

(GMANNING) PMT BT RT. CHANGED BOTH FILTERS.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14525

USING DEPT NO:	504302	OPENED DATE:	08/02/2013 08:58:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2013 10:16:19	METER 1 - M:	34682	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2013 10:16:20	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.80	\$46.00	\$79.41	\$0.00	\$125.41
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '1	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.30	74.75	79.41	0.00	154.16
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-01-004	REPLACE NEW BLOWER MOTOR	10260422	08/02/2013 11:18:08	08/02/2013 12:06:08	0.80	\$46.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11268671	08/02/2013 08:59:56	08/02/2013 09:29:56	0.50	\$28.75
					LABOR	74.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-01-004	REPLACE NEW BLOWER MOTOR	TYC700099	BLOWER MOTOR	79.41	1	\$79.41
					PARTS	79.41

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14525

## Work Order Notes

(LPATE) PER SHANE A/C IS NOT WORKING AT ALL

## Job Notes

### 03-01-004 - REPLACE NEW BLOWER MOTOR

(LPATE) REPLACED BLOWER MOTOR. CHECKED OK WORKING ON ALL SPEEDS.

### 35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LPATE) BLOWER MOTOR IS INOP

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14881

USING DEPT NO:	504302	OPENED DATE:	09/12/2013 11:50:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/13/2013 08:23:29	METER 1 - M:	35218	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/13/2013 08:23:30	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-029	REPLACE NEW SEAT TRIM	DON	O	N	GARAGE	2.00	\$115.00	\$1,078.33	\$0.00	\$1,193.33

JOB COUNT: 1	WORK ORDER TOTAL:	2.00	115.00	1,078.33	0.00	1,193.33
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-029	REPLACE NEW SEAT TRIM	11074414	09/13/2013 06:00:00	09/13/2013 07:00:00	1.00	\$57.50
03-02-029	REPLACE NEW SEAT TRIM	10260422	09/13/2013 06:00:00	09/13/2013 07:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>115.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-029	REPLACE NEW SEAT TRIM	6C3Z2562900	SEAT COVER	744.96	1	\$744.96
03-02-029	REPLACE NEW SEAT TRIM	4C3Z25632A22AA	SEAT BOTTOM FOAM	333.37	1	\$333.37
03-02-029	REPLACE NEW SEAT TRIM	6C3Z2562900	SEAT COVER	744.96	(1)	(\$744.96)
03-02-029	REPLACE NEW SEAT TRIM	6C3Z2562900BC	SEAT COVER	744.96	1	\$744.96
					<b>PARTS</b>	<b>1078.33</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14881

## Work Order Notes

(LPATE) INSTALL NEW SEAT BOTTOM AND FOAM HAS A LARGE HOLE ON PASSENGER SIDE

## Job Notes

03-02-029 - REPLACE NEW SEAT TRIM

(GMANNING) R&R BOTTOM HALF OF SEAT. REPLACED PAD AND COVER.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14909

USING DEPT NO:	504302	OPENED DATE:	09/17/2013 07:57:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2013 11:14:32	METER 1 - M:	35253	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2013 11:14:34	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$130.50	\$0.00	\$159.25
03-34-013	REPLACE NEW FLASHER	DON	O	N	GARAGE	0.28	\$16.13	\$18.90	\$0.00	\$35.03

JOB COUNT: 2	WORK ORDER TOTAL:	0.78	44.88	149.40	0.00	194.28
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-013	REPLACE NEW FLASHER	11338644	09/19/2013 15:42:15	09/19/2013 15:59:05	0.28	\$16.13
03-32-002	REPLACE NEW BATTERY	11338644	09/17/2013 07:59:17	09/17/2013 08:29:17	0.50	\$28.75
					LABOR	44.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-013	REPLACE NEW FLASHER	TRDEP27	FLASHER	18.90	1	\$18.90
03-32-002	REPLACE NEW BATTERY	65-1	BATTERY- FORD TOP POST HD	130.50	1	\$130.50
					PARTS	149.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 14909

## Work Order Notes

(LPATE) PER SHANE TRUCK SLOW TO CRANK THIS MORNING, HAD TO JUMP OFF WHILE AT BREWER PORCH

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY, CHECKED ALT CHARGING GOOD

### 03-34-013 - REPLACE NEW FLASHER

(LPATE) REPLASHED FLASHER FOR HAZARD LIGHTS RECHECKED OK



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15105

USING DEPT NO:	504302	OPENED DATE:	10/11/2013 09:43:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2013 13:59:20	METER 1 - M:	35486	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/14/2013 13:59:21	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-017	REPLACE NEW DOOR PANELS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$575.00	\$575.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	<b>575.00</b>	<b>575.00</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-017	REPLACE NEW DOOR PANELS	11076414	TCS33758	0021543	(\$575.00)
03-02-017	REPLACE NEW DOOR PANELS	11076414	TCS33758	0021543	\$575.00
03-02-017	REPLACE NEW DOOR PANELS	11076414	TCS33758	0021543	(\$575.00)
03-02-017	REPLACE NEW DOOR PANELS	11076414	TCS33758	0021543	\$575.00
03-02-017	REPLACE NEW DOOR PANELS	11076414	TCS33758	0021543	\$575.00
<b>COMML</b>					<b>575.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15105

---

## Work Order Notes

(LPATE) BOTTOM PANEL ON CARGO DOOR IS PEELING

---

## Job Notes

03-02-017 - REPLACE NEW DOOR PANELS

(LPATE) OVERHEAD DOOR REPLACED BOTTOM SECTION ON TRUCK. PD BY CC

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15556

USING DEPT NO:	504302	OPENED DATE:	12/04/2013 15:16:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2013 13:14:56	METER 1 - M:	35932	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2013 13:14:56	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$55.94	\$0.00	\$73.77
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.75	\$17.79	\$0.00	\$46.54

JOB COUNT: 2	WORK ORDER TOTAL:	0.81	46.58	73.73	0.00	120.31
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10260422	12/05/2013 06:18:36	12/05/2013 06:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	10260422	12/05/2013 06:00:00	12/05/2013 06:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>46.58</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	7	\$39.69
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	11.10	1	\$11.10
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	17.79	1	\$17.79
					<b>PARTS</b>	<b>73.73</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15556

## Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.78

(LPATE) PM BY GM/SH-REPLACED OIL DRAIN PLUG

**66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LPATE) REPLACED FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15820

USING DEPT NO:	504302	OPENED DATE:	01/10/2014 07:15:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/10/2014 10:19:55	METER 1 - M:	36194	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/10/2014 10:19:56	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-051	REPLACE NEW SEAT COVER	DON	O	N	GARAGE	0.50	\$28.75	\$764.89	\$0.00	\$793.64

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.50</b>	<b>28.75</b>	<b>764.89</b>	<b>0.00</b>	<b>793.64</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-051	REPLACE NEW SEAT COVER	11568366	01/10/2014 08:05:15	01/10/2014 08:35:15	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-051	REPLACE NEW SEAT COVER	6C3Z2564416BA	SEAT BACK COVER	764.89	1	\$764.89
					<b>PARTS</b>	<b>764.89</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15820

## Work Order Notes

(LPATE) DRIVER REQUESTED NEW SEAT BACK COVER

## Job Notes

03-02-051 - REPLACE NEW SEAT COVER

(LPATE) REMOVED AND INSTALLED NEW SEAT BACK COVER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15869

USING DEPT NO:	504302	OPENED DATE:	01/16/2014 06:04:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2014 14:39:24	METER 1 - M:	36222	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/25/2014 14:39:26	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-014	REPLACE NEW HYDRAULIC LIFT SYSTI	DON	O	N	GARAGE	1.00	\$57.50	\$1,181.65	\$0.00	\$1,239.15
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:	2.00	115.00	1,181.65	0.00	1,296.65
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	10260422	02/25/2014 06:00:00	02/25/2014 07:00:00	(1.00)	(\$57.50)
66-79-002	PERFORM SERVICE CALL	10260422	02/25/2014 06:00:00	02/25/2014 07:00:00	1.00	\$57.50
66-79-002	PERFORM SERVICE CALL	11074414	02/25/2014 06:00:00	02/25/2014 07:00:00	1.00	\$57.50
03-55-014	REPLACE NEW HYDRAULIC LIFT SYSTM PUMP MOTI	10260422	02/25/2014 07:00:00	02/25/2014 08:00:00	1.00	\$57.50
					LABOR	115.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-55-014	REPLACE NEW HYDRAULIC LIFT SYSTM PUMP MOTI	28061001	12VDC POWER UNIT (MAXON)	1135.41	1	\$1,135.41
03-55-014	REPLACE NEW HYDRAULIC LIFT SYSTM PUMP MOTI	VV324	TRANS FLUID QT	7.01	1	\$7.01
03-55-014	REPLACE NEW HYDRAULIC LIFT SYSTM PUMP MOTI	SHIPPING	SHIPPING AND HANDLING	39.23	1	\$39.23
					PARTS	1181.65

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 15869

## Work Order Notes

(GMANNING) SERVICE CALL - LIFT WONT GO UP.

## Job Notes

**03-55-014 - REPLACE NEW HYDRAULIC LIFT SYSTM PUMP MOTR**

(LPATE) REMOVED AND REPLACED HYD MOTOR ON LIFTGATE FILLED WITH FLUID, OPERATED CHECKS GOOD

**66-79-002 - PERFORM SERVICE CALL**

(LPATE) SERVICE CALL TO REESE PHIFER GOT LIFT UP AND DROVE TO GARAGE



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 16428

USING DEPT NO:	504302	OPENED DATE:	03/19/2014 08:05:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2014 10:11:03	METER 1 - M:	36782	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2014 10:11:05	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$327.21	\$327.21
03-55-009	REPLACE NEW LIFT ASSEMBLY - LIFT 1	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$5,442.95	\$5,442.95
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
16-55	TRANSPORT CARGO HNDLNG,RESTRN	DON	O	N	GARAGE	12.00	\$690.00	\$0.00	\$0.00	\$690.00

JOB COUNT: 4	WORK ORDER TOTAL:	13.00	747.50	0.00	5,770.16	6,517.66
--------------	-------------------	-------	--------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-55-009	REPLACE NEW LIFT ASSEMBLY - LIFT TRUCKS	11153069	3211401	0023219	\$5,442.95
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	7588361	4800136133	0023235	\$327.21
COMML					5770.16

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	10260422	03/21/2014 06:00:00	03/21/2014 10:00:00	(4.00)	(\$230.00)
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	10260422	03/21/2014 06:00:00	03/21/2014 10:00:00	4.00	\$230.00
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	10260422	03/21/2014 06:00:00	03/21/2014 12:00:00	6.00	\$345.00
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	11338644	03/21/2014 07:00:00	03/21/2014 13:00:00	6.00	\$345.00
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	11338644	03/21/2014 07:00:00	03/21/2014 11:00:00	4.00	\$230.00
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	11338644	03/21/2014 07:00:00	03/21/2014 11:00:00	(4.00)	(\$230.00)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11338644	03/21/2014 07:00:00	03/21/2014 08:00:00	1.00	\$57.50
LABOR						747.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 16428

## Work Order Notes

(LPATE) TAKE TRUCK TO LYNCOACH IN TROY AL TO HAVE NEW LIFTGATE INSTALLED.

## Job Notes

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(GMANNING) TCI REPLACED TIRE ON LOOSE RIM. PD BY CC.

### **03-55-009 - REPLACE NEW LIFT ASSEMBLY - LIFT TRUCKS**

(RWINTERS) LYNCOACH REMOVED EXISTING LIFTGATE AND INSTALLED A NEW WALTCO EMW 33 TC, WITH A 50" X 80" WEDGE PLATFORM. PD BY PAYPAL.

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(RWINTERS) RS REMOVED LF TIRE/RIM TOOK LOOSE TIRE/RIM TO TCI. REINSTALLED NEW TIRE/RIM. pd cc

### **16-55 - TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS**

(GMANNING) GM TOOK TRUCK TO LYNCOACH. RS BROUGHT TRUCK BACK FROM LYNCOACH.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 16675

USING DEPT NO:	504302	OPENED DATE:	04/21/2014 08:00:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2014 09:46:20	METER 1 - M:	37408	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/22/2014 09:46:21	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.04	\$2.30	\$33.72	\$0.00	\$36.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.85	\$106.60	\$50.33	\$0.00	\$156.93

JOB COUNT: 2	WORK ORDER TOTAL:	1.89	108.90	84.05	0.00	192.95
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/21/2014 10:26:06	04/21/2014 10:44:42	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/21/2014 10:15:43	04/21/2014 10:18:07	0.04	\$2.30
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/21/2014 08:11:47	04/21/2014 09:44:25	1.54	\$88.77
					LABOR	108.90

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	16.86	2	\$33.72
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
					PARTS	84.05

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 16675

## Work Order Notes

(GMANNING) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(GMANNING) REPLACED BOTH WIPER BLADES.

### 66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.78

(GMANNING) PM BY SH/RS. USED 1/2 QT OIL ALREADY CHARGED OUT. GREASED LIFTGATE.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 17937

USING DEPT NO:	504302	OPENED DATE:	08/29/2014 13:26:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2014 07:54:57	METER 1 - M:	39500	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2014 07:54:58	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR,TAIL,STO	DON	N	N	GARAGE	0.30	\$17.25	\$0.75	\$0.00	\$18.00
24-02-018	REPAIR DOOR MECHANISM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	0.80	46.00	0.75	0.00	46.75
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-02-018	REPAIR DOOR MECHANISM	11074414	08/29/2014 13:28:35	08/29/2014 14:28:35	(1.00)	(\$57.50)
24-02-018	REPAIR DOOR MECHANISM	11074414	08/29/2014 13:28:35	08/29/2014 14:28:35	1.00	\$57.50
24-02-018	REPAIR DOOR MECHANISM	11074414	08/29/2014 13:28:35	08/29/2014 13:58:35	0.50	\$28.75
03-34-002	REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC	11074414	08/29/2014 13:28:29	08/29/2014 13:46:29	0.30	\$17.25
					LABOR	46.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC	3157	BULB-BRAKE/TURN/PARK	0.75	1	\$0.75
					PARTS	0.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 17937

## Work Order Notes

(LPATE) LEFT FRONT TURN SIGNAL IS OUT-DRIVER DOOR IS RATTLING

## Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT FRONT TURN SIGNAL BULB

24-02-018 - REPAIR DOOR MECHANISM

(LPATE) REMOVED DOOR PANEL FOUND DOOR WAS CRACKED AT THE WINDOW CHANNEL BRACKET. INSTALLED A WASHER TIGHTENED UP. REINSTALLED PANEL. RECHECKED OK

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 18195

USING DEPT NO:	504302	OPENED DATE:	09/23/2014 08:04:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2014 08:45:46	METER 1 - M:	39828	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2014 08:45:47	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-010	REPLACE NEW STARTER	DON	O	N	GARAGE	0.80	\$46.00	\$128.82	\$0.00	\$174.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$51.23	\$0.00	\$69.06
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$17.79	\$0.00	\$46.54

JOB COUNT: 3	WORK ORDER TOTAL:	1.61	92.58	197.84	0.00	290.42
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	09/24/2014 06:00:00	09/24/2014 06:18:36	0.31	\$17.83
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10260422	09/24/2014 06:18:36	09/24/2014 06:48:36	0.50	\$28.75
03-32-010	REPLACE NEW STARTER	11397026	09/24/2014 07:00:00	09/24/2014 07:48:00	0.80	\$46.00
					LABOR	92.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-010	REPLACE NEW STARTER	WPS6646N	STARTER	128.82	1	\$128.82
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	8	\$46.08
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	17.79	1	\$17.79
					PARTS	197.84

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 18195

## Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER-REPLACE STARTER

## Job Notes

### **03-32-010 - REPLACE NEW STARTER**

(LPATE) REPLACED THE STARTER, RECHECKED OK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.78

(LPATE) PM BY NT/GM

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LPATE) REPLACED FUEL FILTER



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 18467

USING DEPT NO:	504302	OPENED DATE:	10/17/2014 15:46:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2014 11:25:48	METER 1 - M:	40029	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2014 11:25:50	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-007	INSTALL CAMERA	DON	O	N	GARAGE	5.00	\$287.50	\$649.95	\$0.00	\$937.45

JOB COUNT: 1	WORK ORDER TOTAL:	5.00	287.50	649.95	0.00	937.45
--------------	-------------------	------	--------	--------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-007	INSTALL CAMERA	11397026	10/23/2014 07:00:00	10/23/2014 12:00:00	5.00	\$287.50
					<b>LABOR</b>	<b>287.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-007	INSTALL CAMERA	CAM3221	BACK UP CAMERA SYSTEM	600.00	1	\$600.00
14-52-007	INSTALL CAMERA	PIC5141A	3/8 CONVOLUTED TUBING 50FT	0.62	50	\$30.75
14-52-007	INSTALL CAMERA	CONNECTOR	CONNECTOR-NYLON	0.84	1	\$0.84
14-52-007	INSTALL CAMERA	PCP WIRE	WIRE-PLASTIC COATED PRIMARY	0.33	10	\$3.30
14-52-007	INSTALL CAMERA	SHIPPING	SHIPPING AND HANDLING	15.06	1	\$15.06
					<b>PARTS</b>	<b>649.95</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 18467

---

## Work Order Notes

(LPATE) INSTALL BACK-UP CAMERA

---

## Job Notes

14-52-007 - INSTALL CAMERA

(LPATE) INSTALLED MONITOR AND BACK UP CAMERA SYSTEM, RAN WIRES AND SOLDERED ALL THE CONNECTIONS. RECHECKED EVERYTHING OK

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 19441

USING DEPT NO:	504302	OPENED DATE:	02/03/2015 13:29:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2015 06:37:43	METER 1 - M:	41100	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2015 06:37:44	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.12	\$6.77	\$43.17	\$0.00	\$49.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.42	\$81.68	\$78.96	\$0.00	\$160.64
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$17.79	\$0.00	\$46.54

JOB COUNT: 3	WORK ORDER TOTAL:	2.04	117.20	139.92	0.00	257.12
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10260422	02/04/2015 08:10:09	02/04/2015 08:40:09	0.50	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	10260422	02/04/2015 08:10:09	02/04/2015 08:17:13	0.12	\$6.77
66-PM-PMA	PERFORM OIL CHANGE	10260422	02/04/2015 06:44:55	02/04/2015 08:10:09	1.42	\$81.68
					LABOR	117.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	8	\$46.08
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.15	1	\$5.15
03-51-038	REPLACE NEW WIPER BLADES	40722A	WIPER BLADE 22"	21.59	2	\$43.17
66-PM-PMA	PERFORM OIL CHANGE	WIX49136	AIR FILTER	27.73	1	\$27.73
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	17.79	1	\$17.79
					PARTS	139.92

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 19441

## Work Order Notes

(LPATE) PM-REPLACE WIPERS AND FUEL FILTER

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LPATE) REPLACED WIPERS

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.78

(LPATE) PM BY GM/SH-REPLACED AIR FILTER

### 66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE) REPLACED FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 20588

USING DEPT NO:	504302	OPENED DATE:	06/22/2015 09:39:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/24/2015 06:40:58	METER 1 - M:	42582	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2015 06:40:59	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$20.88	\$33.29	\$0.00	\$54.17
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.03	\$1.48	\$7.31	\$0.00	\$8.79

JOB COUNT: 2	WORK ORDER TOTAL:	0.39	22.36	40.60	0.00	62.96
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	06/22/2015 13:58:27	06/22/2015 14:00:00	0.03	\$1.48
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	06/22/2015 14:15:00	06/23/2015 06:37:11	16.37	\$941.26
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	06/22/2015 14:15:00	06/23/2015 06:37:11	(16.37)	(\$941.26)
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/22/2015 13:36:35	06/22/2015 13:58:22	0.36	\$20.88
					LABOR	22.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.76	8	\$30.08
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.21	1	\$3.21
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3243	FUEL FILTER	7.31	1	\$7.31
					PARTS	40.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 20588

## Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

The following parts are included with the standard job:

Part No : 5W20FS

Qty : 8

Description : HAVOLINE 5W20 FULL SYN. OIL QT

Manufacturer :

(LPATE) PM BY SH-CLEANED BATTERY CABLES, GREASED LIFTGATE

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LPATE) REPLACED FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 20920

USING DEPT NO:	504302	OPENED DATE:	07/28/2015 08:41:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2015 06:45:57	METER 1 - M:	43069	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/29/2015 06:45:58	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$4.73	\$0.00	\$21.98

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.30</b>	<b>17.25</b>	<b>4.73</b>	<b>0.00</b>	<b>21.98</b>
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11338644	07/28/2015 08:47:42	07/28/2015 09:05:42	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	4.73	1	\$4.73
					<b>PARTS</b>	<b>4.73</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 20920

## Work Order Notes

(LPATE) BRAKE LIGHT OUT

## Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT BRAKE LIGHT BULB



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21017

USING DEPT NO:	504302	OPENED DATE:	08/06/2015 07:41:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/11/2015 13:52:27	METER 1 - M:	43205	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/11/2015 13:52:29	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,750.53	\$1,750.53
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>	<b>1.00</b>	<b>57.50</b>	<b>0.00</b>	<b>1,750.53</b>	<b>1,808.03</b>
---------------------	--------------------------	-------------	--------------	-------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	7588361	4800146547	0029590	\$1,750.53
				<b>COMML</b>	<b>1750.53</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	08/11/2015 07:00:00	08/11/2015 08:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21017

## Work Order Notes

(LPATE) TAKE TRUCK TO TCI TO REPLACE 1 STEER TIRE AND ALL 4 REAR TIRES.

## Job Notes

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) TCI REPLACED 5 TIRES. PD BY CC

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO TCI BY GM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21413

USING DEPT NO:	504302	OPENED DATE:	09/14/2015 08:56:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/15/2015 08:41:27	METER 1 - M:	43681	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/15/2015 08:41:28	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	0.00	0.00	17.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	10260422	09/14/2015 08:57:03	09/14/2015 09:15:03	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21413

## Work Order Notes

(LPATE) GEARLD REQUESTED A SERVICE CALL TO ASB LOADING DOCK BATTERY IS DEAD

## Job Notes

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL COMPLETED. JUMP STARTED. ALT CHARGING AT 14.4V

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21482

USING DEPT NO:	504302	OPENED DATE:	09/21/2015 08:07:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2015 13:00:44	METER 1 - M:	43722	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2015 13:00:45	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	F	GARAGE	0.50	\$28.75	\$61.75	\$0.00	\$90.50
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:	1.50	86.25	61.75	0.00	148.00
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11268671	09/21/2015 08:08:53	09/21/2015 08:38:53	0.50	\$28.75
66-79-002	PERFORM SERVICE CALL	11268671	09/21/2015 08:08:26	09/21/2015 09:08:26	1.00	\$57.50
					LABOR	86.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	65-1	BATTERY- FORD TOP POST HD	61.75	1	\$61.75
					PARTS	61.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21482

## Work Order Notes

(RWINTERS) MANNING REQUESTED A SERVICE CALL TO REESE PHIFER TRUCK HAS A DEAD BATTERY AGAIN

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REPLACED BATTERY

### 66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21521

USING DEPT NO:	504302	OPENED DATE:	09/24/2015 07:30:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2015 09:19:52	METER 1 - M:	43765	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2015 09:19:54	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-78-040	REPAIR TENT STAKE DRIVER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$172.50	\$172.50

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	0.00	172.50	230.00
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-78-040	REPAIR TENT STAKE DRIVER	3439100	16484	0030341	\$172.50
				COMML	172.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	10337093	09/24/2015 07:32:12	09/24/2015 08:32:12	1.00	\$57.50
					LABOR	57.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21521

## Work Order Notes

(LISAPATE) TENT STAKE IS BROKEN

## Job Notes

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) STAKE TAKEN TO HARDSTEEL BY AY

24-78-040 - REPAIR TENT STAKE DRIVER

(LISAPATE) HARDSTEEL REPAIRED TENT STAKE. PD BY CC



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21565

USING DEPT NO:	504302	OPENED DATE:	09/28/2015 14:26:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2015 08:27:45	METER 1 - M:	43765	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2015 08:27:46	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-78-040	PURCHASED TENT STAKE DRIVER	DON	O	N	GARAGE	0.00	\$0.00	\$258.93	\$0.00	\$258.93

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	258.93	0.00	258.93
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-78-040	PURCHASED TENT STAKE DRIVER	SHIPPING	SHIPPING AND HANDLING	29.25	1	\$29.25
PU-78-040	PURCHASED TENT STAKE DRIVER	218D226C	DRIVER SHANK/DRIVER HEAD SET	114.84	2	\$229.68
					PARTS	258.93

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21565

## Work Order Notes

(LISAPATE) RW PURCHASED 2 NEW TENT DRIVER SHANK/DRIVER HEADS FOR LOGISTICS DEPT

## Job Notes

PU-78-040 - PURCHASED TENT STAKE DRIVER

(LISAPATE) PARTS GIVEN TO DEPT

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 21892

USING DEPT NO:	504302	OPENED DATE:	11/04/2015 11:11:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2015 07:18:17	METER 1 - M:	44153	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/06/2015 07:18:19	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-53-014	PURCHASED 5 GAL GAS CAN	DON	O	N	GARAGE	0.00	\$0.00	\$17.10	\$0.00	\$17.10

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	17.10	0.00	17.10
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-53-014	PURCHASED 5 GAL GAS CAN	PLC5600	5GAL PLASTIC GAS CAN	17.10	1	\$17.10
					<b>PARTS</b>	<b>17.10</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **21892**

---

## Work Order Notes

(LISAPATE) MANNING REQUESTED A GAS CAN FOR FILLING GENERATOR

---

## Job Notes

**PU-53-014 - PURCHASED 5 GAL GAS CAN**

(LISAPATE) GAVE MANNING EMPTY GAS CAN.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 22189

USING DEPT NO:	504302	OPENED DATE:	12/10/2015 14:37:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2016 13:38:01	METER 1 - M:	45235	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/03/2016 13:38:02	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	2.00	\$115.00	\$93.77	\$0.00	\$208.77
03-15-009	REPLACE NEW TIE ROD	DON	O	N	GARAGE	1.00	\$57.50	\$97.19	\$0.00	\$154.69
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	2.70	\$155.25	\$143.34	\$0.00	\$298.59
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	5.24	\$301.48	\$8.99	\$0.00	\$310.47
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.50	\$28.75	\$26.37	\$0.00	\$55.12
03-78-043	REPLACE NEW REAR BUMPER GUARD	DON	O	N	GARAGE	1.34	\$77.05	\$113.35	\$0.00	\$190.40
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$97.75	\$97.75
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.22	\$12.71	\$0.00	\$0.00	\$12.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$23.43	\$30.91	\$0.00	\$54.34

JOB COUNT: 10	WORK ORDER TOTAL:	14.41	828.67	513.92	97.75	1,440.34
---------------	-------------------	-------	--------	--------	-------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11074243	16483	0031698	\$97.75
				COMML	97.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	01/20/2016 07:00:00	01/20/2016 08:00:00	1.00	\$57.50
03-78-043	REPLACE NEW REAR BUMPER GUARDS	11338644	01/20/2016 07:00:00	01/20/2016 07:30:00	0.50	\$28.75
03-15-009	REPLACE NEW TIE ROD	11268671	01/20/2016 07:00:00	01/20/2016 08:00:00	1.00	\$57.50
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	01/20/2016 07:00:00	01/20/2016 09:00:00	2.00	\$115.00
66-79-003	PERFORM SAFETY INSPECTION	11338644	12/14/2015 10:49:39	12/14/2015 11:02:55	0.22	\$12.71
66-PM-PMA	PERFORM OIL CHANGE	11338644	12/14/2015 10:25:09	12/14/2015 10:49:36	0.41	\$23.43
03-34-001	REPLACE NEW HEADLAMPS	10260422	12/14/2015 08:44:31	12/14/2015 13:59:06	5.24	\$301.48
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	11213180	01/20/2016 07:00:00	01/20/2016 07:30:00	0.50	\$28.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-33-004	REPLACE NEW SPARK PLUGS	11397026	01/20/2016 07:00:00	01/20/2016 09:42:00	2.70	\$155.25
03-78-043	REPLACE NEW REAR BUMPER GUARDS	11338644	01/20/2016 13:48:42	01/20/2016 14:15:00	0.44	\$25.20
03-78-043	REPLACE NEW REAR BUMPER GUARDS	11338644	01/20/2016 14:30:00	01/20/2016 14:54:06	0.40	\$23.10
					<b>LABOR</b>	<b>828.67</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	8.99	1	\$8.99
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	3.77	7	\$26.39
66-PM-PMA	PERFORM OIL CHANGE	ATM20	FUSE-20 AMP MINI	0.54	1	\$0.54
03-15-009	REPLACE NEW TIE ROD	GATK061000	BELT	26.37	1	\$26.37
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK061000	BELT	26.37	1	\$26.37
03-15-009	REPLACE NEW TIE ROD	GATK061000	BELT	26.37	(1)	(\$26.37)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABATD1066M	FRONT PADS	93.77	1	\$93.77
03-78-043	REPLACE NEW REAR BUMPER GUARDS	SHIPPING	SHIPPING AND HANDLING	11.47	1	\$11.47
03-78-043	REPLACE NEW REAR BUMPER GUARDS	RUBBER DOCK BUMPERS	3X12 RUBBER DOCK BUMPERS	16.98	6	\$101.88
03-15-009	REPLACE NEW TIE ROD	MOGES80755	TIE ROD END	97.19	1	\$97.19
03-33-004	REPLACE NEW SPARK PLUGS	SF16	SEA FOAM 16OZ	7.37	2	\$14.74
03-33-004	REPLACE NEW SPARK PLUGS	7989	SPARK PLUG	12.86	10	\$128.60
					<b>PARTS</b>	<b>513.92</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 22189

## Work Order Notes

(LISAPATE) PM-DO SI-REAR BUMPER GUARDS ARE WORN OUT

## Job Notes

### **03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS**

(LISAPATE) REPLACED REAR BRAKE PADS. TEST DROVE OK

### **03-15-009 - REPLACE NEW TIE ROD**

(LISAPATE) REPLACED RIGHT SIDE TIE ROD

### **03-33-004 - REPLACE NEW SPARK PLUGS**

(LISAPATE) ADDED SEAFOAM DEPT RAN TRUCK WHEN FUELED UP ADDED ANOTHER BOTTLE. BROUGHT BACK TO GARAGE REPLACED PLUGS AND BOOTS

### **03-34-001 - REPLACE NEW HEADLAMPS**

(LISAPATE) REPLACED RIGHT FRONT HEADLAMP

### **03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.**

(LISAPATE) REPLACED BELT

### **03-78-043 - REPLACE NEW REAR BUMPER GUARDS**

(LISAPATE) REMOVED AND INSTALLED NEW BUMPER GUARDS

### **09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(LISAPATE) FRED ROBERTSON COMPLETED ALIGNMENT. PD BY CC

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LISAPATE) TAKEN TO FRED ROBERTSON BY AY

### **66-79-003 - PERFORM SAFETY INSPECTION**

(LISAPATE) SAFETY INSPECTION COMPLETED. SEE ATTACHED

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 8 Cost 3.780000

(LISAPATE) PM BY SH/GM/RS

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 22622

USING DEPT NO:	504302	OPENED DATE:	02/24/2016 11:50:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2016 11:29:20	METER 1 - M:	45752	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/02/2016 11:29:22	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.93	\$53.68	\$133.80	\$0.00	\$187.48
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	0.00	\$0.00	\$32.10	\$0.00	\$32.10
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$3.98	\$0.00	\$21.23
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 5	WORK ORDER TOTAL:	2.98	171.56	186.94	0.00	358.50
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/01/2016 06:00:00	03/01/2016 06:15:00	0.25	\$14.38
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	03/01/2016 07:00:00	03/01/2016 08:30:00	1.50	\$86.25
03-33-003	REPLACE NEW COIL	11397026	03/01/2016 09:34:09	03/01/2016 09:36:10	0.03	\$1.93
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	03/01/2016 06:15:00	03/01/2016 06:33:00	0.30	\$17.25
03-33-003	REPLACE NEW COIL	11397026	03/01/2016 07:00:00	03/01/2016 07:54:00	0.90	\$51.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/29/2016 06:00:00	02/29/2016 06:15:00	(0.25)	(\$14.38)
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/29/2016 06:00:00	02/29/2016 06:15:00	0.25	\$14.38
					LABOR	171.56

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	3.98	1	\$3.98
03-33-003	REPLACE NEW COIL	MOTDG511	COIL ASSY	66.90	2	\$133.80
03-33-004	REPLACE NEW SPARK PLUGS	702460	PLUG BOOTS	3.21	10	\$32.10
					PARTS	186.94



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 22622

## Work Order Notes

(LISAPATE) NEEDS WIPERS-RR BRAKE LIGHT OUT-CHECK ENGINE LIGHT BEEN ON AND OFF-RUNNING ROUGH

## Job Notes

### **03-33-003 - REPLACE NEW COIL**

(LISAPATE) CHECKED OUT REPLACED COILS ON #5 AND #10 CYLINDERS. ALSO REPLACED THE SPARK PLUGS ON THOSE CYLINDERS (WARRANTY DEFECT ON PLUGS)

### **03-33-004 - REPLACE NEW SPARK PLUGS**

(AJONES) PART WAS LEFT OF WO 22189

### **03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LISAPATE) REPLACED RR BRAKE LIGHT

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE)

The following parts are included with the standard job:

Part No : 60-2040

Qty : 2

Description : WIPER BLADE

Manufacturer :

(LISAPATE) REPLACED WIPERS

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT P0305-P0310 CYLINDER MSFIRE #5 AND #10

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 23129

USING DEPT NO:	504302	OPENED DATE:	04/15/2016 09:56:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2016 13:11:54	METER 1 - M:	47463	METER 2 - H: 7927
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/15/2016 13:11:57	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-55-039	REPAIR LIFTGATE ASSY	DON	O	N	GARAGE	2.50	\$143.75	\$435.07	\$0.00	\$578.82

JOB COUNT: 1	WORK ORDER TOTAL:	2.50	143.75	435.07	0.00	578.82
--------------	-------------------	------	--------	--------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-039	REPAIR LIFTGATE ASSY	11213180	04/15/2016 10:10:29	04/15/2016 11:40:29	1.50	\$86.25
24-55-039	REPAIR LIFTGATE ASSY	11213180	04/15/2016 10:10:29	04/15/2016 11:40:29	(1.50)	(\$86.25)
24-55-039	REPAIR LIFTGATE ASSY	11213180	04/15/2016 10:10:29	04/15/2016 12:40:29	2.50	\$143.75
					<b>LABOR</b>	<b>143.75</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-039	REPAIR LIFTGATE ASSY	26580011	FLOW REGULATOR VALVE	60.00	2	\$120.00
24-55-039	REPAIR LIFTGATE ASSY	80001429	SWITCH KIT	114.48	2	\$228.96
24-55-039	REPAIR LIFTGATE ASSY	SHIPPING	SHIPPING AND HANDLING	80.00	1	\$80.00
24-55-039	REPAIR LIFTGATE ASSY	CONNECTOR	CONNECTOR-NYLON	0.56	2	\$1.12
24-55-039	REPAIR LIFTGATE ASSY	BOLT	BOLT	4.99	1	\$4.99
					<b>PARTS</b>	<b>435.07</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **23129**

---

## Work Order Notes

(LISAPATE) REPLACE 2 HOLDING VALVES AND INSTALL AUX CONTROL SWITCH  
(LISAPATE) GAVE GERALD A BOLT FOR TENTS

---

## Job Notes

### **24-55-039 - REPAIR LIFTGATE ASSY**

(LISAPATE) REPLACED HOLDING VALVES IN BOTH CYLINDERS AND FILLED WITH FLUID. INSTALLED SECOND CONTROL SWITCH AND WIRED SWITCH INTO EXISTING HARNESS. VERIFIED OPERATION.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 23551

USING DEPT NO:	504302	OPENED DATE:	05/31/2016 08:30:19	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/06/2016 14:36:32	METER 1 - M:	48059	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2016 14:36:34	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-002	REPLACE NEW RADIATOR	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$947.37	\$947.37
03-42-006	REPLACE NEW THERMOSTATS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	1.39	\$79.88	\$0.00	\$0.00	\$79.88
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$884.35	\$884.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$1.31	\$39.80	\$0.00	\$41.11
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.60	\$34.58	\$7.46	\$0.00	\$42.04
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	DON	O	N	GARAGE	0.00	\$0.00	\$25.96	\$0.00	\$25.96
RT-00	RENTAL COMPLETE VEHICLE	DON	O	N	GARAGE	0.00	\$0.00	\$21.00	\$166.75	\$187.75

JOB COUNT: 8	WORK ORDER TOTAL:	2.01	115.77	94.22	1,998.47	2,208.46
--------------	-------------------	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-42-002	REPLACE NEW RADIATOR	3502120	186866	0034114	\$947.37
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS38349	0034101	\$884.35
RT-00	RENTAL COMPLETE VEHICLE	762070	88092319	0034139	\$166.75
COMML					1998.47

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-42	TRANSPORT COOLING SYSTEM	10337093	07/01/2016 10:28:50	07/01/2016 11:52:11	1.39	\$79.88
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	06/01/2016 07:00:00	06/01/2016 07:36:00	0.60	\$34.50
66-PM-PMA	PERFORM OIL CHANGE	11758845	05/31/2016 15:13:54	05/31/2016 15:15:16	0.02	\$1.31
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	06/03/2016 13:26:22	06/03/2016 13:26:27	0.00	\$0.08
LABOR						115.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	240	\$24.00
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	11.82	1	\$11.82

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3243	FUEL FILTER	7.46	1	\$7.46
RT-00	RENTAL COMPLETE VEHICLE	FUEL	FUEL	21.00	1	\$21.00
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	SIRWC1000	WHEEL CHOCKS	12.68	2	\$25.36
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	LLH13447	NYLON ROPE	0.20	3	\$0.60
<b>PARTS</b>						<b>94.22</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 23551

## Work Order Notes

(LISAPATE) PM-REPLACE FUEL FILTER-REAR DOOR WONT OPEN

## Job Notes

### **03-42-002 - REPLACE NEW RADIATOR**

(LISAPATE) TRUCK BROKE DOWN IN DECATUR. RAN HOT TOOK TO LYNN LAYTON TO BE REPAIRED THEY REPLACED RADIATOR. PD BY CC

### **03-42-006 - REPLACE NEW THERMOSTATS**

(LISAPATE) LYNN LAYTON ALSO REPLACED THERMOSTAT DUE TO RUNNING HOT. PD BY CC

### **16-42 - TRANSPORT COOLING SYSTEM**

(LISAPATE) TRUCK PICKED UP IN DECATUR AND TRANSPORTED BACK TO TUSCALOOSA.

### **24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP**

(LISAPATE) OVERHEAD DOOR CAME TO THE GARAGE REPLACED SPRINGS AND REPAIRED REAR SLIDE UP DOOR ON TRUCK. PD BY CC

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM BY CS-REPLACED AIR FILTER

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LISAPATE) REPLACED FUEL FILTER

### **PU-79-022 - PURCHASED WHEEL CHOCKS/BLOCKS**

(LISAPATE) PURCHASED WHEEL CHOCKS AND ROPE FOR TRUCK. GAVE TO THE DRIVER

### **RT-00 - RENTAL COMPLETE VEHICLE**

(LISAPATE) DEPT HAD TO RENT A UHAUL TO MOVE THEIR LOAD TO AND BRING BACK TO TUSCALOOSA WHEN THEIR TRUCK BROKE DOWN. PD BY CC AUTHORIZED PURCHASING

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 2415

USING DEPT NO:	504302	OPENED DATE:	11/17/2008 11:09:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2008 07:08:59	METER 1 - M:	14272	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/18/2008 07:09:00	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$66.31	\$0.00	\$84.14

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.31</b>	<b>17.83</b>	<b>66.31</b>	<b>0.00</b>	<b>84.14</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/17/2008 12:00:00	11/17/2008 12:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	256	\$30.72
66-PM-PMA	PERFORM OIL CHANGE	WIX49136	AIR FILTER	27.73	1	\$27.73
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
					<b>PARTS</b>	<b>66.31</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 2415

## Work Order Notes

(LPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20 MOTOR OIL Qty 224 Cost 0

Part 1198 OIL PLUG FORD Qty 1 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JE



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25076

<b>USING DEPT NO:</b>	504302	<b>OPENED DATE:</b>	11/23/2016 07:20:42	<b>LOCATION:</b>	GARAGE - University Automotive Services				
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	12/20/2016 13:31:53	<b>METER 1 - M:</b>	50543	<b>METER 2 - H:</b>	7927		
<b>WO VISIT REASON:</b>	PREVENTIVE MAINT	<b>CLOSED DATE:</b>	12/20/2016 13:31:54	<b>IN-SERVICE DATE:</b>	05/30/2005				
<b>TECH SPEC NO:</b>	05TKFORDF550	2005 Ford F550							
			<b>UNIT SERIAL NO:</b>	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-019	REPLACE NEW OXYGEN SENSOR	DON	O	N	GARAGE	0.60	\$34.50	\$33.90	\$0.00	\$68.40
03-05-020	REPLACE NEW PCM/PROCESSOR ASS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$987.00	\$987.00
16-05	TRANSPORT ELECTRONIC ENGINE EE	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$49.56	\$35.54	\$0.00	\$85.10
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 5	WORK ORDER TOTAL:	4.96	285.31	69.44	987.00	1,341.75
--------------	-------------------	------	--------	-------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-05-020	REPLACE NEW PCM/PROCESSOR ASSEMBLY	4910000	537475	0036846	\$987.00
COMML					987.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	12/20/2016 07:00:00	12/20/2016 08:30:00	1.50	\$86.25
16-05	TRANSPORT ELECTRONIC ENGINE EEC SYSTEM	10208562	12/20/2016 07:00:00	12/20/2016 09:00:00	2.00	\$115.00
03-05-019	REPLACE NEW OXYGEN SENSOR	11397026	12/20/2016 08:30:00	12/20/2016 09:06:00	0.60	\$34.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2016 10:56:23	11/23/2016 11:29:30	0.55	\$31.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2016 07:21:41	11/23/2016 07:40:17	0.31	\$17.83
LABOR						285.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.10	240	\$24.00
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	7.56	1	\$7.56
03-05-019	REPLACE NEW OXYGEN SENSOR	DEN2344374	O2 SENSOR	33.90	1	\$33.90
PARTS						69.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25076

## Work Order Notes

(LISAPATE) PM-CHECK ENGINE LIGHT ON

## Job Notes

### **03-05-019 - REPLACE NEW OXYGEN SENSOR**

(LISAPATE) REPLACED BANK 1 SENSOR 1 O2 SENSOR DUE TO RULING OUT O2 SENSOR TO BE BAD

### **03-05-020 - REPLACE NEW PCM/PROCESSOR ASSEMBLY**

(LISAPATE) TOWN AND COUNTRY REPLACED AND PROGRAMMED PCM. RECHECKED OK PD BY CC

### **16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) TAKEN TO FORD BY EK

### **66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(IFALLS) SH PERFORMED PM

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT P0135-HO2SHTR11-HEATER CIRCUIT MALFUNCTION

P0155- H02SHTR21-HEATER CIRCUIT MALFUNCTION

P0443-PURGE VALVE CIRCUIT FAULT

LOOKED AT SCAN DATA AND FOUND FAULT ON THE HEATER CNTROLS(BANK 1 SENSOR 1 02) BANK 2 SENSOR 102) ALSO FOUND FAULT ON THE PURGE VALVE CIRCUIT, WENT THROUGH ALL THE PINPOINT TEST AND OHMED WIRES OUT FOR THE 02 SENSORS TOO. THE PCM CONNECTOR AND OHMED WIRES OUT FROM THE PURGE VALVE TO THE PCM CONNECTOR. ALL THE WIRES CHECKED GOOD AND ALL THE INS LOOKED GOOD IN THE CONNECTOR NEEDS PCM REPLACED.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25407

USING DEPT NO:	504302	OPENED DATE:	01/10/2017 15:08:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2017 13:39:07	METER 1 - M:	51087	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2017 13:39:09	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-65-008	REPLACE NEW HOSES & LINES	DON	O	N	GARAGE	0.50	\$28.75	\$86.06	\$0.00	\$114.81

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	86.06	0.00	114.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-65-008	REPLACE NEW HOSES & LINES	11170580	01/17/2017 07:00:00	01/17/2017 07:30:00	0.50	\$28.75
					LABOR	28.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-65-008	REPLACE NEW HOSES & LINES	PAYMENT FEE	PAYPAL FEE	2.80	1	\$2.80
03-65-008	REPLACE NEW HOSES & LINES	75083133	TUBE	10.99	2	\$21.98
03-65-008	REPLACE NEW HOSES & LINES	75082747	BARBED TEE	1.79	1	\$1.79
03-65-008	REPLACE NEW HOSES & LINES	75082745	BARBED FITTING	2.17	1	\$2.17
03-65-008	REPLACE NEW HOSES & LINES	SHIPPING	SHIPPING AND HANDLING	57.32	1	\$57.32
					PARTS	86.06

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **25407**

---

## Work Order Notes

(LISAPATE) PER DRIVER HYD HOSE IS LEAKING

---

## Job Notes

**03-65-008 - REPLACE NEW HOSES & LINES**

(LISAPATE) FOUND HYD HOSE ON LIFTGATE LEAKING AT THE PLASTIC T FITTINGS. ON FITTING WAS BROKEN. REPLACED HYD LINE AND BOTH PLASTIC T FITTINGS. RECHECKED OK

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25670

USING DEPT NO:	504302	OPENED DATE:	02/06/2017 08:53:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/09/2017 09:58:28	METER 1 - M:	51431	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/09/2017 09:58:29	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.70	\$40.25	\$66.90	\$0.00	\$107.15
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 2	WORK ORDER TOTAL:	2.20	126.50	66.90	0.00	193.40
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11268671	02/08/2017 07:00:00	02/08/2017 08:30:00	1.50	\$86.25
03-33-003	REPLACE NEW COIL	11268671	02/08/2017 08:30:00	02/08/2017 09:12:00	0.70	\$40.25
					LABOR	126.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-33-003	REPLACE NEW COIL	MOTDG511	COIL ASSY	66.90	1	\$66.90
					PARTS	66.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25670

## Work Order Notes

(LISAPATE) ENGINE IS SKIPPING-NO LIGHTS ON-WAS RUNNING FINE FRIDAY

## Job Notes

### **03-33-003 - REPLACE NEW COIL**

(LISAPATE) REPLACED #1 COIL. RECHECKED ALL GOOD

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) CHECKED ENGINE SKIP FOUND #1 COIL ARCING

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25774

USING DEPT NO:	504302	OPENED DATE:	02/15/2017 15:03:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2017 08:09:45	METER 1 - M:	51479	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2017 08:10:04	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-72-004	ADJUST REAR DOOR ASSEMBLY - ROL	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$126.50	\$126.50
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$97.69	\$0.00	\$126.44
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	3.40	\$195.50	\$184.10	\$0.00	\$379.60
03-44-074	REPLACE NEW FUEL INJECTOR ORING	DON	O	N	GARAGE	1.00	\$57.50	\$4.30	\$0.00	\$61.80
06-71-038	INSPECT REAR DOOR ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 6	WORK ORDER TOTAL:	6.90	396.75	286.09	126.50	809.34
--------------	-------------------	------	--------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
01-72-004	ADJUST REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS40481	0037658	\$126.50
	COMML				126.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	03/02/2017 07:00:00	03/02/2017 08:30:00	1.50	\$86.25
06-71-038	INSPECT REAR DOOR ASSY	11213180	03/02/2017 08:30:00	03/02/2017 09:00:00	0.50	\$28.75
03-33-004	REPLACE NEW SPARK PLUGS	11213180	03/02/2017 09:30:00	03/02/2017 12:54:00	3.40	\$195.50
03-32-002	REPLACE NEW BATTERY	11213180	03/02/2017 09:00:00	03/02/2017 09:30:00	0.50	\$28.75
03-44-074	REPLACE NEW FUEL INJECTOR ORINGS	11213180	03/02/2017 08:30:00	03/02/2017 09:30:00	1.00	\$57.50
	LABOR					396.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-074	REPLACE NEW FUEL INJECTOR ORINGS	STISK9	INJECTOR SEAL KIT	4.30	1	\$4.30
03-32-002	REPLACE NEW BATTERY	65X	BATTERY-EXTREME-FORD TOP POT	97.69	1	\$97.69
03-33-004	REPLACE NEW SPARK PLUGS	CSP7989	SPARK PLUGS PLATINUM	13.86	10	\$138.60
03-33-004	REPLACE NEW SPARK PLUGS	STWSPP87E	SPARK PLUG BOOTS	4.23	2	\$8.46
03-33-004	REPLACE NEW SPARK PLUGS	DEN6718164	COIL BOOT	37.04	1	\$37.04
	PARTS					286.09

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 25774

## Work Order Notes

(LISAPATE) TRUCK IS SPITTING AND SPUTTERING-CHECK ENGINE LIGHT IS ON-CABLE ON DRIVER SIDE TO REAR DOOR IS BROKEN

## Job Notes

### **01-72-004 - ADJUST REAR DOOR ASSEMBLY - ROLL-UP**

(LISAPATE) OVERHEAD DOOR CAME TO GARAGE, REPAIRED AND ADJUSTED RER DOOR. RECHEKED OK . PD BY CC

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) REPLACED BATTERY

### **03-33-004 - REPLACE NEW SPARK PLUGS**

(LISAPATE) IF REPLACED #1 COIL. MS REPLACED ALL 10 SPARK PLUGS AND BOOTS.

### **03-44-074 - REPLACE NEW FUEL INJECTOR ORINGS**

(LISAPATE) REPLACED INJECTOR ORINGS

### **06-71-038 - INSPECT REAR DOOR ASSY**

(LISAPATE) CHECKED REAR DOOR IS OUT OF ADJUSTMENT. CALLED FOR OVERHEAD DOOR

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) FOUND 1 COIL AND SPARK PLUGS TO BE DEFECTIVE



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 26283

USING DEPT NO:	504302	OPENED DATE:	05/04/2017 08:30:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2017 11:02:58	METER 1 - M:	52166	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2017 11:03:00	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	0.70	\$40.25	\$69.43	\$0.00	\$109.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.20	\$0.00	\$48.03
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$7.46	\$0.00	\$36.21
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	1.00	\$57.50	\$83.94	\$0.00	\$141.44
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 5	WORK ORDER TOTAL:	4.01	230.58	191.03	0.00	421.61
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-33-003	REPLACE NEW COIL	11170580	05/09/2017 07:18:36	05/09/2017 08:00:36	0.70	\$40.25
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	05/09/2017 08:48:36	05/09/2017 10:18:36	1.50	\$86.25
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11170580	05/09/2017 07:48:36	05/09/2017 08:48:36	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11170580	05/09/2017 07:18:36	05/09/2017 07:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11170580	05/09/2017 07:00:00	05/09/2017 07:18:36	0.31	\$17.83
					LABOR	230.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	240	\$14.40
66-PM-PMT	PERFORM TRANSMISSION SERVICE	VV322	TRANS FLUID VAL MAXLIFE GAL	16.50	2	\$33.00
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	11.82	1	\$11.82
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3243	FUEL FILTER	7.46	1	\$7.46
03-33-003	REPLACE NEW COIL	MOTDG511	COIL ASSY	69.43	1	\$69.43
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7A098AA	TRANSMISSION FILTER KIT	25.11	1	\$25.11
66-PM-PMT	PERFORM TRANSMISSION SERVICE	3C3Z7B155BA	IN-LINE TRANSMISSION FILTER	25.83	1	\$25.83
					PARTS	191.03

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 26283

## Work Order Notes

(LISAPATE) ENGINE LIGHT ON-PM-PMF-PMT

## Job Notes

### **03-33-003 - REPLACE NEW COIL**

(LISAPATE) REPLACED #4 COIL PACK. TEST DROVE RECHECKED OK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM BY AB-REPLACED AIR FILTER

COOLANT -25'

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LISAPATE) REPLACED FUEL FILTER

### **66-PM-PMT - PERFORM TRANSMISSION SERVICE**

(RWINTERS) SERVICED TRANSMISSION REPLACED FILTER AND FLUID. TEST DOVE RECHECKED OK

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT P0354 CYLINER 4 COIL MISFIRE

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 27147

USING DEPT NO:	504302	OPENED DATE:	08/16/2017 15:53:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2017 14:29:01	METER 1 - M:	53518	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2017 14:29:03	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-025	REPLACE NEW FOLDING LIFT ARM SPI	DON	O	N	GARAGE	0.30	\$17.25	\$49.71	\$0.00	\$66.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	49.71	0.00	66.96
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	11758845	08/18/2017 07:00:00	08/18/2017 07:18:00	0.30	\$17.25
					LABOR	17.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	36.33	1	\$36.33
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	36.33	(1)	(\$36.33)
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	36.33	1	\$36.33
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	36.33	(1)	(\$36.33)
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	36.33	1	\$36.33
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	13.38	1	\$13.38
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	13.38	(1)	(\$13.38)
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	13.38	1	\$13.38
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	13.38	(1)	(\$13.38)
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	13.38	1	\$13.38
					PARTS	49.71

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 27147

---

## Work Order Notes

(LISAPATE) REPLACE LR LIFTGATE SPRING

---

## Job Notes

03-55-025 - REPLACE NEW FOLDING LIFT ARM SPRING(S)

(LISAPATE) REMOVED BROKEN SPRING AND INSTALLED NEW SPRING

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 27498

USING DEPT NO:	504302	OPENED DATE:	09/18/2017 11:17:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2017 09:56:28	METER 1 - M:	53980	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2017 09:56:29	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-65-021	REPAIR HYDRAULIC VALVE (RELIEF)	DON	O	N	GARAGE	1.00	\$57.50	\$2.11	\$0.00	\$59.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$37.52	\$23.17	\$0.00	\$60.69
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.22	\$12.86	\$7.46	\$0.00	\$20.32

JOB COUNT: 3	WORK ORDER TOTAL:	1.88	107.88	32.74	0.00	140.62
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-65-021	REPAIR HYDRAULIC VALVE (RELIEF)	11213180	09/19/2017 07:00:00	09/19/2017 08:00:00	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	09/19/2017 08:14:58	09/19/2017 08:28:23	0.22	\$12.86
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/19/2017 07:35:45	09/19/2017 08:14:54	0.65	\$37.52
					LABOR	107.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.06	240	\$14.40
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	4.79	1	\$4.79
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3243	FUEL FILTER	7.46	1	\$7.46
24-65-021	REPAIR HYDRAULIC VALVE (RELIEF)	C111	RED BRAKE CLEANER	2.11	1	\$2.11
					PARTS	32.74

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 27498

## Work Order Notes

(LISAPATE) PM-PMF

## Job Notes

### **24-65-021 - REPAIR HYDRAULIC VALVE (RELIEF)**

(LISAPATE) REMOVED RELIEF VALVE AND CLEANED. REINSTALLED AND RECHECKED OK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM BY SH

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LISAPATE) REPLACED FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 28173

USING DEPT NO:	504302	OPENED DATE:	11/16/2017 07:54:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2017 13:12:19	METER 1 - M:	54961	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2017 13:12:21	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-78-043	REPLACE NEW REAR BUMPER GUARD	DON	O	N	GARAGE	0.25	\$14.38	\$47.38	\$0.00	\$61.76
24-71	REPAIR BODY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$143.75	\$143.75
PU-53-996	PURCHASED MISC TOOLS	DON	O	N	GARAGE	0.00	\$0.00	\$9.30	\$0.00	\$9.30

JOB COUNT: 4	WORK ORDER TOTAL:	1.25	71.88	56.68	143.75	272.31
--------------	-------------------	------	-------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS41892	0041077	\$143.75
				COMML	143.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-71	REPAIR BODY	11074414	11/16/2017 08:19:28	11/16/2017 09:19:28	1.00	\$57.50
03-78-043	REPLACE NEW REAR BUMPER GUARDS	11170580	11/16/2017 08:18:07	11/16/2017 08:33:07	0.25	\$14.38
					LABOR	71.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-78-043	REPLACE NEW REAR BUMPER GUARDS	3X12BUMPERS	3X12 BUMPERS	15.40	2	\$30.80
PU-53-996	PURCHASED MISC TOOLS	21408	HEX NUT	0.27	2	\$0.54
PU-53-996	PURCHASED MISC TOOLS	104080700	BOLT	3.62	2	\$7.24
PU-53-996	PURCHASED MISC TOOLS	062138	WASHERS	0.76	2	\$1.52
03-78-043	REPLACE NEW REAR BUMPER GUARDS	SHIPPING	SHIPPING AND HANDLING	16.58	1	\$16.58
					PARTS	56.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 28173

## Work Order Notes

(LISAPATE) PURCHASE NEW BUMPER GUARDS-REPAIR HOLES IN BED OF TRUCK-REPAIR ROLL UP DOOR

## Job Notes

### **03-78-043 - REPLACE NEW REAR BUMPER GUARDS**

(LISAPATE) INSTALLED NEW REAR BUMPER GUARDS

### **24-71 - REPAIR BODY**

(LISAPATE) REPAIRED 3 HOLES IN THE BOX OF THE TRUCK

### **24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP**

(LISAPATE) OVER HEAD DOOR CAME TO THE GARAGE AND REPAIRED THE ROLL UP DOOR. PD BY CC

### **PU-53-996 - PURCHASED MISC TOOLS**

(LISAPATE) PURCHASED NUTS, BOLTS AND WASHERS FOR TENT SET UP GAVE TO THE MOVERS



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 28943

USING DEPT NO:	504302	OPENED DATE:	02/21/2018 08:16:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2018 14:57:19	METER 1 - M:	56025	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2018 14:57:21	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$3.98	\$0.00	\$21.23
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44

JOB COUNT: 2	WORK ORDER TOTAL:	0.55	31.63	21.04	0.00	52.67
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11758845	02/21/2018 08:21:43	02/21/2018 08:36:43	0.25	\$14.38
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11758845	02/21/2018 08:21:33	02/21/2018 08:39:33	0.30	\$17.25
					LABOR	31.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	3.98	1	\$3.98
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	2	\$17.06
					PARTS	21.04

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 28943

## Work Order Notes

(LISAPATE) RR TAILLIGHT OUT  
WIPERS NEED REPLACED

## Job Notes

**03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LISAPATE) REPLACED RIGHT REAR TAILLIGHT

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE)

The following parts are included with the standard job:

Part No : 60-2040

Qty : 2

Description : WIPER BLADE

Manufacturer :

(LISAPATE) REPLACED BOTH FRONT WIPER BLADES

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29138

USING DEPT NO:	504302	OPENED DATE:	03/20/2018 14:27:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/30/2018 07:18:12	METER 1 - M:	56325	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/30/2018 07:18:13	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-054	REPLACE NEW WASHER PUMP	DON	O	N	GARAGE	0.50	\$28.75	\$17.51	\$0.00	\$46.26
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIF	DON	O	N	GARAGE	0.30	\$17.25	\$12.73	\$0.00	\$29.98
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$19.98	\$0.00	\$37.81
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.75	\$12.09	\$0.00	\$40.84

JOB COUNT: 5	WORK ORDER TOTAL:	2.11	121.33	62.31	0.00	183.64
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11758845	03/23/2018 07:18:00	03/23/2018 07:48:00	0.50	\$28.75
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	03/23/2018 07:36:36	03/23/2018 08:06:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11758845	03/23/2018 07:18:00	03/23/2018 07:36:36	0.31	\$17.83
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	11758845	03/23/2018 07:00:00	03/23/2018 07:18:00	0.30	\$17.25
03-51-054	REPLACE NEW WASHER PUMP	11758845	03/23/2018 08:06:36	03/23/2018 08:36:36	0.50	\$28.75
					LABOR	121.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	SLM30010	INNER TUBE 4.10/3.50-4	12.73	1	\$12.73
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	12.09	1	\$12.09
03-51-054	REPLACE NEW WASHER PUMP	ACI173686	WASHER PUMP	17.51	1	\$17.51
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.00	8	\$16.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	12.09	(1)	(\$12.09)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33243	FUEL FILTER	12.09	1	\$12.09
					PARTS	62.31

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29138

## Work Order Notes

(LISAPATE) NAIL IN DOLLY TIRE

(LISAPATE) PM-PMF-CHECK TIRES-ADD MORE RAILS IN REAR OF THE BOX TRUCK

## Job Notes

### **03-51-054 - REPLACE NEW WASHER PUMP**

(LISAPATE) REPLACED WASHER PUMP AND RECHECKED OK

### **24-17-019 - REPAIR DOLLY/GOLF CART/UTILITY TIRES**

(LISAPATE) INSTALLED NEW TUBE AND AIRED UP TIRE ON DOLLY

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE) ROTATED TIRES

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM BY SH/CS/IF

COOLANT -35'

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LISAPATE) REPLACED FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29736

USING DEPT NO:	504302	OPENED DATE:	05/08/2018 15:49:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/14/2018 09:26:58	METER 1 - M:	56952	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/14/2018 09:26:59	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11901357	05/09/2018 07:00:00	05/09/2018 07:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29736

## Work Order Notes

(LISAPATE) INSTALL GPS SYSTEM

## Job Notes

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) INSTALLED GPS SYSTEM

SERIAL# 5015914533

(IFALLS) USED HARNESS 109

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29982

USING DEPT NO:	504302	OPENED DATE:	06/07/2018 14:51:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/18/2018 07:14:54	METER 1 - M:	57421	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/18/2018 07:14:55	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-40-405	REPLACE NEW VALVE COVERS/GASKE	DON	O	N	GARAGE	3.00	\$172.50	\$76.80	\$0.00	\$249.30
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00

JOB COUNT: 2	WORK ORDER TOTAL:	5.00	287.50	76.80	0.00	364.30
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	06/15/2018 07:00:00	06/15/2018 09:00:00	2.00	\$115.00
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	11213180	06/15/2018 09:00:00	06/15/2018 12:00:00	3.00	\$172.50
					<b>LABOR</b>	<b>287.50</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	VS50656R	VALVE COVER GASKET SET	72.58	1	\$72.58
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	OTC5607	ADAPTER	33.86	1	\$33.86
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	C111	RED BRAKE CLEANER	2.11	2	\$4.22
03-40-405	REPLACE NEW VALVE COVERS/GASKETS	OTC5607	ADAPTER	33.86	(1)	(\$33.86)
					<b>PARTS</b>	<b>76.80</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 29982

## Work Order Notes

(RTUNAITI) Sputtering, accelerating in reverse

## Job Notes

### **03-40-405 - REPLACE NEW VALVE COVERS/GASKETS**

(RTUNAITI) Removed passenger side valve cover and inspected valves/springs. All looked ok

Performed compression test; compression good on all cylinders 185psi within 5%

Noticed number 4 spark plug to be loose during test. Installed new valve cover gasket and torqued all plugs to spec. Test drove all ok.

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(RTUNAITI) No codes stored



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 30129

USING DEPT NO:	504302	OPENED DATE:	06/28/2018 09:06:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2018 13:11:08	METER 1 - M:	57421	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2018 13:11:09	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$159.92	\$0.00	\$159.92

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	159.92	0.00	159.92
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8PG	8' HORIZONTAL E-TRACK	19.99	8	\$159.92
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8PG	8' HORIZONTAL E-TRACK	19.99	(8)	(\$159.92)
PU-55-012	PURCHASED CARGO RESTRAINTS	HET8PG	8' HORIZONTAL E-TRACK	19.99	8	\$159.92
					<b>PARTS</b>	<b>159.92</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 30129

## Work Order Notes

(RTUNAITI) Purchase cargo track rails for moving truck

## Job Notes

### **PU-55-012 - PURCHASED CARGO RESTRAINTS**

(RTUNAITI) Purchased rails from US Cargo. Customer picked up rails and will have Building Maintenance install.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 3043

USING DEPT NO:	504302	OPENED DATE:	03/09/2009 10:36:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2009 14:31:36	METER 1 - M:	15502	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	03/25/2009 14:31:40	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
03-32-010	REPLACE NEW STARTER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$662.71	\$662.71
16-32	TRANSPORT CRANKING SYSTEM	DON	O	N	GARAGE	0.00	\$0.21	\$0.00	\$0.00	\$0.21
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$43.73	\$0.00	\$43.73

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.21	43.73	662.71	706.65
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-32-010	REPLACE NEW STARTER	11078175	292312	0003940	\$662.71
				COMML	662.71

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-32	TRANSPORT CRANKING SYSTEM	11088474	03/13/2009 07:19:01	03/13/2009 07:19:14	0.00	\$0.21
					LABOR	0.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	256	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	1198	OIL DRAIN PLUG FORD	8.99	1	\$8.99
					PARTS	43.73

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 3043

## Work Order Notes

(LPATE) STARTER STICKS AT TIMES WILL NOT START--BLOWER ONLY WORKS ON HIGH HAS BEEN FIXED UNDER WARRANTY TWICE BEFORE JAN AND APR 08--TOWNSEND FORD TO REPLACE STARTER AT 50% COST WE WILL PAY 50%--PICKED UP TRUCK STARTED BACK TO SHOP WOULD NOT IDLE TOOK BACK TO FORD---PM  
FORD COMBINED ALL CHARGES PER PATRICK USE SAME PO FOR ENTIRE WORK ORDER

## Job Notes

### **03-01-004 - REPLACE NEW BLOWER MOTOR**

(LPATE) FORD COMPLETED A/C DIAG FOUND RESISTOR UNPLUGGED..RECHECKED AFTER FIXING OK P0020250

### **03-32-010 - REPLACE NEW STARTER**

(LPATE) TOWNSEND FOR REPLACED STARTER AND ONLY CHARGED US 107.09 DED THEY PAID REMAINING CHARGES P0020250

### **16-32 - TRANSPORT CRANKING SYSTEM**

(LPATE) TAKEN TO FORD BY JE

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE) The following parts are included with the standard job:

Part No : 1198  
Qty : 1  
Description : OIL PLUG FORD  
Manufacturer :

Part No : 51372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : MOTOR OIL  
Manufacturer :

(LPATE) PM BY JE

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 30437

USING DEPT NO:	504302	OPENED DATE:	07/31/2018 13:28:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/03/2018 14:52:11	METER 1 - M:	58117	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2018 14:52:13	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-040	REPLACE NEW THROTTLE BODY ASSY	DON	O	N	GARAGE	0.80	\$0.00	\$247.28	\$0.00	\$247.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$26.30	\$0.00	\$26.30
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.60	\$0.00	\$7.46	\$0.00	\$7.46
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	3.71	0.00	281.04	0.00	281.04
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	08/02/2018 07:00:00	08/02/2018 09:00:00	2.00	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	08/02/2018 06:18:36	08/02/2018 06:48:36	(0.50)	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	08/02/2018 06:18:36	08/02/2018 06:48:36	0.50	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	08/02/2018 06:18:36	08/02/2018 06:54:36	0.60	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/02/2018 06:00:00	08/02/2018 06:18:36	0.31	\$0.00
03-44-040	REPLACE NEW THROTTLE BODY ASSY	11213180	08/02/2018 07:00:00	08/02/2018 07:48:00	0.80	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-040	REPLACE NEW THROTTLE BODY ASSY	TECS20021	THROTTLE BODY ASSY	247.28	1	\$247.28
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3243	FUEL FILTER	7.46	1	\$7.46
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.79	8	\$22.32
					PARTS	281.04

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 30437

## Work Order Notes

(LISAPATE) PM-PMF-CHECK ENGINE LIGHT ON- WRENCH LIGHT WAS ON ENT OFF- IDLING AND RUNNING OK AT THIS TIME-DOES SURGE AT TIMES WHEN IDLING

## Job Notes

### **03-44-040 - REPLACE NEW THROTTLE BODY ASSY**

(LISAPATE) FOUND THROTTLE ACTUATOR TO HAVE INTERNAL FAULT  
REPALCED THROTTLE BODY ASSY  
TEST DROVE RECHECKED OK

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM BY AG,RC,EK,SH

COOLANT -35'

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LISAPATE) REPLACED FUEL FILTER

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) SCAN OUT VCI FORD P15E THROTTLE RET CONTROL TB FLU TURN AT MAX LIMIT  
P2106 TAC-FOUND LIMITED PACK  
P2135 TP SENSOR A&B RATIONALITY- PLAUSIBILITY ERROR

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 31331

USING DEPT NO:	504302	OPENED DATE:	10/29/2018 15:29:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2018 07:26:13	METER 1 - M:	59255	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2018 07:26:15	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11915538	10/30/2018 07:00:00	10/30/2018 08:00:00	1.00	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 31331

## Work Order Notes

(RTUNAITI) Won't start

## Job Notes

### 66-79-002 - PERFORM SERVICE CALL

(RTUNAITI) Left lights On - Jumped Off

After we jumped it off they said they would leave it running to charge battery and come by shop if any more problems



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 31431

USING DEPT NO:	504302	OPENED DATE:	11/08/2018 14:36:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2018 09:30:03	METER 1 - M:	59274	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2018 09:30:05	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-025	REPLACE NEW FOLDING LIFT ARM SPI	DON	O	N	GARAGE	0.82	\$0.00	\$268.38	\$0.00	\$268.38
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.82	0.00	268.38	0.00	268.38
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11915538	12/06/2018 07:00:00	12/06/2018 08:00:00	1.00	\$0.00
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	11074414	11/19/2018 09:15:00	11/19/2018 09:26:43	0.20	\$0.00
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	11074414	11/19/2018 08:22:38	11/19/2018 09:00:00	0.62	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SPRING PIN	WALTCO SPRING PIN ASSY	45.55	2	\$91.10
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	21514301	SPRING OUTER PLATFORM GREEN	44.88	(1)	(\$44.88)
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	75085162	LOCK NUT NYLON 1/2-13	0.53	2	\$1.06
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	26418001	TUBE .750DX.083WX1.0L SS	3.78	2	\$7.56
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	750001042	HEX BOLT 1/2-13X3 GR8	2.58	2	\$5.16
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	75089542	SPIRAL-COILED PIN .500X2.00	2.51	2	\$5.02
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	75085015	HEX NUT	0.73	2	\$1.46
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	750001030	HEX BOLT	4.95	2	\$9.90
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	21514301	SPRING OUTER PLATFORM GREEN	44.88	1	\$44.88
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	22114300	LIFTGATE SPRING DECK RED TIP	39.78	1	\$39.78
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	107.34	1	\$107.34
					PARTS	268.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 31431

## Work Order Notes

(LISAPATE) Replace leveling springs on bed

## Job Notes

### **03-55-025 - REPLACE NEW FOLDING LIFT ARM SPRING(S)**

(IFALLS) Installed a new assist spring on left side of lift gate. Installed a new spring retainer bolt and torque to 110 ft lbs. Installed 2 new platform retainer bolts and adjusted. Missing right side will install when it gets here. Installed Right side assist spring and rod also rod on the left side. Retorque retainer bolts to 110 ft lbs operated lift. Rechecked good

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) RC completed service call jumped truck off at Ferguson Center

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 3180

USING DEPT NO:	504302	OPENED DATE:	04/06/2009 08:37:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2009 15:12:17	METER 1 - M:	15662	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/07/2009 15:12:17	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	0.00	0.00	17.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11268671	04/06/2009 09:00:00	04/06/2009 09:18:00	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **3180**

---

## Work Order Notes

(LPATE) REQUESTED SVC CALL DEAD BATTERY

---

## Job Notes

**66-79-002 - PERFORM SERVICE CALL**

(LPATE) IKE WENT TO ASB BLDG AND JUMPED OFF..ARTHUR BROUGHT TO SHOP AND LISA TIGHTENED NEGATIVE BATTERY CABLE

---

# Work Order Charge Detail

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 32002

<b>USING DEPT NO:</b>	504302	<b>OPENED DATE:</b>	01/23/2019 09:29:41	<b>LOCATION:</b>	GARAGE - University Automotive Services				
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	03/18/2019 09:39:15	<b>METER 1 - M:</b>	60775	<b>METER 2 - H:</b>	7927		
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	03/18/2019 09:39:18	<b>IN-SERVICE DATE:</b>	05/30/2005				
<b>TECH SPEC NO:</b>	05TKFORDF550	2005 Ford F550		<b>UNIT SERIAL NO:</b>	1FDAF56Y65ED25884				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-005	REPLACE NEW COMPRESSOR	DON	O	N	GARAGE	3.60	\$0.00	\$170.00	\$0.00	\$170.00
03-01-006	REPLACE NEW CONDENSER	DON	O	N	GARAGE	0.70	\$0.00	\$89.39	\$0.00	\$89.39
03-01-010	REPLACE NEW EVAPORATOR	DON	O	N	GARAGE	1.70	\$0.00	\$76.77	\$0.00	\$76.77
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILT	DON	O	N	GARAGE	0.50	\$0.00	\$1.25	\$0.00	\$1.25
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	DON	O	N	GARAGE	0.50	\$0.00	\$26.64	\$0.00	\$26.64
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	DON	O	N	GARAGE	3.40	\$0.00	\$8.12	\$0.00	\$8.12
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.26	\$0.00	\$98.33	\$0.00	\$98.33
03-32-010	REPLACE NEW STARTER	DON	O	N	GARAGE	0.00	\$0.00	\$100.68	\$0.00	\$100.68
19-54-003	WIRE/REWIRE WARNING BUZZER	DON	O	N	GARAGE	1.00	\$0.00	\$21.91	\$0.00	\$21.91
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.16	\$0.00	\$0.00	\$0.00	\$0.00
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.00	\$0.00	\$13.15	\$0.00	\$13.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.19	\$0.00	\$27.98	\$0.00	\$27.98

JOB COUNT: 13	WORK ORDER TOTAL:	15.50	0.00	634.22	0.00	634.22
---------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-32	DIAGNOSE CRANKING SYSTEM	11074414	03/06/2019 06:00:00	03/06/2019 06:30:00	0.50	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	03/06/2019 07:00:00	03/06/2019 08:00:00	1.00	\$0.00
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	11310047	03/06/2019 07:00:00	03/06/2019 09:00:00	2.00	\$0.00
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	11310047	03/06/2019 07:00:00	03/06/2019 07:30:00	0.50	\$0.00
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	11310047	03/06/2019 07:00:00	03/06/2019 07:30:00	0.50	\$0.00
03-01-006	REPLACE NEW CONDENSER	11310047	03/06/2019 07:00:00	03/06/2019 07:42:00	0.70	\$0.00
03-01-005	REPLACE NEW COMPRESSOR	11310047	03/06/2019 07:00:00	03/06/2019 10:36:00	3.60	\$0.00
19-54-003	WIRE/REWIRE WARNING BUZZER	11310047	03/06/2019 07:00:00	03/06/2019 08:00:00	1.00	\$0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-01-010	REPLACE NEW EVAPORATOR	11310047	03/06/2019 07:00:00	03/06/2019 08:42:00	1.70	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	02/26/2019 14:30:00	02/26/2019 15:30:00	1.00	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	02/26/2019 14:05:37	02/26/2019 14:15:00	0.16	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	02/26/2019 14:30:00	02/27/2019 07:01:30	(16.53)	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	02/26/2019 14:30:00	02/27/2019 07:01:30	16.53	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/25/2019 09:30:00	02/25/2019 10:18:55	0.82	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/25/2019 08:52:28	02/25/2019 09:15:00	0.38	\$0.00
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	11310047	02/11/2019 09:56:50	02/11/2019 09:56:55	0.00	\$0.00
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	11310047	01/24/2019 10:31:22	01/24/2019 11:55:01	1.39	\$0.00
03-32-002	REPLACE NEW BATTERY	11074414	01/23/2019 10:12:53	01/23/2019 10:28:25	0.26	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-01-010	REPLACE NEW EVAPORATOR	288330	A/C EVAPORATOR CORE	66.10	1	\$66.10
03-01-006	REPLACE NEW CONDENSER	1K100100	A/C CONDENSER	89.39	1	\$89.39
03-01-005	REPLACE NEW COMPRESSOR	FJC2468	A/C PAG OIL	6.35	1	\$6.35
19-54-003	WIRE/REWIRE WARNING BUZZER	XL3Z11A128AA	REPAIR HARNESS IGNITION CHIME	21.91	1	\$21.91
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	F57Z7212A	SHIFT TUBE	41.64	(1)	(\$41.64)
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	F57Z7212A	SHIFT TUBE	41.64	1	\$41.64
03-01-056	REPLACE NEW A/C ORFICE VALVE/FILTER	207317	ORFICE TUBE	1.25	1	\$1.25
03-01-063	REPLACE NEW ACCUMULATOR/DRIER	408904	ACCUMULATOR/DRIER	26.64	1	\$26.64
03-01-005	REPLACE NEW COMPRESSOR	274501	A/C COMPRESSOR	134.63	1	\$134.63
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.30	1	\$0.30
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.22	1	\$0.22
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	2	\$0.18
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	F3TZ7L278A	BUSHING	4.06	2	\$8.12
03-32-010	REPLACE NEW STARTER	WPS6646N	STARTER	100.68	1	\$100.68
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	8	\$24.00
03-01-005	REPLACE NEW COMPRESSOR	A/C FLUSH	A/C FLUSH DURA II 32OZ	26.91	1	\$26.91
03-01-005	REPLACE NEW COMPRESSOR	C111	RED BRAKE CLEANER	2.11	1	\$2.11
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134ALB	FREON-POUND	3.64	2	\$7.28

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.20	13	\$2.60
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.03	3	\$3.09
03-01-010	REPLACE NEW EVAPORATOR	801844	A/C SYSTEM SEAL KIT	10.67	1	\$10.67
					<b>PARTS</b>	<b>634.22</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **32002**

---

## Work Order Notes

(LISAPATE) Check battery had to jump off battery was dead-PM-PMF-A/C is not working

---

## Job Notes



# Work Order Charge Detail

## 03-01-005 - REPLACE NEW COMPRESSOR

(EKIMBREL) EH replaced compressor.

## 03-01-006 - REPLACE NEW CONDENSER

(EKIMBREL) EH replaced condenser

## 03-01-010 - REPLACE NEW EVAPORATOR

(EKIMBREL) EH replaced evaporator

## 03-01-056 - REPLACE NEW A/C ORFICE VALVE/FILTER

(EKIMBREL) EH replaced orifice

## 03-01-063 - REPLACE NEW ACCUMULATOR/DRIER

(EKIMBREL) EH replaced accumulator.

## 03-15-025 - REPLACE NEW SHIFT TUBE/BUSHINGS

(EKIMBREL) Replaced plastic bushings due to excessive slack in gear shifter. EH

## 03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery checked bad, installed a new battery. Alt is charging at 14.1 volts  
cleaned battery cables

## 03-32-010 - REPLACE NEW STARTER

(EKIMBREL) Replaced starter motor. The vehicle is now starting properly. EH, AB, IF

## 19-54-003 - WIRE/REWIRE WARNING BUZZER

(EKIMBREL) Door chime not operating properly. Replaced ignition door chime wire. EH/IF

## 35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(EKIMBREL) AC sniffer tool alerted near evaporator core. Also found metal and what appeared to be compressor teflon seal remains on orifice screen.

## 35-32 - DIAGNOSE CRANKING SYSTEM

(EKIMBREL) Starter motor faulty.

## 66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EKIMBREL) EH flushed ac lines using ac flush. Added oil and charged to 2.81 lbs. AC is now blowing cold. Leak test passed after vacuum was pulled.

## 66-79-002 - PERFORM SERVICE CALL

## 66-PM-PMA - PERFORM OIL CHANGE

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(EKIMBREL) Top: RC, Bot: AG

Coolant -35

Greased front end and liftgate

**66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 32417

USING DEPT NO:	504302	OPENED DATE:	03/20/2019 15:47:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/21/2019 13:27:35	METER 1 - M:	60889	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/21/2019 13:27:36	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-004	REPLACE NEW CLEARANCE/MARKER	DON	O	N	GARAGE	0.60	\$0.00	\$0.30	\$0.00	\$0.30

JOB COUNT: 1	WORK ORDER TOTAL:	0.60	0.00	0.30	0.00	0.30
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-004	REPLACE NEW CLEARANCE/MARKER	11915538	03/21/2019 07:00:00	03/21/2019 07:36:00	0.60	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-004	REPLACE NEW CLEARANCE/MARKER	194	BULB-TAG/MARKER	0.15	2	\$0.30
					PARTS	0.30

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 32417

## Work Order Notes

(LISAPATE) Top marker light out

## Job Notes

03-34-004 - REPLACE NEW CLEARANCE/MARKER

(LISAPATE) Replaced 2 top marker lights

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 32784

USING DEPT NO:	504302	OPENED DATE:	05/01/2019 10:37:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2019 14:58:54	METER 1 - M:	61831	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/23/2019 14:58:57	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-051	REPLACE NEW HEATER HOSES	DON	O	N	GARAGE	1.00	\$0.00	\$174.13	\$0.00	\$174.13
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.00	\$0.00	\$79.17	\$0.00	\$79.17
03-55-039	REPLACE NEW LIFTGATE ASSY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-55	TRANSPORT CARGO HNDLNG,RESTRN	DON	O	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00
19-55-028	WIRE/REWIRE MASTER CONTROL SWI	DON	O	N	GARAGE	2.50	\$0.00	\$41.69	\$0.00	\$41.69
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.50	\$0.00	\$944.52	\$0.00	\$944.52
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	1.00	\$0.00	\$1.08	\$0.00	\$1.08

JOB COUNT: 7	WORK ORDER TOTAL:	7.33	0.00	1,240.59	0.00	1,240.59
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-55-039	REPLACE NEW LIFTGATE ASSY	11153069	51256	0048174	\$0.00
				COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11170580	05/22/2019 07:00:00	05/22/2019 08:00:00	1.00	\$0.00
19-55-028	WIRE/REWIRE MASTER CONTROL SWITCH	11213180	05/22/2019 09:00:00	05/22/2019 11:30:00	2.50	\$0.00
03-01-051	REPLACE NEW HEATER HOSES	11170580	05/22/2019 08:00:00	05/22/2019 09:00:00	1.00	\$0.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	05/22/2019 07:00:00	05/22/2019 09:00:00	(2.00)	\$0.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	05/22/2019 07:00:00	05/22/2019 09:00:00	2.00	\$0.00
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	11915538	05/13/2019 11:35:02	05/13/2019 11:55:03	0.33	\$0.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	05/22/2019 07:00:00	05/22/2019 08:00:00	1.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	05/22/2019 06:00:00	05/22/2019 07:30:00	1.50	\$0.00
					<b>LABOR</b>	<b>0.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	009121	TIRE 225/70R19.5 BRDG R238 LRG	311.56	3	\$934.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1066TRH	BRAKE PADS	79.17	1	\$79.17
19-55-028	WIRE/REWIRE MASTER CONTROL SWITCH	ST80	SOLENOID 12V CONTINUOUS DUTY	32.40	1	\$32.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	LT1	19.5 WHEEL WEIGHT	0.74	9	\$6.66
66-79-002	PERFORM SERVICE CALL	10 CLAMP	CLAMP 9/16-1 1/16	0.36	2	\$0.72
03-01-051	REPLACE NEW HEATER HOSES	10 CLAMP	CLAMP 9/16-1 1/16	0.36	1	\$0.36
03-01-051	REPLACE NEW HEATER HOSES	ANTIFREEZE GOLD	ANTIFREEZE-FORD	16.95	1	\$16.95
66-79-002	PERFORM SERVICE CALL	10 CLAMP	CLAMP 9/16-1 1/16	0.36	(2)	(\$0.72)
66-79-002	PERFORM SERVICE CALL	10 CLAMP	CLAMP 9/16-1 1/16	0.36	3	\$1.08
03-01-051	REPLACE NEW HEATER HOSES	10 CLAMP	CLAMP 9/16-1 1/16	0.36	(1)	(\$0.36)
03-01-051	REPLACE NEW HEATER HOSES	SHIPPING	SHIPPING AND HANDLING	10.00	1	\$10.00
03-01-051	REPLACE NEW HEATER HOSES	5C3Z18472CA	HEATER HOSE ASSY, INLET	90.25	1	\$90.25
03-01-051	REPLACE NEW HEATER HOSES	5C3Z18472BB	HEATER HOSE ASSY, OUTLET	56.93	1	\$56.93
19-55-028	WIRE/REWIRE MASTER CONTROL SWITCH	784333	RING TERM, 14-16GA NO10 20 PCS	2.54	1	\$2.54
19-55-028	WIRE/REWIRE MASTER CONTROL SWITCH	DKB05462	LUG, COPPER 2 GA 5/16IN	0.92	5	\$4.60
19-55-028	WIRE/REWIRE MASTER CONTROL SWITCH	PIC1804KT	RING TERM NO8 16-14 GA 20PC	2.15	1	\$2.15
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.06	3	\$3.18
					<b>PARTS</b>	<b>1240.59</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 32784

## Work Order Notes

(LISAPATE) Movers transported truck to Troy to have new lift gate assy installed.

(LISAPATE) Service call after truck was back in town running hot

## Job Notes

### **03-01-051 - REPLACE NEW HEATER HOSES**

(LISAPATE) Installed both new heater hoses. Used 1 gallon of coolant. Rechecked ok

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(LISAPATE) Replaced front brake pads

### **03-55-039 - REPLACE NEW LIFTGATE ASSY**

(LISAPATE) Lyncoach removed and installed new liftgate assy. Pd for by dept not by Automotive Services

### **16-55 - TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS**

(LISAPATE) Taken to Lyncoach by EK/RC

### **19-55-028 - WIRE/REWIRE MASTER CONTROL SWITCH**

(LISAPATE) Wired lift gate to solenoid for control with aux switches in truck

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) SH/MS Mount and balanced 3 new tires. Did not replace LF tire

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) AB Performed service call. Found heater hose is broken

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 33262

USING DEPT NO:	504302	OPENED DATE:	06/27/2019 10:19:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2019 14:37:47	METER 1 - M:	62443	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2019 14:37:48	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-31-001	REPLACE NEW ALTERNATOR	DON	B	N	GARAGE	0.10	\$0.00	\$135.57	\$0.00	\$135.57
06-31-001	INSPECT ALTERNATOR	DON	B	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.01	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.61	0.00	135.57	0.00	135.57
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-31-001	INSPECT ALTERNATOR	11170580	06/28/2019 07:00:00	06/28/2019 07:30:00	0.50	\$0.00
03-31-001	REPLACE NEW ALTERNATOR	11170580	06/28/2019 07:30:00	06/28/2019 07:36:00	0.10	\$0.00
66-79-002	PERFORM SERVICE CALL	10208562	06/28/2019 07:00:00	06/28/2019 08:00:00	1.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	06/27/2019 13:03:55	06/27/2019 13:33:55	(0.50)	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	06/27/2019 13:03:55	06/27/2019 13:33:55	0.50	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	06/27/2019 13:03:55	06/27/2019 14:26:28	(1.38)	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	06/27/2019 13:03:55	06/27/2019 14:26:28	1.38	\$0.00
66-79-002	PERFORM SERVICE CALL	11915538	06/27/2019 13:03:55	06/27/2019 13:04:31	0.01	\$0.00
					<b>LABOR</b>	<b>0.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	97.81	(1)	(\$97.81)
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	97.81	2	\$195.62
03-31-001	REPLACE NEW ALTERNATOR	1N3200	ALTERNATOR	135.57	1	\$135.57
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	97.81	(2)	(\$195.62)
					<b>PARTS</b>	<b>135.57</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 33262

## Work Order Notes

(EKIMBREL) service call; inspect alternator

## Job Notes

### **03-31-001 - REPLACE NEW ALTERNATOR**

(EKIMBREL) AB installed new alternator. Charging at 14.4 V, rechecked ok.

### **06-31-001 - INSPECT ALTERNATOR**

(EKIMBREL) AB found alternator not charging.

### **66-79-002 - PERFORM SERVICE CALL**

(EKIMBREL) EK performed service call. Tried to jump vehicle off but wouldn't stay cranked. replaced battery and customer drove truck back to shop.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 33999

USING DEPT NO:	504302	OPENED DATE:	09/06/2019 15:24:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2019 14:11:07	METER 1 - M:	63555	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2019 14:11:08	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-009	REPLACE NEW TIE ROD	DON	O	N	GARAGE	1.78	\$0.00	\$483.13	\$0.00	\$483.13
03-15-029	REPLACE NEW STEERING STABILIZER	DON	O	N	GARAGE	1.00	\$0.00	\$39.38	\$0.00	\$39.38
09-15	ALIGN STEERING	DON	O	N	GARAGE	2.39	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$0.00	\$39.48	\$0.00	\$39.48

JOB COUNT: 4	WORK ORDER TOTAL:	6.01	0.00	561.99	0.00	561.99
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-15-011	REPLACE NEW PITMAN ARM	11310047	09/13/2019 07:00:00	09/13/2019 08:06:00	1.10	\$0.00
03-15-011	REPLACE NEW PITMAN ARM	11310047	09/13/2019 07:00:00	09/13/2019 08:06:00	(1.10)	\$0.00
09-15	ALIGN STEERING	11310047	09/12/2019 13:01:11	09/12/2019 14:08:57	1.13	\$0.00
09-15	ALIGN STEERING	11310047	09/12/2019 10:16:23	09/12/2019 11:31:44	1.26	\$0.00
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	09/09/2019 14:41:51	09/09/2019 14:58:59	0.29	\$0.00
03-15-009	REPLACE NEW TIE ROD	11310047	09/09/2019 13:51:13	09/09/2019 13:55:19	0.07	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/07/2019 12:45:42	09/07/2019 13:11:28	0.43	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/07/2019 12:45:16	09/07/2019 13:10:53	0.43	\$0.00
03-15-009	REPLACE NEW TIE ROD	11310047	09/09/2019 14:58:59	09/09/2019 15:42:03	0.72	\$0.00
03-15-009	REPLACE NEW TIE ROD	11310047	09/10/2019 07:06:44	09/10/2019 07:19:43	0.22	\$0.00
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	09/10/2019 07:19:43	09/10/2019 08:02:24	0.71	\$0.00
03-15-009	REPLACE NEW TIE ROD	11310047	09/12/2019 09:27:48	09/12/2019 09:27:48	0.00	\$0.00
03-15-009	REPLACE NEW TIE ROD	11310047	09/12/2019 09:30:00	09/12/2019 10:16:23	0.77	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	11.82	1	\$11.82
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.96	8	\$23.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-011	REPLACE NEW PITMAN ARM	5C3Z3590CA	PITMAN ARM	47.63	(1)	(\$47.63)
03-15-029	REPLACE NEW STEERING STABILIZER	SC2965	STEERING STABILIZER	39.38	1	\$39.38
03-15-009	REPLACE NEW TIE ROD	2696122	RH INNER TIE ROD END	106.10	1	\$106.10
03-15-009	REPLACE NEW TIE ROD	2695600	RH OUTER TIE ROD END	97.08	1	\$97.08
03-15-009	REPLACE NEW TIE ROD	2695599	LH OUTER TIE ROD END	97.08	1	\$97.08
03-15-009	REPLACE NEW TIE ROD	2693170	RH OUTER TIE ROD	40.29	1	\$40.29
03-15-009	REPLACE NEW TIE ROD	7C3Z3281F	TUBE, TIE ROD ADJUSTING CENTER	119.17	1	\$119.17
03-15-009	REPLACE NEW TIE ROD	7C3Z3280D	ADJUSTER SLEEVE, TIE ROD	23.41	1	\$23.41
03-15-011	REPLACE NEW PITMAN ARM	5C3Z3590CA	PITMAN ARM	47.63	1	\$47.63
					<b>PARTS</b>	<b>561.99</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 33999

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 03-15-009 - REPLACE NEW TIE ROD

(LISAPATE) The right tie rod was excessively worn. Replaced drag link, right tie rod end that connects to the drag link, tie rod end that connects to inner tie rod, inner tie rod and left tie rod end.

### 03-15-011 - REPLACE NEW PITMAN ARM

### 03-15-029 - REPLACE NEW STEERING STABILIZER

(LISAPATE) Replaced steering stabilizer

### 09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment 2.0 hors extra time needed for performing job off of the alignment rack and having to make additional adjustments.

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM by AG/SH

Coolant -35'

### 66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35

USING DEPT NO:	504302	OPENED DATE:	09/10/2007 13:16:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2007 11:43:18	METER 1 - M:	8196	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/12/2007 11:43:43	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-31-001	DIAGNOSE ALTERNATOR	DON	O	N	GARAGE	0.70	\$31.50	\$0.00	\$0.00	\$31.50

JOB COUNT: 1	WORK ORDER TOTAL:	0.70	31.50	0.00	0.00	31.50
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
35-31-001	DIAGNOSE ALTERNATOR	11112000	MRCS104208	00019	\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 08:12:44	09/12/2007 09:17:55	1.09	\$48.89
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 07:31:58	09/12/2007 07:23:00	(0.15)	(\$6.72)
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 07:23:00	09/12/2007 07:31:58	0.15	\$6.72
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 07:23:00	09/12/2007 07:44:00	0.35	\$15.75
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 09:17:55	09/12/2007 08:12:44	(1.09)	(\$48.89)
35-31-001	DIAGNOSE ALTERNATOR	11088474	09/12/2007 08:12:44	09/12/2007 08:33:44	0.35	\$15.75
				LABOR		31.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35

## Work Order Notes

(LOBRIEN) Alternator not charging.

## Job Notes

### 35-31-001 - DIAGNOSE ALTERNATOR

(RWINTERS) r and r alternator, had madden warranty part. truck is under warranty, did not think it would fit in their shop. instead of driving truck to b'ham, the garage installed part.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35297

USING DEPT NO:	504302	OPENED DATE:	01/06/2020 08:08:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2020 06:52:27	METER 1 - M:	64948	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2020 06:52:28	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.63	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.63	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	12052187	01/06/2020 08:25:51	01/06/2020 09:03:33	0.63	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35297

---

## Work Order Notes

(EKIMBREL) Install new 4G GPS

---

## Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(EKIMBREL) JW installed New GPS #5041372291

Old GPS#5015914533

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35529

USING DEPT NO:	504302	OPENED DATE:	01/29/2020 11:16:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2020 11:17:40	METER 1 - M:	65276	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2020 11:17:42	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-52-024	ADJUST BACK UP CAMERA	DON	O	N	GARAGE	0.56	\$0.00	\$0.00	\$0.00	\$0.00
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.30	\$0.00	\$7.01	\$0.00	\$7.01
03-34-004	REPLACE NEW CLEARANCE/MARKER	DON	O	N	GARAGE	0.17	\$0.00	\$6.62	\$0.00	\$6.62
03-79-009	REPLACE NEW SEAT BELT(S)	DON	O	N	GARAGE	1.22	\$0.00	\$459.22	\$0.00	\$459.22
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	2.57	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.35	\$0.00	\$27.58	\$0.00	\$27.58

JOB COUNT: 6	WORK ORDER TOTAL:	6.18	0.00	500.43	0.00	500.43
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/30/2020 13:02:09	01/30/2020 14:00:00	0.96	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	01/30/2020 13:02:44	01/30/2020 14:15:00	1.20	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	01/30/2020 14:30:00	01/30/2020 14:54:16	0.40	\$0.00
01-52-024	ADJUST BACK UP CAMERA	11074414	01/30/2020 14:25:21	01/30/2020 14:59:06	0.56	\$0.00
03-79-009	REPLACE NEW SEAT BELT(S)	11074414	02/06/2020 13:36:01	02/06/2020 14:49:16	1.22	\$0.00
03-34-001	REPLACE NEW HEADLAMPS	11213180	02/07/2020 07:00:00	02/07/2020 07:18:00	0.30	\$0.00
03-34-004	REPLACE NEW CLEARANCE/MARKER	11074414	01/30/2020 14:15:00	01/30/2020 14:25:21	0.17	\$0.00
03-34-004	REPLACE NEW CLEARANCE/MARKER	11074414	01/30/2020 14:01:40	01/30/2020 14:01:40	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/30/2020 10:32:24	01/30/2020 11:53:25	1.35	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-79-009	REPLACE NEW SEAT BELT(S)	6C3Z25611B08AAA	SEAT BELT	195.19	1	\$195.19
03-34-004	REPLACE NEW CLEARANCE/MARKER	GRO45263	SIDE MARKER ASSY AMBER 4IN	3.31	1	\$3.31
03-34-004	REPLACE NEW CLEARANCE/MARKER	GRO45262	SIDE MARKER ASSY RED 4IN	3.31	1	\$3.31
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	7.01	1	\$7.01
03-79-009	REPLACE NEW SEAT BELT(S)	1C3Z25611B60AAD	SEAT BUCKLE KIT (3)W/ LAP BELT	239.03	1	\$239.03

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	2.95	8	\$23.60
03-79-009	REPLACE NEW SEAT BELT(S)	SHIPPING	SHIPPING AND HANDLING	25.00	1	\$25.00
					<b>PARTS</b>	<b>500.43</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35529

## Work Order Notes

(LISAPATE) PM-PMF-Back up camera bracket bent too far down-LR top marker light is broken-SI is due

## Job Notes

### **01-52-024 - ADJUST BACK UP CAMERA**

(LISAPATE) Straightened camera bracket and adjusted camera

### **03-34-001 - REPLACE NEW HEADLAMPS**

(LISAPATE) Replaced LF headlamp

### **03-34-004 - REPLACE NEW CLEARANCE/MARKER**

(LISAPATE) Replaced LR top marker light and RF top marker light due to damages

### **03-79-009 - REPLACE NEW SEAT BELT(S)**

(LISAPATE) Replaced driver seat belt buckle, both passenger seat belt buckles and middle seat lap belt. also replaced passenger seat belt assy. Cut up and destroyed old belts and buckles

### **66-79-003 - PERFORM SAFETY INSPECTION**

(LISAPATE) Safety Inspection completed. See attached

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 8 Cost 0.100000

(LISAPATE) PM by SH

Coolant -10'

Greased liftgate

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35946

USING DEPT NO:	504302	OPENED DATE:	03/09/2020 08:25:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/26/2020 14:13:35	METER 1 - M:	65728	METER 2 - H: 7927
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/01/2020 13:59:39	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,252.92	\$1,252.92
16-00	TRANSPORT COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$300.00	\$300.00
16-55-039	TRANSPORT LIFTGATE ASSY	DON	O	N	GARAGE	4.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	4.00	0.00	0.00	1,552.92	1,552.92
--------------	-------------------	------	------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-34-011	REPLACE NEW TAILLIGHT ASSEMBLY	11153069	51878		\$1,252.92
16-00	TRANSPORT COMPLETE VEHICLE	11153069	51889		(\$300.00)
16-00	TRANSPORT COMPLETE VEHICLE	11153069	51889		\$300.00
16-00	TRANSPORT COMPLETE VEHICLE	11153069	0		(\$300.00)
16-00	TRANSPORT COMPLETE VEHICLE	11153069	0		\$300.00
16-00	TRANSPORT COMPLETE VEHICLE	11153069	51889		\$300.00
COMML					1552.92

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-55-039	TRANSPORT LIFTGATE ASSY	11915538	03/26/2020 07:00:00	03/26/2020 15:00:00	(8.00)	\$0.00
16-55-039	TRANSPORT LIFTGATE ASSY	11915538	03/26/2020 07:00:00	03/26/2020 15:00:00	8.00	\$0.00
16-55-039	TRANSPORT LIFTGATE ASSY	11915538	03/26/2020 07:00:00	03/26/2020 11:00:00	4.00	\$0.00
LABOR						0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 35946

## Work Order Notes

(LISAPATE) RR brake light housing damaged

## Job Notes

### **03-34-011 - REPLACE NEW TAILLIGHT ASSEMBLY**

(RWINTERS) Lyncoach purchased and replaced RR stirrup step, dock bumper assembly / brake light housing

(RWINTERS) liftgate inspected by Lyncoach for damage and recertified ok'd for use.

### **16-00 - TRANSPORT COMPLETE VEHICLE**

(IFALLS) Due to covid-19 and travel ban Lyncoach delivered truck

(IFALLS) delivery charges to be split between s6031a and s5763a

### **16-55-039 - TRANSPORT LIFTGATE ASSY**

(IFALLS) EK performed transport

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 36230

USING DEPT NO:	504302	OPENED DATE:	04/27/2020 08:04:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/27/2020 14:26:08	METER 1 - M:	66131	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2020 15:36:07	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$0.00	\$48.20	\$0.00	\$48.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$0.00	\$4.25	\$0.00	\$4.25

JOB COUNT: 2	WORK ORDER TOTAL:	0.73	0.00	52.45	0.00	52.45
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/27/2020 11:39:52	04/27/2020 11:54:43	0.25	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/27/2020 14:24:39	04/27/2020 14:39:39	0.25	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/27/2020 11:39:17	04/27/2020 11:53:10	0.23	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
03-51-038	REPLACE NEW WIPER BLADES	5W20TQT	QUART CAM2 SYN 5W20 32OZ	3.88	7	\$27.16
03-51-038	REPLACE NEW WIPER BLADES	BALB329	OIL FILTER	3.98	1	\$3.98
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	4.25	1	\$4.25
					PARTS	52.45

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 36230

## Work Order Notes

(IFALLS) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(RTUNAITI)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(IFALLS) JW installed 2 new wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

The following parts are included with the standard job:

Part No : 5W20FS  
Qty : 8  
Description : HAVOLINE 5W20 FULLSYN OIL BULK  
Manufacturer :  
Bin :

(IFALLS) JW/AG performed pm

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 37448

USING DEPT NO:	504302	OPENED DATE:	08/27/2020 14:37:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/31/2020 14:29:23	METER 1 - M:	67300	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/31/2020 14:29:24	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.10	\$0.00	\$98.63	\$0.00	\$98.63
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.00	\$0.00	\$262.73	\$0.00	\$262.73
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.27	0.00	361.36	0.00	361.36
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	08/28/2020 07:16:16	08/28/2020 08:16:21	1.00	\$0.00
03-32-002	REPLACE NEW BATTERY	11074414	08/27/2020 15:34:05	08/27/2020 15:40:01	0.10	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/27/2020 15:25:07	08/27/2020 15:35:28	0.17	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.41	2	\$0.82
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	97.81	1	\$97.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	009121	TIRE 225/70R19.5 BRDG R238 LRG	261.00	1	\$261.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	1.06	1	\$1.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	LT1	19.5 WHEEL WEIGHT	0.67	1	\$0.67
					PARTS	361.36



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 37448

## Work Order Notes

(LISAPATE) PM-RR tire has a cut in the sidewall-battery light flickers on and off

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(SHARBIN) Battery tested bad. Replaced battery ALT charging 14.3

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(AGUERRA) Mounted and balanced R/R outer tire. AMG Scott assisted.

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) Did not change oil, checked fluids and tire pressures. updated oil change sticker. AMG

(AGUERRA) Needs R/R outer tire.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 38387

USING DEPT NO:	504302	OPENED DATE:	11/16/2020 08:47:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2020 14:25:22	METER 1 - M:	68110	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/18/2020 07:27:05	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.77	\$59.11	\$0.00	\$135.88

JOB COUNT: 1	WORK ORDER TOTAL:	0.65	76.77	59.11	0.00	135.88
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/17/2020 08:37:39	11/17/2020 08:53:31	0.26	\$31.20
66-PM-PMA	PERFORM OIL CHANGE	11170580	11/16/2020 15:10:47	11/16/2020 15:33:57	0.39	\$45.56
					<b>LABOR</b>	<b>76.76</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	8	\$35.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	6.77	1	\$6.77
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	16.82	1	\$16.82
					<b>PARTS</b>	<b>59.11</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 38387

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° AB,EH/JAW

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 38907

USING DEPT NO:	504302	OPENED DATE:	01/26/2021 09:02:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/01/2021 08:47:24	METER 1 - M:	68691	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/02/2021 09:03:43	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.01	\$0.62	\$0.00	\$0.00	\$0.62
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.43	\$51.20	\$0.00	\$0.00	\$51.20
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.85	\$100.17	\$786.02	\$0.00	\$886.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$52.15	\$0.00	\$0.00	\$52.15

JOB COUNT: 4	WORK ORDER TOTAL:	1.73	204.14	786.02	0.00	990.16
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	12052187	01/27/2021 13:52:09	01/27/2021 13:52:28	0.01	\$0.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	01/27/2021 13:00:00	01/27/2021 13:50:56	0.85	\$100.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	01/27/2021 12:26:28	01/27/2021 12:26:28	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/26/2021 13:47:25	01/26/2021 14:13:56	0.44	\$52.15
09-15	ALIGN STEERING	11310047	01/29/2021 08:48:58	01/29/2021 09:15:00	0.43	\$51.20

					LABOR	204.14
--	--	--	--	--	-------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	009121	TIRE 225/70R19.5 BRDG R238 LRG	391.50	2	\$783.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	LT1	19.5 WHEEL WEIGHT	1.01	3	\$3.02
					PARTS	786.02

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 38907

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **06-15 - INSPECT STEERING**

(JWRIGHT) Checked front end all good. JAW, AMG

### **09-15 - ALIGN STEERING**

(EHOWELL) Performed Alignment. No adjustments were necessary. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced steer tires. Aired and balanced. Torqued to spec. Brakes are good. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has only been 581 miles since last pm service. Updated pm sticker. Checked all fluids and tires. Needs both front tires replaced due to age and wear. Coolant -34°. JAW

MILEAGE-68691

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 39711

USING DEPT NO:	504302	OPENED DATE:	04/16/2021 09:09:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/16/2021 14:10:50	METER 1 - M:	69598	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/19/2021 09:10:53	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.89	\$45.06	\$0.00	\$78.95

JOB COUNT: 1	WORK ORDER TOTAL:	0.29	33.89	45.06	0.00	78.95
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/16/2021 09:27:09	04/16/2021 09:44:23	0.29	\$33.89
					<b>LABOR</b>	<b>33.89</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.66	1	\$9.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
					<b>PARTS</b>	<b>45.06</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 39711

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 69598 Completed PM topside, Ronny assisted, Scott was bottomside. AMG RC/SH Completed checklist. AMG

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 40490

USING DEPT NO:	504302	OPENED DATE:	07/21/2021 08:36:10	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2021 15:25:33	METER 1 - M:	70567	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2021 09:02:41	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550							
			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-004	REPLACE NEW SPARK PLUGS	DON	O	N	GARAGE	0.83	\$97.78	\$229.47	\$0.00	\$327.25
03-33-009	REPLACE NEW SPARK PLUG WIRES	DON	O	N	GARAGE	0.35	\$41.30	\$48.34	\$0.00	\$89.64
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.45	\$53.62	\$6.77	\$0.00	\$60.39
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.03	\$3.41	\$14.67	\$0.00	\$18.08
06-72-004	INSPECT REAR DOOR ASSEMBLY - RO	DON	O	N	GARAGE	1.46	\$172.58	\$0.00	\$0.00	\$172.58
19-34-003	WIRE/REWIRE SIGNAL, PARKING, & BA	DON	O	N	GARAGE	1.45	\$171.23	\$0.00	\$0.00	\$171.23
19-34-010	WIRE/REWIRE TAG LIGHT	DON	O	N	GARAGE	0.61	\$71.72	\$0.00	\$0.00	\$71.72
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$155.25	\$155.25
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	2.36	\$278.97	\$0.00	\$0.00	\$278.97
35-34-010	DIAGNOSE TAG LIGHT	DON	O	N	GARAGE	1.13	\$133.18	\$0.00	\$0.00	\$133.18
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	O	N	GARAGE	0.18	\$21.37	\$8.14	\$0.00	\$29.51
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.19	\$0.00	\$0.00	\$22.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.08	\$245.11	\$0.00	\$0.00	\$245.11

JOB COUNT: 14	WORK ORDER TOTAL:	11.12	1,312.46	307.39	157.25	1,777.10
---------------	-------------------	-------	----------	--------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
06-72-004	INSPECT REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS50039		\$155.25
06-72-004	INSPECT REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS50039		(\$155.25)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS50039		\$155.25
COMML					157.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-33-009	REPLACE NEW SPARK PLUG WIRES	11310047	07/29/2021 15:30:35	07/29/2021 15:51:35	0.35	\$41.30



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	07/29/2021 14:30:00	07/29/2021 14:40:52	0.18	\$21.37
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	07/29/2021 14:29:07	07/29/2021 14:29:07	0.00	\$0.00
19-34-003	WIRE/REWIRE SIGNAL,PARKING, & BACKUP LAMPS	11310047	07/26/2021 14:30:00	07/26/2021 15:55:19	1.42	\$167.79
19-34-003	WIRE/REWIRE SIGNAL,PARKING, & BACKUP LAMPS	11310047	07/26/2021 14:13:15	07/26/2021 14:15:00	0.03	\$3.44
19-34-010	WIRE/REWIRE TAG LIGHT	11310047	07/22/2021 12:58:41	07/22/2021 13:35:09	0.61	\$71.72
35-34-010	DIAGNOSE TAG LIGHT	11310047	07/22/2021 12:02:40	07/22/2021 12:56:01	0.89	\$104.92
35-34-010	DIAGNOSE TAG LIGHT	11310047	07/22/2021 10:42:04	07/22/2021 10:56:26	0.24	\$28.25
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	07/21/2021 08:48:32	07/21/2021 09:28:40	(0.67)	(\$78.93)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	07/21/2021 08:48:32	07/21/2021 09:28:40	0.67	\$78.93
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	07/21/2021 08:48:32	07/21/2021 09:48:32	1.00	\$118.00
06-72-004	INSPECT REAR DOOR ASSEMBLY - ROLL-UP	11310047	07/21/2021 09:28:40	07/21/2021 10:56:25	1.46	\$172.58
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	07/21/2021 12:05:46	07/21/2021 13:27:37	1.36	\$160.97
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/22/2021 09:32:12	07/22/2021 09:42:40	0.17	\$20.58
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	07/22/2021 08:37:26	07/22/2021 10:42:04	2.08	\$245.11
03-51-038	REPLACE NEW WIPER BLADES	11310047	07/26/2021 13:18:08	07/26/2021 13:19:52	0.03	\$3.41
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11310047	07/26/2021 13:19:52	07/26/2021 13:47:08	0.45	\$53.62
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/27/2021 13:48:31	07/27/2021 13:49:20	0.01	\$1.61
03-33-004	REPLACE NEW SPARK PLUGS	11310047	07/29/2021 14:40:52	07/29/2021 15:30:35	0.83	\$97.78
					<b>LABOR</b>	<b>1312.45</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.34	2	\$14.67
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	194	BULB-TAG/MARKER	0.65	2	\$1.29
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	194	BULB-TAG/MARKER	0.65	(2)	(\$1.29)
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	4057	BULB- BRAKE TURN RUNNING	2.04	1	\$2.04
03-33-004	REPLACE NEW SPARK PLUGS	STWSPP87E	SPARK PLUG BOOTS	6.51	2	\$13.02
03-33-004	REPLACE NEW SPARK PLUGS	SP546	SPARK PLUG MOTORCRAFT	21.65	10	\$216.45
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	GRO46713	MARKER LIGHT	4.73	1	\$4.73
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	38	\$5.13
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	7	\$2.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	1	\$1.01
03-33-009	REPLACE NEW SPARK PLUG WIRES	DEN671-8164	COP BOOTS	48.34	1	\$48.34

# Work Order Charge Detail

PARTS	307.39
-------	--------

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **40490**

---

## Work Order Notes

(LISAPATE) PM-Roll up door popping at the top-misfire on cold start-a/c not getting cold blows warm at times

---

## Job Notes

# Work Order Charge Detail

## 03-33-004 - REPLACE NEW SPARK PLUGS

(EHOWELL) Replaced all ten spark plugs. EH

## 03-33-009 - REPLACE NEW SPARK PLUG WIRES

(EHOWELL) Replaced all ten spark plug boots. EH/AMG

## 03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(EHOWELL) Replaced the right front turn signal bulb. EH

## 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 60-2040

Qty : 2

Description : WIPER BLADE

Manufacturer :

Bin :

(LISAPATE) Replaced wipers

## 06-72-004 - INSPECT REAR DOOR ASSEMBLY - ROLL-UP

(LISAPATE) Techs inspected door and found it out of adjustment. Called for Overhead Door to come and repair

## 19-34-003 - WIRE/REWIRE SIGNAL,PARKING, & BACKUP LAMPS

(EHOWELL) Replaced the marker lamp housing/bulb assembly on the top left corner of the enclosed box. EH .3 Hour

## 19-34-010 - WIRE/REWIRE TAG LIGHT

(EHOWELL) Installed a new wire with an I-let and bolted the I-let to an existing vehicle ground. The tag light is now working. EH .5 Hour

## 24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP

(LISAPATE) Overhead door came out and repaired roll up door on back of truck. reset cables, fixed bottom hinge, adjusted tension, lubed door. PD by CC

## 35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(IFALLS) The vehicle was .4 lb. low on refrigerant. Inspected for a leak using the black light, but did not find one. Removed blower motor from HVAC box and inspected evaporator core for a leak. Verified operation of low pressure cycling switch and verified that the gap was correct on the AC compressor clutch. Injected oil dye into AC system so a leak will be easier to identify if the customer returns. The AC is blowing cold. EH 1 Hour

## 35-34-010 - DIAGNOSE TAG LIGHT

(EHOWELL) The tag light was not working because it did not have a proper ground. EH

## 66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Evacuated and recharged refrigerant from the vehicle. Recovered 2.388 lb. of refrigerant. Pulled a vacuum on the system. Leak test failed. Charged with 2.8 lb. of refrigerant. Added 1.0 oz. of oil with dye so that system could be checked for leaks. EH 1.0 Hour

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

## 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 969 miles. Updated sticker. Checked fluids and tires. Coolant -34°. JAW,EH  
MILEAGE-70567

## CH-SP - CHARGE Shop Supplies

## SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) There were no misfire related DTCs, however, the vehicle hasn't had the spark plugs replaced in at least 3 years. Used the scan to view the misfire graphic. EH 1.0  
Hour

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 41045

USING DEPT NO:	504302	OPENED DATE:	09/16/2021 10:17:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2021 14:07:36	METER 1 - M:	71104	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2021 15:04:13	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	1.00	\$118.00	\$166.17	\$0.00	\$284.17
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.23	\$26.81	\$0.00	\$0.00	\$26.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.23	144.81	166.17	2.00	312.98
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-31-001	REPLACE NEW ALTERNATOR	11170580	09/16/2021 11:58:40	09/16/2021 12:58:40	1.00	\$118.00
35-31	DIAGNOSE CHARGING SYSTEM	11170580	09/16/2021 11:45:02	09/16/2021 11:58:40	0.23	\$26.81
					LABOR	144.81

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-31-001	REPLACE NEW ALTERNATOR	REM23793	ALTERNATOR	166.17	1	\$166.17
					PARTS	166.17

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 41045

---

## Work Order Notes

(LISAPATE) Battery light keeps flashing on and off

---

## Job Notes

### 03-31-001 - REPLACE NEW ALTERNATOR

(LISAPATE) AB installed new alternator. Rechecked ok

### 35-31 - DIAGNOSE CHARGING SYSTEM

(ABBLACK) Vehicle needs new alternator. Voltage regulator has gone out

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 41476

USING DEPT NO:	504302	OPENED DATE:	11/01/2021 11:51:11	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2021 14:02:42	METER 1 - M:	71680	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2021 08:38:09	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550									
				UNIT SERIAL NO:	1FDAF56Y65ED25884						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-003	REPLACE NEW COIL	DON	O	N	GARAGE	3.59	\$423.13	\$56.46	\$0.00	\$479.59
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.70	\$15.18	\$0.00	\$24.88
06-55-039	INSPECT LIFTGATE ASSY	DON	O	N	GARAGE	0.44	\$51.92	\$0.00	\$0.00	\$51.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$96.92	\$40.13	\$0.00	\$137.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-40	SCAN OUT ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	2.58	\$304.08	\$0.00	\$0.00	\$304.08

JOB COUNT: 6	WORK ORDER TOTAL:	7.51	885.75	111.77	2.00	999.52
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-55-039	INSPECT LIFTGATE ASSY	11310047	11/05/2021 08:25:44	11/05/2021 08:52:08	0.44	\$51.92
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/04/2021 10:45:53	11/04/2021 10:50:49	0.08	\$9.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2021 10:09:02	11/04/2021 10:45:33	0.61	\$71.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2021 09:30:00	11/04/2021 09:33:36	0.06	\$7.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/04/2021 09:05:50	11/04/2021 09:15:00	0.15	\$18.03
03-33-003	REPLACE NEW COIL	11310047	11/03/2021 14:30:00	11/03/2021 15:08:29	0.64	\$75.68
03-33-003	REPLACE NEW COIL	11310047	11/03/2021 13:00:00	11/03/2021 14:15:00	1.25	\$147.50
03-33-003	REPLACE NEW COIL	11310047	11/03/2021 12:59:50	11/03/2021 12:59:50	0.00	\$0.00
03-33-003	REPLACE NEW COIL	11310047	11/03/2021 07:03:05	11/03/2021 08:14:46	1.19	\$140.98
03-33-003	REPLACE NEW COIL	11310047	11/02/2021 15:24:15	11/02/2021 15:54:14	0.50	\$58.97
SO-40	SCAN OUT ENGINE / MOTOR SYSTEMS	11310047	11/01/2021 14:30:00	11/01/2021 15:54:43	1.41	\$166.61
SO-40	SCAN OUT ENGINE / MOTOR SYSTEMS	11310047	11/01/2021 13:05:06	11/01/2021 14:15:00	1.17	\$137.47



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

					LABOR	885.76
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
03-33-003	REPLACE NEW COIL	STIFD508T	COIL ON PLUG COIL	28.23	1	\$28.23
03-33-003	REPLACE NEW COIL	STIFD508T	COIL ON PLUG COIL	28.23	1	\$28.23
03-33-003	REPLACE NEW COIL	STIFD508T	COIL ON PLUG COIL	28.23	(1)	(\$28.23)
03-33-003	REPLACE NEW COIL	STIFD508T	COIL ON PLUG COIL	28.23	1	\$28.23
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
					PARTS	111.77

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 41476

## Work Order Notes

(IFALLS) PM / INSPECT LIFT GATE POPS AT TIMES / SCAN OUT ENGINE MISSFIRES

## Job Notes

### 03-33-003 - REPLACE NEW COIL

(IFALLS) Replaced ignition coils for cylinders #2 and #3. Performed a road test after repair. EH

### 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced wipers. SH

### 06-55-039 - INSPECT LIFTGATE ASSY

(IFALLS) The liftgate is making a noise, but it is operating properly at this time. Greased and inspected liftgate. EH/AB/MS/IF

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

### CH-SP - CHARGE Shop Supplies

### SO-40 - SCAN OUT ENGINE / MOTOR SYSTEMS

(EHOWELL) Found DTC P0353 Ignition Coil C Primary/Secondary Circuit Malfunction. Used the Ford Scan tool to view the misfire graphic while performing a road test. Spark plugs have already been replaced. Removed spark plug and verified that it was not damaged from previous install. EH

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4153

USING DEPT NO:	504302	OPENED DATE:	08/20/2009 08:14:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2009 14:38:50	METER 1 - M:	17690	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2009 14:38:52	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,608.56	\$1,608.56
03-34-013	REPLACE NEW FLASHER	DON	O	N	GARAGE	0.04	\$2.33	\$27.79	\$0.00	\$30.12
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.88	\$108.16	\$0.00	\$0.00	\$108.16

JOB COUNT: 3	WORK ORDER TOTAL:	1.92	110.49	27.79	1,608.56	1,746.84
--------------	-------------------	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11078579	88612	0005578	\$1,608.56
				COMML	1608.56

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11274660	08/21/2009 09:30:25	08/21/2009 11:23:17	1.88	\$108.16
03-34-013	REPLACE NEW FLASHER	11274660	08/20/2009 14:54:41	08/20/2009 14:57:07	0.04	\$2.33
				LABOR		110.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-013	REPLACE NEW FLASHER	MOTSF633	DIRECTIONAL FLASHER	27.79	1	\$27.79
					PARTS	27.79

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4153

## Work Order Notes

(LPATE) TURN SIGNALS AND HAZARD LIGHTS ARE INOP-NEEDS ALL NEW TIRES AND ALIGNMENT

## Job Notes

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) GCR REPLACED ALL 6 TIRES AND ALIGNED P0023217

**03-34-013 - REPLACE NEW FLASHER**

(RWINTERS) DIAGNOSTICS-REPLACED NEW FLASHER

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO GCR BY TONY

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 42425

USING DEPT NO:	504302	OPENED DATE:	02/21/2022 09:28:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2022 11:07:37	METER 1 - M:	73153	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2022 14:31:03	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$15.18	\$0.00	\$20.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$71.36	\$41.06	\$0.00	\$112.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.65	76.38	56.24	2.00	134.62
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/21/2022 15:19:11	02/21/2022 15:21:44	0.04	\$5.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2022 14:42:43	02/21/2022 15:19:00	0.60	\$71.36
					LABOR	76.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	8	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.66	1	\$5.66
					PARTS	56.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 42425

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

**01-13 - ADJUST BRAKES**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH Performed PM and greased the lift gate.

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43151

USING DEPT NO:	504302	OPENED DATE:	05/05/2022 15:08:29	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/03/2022 09:27:41	METER 1 - M:	74279	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2022 09:02:34	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550							
			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.60	\$70.80	\$93.62	\$0.00	\$164.42
03-01-014	REPLACE NEW RESISTOR	DON	O	N	GARAGE	0.50	\$59.00	\$29.47	\$0.00	\$88.47
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.67	\$15.18	\$0.00	\$18.85
03-52-024	REPLACE NEW BACK UP CAMERA	DON	O	N	GARAGE	3.00	\$354.00	\$1,080.59	\$38.41	\$1,473.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
35-52-024	DIAGNOSE BACK UP CAMERA	DON	O	N	GARAGE	3.54	\$417.20	\$0.00	\$0.00	\$417.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$120.43	\$15.83	\$0.00	\$136.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 8	WORK ORDER TOTAL:	8.89	1,048.70	1,234.69	43.41	2,326.80
--------------	-------------------	------	----------	----------	-------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-52-024	REPLACE NEW BACK UP CAMERA	5761126	2108574		\$18.92
03-52-024	REPLACE NEW BACK UP CAMERA	5761126	2108764		\$19.49
COMML					43.41

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-52-024	REPLACE NEW BACK UP CAMERA	11213180	08/24/2022 08:06:00	08/24/2022 11:06:00	3.00	\$354.00
03-01-014	REPLACE NEW RESISTOR	11213180	08/24/2022 07:36:00	08/24/2022 08:06:00	0.50	\$59.00
03-01-004	REPLACE NEW BLOWER MOTOR	11213180	08/24/2022 07:00:00	08/24/2022 07:36:00	0.60	\$70.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/09/2022 07:21:34	05/09/2022 08:22:48	1.02	\$120.43
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/09/2022 07:19:26	05/09/2022 07:21:18	0.03	\$3.67
35-52-024	DIAGNOSE BACK UP CAMERA	11213180	05/24/2022 08:17:45	05/24/2022 10:53:42	2.60	\$306.70
35-52-024	DIAGNOSE BACK UP CAMERA	11213180	05/24/2022 13:13:14	05/24/2022 14:09:25	0.94	\$110.49
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	08/24/2022 07:00:00	08/24/2022 07:12:00	0.20	\$23.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

					LABOR	1048.69
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.38	1	\$7.38
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.38	(1)	(\$7.38)
03-01-014	REPLACE NEW RESISTOR	STIRU445	BLOWER RESISTOR	29.47	1	\$29.47
03-01-004	REPLACE NEW BLOWER MOTOR	TYC700099	BLOWER MOTOR	93.62	1	\$93.62
66-PM-PMA	PERFORM OIL CHANGE	PA4172	AIR FILTER	15.83	1	\$15.83
66-PM-PMA	PERFORM OIL CHANGE	LOP10393	CHAIN LUBE	11.24	(1)	(\$11.24)
66-PM-PMA	PERFORM OIL CHANGE	LOP10393	CHAIN LUBE	11.24	1	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	LOP10393	CHAIN LUBE	11023.50	(1)	(\$11,023.50)
66-PM-PMA	PERFORM OIL CHANGE	LOP10393	CHAIN LUBE	11023.50	1	\$11,023.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-916	STANDARD CAMERA KIT	292.50	1	\$292.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-PM-1980S	7" QUAD MONITOR	778.50	1	\$778.50
03-52-024	REPLACE NEW BACK UP CAMERA	06133	ELECTRICAL TAPE 3M SUPER 33+	9.59	1	\$9.59
					PARTS	1234.69



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43151

## Work Order Notes

(CWIGLEY) PM-Replace Wipers A/C not blowing at all. backup camera not working

## Job Notes

### **03-01-004 - REPLACE NEW BLOWER MOTOR**

(EKIMBREL) Replaced blower motor. MS

### **03-01-014 - REPLACE NEW RESISTOR**

(EKIMBREL) Replaced resistor. MS

### **03-51-038 - REPLACE NEW WIPER BLADES**

(CWIGLEY)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(AGUERRA) Replaced wipers. AMG

### **03-52-024 - REPLACE NEW BACK UP CAMERA**

(EKIMBREL) Replaced rear camera and monitor wired in new monitor. MS

### **35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT**

(MSIDES) Found blower motor to be inop. Unit will need blower and blower resistor replaced. MS

### **35-52-024 - DIAGNOSE BACK UP CAMERA**

(EKIMBREL) Camera and monitor need replaced. MS

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 74279 Vehicle has been 1052 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43508

USING DEPT NO:	504302	OPENED DATE:	06/03/2022 09:27:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/03/2022 14:58:38	METER 1 - M:	74608	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2022 10:39:22	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.20	\$23.08	\$7.38	\$0.00	\$30.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.10	\$11.80	\$11.24	\$0.00	\$23.04

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	34.88	18.62	2.00	55.50
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11074414	06/03/2022 09:31:10	06/03/2022 09:42:54	0.20	\$23.08
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	10208562	06/03/2022 14:21:27	06/03/2022 14:27:27	0.10	\$11.80
					LABOR	34.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	LOP10393	CHAIN LUBE	11.24	1	\$11.24
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	7.38	1	\$7.38
					PARTS	18.62

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43508

## Work Order Notes

(LISAPATE) Truck is low on oil

## Job Notes

**AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&**

(HHARBIN) Customer requested the oil level be checked in his truck. Was 1 quart low added oil and rechecked. All good. SH

**CH-SP - CHARGE Shop Supplies**

**PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&**

(EKIMBREL) CUSTOMER PICKED UP 1 CAN OF LUB.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43624

USING DEPT NO:	504302	OPENED DATE:	06/13/2022 08:02:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2022 13:34:33	METER 1 - M:	74754	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2022 15:38:17	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-33-012	REPLACE NEW WIRING HARNESS	DON	O	N	GARAGE	1.15	\$135.90	\$23.63	\$0.00	\$159.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.76	\$89.84	\$0.00	\$0.00	\$89.84

JOB COUNT: 3	WORK ORDER TOTAL:	1.91	225.74	23.63	2.00	251.37
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	06/13/2022 08:29:19	06/13/2022 09:15:00	0.76	\$89.84
03-33-012	REPLACE NEW WIRING HARNESS	11310047	06/15/2022 09:29:30	06/15/2022 09:29:30	0.00	\$0.00
03-33-012	REPLACE NEW WIRING HARNESS	11310047	06/15/2022 09:30:00	06/15/2022 10:39:06	1.15	\$135.90
				LABOR		225.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-33-012	REPLACE NEW WIRING HARNESS	06133	ELECTRICAL TAPE 3M SUPER 33+	9.59	1	\$9.59
03-33-012	REPLACE NEW WIRING HARNESS	PIC5713PT	IGN COIL CONNECTOR	7.02	2	\$14.04
					PARTS	23.63

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43624

## Work Order Notes

(LISAPATE) Check engine light is on

## Job Notes

### 03-33-012 - REPLACE NEW WIRING HARNESS

(IFALLS) Replaced electrical connectors for #1 and #3 ignition coils. Used solder and heat shrink. EH .5 HR

### CH-SP - CHARGE Shop Supplies

### SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0353 Ignition Coil C Primary Circuit Fault. Cylinder #3 misfired for a short period of time. Swapped #1 and #3 ignition coils, but the misfire did not occur after swapping coils. Pressure tested cooling system to see if coolant in cylinders could be causing the vehicle to misfire. Test passed. Drove vehicle again but was unable to duplicate the concern. EH

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43971

USING DEPT NO:	504302	OPENED DATE:	07/14/2022 07:37:31	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2022 15:03:04	METER 1 - M:	75416	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/15/2022 09:06:01	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550							
			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.17	\$19.50	\$63.74	\$0.00	\$83.24
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	DON	O	N	GARAGE	0.55	\$65.46	\$32.58	\$0.00	\$98.04
03-02-103	REPLACE NEW BEZEL	DON	O	N	GARAGE	0.08	\$9.24	\$20.38	\$0.00	\$29.62
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.08	\$9.54	\$11.64	\$0.00	\$21.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.88	103.74	128.34	2.00	234.08
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-103	REPLACE NEW BEZEL	11901357	07/14/2022 08:40:28	07/14/2022 08:45:10	0.08	\$9.24
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11901357	07/14/2022 08:34:54	07/14/2022 08:39:45	0.08	\$9.54
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	11901357	07/14/2022 07:57:00	07/14/2022 08:30:17	0.55	\$65.46
03-02-010	REPLACE NEW MIRRORS	11901357	07/14/2022 07:46:50	07/14/2022 07:56:45	0.17	\$19.50
					LABOR	103.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-031	REPLACE NEW EXTERIOR BODY MOLDINGS	F81Z2520758AA	LOWER DOOR WEATHERSTRIP	32.58	1	\$32.58
03-02-103	REPLACE NEW BEZEL	6C3Z25224A34AA	ARMREST COVER	10.19	1	\$10.19
03-02-103	REPLACE NEW BEZEL	6C3Z25224A35AA	ARMREST COVER	10.19	1	\$10.19
03-02-010	REPLACE NEW MIRRORS	YC3Z17K707CA	LOWER MIRROR	63.74	1	\$63.74
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.82	2	\$11.64
					PARTS	128.34

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 43971

## Work Order Notes

(LISAPATE) Replace passenger lower mirror and driver door trim.

## Job Notes

### **03-02-010 - REPLACE NEW MIRRORS**

(AGUERRA) miles: 75416 Replaced right outside lower convex mirror. Checked for proper operation, all good. AMG

### **03-02-031 - REPLACE NEW EXTERIOR BODY MOLDINGS**

(AGUERRA) Replaced left door lower molding. AMG

### **03-02-103 - REPLACE NEW BEZEL**

(AGUERRA) Replaced armrest bezel on driver and passenger doors. AMG

### **AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&**

(AGUERRA) Topped of engine oil, used 1.5 quarts of 5W20. AMG

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44

USING DEPT NO:	504302	OPENED DATE:	09/07/2007 11:45:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2007 13:37:15	METER 1 - M:	8183	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/12/2007 13:39:45	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$22.50	\$105.24	\$0.00	\$127.74

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	22.50	105.24	0.00	127.74
--------------	-------------------	------	-------	--------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11088858	09/07/2007 12:00:00	09/07/2007 12:30:00	0.50	\$22.50
					<b>LABOR</b>	<b>22.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	665MF	BATTERY	105.24	1	\$105.24
					<b>PARTS</b>	<b>105.24</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44

## Work Order Notes

(RWINTERS) customer had to jump off, drove to garage

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(RWINTERS) replaced battery, acid had leaked out. charging system is low. installed battery, driver will bring back for alt. replacement.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4435

USING DEPT NO:	504302	OPENED DATE:	10/01/2009 14:31:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/02/2009 07:45:16	METER 1 - M:	18236	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/02/2009 07:45:17	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$7.62	\$0.00	\$24.87
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$62.47	\$0.00	\$80.30

JOB COUNT: 3	WORK ORDER TOTAL:	0.86	49.46	100.99	0.00	150.45
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11274660	10/01/2009 17:00:00	10/01/2009 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11274660	10/01/2009 17:18:36	10/01/2009 17:33:36	0.25	\$14.38
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11274660	10/01/2009 17:33:36	10/01/2009 17:51:36	0.30	\$17.25
					LABOR	49.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49136	FILTER-AIR	27.73	1	\$27.73
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	256	\$26.88
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	(224)	(\$23.52)
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	7.62	1	\$7.62
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.86	1	\$7.86
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
					PARTS	100.99

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4435

## Work Order Notes

(LPATE) PM-REPLACE WIPERS-LEFT REAR TURN SIGNAL INOP

## Job Notes

**03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LPATE) REPLACED LEFT REAR TURN SIGNAL BULB

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) The following parts are included with the standard job:

Part No : 91-20  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE) The following parts are included with the standard job:

Part No : 1198  
Qty : 1  
Description : OIL DRAIN PLUG FORD  
Manufacturer :

Part No : 51372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : OIL BOTTLE  
Manufacturer :

(LPATE) PM BY TF

(LPATE) REPLACED AIR FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44493

USING DEPT NO:	504302	OPENED DATE:	08/29/2022 09:31:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/29/2022 14:43:42	METER 1 - M:	76140	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/29/2022 14:43:48	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.25	29.50	0.00	5.00	34.50
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	08/29/2022 14:42:04	08/29/2022 14:57:04	0.25	\$29.50
					LABOR	29.50

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44493

## Work Order Notes

(CWIGLEY) A/C not working.

## Job Notes

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(CWIGLEY) Repaired vacuum line, no charge for vacuum hose.

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4458

USING DEPT NO:	504302	OPENED DATE:	10/07/2009 07:44:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2009 11:20:16	METER 1 - M:	18288	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/07/2009 11:20:17	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$92.82	\$0.00	\$121.57
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:	1.50	86.25	92.82	0.00	179.07
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11274660	10/07/2009 18:00:00	10/07/2009 18:30:00	0.50	\$28.75
66-79-002	PERFORM SERVICE CALL	11274660	10/07/2009 17:00:00	10/07/2009 18:00:00	1.00	\$57.50
					LABOR	86.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	65-6	BATTERY TOP POST	92.82	1	\$92.82
					PARTS	92.82

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 4458

## Work Order Notes

(LPATE) REQUESTED SVC CALL FOR DEAD BATTERY

## Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

66-79-002 - PERFORM SERVICE CALL

(LPATE) SVC CALL TO GORDON PALMER HALL FOR DEAD BATTERY

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44588

USING DEPT NO:	504302	OPENED DATE:	09/07/2022 08:10:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2022 11:02:21	METER 1 - M:	76281	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 12:46:22	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-14-004	REPLACE NEW CAB & BODY MOUNTIN	DON	O	N	GARAGE	1.19	\$140.85	\$668.76	\$0.00	\$809.61
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.65	\$76.50	\$0.00	\$0.00	\$76.50
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.14	\$134.68	\$0.00	\$0.00	\$134.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$83.62	\$65.32	\$0.00	\$148.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	3.69	435.65	734.08	5.00	1,174.73
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11901357	09/08/2022 09:23:44	09/08/2022 09:23:44	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	09/08/2022 09:30:00	09/08/2022 10:38:29	1.14	\$134.68
03-14-004	REPLACE NEW CAB & BODY MOUNTINGS	11213180	09/09/2022 09:30:00	09/09/2022 09:59:08	0.49	\$57.30
03-14-004	REPLACE NEW CAB & BODY MOUNTINGS	11213180	09/09/2022 08:32:31	09/09/2022 09:15:00	0.71	\$83.55
07-55-039	LUBRICATE LIFTGATE ASSY	11901357	09/08/2022 08:36:06	09/08/2022 09:15:00	0.65	\$76.50
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/08/2022 08:06:56	09/08/2022 08:35:38	0.48	\$56.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2022 07:39:18	09/08/2022 07:53:07	0.23	\$27.17
					LABOR	435.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	6.74	1	\$6.74
03-14-004	REPLACE NEW CAB & BODY MOUNTINGS	DOR924329	BODY MOUNT KIT	167.19	4	\$668.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	8	\$48.72
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.86	1	\$9.86
					PARTS	734.08



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44588

## Work Order Notes

(LISAPATE) Adjust brakes-Do annual SI-PM-replace wipers-Clean and lubricate lift

## Job Notes

### 01-13 - ADJUST BRAKES

### 03-14-004 - REPLACE NEW CAB & BODY MOUNTINGS

(MSIDES) Replaced 4 rear most cab mounts. MS

### 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE)

The following parts are included with the standard job:

Part No : 60-2040

Qty : 2

Description : WIPER BLADE

Manufacturer :

Bin :

### 07-55-039 - LUBRICATE LIFTGATE ASSY

(AGUERRA) Lubricated lift gate assembly. AMG

### 66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) Completed safety inspection, found that vehicle needs body mounts, verified by Matt Sides. No other issues found. AMG

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 76281 Completed PM top and bottom side, Scott assisted top side. AMG SH/AMG

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44978

USING DEPT NO:	504302	OPENED DATE:	10/13/2022 13:19:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2022 15:08:17	METER 1 - M:	76772	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 07:20:23	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	P	N	GARAGE	0.15	\$17.70	\$146.72	\$0.00	\$164.42
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.65	76.70	146.72	5.00	228.42
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	10/14/2022 07:00:00	10/14/2022 07:09:00	0.15	\$17.70
66-79-002	PERFORM SERVICE CALL	11074414	10/13/2022 14:16:31	10/13/2022 14:16:31	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11074414	10/13/2022 14:16:31	10/13/2022 14:16:31	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	11074414	10/13/2022 14:16:31	10/13/2022 14:46:31	0.50	\$59.00
				LABOR		76.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	652	BATTERY BCI 65 850 CCA	146.72	1	\$146.72
					PARTS	146.72

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 44978

---

## Work Order Notes

(CHANNELL) won,t start

---

## Job Notes

**03-32-002 - REPLACE NEW BATTERY**

(EKIMBREL) SH REPLACED BATTERY

**66-79-002 - PERFORM SERVICE CALL**

(SHARBIN) SH EH Performed a service call to recycling for a dead battery. Battery was 2 years old. Replaced the battery on site ALT charging at 14 volts. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 45573

USING DEPT NO:	504302	OPENED DATE:	12/14/2022 08:21:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/15/2022 12:29:56	METER 1 - M:	77655	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/15/2022 13:57:43	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.41	\$15.63	\$0.00	\$19.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.30	\$55.77	\$0.00	\$87.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.29	34.71	71.40	5.00	111.11
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2022 15:19:12	12/14/2022 15:29:07	0.17	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/14/2022 13:53:45	12/14/2022 13:59:45	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/14/2022 13:51:50	12/14/2022 13:53:34	0.03	\$3.41
				LABOR		34.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	8	\$49.92
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.85	1	\$5.85
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
				PARTS		71.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 45573

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(EHANNAH)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(SHARBIN) Replaced the wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 45927

USING DEPT NO:	504302	OPENED DATE:	01/26/2023 10:38:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2023 15:20:34	METER 1 - M:	78098	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2023 09:20:34	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	3.26	\$385.24	\$434.29	\$0.00	\$819.53
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.27	\$31.86	\$0.00	\$0.00	\$31.86
06-15-013	INSPECT POWER STEERING LINES	DON	O	N	GARAGE	2.12	\$250.26	\$0.00	\$0.00	\$250.26
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.80	\$212.40	\$0.00	\$0.00	\$212.40
24-18-007	REPAIR WHEEL STUD /NUT	DON	O	N	GARAGE	0.14	\$16.39	\$5.78	\$0.00	\$22.17
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	1.39	\$164.45	\$0.00	\$0.00	\$164.45
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.60	\$70.80	\$704.36	\$0.00	\$775.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-13	SCAN OUT BRAKES	DON	O	N	GARAGE	0.37	\$43.37	\$0.00	\$0.00	\$43.37

JOB COUNT: 9	WORK ORDER TOTAL:	9.96	1,174.77	1,144.43	5.00	2,324.20
--------------	-------------------	------	----------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-13	SCAN OUT BRAKES	11310047	02/01/2023 08:16:46	02/01/2023 08:38:49	0.37	\$43.37
06-15-013	INSPECT POWER STEERING LINES	11310047	01/31/2023 13:02:55	01/31/2023 15:10:10	2.12	\$250.26
66-13-130	PERFORM Burnish Brakes	11310047	01/31/2023 11:39:18	01/31/2023 13:02:55	1.39	\$164.45
09-15	ALIGN STEERING	11310047	01/31/2023 09:34:48	01/31/2023 11:22:48	1.80	\$212.40
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	01/27/2023 09:30:00	01/27/2023 11:00:00	1.50	\$177.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	01/27/2023 09:21:05	01/27/2023 09:21:05	0.00	\$0.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	01/27/2023 12:50:52	01/27/2023 14:15:00	1.40	\$165.46
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	01/27/2023 14:30:00	01/27/2023 14:51:45	0.36	\$42.78
06-15	INSPECT STEERING	11310047	01/31/2023 11:23:06	01/31/2023 11:39:18	0.27	\$31.86

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-18-007	REPAIR WHEEL STUD /NUT	11310047	02/01/2023 08:38:49	02/01/2023 08:47:09	0.14	\$16.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	02/03/2023 07:00:00	02/03/2023 07:36:00	0.60	\$70.80
					<b>LABOR</b>	<b>1174.77</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	4.01	2	\$8.01
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.46	2	\$8.91
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58124	1.25 OZ WHEEL WEIGHT	0.60	1	\$0.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58125	1.50 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58126	1.75 OZ WHEEL WEIGHT	0.74	1	\$0.74
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58127	2.00 OZ WHEEL WEIGHT	0.86	2	\$1.71
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	FBRSB680305	FRONT ROTORS	151.41	2	\$302.82
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1066TRH	BRAKE PADS	116.63	1	\$116.63
24-18-007	REPAIR WHEEL STUD /NUT	DOR611246	WHEEL NUT	5.78	1	\$5.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	248426	TIRE 225/70R19.5 FS 561	346.11	2	\$692.22
					<b>PARTS</b>	<b>1144.43</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 45927

## Work Order Notes

(LISAPATE) Gerald requested replace tires due to drivers are sliding in the rain. Tires are worn ordered all new tires

## Job Notes

### **03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS**

(EHOWELL) Replaced front brake pads and rotors. Greased slide pins. Add additional .3 for bleeding front brakes. EH

### **06-15 - INSPECT STEERING**

(EHOWELL) Checked front end. EH/JAW

### **06-15-013 - INSPECT POWER STEERING LINES**

(EHOWELL) One of the power steering lines was leaking fluid due to being loose. Tightened line, cleaned off fluid, and verified repair. Topped off power steering fluid after repair. Also, sprayed off oil leaks near front cover and rear cover of engine. Allowed vehicle to idle for a while. The leaks are not dripping excessively at this time. EH .5

### **09-15 - ALIGN STEERING**

(EHOWELL) Checked alignment. The camber, caster and toe were within specification. Moved adjuster slightly so that steering wheel would be in the center position. EH 1.0 HR

### **24-18-007 - REPAIR WHEEL STUD /NUT**

(EHOWELL) Repaired damaged threads on wheel studs and installed a new lug nut. EH

### **66-13-130 - PERFORM Burnish Brakes**

(EHOWELL) Made multiple hard stops after brake job was performed. The ABS activated while making hard stops on a wet road. This is considered normal operation. Driver's need to drive cautiously when road conditions are wet. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) GC/JW mounted and balanced 2 front tires

### **CH-SP - CHARGE Shop Supplies**

### **SO-13 - SCAN OUT BRAKES**

(EHOWELL) There were no On Demand DTCs stored for the Antilock Braking System. The ABS light is not illuminated. EH



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 46568

USING DEPT NO:	504302	OPENED DATE:	03/30/2023 13:27:00	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/31/2023 12:42:46	METER 1 - M:	78817	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2023 10:46:26	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-55-012	REPAIR CARGO RESTRAINTS	DON	O	N	GARAGE	0.26	\$31.07	\$0.00	\$0.00	\$31.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.63	\$12.51	\$0.00	\$58.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.06	\$6.72	\$0.00	\$0.00	\$6.72

JOB COUNT: 4	WORK ORDER TOTAL:	0.71	83.42	12.51	5.00	100.93
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-55-012	REPAIR CARGO RESTRAINTS	12052187	03/31/2023 08:35:14	03/31/2023 08:51:02	0.26	\$31.07
WA-00	WASH COMPLETE VEHICLE	12052187	03/31/2023 08:26:15	03/31/2023 08:29:40	0.06	\$6.72
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/31/2023 08:02:49	03/31/2023 08:26:01	0.39	\$45.63
				LABOR		83.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	2	\$12.51
					PARTS	12.51

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 46568

## Work Order Notes

(EHANNAH) pm- replace wipers- wash- adjust brakes- strap bars are coming loose please screw them down

## Job Notes

### 01-13 - ADJUST BRAKES

### 03-51-038 - REPLACE NEW WIPER BLADES

(EHANNAH)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

### 24-55-012 - REPAIR CARGO RESTRAINTS

(JWRIGHT) Removed cargo restraint from left rear of box and straightened the bracket out. Reinstalled in truck. JAW  
1/2 hr labor

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1162 miles. Checked fluids and tires. Coolant -34°. JAW  
MILEAGE-78817

### CH-SP - CHARGE Shop Supplies

### WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Wash Bay closed

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 47359

USING DEPT NO:	504302	OPENED DATE:	06/14/2023 09:17:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2023 14:19:38	METER 1 - M:	79921	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 07:54:25	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-004	REPLACE NEW CLEARANCE/MARKER	DON	O	N	GARAGE	0.08	\$9.70	\$5.85	\$0.00	\$15.55
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$29.50	\$16.62	\$0.00	\$46.12
07-55-039	LUBRICATE LIFTGATE ASSY	DON	P	N	GARAGE	0.20	\$24.09	\$0.00	\$0.00	\$24.09
25-02-037	REMOVE SEAT ASSEMBLY	DON	O	N	GARAGE	0.61	\$72.41	\$0.00	\$0.00	\$72.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.66	\$55.98	\$0.00	\$111.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.62	191.36	78.45	5.00	274.81
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/28/2023 07:00:00	06/28/2023 07:15:00	0.25	\$29.50
03-34-004	REPLACE NEW CLEARANCE/MARKER	12201267	06/15/2023 07:25:34	06/15/2023 07:30:30	0.08	\$9.70
25-02-037	REMOVE SEAT ASSEMBLY	11074414	06/14/2023 15:16:41	06/14/2023 15:53:30	0.61	\$72.41
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	06/14/2023 15:04:09	06/14/2023 15:16:24	0.20	\$24.09
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/14/2023 14:32:06	06/14/2023 15:00:24	0.47	\$55.66
				LABOR		191.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	8	\$50.04
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.31	2	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
03-34-004	REPLACE NEW CLEARANCE/MARKER	GRO45263	SIDE MARKER ASSY AMBER 4IN	5.85	1	\$5.85
				PARTS		78.45

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 47359

## Work Order Notes

(EHANNAH) check fluid - remove seat for other shop

## Job Notes

### **03-34-004 - REPLACE NEW CLEARANCE/MARKER**

(GRCOOK) Installed new marker lens cover, light is working just needed a new lens-GC

### **03-51-038 - REPLACE NEW WIPER BLADES**

(EKIMBREL)

The following parts are included with the standard job:

Part No : 60-2040  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :  
Bin :

(LISAPATE) replaced wipers

### **07-55-039 - LUBRICATE LIFTGATE ASSY**

(SHARBIN) Greased the lift gate. SH

### **25-02-037 - REMOVE SEAT ASSEMBLY**

(SHARBIN) Removed the seat. RC Carried the seat to the upholstery shop. SH

(SHARBIN) Reinstalled the seat. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48138

USING DEPT NO:	504302	OPENED DATE:	09/08/2023 11:44:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2023 08:45:06	METER 1 - M:	80835	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 08:45:10	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-038	REPLACE NEW CARGO DOOR LIFT SPI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$552.00	\$552.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	557.00	557.00
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-55-038	REPLACE NEW CARGO DOOR LIFT SPRINGS	11076414	TCS53724		\$552.00
				COMML	557.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48138

## Work Order Notes

(LISAPATE) Cargo door will not open

## Job Notes

03-55-038 - REPLACE NEW CARGO DOOR LIFT SPRINGS

(LISAPATE) Overhead door removed and installed 1 new spring. rechecked ok PD by CC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48626

USING DEPT NO:	504302	OPENED DATE:	10/19/2023 08:29:07	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/27/2023 07:25:44	METER 1 - M:	84461	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/27/2023 10:11:53	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550									
				UNIT SERIAL NO:	1FDAF56Y65ED25884						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.75	\$88.07	\$66.83	\$0.00	\$154.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					1.00	117.57	66.83	5.00	189.40
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	12395904	10/27/2023 07:00:00	10/27/2023 07:15:00	0.25	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/19/2023 14:42:13	10/19/2023 15:27:00	0.75	\$88.07
LABOR						117.57

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	8	\$50.04
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.96	1	\$5.96
PARTS						66.83

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48626

## Work Order Notes

(EHANNAH) pm- inspect steering- adjust brakes. repair the scrap bar

## Job Notes

01-13 - ADJUST BRAKES

06-15 - INSPECT STEERING

(LISAPATE) Checked steering good.. FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil change and fluid check FC -sh

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48872

USING DEPT NO:	504302	OPENED DATE:	11/07/2023 15:22:28	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2023 12:18:37	METER 1 - M:	81600	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2023 13:33:54	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-55-012	REPAIR CARGO RESTRAINTS	DON	N	N	GARAGE	0.26	\$30.94	\$44.94	\$0.00	\$75.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.26	30.94	44.94	5.00	80.88
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-55-012	REPAIR CARGO RESTRAINTS	12201267	11/07/2023 15:27:59	11/07/2023 15:43:43	0.26	\$30.94
LABOR						30.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-55-012	REPAIR CARGO RESTRAINTS	3XMT7	E-TRACK	22.47	2	\$44.94
PARTS						44.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 48872

## Work Order Notes

(LISAPATE) Repair cargo restraints

## Job Notes

### 24-55-012 - REPAIR CARGO RESTRAINTS

(GRCOOK) Repaired and cut out a piece of broke restraint and installed new piece, also put other new piece of restraint where drive wanted me to install it, went through and tightened down and loose places. -GC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 49328

USING DEPT NO:	504302	OPENED DATE:	01/03/2024 10:12:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/04/2024 08:57:44	METER 1 - M:	84461	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/04/2024 11:56:26	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.06	\$7.47	\$9.17	\$0.00	\$16.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.06	7.47	9.17	5.00	21.64
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11074414	01/03/2024 10:20:25	01/03/2024 10:24:13	0.06	\$7.47
					LABOR	7.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	9.17	1	\$9.17
					PARTS	9.17

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 49328

## Work Order Notes

(LISAPATE) Truck is low on oil. Driver will bring back for service later

## Job Notes

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(SHARBIN) Checked oil per driver request. Was 1 QT low. Added 1 QT. Did not see any visible leaks. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 49479

USING DEPT NO:	504302	OPENED DATE:	01/17/2024 13:48:51	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2024 10:51:43	METER 1 - M:	82466	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2024 07:16:06	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550							
			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	N	N	GARAGE	8.44	\$995.36	\$619.73	\$0.00	\$1,615.09
03-15-029	REPLACE NEW STEERING STABILIZER	DON	N	N	GARAGE	4.54	\$535.16	\$173.28	\$0.00	\$708.44
03-16-006	REPLACE NEW REAR SHOCK ABSORB	DON	N	N	GARAGE	4.83	\$569.81	\$299.01	\$0.00	\$868.82
03-16-028	REPLACE NEW FRONT/ REAR BUMP S	DON	N	N	GARAGE	0.11	\$12.52	\$78.45	\$0.00	\$90.97
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.37	\$43.07	\$199.98	\$0.00	\$243.05
03-40-419	REPLACE NEW OIL PAN/GASKET	DON	N	N	GARAGE	7.17	\$845.60	\$168.24	\$0.00	\$1,013.84
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	3.70	\$436.63	\$16.65	\$0.00	\$453.28
06-02-016	INSPECT TAIL&LIFT GATE	DON	N	N	GARAGE	0.75	\$88.53	\$9.39	\$0.00	\$97.92
06-17-013	INSPECT ALIGNMENT	DON	N	N	GARAGE	0.15	\$17.31	\$0.00	\$0.00	\$17.31
06-32-010	INSPECT STARTER	DON	O	N	GARAGE	0.25	\$29.30	\$0.00	\$0.00	\$29.30
24-02	REPAIR CAB & SHEET METAL	DON	N	N	GARAGE	1.19	\$140.22	\$0.00	\$0.00	\$140.22
35-30-005	DIAGNOSE LIFTGATE SWITCH	DON	N	N	GARAGE	1.46	\$172.77	\$229.40	\$0.00	\$402.17
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	2.82	\$333.09	\$0.00	\$0.00	\$333.09
66-17-017	PERFORM BALANCE TIRES	DON	P	N	GARAGE	0.47	\$55.95	\$16.17	\$0.00	\$72.12
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	3.59	\$423.82	\$0.00	\$0.00	\$423.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.25	\$51.18	\$0.00	\$105.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 17 WORK ORDER TOTAL: 40.28 4,753.39 1,861.48 5.00 6,619.87

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
----------	-----------------	--------------	-------	--------	----------	------------

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02	REPAIR CAB & SHEET METAL	11310047	02/05/2024 09:30:00	02/05/2024 10:41:18	1.19	\$140.22
24-02	REPAIR CAB & SHEET METAL	11310047	02/05/2024 09:27:46	02/05/2024 09:27:46	0.00	\$0.00
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	02/12/2024 10:59:25	02/12/2024 11:53:52	0.91	\$107.09
06-32-010	INSPECT STARTER	11310047	02/12/2024 09:29:14	02/12/2024 09:44:08	0.25	\$29.30
66-13-130	PERFORM Burnish Brakes	11310047	02/12/2024 08:39:50	02/12/2024 09:29:14	0.82	\$97.15
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/24/2024 13:02:37	01/24/2024 13:08:09	0.09	\$10.88
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/24/2024 09:30:00	01/24/2024 10:30:46	1.01	\$119.51
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/24/2024 09:02:15	01/24/2024 09:15:00	0.21	\$25.08
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/24/2024 07:03:16	01/24/2024 09:02:15	1.98	\$234.00
35-30-005	DIAGNOSE LIFTGATE SWITCH	11310047	01/23/2024 07:24:23	01/23/2024 08:52:14	1.46	\$172.77
06-02-016	INSPECT TAIL&LIFT GATE	11310047	01/18/2024 08:16:42	01/18/2024 08:31:09	0.24	\$28.42
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/17/2024 14:30:00	01/17/2024 14:57:35	0.46	\$54.25
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/17/2024 14:23:33	01/17/2024 14:23:33	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11310047	01/18/2024 08:31:09	01/18/2024 11:46:40	3.26	\$384.52
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/24/2024 13:42:33	01/24/2024 14:15:00	0.54	\$63.82
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/24/2024 14:30:00	01/24/2024 15:52:23	1.37	\$162.02
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/25/2024 07:01:31	01/25/2024 09:15:00	2.22	\$262.52
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/25/2024 09:30:00	01/25/2024 11:54:01	2.40	\$283.23
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/25/2024 13:00:29	01/25/2024 14:15:00	1.24	\$146.55
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11310047	01/25/2024 14:30:00	01/25/2024 15:50:35	1.34	\$158.48
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/29/2024 14:36:30	01/29/2024 15:54:13	1.30	\$152.84
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	11310047	01/30/2024 07:04:07	01/30/2024 11:53:51	4.83	\$569.81
03-40-419	REPLACE NEW OIL PAN/GASKET	11310047	01/30/2024 14:02:10	01/30/2024 15:55:04	1.88	\$222.04
03-51-038	REPLACE NEW WIPER BLADES	11310047	01/31/2024 06:59:56	01/31/2024 10:41:57	3.70	\$436.63
03-32-002	REPLACE NEW BATTERY	11310047	01/31/2024 10:41:57	01/31/2024 11:03:51	0.37	\$43.07
06-17-013	INSPECT ALIGNMENT	11310047	02/12/2024 10:20:03	02/12/2024 10:28:51	0.15	\$17.31
06-02-016	INSPECT TAIL&LIFT GATE	11310047	02/12/2024 10:28:51	02/12/2024 10:59:25	0.51	\$60.11
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOPS	11310047	02/12/2024 10:13:41	02/12/2024 10:20:03	0.11	\$12.52
66-13-130	PERFORM Burnish Brakes	11310047	02/09/2024 13:37:43	02/09/2024 14:15:00	0.62	\$73.32
66-13-130	PERFORM Burnish Brakes	11310047	02/09/2024 14:30:00	02/09/2024 15:52:41	1.38	\$162.61

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	02/09/2024 07:57:47	02/09/2024 09:15:00	1.29	\$151.86
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	02/09/2024 09:30:00	02/09/2024 11:00:00	1.50	\$177.00
03-15-029	REPLACE NEW STEERING STABILIZER	11310047	01/31/2024 13:19:30	01/31/2024 14:09:57	0.84	\$99.22
66-79-003	PERFORM SAFETY INSPECTION	11310047	01/31/2024 11:03:51	01/31/2024 11:23:50	0.33	\$39.30
66-17-017	PERFORM BALANCE TIRES	11310047	01/31/2024 11:23:50	01/31/2024 11:52:17	0.47	\$55.95
					<b>LABOR</b>	<b>4753.40</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-016	INSPECT TAIL&LIFT GATE	06133	ELECTRICAL TAPE 3M SUPER 33+	9.39	1	\$9.39
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	8	\$45.24
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	6.44	1	\$6.44
03-40-419	REPLACE NEW OIL PAN/GASKET	82180	ULTRA BLACK RTV	9.11	1	\$9.11
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	6.44	(1)	(\$6.44)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	6.42	2	\$12.84
03-32-002	REPLACE NEW BATTERY	651	BATTERY BCI 65 750CCA	199.98	1	\$199.98
03-40-419	REPLACE NEW OIL PAN/GASKET	PIGMAT	OIL ABSORMENT MAT	1.19	12	\$14.22
03-40-419	REPLACE NEW OIL PAN/GASKET	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	21.65	3	\$64.94
03-40-419	REPLACE NEW OIL PAN/GASKET	4 CLAMP	HOSE CLAMPS	0.68	2	\$1.35
66-17-017	PERFORM BALANCE TIRES	61130	LT1 .50 OZ WHEEL WEIGHT	0.68	4	\$2.70
66-17-017	PERFORM BALANCE TIRES	61131	LT1 1.00 OZ WHEEL WEIGHT	1.07	6	\$6.39
66-17-017	PERFORM BALANCE TIRES	61133	LT1 2.00 OZ WHEEL WEIGHT	1.77	4	\$7.08
03-40-419	REPLACE NEW OIL PAN/GASKET	5C3Z9L437AA	GASKET	10.76	1	\$10.76
03-40-419	REPLACE NEW OIL PAN/GASKET	F1AZ6626A	GASKET	6.00	1	\$6.00
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	W716805S442	NUT	11.55	1	\$11.55
03-15-029	REPLACE NEW STEERING STABILIZER	5C3Z18198AA	SHOCK ABSORBER	64.02	1	\$64.02
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	W716805S442	NUT	11.55	(1)	(\$11.55)
03-15-029	REPLACE NEW STEERING STABILIZER	W716805S442	NUT	11.55	1	\$11.55
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOPS	DC3Z3020A	FRONT BUM STOPS	32.21	2	\$64.41
03-15-029	REPLACE NEW STEERING STABILIZER	5C3Z3E651D	STEERING STABILIZER	97.71	1	\$97.71
35-30-005	DIAGNOSE LIFTGATE SWITCH	WPL2750	LIFTGATE SWITCH	229.40	1	\$229.40
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABSP1066TRH	BRAKE PADS	116.63	1	\$116.63
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB680374	REAR ROTORS	140.19	2	\$280.38

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-40-419	REPLACE NEW OIL PAN/GASKET	FELOS30710R	OIL PAN GASKET	61.86	1	\$61.86
03-16-006	REPLACE NEW REAR SHOCK ABSORBER	MON65168	REAR SHOCKS	149.51	2	\$299.01
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	AMA5276080	80W90 GEAR OIL FED	12.30	3	\$36.90
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOPS	DOR926555	REAR AXLE O-RING KIT	14.04	1	\$14.04
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	AMA5276080	80W90 GEAR OIL FED	12.30	3	\$36.90
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	CRS34928	OIL SEAL	68.04	2	\$136.08
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOPS	DC3Z3020A	FRONT BUM STOPS	32.21	(2)	(\$64.41)
03-16-028	REPLACE NEW FRONT/ REAR BUMP STOPS	DC3Z3020A	FRONT BUM STOPS	32.21	2	\$64.41
03-15-029	REPLACE NEW STEERING STABILIZER	5C3Z18198AA	SHOCK ABSORBER	64.02	(1)	(\$64.02)
03-15-029	REPLACE NEW STEERING STABILIZER	5C3Z18198AA	SHOCK ABSORBER	64.02	1	\$64.02
					<b>PARTS</b>	<b>1861.48</b>



# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **49479**

---

## Work Order Notes

(EHANNAH) pm- Front fend shakes hard when speeding up- Lift gate socket needs to be replaced or checked- Remotes are in black tote in back of truck- lift gate switch cover is broken

(EHANNAH) driver reports it makes noise at times when trying to crank it.

---

## Job Notes

# Work Order Charge Detail

## 03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) Removed axles and rear hubs. Removed the bolts to separate the rotor from the hub. Installed new rear brake rotors, wheel hub seals, and axle O-rings. Installed new rear brake pads and pad hardware. Drained and filled rear differential fluid. EH Add .3 HR for drain and fill.

## 03-15-029 - REPLACE NEW STEERING STABILIZER

(EHOWELL) Installed a new steering stabilizer. EH

## 03-16-006 - REPLACE NEW REAR SHOCK ABSORBER

(EHOWELL) Replaced rear shock absorbers. EH

## 03-16-028 - REPLACE NEW FRONT/ REAR BUMP STOPS

(IFALLS) Removed remains of old front bump stops and installed new ones. EH

## 03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Installed a new battery. The alternator is charging at 14 volts. EH

## 03-40-419 - REPLACE NEW OIL PAN/GASKET

(EHOWELL) Replaced oil pan gasket, oil pickup tube O-ring, and oil cooler O-ring. It was necessary to remove the throttle body adapter to raise the engine. Installed a new throttle body adapter gasket. Filled the engine with oil and installed a new oil filter. Filled cooling system with coolant. Ran the engine and verified that oil was no longer dripping on the ground. EH

## 03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL)

The following parts are included with the standard job:

Part No : 60-2040

Qty : 2

Description : WIPER BLADE

Manufacturer :

Bin :

(EHOWELL) Replaced wipers. EH

## 06-02-016 - INSPECT TAIL&LIFT GATE

(EHOWELL) One of the liftgate remotes was not functioning in both directions. Also, repaired the wall socket that the remote plugs into. We ordered a new remote, but it only operated in the down position. Removed the cover from the remote and used a multimeter to verify that the remote switch was faulty. The company sent us another remote and it done the same thing. As it turns out, the switch wire functions were wrong on the paper that the company sent with the new liftgate remote. Rewired remote and verified operation after repair. It appears, afterwards, that the old remote wasn't wired properly either. EH 1.0HR

## 06-17-013 - INSPECT ALIGNMENT

(EHOWELL) The vehicle had an alignment approximately 4440 miles ago. It probably does not need an alignment at this time. Also, some of the tires will need to be replaced in the near future, so the vehicle will need an alignment then. EH

## 06-32-010 - INSPECT STARTER

# Work Order Charge Detail

(EHOWELL) The starter motor is operating properly, and no abnormal noises have been noticed by the technician. Did not hear any abnormal noise from the AC compressor. EH

## 24-02 - REPAIR CAB & SHEET METAL

(EHOWELL) Cut out a piece of sheet metal and painted it. Installed sheet metal over the punctured location of the box and secured using four rivets. EH .5 HR

## 35-30-005 - DIAGNOSE LIFTGATE SWITCH

(EHOWELL) The liftgate switch housing was broken. Installed a new liftgate switch/housing assembly on the right rear of the vehicle. Verified operation after repair. EH .5 HR

## 66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made multiple hard stops after brake job was performed. EH

## 66-17-017 - PERFORM BALANCE TIRES

(EHOWELL) Performed a road test. The vehicle seemed to be shaking due to the tires being out of balance. Both LR tires were missing weights on the inside. RR tire did not have any weights on the outside of the rim. Balanced all six tires. Front tires were rotated side to side. EH

## 66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed Safety Inspection. EH

## 66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check FC

## CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 51332

<b>USING DEPT NO:</b>	504302	<b>OPENED DATE:</b>	06/27/2024 14:31:22	<b>LOCATION:</b>	GARAGE - University Automotive Services				
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	06/27/2024 14:35:56	<b>METER 1 - M:</b>	83309	<b>METER 2 - H:</b>	7927		
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	06/27/2024 14:36:30	<b>IN-SERVICE DATE:</b>	05/30/2005				
<b>TECH SPEC NO:</b>	05TKFORDF550	2005 Ford F550		<b>UNIT SERIAL NO:</b>	1FDAF56Y65ED25884				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-02-002	TRANSPORT FENDERS	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-02-002	REPAIR FENDERS	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-002	REPAIR FENDERS	11130159	8012		\$0.00
COMML					0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 51332

## Work Order Notes

(IFALLS) repair right front fender  
someone backed into the right front fender there insurance covered all repair cost

## Job Notes

### **16-02-002 - TRANSPORT FENDERS**

(IFALLS) chad performed transport

### **24-02-002 - REPAIR FENDERS**

(IFALLS) browns repaired per est. no cost  
other party covered all charges.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 51502

USING DEPT NO:	504302	OPENED DATE:	07/16/2024 15:35:33	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2024 14:04:05	METER 1 - M:	83562	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2024 08:29:30	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550							
			UNIT SERIAL NO:	1FDAF56Y65ED25884					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.03	\$3.25	\$0.00	\$0.00	\$3.25
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$729.27	\$0.00	\$729.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.11	\$0.00	\$0.00	\$1.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:					0.04	4.36	729.27	5.00	738.63
--------------	-------------------	--	--	--	--	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/17/2024 07:53:42	07/17/2024 07:54:16	0.01	\$1.11
06-15	INSPECT STEERING	12395904	07/17/2024 07:51:32	07/17/2024 07:53:11	0.03	\$3.25
LABOR						4.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	GL1173592195	TIRE 225/70R19.5 ZENNA AP250	232.50	3	\$697.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	61137	LT1 4.00 OZ WHEEL WEIGHT	3.26	1	\$3.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58127	2.00 OZ WHEEL WEIGHT	1.38	1	\$1.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGHT	0.84	1	\$0.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58126	1.75 OZ WHEEL WEIGHT	0.74	1	\$0.74
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58124	1.25 OZ WHEEL WEIGHT	0.60	1	\$0.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	7.89	3	\$23.67
PARTS						729.27

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 51502

## Work Order Notes

(EHANNAH) pm- adjust brakes- inspect steering- inspect ac

## Job Notes

**01-13 - ADJUST BRAKES**

**06-15 - INSPECT STEERING**

(FCONTRER) perform inspect esteering good

(GARAGE) also inspected steering and found no issues at this time-GC

**66-17-013 - PERFORM ALIGNMENT**

(GARAGE) Performed alignment. Made no adjustments. Test drove and everything is good. JAW

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) Mounted and Balanced 3 new tires on box truck unit 6031A, Put 2 new tires up front and rotated the front tires to the rear with the other new tire.-GC

**66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform fluid check FC

**CH-SP - CHARGE Shop Supplies**

Work Order Charge Detail

UNIT NO:		236106	2005 FORD F550				WORK ORDER NO:		51821			
USING DEPT NO:		504302	OPENED DATE:		08/15/2024 08:05:32		LOCATION: GARAGE - University Automotive Services					
WO STATUS:		CLOSED	COMPLETED DATE:		08/17/2024 08:57:12		METER 1 - M:		83893	METER 2 - H: 7927		
WO VISIT REASON:		SCHEDULED	CLOSED DATE:		08/17/2024 09:07:31		IN-SERVICE DATE:		05/30/2005			
TECH SPEC NO:		05TKFORDF550	2005 Ford F550				UNIT SERIAL NO:		1FDAF56Y65ED25884			
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
AD-PM-PMH		ADDED SERVICE HYD. FLUID AND FILT		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:						0.00	0.00	0.00	0.00	0.00



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 51821

## Work Order Notes

(EHANNAH) add oil - driver reports very low.

## Job Notes

AD-PM-PMH - ADDED SERVICE HYD. FLUID AND FILTER

(GARAGE) added a half quart of oil

GC\RC

(EKIMBREL) used charged out oil.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 52219

USING DEPT NO:	504302	OPENED DATE:	09/25/2024 08:33:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2024 10:51:10	METER 1 - M:	84459	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2024 11:10:41	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
AD-PM-PMH	ADDED SERVICE HYD. FLUID AND FILT	DON	P	N	GARAGE	0.00	\$0.00	\$8.33	\$0.00	\$8.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	8.33	5.00	13.33
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-PM-PMH	ADDED SERVICE HYD. FLUID AND FILTER	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.33	1	\$8.33
					PARTS	8.33

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 52219

## Work Order Notes

(EHANNAH) add fluid

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

AD-PM-PMH - ADDED SERVICE HYD. FLUID AND FILTER

(GARAGE) Vehicle was low on oil, added 1 quart of oil to unit 6031A-GC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 5265

USING DEPT NO:	504302	OPENED DATE:	02/11/2010 11:36:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/11/2010 13:39:26	METER 1 - M:	21121	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/11/2010 13:39:28	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$4.43	\$0.00	\$21.68

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	4.43	0.00	21.68
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11274660	02/11/2010 17:00:00	02/11/2010 17:18:00	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	GEB4157	TURN SIGNAL BULB/AMBER	4.43	1	\$4.43
					<b>PARTS</b>	<b>4.43</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 5265

---

## Work Order Notes

(LPATE) RIGHT FRONT TURN SIGNAL OUT

---

## Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED RIGHT FRONT TURN SIGNAL BULB

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 52924

USING DEPT NO:	504302	OPENED DATE:	11/27/2024 10:02:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2024 10:38:13	METER 1 - M:	85204	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 10:43:22	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	N	N	GARAGE	0.00	\$0.00	\$16.65	\$0.00	\$16.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	16.65	5.00	21.65
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.33	2	\$16.65
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.33	(1)	(\$8.33)
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.33	1	\$8.33
					PARTS	16.65

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 52924

## Work Order Notes

(EKIMBREL) low oil

## Job Notes

**AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&**

(GARAGE) added 1 1/2 quarts of oil to unit 6031A, unit was low on oil, also added a little bit of Lucas Oil Stabilizer that was in the flammable cabinet. oil level is good.-GC  
Miles, 85,204

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 53009

USING DEPT NO:	504302	OPENED DATE:	12/06/2024 08:54:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2024 10:54:58	METER 1 - M:	85204	METER 2 - H: 7927
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2024 12:11:24	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$189.75	\$189.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	194.75	194.75
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS55688		\$189.75
				COMML	194.75



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 53009

## Work Order Notes

(EHANNAH) Overhead door came out to repair the wire on the left side door wire coming off track.

## Job Notes

24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP

(EHOWELL) Overhead door came to our facility and adjusted the drum on the rollup door.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 53606

USING DEPT NO:	504302	OPENED DATE:	02/04/2025 08:13:24	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2025 12:48:02	METER 1 - M:	85721	METER 2 - H:	7927				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2025 14:18:35	IN-SERVICE DATE:	05/30/2005						
TECH SPEC NO:	05TKFORDF550	2005 Ford F550									
				UNIT SERIAL NO:	1FDAF56Y65ED25884						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-55-039	INSPECT LIFTGATE ASSY	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$78.66	\$0.00	\$78.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	78.66	5.00	83.66
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	9.09	8	\$72.72
PARTS						78.66

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 53606

## Work Order Notes

(EHANNAH) pm- wash- adjust brakes - inspect steering- SI

## Job Notes

**01-13 - ADJUST BRAKES**

**06-55-039 - INSPECT LIFTGATE ASSY**

(GARAGE) inspected greased and operated liftgate unit checked ok, cm

**66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) PERFORMED SI CM 85721 MILES, CHECKED over vehicle everything checked ok, brake pads were 10 mm or more

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- topside

JR- pit

perform PM, changed oil and filter, checked air filters, checked fluids, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid  
85721 miles

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 54112

USING DEPT NO:	504302	OPENED DATE:	03/24/2025 08:56:06	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2025 08:40:48	METER 1 - M:	86147	METER 2 - H:	7927		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/28/2025 07:48:21	IN-SERVICE DATE:	05/30/2005				
TECH SPEC NO:	05TKFORDF550	2005 Ford F550	UNIT SERIAL NO: 1FDAF56Y65ED25884						

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **54112**

---

## Work Order Notes

(EHANNAH) prep for sale

---

## Job Notes

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) PERFORMED DECOMMISSION PER PREP FOR SALE SHEET. CQ

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 5654

USING DEPT NO:	504302	OPENED DATE:	04/21/2010 07:38:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2010 09:40:05	METER 1 - M:	21091	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2010 09:40:07	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$38.01	\$0.00	\$52.39
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$34.87	\$0.00	\$52.70

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	32.21	72.88	0.00	105.09
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11046945	04/21/2010 17:00:00	04/21/2010 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11046945	04/21/2010 17:18:36	04/21/2010 17:33:36	0.25	\$14.38
					LABOR	32.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	MILS453	VALVE STEM EXTENSIONS	2.65	1	\$2.65
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.34	1	\$5.34
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	256	\$26.88
03-51-038	REPLACE NEW WIPER BLADES	60-2240	WIPER BLADE	19.01	2	\$38.01
					PARTS	72.88

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 5654

## Work Order Notes

(LPATE) PM-REPLACE WIPERS

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LPATE)

The following parts are included with the standard job:

Part No : 91-20  
Qty : 2  
Description : WIPER BLADE  
Manufacturer :

(LPATE) REPLACED WIPERS

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 51372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY BB

ADDED VALVE STEM EXTENSIONS TO REAR TIRES

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 6444

USING DEPT NO:	504302	OPENED DATE:	08/06/2010 15:40:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2010 07:08:14	METER 1 - M:	22410	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2010 07:08:17	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$10.29	\$29.71	\$0.00	\$40.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.18	10.29	29.71	0.00	40.00
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10230946	08/07/2010 10:00:56	08/07/2010 10:11:40	0.18	\$10.29
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10230946	08/07/2010 09:55:34	08/07/2010 10:00:43	0.09	\$4.93
					LABOR	15.22

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	240	\$25.20
					PARTS	29.71



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 6444

## Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER-LUBE LIFT GATE  
(LPATE) DID NOT REPLACE FUEL FILTER AT THIS TIME

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY JM/IF

### **66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT**

(LPATE) CANCELLED JOB DID NOT REPLACE FUEL FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 663

USING DEPT NO:	504302	OPENED DATE:	01/14/2008 11:30:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/15/2008 09:23:10	METER 1 - M:	9582	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/15/2008 09:23:12	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	0.00	\$0.19	\$0.00	\$0.00	\$0.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.23	\$30.98	\$0.00	\$31.20

JOB COUNT: 3	WORK ORDER TOTAL:	0.01	0.42	30.98	0.00	31.39
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-01-004	REPLACE NEW BLOWER MOTOR	11112000	MRCS107270	00770	\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11088474	01/14/2008 15:34:20	01/14/2008 15:34:35	0.00	\$0.19
66-PM-PMA	PERFORM OIL CHANGE	11088474	01/14/2008 11:54:00	01/14/2008 11:54:18	0.01	\$0.23
				LABOR		0.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.46	1	\$7.46
					PARTS	30.98

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 663

---

## Work Order Notes

(LOBRIEN) PM DUE AND BLOWER SWITCH ONLY WORK ON HIGH.

---

## Job Notes

### **03-01-004 - REPLACE NEW BLOWER MOTOR**

(RWINTERS) MADDEN REPLACED THE BLOWER RESISTOR.

### **16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT**

(LOBRIEN) TAKEN TO MADDEN.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LOBRIEN) PM BY JASON ELMORE.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 6769

USING DEPT NO:	504302	OPENED DATE:	09/15/2010 07:25:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/15/2010 14:22:23	METER 1 - M:	22908	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/15/2010 14:22:25	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-55-028	REPLACE NEW MASTER CONTROL SW	DON	O	N	GARAGE	2.59	\$148.84	\$280.62	\$0.00	\$429.46

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>2.59</b>	<b>148.84</b>	<b>280.62</b>	<b>0.00</b>	<b>429.46</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-55-028	REPLACE NEW MASTER CONTROL SWITCH	11274660	09/15/2010 11:25:38	09/15/2010 14:00:57	2.59	\$148.84
					<b>LABOR</b>	<b>148.84</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-55-028	REPLACE NEW MASTER CONTROL SWITCH	SHIPPING	SHIPPING AND HANDLING	16.11	1	\$16.11
03-55-028	REPLACE NEW MASTER CONTROL SWITCH	MS264346	LIFTGATE SWITCH	132.26	2	\$264.51
03-55-028	REPLACE NEW MASTER CONTROL SWITCH	SHIPPING	SHIPPING AND HANDLING	16.11	(1)	(\$16.11)
03-55-028	REPLACE NEW MASTER CONTROL SWITCH	SHIPPING	SHIPPING AND HANDLING	16.11	1	\$16.11
					<b>PARTS</b>	<b>280.62</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **6769**

---

## Work Order Notes

(RWINTERS) LIFTGATE SWITCH INOP

---

## Job Notes

**03-55-028 - REPLACE NEW MASTER CONTROL SWITCH**

(LPATE) INSTALLED NEW LIFTGATE SWITCH AND GAVE DRIVER EXTRA TO KEEP IN DASH IN CASE GOES BAD AGAIN IN FUTURE WILL NOT HAVE TO SPECIAL ORDER AND WAIT

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 7263

USING DEPT NO:	504302	OPENED DATE:	12/02/2010 07:04:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/03/2010 13:08:44	METER 1 - M:	23694	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/03/2010 13:08:47	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$45.82	\$45.36	\$0.00	\$91.18

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.80</b>	<b>45.82</b>	<b>45.36</b>	<b>0.00</b>	<b>91.18</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10230946	12/02/2010 08:27:11	12/02/2010 09:15:00	0.80	\$45.82
					<b>LABOR</b>	<b>45.82</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	240	\$25.20
66-PM-PMA	PERFORM OIL CHANGE	9136	AIR FILTER	15.65	1	\$15.65
					<b>PARTS</b>	<b>45.36</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 7263

## Work Order Notes

(RWINTERS) PM, GREASE AND LUBE LIFTGATE

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

The following parts are included with the standard job:

Part No : 1198  
Qty : 1  
Description : OIL DRAIN PLUG FORD  
Manufacturer :

Part No : 1372  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

Part No : 5W20  
Qty : 224  
Description : OIL BOTTLE  
Manufacturer :

(LPATE) PM BY RS/JM/TM-REPLACED AIR FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 7312

USING DEPT NO:	504302	OPENED DATE:	12/08/2010 08:06:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2010 07:45:23	METER 1 - M:	23720	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2010 07:45:25	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

<b>JOB COUNT: 2</b>	<b>WORK ORDER TOTAL:</b>					<b>1.50</b>	<b>86.25</b>	<b>0.00</b>	<b>0.00</b>	<b>86.25</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11328035	12/08/2010 17:00:00	12/08/2010 18:00:00	1.00	\$57.50
15-32-002	WARRANTY BATTERY	11328035	12/08/2010 18:00:00	12/08/2010 18:30:00	0.50	\$28.75
					<b>LABOR</b>	<b>86.25</b>



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 7312

## Work Order Notes

(LPATE) SHANE REQUESTED SVC CALL FOR DEAD BATTERY AFTER LEAVING FLASHERS ON FOR 30 MIN

## Job Notes

### **15-32-002 - WARRANTY BATTERY**

(LPATE) REPLACED BATTERY AS WARRANTY INSTALLED 10/7/09-TRIED TO CHARGE AND PUT OLD BATTERY BACK IN WENT RIGHT BACK DEAD OVER NIGHT.

REPLACED BATTERY CHECKED ALTERNATOR CHARGING OK.

(LPATE) Visit Reason Changed On 12/8/2010 8:09:31 AM By LPATE

### **66-79-002 - PERFORM SERVICE CALL**

(LPATE) SVC CALL TO FOSTER AUDITORIUM FOR DEAD BATTERY-INSTALLED BATTERY 65-6 WARRANTY WAS REPLACED 10/7/09

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 7774

USING DEPT NO:	504302	OPENED DATE:	02/18/2011 09:47:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/21/2011 10:15:02	METER 1 - M:	24201	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2011 10:15:03	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-55-012	INSTALL CARGO RESTRAINTS	DON	O	N	GARAGE	1.00	\$57.50	\$43.69	\$0.00	\$101.19

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>1.00</b>	<b>57.50</b>	<b>43.69</b>	<b>0.00</b>	<b>101.19</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-55-012	INSTALL CARGO RESTRAINTS	11328035	02/18/2011 17:00:00	02/18/2011 18:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-55-012	INSTALL CARGO RESTRAINTS	HET8P	8' HORIZONTAL E-TRACK PAINTED	24.73	1	\$24.73
14-55-012	INSTALL CARGO RESTRAINTS	HET5P	8' HORIZONTAL E-TRACK PAINTED	24.73	(1)	(\$24.73)
14-55-012	INSTALL CARGO RESTRAINTS	BOX SCREWS	MISC SCREWS	8.99	1	\$8.99
14-55-012	INSTALL CARGO RESTRAINTS	SCREWS	SELF TAPING SCREWS	0.52	19	\$9.97
14-55-012	INSTALL CARGO RESTRAINTS	HET5P	8' HORIZONTAL E-TRACK PAINTED	24.73	1	\$24.73
					<b>PARTS</b>	<b>43.69</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                **236106**                **2005 FORD F550**

**WORK ORDER NO:**        **7774**

---

## Work Order Notes

(LPATE) INSTALL E-TRACK AND GIVE DRIVE CARGO STRAPS

---

## Job Notes

**14-55-012 - INSTALL CARGO RESTRAINTS**

(LPATE) INSTALLED E-TRACK IN BACK OF TRUCK FOR STRAPPING OBJECTS WHILE MOVING THEM.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 8802

USING DEPT NO:	504302	OPENED DATE:	07/27/2011 15:09:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2011 14:37:47	METER 1 - M:	26213	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2011 14:37:49	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$5.77	\$33.48	\$0.00	\$39.25

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.10</b>	<b>5.77</b>	<b>33.48</b>	<b>0.00</b>	<b>39.25</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	07/27/2011 15:35:42	07/27/2011 15:41:43	0.10	\$5.77
					<b>LABOR</b>	<b>5.77</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.68	1	\$4.68
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	240	\$28.80
					<b>PARTS</b>	<b>33.48</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 8802

## Work Order Notes

(LPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 1198 OIL DRAIN PLUG FORD Qty 1 Cost 0

Part 1372 FILTER-OIL Qty 1 Cost 0

Part 5W20 OIL BOTTLE Qty 224 Cost 0

(LPATE) PM BY RS/TM

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9268

USING DEPT NO:	504302	OPENED DATE:	09/29/2011 10:50:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2011 11:15:34	METER 1 - M:	26860	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2011 11:15:36	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11338644	09/29/2011 17:00:00	09/29/2011 18:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9268

## Work Order Notes

(LPATE) DRIVER LEFT FLASHERS ON WHILE PARKED IN ROAD. REQUESTED SVC CALL FOR DEAD BATTERY.

## Job Notes

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL TO HARDAWAY HALL JUMPED OFF TRUCK FOR DRIVER.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9659

USING DEPT NO:	504302	OPENED DATE:	11/10/2011 15:46:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2011 09:42:38	METER 1 - M:	27429	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2011 09:42:39	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.50	86.25	0.00	0.00	86.25
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11413680	11/10/2011 18:00:00	11/10/2011 18:30:00	0.50	\$28.75
66-79-002	PERFORM SERVICE CALL	11413680	11/10/2011 17:00:00	11/10/2011 18:00:00	1.00	\$57.50
					LABOR	86.25



# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9659

## Work Order Notes

(RWINTERS) DEAD BATTERY AT BIDGOOD HALL

## Job Notes

**66-79-002 - PERFORM SERVICE CALL**

(LPATE) SVC CALL TO BIDGOOD HALL FOR DEAD BATTERY

**CH-32-002 - CHARGE BATTERY**

(LPATE) INSTALLED BATTERY IN TRUCK WHILE BRINGING BATTERY TO GARAGE TO BE CHARGED. AFTER CHARGED AND CHECKED OK REINSTALLED IN TRUCK.

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9702

USING DEPT NO:	504302	OPENED DATE:	11/16/2011 08:09:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2011 15:54:31	METER 1 - M:	27525	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2011 15:54:33	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	0.00	0.00	17.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11074414	11/16/2011 17:00:00	11/16/2011 17:18:00	0.30	\$17.25
					<b>LABOR</b>	<b>17.25</b>

# Work Order Charge Detail

*The University of Alabama*

*Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI*

**UNIT NO:**                    **236106**                    **2005 FORD F550**

**WORK ORDER NO:**                    **9702**

---

**Work Order Notes**

(LPATE) SHANE REQUESTED SERVICE CALL TO ASB LOADING DOCK FOR DEAD BATTERY

---

**Job Notes**

**66-79-002 - PERFORM SERVICE CALL**

(LPATE) JUMPED OFF RUNNING OK. DRIVER WILL DRIVE TO RECHARGE BATTERY

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9913

USING DEPT NO:	504302	OPENED DATE:	12/19/2011 07:45:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2011 13:03:13	METER 1 - M:	27793	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2011 13:03:14	IN-SERVICE DATE:	05/30/2005	
TECH SPEC NO:	05TKFORDF550	2005 Ford F550		UNIT SERIAL NO:	1FDAF56Y65ED25884	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11413680	12/19/2011 17:00:00	12/19/2011 18:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 04/14/2025 12:28:12 By User: GLOBETTI

UNIT NO: 236106 2005 FORD F550

WORK ORDER NO: 9913

## Work Order Notes

(LPATE) SHANE REQUESTED SERVICE CALL TO BEVILL HALL FOR DEAD BATTERY

## Job Notes

66-79-002 - PERFORM SERVICE CALL

(LPATE) FLASHERS WERE LEFT ON. JUMPED TRUCK OFF, CHECKED ALTERNATOR CHARGING OK.

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon Apr 14 2025 12:28:12 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '236106') //Q=