

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 28238

USING DEPT NO:	209317	OPENED DATE:	11/22/2017 15:07:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2017 06:51:39	METER 1 - M:	164	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/27/2017 06:51:40	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	11/22/2017 15:08:19	11/22/2017 15:38:19	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: **242550** **2018 TOYOTA CAMRY**

WORK ORDER NO: **28238**

Work Order Notes

(IFALLS) PERFORM NEW UNIT INSPECTION

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(IFALLS) AB PERFORMED INSPECTION

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 29185

USING DEPT NO:	209317	OPENED DATE:	03/23/2018 15:37:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/30/2018 07:32:36	METER 1 - M:	5315	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/30/2018 07:32:38	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.19	\$0.00	\$51.02

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	33.19	0.00	51.02
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/26/2018 07:00:00	03/26/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.54	5	\$27.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.49	1	\$5.49
					PARTS	33.19

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 29185

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30337

USING DEPT NO:	209317	OPENED DATE:	07/23/2018 15:07:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2018 10:40:20	METER 1 - M:	9362	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2018 10:40:22	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$33.61	\$0.00	\$33.61

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	0.00	33.61	0.00	33.61
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/24/2018 07:00:00	07/24/2018 07:18:36	0.31	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.41	1	\$5.41
					PARTS	33.61

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30337

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS,SH/AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30484

USING DEPT NO:	209317	OPENED DATE:	08/06/2018 15:21:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2018 07:51:47	METER 1 - M:	9394	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2018 07:51:49	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CL-32-007	CLEANED CLEAN TERMINAL(S)	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	2.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	09/19/2018 07:00:00	09/19/2018 09:00:00	2.00	\$0.00
CL-32-007	CLEANED CLEAN TERMINAL(S)	11901357	09/19/2018 07:00:00	09/19/2018 07:30:00	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30484

Work Order Notes

(LISAPATE) WOULD NOT CRANK THIS MORNING-BUT CRANKED THIS AFTERNOON-CHECK ENGINE LIGHT ON NOW-STEADY-RUNNING OK

Job Notes

CL-32-007 - CLEANED CLEAN TERMINAL(S)

(LISAPATE) Cleaned battery terminals and posts, checked charging system, good at 13.9 volts

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out OTC- Engine light never came on. Vehicle did have a long crank 1 time. Inspected engine harness for chewed wires and found none. Test drove multiple time. Used as a chase vehicle for several days, could not duplicate

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30927

USING DEPT NO:	209317	OPENED DATE:	09/24/2018 08:40:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2018 07:15:52	METER 1 - M:	13969	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2018 07:15:57	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$0.00	\$33.74	\$0.00	\$33.74

JOB COUNT: 1	WORK ORDER TOTAL:	0.53	0.00	33.74	0.00	33.74
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/24/2018 13:28:01	09/24/2018 14:00:00	0.53	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.67	5	\$28.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.39	1	\$5.39
					PARTS	33.74

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 30927

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 9/24/2018 8:41 AM By LISAPATE

(LISAPATE) PM by SH

Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 31585

USING DEPT NO:	209317	OPENED DATE:	11/29/2018 09:56:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2018 06:43:04	METER 1 - M:	18869	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/30/2018 06:43:06	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.11	\$0.00	\$17.06	\$0.00	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$0.00	\$33.98	\$0.00	\$33.98

JOB COUNT: 2	WORK ORDER TOTAL:	0.48	0.00	51.04	0.00	51.04
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/29/2018 10:42:55	11/29/2018 10:49:16	0.11	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/29/2018 10:20:28	11/29/2018 10:42:39	0.37	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.72	5	\$28.60
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.38	1	\$5.38
					PARTS	51.04

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 31585

Work Order Notes

(LISAPATE) PM-Low tire pressure light is on

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 32032

USING DEPT NO:	209317	OPENED DATE:	01/25/2019 11:08:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/11/2019 11:20:57	METER 1 - M:	19640	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/11/2019 11:20:58	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	2.58	\$0.00	\$0.00	\$0.00	\$0.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,197.50	\$1,197.50

JOB COUNT: 2	WORK ORDER TOTAL:	2.58	0.00	0.00	1,197.50	1,197.50
--------------	-------------------	------	------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	167091	0046813	\$0.00
24-71	REPAIR BODY	11150605	167092	0046814	\$1,197.50
COMML					1197.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	01/30/2019 09:11:47	01/30/2019 09:15:00	0.05	\$0.00
16-71	TRANSPORT BODY	10208562	01/30/2019 09:30:00	01/30/2019 12:00:00	2.50	\$0.00
16-71	TRANSPORT BODY	10208562	01/30/2019 13:00:00	01/30/2019 13:01:49	0.03	\$0.00
LABOR						0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 32032

Work Order Notes

(LISAPATE) Take to Andrews to repair rear bumper damage. Progressive Insurance will pay damage to rear bumper. Dept will pay for damage to left door

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71 - REPAIR BODY

(LISAPATE) UA paid \$1197.50

Progressive issued check to Andrews for \$820.37 Claim# 19-1700571-02 Progressive Check # 2024860794 1/30/19.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 32416

USING DEPT NO:	209317	OPENED DATE:	03/20/2019 15:05:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2019 11:13:37	METER 1 - M:	23994	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2019 11:13:38	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.96	\$0.00	\$33.53	\$0.00	\$33.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.96	0.00	33.53	0.00	33.53
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/21/2019 09:06:23	03/21/2019 10:04:08	0.96	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.75	5	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.78	1	\$4.78
					PARTS	33.53

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 32416

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 33195

USING DEPT NO:	209317	OPENED DATE:	06/20/2019 09:34:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/24/2019 10:06:40	METER 1 - M:	28535	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/24/2019 10:06:41	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	1.01	\$0.00	\$5.26	\$0.00	\$5.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$0.00	\$50.69	\$0.00	\$50.69

JOB COUNT: 3	WORK ORDER TOTAL:	1.83	0.00	55.95	0.00	55.95
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	06/21/2019 08:09:14	06/21/2019 09:00:00	0.85	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/21/2019 10:41:06	06/21/2019 10:41:10	0.00	\$0.00
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	06/21/2019 06:00:00	06/21/2019 06:30:00	0.50	\$0.00
66-17-030	PERFORM TIRE PATCH	11074414	06/21/2019 07:11:05	06/21/2019 07:20:39	0.16	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/20/2019 11:33:34	06/20/2019 11:52:56	0.32	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.46	1	\$4.46
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.97	5	\$19.85
66-PM-PMA	PERFORM OIL CHANGE	17801F0050	AIR FILTER 2018 CAMRY	22.17	1	\$22.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	2.20	1	\$2.20
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.28	1	\$0.28
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	11	\$0.44
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
					PARTS	55.95

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 33195

Work Order Notes

(LISAPATE) PM--tire light on-scrubbing noise around LR wheel from trim

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) Rotated tires

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Patched LR tire from the inside. Found trim loose at bottom of LR wheel well secured with a nut, bolt and washer

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Replaced air filter

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 34224

USING DEPT NO:	209317	OPENED DATE:	09/24/2019 08:29:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2019 14:38:12	METER 1 - M:	33350	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2019 14:38:14	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$0.00	\$32.44	\$0.00	\$32.44

JOB COUNT: 1 WORK ORDER TOTAL: 0.58 0.00 32.44 0.00 32.44

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/24/2019 08:35:44	09/24/2019 09:10:42	0.58	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.90	5	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.36	1	\$4.36
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	(1)	(\$4.29)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	2	\$8.58
					PARTS	32.44

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: **242550** **2018 TOYOTA CAMRY**

WORK ORDER NO: **34224**

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC/JW. Coolant -34

JW found oil plug leaking due to not having a gasket on it. Added a new gasket to the plug and cleaned the undercarriage. Found no other issues.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 34792

USING DEPT NO:	209317	OPENED DATE:	11/08/2019 10:33:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2019 08:43:27	METER 1 - M:	37884	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2019 08:43:28	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$0.00	\$23.80	\$0.00	\$23.80

JOB COUNT: 1	WORK ORDER TOTAL:	0.15	0.00	23.80	0.00	23.80
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/08/2019 14:30:00	11/08/2019 14:39:00	0.15	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/08/2019 14:17:52	11/08/2019 14:17:52	0.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.35	1	\$4.35
					PARTS	23.80

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 34792

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/SH

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 35680

USING DEPT NO:	209317	OPENED DATE:	02/17/2020 14:32:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2020 06:33:26	METER 1 - M:	43360	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2020 06:33:27	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$0.00	\$26.38	\$0.00	\$26.38

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	0.00	26.38	0.00	26.38
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/17/2020 14:47:41	02/17/2020 15:17:53	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/17/2020 14:48:07	02/17/2020 15:17:39	0.49	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	4.41	5	\$22.05
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					PARTS	26.38

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 35680

Work Order Notes

(RTUNAITI) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/SH. coolant -25

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 37679

USING DEPT NO:	209317	OPENED DATE:	09/22/2020 09:11:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2020 14:28:36	METER 1 - M:	45724	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2020 10:07:23	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.78	\$0.00	\$23.83	\$0.00	\$23.83

JOB COUNT: 1	WORK ORDER TOTAL:	0.78	0.00	23.83	0.00	23.83
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/22/2020 13:00:00	09/22/2020 13:26:26	0.44	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/22/2020 12:59:05	09/22/2020 12:59:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/22/2020 13:00:00	09/22/2020 13:20:32	0.34	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/22/2020 12:55:02	09/22/2020 12:55:02	0.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.90	5	\$19.50
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					PARTS	23.83

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 37679

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) PM topside Josh assisted, Josh was bottom side. Completed checklist. AMG JW

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 38180

USING DEPT NO:	209317	OPENED DATE:	10/27/2020 15:48:12	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/30/2020 09:37:43	METER 1 - M:	45724	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2020 09:48:10	IN-SERVICE DATE:	11/20/2017						
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry									
			UNIT SERIAL NO:	4T1B11HK9JU038527							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.88	\$103.61	\$0.00	\$0.00	\$103.61
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.25	\$29.63	\$247.97	\$0.00	\$277.60
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.34	\$39.69	\$0.00	\$0.00	\$39.69

JOB COUNT: 4	WORK ORDER TOTAL:					1.67	196.53	247.97	0.00	444.50
--------------	-------------------	--	--	--	--	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11170580	10/29/2020 10:39:23	10/29/2020 10:54:27	0.25	\$29.63
66-79-002	PERFORM SERVICE CALL	11170580	10/29/2020 10:54:54	10/29/2020 11:15:05	0.34	\$39.69
06-15	INSPECT STEERING	11310047	10/30/2020 07:00:00	10/30/2020 07:12:00	0.20	\$23.60
09-15	ALIGN STEERING	11310047	10/29/2020 07:23:44	10/29/2020 08:16:25	0.88	\$103.61
					LABOR	196.53

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	240.63	1	\$240.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	C111	RED BRAKE CLEANER	3.36	1	\$3.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	11	\$0.66
					PARTS	247.97

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 38180

Work Order Notes

(LISAPATE) Lindsey hit a curb has a flat tire at Circle K on Univ Blvd

Job Notes

06-15 - INSPECT STEERING

(GARAGE) Checked front end. No issues found. EH

09-15 - ALIGN STEERING

(GARAGE) Performed 4 Wheel Alignment. Reset steering angle sensor using code link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(ABLACK) AB mounted and balanced 1 tire for the left front.

66-79-002 - PERFORM SERVICE CALL

(ABLACK) AB and EK performed service call. Put spare on vehicle and drove back to the shop to have new tire put on.

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 38914

USING DEPT NO:	209317	OPENED DATE:	01/26/2021 11:15:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2021 14:35:20	METER 1 - M:	45920	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2021 08:01:38	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.41	\$0.00	\$0.00	\$54.41

JOB COUNT: 1	WORK ORDER TOTAL:	0.46	54.41	0.00	0.00	54.41
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2021 09:30:00	01/27/2021 09:54:02	0.40	\$47.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2021 09:11:22	01/27/2021 09:15:00	0.06	\$7.15
					LABOR	54.42

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 38914

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 45920. Vehicle has been driven 196 miles since last oil change. Checked fluids battery tire pressure and updated oil change sticker. Washed and vacuumed was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 39946

USING DEPT NO:	209317	OPENED DATE:	05/13/2021 15:22:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2021 13:13:45	METER 1 - M:	48519	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	05/20/2021 11:52:38	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	O	N	GARAGE	0.43	\$50.51	\$244.65	\$0.00	\$295.16

JOB COUNT: 1	WORK ORDER TOTAL:	0.43	50.51	244.65	0.00	295.16
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	12052187	05/14/2021 07:43:25	05/14/2021 08:09:06	0.43	\$50.51
					LABOR	50.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	240.63	1	\$240.63
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	1	\$0.48
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	4	\$0.24
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	1	\$3.30
					PARTS	244.65

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 39946

Work Order Notes

(LISAPATE) replace right rear tire is damaged

Job Notes

03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced RR tire with new. Aired and balanced. Torqued all lugs to spec. JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 40031

USING DEPT NO:	209317	OPENED DATE:	05/26/2021 09:30:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2021 07:35:57	METER 1 - M:	49284	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2021 07:34:30	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.80	\$13.28	\$0.00	\$25.08
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.27	\$31.79	\$0.00	\$0.00	\$31.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.27	\$149.73	\$65.40	\$0.00	\$215.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.10	\$11.80	\$11.06	\$0.00	\$22.86

JOB COUNT: 4	WORK ORDER TOTAL:	1.74	205.12	89.74	0.00	294.86
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/27/2021 08:32:07	05/27/2021 09:06:34	0.57	\$67.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/27/2021 08:36:17	05/27/2021 09:15:00	0.65	\$76.14
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/27/2021 09:17:07	05/27/2021 09:23:07	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/27/2021 09:17:07	05/27/2021 09:17:07	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/27/2021 09:17:07	05/27/2021 09:17:07	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/27/2021 09:18:09	05/27/2021 09:24:09	0.10	\$11.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/27/2021 09:18:09	05/27/2021 09:18:09	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/27/2021 09:18:09	05/27/2021 09:18:09	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/27/2021 09:52:43	05/27/2021 10:08:53	0.27	\$31.79
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/26/2021 15:09:43	05/26/2021 15:12:41	0.05	\$5.83
					LABOR	205.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.82	5	\$29.10
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	17801F0050	AIR FILTER 2018 CAMRY	29.79	1	\$29.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	17801F0050	AIR FILTER 2018 CAMRY	29.79	(1)	(\$29.79)
66-PM-PMA	PERFORM OIL CHANGE	17801F0050	AIR FILTER 2018 CAMRY	29.79	1	\$29.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	11.06	1	\$11.06

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	6.14	1	\$6.14
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.14	1	\$7.14
					PARTS	89.74

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 40031

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers due to normal wear. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires inspected brakes washed and filled with gas. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 49284. SH/AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 40176

USING DEPT NO:	209317	OPENED DATE:	06/15/2021 08:23:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:31:11	METER 1 - M:	49285	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 14:31:14	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	B	N	GARAGE	0.38	\$45.04	\$244.47	\$0.00	\$289.51

JOB COUNT: 1	WORK ORDER TOTAL:	0.38	45.04	244.47	0.00	289.51
--------------	-------------------	------	-------	--------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	06/15/2021 14:28:02	06/15/2021 14:28:02	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11901357	06/15/2021 14:28:02	06/15/2021 14:28:02	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	06/15/2021 13:52:06	06/15/2021 14:15:00	0.38	\$45.04
					LABOR	45.04

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	240.63	1	\$240.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	1	\$3.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	9	\$0.54
					PARTS	244.47

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 40176

Work Order Notes

(LISAPATE) Per driver had a flat yesterday. Spare tire is on. Vehicle is parked in the circle at Univ Hall
(IFALLS) Department dropped vehicle off at AS for repair.

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) miles: 49405 Replaced and balanced R/R tire. AMG

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) Damage to close to sidewall tire needs replacing. AMG

66-79-002 - PERFORM SERVICE CALL

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 41280

USING DEPT NO:	209317	OPENED DATE:	10/11/2021 09:26:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2021 15:14:00	METER 1 - M:	52059	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2021 09:14:02	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.02	\$17.90	\$0.00	\$22.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.39	\$44.89	\$0.00	\$73.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.28	33.41	62.79	2.00	98.20
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/11/2021 14:54:46	10/11/2021 15:09:12	0.24	\$28.39
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/11/2021 14:52:04	10/11/2021 14:54:37	0.04	\$5.02
					LABOR	33.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.13	5	\$35.63
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.26	1	\$9.26
					PARTS	62.79

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 41280

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/EH
MILEAGE-52059

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 42635

USING DEPT NO:	209317	OPENED DATE:	03/10/2022 09:14:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2022 13:53:01	METER 1 - M:	57788	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/11/2022 08:05:19	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.11	\$17.90	\$0.00	\$21.01
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.40	\$39.00	\$0.00	\$76.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.51	56.90	2.00	99.41
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/10/2022 09:30:00	03/10/2022 09:49:01	0.32	\$37.40
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/10/2022 09:27:31	03/10/2022 09:27:31	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/10/2022 09:49:11	03/10/2022 09:50:46	0.03	\$3.11
				LABOR		40.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.40	1	\$5.40
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
				PARTS		56.90

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 42635

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH,AMG/JAW
MILEAGE-57788

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 43664

USING DEPT NO:	209317	OPENED DATE:	06/15/2022 09:45:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/15/2022 14:39:47	METER 1 - M:	61786	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2022 15:14:42	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.04	\$43.52	\$0.00	\$64.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.18	21.04	43.52	2.00	66.56
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/15/2022 14:30:00	06/15/2022 14:31:26	0.02	\$2.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/15/2022 14:05:44	06/15/2022 14:15:00	0.15	\$18.22
				LABOR		21.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.17	1	\$6.17
					PARTS	43.52

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 43664

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/AMG Performed PM. Needs 2 rear tires LR is at 3/32 and the RR has a gash in the side wall. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 43671

USING DEPT NO:	209317	OPENED DATE:	06/15/2022 14:40:07	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/24/2022 13:47:50	METER 1 - M:	61786	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2022 15:32:03	IN-SERVICE DATE:	11/20/2017						
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry									
			UNIT SERIAL NO:	4T1B11HK9JU038527							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$14.39	\$0.00	\$0.00	\$14.39
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.64	\$75.65	\$0.00	\$0.00	\$75.65
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.88	\$104.10	\$342.56	\$0.00	\$446.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.65	194.14	342.56	2.00	538.70
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11074414	06/15/2022 14:57:16	06/15/2022 15:04:35	0.12	\$14.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	06/21/2022 07:37:48	06/21/2022 08:30:44	0.88	\$104.10
66-17-013	PERFORM ALIGNMENT	11310047	06/22/2022 10:04:25	06/22/2022 10:42:53	0.64	\$75.65
					LABOR	194.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	5	\$0.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	2	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.52	2	\$11.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000219	TIRE BSTONE ECOPIA 215/55R17	165.06	2	\$330.12
					PARTS	342.56

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 43671

Work Order Notes

(EKIMBREL) INSPECT STEERING, 2 TIRES, ALIGNMENT

Job Notes

06-15 - INSPECT STEERING

(HHARBIN) Inspected steering found no issues at this time. SH AMG

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(HHARBIN) SH Mounted and AMG balanced 2 tires. Put the new tires on the front. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 44920

USING DEPT NO:	209317	OPENED DATE:	10/07/2022 14:32:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2022 15:17:46	METER 1 - M:	63193	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2022 07:23:15	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.27	\$0.00	\$0.00	\$23.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	23.27	0.00	5.00	28.27
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/10/2022 07:27:42	10/10/2022 07:39:32	0.20	\$23.27
					LABOR	23.27

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 44920

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1407 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-63193

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 46134

USING DEPT NO:	209317	OPENED DATE:	02/13/2023 15:26:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2023 09:58:32	METER 1 - M:	63497	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/16/2023 10:51:06	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.61	\$23.26	\$0.00	\$26.87
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.51	\$59.59	\$0.00	\$0.00	\$59.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.28	\$33.40	\$65.73	\$0.00	\$99.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$2.95	\$22.73	\$0.00	\$25.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.84	99.55	111.72	5.00	216.27
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	02/14/2023 10:58:47	02/14/2023 11:00:37	0.03	\$3.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	02/14/2023 10:56:55	02/14/2023 10:58:25	0.03	\$2.95
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/14/2023 10:39:37	02/14/2023 10:56:36	0.28	\$33.40
66-79-003	PERFORM SAFETY INSPECTION	12201267	02/14/2023 11:02:24	02/14/2023 11:32:42	0.51	\$59.59
				LABOR		99.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	11.94	5	\$59.70
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.03	1	\$6.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
				PARTS		111.72

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 46134

Work Order Notes

(EHANNAH) pm- replace wipers- perform safety inspections

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers- CW

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection-GC

Found no issues at this time, Brake pads- LF-7mm, RF-7mm, LR-7mm, RR-7mm

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- CW-GC, changed oil and oil filter, checked fluids, tires, and tire pressure.

Miles, 63,497

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced cabin filter-CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 47689

USING DEPT NO:	209317	OPENED DATE:	07/21/2023 08:43:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2023 14:28:58	METER 1 - M:	63809	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2023 14:29:01	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.90	\$0.00	\$0.00	\$19.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.44	\$51.89	\$0.00	\$0.00	\$51.89

JOB COUNT: 3	WORK ORDER TOTAL:	0.61	71.79	0.00	5.00	76.79
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	07/21/2023 15:00:56	07/21/2023 15:27:19	0.44	\$51.89
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/21/2023 14:50:49	07/21/2023 15:00:56	0.17	\$19.90
					LABOR	71.79

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 47689

Work Order Notes

(LISAPATE) PM-replace wipers-wash
(EKIMBREL) DID NOT NEED WIPERS YET

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Vehicle has been driven 996 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 48958

USING DEPT NO:	209317	OPENED DATE:	11/14/2023 13:20:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2023 14:00:21	METER 1 - M:	65437	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2023 15:39:32	IN-SERVICE DATE:	11/20/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK9JU038527	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.42	\$167.07	\$0.00	\$0.00	\$167.07

JOB COUNT: 2	WORK ORDER TOTAL:	1.42	167.07	0.00	5.00	172.07
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	11/16/2023 09:30:00	11/16/2023 10:44:18	1.24	\$146.12
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	11/16/2023 09:04:21	11/16/2023 09:15:00	0.18	\$20.95
					LABOR	167.07

Work Order Charge Detail

The University of Alabama

Report Printed: 11/17/2023 15:46:41 By User: GLOBETTI

UNIT NO: 242550 2018 TOYOTA CAMRY

WORK ORDER NO: 48958

Work Order Notes

(EHANNAH) Prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag RC
millage 65437

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Nov 17 2023 15:46:41 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242550') //Q=