The University of Alabama

Work Order Charge Detail

240682

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

LABOR

17629

UNIT NO: 2014 FORD E350 **WORK ORDER NO: USING DEPT NO:** 504131 **OPENED DATE:** 07/25/2014 07:49:58 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 07/25/2014 08:49:17 **COMPLETED DATE:** METER 1 - M: 237 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 07/25/2014 08:49:19 **IN-SERVICE DATE: CLOSED DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905

COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION STAT PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE DON С **GARAGE** 0.50 \$28.75 \$0.00 \$0.00 \$28.75 JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** PS-00-001 PREP SERVICE NEW UNIT IN-SERVICE INSPECTION 10260422 07/25/2014 07:50:44 07/25/2014 08:20:44 0.50 \$28.75

28.75

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 17629

Work Order Notes

(LPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETE-AFTERMARKET ALREADY INSTALLED UPON DELIVERY WAS A ROOF MOUNT LADDER RACK

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

240682 **UNIT NO:** 2014 FORD E350 **WORK ORDER NO:** 17879 **USING DEPT NO:** 504131 OPENED DATE: 08/25/2014 07:29:55 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 08/25/2014 10:34:11 COMPLETED DATE: **METER 1 - M:** 726 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 08/25/2014 10:34:13 **CLOSED DATE: IN-SERVICE DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905 JOB CODE RSN WRTY JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT LABOR 03-15-024 REPLACE NEW STEERING WHEEL CO\ DON 0 **GARAGE** \$18.93 0.30 \$17.25 \$0.00 \$36.18 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.30 17.25 18.93 0.00 36.18 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 03-15-024 REPLACE NEW STEERING WHEEL COVER 11237753 08/25/2014 07:31:25 08/25/2014 07:49:25 0.30 \$17.25 **LABOR** 17.25 Job Code **Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 03-15-024 ZZZ580950B STEERING WHEEL COVER 18.93 \$18.93 REPLACE NEW STEERING WHEEL COVER **PARTS** 18.93

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 17879

Work Order Notes

(LPATE) TERRY REQUESTED A STEERING WHEEL COVER TO PROTECT STEERING WHEEL FROM WEAR

Job Notes

03-15-024 - REPLACE NEW STEERING WHEEL COVER

(LPATE) INSTALLED STEERING WHEEL COVER

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 **WORK ORDER NO:** 17933 **USING DEPT NO:** 504131 **OPENED DATE:** 08/29/2014 09:39:34 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 09/04/2014 08:44:25 COMPLETED DATE: **METER 1 - M:** 793 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 09/04/2014 08:44:26 **IN-SERVICE DATE: CLOSED DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905 COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION STAT 03-51-046 DON 0 **GARAGE** 0.00 \$0.00 \$0.00 REPLACE NEW KEY BLANK(S) \$6.48 \$6.48 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 6.48 0.00 6.48 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 3 \$6.48 03-51-046 REPLACE NEW KEY BLANK(S) **KEY BLANK** KEY BLANK 2.16 **PARTS** 6.48

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 17933

Work Order Notes

(LPATE) RICKY REQUESTED EXTRA KEYS

Job Notes

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) CUT 2 KEYS AND 1 FOR MASTER BOX

UNIT NO:		240682	2014 FOR	D E350)				WORK OR	DER NO:	192	97	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	01/26/20	15 13:48:46 15 08:03:30 15 08:03:33	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	DATE: 0	MET 7/24/2014	ER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY			LABOR	MATERIA		MERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.20	\$11.61	\$39.71	\$0.00)	\$51.32
JOB COUN	NT: 1				wo	RK ORI	DER TOTAL	: 0.20	11.0	61 3	9.71	0.00	51.32
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414		01	1/22/2015 14:15:00	01/22/2015	5 14:27:07		0.20	\$11.61
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414		0′	1/22/2015 14:08:40	01/22/2015	5 14:08:40		0.00	\$0.00
											_	LABOR	11.61
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u>Uni</u>	t Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		0	IL FILTER			5.15	1	\$5.15
66-PM-PMA	PERFORM (OIL CHANGE		5'	W20FS		H	AVOLINE 5W20 FL	JLLSYN OIL BUI	LK	5.76	6	\$34.56
												PARTS	39.71

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 19297

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY SH/GM -TIGHTENED DRIVER SIDE RUNNING BOARD

UNIT NO:		240682	2014 FORE	D E350					WORK OF	RDER NO): 2	0750	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E3	ETED I	DATE:	07/14/20	15 14:17:13 15 08:38:02 15 08:38:04	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	n: 5036 DATE:	M 07/24/20		0
JOB CODE	_	JOB DESCRIPTI		<u>STAT</u>	RSN	WRTY			LABOR	MATE		OMMERCIAL	TOTAL COST
31-17	ROTATE	TIRES, TUBES, LI	NERS & VALV	DON	Р	N	GARAGE	0.93	\$53.66	\$0.00	\$0	0.00	\$53.66
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.63	\$36.23	\$29.53	\$0	0.00	\$65.76
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	: 1.56	89.	89	29.53	0.00	119.42
Job Code		Job Descrip	<u>tion</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		11	074414		0	7/09/2015 14:23:58	07/09/201	5 15:01:46		0.63	\$36.23
31-17	ROTATE TIF	RES, TUBES, LINERS	S & VALVES	11	074414		0.	7/10/2015 06:02:40	07/10/201	5 06:58:40		0.93	\$53.66
66-PM-PMA	PERFORM (OIL CHANGE		11	074414		0	7/09/2015 14:23:58	07/10/201	5 06:01:33		(15.63)	(\$898.52)
66-PM-PMA	PERFORM (OIL CHANGE		11	074414		0	7/09/2015 14:23:58	07/10/201	5 06:01:33		15.63	\$898.52
												LABOR	89.89
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5\	V20FS		Н	AVOLINE 5W20 FL	JLLSYN OIL BU	LK	3.76	3 7	\$26.32
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		0	IL FILTER			3.21	11	\$3.21
												PARTS	29.53

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 20750

Work Order Notes

(LPATE) PM-ROTATE TIRES

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) SH/GM ROTATED TIRES. ADJUSTED TIRE PRESSURE

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY SH

UNIT NO:		240682	2014 FOR	D E350)				WORK OF	RDER NO): 2	2218	
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED	DATE:	12/18/201	15 15:12:40 5 08:15:29 15 08:15:30	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 7198 DATE:	M 07/24/20	ity Automotive S IETER 2 - N: 014 BEL0EDA81905	0
JOB CODI	<u>—</u>	JOB DESCRIPTI M OIL CHANGE	<u>ON</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.49	LABOR \$28.43	MATE \$34.00		COMMERCIAL 0.00	TOTAL COST \$62.43
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.49	28.	43	34.00	0.00	62.43
Job Code		Job Descript	ion_		<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	0260422		12	/17/2015 06:41:18	12/17/201	5 07:10:58		0.49	\$28.43
												LABOR	28.43
Job Code		Job Descript	ion			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		P	A4878F		All	R FILTER REPL 64	418		7.40	1	\$7.40
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			3.98	3 1	\$3.98
66-PM-PMA	PERFORM (OIL CHANGE		5	W20FS		HA	VOLINE 5W20 FU	JLLSYN OIL BU	LK	3.77	76	\$22.62
												PARTS	34.00

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 22218

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM/SH

UNIT NO:	NIT NO: 240682 2		2014 FORE	E350)				WORK C	RDER NO): 2	3849	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	ı	COMPL	ED DATE ETED I ED DATE 350	DATE:	07/12/20	16 11:32:39 16 06:36:17 16 06:36:20	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 10001 E DATE:	M 07/24/20	ty Automotive S IETER 2 - N: 014 BEL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATI</u>	ERIAL C	OMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-RE	EAR,TAIL,STO	DON	Р	Ν	GARAGE	0.14	\$8.02	\$0.25	\$0	0.00	\$8.27
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	1.00	\$57.34	\$23.18	\$0	0.00	\$80.52
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	: 1.14	1 6	5.36	23.43	0.00	88.79
Job Code		Job Descript	tion_		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	1074414		07	/08/2016 15:44:10	07/08/20	016 15:52:32		0.14	\$8.02
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414		07	7/08/2016 14:44:16	07/08/20	016 15:44:06		1.00	\$57.34
												LABOR	65.36
Job Code		Job Descript	<u>tion</u>		ļ	Part No	<u>.</u>	<u>De</u>	scription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5	W20FS		H	AVOLINE 5W20 F	ULLSYN OIL E	BULK	0.10	192	\$19.20
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		O	L FILTER			3.98	3 1	\$3.98
03-34-002	REPLACE N	IEW LAMPS-REAR,T	AIL,STOP,TURN	ETC 9	12		ВІ	JLB-BRAKE-3RD			0.25	51	\$0.25
												PARTS	23.43

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 23849

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACED LEFT SIDE BULB IN 3RD BRAKE LIGHT

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AY, SH/CS

The University of Alabama

Work Order Charge Detail

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 **WORK ORDER NO:** 23944 **USING DEPT NO:** 504131 **OPENED DATE:** 07/20/2016 08:21:58 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 07/25/2016 11:52:25 **COMPLETED DATE: METER 1 - M**: 10001 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 07/25/2016 11:52:27 **CLOSED DATE: IN-SERVICE DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905 **LABOR** COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **MATERIAL** JOB DESCRIPTION STAT PU-34-033 PURCHASED SPOT LIGHT DON 0 **GARAGE** 0.00 \$0.00 \$275.34 \$275.34 \$0.00 275.34 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 275.34 0.00 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** PU-34-033 **GO-LIGHT STROBE LIGHT** \$275.34 PURCHASED SPOT LIGHT GOL7901 275.34 **PARTS** 275.34

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 23944

Work Order Notes

(LISAPATE) RICKY LUKER REQUESTED A SPOT LIGHT FOR THIS TRUCK FOR CALL OUTS AT NIGHT

Job Notes

PU-34-033 - PURCHASED SPOT LIGHT

(LISAPATE) GAVE RICKY SPOT LIGHT

UNIT NO:	240682	2014 FORD E35	0			WORK ORDER NO): 242	44	
USING DEPT NO:	504131	OPEN	ED DATE:	08/29/201	6 09:45:35	LOCATION: GARAGE	- University A	\utomotive {	Services
WO STATUS:	CLOSED	COMP	LETED DATE:	09/01/201	6 08:36:59	METER 1 - M : 10516	MET	ER 2 - N:	0
WO VISIT REASO	N: SCHEDULED	CLOSI	ED DATE:	09/01/201	6 08:37:02	IN-SERVICE DATE:	07/24/2014	•	
TECH SPEC NO:	14FORDE350	2014 FORD E	350			UNIT SERIAL NO:	1FTSE3EL	0EDA81905	;
JOB CODE	JOB DESCRIPT	ION STAT	RSN WRTY	JOB LOC	LABOR HRS	LABOR MATE	RIAL COM	MERCIAL	TOTAL COST
66-79-002 PE	RFORM SERVICE CALL	DON	B N	GARAGE	0.30	\$17.25 \$0.00	\$0.00)	\$17.25
JOB COUNT: 1			WORK OR	DER TOTAL:	0.30	17.25	0.00	0.00	17.25
Job Code	Job Descrip	tion_	<u>Employee</u>	No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
66-79-002 PERF	FORM SERVICE CALL	•	11758845	08/2	29/2016 09:46:13	08/29/2016 10:04:13		0.30	\$17.25
							_	LABOR	17.25

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 24244

Work Order Notes

(LISAPATE) DRIVER LEFT POWER INVERTOR ON OVER THE WEEKEND.

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) JUMPED OFF RUNNING OK

The University of Alabama

Work Order Charge Detail

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 **WORK ORDER NO:** 25020 **USING DEPT NO:** 504131 **OPENED DATE:** 11/17/2016 14:59:25 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 11/18/2016 09:49:49 COMPLETED DATE: **METER 1 - M**: 11228 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 11/18/2016 09:49:51 **CLOSED DATE: IN-SERVICE DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905 COMMERCIAL TOTAL COST JOB CODE **JOB DESCRIPTION** RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** STAT PU-35-006 PURCHASED FUSE(S) DON 0 **GARAGE** 0.00 \$0.00 \$2.19 \$0.00 \$2.19 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 2.19 0.00 2.19 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** PU-35-006 PURCHASED FUSE(S) 3 \$2.19 ATO15 FUSE-15 AMP 0.73 **PARTS** 2.19

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 25020

Work Order Notes

(LISAPATE) RICKY LUKER REQUESTED 3 FUSES

Job Notes

PU-35-006 - PURCHASED FUSE(S)

(LISAPATE) GAVE RICKY 3 FUSES

UNIT NO: 240682 2014 FORD E		E350)				WORK OF	RDER NO	: 25	5438			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	ı	OPENE COMPL CLOSE ORD E	ETED	DATE:	01/17/20	17 15:37:04 17 10:44:30 17 10:44:32	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 11930 E DATE:	ME 07/24/20	y Automotive \$ ETER 2 - N: 14 EL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-RE	EAR,TAIL,STO	DON	0	Ν	GARAGE	0.30	\$17.25	\$0.62	\$0.	.00	\$17.87
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.31	\$17.83	\$23.18	\$0.	.00	\$41.01
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	0.61	35	.08	23.80	0.00	58.88
Job Code		Job Descript	<u>tion</u>		Em	ployee	No.	<u>Start</u>	<u> </u>	<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	1758845		01	/12/2017 15:39:05	01/12/201	7 15:57:41		0.31	\$17.83
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	1758845		01	/12/2017 15:37:57	01/12/201	7 15:55:57		0.30	\$17.25
												LABOR	35.08
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	scription	<u>!</u>	Unit Price	Quantity	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 9	12		ВІ	JLB-BRAKE-3RD			0.31	2	\$0.62
66-PM-PMA	PERFORM (OIL CHANGE		5	W20FS		HA	WOLINE 5W20 FL	JLLSYN OIL BL	JLK	0.10	192	\$19.20
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OIL FILTER				3.98	1	\$3.98
												PARTS	23.80

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 25438

Work Order Notes

(LISAPATE) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACE BOTH 3RD BRAKE LIGHT BULBS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS COOLANT -30'

UNIT NO: 240682 2014 FORD E		E350)				WORK (ORDER NO): 2 [°]	7497			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		COMPL	ED DATI ETED I ED DATI 350	DATE:	09/20/20	017 11:03:49 017 09:15:06 017 09:15:08		- M: 14422 CE DATE:	M 07/24/20	ey Automotive S ETER 2 - N: 114 EL0EDA81905	0
JOB CODE		JOB DESCRIPT	ION	STAT	RSN	WRTY	JOB LO	LABOR HRS	LABO	R MATI	ERIAL C	OMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-RI	EAR,TAIL,STO	DON	0	Ν	GARAGE	0.19	\$10.75	\$0.50	\$0	0.00	\$11.25
15-27	WARRAN	ITY TRANSMISSI	ON - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0	0.00	\$0.00
16-27	TRANSP	ORT TRANSMISS	SION - MAIN, A	DON	0	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.26	\$14.84	\$23.06	\$0	0.00	\$37.90
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	_: 1.45	5 8	33.09	23.56	0.00	106.6
Job Code 15-27	WARRANTY	Job Descrip TRANSMISSION - I		C 1	V 1078175	endor N		<u>Invoice No.</u> V10255	<u>Purch</u> 004017	nase Order N 9	<u>lo.</u>	COMML	Total Cost \$0.0
Job Code		Job Descrip	otion		Em	ployee	No.	<u>Start</u>		Finish		Quantity	Total Cost
66-PM-PMA	PERFORM (DIL CHANGE		1	1074414	-		9/18/2017 14:41:28	3 09/18/2	2017 14:56:57		0.26	\$14.8
03-34-002	REPLACE N	EW LAMPS-REAR,1	TAIL,STOP,TURN	ETC 1	1074414		C	9/18/2017 14:30:13	3 09/18/2	2017 14:41:26		0.19	\$10.7
16-27	TRANSPOR	T TRANSMISSION -	MAIN, AUTOMAT	ΓIC 1	0208562	<u>!</u>	C	9/19/2017 07:00:00	09/19/2	2017 08:00:00		1.00	\$57.5
												LABOR	83.0
Job Code		Job Descrip	<u>otion</u>			Part No	<u>.</u>	Des	scription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	198		C	OIL DRAIN PLUG F	ORD		7.56	1	\$7.5
03-34-002	REPLACE N	EW LAMPS-REAR,1	TAIL,STOP,TURN	ETC 9	12		Е	BULB-BRAKE-3RD			0.50	1	\$0.5
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		C	OIL FILTER			3.98	1	\$3.9
66-PM-PMA	PERFORM (OIL CHANGE		5	W-20P		F	ROTECK OIL FUL	L SYNTHETIC		0.06	192	\$11.5
66-PM-PMA	PERFORM (OIL CHANGE		5	W-20P		F	ROTECK OIL FUL	L SYNTHETIC		0.06	(6)	(\$0.3
66-PM-PMA	PERFORM (OIL CHANGE		5	W-20P		F	ROTECK OIL FUL	L SYNTHETIC		0.06	6	\$0.3
												PARTS	23.5

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 27497

Work Order Notes

(LISAPATE) TAKE TO FORD THE PLANETARY IN THE TRANSMISSION IS COMING APART

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACED 3RD BRAKE LIGHT BULB

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) PER FORD INVOICE-TRANSMISSION ASSY-REMOVE AND INSTALL OR REPLACE DIAG DROP PAN EXCESSIVE FRICTION MATERIAL REMOVE TRANS INSTA HOLDING FIXTURE DISSEMBLE TRANS EXCESSIVE DAMAGE PUMP PLANETART REVERSE DRUM PERFORMED COST CAP OVER CAP REPLACE UNIT REASSEMBLE FLUSH COOLER. ROAD TEST OK

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) TAKEN TO FORD BY EK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH -REPLACED OIL DRAIN PLUG

UNIT NO:		240682	2014 FOR	RD E350					WORK O	RDER NO	: 2	9439	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	04/18/201	18 08:22:16 18 14:56:08 18 14:56:10	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 16728 E DATE :	M 07/24/20	ity Automotive (IETER 2 - N: 014 BEL0EDA81905	0
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	0	Ν	GARAGE	0.25	\$14.38	\$17.06	\$0	0.00	\$31.44
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.31	\$17.83	\$15.98	\$0	0.00	\$33.81
JOB COUN	T: 2				wo	RK ORI	DER TOTAL:	0.56	32	.21	33.04	0.00	65.25
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	nployee	No.	<u>Start</u>	<u>!</u>	Finish		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		1	1074414		04	/17/2018 10:04:34	04/17/201	18 10:23:10		0.31	\$17.83
03-51-038	REPLACE N	EW WIPER BLADES		1	1901357	•	04	/17/2018 10:04:41	04/17/201	18 10:19:41		0.25	\$14.38
												LABOR	32.21
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		W	/W-2000)-PC	W	PER BLADE 20"			8.53	3 2	\$17.06
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		BU	ILK OIL 5W20 SYI	NTHETIC THO	MAS	2.00	0 6	\$12.00
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			3.98	81	\$3.98
												PARTS	33.04

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 29439

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG/SH COOLANT -35'

UNIT NO:		240682	2014 FOF	RD E350)				WORK OF	DER NO	: 3	1112	
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED	DATE:	10/10/201	18 07:08:13 18 07:03:36 18 07:03:39	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	l: 17029 DATE :	M 07/24/20		0
JOB CODI 03-32-002		JOB DESCRIPTION E NEW BATTERY	<u>ON</u>	<u>STAT</u> DON	RSN O	WRTY N	JOB LOC GARAGE	LABOR HRS 0.50	LABOR \$0.00	MATE \$76.11		OMMERCIAL 0.00	TOTAL COST \$76.11
JOB COUN	NT: 1				WO	RK ORI	DER TOTAL:	0.50	0.	00	76.11	0.00	76.11
Job Code		Job Descript	ion		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
03-32-002	REPLACE N	EW BATTERY		1	0208562	2	10	/09/2018 10:59:50	10/09/201	8 11:29:50		0.50	\$0.00
												LABOR	0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u> </u>	Jnit Price	Quantity	Total Cost
03-32-002	REPLACE N	EW BATTERY		7	40245		BA	TTERY TERM PR	OTECTOR WAS	SHER	0.21	1	\$0.21
03-32-002	REPLACE N	EW BATTERY		7	40245		BA	TTERY TERM PR	OTECTOR WAS	SHER	0.21	1	\$0.21
03-32-002	REPLACE N	EW BATTERY		6	50		BA	TTERY BCI 65 65	0 CCA		75.69) 1	\$75.69
												PARTS	76.11

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 31112

Work Order Notes

(LISAPATE) Check battery-jumped off yesterday dragging today (RWINTERS)

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) EK replaced battery. Alternator charging at 14.26 volts

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

LABOR

6

3.36

UNIT NO:	240682	2014 FORD E350	WORK ORDER NO:	31214

USING DEPT NO: 504131 OPENED DATE: 10/18/2018 13:53:26 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 10/24/2018 07:22:21
 METER 1 - M:
 18870
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 10/24/2018 07:22:23
 IN-SERVICE DATE:
 07/24/2014

TECH SPEC NO: 14FORDE350 2014 FORD E350 **UNIT SERIAL NO**: 1FTSE3EL0EDA81905

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	0	Ν	GARAGE	2.00	\$0.00	\$186.71	\$0.00	\$186.71
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	Р	N	GARAGE	0.13	\$0.00	\$0.49	\$0.00	\$0.49
09-15	ALIGN STEERING	DON	0	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	0	N	GARAGE	0.82	\$0.00	\$474.29	\$0.00	\$474.29
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.61	\$0.00	\$31.08	\$0.00	\$31.08

J	OB COUN	Т: 5	WORK ORDER TO	OTAL: 4.56	0.00	692.57 0.00	692.57	
<u>J</u>	ob Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost	
03-	34-002	REPLACE NEW LAMPS-REAR.TAIL.STOP.TURN.ETC	11074414	10/23/2018 08:11:35	10/23/2018 08:19:26	0.13	\$0.00	

03-13-002 REPLACE NEW REAR BRAKES & DRUMS/ROTORS 11268671 2.00 \$0.00 10/23/2018 07:00:00 10/23/2018 09:00:00 09-15 ALIGN STEERING 11213180 10/23/2018 07:00:00 10/23/2018 08:00:00 1.00 \$0.00 66-17-028 PERFORM MOUNT AND BALANCE TIRES 11901357 10/22/2018 13:20:38 10/22/2018 14:09:55 0.82 \$0.00 PERFORM OIL CHANGE 66-PM-PMA 11074414 10/19/2018 06:09:32 10/19/2018 06:27:46 0.30 \$0.00 66-PM-PMA PERFORM OIL CHANGE 11901357 0.31 \$0.00 10/19/2018 06:09:00 10/19/2018 06:27:24

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost	
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.33	4	\$9.32	
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	11	\$2.97	
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	115.50	4	\$462.00	
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	3.98	1	\$3.98	
66-PM-PMA	PERFORM OIL CHANGE	PA4878F	AIR FILTER REPL 6418	6.94	1	\$6.94	
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	680679R	BRAKE ROTOR	65.94	2	\$131.88	
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SP1329TRH	BRAKE PAD SET	54.83	1	\$54.83	
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49	

BULK OIL 5W20 SYNTHETIC THOMAS

5W20BT

PERFORM OIL CHANGE

66-PM-PMA

\$20.16

0.00

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

PARTS

692.57

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 31214

Work Order Notes

(EKIMBREL) pm, check front tires

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(LISAPATE) IF installed new rotors and pads on the rear, front brakes looked good

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) Replaced LR turn signal bulb

09-15 - ALIGN STEERING

(LISAPATE) MS performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires from inventory

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG

Coolant -35'

Replaced air filter

UNIT NO:		240682	2014 FOR	D E350)				WORK O	RDER NO): 3	33270	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	06/28/20	19 14:55:53 19 11:45:09 19 11:45:11	LOCATION METER 1 - IN-SERVIC UNIT SERIA	M: 21528 E DATE:	N 07/24/2	ity Automotive S IETER 2 - N: 014 3EL0EDA81905	0
JOB CODE 66-PM-PMA		JOB DESCRIPTION M OIL CHANGE	<u>ON</u>	STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.64	<u></u>	MATI \$38.75		COMMERCIAL 60.00	TOTAL COST \$38.75
JOB COUN	IT: 1				WO	RK ORI	DER TOTAL	: 0.64	ļ ().00	38.75	0.00	38.75
Job Code		Job Descript	ion		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM C	OIL CHANGE		1	1901357	•	06	5/28/2019 07:55:19	06/28/20	19 08:33:57		0.64	\$0.00
												LABOR	0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM C	OIL CHANGE		5	W20BT		В	JLK OIL 5W20 SY	NTHETIC THO	MAS	2.9	6 6	\$17.76
66-PM-PMA	PERFORM C	OIL CHANGE		Α	NTIFRE	EZE GOI	_D Af	NTIFREEZE-FORD)		17.0	1 1	\$17.01
66-PM-PMA	PERFORM C	OIL CHANGE		В	ALB329		O	L FILTER			3.9	8 1	\$3.98
												PARTS	38.75

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 33270

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) AG/SH; Coolant -35

UNIT NO:		240682	2014 FORI	D E350					WORK (ORDER NO): (34482	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E	ETED D DATI	DATE:	10/21/20	19 08:21:09 19 07:35:17 19 07:35:19	LOCATIO METER 1 IN-SERVIO UNIT SER	- M: 22960 CE DATE:	07/24/2	sity Automotive S METER 2 - N: 2014 3EL0EDA81905	0
JOB CODE	Ī	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MATE	ERIAL (COMMERCIAL	TOTAL COST
03-52-021	REPLAC	E NEW GPS SYST	ΞM	DON	0	Ν	GARAGE	0.66	\$0.00	\$0.00	\$	\$0.00	\$0.00
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.47	\$0.00	\$21.68	\$	\$0.00	\$21.68
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	.: 1.13	3	0.00	21.68	0.00	21.68
Job Code		Job Descript	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		11	901357		1	0/17/2019 09:21:44	10/17/2	2019 09:49:55		0.47	\$0.00
03-52-021	REPLACE N	IEW GPS SYSTEM		11	901357		1	0/17/2019 08:42:06	3 10/17/2	2019 09:21:44		0.66	\$0.00
												LABOR	0.00
Job Code		Job Descript	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	e Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5\	W20BT		В	ULK OIL 5W20 SY	NTHETIC TH	OMAS	2.9	95 6	\$17.70
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		0	IL FILTER			3.9	981	\$3.98
												PARTS	21.68

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 34482

Work Order Notes

(LISAPATE) Remove 3G install 4G GPS system (LISAPATE) PM

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(LISAPATE) Removed GPS Serial # 5014689210 Installed Model# 5500N4VL Serial# 5041373472

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG Coolant -35' Syn 4.85

UNIT NO: 240682		240682	2014 FOR	D E350)					WORK ORDE	ER NO	:	35791		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014 F	OPENE COMPL CLOSE ORD E	ETED	DATE:	02/28/20	020 11:03:10 020 08:10:26 020 08:10:27		LOCATION: G, METER 1 - M: IN-SERVICE DA UNIT SERIAL N	24544 T E :	07/24/2	METER 2 - N:	0	
JOB CODE 03-32-002	_	JOB DESCRIPTION E NEW BATTERY	<u>ON</u>	STAT DON	RSN O	<u>WRTY</u> N	JOB LOC	-		LABOR \$0.00	MATE \$98.65		COMMERCIAL \$0.00	TOTAL COS \$98.65	<u>3T</u>
66-79-002		M SERVICE CALL		DON	В	N	GARAGE				\$0.00		\$0.00	\$0.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	.: 2	2.01	0.00		98.65	0.00	98	8.65
Job Code 03-32-002	REPLACE N	Job Descript	<u>tion</u>	1	<u>En</u> 1170580	nployee		<u>Start</u> 2/27/2020 07:00	0:00	<u>Finis</u> 02/27/2020 07			Quantity 0.50	Total Cos	s <u>t</u> 80.00
66-79-002	PERFORM	SERVICE CALL		1	0208562	208562 02/26/2020 11:07:25			7:25	02/26/2020 12:00:00			0.88	\$(0.00
66-79-002	PERFORM	SERVICE CALL		1	1170580)	0	2/26/2020 11:15	5:26	02/26/2020 11	:53:43		0.64	\$	0.00
													LABOR	- (0.00
Job Code	Job Description Part No.				<u>.</u>	<u>Description</u>				Unit Pric	e Quantity	Total Cos	<u>t</u>		
03-32-002	REPLACE N	IEW BATTERY		6	52		В	ATTERY BCI 65	5 850	CCA		97.	81 1	\$9	97.81
66-79-002	PERFORM S	SERVICE CALL		6	52		В	ATTERY BCI 65	5 850) CCA		97.	81 (1)	(\$97	7.81)
66-79-002	PERFORM S	SERVICE CALL		652			В	BATTERY BCI 65 850 CCA				97.	81 1	\$9	97.81
66-79-002	PERFORM	SERVICE CALL		740245		В	BATTERY TERM PROTECTOR WA		OTECTOR WASHE	R	0.	42 2	\$	0.84	
66-79-002	PERFORM	SERVICE CALL		740245			BATTERY TERM P		I PRO	ROTECTOR WASHER		0.	42 (2)	(\$0	0.84)
03-32-002	REPLACE N	IEW BATTERY		740245			В	BATTERY TERM PROTEC		DTECTOR WASHER		0.	422	\$	0.84
													PARTS	98	8.65

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 35791

Work Order Notes

(LISAPATE) Chuck requested a service call to Colonial Dr for a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery tested bad Installed new battery

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed.

UNIT NO:		240682	2014 FOR	RD E350)				WORK	ORDER NO	D: 3	6666	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	06/03/202	20 07:20:53 20 15:22:48 20 13:29:39	METER 1	- M: 25881 CE DATE:	M 07/24/20		0
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MAT	ERIAL C	OMMERCIAL	TOTAL COST
03-51-044	REPLAC	E NEW KEY FOB/R	REMOTE	DON	0	N	GARAGE	0.11	\$0.00	\$43.68	\$0	0.00	\$43.68
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.06	\$0.00	\$21.68	\$0	0.00	\$21.68
CU-51-046	CUT KEY	BLANK(S)		DON	0	N	GARAGE	0.52	\$0.00	\$1.02	\$0	0.00	\$1.02
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.68		0.00	66.38	0.00	66.3
Job Code		Job Descripti	<u>ion</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
03-51-044	REPLACE N	IEW KEY FOB/REMOT	TE	1	1170580		06	/03/2020 14:15:54	06/03/2	2020 14:15:54		0.00	\$0.
CU-51-046	CUT KEY BI	_ANK(S)		1	1901357		06	/03/2020 09:33:29	06/03/2	2020 10:04:25		0.52	\$0.
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357		06	/03/2020 09:30:00	06/03/2	2020 09:33:29		0.06	\$0.
66-PM-PMA	PERFORM (OIL CHANGE		1	1901357		06	/03/2020 09:18:16	06/03/2	2020 09:18:16		0.00	\$0.
66-PM-PMA	PERFORM (OIL CHANGE		1:	2052187	,	06	/03/2020 09:17:03	06/03/2	2020 09:17:03		0.00	\$0.
03-51-044	REPLACE N	IEW KEY FOB/REMOT	TE	1	1901357		06	/03/2020 09:08:22	06/03/2	2020 09:15:00		0.11	\$0.
												LABOR	0.0
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
03-51-044	REPLACE N	IEW KEY FOB/REMOT	TE	81	L3Z15K6	601B	KE	Y FOB			43.68	1	\$43.
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		OI	L FILTER			3.98	1	\$3.
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		BU	ILK OIL 5W20 SYI	NTHETIC TH	IOMAS	2.95	6	\$17.
CU-51-046	CUT KEY BI	_ANK(S)		K	EY BLA	NK	KE	Y BLANK			1.02		\$1.
												PARTS	66.3

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 36666

Work Order Notes

(EKIMBREL) PM

Job Notes

03-51-044 - REPLACE NEW KEY FOB/REMOTE

(ABLACK) AB programmed 1 new key fob. Tested ok.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC,AG/JW performed Coolant -35

CU-51-046 - CUT KEY BLANK(S)

(EKIMBREL) AG cut 1 key.

UNIT NO:		240682	2014 FOR	D E350)				WORK	ORDER NO): 3(6757	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED UNSCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	06/11/20	020 07:05:58 020 10:55:37 020 08:09:24	METER IN-SER	ON: GARAGE 1 - M: 25894 Vice date: Erial No:	M 07/24/20	ETER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LO	LABOR HRS	<u>LAB</u>	OR MATI	ERIAL C	OMMERCIAL	TOTAL COST
66-79-002	PERFOR	M SERVICE CALL		DON	В	N	GARAGE	0.89	\$0.00	\$0.00	\$0	0.00	\$0.00
CH-32-002	CHARGE	BATTERY		DON	0	N	GARAGE	0.43	\$0.00	\$0.00	\$0	0.00	\$0.00
JOB COUN	T: 2				wo	RK ORI	DER TOTA	_: 1.32	2	0.00	0.00	0.00	0.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
CH-32-002	CHARGE BA	TTERY		1:	2052187	•	C	6/10/2020 08:35:48	3 06/10	0/2020 08:43:01		0.12	\$0.00
CH-32-002	CHARGE BA	ATTERY		1:	2052187	•	C	6/11/2020 07:17:44	1 06/11	1/2020 07:36:23		0.31	\$0.00
66-79-002	PERFORM S	SERVICE CALL		1:	2052187	•	C	6/10/2020 07:12:13	3 06/10	0/2020 08:05:42		0.89	\$0.00
												LABOR	0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	Des	scription		Unit Price	Quantity	Total Cost
66-79-002	PERFORM S	SERVICE CALL		74	40245		E	SATTERY TERM PR	ROTECTOR	R WASHER	0.42	2	\$0.84
66-79-002	PERFORM S	SERVICE CALL		6	52		E	SATTERY BCI 65 8	50 CCA		97.81	1	\$97.81
66-79-002	PERFORM S	SERVICE CALL		7	40245		E	ATTERY TERM P	ROTECTOR	R WASHER	0.42	(2)	(\$0.84)
66-79-002	PERFORM S	SERVICE CALL		6	52		E	SATTERY BCI 65 8	50 CCA		97.81	(1)	(\$97.81)
												PARTS	0.00

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 36757

Work Order Notes

(LISAPATE) Terry requested a service call to Fac lot for a dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(EKIMBREL) JW jumped vehicle off and brought to shop to charge battery.

CH-32-002 - CHARGE BATTERY

(EKIMBREL) JW charged battery to 100% and checked good. Driver stated the unit has not been touched in a week and found phone charger was plugged up with a light on causing the battery to slowly drain. Alternator charging at 14.4 volts.

240682

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 2014 FORD E350 **WORK ORDER NO:** 37485 **USING DEPT NO:** 504131 **OPENED DATE:** 09/02/2020 09:03:50 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 09/02/2020 10:15:56 COMPLETED DATE: **METER 1 - M**: 26951 **METER 2 - N**: 0 **WO VISIT REASON:** UNSCHEDULED 09/02/2020 13:40:35 **CLOSED DATE: IN-SERVICE DATE:** 07/24/2014

TECH SPEC NO: 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905

JOB CODE **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS LABOR 03-34-002 REPLACE NEW LAMPS-REAR, TAIL, STO DON 0 **GARAGE** 0.30 \$0.00 \$0.50 \$0.50 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.30 0.00 0.50 0.00 0.50 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 03-34-002 REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC 11074414 09/02/2020 10:15:13 09/02/2020 10:33:13 0.30 \$0.00 **LABOR** 0.00 Job Code **Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 03-34-002 0.50 \$0.50 REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC 3157 **BULB-BRAKE/TURN/PARK PARTS** 0.50

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 37485

Work Order Notes

(RTUNAITI) LR turn signal is out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) Replaced LR turn signal bulb

UNIT NO:		240682	2014 FOR	D E350)				WORK O	RDER NO): ;	38568	
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	12/08/202	20 10:01:12 20 09:14:35 20 10:32:45	LOCATION METER 1 - IN-SERVICE UNIT SERIA	M: 28300 E DATE:	07/24/2	sity Automotive S METER 2 - N: 2014 3EL0EDA81905	0
JOB CODI 66-PM-PMA	_	JOB DESCRIPTI M OIL CHANGE	<u>ON</u>	STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.77	LABOR \$90.40	MATE \$33.32		COMMERCIAL \$0.00	TOTAL COST \$123.72
JOB COUN	NT: 1				WO	RK ORI	DER TOTAL:	. 0.77	90	.40	33.32	0.00	123.72
Job Code		Job Descript	tion_		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM C	OIL CHANGE		1	1901357		12	/07/2020 13:21:28	12/07/20	20 14:01:18		0.66	\$78.34
66-PM-PMA	PERFORM (OIL CHANGE		1:	2052187	•	12	/07/2020 13:29:46	12/07/202	20 13:35:54		0.10	\$12.06
												LABOR	90.40
Job Code		Job Descript	tion_			Part No	<u>.</u>	<u>Des</u>	scription		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM C	OIL CHANGE		5	W20BT		BU	JLK OIL 5W20 SY	NTHETIC THO	MAS	4.4	43 6	\$26.55
66-PM-PMA	PERFORM C	OIL CHANGE		В	ALB329		OI	L FILTER			6.7	77 1	\$6.77
												PARTS	33.32

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 38568

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Performed pm service. Jaw,amg/jaw Coolant-35 MILEAGE-28300 Washed and vacuumed JAW

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

1.38

LABOR

UNIT NO:		240682	2014 FOR	D E350)				WORK O	RDER NO:	393	70	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	03/12/202	1 13:38:33 1 11:18:24 1 15:51:24	LOCATION METER 1 - IN-SERVICI UNIT SERIA	E DATE:	MET 07/24/2014	ER 2 - N:	ervices 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CON	<u>IMERCIAL</u>	TOTAL COST
35-31	DIAGNO	SE CHARGING SYS	STEM	DON	0	Ν	GARAGE	1.00	\$118.00	\$0.00	\$0.00)	\$118.00
66-79-002	PERFOR	RM SERVICE CALL		DON	В	Ν	GARAGE	1.38	\$162.55	\$0.00	\$0.00)	\$162.55
CH-32-002	CHARGE	BATTERY		DON	0	N	GARAGE	0.12	\$14.49	\$0.00	\$0.00)	\$14.49
JOB COUN	T: 3				wo	RK ORE	DER TOTAL:	2.50	295	5.04	0.00	0.00	295.04
Job Code		Job Descripti	<u>on</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
35-31	DIAGNOSE	CHARGING SYSTEM		1	1213180	1	03/	16/2021 07:00:00	03/16/202	21 07:06:00		(0.10)	(\$11.80)
35-31	DIAGNOSE	CHARGING SYSTEM		1	1213180	١	03/	16/2021 07:00:00	03/16/20	21 07:06:00		0.10	\$11.80
35-31	DIAGNOSE	CHARGING SYSTEM		1	1213180	١	03/	16/2021 07:00:00	03/16/202	21 08:00:00		1.00	\$118.00
CH-32-002	CHARGE BA	ATTERY		1	1074414		03/	12/2021 10:21:54	03/12/202	21 10:29:16		0.12	\$14.49

03/10/2021 14:31:45

03/10/2021 15:54:24

11915538

PERFORM SERVICE CALL

66-79-002

\$162.55

295.04

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 39370

Work Order Notes

(LISAPATE) Per Terry door got left open van has a dead battery. Just jump off and driver will run vehicle about to start night shift. Unit is parked in backside of Fac lot.

Job Notes

35-31 - DIAGNOSE CHARGING SYSTEM

(LISAPATE) Checked for a draw no problem found at this time.

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) jumped off left it with customer RC/EK Jumped off again and brought to the shop

CH-32-002 - CHARGE BATTERY

(SHARBIN) Mileage 30025. Charged battery rechecked good ALT charging at14.3 SH

UNIT NO:	240682	2014 FORD E350				WORK ORDER N	O: 3	39487	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:	504131 CLOSED SCHEDULED 14FORDE350	_	ETED DATE: D DATE:	03/26/202	1 14:43:20 1 11:57:11 1 14:45:12	LOCATION: GARAG METER 1 - M: 3005 IN-SERVICE DATE: UNIT SERIAL NO:	N 07/24/2	METER 2 - N:	0
JOB CODE 03-32-002 REPLAC	JOB DESCRIPTION DE NEW BATTERY	ON STAT DON	RSN WRTY O N	JOB LOC GARAGE	LABOR HRS 0.04	LABOR MAT \$4.20 \$113.5		COMMERCIAL 60.00	TOTAL COST \$117.75
JOB COUNT: 1			WORK ORI	DER TOTAL:	0.04	4.20	113.55	0.00	117.75
Job Code 03-32-002 REPLACE	Job Descript NEW BATTERY		Employee 915538		<u>Start</u> 24/2021 15:05:28	Finish 03/24/2021 15:07:36		Quantity 0.04 LABOR	**Total Cost
Job Code 03-32-002 REPLACE	Job Descript NEW BATTERY	i <mark>ion</mark> 65	<u>Part No</u>	_	<u>Des</u> TTERY BCI 65 650	cription D CCA	Unit Price		Total Cost \$113.55 113.55

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 39487

Work Order Notes

(LISAPATE) Battery dead again

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) replaced battery\\RC CHARGING AT 14.1 VOLTS

UNIT NO:		240682	2014 FOR	E350)				WORK OF	RDER NO): 3	9535	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE	ETED D DATI	DATE:	04/12/20	21 09:47:31 21 14:11:20 21 15:44:14	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 30269 DATE:	N 07/24/20	ity Automotive S IETER 2 - N: 014 BEL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	COMMERCIAL	TOTAL COST
03-15-025	REPLAC	E NEW SHIFT TUBE	/BUSHINGS	DON	0	Ν	GARAGE	0.98	\$115.35	\$117.80	\$	0.00	\$233.15
03-31-001	REPLAC	E NEW ALTERNATO	R	DON	0	Ν	GARAGE	1.52	\$178.97	\$284.69	\$	0.00	\$463.66
35-32	DIAGNO	SE CRANKING SYST	TEM	DON	0	N	GARAGE	4.19	\$493.86	\$0.00	\$	0.00	\$493.86
JOB COUN	T: 3				wo	RK ORI	DER TOTAL	: 6.68	788.	18	402.49	0.00	1,190.67
Job Code		Job Descriptio	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u> </u>	inish		Quantity	Total Cost
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	11	1213180		04	1/09/2021 09:30:00	04/09/202	1 10:27:34		0.96	\$113.21
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	1′	1213180		04	1/09/2021 09:13:55	04/09/202	1 09:15:00		0.02	\$2.13
35-32	DIAGNOSE	CRANKING SYSTEM		1′	1213180		04	1/02/2021 11:59:31	04/02/202	1 15:04:40		3.09	\$364.13
35-32	DIAGNOSE	CRANKING SYSTEM		1	1213180		04	1/02/2021 09:49:17	04/02/202	1 10:55:15		1.10	\$129.73
03-31-001	REPLACE N	EW ALTERNATOR		1	1213180		04	1/02/2021 08:18:06	04/02/202	1 09:49:06		1.52	\$178.97
												LABOR	788.17
Job Code		Job Descriptio	o <u>n</u>			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>		Unit Price	<u>Quantity</u>	Total Cost
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	D	OR9051	10	SI	HIFT TUBE CLAME)		22.3	7 2	\$44.73
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	90	0500961		SI	HIFT TUBE DAMPE	ER		18.0	3 1	\$18.03
03-31-001	REPLACE N	EW ALTERNATOR		R	EM1293	4	Al	TERNATOR			284.69	9 1	\$284.69
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	F	ODZ7W	441A	SI	HIFT BUSHING			6.9	2 1	\$6.92
03-15-025	REPLACE N	EW SHIFT TUBE/BUSH	HINGS	F:	2DZ7D2	82A	SI	HIFT TUBE LEVER			48.1	21	\$48.12
												PARTS	402.49

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 39535

Work Order Notes

(LISAPATE) Per driver battery is dead again

Job Notes

03-15-025 - REPLACE NEW SHIFT TUBE/BUSHINGS

(MSIDES) Replaced shift tube bushing and dampener also replaced park lever at the base of shift tube. Rechecked to verify that the IPC was not drawing 0.620 amps and found draw to only be 0.01 amps which is well within spec for vehicle. MS

03-31-001 - REPLACE NEW ALTERNATOR

(MSIDES) Replace alternator. MS

35-32 - DIAGNOSE CRANKING SYSTEM

(MSIDES) Checked vehicle for draw and found no significate draw present. Let vehicle sit over night and found battery to still be charged the next day then inspected upfitted power invertor and noticed that within about 5 minutes the battery voltage had went from 12.4V to 7.8V which would indicate a very large draw in a very short amount of time. According to the repair manual this type of sudden and large draw would likely be caused by a internally shorted alternator. MS

(MSIDES) After replacing the alternator found the vehicle to still have about a half of an amp draw still. Draw appeared to be coming from the instrument cluster removed dash to verify cluster was causing the draw and noticed the shift tube bushing being severely worn. After further inspection found that the park level at the base of the shift tube was broken, this lever is used by the BCM to determine if the vehicle is actually in park or not therefore the lever being broken was causing the BCM to still provide power to the cluster causing the draw. Will need to replace broken shift tube parts to verify this issue is causing the draw could still possibly have a bad cluster. MS

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 **WORK ORDER NO:** 39902 **USING DEPT NO:** 504131 OPENED DATE: 05/07/2021 09:52:06 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 05/10/2021 12:20:33 COMPLETED DATE: **METER 1 - M:** 30763 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 05/10/2021 15:24:30 **CLOSED DATE: IN-SERVICE DATE:** 07/24/2014 **TECH SPEC NO:** 14FORDE350 2014 FORD E350 **UNIT SERIAL NO:** 1FTSE3EL0EDA81905 COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION STAT 66-PM-PMA PERFORM OIL CHANGE DON Ρ Ν **GARAGE** 0.31 \$36.15 \$0.00 \$0.00 \$36.15 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.31 36.15 0.00 0.00 36.15 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** 66-PM-PMA PERFORM OIL CHANGE 12052187 05/07/2021 14:30:00 05/07/2021 14:48:23 0.31 \$36.15 66-PM-PMA PERFORM OIL CHANGE 12052187 0.00 \$0.00 05/07/2021 14:28:38 05/07/2021 14:28:38 LABOR 36.15

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 39902

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 2463 miles since last pm. Customer wanted unit back quick and communicated with Lisa and advised us to check fluids on site. Went to unit and checked all fluids and tires. Updated pm sticker. Coolant -34°. JAW MILEAGE-30763

UNIT NO:		240682	2014 FORI	D E350)				WORK O	RDER N	0:	40174	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE	ETED D DATI	DATE:	06/18/202	21 08:02:28 21 13:41:20 21 13:41:23	LOCATION METER 1 - IN-SERVICE UNIT SERIA	M: 31501 E DATE :	07/24/	rsity Automotive s METER 2 - N: /2014 E3EL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPT	<u>ION</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL	COMMERCIAL	TOTAL COST
03-01-066	REPLAC	E NEW VACUUM	TANK UNIT	DON	0	Ν	GARAGE	1.38	\$163.17	\$28.44		\$0.00	\$191.61
35-01	DIAGNO	SE AIR CONDITIC	ONING, HEAT, '	DON	0	N	GARAGE	0.60	\$70.60	\$0.00		\$0.00	\$70.60
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	1.98	233	3.77	28.44	0.00	262.21
Job Code		Job Descrip	<u>otion</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	1	1310047		06	/15/2021 14:30:00	06/15/202	21 15:52:58		1.38	\$163.17
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	1	1310047		06	/15/2021 14:24:54	06/15/202	21 14:24:54		0.00	\$0.00
35-01	DIAGNOSE	AIR CONDITIONING	S, HEAT, VENT	1	1310047		06	/15/2021 09:45:59	06/15/202	21 10:21:53		0.60	\$70.60
												LABOR	233.77
Job Code		Job Descrip	<u>otion</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Pric	ce Quantity	Total Cost
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	3	7/3	32 VACUUM / WS\	W HOSE FT		0.	.50 1	\$0.50
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	3	7/3	32 VACUUM / WS\	N HOSE FT		0.	.50 (1)	(\$0.50)
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	3	7/3	32 VACUUM / WS\	N HOSE FT		0.	.50 1	\$0.50
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	D	OR4714	.9	CH	IECK VALVE			6	.58 1	\$6.58
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	D	OR4707	6	VA	CUUM TANK RES	SERVOIR		20	.10 1	\$20.10
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	1	7/6	34 VACUUM HOSE	≣		0.	.32 4	\$1.26
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	1	7/6	34 VACUUM HOSE	≣		0	.32 (4)	(\$1.26)
03-01-066	REPLACE N	IEW VACUUM TANK	UNIT	G	AT2704	1	7/6	64 VACUUM HOSE	≣		0	.32 4	\$1.26
												PARTS	28.44

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 40174

Work Order Notes

(LISAPATE) Per driver a/c wont change from vent to defrost at times

Job Notes

03-01-066 - REPLACE NEW VACUUM TANK UNIT

(EHOWELL) Bypassed factory vacuum tank and installed a new vacuum tank unit with an inline check valve. The AC, heat, and modes are now working properly. EH

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(EHOWELL) The vacuum tank for the HVAC was faulty. EH

UNIT NO:		240682	2014 FORI	D E350)				WORK OR	DER NO:	411	74	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE FORD E	ETED	DATE:	10/11/202	1 10:27:11 1 14:25:04 1 11:32:28	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	33565 DATE:	MET 07/24/2014	ER 2 - N:	0
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL COI	MMERCIAL	TOTAL COST
03-13-001	REPLAC	E NEW FRONT BR	AKES & ROT	DON	0	N	GARAGE	3.05	\$359.77	\$706.76	\$0.00	0	\$1,066.53
03-13-002	REPLAC	E NEW REAR BRA	KES & DRUN	DON	Ο	N	GARAGE	1.70	\$200.63	\$358.77	\$0.00	0	\$559.40
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	N	GARAGE	0.08	\$9.37	\$15.18	\$0.00	0	\$24.55
24-34-003	REPAIR	SIGNAL,PARKING,	& BACKUP L	DON	0	N	GARAGE	0.11	\$12.49	\$0.00	\$0.00	0	\$12.49
66-13-130	PERFOR	RM Burnish Brakes		DON	0	N	GARAGE	0.25	\$29.96	\$0.00	\$0.00	0	\$29.96
66-17-030	PERFOR	RM TIRE PATCH		DON	0	N	GARAGE	1.07	\$126.42	\$9.36	\$0.00	0	\$135.78
66-17-033	PERFOR	RM TIRE ROTATION	I AND BRAKE	DON	Ο	N	GARAGE	0.06	\$7.21	\$0.00	\$0.00	0	\$7.21
66-79-002	PERFOR	RM SERVICE CALL		DON	В	N	GARAGE	0.03	\$3.05	\$0.00	\$0.00	0	\$3.05
66-79-003	PERFOR	RM SAFETY INSPE	CTION	DON	Υ	N	GARAGE	0.66	\$78.31	\$0.00	\$0.00	0	\$78.31
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.18	\$21.50	\$31.37	\$0.00	0	\$52.87
CH-SP	CHARGE	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	0	\$2.00
JOB COUN	IT: 11				wo	RK ORI	DER TOTAL:	7.19	848.7	1 1, ⁴	121.44	2.00	1,972.15
Job Code		Job Descript	<u>ion</u>		V	endor N	l <u>o.</u>	Invoice No.	Purchase	Order No	<u>.</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1				_		\$2.00
												COMML	2.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	nish		Quantity	Total Cost
66-17-033	PERFORM ¹	TIRE ROTATION AND	BRAKE INSPE	CTION 1	2052187	7	10/	01/2021 14:03:56	10/01/2021	14:07:36		0.06	\$7.21
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	1	1170580)	10/	05/2021 10:19:56	10/05/2021	10:41:56		0.37	\$43.27
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS		1170580		10/	05/2021 13:06:45	10/05/2021	13:32:45		0.43	\$51.13
03-51-038	REPLACE N	IEW WIPER BLADES			1170580		10/	06/2021 09:07:38	10/06/2021	09:12:24		0.08	\$9.37
66-PM-PMA	PERFORM	OIL CHANGE		1	1170580)		06/2021 09:12:32		09:15:00		0.04	\$4.85
66-PM-PMA		OIL CHANGE			1170580			06/2021 09:30:00				0.14	\$16.65
66-17-030	PERFORM ¹	TIRE PATCH		1	2052187	7	10/	01/2021 10:37:50	10/01/2021	11:11:59		0.57	\$67.16
FleetFocus M5	- WODETAIL	- Work Order Detail v2	20.0										Page:1

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	12052187	10/01/2021 12:17:04	10/01/2021 12:18:37	0.03	\$3.05
66-79-003	PERFORM SAFETY INSPECTION	12052187	10/01/2021 12:18:47	10/01/2021 12:52:11	0.56	\$65.69
24-34-003	REPAIR SIGNAL, PARKING, & BACKUP LAMPS	12052187	10/01/2021 12:52:20	10/01/2021 12:58:41	0.11	\$12.49
66-17-030	PERFORM TIRE PATCH	12052187	10/01/2021 12:59:02	10/01/2021 13:29:10	0.50	\$59.26
66-79-003	PERFORM SAFETY INSPECTION	12052187	10/01/2021 13:53:46	10/01/2021 14:00:11	0.11	\$12.62
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11170580	10/05/2021 07:36:07	10/05/2021 08:48:39	1.21	\$142.65
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11170580	10/05/2021 09:06:26	10/05/2021 09:15:00	0.14	\$16.85
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11170580	10/05/2021 14:58:26	10/05/2021 15:52:16	0.90	\$105.87
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11170580	10/06/2021 07:19:13	10/06/2021 09:01:14	1.70	\$200.63
66-13-130	PERFORM Burnish Brakes	11170580	10/06/2021 09:38:35	10/06/2021 09:53:49	0.25	\$29.96
					LABOR	848.71

Job Code	Job Description	Part No.	<u>Description</u>	<u>Unit Price</u>	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	680681R	ROTOR AND HUB	226.08	2	\$452.16
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	680679R	BRAKE ROTOR	139.43	2	\$278.85
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SP1329TRH	BRAKE PAD SET	67.97	1	\$67.97
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR15245	BEARINGS	6.56	2	\$13.11
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR50	BEARINGS	21.95	2	\$43.89
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	B-0710625	SEALS	47.13	2	\$94.26
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR50	BEARINGS	21.95	(2)	(\$43.89)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR50	BEARINGS	21.95	2	\$43.89
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR15245	BEARINGS	6.56	(2)	(\$13.11)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15245	BEARINGS	6.56	2	\$13.11
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	3.92	1	\$3.92
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	C111	RED BRAKE CLEANER	5.57	1	\$5.57
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR15101	OUTER WHEEL BEARING	16.91	2	\$33.81
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR15101	OUTER WHEEL BEARING	16.91	(2)	(\$33.81)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	B-0710625	SEALS	47.13	(2)	(\$94.26)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKFBR15101	OUTER WHEEL BEARING	16.91	2	\$33.81

The University of Alabama

Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	B-0710625	SEALS	47.13	2	\$94.26
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABSP1328TRH	BRAKE PADS	69.53	1	\$69.53
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	VAL614	GREASE	6.38	1	\$6.38
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	0.35	1	\$0.35
66-17-030	PERFORM TIRE PATCH	58106	1.75 OZ WHEEL WEIGHT	0.62	2	\$1.23
					PARTS	1121.44

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 41174

Work Order Notes

(LISAPATE) Terry requested a service call to Fac Lot van has a flat tire

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(ABLACK) AB installed new front brake pads and rotors. Installed new inner and outer wheel bearings and seals.

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(ABLACK) AB installed new rear brake pads and rotors.

03-51-038 - REPLACE NEW WIPER BLADES

(ABLACK) AB installed new wiper blades

24-34-003 - REPAIR SIGNAL, PARKING, & BACKUP LAMPS

(JWRIGHT) Found no power getting to reverse lights. Checked and found fuse had been removed and put into a spare section. Reinstalled fuse and lights work good. JAW .10 labor

66-13-130 - PERFORM Burnish Brakes

(ABLACK) AB test drove and burnished brakes. Rechecked ok

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired RR tire and installed new valve stem. Aired to spec and torqued lug nuts to spec. JAW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Adjusted tire pressures. Front pads 6mm and damaged due to bad rotors. Rear pads 4mm. All pads and rotors need replaced. JAW

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Went to facility and aired tire up. Brought back to shop for repair

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Found all brakes and rotors need to be replaced, bleed the brake system due to spongey brakes, adjust front wheel bearings verified with AB. JAW

66-PM-PMA - PERFORM OIL CHANGE

(ABLACK) AB performed oil change

CH-SP - CHARGE Shop Supplies

UNIT NO:		240682	2014 FORE	E350)				WORK OF	RDER NO): 4	11442	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E	ETED	DATE:	10/29/202	21 09:39:53 21 07:03:03 21 07:03:10	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 33676 EDATE:	N 07/24/2	ity Automotive S //ETER 2 - N: 014 3EL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (COMMERCIAL	TOTAL COST
03-34-002	REPLAC	E NEW LAMPS-RE	EAR,TAIL,STO	DON	0	N	GARAGE	0.10	\$11.80	\$0.75	\$	60.00	\$12.55
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	51.26	\$1.26
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	: 0.10	11.	.80	0.75	1.26	13.81
Job Code		Job Descript	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcha	se Order No	<u>o.</u>		Total Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1						\$1.26
												COMML	1.26
Job Code		Job Descript	<u>tion</u>		<u>En</u>	ployee	No.	<u>Start</u>	<u> </u>	-inish		Quantity	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	2052187	•	10	/28/2021 09:44:12	10/28/202	1 09:50:12		0.10	\$11.80
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	2052187	•	10)/28/2021 09:44:12	10/28/202	1 09:55:52		0.19	\$22.94
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	2052187	•	10)/28/2021 09:44:12	10/28/202	1 09:55:52		(0.19)	(\$22.94)
												LABOR	11.80
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	Des	scription	<u>.</u>	Unit Price	<u>Quantity</u>	Total Cost
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 3	157		ВІ	JLB-BRAKE/TURN	N/PARK		0.7	5 1	\$0.75
												PARTS	0.75

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 41442

Work Order Notes

(LISAPATE) LR turn signal bulb is out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(JWRIGHT) Replaced bulb

CH-SP - CHARGE Shop Supplies

UNIT NO:		240682	2014 FORD E350						WORK ORDE	R NO:	41897	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE	ETED D DATI	DATE:	12/20/202	1 07:47:52 1 14:17:24 1 15:07:04	LOCATION: GAMETER 1 - M: GAMETER 1 -	34621 TE : 07/24	rsity Automotive S METER 2 - N: /2014 E3EL0EDA81905	0
JOB CODE		JOB DESCRIPTION	<u>NC</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFOR	M MOUNT AND BA	LANCE TIRE	DON	0	N	GARAGE	0.54	\$63.26	5163.52	\$0.00	\$226.78
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	60.00	\$2.00	\$2.00
JOB COUN	T: 2				wo	RK ORE	DER TOTAL:	0.54	63.26	163.52	2.00	228.78
Job Code CH-SP	Job Description CHARGE Shop Supplies		<u>Vendor No</u> 503163			0. 1	Invoice No.	Purchase O	rder No.	COMML	*2.00	
Job Code		Job Descript				Employee No.		<u>Start</u>	<u>Finis</u>		Quantity	Total Cost
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	1′	1074414		12/	15/2021 09:12:52	12/15/2021 09:	:15:00	0.04	\$4.20
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	1′	1074414		12/	16/2021 07:31:07	12/16/2021 08:	:01:09	0.50	\$59.07
											LABOR	63.27
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription	<u>Unit Pr</u>	ce Quantity	Total Cost
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	23	3131		TPI	MS SNAP IN VAL	VE 21060	3	3.82 1	\$3.82
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	00	02761		TIR	E LT245/75R16 F	S TRANSF HT2	159	9.11 1	\$159.11
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	58	3100		.25	OZ WHEEL WEI	GHT	().18 1	\$0.18
66-17-028	PERFORM N	MOUNT AND BALANG	CE TIRES	58103			1.0	O OZ WHEEL WE	IGHT	().411	\$0.41
											PARTS	163.52

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 41897

Work Order Notes

(LISAPATE) Driver has 4 screws in RF tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Tire can't be patched all 4 screws are in one area will need a new tire. SH (SHARBIN) Tire could not be patched all 4 screws were in one spot. Mounted and balanced 1 tire. SH

CH-SP - CHARGE Shop Supplies

USING DEPT NO: WO STATUS: WO VISIT REASON:		240682	2014 FORD E35				WORK OF	RDER NO	: 4	1952			
		504131 CLOSED SCHEDULED 14FORDE350	COMP	OPENED DATE: COMPLETED DATE: CLOSED DATE: 14 FORD E350			01/04/2022 07:22:51 01/06/2022 07:54:51 01/06/2022 11:07:45				ty Automotive S IETER 2 - N: 014 IEL0EDA81905	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL CO	<u>OST</u>
66-79-002	PERFOR	M SERVICE CALL	DON	В	N	GARAGE	0.50	\$59.00	\$0.00	\$0	0.00	\$59.00	
CH-32-002	CHARGE	BATTERY	DON	0	N	GARAGE	0.15	\$17.70	\$0.00	\$0	0.00	\$17.70	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3			wo	RK ORI	DER TOTAL:	0.65	76	.70	0.00	2.00	ı	78.70
Job Code	CHARGE SI	Job Descripti		<u>Vendor N</u> 503163			No. Invoice No.		se Order No	<u>).</u>		Total Co	ost \$2.00
C11-01	CHARGE SI	юр очррпез		03103		'					COMML		2.00
Job Code		Job Descripti	<u>on</u>	<u>E</u> r	nployee	No.	<u>Start</u>	<u> </u>	-inish		Quantity	Total Co	ost
66-79-002	PERFORM	SERVICE CALL	1	1074414	1	01/	06/2022 07:00:00	01/06/202	22 07:30:00		0.50	5	\$59.00
66-79-002	PERFORM	SERVICE CALL	1	205218	7	01/	06/2022 07:00:00	01/06/202	22 07:30:00		0.50	S	\$59.00
66-79-002	PERFORM	SERVICE CALL	1	205218	7	01/	06/2022 07:00:00	01/06/202	01/06/2022 07:30:00		(0.50)	(\$	59.00)
CH-32-002	CHARGE BA	ATTERY	1	12052187		01/	05/2022 07:00:00	01/05/2022 07:09:00			0.15	5	\$17.70
											LABOR		76.70

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 41952

Work Order Notes

(LISAPATE) Terry requested a service call to Fac for a dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(EKIMBREL) SH PERFORMED SERVICE CALL

CH-32-002 - CHARGE BATTERY

(EKIMBREL) SH CHARGED BATTERY, CHECKED GOOD. JW REINSTALLED BATTERY.

CH-SP - CHARGE Shop Supplies

UNIT NO:		240682	2014 FORD E350							ORDER NO	2615		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED	DATE:	03/09/20	22 08:14:01 22 15:21:02 22 07:53:56	METER 1	- M: 35898 CE DATE:	MI 07/24/20	y Automotive S E TER 2 - N: 14 EL0EDA81905	0
JOB CODE		JOB DESCRIPTI	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATE	RIAL C	OMMERCIAL	TOTAL COS
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	N	GARAGE	0.15	\$17.70	\$15.18	\$0	.00	\$32.88
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.28	\$33.56	\$31.82	\$0	.00	\$65.38
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL	: 0.43		51.26	47.00	2.00	100.
Job Code CH-SP	CHARGE SI	Job Description Supplies	<u>tion</u>	5	<u>V</u> 03163	endor N	lo. 1	Invoice No.	<u>Purc</u>	hase Order N	<u>o.</u>	COMML	Total Cost \$2
Job Code		Job Descrip	tion		Fm	nployee	No	<u>Start</u>		Finish		Quantity	Total Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1:	 2052187			<u>3/09/2022</u> 09:22:18	03/09/	2022 09:22:18		0.00	\$0
03-51-038	REPLACE N	IEW WIPER BLADES	3	1:	2052187	7	03	3/09/2022 09:22:18	03/09/	2022 09:22:18		0.00	\$0
03-51-038	REPLACE N	IEW WIPER BLADES	S	1:	2052187	7	03	3/09/2022 09:22:18	03/09/	2022 09:31:18		0.15	\$17
66-PM-PMA	PERFORM (OIL CHANGE		1:	2052187	7	03	3/09/2022 08:57:56	03/09/	2022 09:15:00		0.28	\$33
												LABOR	51.
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		В	JLK OIL 5W20 SYI	NTHETIC TH	IOMAS	4.43	6	\$26
03-51-038	REPLACE N	IEW WIPER BLADES	3	Т	WB20-1		W	IPER BLADE 20"			7.59	2	\$15
66-PM-PMA	PERFORM (FORM OIL CHANGE		BALB329			OIL FILTER				5.27	1	\$5
												PARTS	47.

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 42615

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW MILEAGE-35898

CH-SP - CHARGE Shop Supplies

UNIT NO:		240682	2014 FORD E350							WORK ORDER NO: 42				
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DATI	DATE:	04/18/202	2 07:37:17 2 14:15:51 2 08:54:49	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 36054 DATE:	ME 07/24/20	y Automotive S ETER 2 - N: 14 EL0EDA81905	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-13-129	REPLAC	E NEW CONTROLL	.ER	DON	0	Ν	GARAGE	1.00	\$118.00	\$310.34	\$0	.00	\$428.34	
66-79-002	PERFOR	M SERVICE CALL		DON	В	Ν	GARAGE	0.71	\$83.52	\$0.00	\$0	.00	\$83.52	
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.15	\$17.70	\$0.00	\$0	.00	\$17.70	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00	
JOB COUNT: 4					wo	RK ORI	DER TOTAL:	1.86	219	.22	310.34	2.00		531.56
Job Code		Job Descripti	<u>on</u>		<u>V</u>	endor N	<u>o.</u>	Invoice No.	<u>Purcha</u> :	se Order N	<u>0.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	nop Supplies		50	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>. Start</u> <u>l</u>				Quantity	<u>Total</u>	Cost
CH-32-002	CHARGE BA	ATTERY		1	310047		04/	18/2022 07:00:00	04/18/202	22 07:09:00		0.15		\$17.70
03-13-129	REPLACE N	EW CONTROLLER		1	310047		04/	18/2022 07:00:00	04/18/202	22 08:00:00		1.00		\$118.00
66-79-002	PERFORM S	SERVICE CALL		1	074414		03/	24/2022 07:43:53	03/24/202	22 08:26:21		0.71		\$83.52
												LABOR	_	219.22
Job Code		Job Descripti	<u>on</u>			Part No	<u> </u>	Des	scription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
03-13-129	REPLACE N	EW CONTROLLER		9C2Z2C006A				AILER BRAKE MO	LER BRAKE MODULE			1		\$310.34
												PARTS		310.34

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 42685

Work Order Notes

(LISAPATE) Per Terry unit has a dead battery again has been checked a few times.

Job Notes

03-13-129 - REPLACE NEW CONTROLLER

(LISAPATE) Installed new trailer brake control module. There is no warning message displayed now. Parasitic draw of about 55ma. EH

03-32-002 - REPLACE NEW BATTERY

15-32-002 - WARRANTY BATTERY

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) SH RC Performed a service call to BLDG MAINT for a dead battery. Jumped vehicle off and drove it back to the shop.

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery. tested good. Used table charger in battery room . Alternator is charging at 14.1 volts

CH-SP - CHARGE Shop Supplies

UNIT NO: 240682 20		2014 FOR	D E350	١				WORK	ORDER NO:	4	43093			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED UNSCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DAT	DATE:	05/02/202	2 12:21:27 2 10:54:03 2 07:52:23	METER 1	ON: GARAGE - I - M: 36460 ICE DATE: RIAL NO:	M 07/24/20	IETER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABO	OR MATER	RIAL C	OMMERCIAL	TOTAL COST	
66-79-002	PERFOR	RM SERVICE CALL		DON	В	Ν	GARAGE	0.50	\$59.00	\$0.00	\$0	0.00	\$59.00	
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.15	\$17.70	\$0.00	\$0	0.00	\$17.70	
CH-SP	CHARGE Shop Supplies			DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.65		76.70	0.00	2.00	78.70	
Job Code	CHARGE SI	Job Descript	<u>ion</u>	<u>Vendor No</u> 503163			<u>lo.</u> 1	Invoice No.		Purchase Order No			Total Cost \$2.00	
												COMML	2.00	
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost	
66-79-002	PERFORM	SERVICE CALL		11	1915538	}	05/	02/2022 07:00:00	05/02/2022 07:30:00			0.50	\$59.00	
CH-32-002	CHARGE BA	ATTERY		12052187				04/29/2022 12:22:42		04/29/2022 12:31:42		0.15	\$17.70	
											LABOR	76.70		

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 43093

Work Order Notes

(EKIMBREL) SERVICE CALL DEAD BATTERY.

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed jumped off drove to the shop

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery overnight. Tested good. Alternator charging at 13.7 volts and no issues found JW

CH-SP - CHARGE Shop Supplies

UNIT NO: 240682			2014 FOR	D E350)			WORK O	RDER NO:	43	3179			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E	ETED D DATI	DATE:	05/10/202	22 10:29:31 2 14:51:55 2 07:35:30	LOCATION METER 1 - I IN-SERVICE UNIT SERIA	M: 36553 E DATE:	ME 07/24/20	y Automotive S ETER 2 - N: 14 EL0EDA81905	0	
JOB CODE		JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CO	OMMERCIAL	TOTAL COST	<u> </u>
03-34-002	REPLAC	E NEW LAMPS-RE	EAR,TAIL,STO	DON	0	N	GARAGE	0.16	\$19.01	\$0.95	\$0	.00	\$19.96	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00	
JOB COUN	JOB COUNT: 2				WORK ORDER TOTA			0.16	19	.01	0.95	2.00	21.	96
Job Code		Job Descript	<u>tion</u>		<u>Vendor No.</u>			Invoice No.	Purchase Order N		<u>.</u>		Total Cost	
CH-SP	CHARGE Sh	Shop Supplies		50	503163		1							.00
												COMML	2.	00
Job Code		Job Descript	<u>tion</u>		<u>En</u>	ployee	No.	<u>Start</u>	!	Finish		Quantity	Total Cost	
03-34-002	REPLACE N	EW LAMPS-REAR,T	AIL,STOP,TURN	ETC 1	1901357	•	05/	10/2022 10:37:42	05/10/202	22 10:47:22		0.16	\$19.	01
												LABOR	19.	01
Job Code		Job Descript	tion			Part No	<u> </u>	Des	scription		Init Price	Quantity	Total Cost	
03-34-002	REPLACE NEW LAMPS-REAR,TAI		AIL,STOP,TURN	ETC 3	157		BU	BULB-BRAKE/TURN			0.95	1	\$0	.95
												PARTS	0.	95

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 43179

Work Order Notes

(LISAPATE) RR turn signal is out

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(AGUERRA) miles: 36553 Replaced R/R blinker/brake light bulb. Checked for proper operation, all good. AMG

UNIT NO:		240682	2014 FOR	D E350)				WORK O	RDER NO	: 4	3268		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DAT	DATE:	05/18/20	022 07:50:35 022 11:39:42 022 13:44:42		M: 36662 E DATE:	M 07/24/20	ty Automotive S IETER 2 - N: 014 BEL0EDA81905	0	
JOB CODE	_	JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY			LABOR			OMMERCIAL	TOTAL	COST
66-17-030	PERFOR	M TIRE PATCH		DON	0	N	GARAGE	0.51	\$60.61	\$10.96	\$0	0.00	\$71.57	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	T: 2				wo	RK ORI	DER TOTAL	.: 0.51	60	0.61	10.96	2.00		73.57
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcha	ase Order No	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-17-030	PERFORM T	TRE PATCH		1	1074414		0	5/17/2022 07:57:47	05/17/20	22 08:28:36		0.51		\$60.61
												LABOR		60.61
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	scription	ļ	Unit Price	Quantity	<u>Total</u>	Cost
66-17-030	PERFORM T	TRE PATCH		5	8107		V	HEEL WEIGHT PF	E 2.00		0.84	4 1		\$0.84
66-17-030	PERFORM T	TRE PATCH		2	3131		Т	PMS SNAP IN VAL	VE 21060		3.82	2 1		\$3.82
66-17-030	PERFORM T	TRE PATCH		1	4042		Р	ATCH 3/8 PILOT W	/IRE		5.73	3 1		\$5.73
66-17-030	PERFORM T	TRE PATCH		5	8103		1	.00 OZ WHEEL WE	EIGHT		0.57	71		\$0.57
												PARTS		10.96

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 43268

Work Order Notes

(LISAPATE) Nail in LR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(HHARBIN) Patched left rear tire. SH

UNIT NO:		240682	2014 FOR	D E350	١				WORK	ORDER NO:	43	3408	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD EX	ETED D DAT	DATE:	05/26/202	2 07:38:49 2 14:23:06 2 14:58:02	METER 1	ON: GARAGE - - M: 36927 ICE DATE: RIAL NO:	ME 07/24/201	TER 2 - N:	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	<u>MATER</u>	IAL CO	OMMERCIAL	TOTAL COST
66-79-002	PERFOR	M SERVICE CALL		DON	В	N	GARAGE	0.02	\$1.80	\$0.00	\$0.	.00	\$1.80
CH-32-002	CHARGE	BATTERY		DON	0	N	GARAGE	0.15	\$17.70	\$0.00	\$0.	.00	\$17.70
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.	.95	\$1.95
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.17		19.50	0.00	1.95	21.45
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	lo.	Invoice No.	Purc	hase Order No.			Total Cost
CH-SP	CHARGE Sh	op Supplies		50	3163		1						\$1.95
												COMML	1.95
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
CH-32-002	CHARGE BA	ATTERY		12	2052187	,	05/	26/2022 13:41:57	05/26/2	2022 13:50:57		0.15	\$17.70
66-79-002	PERFORM S	SERVICE CALL		12	2052187	7	05/	26/2022 13:41:02	05/26/2	2022 13:41:57		0.02	\$1.80
												LABOR	19.50

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 43408

Work Order Notes

(LISAPATE) Van is parked in Fac lot has a dead battery again

Job Notes

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Performed service call and jumped unit off. Charged battery and tested system, found the phone charger plugged in was draining the battery. Battery tested good. JAW

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery and tested system, found the phone charger plugged in was draining the battery. Battery tested good. JAW (EHOWELL) Tested vehicle for a parasitic drain. The average drain is about 62 milliamps. Accessories do not need to be plugged in when the vehicle is not running. The alternator is charging. EH

(IFALLS) pulled fuse to power inverter.

UNIT NO:		240682	2014 FOR	D E350)				WORK O	RDER NO:	: 44	4594		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED	DATE:	09/09/202	22 10:12:19 22 11:00:45 22 12:13:52	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 38651 E DATE:	M I 07/24/20	ty Automotive S ETER 2 - N: 014 EL0EDA81905	0	
JOB CODE		JOB DESCRIPTION	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-046	REPLAC	E NEW KEY BLANI	Κ (S)	DON	0	Ν	GARAGE	0.20	\$23.60	\$3.15	\$0	0.00	\$26.75	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL:	0.20	23	.60	3.15	5.00		31.75
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	l <u>o.</u>	Invoice No.	<u>Purcha</u>	se Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	op Supplies		50	03163		1					-		\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u> </u>	Finish		Quantity	<u>Total</u>	Cost
03-51-046	REPLACE N	EW KEY BLANK(S)		10	0208562	2	09	/09/2022 07:00:00	09/09/202	22 07:12:00		0.20		\$23.60
												LABOR	_	23.60
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription	<u>U</u>	Jnit Price	Quantity	<u>Total</u>	Cost
03-51-046	REPLACE N	EW KEY BLANK(S)		K	EY BLA	NK	KE	Y BLANK			1.58	3 2		\$3.15
												PARTS		3.15

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 44594

Work Order Notes

(LISAPATE) Dept requested 2 extra keys

Job Notes

03-51-046 - REPLACE NEW KEY BLANK(S)

(EKIMBREL) if cut 2 keys

UNIT NO:

240682

2014 FORD E350

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

44948

WORK ORDER NO:

USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	504131 CLOSED SCHEDULED 14FORDE350 2014	COMP	ED DAT LETED ED DAT 350	DATE:	10/18/202	22 08:34:41 22 14:28:32 22 07:30:29	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	39294 DATE:	ME 07/24/201	TER 2 - N:	0	
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-05-019	REPLAC	E NEW OXYGEN SENSOR	DON	0	N	GARAGE	0.72	\$84.99	\$111.45	\$0.0	00	\$196.44	
06-15	INSPECT	TSTEERING	DON	0	N	GARAGE	0.28	\$33.50	\$0.00	\$0.0	00	\$33.50	
66-17-013	PERFOR	RM ALIGNMENT	DON	0	N	GARAGE	0.95	\$111.58	\$0.00	\$0.0	00	\$111.58	
66-17-028	PERFOR	RM MOUNT AND BALANCE TIR	E DON	0	N	GARAGE	1.29	\$151.76	\$502.22	\$0.0	00	\$653.98	
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.23	\$26.98	\$68.01	\$0.0	00	\$94.99	
CH-SP	CHARGE	E Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00	
SO-05	SCAN O	UT ELECTRONIC ENGINE EEC	DON	0	N	GARAGE	2.16	\$254.88	\$0.00	\$0.0	00	\$254.88	
JOB COUN	T: 7			WC	ORK ORE	DER TOTAL:	5.62	663.6	9	681.68	5.00	,	1,350.37
Job Code		Job Description		<u>v</u>	/endor N	<u>o.</u>	Invoice No.	<u>Purchase</u>	Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	nop Supplies	5	03163		1							\$5.00
											COMML		5.00
Job Code		Job Description			nployee		<u>Start</u>		<u>nish</u>		Quantity	<u>Total</u>	Cost
06-15	INSPECT ST	TEERING	1	1074414	4	10	/14/2022 08:46:08	10/14/2022	09:03:10		0.28		\$33.50
66-17-028	PERFORM I	MOUNT AND BALANCE TIRES	1	1074414	4	10	/14/2022 07:28:45	10/14/2022	08:45:55		1.29		\$151.76
03-05-019	REPLACE N	NEW OXYGEN SENSOR	1	1310047	7	10	/13/2022 08:30:18	10/13/2022	09:13:31		0.72		\$84.99
SO-05	SCAN OUT	ELECTRONIC ENGINE EEC SYSTE	EM 1	1310047	7	10	/11/2022 10:25:23	10/11/2022	11:20:15		0.91		\$107.90
SO-05	SCAN OUT	ELECTRONIC ENGINE EEC SYSTE	EM 1	1310047	7	10	/11/2022 09:01:07	10/11/2022	10:15:51		1.25		\$146.98
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414	4	10	/11/2022 09:30:00	10/11/2022	09:36:31		0.11		\$12.82
66-PM-PMA	PERFORM (OIL CHANGE	1	1074414	4	10	/11/2022 09:07:48	10/11/2022	09:15:00		0.12		\$14.16
66-17-013	PERFORM A	ALIGNMENT	1	1310047	7	10	/14/2022 14:19:53	10/14/2022	15:16:37		0.95		\$111.58
											LABOR		663.69
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>।</u>	Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (OIL CHANGE	F	PA4878F	:	AIF	R FILTER REPL 64	118		24.06	1		\$24.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	6.42	1	\$6.42
03-05-019	REPLACE NEW OXYGEN SENSOR	DEN2345113	OXYGEN SENSOR	111.45	1	\$111.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.31	3	\$6.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	3	\$2.39
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	3	\$2.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	163.04	3	\$489.11
					PARTS	681.68

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 44948

Work Order Notes

(LISAPATE) PM

Job Notes

03-05-019 - REPLACE NEW OXYGEN SENSOR

(EHOWELL) Replaced bank 2 sensor 1 oxygen sensor. Cleared DTC and reset keep alive memory. EH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. 1.0 HR EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 3 tires. Put the good tire from the right front on the right rear and adjusted the tire pressure. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH Vehicle needs 3 tires the right rear is at 2/32 left rear at 4/32 left front 5/32 right front 10/32. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0151 Oxygen Sensor Circuit Low Voltage (Bank 2 Sensor 1). Verified proper measurements for sensor wiring using a digital multimeter. EH

UNIT NO:		240682	2014 FOR	D E350)				WORK	ORDER NO:	4	5501	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	2014	OPENE COMPL CLOSE FORD E	ETED D DAT	DATE:	12/12/202	22 07:58:07 22 10:10:14 22 13:40:19	IN-SERVI	ON: GARAGE - - M: 40017 ICE DATE: RIAL NO:	M 07/24/20	ity Automotive S IETER 2 - N: 014 BEL0EDA81905	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABC	<u>MATER</u>	IAL C	OMMERCIAL	TOTAL COST
66-79-002	PERFOR	RM SERVICE CALL		DON	В	Ν	GARAGE	0.14	\$16.62	\$0.00	\$0	0.00	\$16.62
CH-32-002	CHARGI	E BATTERY		DON	0	N	GARAGE	0.03	\$3.34	\$0.00	\$0	0.00	\$3.34
CH-SP	CHARGI	E Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$:	5.00	\$5.00
JOB COUN	IT: 3				WC	RK ORI	DER TOTAL:	0.17		19.96	0.00	5.00	24.9
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	<u>Purc</u>	hase Order No.			Total Cost
CH-SP	CHARGE S	hop Supplies		50	03163		1						\$5.0
												COMML	5.0
Job Code		Job Descript	<u>ion</u>		En	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
CH-32-002	CHARGE B	ATTERY		1′	1915538	3	12/	/12/2022 07:58:39	12/12/	2022 08:00:21		0.03	\$3.3
66-79-002	PERFORM	SERVICE CALL		1	1915538	3	12/	/12/2022 07:50:12	12/12/	2022 07:58:39		0.14	\$16.6
												LABOR	19.9

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 45501

Work Order Notes

(EHANNAH) request service call to the facilities lot due to dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped off brought back to shop\RC\CW

CH-32-002 - CHARGE BATTERY

(GARAGE) put battery on charge. alt charging at 14.2\RC

UNIT NO:		240682	2014 FORD	E350)				WORK C	RDER NO): 4	6344	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350	(OPENE COMPL CLOSE ORD E	ETED D DATI	DATE:	03/03/20	023 07:42:34 023 14:45:54 023 07:35:38		M: 41714 E DATE:	M 07/24/20		0
JOB CODE		JOB DESCRIPTIO	<u>N</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOF	R MATE	RIAL C	OMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLAD	DES	DON	Р	N	GARAGE	0.15	\$17.70	\$15.63	\$0	0.00	\$33.33
66-79-003	PERFOR	M SAFETY INSPEC	TION	DON	Υ	N	GARAGE	0.41	\$48.12	\$0.00	\$0	0.00	\$48.12
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.56	\$65.88	\$43.47	\$0	0.00	\$109.35
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3	5.00	\$5.00
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	.: 1.12	13	1.70	59.10	5.00	195.80
Job Code CH-SP	CHARGE SI	Job Description op Supplies	<u>on</u>	50	V 03163	endor N	lo. 1	Invoice No.	<u>Purch</u>	ase Order No	<u>o.</u>	COMML	*5.00
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		11	1074414		0:	3/03/2023 08:53:50	03/03/20	023 09:02:50		0.15	\$17.70
66-79-003	PERFORM S	SAFETY INSPECTION		11	1074414		0:	3/03/2023 09:50:34	03/03/20	023 10:09:45		0.32	\$37.73
66-79-003	PERFORM	SAFETY INSPECTION		11	1074414		0	3/03/2023 09:30:00	03/03/20	023 09:35:17		0.09	\$10.39
66-79-003	PERFORM S	SAFETY INSPECTION		11	1074414		0	3/03/2023 09:22:08	03/03/20	023 09:22:08		0.00	\$0.00
66-PM-PMA	PERFORM (OIL CHANGE		11	1074414		0:	3/03/2023 08:54:44	03/03/20	023 09:15:00		0.34	\$39.86
66-PM-PMA	PERFORM (OIL CHANGE		11	1074414		0	3/03/2023 08:40:36	03/03/20	023 08:53:50		0.22	\$26.03
												LABOR	131.71
Job Code		Job Description	<u>on</u>			Part No	<u>).</u>	Des	scription	<u>!</u>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (OIL CHANGE		5\	W20BT		В	ULK OIL 5W20 SYI	NTHETIC THO	DMAS	6.26	6	\$37.53
03-51-038	REPLACE N	EW WIPER BLADES		T	WB20-1		W	/IPER BLADE 20"			7.82	2 2	\$15.63
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		O	IL FILTER			5.94	1 PARTS	\$5.94 59.10

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 46344

Work Order Notes

(LISAPATE) PM-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

(SHARBIN) Front pads measure 10MM the rear pads measure 6MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

UNIT NO:		240682	2014 FORI	D E350)				WORK OF	RDER NO): 47	884		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E	ETED D DAT	DATE:	08/18/20	23 07:33:20 23 10:01:31 23 13:56:16	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 44262 EDATE:	ME 07/24/201		0	
JOB CODE		JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	<u>OMMERCIAL</u>	TOTAL COS	<u>T</u>
03-13-002	REPLAC	E NEW REAR BRA	KES & DRUN	DON	N	N	GARAGE	0.25	\$29.60	\$336.19	\$0.	00	\$365.79	
06-13	INSPECT	BRAKES		DON	N	Ν	GARAGE	0.33	\$39.50	\$0.00	\$0.	00	\$39.50	
66-13-130	PERFOR	M Burnish Brakes		DON	N	N	GARAGE	1.59	\$187.75	\$0.00	\$0.	00	\$187.75	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.50	\$59.49	\$62.15	\$0.	00	\$121.64	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
WA-00	WASH C	OMPLETE VEHICL	E	DON	Р	N	GARAGE	0.48	\$56.25	\$0.00	\$0.	00	\$56.25	
JOB COUN	T: 6				WC	RK ORI	DER TOTAL	: 3.16	372	.59	398.34	5.00	775	5.93
Job Code CH-SP	CHARGE Sh	Job Descript nop Supplies	<u>ion</u>	5	<u>V</u> 03163	<u>endor N</u>	lo. 1	Invoice No.	Purchas	se Order N	<u>o.</u>	COMML		<u>t</u> 5.00
Job Code		Job Descript	ion		Fn	nployee	No.	<u>Start</u>		inish		Quantity	Total Cost	
03-13-002	REPLACE N	EW REAR BRAKES 8		DRS 1	 1310047	_		<u></u> 3/17/2023 09:09:19	_	3 09:24:22		0.25	•	- 9.60
66-13-130	PERFORM E	Burnish Brakes		1	1310047	7	08	3/17/2023 07:33:51	08/17/202	3 09:09:19		1.59	\$187	7.75
66-PM-PMA	PERFORM (OIL CHANGE		1	2201267	7	08	3/11/2023 09:49:39	08/11/202	3 10:19:54		0.50	\$59	9.49
WA-00	WASH COM	PLETE VEHICLE		1	2201267	7	08	3/11/2023 10:19:54	08/11/202	3 10:48:30		0.48	\$56	6.25
06-13	INSPECT BE	RAKES		1	2201267	7	08	3/11/2023 12:55:46	08/11/202	3 12:55:46		0.00	\$0	0.00
06-13	INSPECT BE	RAKES		1	2201267	7	08	3/11/2023 13:00:00	08/11/202	3 13:20:05		0.33	\$39	9.50
												LABOR	372	.59
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Price	Quantity	Total Cost	<u>t</u>
66-PM-PMA	PERFORM (OIL CHANGE		5	W20BT		В	ULK OIL 5W20 SYI	NTHETIC THOM	MAS	6.29	6	\$37	7.71
66-PM-PMA	PERFORM (OIL CHANGE		Р	A4878F		Α	IR FILTER REPL 64	418		18.50	1	\$18	8.50
66-PM-PMA	PERFORM (OIL CHANGE		В	ALB329		0	IL FILTER			5.94	1	\$	5.94
03-13-002	REPLACE N	EW REAR BRAKES &	& DRUMS/ROTO	DRS C	111		R	ED BRAKE CLEAN	IER		6.32	2	\$12	2.63
03-13-002	REPLACE N	EW REAR BRAKES &	& DRUMS/ROTO	DRS S	ANDPAI	PER	V	AR GRIT SINGLE S	SHEET SANDPA	APE	1.82	1	\$	1.82

The University of Alabama

Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB680679	REAR ROTORS	100.91	1	\$100.91
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWR171329	REAR BRAKES	69.92	1	\$69.92
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB680679	REAR ROTORS	100.91	(1)	(\$100.91)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB680679	REAR ROTORS	100.91	2	\$201.81
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	BC2Z2C150A	CALIPER BOLT PIN KIT	25.01	2	\$50.01
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	BC2Z2C150A	CALIPER BOLT PIN KIT	25.01	(2)	(\$50.01)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	BC2Z2C150A	CALIPER BOLT PIN KIT	25.01	2	\$50.01
					PARTS	398.34

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 47884

Work Order Notes

(EHANNAH) pm- wash - inspect brakes- DR is making noise.

Job Notes

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(EHOWELL) The rear brake pad had worn metal to metal. Replaced rear brake pads and rotors. The caliper slide pins had rust on them and the rubber sleeve on the pin was deteriorated. The pins could not move freely in the bore. Sanded all four caliper pin bores with sandpaper and cleaned with brake cleaner. Installed new pins with rubber sleeves and applied grease to pins. EH

Extra .3 HR for reconditioning caliper bores

06-13 - INSPECT BRAKES

(GARAGE) Pulled van on 4 post, pulled all 4 wheels to inspect front and rear brakes. Front brakes and pads are good 8mm, Rear pads are gone, Had JW, inspect the rear and he said it needs brake pads and new drums.-GC

(EHOWELL) The front tires were cupped. Rotated tires, relearned positions, and set air pressures. EH

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made approximately 30 hard stops after the brake job was performed. EH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, changed air filter, checked tires and tire pressure. Miles, 44.262

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

UNIT NO:		240682	2014 FOR	D E350)				WORK	ORDER NO:	4	18663	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	504131 CLOSED SCHEDULED 14FORDE350		OPENE COMPL CLOSE ORD E	ETED D DAT	DATE:	10/30/202	3 13:44:06 3 08:45:46 3 10:14:19	METER 1	- M: 45143 CE DATE:	07/24/2		0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MATER	RIAL (COMMERCIAL	TOTAL COST
25-52-021	REMOV	E GPS SYSTEM		DON	5	Ν	GARAGE	0.50	\$59.00	\$0.00	\$	60.00	\$59.00
CH-SP	CHARGI	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00
PD-00-999	PREP D	ISPOSE PREPARE	UNIT FOR DI	DON	D	N	GARAGE	0.28	\$33.43	\$0.00	\$	60.00	\$33.43
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.78		92.43	0.00	5.00	97.43
Job Code		Job Descript	<u>ion</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purc	hase Order No	<u>.</u>		Total Cost
CH-SP	CHARGE S	hop Supplies		50	03163		1						\$5.00
												COMML	5.00
Job Code		Job Descript	<u>ion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
PD-00-999	PREP DISP	OSE PREPARE UNIT	FOR DISPOSAL	_ 1	1915538		10/	25/2023 11:35:24	10/25/2	2023 11:52:24		0.28	\$33.43
25-52-021	REMOVE G	PS SYSTEM		1	1915538		10/	30/2023 07:00:00	10/30/2	2023 07:30:00		0.50	\$59.00
												LABOR	92.43

The University of Alabama

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

UNIT NO: 240682 2014 FORD E350 WORK ORDER NO: 48663

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EKIMBREL) removed GPS#5041373472\RC

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) removed wordmarks and tag\RC millage 45143

Report Printed: 11/20/2023 12:41:44 By User: GLOBETTI

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Mon Nov 20 2023 12:41:44 Report User: GLOBETTI

TZ: Central Standard Time

DLL Version: 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB

Third Grouping:

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'240682') //Q=