

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 37819

USING DEPT NO:	507121	OPENED DATE:	09/29/2020 13:09:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2020 16:07:35	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2020 16:11:01	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.30	\$21.75	\$0.00	\$0.00	\$21.75
19-34-004	WIRE/REWIRE CLEARANCE/MARKER	DON	O	N	GARAGE	1.50	\$108.75	\$0.00	\$0.00	\$108.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.80	130.50	0.00	0.00	130.50
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11213180	09/29/2020 16:05:28	09/29/2020 16:23:28	0.30	\$21.75
19-34-004	WIRE/REWIRE CLEARANCE/MARKER	11213180	09/29/2020 16:03:28	09/29/2020 17:33:28	1.50	\$108.75
					LABOR	130.50

Work Order Charge Detail

UNIT NO:2434152017 MP5000-16 CRASHBARRIER

WORK ORDER NO:37819

Work Order Notes

(LISAPATE) Inspect unit for beginning of Football

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(LISAPATE) MS inspected trailer

19-34-004 - WIRE/REWIRE CLEARANCE/MARKER

(LISAPATE) MS rewired trailer harness

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 38041

USING DEPT NO:	507121	OPENED DATE:	10/16/2020 12:48:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/16/2020 15:20:39	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2020 12:51:01	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$185.85	\$0.00	\$203.55

JOB COUNT: 1 WORK ORDER TOTAL: 0.15 17.70 185.85 0.00 203.55

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12052187	10/16/2020 15:20:26	10/16/2020 15:29:26	0.15	\$17.70
					LABOR	17.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	8231	BATTERY BCI 31DC 100AH/800MCA	185.85	1	\$185.85
					PARTS	185.85

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 38041

Work Order Notes

(IFALLS) Dead battery replace per Charlie
(IFALLS) MP5000

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Installed new battery

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 39682

USING DEPT NO:	507121	OPENED DATE:	04/14/2021 14:40:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/19/2021 13:15:44	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2021 08:14:48	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.02	\$1.90	\$0.00	\$0.00	\$1.90
AD-79-046	ADDED CHAINS	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 2	WORK ORDER TOTAL:	0.12	13.70	0.00	0.00	13.70
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/15/2021 11:15:14	04/15/2021 11:16:12	0.02	\$1.90
AD-79-046	ADDED CHAINS	11310047	05/06/2021 07:00:00	05/06/2021 07:06:00	0.10	\$11.80
					LABOR	13.70

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 39682

Work Order Notes

(LISAPATE) Do annual safety inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Adjusted tire pressure checked brake fluid and lights inspected hydraulic lines. SH

AD-79-046 - ADDED CHAINS

(IFALLS) Removed small safety chain with S hook and installed a larger chain with a closed quick connector. (Chain for emergency brake.) EH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 40365

USING DEPT NO:	507121	OPENED DATE:	07/06/2021 13:41:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2021 15:20:54	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2021 12:22:52	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-37-042	INSTALL BATTERY VOLTAGE METER	DON	O	N	GARAGE	1.16	\$136.72	\$25.48	\$0.00	\$162.20

JOB COUNT: 1	WORK ORDER TOTAL:	1.16	136.72	25.48	0.00	162.20
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-37-042	INSTALL BATTERY VOLTAGE METER	11213180	07/08/2021 08:02:10	07/08/2021 09:11:41	1.16	\$136.72
					LABOR	136.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-37-042	INSTALL BATTERY VOLTAGE METER	X001V0HEEF	BATTERY METER	25.48	1	\$25.48
					PARTS	25.48

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 40365

Work Order Notes

(LISAPATE) Install battery voltage meter on trailer

Job Notes

14-37-042 - INSTALL BATTERY VOLTAGE METER

(MSIDES) Installed volt meter and wired to switch. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 40933

USING DEPT NO:	507121	OPENED DATE:	09/03/2021 10:01:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2021 11:37:40	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/13/2021 15:29:06	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17-008	REPLACE NEW VALVE ASSEMBLY	DON	O	N	GARAGE	0.29	\$34.09	\$0.77	\$0.00	\$34.86
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BI	DON	O	N	GARAGE	0.66	\$77.68	\$22.41	\$0.00	\$100.09
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.21	\$24.58	\$0.00	\$0.00	\$24.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.16	136.35	23.18	2.00	161.53
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11170580	09/07/2021 09:23:55	09/07/2021 09:23:55	0.00	\$0.00
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11170580	09/07/2021 09:30:00	09/07/2021 09:42:30	0.21	\$24.58
03-17-008	REPLACE NEW VALVE ASSEMBLY	11170580	09/07/2021 10:56:11	09/07/2021 11:13:31	0.29	\$34.09
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	11170580	09/07/2021 07:16:51	09/07/2021 07:56:21	0.66	\$77.68
				LABOR		136.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-020	REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY	GRO49172	LIGHT BAR RED 3 LAMP	22.41	1	\$22.41
03-17-008	REPLACE NEW VALVE ASSEMBLY	21601	TR 600 HP WIDE VALVE STEM	0.77	1	\$0.77
					PARTS	23.18

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 40933

Work Order Notes

(LISAPATE) Perform safety inspection prior to Football season

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(ABLACK) AB installed a new valve stem on the spare tire. The valve stem was crushed by storing the lazy Susan on top of the spare tire.

03-34-020 - REPLACE NEW THIRD BRAKE LIGHT BULB/ASSY

(ABLACK) AB found third brake light was broken. Installed a new third brake light. Rechecked ok.

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(ABLACK) AB performed safety inspection

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 41093

USING DEPT NO:	507121	OPENED DATE:	09/21/2021 15:05:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2021 10:52:27	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2021 07:40:40	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.25	\$29.50	\$100.48	\$0.00	\$129.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.25	29.50	100.48	2.00	131.98
--------------	-------------------	--	--	--	--	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	09/22/2021 15:01:33	09/22/2021 15:16:33	0.25	\$29.50
03-32-002	REPLACE NEW BATTERY	11074414	09/22/2021 15:01:33	09/22/2021 15:01:54	(0.01)	(\$0.69)
03-32-002	REPLACE NEW BATTERY	11074414	09/22/2021 15:01:33	09/22/2021 15:01:54	0.01	\$0.69
LABOR						29.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	100.48	1	\$100.48
PARTS						100.48

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 41093

Work Order Notes

(LISAPATE) Install new battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Replaced battery. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 41125

USING DEPT NO:	507121	OPENED DATE:	09/27/2021 09:04:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2021 13:45:47	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2021 14:00:01	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-37-031	REPLACE NEW CHARGING OUTLET	DON	O	N	GARAGE	0.35	\$41.30	\$1,276.43	\$0.00	\$1,317.73
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.45	53.10	1,276.43	2.00	1,331.53
--------------	-------------------	------	-------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-37-031	REPLACE NEW CHARGING OUTLET	11213180	09/29/2021 07:00:00	09/29/2021 07:21:00	0.35	\$41.30
35-31	DIAGNOSE CHARGING SYSTEM	11213180	09/29/2021 07:21:00	09/29/2021 07:27:00	0.10	\$11.80
				LABOR		53.10

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-37-031	REPLACE NEW CHARGING OUTLET	2461-77	MP5000 CHARGING OUTLET	373.86	3	\$1,121.58
03-37-031	REPLACE NEW CHARGING OUTLET	SHIPPING	SHIPPING AND HANDLING	154.85	1	\$154.85
				PARTS		1276.43

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 41125

Work Order Notes

(LISAPATE) Check charging system

Job Notes

03-37-031 - REPLACE NEW CHARGING OUTLET

(LISAPATE) Replaced charging receptacle

35-31 - DIAGNOSE CHARGING SYSTEM

(LISAPATE) terminals bent on charging receptacle

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 42879

USING DEPT NO:	507121	OPENED DATE:	04/11/2022 13:03:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2022 09:11:01	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2022 11:37:24	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.41	\$48.48	\$0.00	\$0.00	\$48.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.41	48.48	0.00	2.00	50.48
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11074414	04/12/2022 11:01:04	04/12/2022 11:25:43	0.41	\$48.48
					LABOR	48.48

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 42879

Work Order Notes

(CHANNELL) inspect

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(SHARBIN) Adjusted tire pressure. DOT dates are 3315 tires are almost 7 years old. Battery tested good. Inspected hydraulic safety chains checked lights greased trailer tounge and operated hydraulic lifts. Did not find any issues at this time. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 44533

USING DEPT NO:	507121	OPENED DATE:	08/31/2022 11:24:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2022 09:34:25	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:35:20	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	12296277	09/02/2022 07:00:00	09/02/2022 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 44533

Work Order Notes

(CHANNELL) inspect mp5000
(GARAGE) inspected mp 5000 jdm

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(LISAPATE) inspected mp 5000 jdm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 46433

USING DEPT NO:	507121	OPENED DATE:	03/09/2023 13:35:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2023 15:15:25	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2023 09:08:24	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.23	\$27.37	\$0.00	\$0.00	\$27.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.23 27.37 0.00 5.00 32.37

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	12201267	03/09/2023 15:19:56	03/09/2023 15:33:51	0.23	\$27.37
					LABOR	27.37

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 46433

Work Order Notes

(EHANNAH) inspect Trailor

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(EKIMBREL) GC inspected mp5000. Will re-evaluate new tires after A-day game.

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 46509

USING DEPT NO:	507121	OPENED DATE:	03/23/2023 10:17:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2023 15:53:46	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2023 07:55:55	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1825HC503125 S/N: 92402I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.03	\$3.47	\$0.00	\$0.00	\$3.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3.47	\$3.47

JOB COUNT: 2 WORK ORDER TOTAL: 0.03 3.47 0.00 3.47 6.94

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$3.47
				COMML	3.47

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/23/2023 10:49:55	03/23/2023 10:51:41	0.03	\$3.47
					LABOR	3.47

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 16:16:23 By User: GLOBETTI

UNIT NO: 243415 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 46509

Work Order Notes

(LISAPATE) Do SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Inspected and found all tires outdated but still good. Will not replace at this time. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Feb 29 2024 16:16:23 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243415') //Q=