

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 37822

USING DEPT NO:	507121	OPENED DATE:	09/29/2020 13:11:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2020 16:11:50	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2020 16:13:02	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.30	\$21.75	\$0.00	\$0.00	\$21.75
19-34-004	WIRE/REWIRE CLEARANCE/MARKER	DON	O	N	GARAGE	1.50	\$108.75	\$0.00	\$0.00	\$108.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.80	130.50	0.00	0.00	130.50
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
19-34-004	WIRE/REWIRE CLEARANCE/MARKER	11213180	09/29/2020 16:08:49	09/29/2020 17:38:49	1.50	\$108.75
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11213180	09/29/2020 16:10:49	09/29/2020 16:28:49	0.30	\$21.75
					LABOR	130.50

Work Order Charge Detail

UNIT NO:	243417	2017 MP5000-16 CRASHBARRIER	WORK ORDER NO:	37822
----------	--------	-----------------------------	----------------	-------

Work Order Notes
(LISAPATE) Inspect unit for beginning of Football

Job Notes
06-EQ-019 - INSPECT MP5000 CRASH BARRIER
(LISAPATE) MS inspected trailer
19-34-004 - WIRE/REWIRE CLEARANCE/MARKER
(LISAPATE) MS rewired trailer harness

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 38062

USING DEPT NO:	507121	OPENED DATE:	10/19/2020 14:55:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/20/2020 09:28:29	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/20/2020 15:49:09	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-34-002	INSPECT LAMPS-REAR, TAIL, STOP, TUR	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
24-37-004	REPAIR BRAKE BREAKAWAY SYSTEM	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	23.60	0.00	0.00	23.60
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-34-002	INSPECT LAMPS-REAR, TAIL, STOP, TURN, ETC	11268671	10/20/2020 07:00:00	10/20/2020 07:06:00	0.10	\$11.80
24-37-004	REPAIR BRAKE BREAKAWAY SYSTEM	11268671	10/19/2020 14:57:32	10/19/2020 15:03:32	0.10	\$11.80
					LABOR	23.60

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 38062

Work Order Notes

(IFALLS) install hook on trailer brake away chain
check trailer tail/brake lights

Job Notes

06-34-002 - INSPECT LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Inspected and repaired rear taillights

24-37-004 - REPAIR BRAKE BREAKAWAY SYSTEM

(IFALLS) if installed new hook on brake away chain
(IFALLS) billed on a previous work order

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 39684

USING DEPT NO:	507121	OPENED DATE:	04/14/2021 14:42:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/19/2021 13:16:39	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2021 08:15:59	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.02	\$2.46	\$0.00	\$0.00	\$2.46
AD-79-046	ADDED CHAINS	DON	O	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 2	WORK ORDER TOTAL:					0.12	14.26	0.00	0.00	14.26
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-79-046	ADDED CHAINS	11310047	05/06/2021 07:00:00	05/06/2021 07:06:00	0.10	\$11.80
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/15/2021 11:16:36	04/15/2021 11:17:51	0.02	\$2.46
					LABOR	14.26

Work Order Charge Detail

UNIT NO:	243417	2017 MP5000-16 CRASHBARRIER	WORK ORDER NO:	39684
----------	--------	-----------------------------	----------------	-------

Work Order Notes
(LISAPATE) Do annual safety inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION
(SHARBIN) Adjusted tire pressure checked brake fluid and lights and inspected hydraulic lines. SH

AD-79-046 - ADDED CHAINS
(IFALLS) Removed small safety chain with S hook and installed a larger chain with a closed quick connector. (Chain for emergency brake.) EH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 40367

USING DEPT NO:	507121	OPENED DATE:	07/06/2021 14:01:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2021 15:23:14	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2021 12:21:31	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-37-042	INSTALL BATTERY VOLTAGE METER	DON	O	N	GARAGE	1.26	\$148.39	\$25.48	\$0.00	\$173.87

JOB COUNT: 1	WORK ORDER TOTAL:	1.26	148.39	25.48	0.00	173.87
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-37-042	INSTALL BATTERY VOLTAGE METER	11213180	07/06/2021 14:34:29	07/06/2021 15:49:56	1.26	\$148.39
					LABOR	148.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-37-042	INSTALL BATTERY VOLTAGE METER	X001V0HEEF	BATTERY METER	25.48	1	\$25.48
					PARTS	25.48

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 40367

Work Order Notes

(LISAPATE) Install battery voltage meter on trailer

Job Notes

14-37-042 - INSTALL BATTERY VOLTAGE METER

(MSIDES) Installed volt meter and wired to switch. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 41126

USING DEPT NO:	507121	OPENED DATE:	09/27/2021 09:05:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2021 13:32:35	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2021 11:03:08	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-34	DIAGNOSE LIGHTING SYSTEM	DON	O	N	GARAGE	0.18	\$20.98	\$0.00	\$0.00	\$20.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.18	20.98	0.00	2.00	22.98
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-34	DIAGNOSE LIGHTING SYSTEM	11213180	09/27/2021 10:15:42	09/27/2021 10:26:22	0.18	\$20.98
					LABOR	20.98

Work Order Charge Detail

UNIT NO:2434172017 MP5000-16 CRASHBARRIER

WORK ORDER NO:41126

Work Order Notes

(LISAPATE) Check lights

Job Notes

35-34 - DIAGNOSE LIGHTING SYSTEM

(MSIDES) Found extension to rear tail lights to not be fully plugged in causing a bad connection. MS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 41757

USING DEPT NO:	507121	OPENED DATE:	12/01/2021 09:50:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2021 14:35:16	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	12/02/2021 15:18:48	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-003	REPLACE NEW SIGNAL,PARKING, & BA	DON	O	N	GARAGE	0.77	\$90.83	\$22.41	\$0.00	\$113.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.77 90.83 22.41 2.00 115.24

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	11310047	12/02/2021 10:21:11	12/02/2021 11:07:22	0.77	\$90.83
					LABOR	90.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-003	REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS	GRO49172	LIGHT BAR RED 3 LAMP	22.41	1	\$22.41
					PARTS	22.41

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 41757

Work Order Notes

(EHOWELL) Replace clearance/marker lamp assembly on dolly.

Job Notes

03-34-003 - REPLACE NEW SIGNAL,PARKING, & BACKUP LAMPS

(EHOWELL) Replaced clearance/marker lamp assembly (3 lamps) on the dolly. Soldered wire and used heat shrink. EH .2 HR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 42920

USING DEPT NO:	507121	OPENED DATE:	04/13/2022 13:10:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2022 09:13:22	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2022 14:41:29	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.43	\$50.15	\$0.00	\$0.00	\$50.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.43 50.15 0.00 2.00 52.15

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	11074414	04/14/2022 07:42:43	04/14/2022 08:08:13	0.43	\$50.15
					LABOR	50.15

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 42920

Work Order Notes

(CHANNELL) inspect unit

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(SHARBIN) Adjusted tire pressure. All DOT dates are 3516 tires are almost 6 years old. Checked brake fluid hydraulic lines battery lights and safety chains. Greased fittings on the trailer tounge and operated hydraulic lifts. Did not find any issues at this time. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 44497

USING DEPT NO:	507121	OPENED DATE:	08/29/2022 09:48:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2022 11:38:12	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/01/2022 11:02:58	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-EQ-019	INSPECT MP5000 CRASH BARRIER	DON	O	N	GARAGE	0.49	\$57.56	\$0.00	\$0.00	\$57.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.49	57.56	0.00	5.00	62.56
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-EQ-019	INSPECT MP5000 CRASH BARRIER	12296277	08/29/2022 14:56:28	08/29/2022 15:25:44	0.49	\$57.56
					LABOR	57.56

Work Order Charge Detail

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 44497

Work Order Notes

(LISAPATE) Inspect MP5000

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(LISAPATE) JM completed inspection

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 46514

USING DEPT NO:	507121	OPENED DATE:	03/23/2023 10:23:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2023 15:51:22	METER 1 - M:	0	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2023 07:58:59	IN-SERVICE DATE:	09/06/2017	
TECH SPEC NO:	17DELTACRASH	2017 Delta Sc. Crash Barrier MP500-16		UNIT SERIAL NO:	1DPBB1829HC503127 S/N: 92404I	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-066	REPLACE NEW TRAILER 4WIRE FLAT/7	DON	O	N	GARAGE	0.50	\$59.00	\$12.02	\$0.00	\$71.02
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.00	118.00	12.02	5.00	135.02
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-066	REPLACE NEW TRAILER 4WIRE FLAT/7 PIN CONN	12052187	03/23/2023 12:35:26	03/23/2023 13:05:26	0.50	\$59.00
03-51-066	REPLACE NEW TRAILER 4WIRE FLAT/7 PIN CONN	12052187	03/23/2023 12:35:26	03/23/2023 12:35:26	0.00	\$0.00
03-51-066	REPLACE NEW TRAILER 4WIRE FLAT/7 PIN CONN	12052187	03/23/2023 12:35:26	03/23/2023 12:35:26	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/23/2023 12:29:48	03/23/2023 12:29:48	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/23/2023 12:29:48	03/23/2023 12:29:48	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/23/2023 12:29:48	03/23/2023 12:59:48	0.50	\$59.00
LABOR						118.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-066	REPLACE NEW TRAILER 4WIRE FLAT/7 PIN CONN	HOP48505	MALE 7PIN RV CONNECTOR	12.02	1	\$12.02
PARTS						12.02

Work Order Charge Detail

The University of Alabama

Report Printed: 02/29/2024 15:55:30 By User: GLOBETTI

UNIT NO: 243417 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 46514

Work Order Notes

(LISAPATE) DO SI

Job Notes

03-51-066 - REPLACE NEW TRAILER 4WIRE FLAT/7 PIN CONN

(JWRIGHT) Replaced 7-way plug and repaired 4-way rear plug. JAW
1hr labor

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Inspected unit. Tires are outdated but still good. Will not replace them at this time. 7-way plug is broken. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Feb 29 2024 15:55:30 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243417') //Q=