The University of Alabama

UNIT NO:		243422	2017 MP50	00-16	CRAS	SHBAF	RIER		WORK		D: 3	6534		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507121 CLOSED SCHEDULED 17DELTACRASH		OPENE COMPL CLOSE Delta Sc.	ETED I D DATE	DATE: E:	05/28/202	20 08:08:57 20 09:41:36 20 13:52:42	METER 1	- M: 0 CE DATE:	N 09/06/20	ity Automotive S IETER 2 - N: 017 1822HV503132	0	1091-
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABC	<u>R MATI</u>	<u>ERIAL</u>	COMMERCIAL	<u>TOTAL</u>	COST
06-65-001	INSPECT	ASSEMBLY - HYD	RAULIC SYS	DON	0	Ν	GARAGE	0.50	\$0.00	\$4.94	\$	0.00	\$4.94	
RS-65-001	RESEAL	ASSEMBLY - HYDI	RAULIC SYS1	DON	0	Ν	GARAGE	1.50	\$0.00	\$0.00	\$	0.00	\$0.00	
JOB COUN	T: 2				WO	RK ORI	DER TOTAL:	2.0	0	0.00	4.94	0.00		4.94
Job Code		Job Descript	<u>ion</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	11	213180		05	/21/2020 09:30:0	0 05/21/2	2020 11:32:17		2.04		\$0.00
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	11	213180		05	/21/2020 09:04:4	5 05/21/2	2020 09:34:45		0.50		\$0.00
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	11	213180		05	/21/2020 09:04:4	5 05/21/2	2020 09:15:00		(0.17)		\$0.00
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	11	213180		05	/21/2020 09:04:4	5 05/21/2	2020 09:15:00		0.17		\$0.00
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	11	213180		05	/21/2020 09:30:0	0 05/21/2	2020 11:32:17		(2.04)		\$0.00
RS-65-001	RESEAL AS	SEMBLY - HYDRAUL	IC SYSTEMS	11	213180		05	/28/2020 07:00:0	0 05/28/2	2020 08:30:00		1.50		\$0.00
												LABOR		0.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	De	scription		Unit Price	<u>Quantity</u>	Total	Cost
06-65-001	INSPECT AS	SEMBLY - HYDRAUI	LIC SYSTEMS	С	111		RE	ED BRAKE CLEA	NER		2.4	7 2		\$4.94
												PARTS		4.94

UNIT NO: 243422 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 36534

Work Order Notes

(EKIMBREL) Hydraulics leaking

Job Notes

06-65-001 - INSPECT ASSEMBLY - HYDRAULIC SYSTEMS

(EKIMBREL) MS found fluid seeping from grommet in the top of reservoir.

RS-65-001 - RESEAL ASSEMBLY - HYDRAULIC SYSTEMS

(EKIMBREL) MS used RTV to seal top of grommet into fixed position, rechecked and no leaks found at this time. Thoroughly cleaned entire area where fluid was found.

The University of Alabama

UNIT NO: 243422 20		017 MP5000-16	CRAS	SHBAF	RRIER		WORK ORD	ER NO	: 3	6935		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENE COMPL CLOSE 2017 Delta Sc	ETED	DATE: E:	06/24/20 06/24/20	020 07:21:03 020 13:24:50 020 13:53:50	LOCATION: G METER 1 - M: IN-SERVICE D/ UNIT SERIAL N	0 ATE:	M 09/06/20	ETER 2 - N:	0
JOB CODE	_	JOB DESCRIPTION		<u>RSN</u>	<u>WRTY</u>	JOB LOC		LABOR	MATE		OMMERCIAL	TOTAL COST
03-37-022	REPLAC	E NEW BATTERY	DON	0	N	GARAGE	0.50	\$0.00	\$131.72	\$0	0.00	\$131.72
66-79-002	PERFOR	M SERVICE CALL	DON	В	Ν	GARAGE	1.04	\$0.00	\$0.00	\$0).00	\$0.00
JOB COUN	T: 2			WO		DER TOTAL	.: 1.54	0.00		131.72	0.00	131.72
Job Code		Job Descriptior	<u>1</u>	<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fini</u>	<u>sh</u>		<u>Quantity</u>	Total Cost
03-37-022	REPLACE N	EW BATTERY	1	2052187	7	0	6/24/2020 13:22:14	06/24/2020 1	3:52:14		0.50	\$0.00
66-79-002	PERFORM S	SERVICE CALL	1	1901357	,	0	6/24/2020 07:23:46	06/24/2020 0	8:26:15		1.04	\$0.00
											LABOR	0.00
Job Code		Job Descriptior	<u>1</u>		Part No	<u>.</u>	Des	cription	<u> </u>	<u>Unit Price</u>	Quantity	Total Cost
03-37-022	REPLACE N	EW BATTERY	Р	IC2233F	ΡŢ	F	NING TERM HS 12-	10GA 5/16 5PC		3.91	2	\$7.82
03-37-022	REPLACE N	EW BATTERY	8	231		В	ATTERY BCI 31D0	C 100AH/800MCA		123.90) 1	\$123.90
66-79-002	PERFORM S	SERVICE CALL	3	1S30		В	ATTERY BCI 31 H	D STUD 950 CCA		87.09) 1	\$87.09
66-79-002	PERFORM S	SERVICE CALL	3	1S30		В	ATTERY BCI 31 HE	D STUD 950 CCA		87.09) (1)	(\$87.09)
03-37-022	REPLACE N	EW BATTERY	3	1S30		В	ATTERY BCI 31 HE	D STUD 950 CCA		87.09) 1	\$87.09
03-37-022	REPLACE N	EW BATTERY	3	1S30		В	ATTERY BCI 31 HE	D STUD 950 CCA		87.09) (1)	(\$87.09)
											PARTS	131.72

UNIT NO: 243422 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 36935

Work Order Notes

(LISAPATE) Tim requested a service call to Transit lot unit has a dead battery

Job Notes

03-37-022 - REPLACE NEW BATTERY

(IFALLS) Removed and installed a new deep cycle battery Rechecked ok (IFALLS) JW installed 2 new ring terminals at battery.

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Jumped off and Tim brought to the shop

The University of Alabama

UNIT NO:		243422 20	017 MP5	000-16	CRAS	SHBAF	RRIER		WORK OF):	37820	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	2017	OPENE COMPL CLOSE Delta Sc.	ETED	DATE: E:	09/29/202	20 13:10:31 20 16:24:36 20 16:25:17	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 0 E DATE :	09/06/	rsity Automotive \$ METER 2 - N: /2017 B1822HV503132	0
JOB CODE	L	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL		TOTAL COST
06-EQ-019	INSPECT	۲ MP5000 CRASH BAI	RRIER	DON	0	Ν	GARAGE	0.30	\$21.75	\$0.00		\$0.00	\$21.75
19-34-004	WIRE/RE	WIRE CLEARANCE/	MARKER	DON	0	Ν	GARAGE	1.50	\$108.75	\$0.00		\$0.00	\$108.75
JOB COUN	IT: 2				WO		DER TOTAL:	1.80	130	.50	0.00	0.00	130.50
Job Code		Job Description	<u>1</u>		<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	I	inish		<u>Quantity</u>	Total Cost
06-EQ-019	INSPECT M	P5000 CRASH BARRIER	R	1	1310047	,	09/	/29/2020 16:23:48	09/29/202	0 16:41:48		0.30	\$21.75
19-34-004	WIRE/REWI	RE CLEARANCE/MARK	ER	1	1170580	1	09/	/29/2020 16:23:54	09/29/202	0 17:53:54		1.50	\$108.75
												LABOR	130.50

The University of Alabama

UNIT NO:	243422	2017 MP5000-16 CRASHBARRIER	WORK ORDER NO:	37820
Work Order Notes	<u>s</u>			
(LISAPATE) Inspect u	init for beginning of	Football		
Job Notes				
06-EQ-019 - INSPEC	T MP5000 CRASH	BARRIER		
(LISAPATE) EH inspe	cted trailer			
19-34-004 - WIRE/RE		CE/MARKER		
(LISAPATE) AB rewire	ed trailer harness			

The University of Alabama

UNIT NO:		243422 20	17 MP50	00-16	CRAS	SHBAF	RRIER		WORK O	RDER NO	: 3	7862	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH		OPENE COMPL CLOSE	ETED	DATE: E:	10/07/202	20 09:27:19 20 11:17:40 20 13:51:53	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 0 E DATE:	M 09/06/20	ty Automotive S I ETER 2 - N: 017 822HV503132	0
JOB CODE	-	JOB DESCRIPTION		STAT	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE			TOTAL COST
06-65 CH-32-002	_	FHYDRAULIC SYSTEM BATTERY	IS-SPECI	DON DON	0 0	N N	GARAGE GARAGE	0.10 0.25	\$11.77 \$29.50	\$0.00 \$0.00		0.00 0.00	\$11.77 \$29.50
JOB COUN	IT: 2				wo		DER TOTAL:	0.35	5 41	.27	0.00	0.00	41.27
Job Code		Job Description			Em	nployee	<u>No.</u>	<u>Start</u>	ļ	<u>Finish</u>		<u>Quantity</u>	Total Cost
CH-32-002	CHARGE BA	ATTERY		1	1310047	,	10/	/07/2020 07:00:00	10/07/202	20 07:15:00		0.25	\$29.50
06-65	INSPECT H	YDRAULIC SYSTEMS-SPE	ECIAL APPI	_ 1	1310047	,	10/	/06/2020 15:09:18	10/06/202	20 15:15:17		0.10	\$11.77
												LABOR	41.27

UNIT NO: 243422 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 37862

Work Order Notes

(LISAPATE) Per BJ check for hyd leak and check batteries

Job Notes

06-65 - INSPECT HYDRAULIC SYSTEMS-SPECIAL APPL

(LISAPATE) The electrical system for the hydraulics is operating as designed. The hydraulic system was likely over filled with fluid and pushed excess fluid out of the system. Checked for fluid leaks and verified operation of hydraulic system multiple times. EH

CH-32-002 - CHARGE BATTERY

(LISAPATE) Battery tested good. Charged battery over night.

The University of Alabama

UNIT NO:		243422 20)17 MP5000-16 (CRASHBA	RRIER			IO: 3	8409	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENEL COMPLE CLOSEL 2017 Delta Sc.	ETED DATE: D DATE:	11/19/202 11/20/202	20 12:00:41 20 12:01:19 20 10:07:04	LOCATION: GARAG METER 1 - M: 0 IN-SERVICE DATE: UNIT SERIAL NO:	M 09/06/20	ETER 2 - N:	0
JOB CODE 03-32-002		JOB DESCRIPTION E NEW BATTERY	<u>STAT</u> DON	RSN WRTY O N	<u>JOB LOC</u> GARAGE	LABOR HRS 0.59	LABOR MA \$69.46 \$100.4		COMMERCIAL	<u>TOTAL COST</u> \$169.94
JOB COUN	NT: 1			WORK OF		0.59	69.46	100.48	0.00	169.94
<u>Job Code</u> 03-32-002	REPLACE N	Job Description		Employee 310047		<u>Start</u> /19/2020 07:58:48	<u>Finish</u> 11/19/2020 08:34:07	,	Quantity 0.59	<u>Total Cost</u> \$69.46 69.46
Job Code 03-32-002	REPLACE N	Job Description		Part N HM		Des DBATTERY DC 29	<u>cription</u> M/31S 100AH	<u>Unit Price</u> 100.48		Total Cost \$100.48 100.48

243422 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: UNIT NO:

38409

Work Order Notes

(EKIMBREL) Inspect battery. Bad?

Job Notes

03-32-002 - REPLACE NEW BATTERY

(EHOWELL) Replaced battery and cleaned all connections at battery. Verified charging system operation. The battery is charging at 15.4 volts. EH

06-32-002 - INSPECT BATTERY

The University of Alabama

UNIT NO:	NIT NO: 243422 2017 MP50				CRAS	SHBAF	RIER		WORK OF):	39649		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH		OPENE COMPL CLOSE Delta Sc	ETED	DATE: E:	04/27/202	21 09:01:25 21 10:03:32 21 15:00:23	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	I: 0 DATE :	l 09/06/2	sity Automotive \$ METER 2 - N: 2017 31822HV503132	0	09F
JOB CODE	L	JOB DESCRIPTION	<u>l</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL 0	<u>COST</u>
03-13-007	REPLAC	E NEW LINES & FITT	INGS, AIR	DON	0	Ν	GARAGE	0.97	\$114.39	\$122.23	5	\$0.00	\$236.62	
15-32-002	WARRAN	NTY BATTERY		DON	W	J	GARAGE	0.19	\$21.83	\$0.00	:	\$0.00	\$21.83	
35-32	DIAGNO	SE CRANKING SYST	EM	DON	0	Ν	GARAGE	0.10	\$12.29	\$0.00	1	\$0.00	\$12.29	
66-79-003	PERFOR	M SAFETY INSPECT	ION	DON	Ρ	Ν	GARAGE	2.93	\$346.23	\$12.92	:	\$0.00	\$359.15	
JOB COUN	IT: 4				wo	RK ORI	DER TOTAL	4.19	494.	74	135.15	0.00)	629.89
Job Code					Em	ployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		<u>Quantity</u>	Total (<u>Cost</u>
15-32-002	WARRANTY	BATTERY		1	1310047		04	/14/2021 08:35:54	04/14/202	1 08:47:00		0.19		\$21.83
66-79-003	PERFORM	SAFETY INSPECTION		1	1310047		04	/15/2021 07:03:51	04/15/202	1 09:59:39		2.93		\$345.74
66-79-003	PERFORM	SAFETY INSPECTION		1	1310047		04	/15/2021 14:14:18	04/15/202	1 14:14:33		0.00		\$0.49
35-32	DIAGNOSE	CRANKING SYSTEM		1	1310047		04	/27/2021 07:00:00	04/27/202	1 07:06:00		0.10		\$11.80
03-13-007	REPLACE N	IEW LINES & FITTINGS,	AIR & HYD.	1	1310047		04	/15/2021 13:15:54	04/15/202	1 14:14:04		0.97		\$114.39
35-32	DIAGNOSE	CRANKING SYSTEM		1	1310047		04	/14/2021 08:49:49	04/14/202	1 08:50:04		0.00		\$0.49
												LABOR		494.74
Job Code		Job Description	<u>1</u>			Part No	<u>.</u>	Des	cription		Unit Pric	e Quantity	<u>Total (</u>	Cost
66-79-003	PERFORM	SAFETY INSPECTION		1	0005		GI	REASE RED N TA	CKY NO 2 LUCA	AS	6.8	89 1		\$6.89
66-79-003	PERFORM	SAFETY INSPECTION		В	RAKE F	LUID	BF	RAKE FLUID DOT	3 12OZ		3.0	02 2		\$6.03
03-13-007	REPLACE N	IEW LINES & FITTINGS,	INES & FITTINGS, AIR & HYD. HYD HOSE 1 WIRE 1/4IN			E 1/4IN H`	/D HOSE 1 WIRE	1/4IN		118.9	94 1		\$118.94	
03-13-007	REPLACE N	IEW LINES & FITTINGS,	AIR & HYD.	C	111		RI	ED BRAKE CLEAN	IER		3.2			\$3.29
												PARTS		135.15

UNIT NO: 243422 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO: 39649

Work Order Notes

(LISAPATE) Per driver batteries are bad (LISAPATE) Do annual safety inspection

Job Notes

03-13-007 - REPLACE NEW LINES & FITTINGS, AIR & HYD.

(EHOWELL) Replaced 10 ft. braided brake hose. Filled with brake fluid, bled at all four wheels, and inspected for leaks afterwards. Verified all four brakes are applying after repairs. EH/AMG .7HR

15-32-002 - WARRANTY BATTERY

(EHOWELL) Battery was less than one year old. Replaced battery under warranty. EH

35-32 - DIAGNOSE CRANKING SYSTEM

(EHOWELL) Found battery at 2 volts. It appeared that the battery leaked out an excessive amount of fluid. Verified operation of the charging system. EH

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Performed Safety/Equipment Inspection. Found 10 ft. braided brake line leaking brake fluid. Checked lights, hitch operation, wheel bearings, hydraulic jack operation, safety chains, and tire pressures. Checked for hydraulic leaks, greased wheel bearings and trailer tongue fittings, and verified operation of barrier using the remote control. EH

The University of Alabama

UNIT NO:		243422 2	017 MP5	000-16	CRAS	SHBAF	RRIER		WORK OR	DER NO	: 4	40370	
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	2017	OPENE COMPL CLOSE Delta Sc.	ETED D DATI	DATE: E:	07/15/20	21 14:07:33 21 11:26:37 21 11:52:36	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	0 DATE:	I 09/06/2	sity Automotive S METER 2 - N: 2017 1822HV503132	0
JOB CODE	L	JOB DESCRIPTION	<u>1</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL COST
03-31-200	REPLAC	E NEW BATTERY CH	IARGER	DON	0	Ν	GARAGE	0.92	\$108.04	\$244.42	S	\$0.00	\$352.46
14-37-042	INSTALL	BATTERY VOLTAGE	METER	DON	0	Ν	GARAGE	1.13	\$133.05	\$25.48	5	\$0.00	\$158.53
JOB COUN	B COUNT: 2				WO	RK ORI	DER TOTAL	: 2.04	4 241.0	9	269.90	0.00	510.99
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	Fi	<u>nish</u>		Quantity	Total Cost
03-31-200	REPLACE N	IEW BATTERY CHARGE	ER	1'	1213180	1	07	7/14/2021 13:00:0	0 07/14/2021	13:24:56		0.42	\$49.04
03-31-200	REPLACE N	IEW BATTERY CHARGE	ER	11	1213180	1	07	7/14/2021 11:59:5	5 07/14/2021	12:29:55		0.50	\$59.00
03-31-200	REPLACE N	IEW BATTERY CHARGE	ER	1'	1213180	1	07	7/14/2021 11:59:5	5 07/14/2021	11:59:55		0.00	\$0.00
03-31-200	REPLACE N	IEW BATTERY CHARGE	ĒR	1	1213180	1	07	7/14/2021 11:59:5	5 07/14/2021	11:59:55		0.00	\$0.00
14-37-042	INSTALL BA	TTERY VOLTAGE METE	ER	1	1213180	1	07	7/09/2021 09:16:0	1 07/09/2021	10:23:40		1.13	\$133.05
												LABOR	241.09
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	De	scription	<u>I</u>	Unit Pric	e Quantity	Total Cost
14-37-042	INSTALL BA	TTERY VOLTAGE METE	ΞR	Х	001V0H	EEF	B/	ATTERY METER			25.4	48 1	\$25.48
03-31-200	REPLACE N	IEW BATTERY CHARGE	ER	S	EC1215	UL	B	ATTERY CHARGE	ER MP5000		244.4	121	\$244.42
												PARTS	269.90

243422 2017 MP5000-16 CRASHBARRIER UNIT NO:

WORK ORDER NO:

40370

Work Order Notes

(LISAPATE) Install battery voltage meter on trailer

Job Notes

03-31-200 - REPLACE NEW BATTERY CHARGER

(MSIDES) Replaced battery charger and replaced wiring to battery, rechecked unit now charging at 14 volts as designed. MS

14-37-042 - INSTALL BATTERY VOLTAGE METER

(MSIDES) Installed volt meter and wired to switch. MS

The University of Alabama

UNIT NO:		243422 2	017 MP5	000-16	CRAS	SHBAF	RRIER		WORK OF	DER NO:	4	0935	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507121 CLOSED SCHEDULED 17DELTACRASH	2017	OPENE COMPL CLOSE Delta Sc.	ETED	DATE: E:	09/08/202	1 10:04:18 1 11:31:46 1 07:31:00	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	I: 0 DATE:	M 09/06/20	ty Automotive S ETER 2 - N: 017 822HV503132	0
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>l</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL C	OMMERCIAL	TOTAL COST
06-EQ-019	INSPEC	T MP5000 CRASH BA	RRIER	DON	0	Ν	GARAGE	0.20	\$23.31	\$0.00	\$0	0.00	\$23.31
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00
JOB COUN	T: 2				WO		DER TOTAL:	0.20	23.	31	0.00	2.00	25.31
Job Code		Job Description	<u>n</u>		v	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No.	<u>.</u>		Total Cost
CH-SP	CHARGE SI	hop Supplies		5	03163		1						\$2.00
												COMML	2.00
Job Code		Job Description	<u>n</u>		En	nployee	<u>No.</u>	<u>Start</u>	<u> </u>	<u>inish</u>		<u>Quantity</u>	<u>Total Cost</u>
06-EQ-019	INSPECT M	P5000 CRASH BARRIEF	२	11	1170580		09/	07/2021 09:42:49	09/07/202	1 09:54:40		0.20	\$23.31
												LABOR	23.31

The University of Alabama Report Printed: 02/29/2024 16:00:28 By User: GLOBETTI

UNIT NO:	243422	2017 MP5000-16 CRASHBARRIER	WORK ORDER NO:	40935
Work Order Not	es			
(LISAPATE) Perform	n safety inspection pr	ior to Football season		
Job Notes				
06-EQ-019 - INSPE	CT MP5000 CRASH	BARRIER		
(ABLACK) AB perfo	rmed safety inspectio	n		
CH-SP - CHARGE	Shop Supplies			

The University of Alabama

UNIT NO:		243422 2	2017 MP5	5000-16	CRAS	SHBAF	RRIER		WORK OF	RDER NO	: 4	1019	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507121 CLOSED SCHEDULED 17DELTACRASH	2017	OPENE COMPL CLOSE Delta Sc.	ETED	DATE: E:	09/16/202	1 12:15:44 1 08:08:46 1 12:25:10	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	M: 0 E DATE:	N 09/06/2	ity Automotive S IETER 2 - N: 017 1822HV503132	0
JOB CODE	L	JOB DESCRIPTION	<u>N</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	<u>RIAL</u>		TOTAL COST
06-EQ-019	INSPEC ⁻	T MP5000 CRASH BA	ARRIER	DON	0	Ν	GARAGE	1.98	\$233.54	\$0.00	\$	0.00	\$233.54
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	2.00	\$2.00
JOB COUN	T: 2				WO		DER TOTAL:	1.98	233	.54	0.00	2.00	235.54
Job Code		Job Descriptio	<u>n</u>		v	endor N	<u>o.</u>	Invoice No.	Purcha	se Order No	<u>).</u>		Total Cost
CH-SP	CHARGE SI	hop Supplies		5	03163		1						\$2.00
												COMML	2.00
Job Code		Job Descriptio	<u>n</u>		En	nployee	No.	<u>Start</u>	Ī	-inish		<u>Quantity</u>	<u>Total Cost</u>
06-EQ-019	INSPECT M	P5000 CRASH BARRIE	R	1	1310047	,	09/	14/2021 12:46:30	09/14/202	21 14:45:15		1.98	\$233.54
												LABOR	233.54

243422 UNIT NO: 2017 MP5000-16 CRASHBARRIER

WORK ORDER NO:

41019

Work Order Notes

(LISAPATE) Do annual safety inspection for Football season

Job Notes

06-EQ-019 - INSPECT MP5000 CRASH BARRIER

(EHOWELL) Battery was replaced this year and reads 100%. Battery tested good, charger and extension cord are working, operated barrier plate w/remote, checked wheel bearings, operated jacks, checked tire pressures, greased trailer tongue and hub bearings, checked for hydraulic leaks, checked brake fluid, ran lights, and gave one light bub a better connection. EH

The University of Alabama

UNIT NO:	NIT NO: 243422 201		017 MP5000-16	CRA	SHBAF	RRIER		WORK OR		: 4 [,]	1447		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENE COMPL CLOSE 2017 Delta Sc	ETED D DAT	DATE: E:	11/08/202 11/08/202	21 08:21:24 21 11:48:27 21 14:42:41	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 0 DATE :	M 09/06/20	ty Automotive \$ ETER 2 - N: 117 822HV503132	0	109F
JOB CODE	L	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY	DON	0	Ν	GARAGE	0.38	\$45.20	\$110.55	\$0	0.00	\$155.75	
06-31	INSPEC ⁻	T CHARGING SYSTEM	DON	0	Ν	GARAGE	0.02	\$2.82	\$0.00	\$0	0.00	\$2.82	
CH-SP	CHARGE	E Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	2.00	\$2.00	
JOB COUN	IT: 3			WC		DER TOTAL	0.41	48.0	02	110.55	2.00		160.57
Job Code		Job Description	<u>l</u>	v	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No	<u>.</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies	5	03163		1					_		\$2.00
											COMML		2.00
Job Code		Job Description	<u>l</u>	En	nployee	<u>No.</u>	<u>Start</u>	F	<u>inish</u>		Quantity	Total	Cost
03-32-002	REPLACE N	IEW BATTERY	1	1213180)	10	/29/2021 12:48:32	10/29/2022	1 13:11:31		0.38		\$45.20
06-31	INSPECT C	HARGING SYSTEM	1	1213180)	10	/29/2021 12:46:57	10/29/202	1 12:48:23		0.02		\$2.82
											LABOR		48.02
Job Code		Job Description	<u>l</u>		Part No	<u>.</u>	Des	cription	<u>L</u>	Init Price	Quantity	Total	Cost
03-32-002	REPLACE N	IEW BATTERY	3	1MGM		31	MARINE BATTER	XY MP5000		221.08	1		\$221.08
03-32-002	REPLACE N	IEW BATTERY	3	1MGM		31	MARINE BATTER	Y MP5000		221.08	(1))	(\$221.08
03-32-002	REPLACE N	IEW BATTERY	3	1MGM		31	MARINE BATTER	Y MP5000		110.55	1		\$110.55
											PARTS		110.55

243422 2017 MP5000-16 CRASHBARRIER UNIT NO:

WORK ORDER NO:

41447

Work Order Notes

(LISAPATE) check charging system

Job Notes

03-32-002 - REPLACE NEW BATTERY

(MSIDES) After reading operation/repair manual found battery in unit to be under rated from what the manual calls for. Replaced battery with one rated at 100 amp hours which is called for in the manual. MS

06-31 - INSPECT CHARGING SYSTEM

(MSIDES) Found on board battery charger to be charging as designed (12 volts 15 AMPs). MS 1.0hrs

The University of Alabama

UNIT NO:		243422 201	7 MP5000-1	6 CRA	SHBAF	RRIER		WORK OR	DER NO:	42930	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507121 CLOSED SCHEDULED 17DELTACRASH	СОМІ	IED DAT PLETED ED DAT c. Crash	DATE: E:	04/18/202 04/18/202	2 07:23:11 2 09:55:18 2 14:30:34	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 0 DATE: 0!	niversity Automotive METER 2 - N: 9/06/2017 D9BB1822HV50313	0
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>STA</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIA	L COMMERCIA	L TOTAL COST
66-79-003	PERFOR	RM SAFETY INSPECTIO	N DON	0	Ν	GARAGE	0.60	\$71.10	\$0.00	\$0.00	\$71.10
CH-SP	CHARGE	E Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
JOB COUN	T: 2			wo	ORK ORI	DER TOTAL:	0.60	71 .1	10 (0.00 2.0	0 73.10
Job Code		Job Description		7	/endor N	<u>lo.</u>	Invoice No.	Purchase	<u>e Order No.</u>		Total Cost
CH-SP	CHARGE SI	hop Supplies		503163		1					\$2.00
										COMML	2.00
Job Code		Job Description		Er	nployee	No.	<u>Start</u>	<u>Fi</u>	inish	Quantity	Total Cost
66-79-003	PERFORM	SAFETY INSPECTION		1107441	4	04/	15/2022 07:26:12	04/15/2022	2 08:02:21	0.6	0 \$71.10
										LABOR	71.10

243422 2017 MP5000-16 CRASHBARRIER UNIT NO:

WORK ORDER NO:

42930

Work Order Notes

(LISAPATE) Perform annual inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Adjusted tire pressure. All DOT dates are 4116. The tires are almost 6 years old. Checked brake fluid hydraulic lines battery lights and safety chains. Greased fittings on the trailer tounge and operated hydraulic lifts. Found no issues at this time. SH

The University of Alabama

UNIT NO:		243422 2017	MP5000-16	CRAS	SHBAR	RIER		WORK OF	RDER NO:	44417	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENE COMPL CLOSE 2017 Delta Sc.	ETED D DAT	DATE: E:	08/23/202 08/24/202	2 14:20:49 2 15:01:40 2 07:16:15	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 0 DATE: 0	Jniversity Automotive METER 2 - N: 19/06/2017 D9BB1822HV5031	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIA	AL COMMERCIA	L TOTAL COST
66-79-003	PERFOR	RM SAFETY INSPECTION	DON	Р	Ν	GARAGE	0.26	\$30.25	\$0.00	\$0.00	\$30.25
CH-SP	CHARGE	E Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
JOB COUN	IT: 2			WC		DER TOTAL:	0.26	30.	25	0.00 5.0	00 35.25
Job Code		Job Description		v	endor N	<u>o.</u>	Invoice No.	Purchas	se Order No.		Total Cost
CH-SP	CHARGE SI	hop Supplies	50	03163		1					\$5.00
										COMML	5.00
Job Code		Job Description		En	nployee	No.	<u>Start</u>	Ē	<u>inish</u>	Quantity	<u>Total Cost</u>
66-79-003	PERFORM	SAFETY INSPECTION	1'	1901357	,	08/	23/2022 08:59:37	08/23/202	2 09:15:00	0.2	\$30.25
										LABOR	30.25

243422 2017 MP5000-16 CRASHBARRIER UNIT NO:

WORK ORDER NO:

44417

Work Order Notes

(CWIGLEY) Inspection

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) Completed safety inspection. Tires are outdated but show no signs of dry rot or abnormal wear. Will run tires for another year and reevaluate. No other issues found. AMG

(IFALLS) Issac spoke with Charlie about all tires on mp5000 being out of date. Charlie said if they could hold off this yr and if they keep them next yr he would replace the tires at that time.

The University of Alabama

UNIT NO: 243422 20 ⁷)17 MP5000-16	CRA	SHBAF	RRIER		WORK OR	DER NO:	45325	5325			
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENE COMPI CLOSE 2017 Delta Sc	ETED	DATE: E:	11/22/202 11/30/202	2 07:01:33 2 14:21:16 2 07:46:33	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	DATE: 09/06	ersity Automotive 5 METER 2 - N: 5/2017 B1822HV503132	0			
JOB CODE		JOB DESCRIPTION		<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST			
03-32-002	REPLAC	E NEW BATTERY	DON	Р	N	GARAGE	0.03	\$4.03	\$221.08	\$0.00	\$225.11			
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00			
JOB COUN	NT: 2			wo	ORK ORI	DER TOTAL:	0.03	4.0)3 221.08	5.00	230.11			
Job Code		Job Description		V	/endor N	<u>o.</u>	Invoice No.	<u>Purchas</u>	e Order No.		Total Cost			
CH-SP	CHARGE SI	nop Supplies	5	03163		1					\$5.00			
										COMML	5.00			
Job Code		Job Description		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	F	inish	<u>Quantity</u>	Total Cost			
03-32-002	REPLACE N	IEW BATTERY	1	205218	7	11/	21/2022 07:08:21	11/21/2022	07:10:24	0.03	\$4.03			
										LABOR	4.03			
Job Code		Job Description			Part No	<u>.</u>	Des	cription	<u>Unit Pr</u>	ice <u>Quantity</u>	Total Cost			
03-32-002	REPLACE N	IEW BATTERY	3	1MGM		31	MARINE BATTER	RY MP5000	22	1.081	\$221.08			
										PARTS	221.08			

UNIT NO: 243422 2017 MP5000-16 CRASHBARRIER WORK ORDER NO: 45325

Work Order Notes

(CWIGLEY) Replaced Battery.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Battery went dead in mp5000 and wouldn't hold charge. Replaced with new. JAW, RC

The University of Alabama

UNIT NO:		243422 2017	' MP5000-16	CRAS	SHBAF	RRIER		WORK O	RDER NO) :	46510		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507121 CLOSED SCHEDULED 17DELTACRASH	OPENE COMPL CLOSE 2017 Delta Sc.	ETED D DATI	DATE: E:	03/23/202 03/24/202	3 10:18:50 3 15:53:16 3 07:56:35	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 0 E DATE:	09/06	rsity Automotive METER 2 - N: /2017 B1822HV503132	0	1091
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	<u>TOTAL</u>	COST
66-79-003	PERFOR	M SAFETY INSPECTION	DON	Ρ	Ν	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00	
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
JOB COUN	IT: 2			wo	RK ORI	DER TOTAL:	0.50	59	9.00	0.00	5.00)	64.00
Job Code		Job Description		<u>v</u>	endor N	<u>lo.</u>	Invoice No.	Purcha	ase Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies	50	03163		1							\$5.00
											COMML		5.00
Job Code		Job Description		En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-79-003	PERFORM S	SAFETY INSPECTION	12	2052187	7	03/	23/2023 12:13:49	03/23/20	23 12:13:49		0.00		\$0.00
66-79-003	PERFORM S	SAFETY INSPECTION	12	2052187	,	03/	23/2023 12:13:49	03/23/20	23 12:13:49		0.00		\$0.00
66-79-003	PERFORM S	SAFETY INSPECTION	12	12052187			23/2023 12:13:49	03/23/2023 12:43:49			0.50		\$59.00
											LABOR		59.00

The University of Alabama Report Printed: 02/29/2024 16:00:28 By User: GLOBETTI

UNIT NO:	243422	2017 MP5000-16 CRASHBARRIER	WORK ORDER NO:	46510

Work Order Notes

(LISAPATE) Do SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Inspected unit. Tires are outdated but still good. Will not replace them at this time. JAW

The University of Alabama

UNIT NO:	NIT NO: 243422 2017 MP50				CRAS	SHBAF	RRIER		WORK	ORDER NO	:	49057				
WO STATUS WO VISIT R	USING DEPT NO: 507121 WO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 17DELTACRASH 2			COMPLETED DATE: 1			12/05/202 12/06/202	11/27/2023 11:41:17 12/05/2023 13:25:55 12/06/2023 13:54:08 P500-16		-		rsity Automotive \$ METER 2 - N: /2017 B1822HV503132	0			
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABO</u>	<u>R MATE</u>	RIAL	COMMERCIAL	TOTAL	COST		
06-32-002	INSPECT	BATTERY		DON	Ν	Ν	GARAGE	0.51	\$59.92	\$0.00		\$0.00	\$59.92			
24-13-007	REPAIR I	INES & FITTINGS, AIR	& HYD.	DON	Ν	Ν	GARAGE	0.13	\$15.60	\$0.00		\$0.00	\$15.60			
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00			
JOB COUN	IT: 3				WC	RK ORI	DER TOTAL:	0.64		75.52	0.00	5.00		80.52		
Job Code		Job Description			<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purcl	nase Order No	<u>o.</u>		<u>Total</u>	<u>Cost</u>		
CH-SP	CHARGE Sh	op Supplies		50	03163		1							\$5.00		
												COMML		5.00		
Job Code		Job Description			En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	<u>Total</u>	Cost		
06-32-002	INSPECT BA	TTERY		1'	1074414	Ļ	11/	27/2023 13:00:00	11/27/2	2023 13:30:28		0.51		\$59.92		
06-32-002	INSPECT BA	TTERY		1'	1074414	Ļ	11/	27/2023 12:58:42	11/27/2	2023 12:58:42		0.00		\$0.00		
24-13-007	REPAIR LIN	ES & FITTINGS, AIR & HYI	D.	1:	2052187	7	12/	05/2023 07:17:38	12/05/2	2023 07:25:34		0.13		\$15.60		
												LABOR	- <u></u>	75.52		

243422 2017 MP5000-16 CRASHBARRIER UNIT NO:

WORK ORDER NO:

49057

Work Order Notes

(LRUSHING) no power - check battery

Job Notes

06-32-002 - INSPECT BATTERY

(SHARBIN) IF Found a broken wire. SH Repaired the wire rechecks good. SH

24-13-007 - REPAIR LINES & FITTINGS, AIR & HYD.

(JWRIGHT) Replaced brake line fitting and bled brakes. Test drove and found no issues. JAW .5 hr labor (EKIMBREL) fitting was billed to shop. brake fluid was non-inv

Report Title: Report Author: File Path:	WODETAIL - Work Order Detail v20.0 FleetFocus M5 E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1
Data Extracted: TZ:	Thu Feb 29 2024 16:00:28 Report User: GLOBETTI Central Standard Time
DLL Version:	2021.02.23
Report Comments:	6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 Parameters and Selection Filters
First Grouping:	VIEW_WO_WORKSHEET.WO_NO
Second Grouping:	VIEW_WO_WORKSHEET.JOB
Third Grouping:	
Sorted By:	
From Date:	
To Date:	
Option 1:	
Option 2:	
Selection Filters:	isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243422') //Q=