

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY WORK ORDER NO: 20453

USING DEPT NO:	750201	OPENED DATE:	06/03/2015 08:12:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2015 07:05:06	METER 1 - M:	60	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2015 07:05:07	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10260422	06/03/2015 08:13:22	06/03/2015 08:43:22	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 20453

Work Order Notes

(LPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 22286

USING DEPT NO:	750201	OPENED DATE:	01/05/2016 15:39:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2016 13:55:57	METER 1 - M:	6466	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2016 13:55:58	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$13.15	\$34.39	\$0.00	\$47.54

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.23** **13.15** **34.39** **0.00** **47.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/08/2016 09:30:00	01/08/2016 09:43:43	0.23	\$13.15
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/08/2016 09:29:16	01/08/2016 09:29:16	0.00	\$0.00
					LABOR	13.15

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.19	1	\$6.19
					PARTS	34.39

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 22286

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM/RS

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 24126

USING DEPT NO:	750201	OPENED DATE:	08/12/2016 11:31:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/16/2016 13:27:47	METER 1 - M:	12535	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/16/2016 13:27:49	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$51.78	\$35.13	\$0.00	\$86.91

JOB COUNT: 1 WORK ORDER TOTAL: 0.90 51.78 35.13 0.00 86.91

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/15/2016 06:27:10	08/15/2016 07:21:12	0.90	\$51.78
					LABOR	51.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
					PARTS	35.13

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 24126

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 25656

USING DEPT NO: 750201	OPENED DATE: 02/03/2017 09:57:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/06/2017 13:29:35	METER 1 - M: 18161 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/06/2017 13:29:37	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.36	\$0.00	\$59.19

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **41.36** **0.00** **59.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/03/2017 14:19:16	02/03/2017 14:37:52	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
					PARTS	41.36

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 25656

Work Order Notes

(LISAPATE) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB-REPLACED AIR FILTER
COOLANT -37'

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 27076

USING DEPT NO:	750201	OPENED DATE:	08/11/2017 08:49:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2017 09:54:35	METER 1 - M:	24206	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2017 09:54:38	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.78	\$0.00	\$45.61

JOB COUNT: 2 WORK ORDER TOTAL: 0.31 17.83 27.78 46.00 91.61

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	245253	0039732	\$46.00
					COMML 46.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/15/2017 07:00:00	08/15/2017 07:18:36	0.31	\$17.83
					LABOR 17.83	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS 27.78	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 27076

Work Order Notes

(LISAPATE) PM

Job Notes

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) GLASS DR CAME TO THE GARAGE AND REPAIRED DING IN THE WINDSHIELD IN THE DRIVER VIEW. PD BY CC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY TB/CS

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 27978

USING DEPT NO: 750201	OPENED DATE: 10/27/2017 15:16:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/11/2017 06:22:20	METER 1 - M: 27226 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/11/2017 06:22:26	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-00	TRANSPORT COMPLETE VEHICLE	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,327.63	\$1,327.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.90	\$0.00	\$47.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$7.33	\$0.00	\$24.58

JOB COUNT: 4	WORK ORDER TOTAL:	1.61	92.58	37.23	1,327.63	1,457.44
---------------------	--------------------------	-------------	--------------	--------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	5569647	2665	0041328	\$1,327.63
				COMML	1327.63

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/18/2017 10:52:23	11/18/2017 10:52:31	0.00	(\$0.13)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/18/2017 10:52:23	11/18/2017 10:52:31	0.00	\$0.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/18/2017 10:52:23	11/18/2017 11:10:23	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 08:40:09	11/17/2017 08:58:45	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 08:40:09	11/17/2017 13:40:53	5.01	\$288.20
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 08:40:09	11/17/2017 13:40:53	(5.01)	(\$288.20)
16-00	TRANSPORT COMPLETE VEHICLE	10208562	11/20/2017 06:18:00	11/20/2017 07:18:00	1.00	\$57.50
					LABOR	92.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.16	4	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.16	(4)	(\$16.62)
66-PM-PMA	PERFORM OIL CHANGE	SYNOW20	NAPA 0W20	5.75	4	\$22.98
					PARTS	37.23

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 27978

Work Order Notes

(IFALLS) PM AND GET BODY SHOP EST (BROWNS)

Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(IFALLS) EK PERFORMED TRANSPORT TO BROWNS BODY SHOP

24-71 - REPAIR BODY

(LISAPATE) BROWNS REPAIRED BODY DAMGE TO PASSENGER SIDE OF CAR PER THE ESTIMATE. TRAVELERS PAID BROWNS \$1709.56 ON 11/6/17 CK# 88788256. UA PD \$1154.56.

66-02-017 - PERFORM DOOR PANELS

(IFALLS) BROWNS BODY SHOP REPAIRED RIGHT SIDE OF CAR (DEER RAN INTO THE CAR)

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG PERFORMED PM
(IFALLS) USED NAPA 0W20 OIL

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(IFALLS) AG REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 29750

USING DEPT NO: 750201	OPENED DATE: 05/09/2018 14:33:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/14/2018 07:48:29	METER 1 - M: 29868 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/14/2018 07:48:30	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.03	\$0.00	\$61.86

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **44.03** **0.00** **61.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/10/2018 07:00:00	05/10/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.84	1	\$12.84
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	4	\$18.36
					PARTS	44.03

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 29750

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC,EK/AG
COOLANT -20'

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 31072

USING DEPT NO: 750201	OPENED DATE: 10/05/2018 09:13:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/11/2018 07:34:46	METER 1 - M: 32425 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/11/2018 07:34:48	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$41.97	\$0.00	\$64.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **22.48** **41.97** **0.00** **64.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/05/2018 13:42:49	10/05/2018 14:01:25	0.31	\$22.48
					LABOR	22.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	4	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	(4)	(\$23.34)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
					PARTS	41.97

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 31072

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by CS
Coolant -33'

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 32812

USING DEPT NO: 750201	OPENED DATE: 05/03/2019 10:46:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/09/2019 13:25:40	METER 1 - M: 38001 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2019 13:25:41	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.84	\$60.94	\$133.16	\$0.00	\$194.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.13	\$154.47	\$51.27	\$0.00	\$205.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.30	\$21.75	\$7.33	\$0.00	\$29.08

JOB COUNT: 3	WORK ORDER TOTAL:	3.27	237.16	191.76	0.00	428.92
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/07/2019 06:00:00	05/07/2019 06:18:00	0.30	\$21.75
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	05/06/2019 10:38:53	05/06/2019 11:29:19	0.84	\$60.94
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/03/2019 13:03:19	05/03/2019 14:15:41	1.21	\$87.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2019 13:13:47	05/03/2019 14:09:15	0.92	\$67.02
					LABOR	237.15

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	15.20	1	\$15.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.31	1	\$3.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	131657	TIRE P205/65R16 FS AFFIN TOUR	129.85	1	\$129.85
66-PM-PMA	PERFORM OIL CHANGE	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	1	\$0.41
					PARTS	191.76

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 32812

Work Order Notes

(LISAPATE) PM
(LISAPATE) Nail in outer edge of RR tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced new RR tire

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,SH/SH
Coolant -20'
Replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 34365

USING DEPT NO: 750201	OPENED DATE: 10/08/2019 08:07:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/09/2019 11:00:30	METER 1 - M: 43444 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/09/2019 11:00:32	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.97	\$70.57	\$41.88	\$0.00	\$112.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.97** **70.57** **41.88** **0.00** **112.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/08/2019 08:14:16	10/08/2019 08:38:23	0.40	\$29.14
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/08/2019 08:15:04	10/08/2019 08:33:42	0.31	\$22.52
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/08/2019 08:17:52	10/08/2019 08:33:31	0.26	\$18.91
					LABOR	70.57

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.26	1	\$6.26
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
					PARTS	41.88

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 34365

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,AG/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY WORK ORDER NO: 35682

USING DEPT NO:	750201	OPENED DATE:	02/17/2020 14:47:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2020 07:05:43	METER 1 - M:	48633	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/20/2020 07:05:45	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$9.59	\$54.37	\$0.00	\$63.96	
JOB COUNT: 1						WORK ORDER TOTAL:	0.13	9.59	54.37	0.00	63.96

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/17/2020 15:36:57	02/17/2020 15:44:53	0.13	\$9.59
					LABOR	9.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.33	1	\$12.33
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
					PARTS	54.37

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 35682

Work Order Notes

(RTUNAITI) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH/SH. Coolant -35

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY WORK ORDER NO: 36964

USING DEPT NO:	750201	OPENED DATE:	06/26/2020 10:06:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/26/2020 15:06:26	METER 1 - M:	49823	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/29/2020 08:15:02	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$21.65	\$56.31	\$0.00	\$77.96	
JOB COUNT: 1						WORK ORDER TOTAL:	0.30	21.65	56.31	0.00	77.96

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/26/2020 11:26:44	06/26/2020 11:44:39	0.30	\$21.65
					LABOR	21.65

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	14.19	1	\$14.19
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					PARTS	56.31

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 36964

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EK/SH performed pm. Coolant -35

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY WORK ORDER NO: 38451

USING DEPT NO:	750201	OPENED DATE:	11/23/2020 07:47:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/24/2020 08:42:49	METER 1 - M:	49987	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2020 07:59:51	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.91	\$107.18	\$3.30	\$0.00	\$110.48

JOB COUNT: 1 WORK ORDER TOTAL: 0.91 107.18 3.30 0.00 110.48

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2020 14:30:00	11/23/2020 15:12:59	0.72	\$84.53
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2020 14:29:53	11/23/2020 14:29:53	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/23/2020 13:58:25	11/23/2020 14:09:56	0.19	\$22.65
					LABOR	107.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.30	1	\$3.30
					PARTS	3.30

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 38451

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 49987. Vehicle has been driven 164 miles since last PM. Oil was changed at last PM. Checked fluids, battery, tire pressure and up dated oil change sticker. Washed, vacuumed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 39606

USING DEPT NO: 750201	OPENED DATE: 04/08/2021 12:11:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/09/2021 11:18:20	METER 1 - M: 50001 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/12/2021 08:34:27	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.07	\$8.06	\$113.55	\$0.00	\$121.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$78.57	\$36.63	\$0.00	\$115.20

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.73** **86.63** **150.18** **0.00** **236.81**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	04/08/2021 14:50:40	04/08/2021 14:54:46	0.07	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2021 14:30:00	04/08/2021 14:50:28	0.34	\$40.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2021 14:16:58	04/08/2021 14:16:58	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/08/2021 14:30:00	04/08/2021 14:49:29	0.32	\$38.32
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/08/2021 14:19:59	04/08/2021 14:19:59	0.00	\$0.00
					LABOR	86.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	150.18

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 39606

Work Order Notes

(EKIMBREL) pm

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Battery tested bad. Replaced battery. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 50001. SH/AMG Performed PM. RC Washed was full of gas.

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 40382

USING DEPT NO: 750201	OPENED DATE: 07/07/2021 13:47:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/04/2021 15:19:01	METER 1 - M: 50001 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/05/2021 07:38:49	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	0.00	59.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	5569647	5356		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11074414	08/04/2021 07:00:00	08/04/2021 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 40382

Work Order Notes

(LISAPATE) Take to Browns Body Shop to have rear end body repairs made. Browns has a check.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Browns by SH

24-71 - REPAIR BODY

(LISAPATE) Browns Body Shop repaired rear end damage. Charges were paid direct to Browns by USAA. for \$1497.12. and a supplement was filed for \$ 1286.17.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 41347

USING DEPT NO:	750201	OPENED DATE:	10/18/2021 08:15:46	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 15:29:07	METER 1 - M:	50001	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2021 15:29:14	IN-SERVICE DATE:	06/02/2015		
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK7FU064202		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.18	\$20.78	\$1.41	\$0.00	\$22.19
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.47	\$17.90	\$0.00	\$23.37
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.55	\$64.64	\$0.00	\$0.00	\$64.64
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.99	\$117.05	\$550.76	\$0.00	\$667.81
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.90	\$106.23	\$0.00	\$0.00	\$106.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.48	\$34.32	\$0.00	\$80.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.20	\$23.60	\$23.15	\$0.00	\$46.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 8	WORK ORDER TOTAL:	3.26	384.25	627.54	2.00	1,013.79
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/20/2021 11:10:25	10/20/2021 11:20:20	0.17	\$19.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	10/20/2021 12:06:39	10/20/2021 12:18:39	0.20	\$23.60
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	10/20/2021 12:06:39	10/20/2021 12:06:39	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	10/20/2021 12:06:39	10/20/2021 12:06:39	0.00	\$0.00
09-15	ALIGN STEERING	11310047	10/26/2021 07:03:53	10/26/2021 07:36:45	0.55	\$64.64
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/22/2021 07:56:46	10/22/2021 08:56:17	0.99	\$117.05
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/20/2021 10:38:07	10/20/2021 10:51:50	0.23	\$26.98
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11901357	10/20/2021 09:04:26	10/20/2021 09:15:00	0.18	\$20.78
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/20/2021 09:01:19	10/20/2021 09:04:06	0.05	\$5.47
66-79-003	PERFORM SAFETY INSPECTION	11901357	10/18/2021 14:10:55	10/18/2021 14:15:00	0.07	\$8.03

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11901357	10/18/2021 13:00:00	10/18/2021 13:49:56	0.83	\$98.20
66-79-003	PERFORM SAFETY INSPECTION	11901357	10/18/2021 12:51:46	10/18/2021 12:51:46	0.00	\$0.00
					LABOR	384.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.35	2	\$0.69
66-17-028	PERFORM MOUNT AND BALANCE TIRES	FIR004030	FSTONE ALL SEASON 205/65R16	134.42	4	\$537.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.00	4	\$12.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	23.15	1	\$23.15
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	7443	BULB- TAILLIGHT	1.41	1	\$1.41
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
					PARTS	627.54

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 41347

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(AGUERRA) Replaced R/R brake light bulb, checked for proper operation, all good. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted JW Balanced 4 tires.

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) miles: 53007 Completed safety inspection, found 3 tires outdated. Completed safety inspection checklist. AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 53007. SH/AMG performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) Installed cabin filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 42907

USING DEPT NO: 750201	OPENED DATE: 04/13/2022 09:22:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/15/2022 14:00:50	METER 1 - M: 53654 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/18/2022 09:55:05	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.95	\$17.90	\$0.00	\$22.85
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.97	\$0.00	\$0.00	\$42.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.41	47.92	17.90	2.00	67.82
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/13/2022 13:44:14	04/13/2022 14:06:05	0.36	\$42.97
03-51-038	REPLACE NEW WIPER BLADES	11901357	04/13/2022 13:41:32	04/13/2022 13:44:03	0.04	\$4.95
LABOR					47.92	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
PARTS					17.90	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 42907

Work Order Notes

(CHANNELL) pm replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 53654 Vehicle has been 647 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 44334

USING DEPT NO: 750201	OPENED DATE: 08/16/2022 11:52:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/18/2022 11:46:48	METER 1 - M: 54398 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/18/2022 12:14:38	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.46	\$23.56	\$0.00	\$30.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$46.97	\$36.14	\$0.00	\$83.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.45** **53.43** **59.70** **2.00** **115.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/16/2022 13:32:14	08/16/2022 13:56:07	0.40	\$46.97
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/16/2022 13:27:07	08/16/2022 13:30:24	0.05	\$6.46
LABOR					53.43	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.77	1	\$7.77
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.58	1	\$10.58
03-51-038	REPLACE NEW WIPER BLADES	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
PARTS					59.70	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 44334

Work Order Notes

(CHANNELL) PM REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) miles: 54398 Completed PM topside, Scott was bottom side. AMG/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 45407

USING DEPT NO: 750201	OPENED DATE: 12/01/2022 12:56:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/06/2022 08:01:54	METER 1 - M: 56397 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/06/2022 10:37:08	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$40.78	\$69.35	\$0.00	\$110.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.35** **40.78** **69.35** **5.00** **115.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/02/2022 13:15:10	12/02/2022 13:35:54	0.35	\$40.78
LABOR						40.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	13.29	1	\$13.29
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
PARTS						69.35

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 45407

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 56397 Completed PM topside, Greg was bottomsides. AMG/GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 46760

USING DEPT NO: 750201	OPENED DATE: 04/18/2023 15:08:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2023 13:26:42	METER 1 - M: 57938 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/20/2023 07:58:31	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.14	\$16.88	\$23.62	\$0.00	\$40.50
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.46	\$54.80	\$0.00	\$0.00	\$54.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.06	\$0.00	\$0.00	\$16.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.08	\$0.00	\$0.00	\$3.08

JOB COUNT: 5	WORK ORDER TOTAL:	0.77	90.82	23.62	5.00	119.44
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	04/19/2023 08:47:08	04/19/2023 09:15:00	0.46	\$54.80
WA-00	WASH COMPLETE VEHICLE	12052187	04/19/2023 08:45:25	04/19/2023 08:46:59	0.03	\$3.08
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/19/2023 08:37:02	04/19/2023 08:45:12	0.14	\$16.06
03-51-038	REPLACE NEW WIPER BLADES	12052187	04/19/2023 08:28:16	04/19/2023 08:36:51	0.14	\$16.88
LABOR					90.82	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.18	1	\$13.18
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.44	1	\$10.44
PARTS					23.62	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 46760

Work Order Notes

(EHANNAH) pm- replace wipers- do SI - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers.

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI. Found no issues. Pads are 12mm all around. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1541 miles. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-57938

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Washed unit.

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 48259

USING DEPT NO: 750201	OPENED DATE: 09/19/2023 14:27:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/20/2023 13:44:14	METER 1 - M: 59815 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/22/2023 09:41:34	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$24.08	\$0.00	\$41.78
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$51.17	\$51.97	\$0.00	\$103.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.30	\$35.24	\$0.00	\$0.00	\$35.24

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.88** **104.11** **76.05** **5.00** **185.16**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/20/2023 07:00:00	09/20/2023 07:09:00	0.15	\$17.70
WA-00	WASH COMPLETE VEHICLE	11074414	09/19/2023 15:21:17	09/19/2023 15:39:12	0.30	\$35.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/19/2023 14:55:02	09/19/2023 15:21:03	0.43	\$51.17
					LABOR 104.11	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	14.72	1	\$14.72
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
					PARTS 76.05	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 48259

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 49525

USING DEPT NO: 750201	OPENED DATE: 01/23/2024 06:59:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/23/2024 15:39:11	METER 1 - M: 62201 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/24/2024 07:27:54	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK7FU064202	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.36	\$54.25	\$0.00	\$56.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.41	\$48.81	\$0.00	\$0.00	\$48.81

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.58** **68.87** **54.25** **5.00** **128.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/23/2024 09:13:48	01/23/2024 09:15:00	0.02	\$2.36
WA-00	WASH COMPLETE VEHICLE	12201267	01/23/2024 09:27:41	01/23/2024 09:27:41	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	12201267	01/23/2024 09:30:00	01/23/2024 09:54:49	0.41	\$48.81
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/23/2024 09:15:00	01/23/2024 09:24:00	0.15	\$17.70
LABOR					68.87	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	8.12	1	\$8.12
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
PARTS					54.25	

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 49525

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM,GC, FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 62,201

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 241361 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 49779

USING DEPT NO: 750201	OPENED DATE: 02/12/2024 12:55:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/14/2024 11:28:55	METER 1 - M: 62202 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/14/2024 13:48:02	IN-SERVICE DATE: 06/02/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK7FU064202

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.24	\$28.58	\$0.00	\$0.00	\$28.58

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.24** **28.58** **0.00** **5.00** **33.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	02/13/2024 08:26:35	02/13/2024 08:41:07	0.24	\$28.58
					LABOR	28.58

Work Order Charge Detail

UNIT NO: 241361 2015 TOYOTA CAMRY

WORK ORDER NO: 49779

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Feb 15 2024 09:45:41 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1BF1FK7FU064202') //Q=