

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 28506

USING DEPT NO:	507201	OPENED DATE:	01/04/2018 09:35:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2018 15:18:57	METER 1 - M:	86	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2018 15:18:59	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	8.00	\$460.00	\$1,274.09	\$0.00	\$1,734.09
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$450.00	\$0.00	\$478.75
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	9.00	517.50	1,724.09	0.00	2,241.59
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	01/04/2018 13:46:59	01/04/2018 21:46:59	8.00	\$460.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	01/04/2018 13:46:54	01/04/2018 14:16:54	0.50	\$28.75
14-78-044	INSTALL TOOLBOX ASSY	11213180	01/04/2018 13:47:04	01/04/2018 14:17:04	0.50	\$28.75
					LABOR	517.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.59	1	\$0.59
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONC	ION WIDE ANGLE STROBE CLEAR	162.00	2	\$324.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609C	WHITE STROBE LIGHT KIT	121.50	2	\$243.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81167S	WIRE	23.10	1	\$23.10
14-78-044	INSTALL TOOLBOX ASSY	TBS63ALP	TOOLBOX	450.00	1	\$450.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	6.00	1	\$6.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	7.50	1	\$7.50
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SWITCH	ACCELERATOR SWITCH	7.50	1	\$7.50
					PARTS	1724.09

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 28506

Work Order Notes

(LISAPATE) PDI-INSTALL STROBE LIGHTS AND TOOLBOX

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) INSTALLED INTERIORM AND EXTERIOR STROBES. USED 1 ATO10 FUSE. RECHECKED OK

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) INSTALLED TOOLBOX

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 29793

USING DEPT NO:	507201	OPENED DATE:	05/14/2018 10:20:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2018 06:38:39	METER 1 - M:	1957	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2018 06:38:41	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.99	\$0.00	\$51.82

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	33.99	0.00	51.82
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/15/2018 07:00:00	05/15/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	6	\$27.54
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
					PARTS	33.99

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 29793

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 31276

USING DEPT NO:	507201	OPENED DATE:	10/25/2018 07:13:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2018 18:00:00	METER 1 - M:	4283	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2018 18:00:00	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.12	\$81.06	\$41.59	\$0.00	\$122.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.20	\$14.68	\$9.49	\$0.00	\$24.17

JOB COUNT: 2	WORK ORDER TOTAL:	1.32	95.74	51.08	0.00	146.82
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/25/2018 13:50:16	10/25/2018 14:02:25	0.20	\$14.68
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/25/2018 13:02:34	10/25/2018 13:49:08	0.78	\$56.27
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/25/2018 13:02:22	10/25/2018 13:22:53	0.34	\$24.79
					LABOR	95.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	224871	CABIN AIR FILTER	9.49	1	\$9.49
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.58	1	\$6.58
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
					PARTS	51.08

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 31276

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,RC/AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 31792

USING DEPT NO:	507201	OPENED DATE:	12/18/2018 14:49:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/14/2019 10:47:48	METER 1 - M:	4283	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2019 10:47:50	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-05	WARRANTY ELECTRONIC ENGINE EEC	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-05	TRANSPORT ELECTRONIC ENGINE EE	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.30	\$94.19	\$0.00	\$0.00	\$94.19
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$951.28	\$951.28
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$145.00	\$0.00	\$0.00	\$145.00

JOB COUNT: 5	WORK ORDER TOTAL:	4.30	311.69	0.00	951.28	1,262.97
--------------	-------------------	------	--------	------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	167021	0046488	\$951.28
15-05	WARRANTY ELECTRONIC ENGINE EEC SYSTEM	11076422	6020945	0046489	\$0.00
COMML					951.28

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	01/08/2019 07:00:00	01/08/2019 09:00:00	2.00	\$145.00
16-05	TRANSPORT ELECTRONIC ENGINE EEC SYSTEM	10208562	01/08/2019 07:00:00	01/08/2019 08:00:00	1.00	\$72.50
16-71	TRANSPORT BODY	11915538	12/19/2018 07:51:03	12/19/2018 09:09:00	1.30	\$94.19
LABOR						311.69

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 31792

Work Order Notes

(LISAPATE) Take to Andrews to be repaired. UA has a check from State Farm for \$951.28 dated 11-27-18 Ck# 648264

(LISAPATE) Check engine light is on

Job Notes

15-05 - WARRANTY ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Per Tuscaloosa Toyota Invoice Scanned codes p0302 Cylinder 2 misfire(history) P0303 Cylinder 3 misfire detected (Pending) P1605 rough idling (History)

Performed health check and cleared all codes road test vehicle in test mode to active any codes pending no codes came back on, no service bulletin for current codes no repairs made at this time

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Taken to Tuscaloosa Toyota by EK

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage to rear bumper and tailgate per the State Farm estimate. UA was PD by State Farm invoice estimate and check attached

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out OTC P0303 Cylinder 3 misfire and P16605 Rough idle

Vehicle is still under warranty sending to Tuscaloosa Toyota

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 33916

USING DEPT NO:	507201	OPENED DATE:	08/29/2019 14:25:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2019 11:13:59	METER 1 - M:	7673	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/03/2019 11:14:00	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.32	\$95.90	\$41.51	\$0.00	\$137.41
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.75	\$13.59	\$0.00	\$35.34

JOB COUNT: 2 WORK ORDER TOTAL: 1.62 117.65 55.10 0.00 172.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/30/2019 07:00:00	08/30/2019 07:18:00	0.30	\$21.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/30/2019 06:04:14	08/30/2019 06:40:04	0.60	\$43.30
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/29/2019 15:09:35	08/29/2019 15:53:07	0.73	\$52.60
					LABOR	117.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
					PARTS	55.10

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 33916

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG

Coolant -34'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 36367

USING DEPT NO:	507201	OPENED DATE:	05/11/2020 07:09:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/12/2020 09:38:07	METER 1 - M:	11233	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2020 08:20:21	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.51	\$0.00	\$0.00	\$36.51
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.39	\$28.03	\$0.00	\$0.00	\$28.03
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.19	\$86.23	\$827.31	\$0.00	\$913.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$58.00	\$47.33	\$0.00	\$105.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.03	\$1.99	\$13.59	\$0.00	\$15.58

JOB COUNT: 5	WORK ORDER TOTAL:	2.91	210.76	888.23	0.00	1,098.99
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11901357	05/12/2020 07:00:00	05/12/2020 07:30:00	0.50	\$36.25
09-15	ALIGN STEERING	11213180	05/11/2020 11:31:03	05/11/2020 11:54:15	0.39	\$28.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	05/11/2020 10:19:41	05/11/2020 11:31:03	1.19	\$86.23
06-15	INSPECT STEERING	12052187	05/11/2020 09:12:26	05/11/2020 09:12:39	0.00	\$0.26
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/11/2020 08:55:26	05/11/2020 09:12:26	0.28	\$20.54
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/11/2020 08:43:37	05/11/2020 09:04:44	0.35	\$25.52
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	05/11/2020 08:53:06	05/11/2020 08:54:45	0.03	\$1.99
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/11/2020 08:43:13	05/11/2020 08:53:06	0.16	\$11.94
					LABOR	210.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	7	\$40.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	202.50	4	\$810.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	4	\$13.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	10	\$4.05
					PARTS	888.23

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 36367

Work Order Notes

(EKIMBREL) PM

Job Notes

06-15 - INSPECT STEERING

(EKIMBREL) JW/AG checked front end, no issues.

09-15 - ALIGN STEERING

(EKIMBREL) MS performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) MS mounted and balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/AG performed PM. Coolant -34

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) JW replaced cabin filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 37923

USING DEPT NO:	507201	OPENED DATE:	10/08/2020 08:34:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/08/2020 09:46:02	METER 1 - M:	13177	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/08/2020 13:39:17	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.94	\$48.33	\$0.00	\$93.27

JOB COUNT: 1	WORK ORDER TOTAL:	0.38	44.94	48.33	0.00	93.27
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/08/2020 09:15:00	10/08/2020 09:16:12	0.02	\$2.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/08/2020 08:54:11	10/08/2020 09:00:00	0.10	\$11.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/08/2020 08:58:04	10/08/2020 09:13:54	0.26	\$31.14
					LABOR	44.94

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.84	1	\$6.84
					PARTS	48.33

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 37923

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 39378

USING DEPT NO:	507201	OPENED DATE:	03/11/2021 10:19:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/12/2021 11:21:49	METER 1 - M:	14927	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/15/2021 08:00:07	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.67	\$79.42	\$0.00	\$0.00	\$79.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.39	\$0.00	\$0.00	\$24.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.10	\$11.80	\$7.53	\$0.00	\$19.33

JOB COUNT: 3	WORK ORDER TOTAL:	0.98	115.61	7.53	0.00	123.14
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	03/11/2021 13:19:55	03/11/2021 13:25:55	0.10	\$11.80
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	03/11/2021 13:19:55	03/11/2021 13:20:07	0.00	\$0.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	03/11/2021 13:19:55	03/11/2021 13:20:07	0.00	(\$0.39)
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/11/2021 13:27:26	03/11/2021 14:07:49	0.67	\$79.42
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/11/2021 13:07:05	03/11/2021 13:19:29	0.21	\$24.39
					LABOR	115.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	7.53	1	\$7.53
					PARTS	7.53

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 39378

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH rotated tires inspected brakes washed vacuumed and filled with gas.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1750 miles since last pm. Checked all tires and fluids. Coolant -34°. JAW,SH
MILEAGE-14927

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(JWRIGHT) Replaced filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 40800

USING DEPT NO:	507201	OPENED DATE:	08/20/2021 14:50:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2021 10:29:32	METER 1 - M:	17262	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2021 13:52:28	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.03	\$15.18	\$0.00	\$21.21
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$51.23	\$33.45	\$0.00	\$84.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.49	57.26	48.63	2.00	107.89
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/23/2021 07:37:57	08/23/2021 07:41:01	0.05	\$6.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2021 07:11:43	08/23/2021 07:37:46	0.43	\$51.23
					LABOR	57.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	6	\$27.00
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	48.63

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 40800

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 17262. Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 41714

USING DEPT NO:	507201	OPENED DATE:	11/29/2021 07:50:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2021 11:19:03	METER 1 - M:	19129	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2021 12:18:33	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.22	\$26.48	\$113.55	\$0.00	\$140.03
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.07	\$8.69	\$0.00	\$0.00	\$8.69
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	35.17	113.55	2.00	150.72
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-32-002	INSPECT BATTERY	11213180	11/29/2021 13:41:42	11/29/2021 13:46:07	0.07	\$8.69
03-32-002	REPLACE NEW BATTERY	11213180	11/29/2021 13:28:03	11/29/2021 13:41:31	0.22	\$26.48
					LABOR	35.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	113.55

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 41714

Work Order Notes

(IFALLS) Check battery/starter

Job Notes

03-32-002 - REPLACE NEW BATTERY

(MSIDES) Found battery to have a bad cell voltage was only 7.4 volts. Replaced battery found vehicle to be charging as designed. MS

06-32-002 - INSPECT BATTERY

(MSIDES) Found battery voltage to only be 7.4 volts this indicates a bad cell. MS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 42394

USING DEPT NO:	507201	OPENED DATE:	02/18/2022 08:57:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2022 15:21:40	METER 1 - M:	20528	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 15:21:42	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.64	\$15.18	\$0.00	\$16.82
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.38	\$44.58	\$0.00	\$0.00	\$44.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.24	\$35.39	\$0.00	\$70.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.69	81.46	50.57	2.00	134.03
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/18/2022 11:46:06	02/18/2022 11:46:56	0.01	\$1.64
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	02/18/2022 11:22:43	02/18/2022 11:45:23	0.38	\$44.58
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/18/2022 11:04:48	02/18/2022 11:22:43	0.30	\$35.24
				LABOR		81.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.48	1	\$8.48
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
				PARTS		50.57

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 42394

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotate tires

(JWRIGHT) Rotated tires. Brakes are 7mm. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW

MILEAGE-20528

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 43852

USING DEPT NO:	507201	OPENED DATE:	07/06/2022 10:16:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2022 11:04:59	METER 1 - M:	22505	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 08:51:27	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.92	\$13.11	\$0.00	\$18.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.01	\$0.00	\$0.00	\$25.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.08	\$9.31	\$20.52	\$0.00	\$29.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.33	39.24	33.63	2.00	74.87
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	07/06/2022 15:34:00	07/06/2022 15:38:44	0.08	\$9.31
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/06/2022 15:29:42	07/06/2022 15:32:12	0.04	\$4.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/06/2022 15:15:23	07/06/2022 15:28:06	0.21	\$25.01
				LABOR		39.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	6.57	1	\$6.57
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	6.54	1	\$6.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
				PARTS		33.63

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 43852

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 1977 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(HHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 45509

USING DEPT NO:	507201	OPENED DATE:	12/09/2022 09:48:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2022 09:50:35	METER 1 - M:	23976	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/14/2022 15:43:42	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.64	\$0.00	\$33.34
05-17	REPLACE USED TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.40	\$47.20	\$0.00	\$0.00	\$47.20
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.98	\$116.20	\$0.00	\$0.00	\$116.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.43	\$68.66	\$0.00	\$114.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.92	226.53	84.30	5.00	315.83
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
05-17	REPLACE USED TIRES, TUBES, LINERS & VALVES	10208562	12/14/2022 07:00:00	12/14/2022 07:24:00	0.40	\$47.20
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/09/2022 12:22:09	12/09/2022 12:22:59	0.01	\$1.64
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/09/2022 12:33:59	12/09/2022 12:56:15	0.37	\$43.79
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/09/2022 12:56:42	12/09/2022 13:05:42	0.15	\$17.70
66-79-003	PERFORM SAFETY INSPECTION	11901357	12/09/2022 13:06:08	12/09/2022 14:05:13	0.98	\$116.20
				LABOR		226.53

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.73	1	\$5.73
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
				PARTS		84.30

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 45509

Work Order Notes

(EHANNAH) pm- replace wipers
do annual SI
replace 4 tire and align due to wear

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

05-17 - REPLACE USED TIRES, TUBES, LINERS & VALVES

(EKIMBREL) Swapped tires from unit 1193C to 1528C. AMG SH

06-15 - INSPECT STEERING

09-15 - ALIGN STEERING

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) Completed safety inspection and safety inspection checklist, no issues found. AMG
(EKIMBREL) no alignment per issac. no labor for tires because had to remove during safety inspection

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 23976 Completed PM topside, Greg was bottomside. AMG/GC
(EKIMBREL)

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 46901

USING DEPT NO:	507201	OPENED DATE:	04/28/2023 10:24:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2023 08:47:18	METER 1 - M:	25053	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2023 09:57:17	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.28	\$16.61	\$0.00	\$19.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.08	\$0.00	\$0.00	\$9.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.10	12.36	16.61	5.00	33.97
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/01/2023 10:42:37	05/01/2023 10:44:17	0.03	\$3.28
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/01/2023 10:37:48	05/01/2023 10:42:25	0.08	\$9.08
				LABOR		12.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.28	1	\$8.28
				PARTS		16.61

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 46901

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1077 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-25053

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) wash bay down

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 48239

USING DEPT NO:	507201	OPENED DATE:	09/18/2023 08:48:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2023 14:21:33	METER 1 - M:	26996	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2023 08:38:36	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX103313	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.64	\$21.70	\$0.00	\$25.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.11	\$43.83	\$0.00	\$78.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.27	\$31.60	\$0.00	\$0.00	\$31.60

JOB COUNT: 4	WORK ORDER TOTAL:	0.60	70.35	65.53	5.00	140.88
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/18/2023 11:08:53	09/18/2023 11:10:44	0.03	\$3.64
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/18/2023 10:50:49	09/18/2023 11:08:40	0.30	\$35.11
WA-00	WASH COMPLETE VEHICLE	11074414	09/18/2023 13:50:10	09/18/2023 14:06:14	0.27	\$31.60
				LABOR		70.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
				PARTS		65.53

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 48239

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 49683

USING DEPT NO:	507201	OPENED DATE:	02/02/2024 12:50:28	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/19/2024 09:29:46	METER 1 - M:	28526	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/26/2024 09:37:23	IN-SERVICE DATE:	12/15/2017						
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma									
				UNIT SERIAL NO:	5TFRX5GN2HX103313						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$998.68	\$998.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.30	\$0.00	\$0.00	\$41.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.04	\$4.95	\$11.79	\$0.00	\$16.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.05	\$6.10	\$0.00	\$0.00	\$6.10

JOB COUNT: 6	WORK ORDER TOTAL:	0.94	111.35	11.79	1,003.68	1,126.82
--------------	-------------------	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	16979156		\$998.68
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					1003.68

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	02/19/2024 07:42:34	02/19/2024 07:45:40	0.05	\$6.10
16-71	TRANSPORT BODY	11915538	02/19/2024 07:00:00	02/19/2024 07:30:00	0.50	\$59.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/19/2024 07:39:48	02/19/2024 07:42:19	0.04	\$4.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2024 07:18:48	02/19/2024 07:39:48	0.35	\$41.30
LABOR						111.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
PARTS						11.79

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 49683

Work Order Notes

(EHANNAH) transport and repair body to Andrew's-pm-wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-71 - TRANSPORT BODY

(EKIMBREL) rc transported vehicle to/from body shop

24-71 - REPAIR BODY

(EKIMBREL) andrew's body shop completed body repair

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 1530 miles. Checked fluids tire pressure and updated the oil change sticker. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Clean and full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 50060

USING DEPT NO:	507201	OPENED DATE:	03/04/2024 10:15:43	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2024 08:45:35	METER 1 - M:	28724	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2024 10:20:39	IN-SERVICE DATE:	12/15/2017						
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma			UNIT SERIAL NO:	5TFRX5GN2HX103313					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$118.00	\$0.27	\$0.00	\$118.27

JOB COUNT: 3	WORK ORDER TOTAL:	1.50	177.00	0.27	5.00	182.27
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/05/2024 12:49:57	03/05/2024 13:49:57	1.00	\$118.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/05/2024 12:49:57	03/05/2024 12:49:57	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/05/2024 12:49:57	03/05/2024 12:49:57	0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	11399745	03/06/2024 07:00:00	03/06/2024 07:30:00	(0.50)	(\$59.00)
25-52-021	REMOVE GPS SYSTEM	11399745	03/06/2024 07:00:00	03/06/2024 07:30:00	0.50	\$59.00
25-52-021	REMOVE GPS SYSTEM	11399745	03/06/2024 07:00:00	03/06/2024 07:30:00	0.50	\$59.00
LABOR						177.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
PARTS						0.27

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:29:39 By User: GLOBETTI

UNIT NO: 242575 2017 TOYOTA TACOMA

WORK ORDER NO: 50060

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(LISAPATE) Removed GPS 5040035715

(IFALLS) Visit Reason Changed On 3/6/2024 10:20 AM By IFALLS

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks, tag, and GPS 5040035715 CW/RC

Miles 28,724

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Mar 11 2024 13:29:39 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242575') //Q=