

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 21307

USING DEPT NO:	209317	OPENED DATE:	09/03/2015 14:06:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2015 08:14:06	METER 1 - M:	683	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2015 08:14:07	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11338644	09/03/2015 14:07:08	09/03/2015 14:37:08	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 21307

Work Order Notes

(LPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA WORK ORDER NO: 21883

USING DEPT NO:	209317	OPENED DATE:	11/03/2015 14:17:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2015 09:49:07	METER 1 - M:	5435	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2015 09:49:09	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.52	\$87.51	\$33.67	\$0.00	\$121.18

JOB COUNT: 1 WORK ORDER TOTAL: 1.52 87.51 33.67 0.00 121.18

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/04/2015 06:01:32	11/04/2015 07:32:51	1.52	\$87.51
					LABOR	87.51

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	7	\$26.32
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.57	1	\$4.57
					PARTS	33.67

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 21883

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 22633

USING DEPT NO: 209317	OPENED DATE: 02/25/2016 09:09:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2016 13:59:13	METER 1 - M: 10141 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/25/2016 13:59:14	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$39.37	\$30.86	\$0.00	\$70.23

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.68** **39.37** **30.86** **0.00** **70.23**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2016 10:27:07	02/25/2016 11:08:12	0.68	\$39.37
					LABOR	39.37

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.54	1	\$4.54
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	7	\$26.32
					PARTS	30.86

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 22633

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 23838

USING DEPT NO: 209317	OPENED DATE: 07/07/2016 13:07:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2016 08:02:36	METER 1 - M: 13571 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/12/2016 08:02:38	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.94	\$0.00	\$48.77

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.31** **75.33** **30.94** **0.00** **106.27**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/08/2016 07:00:00	07/08/2016 07:18:36	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11758845	07/08/2016 07:18:36	07/08/2016 08:18:36	1.00	\$57.50
					LABOR	75.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	7	\$26.32
					PARTS	30.94

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 23838

Work Order Notes

(LISAPATE) PM-DO SI GOING OUT OF TOWN

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Visit Reason Changed On 7/7/2016 1:08 PM By LISAPATE

(LISAPATE) SAFETY INSPECTION COMPLETED. SEE ATTACHED

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 7/7/2016 1:08 PM By LISAPATE

(LISAPATE) PM BY CS,AY/IF

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 24604

USING DEPT NO: 209317	OPENED DATE: 10/12/2016 10:57:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/13/2016 14:23:01	METER 1 - M: 21048 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/13/2016 14:23:03	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$19.36	\$35.24	\$0.00	\$54.60

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.59** **33.74** **52.30** **0.00** **86.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	10/12/2016 14:56:22	10/12/2016 15:16:34	0.34	\$19.36
03-51-038	REPLACE NEW WIPER BLADES	11170580	10/12/2016 15:15:59	10/12/2016 15:30:59	0.25	\$14.38
					LABOR	33.74

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	8.06	1	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	6	\$22.56
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
					PARTS	52.30

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 24604

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB,AB/MS-USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 25199

USING DEPT NO: 209317	OPENED DATE: 12/06/2016 14:56:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/13/2016 06:19:57	METER 1 - M: 24795 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/13/2016 06:19:59	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.04	\$0.00	\$50.87

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.31** **75.33** **33.04** **0.00** **108.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	12/12/2016 07:00:00	12/12/2016 07:18:36	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11170580	12/12/2016 07:18:36	12/12/2016 08:18:36	1.00	\$57.50
					LABOR	75.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.60	1	\$4.60
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	7	\$26.32
					PARTS	33.04

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 25199

Work Order Notes

(LISAPATE) DO SI AND PM

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Visit Reason Changed On 12/6/2016 2:57 PM By LISAPATE

(LISAPATE) SI COMPLETED. SEE ATTACHED

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 25994

USING DEPT NO: 209317	OPENED DATE: 03/20/2017 15:57:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/27/2017 13:25:31	METER 1 - M: 29416 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/27/2017 13:25:33	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.13	\$0.00	\$44.96

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **44.19** **0.00** **76.40**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	03/21/2017 07:00:00	03/21/2017 07:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11170580	03/21/2017 07:18:36	03/21/2017 07:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.51	1	\$4.51
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.77	6	\$22.62
					PARTS	44.19

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 25994

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB
COOLANT -37'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 26768

USING DEPT NO: 209317	OPENED DATE: 07/05/2017 13:42:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2017 15:56:24	METER 1 - M: 32688 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/12/2017 15:56:26	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$51.00	\$0.00	\$79.75
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.50** **86.25** **51.00** **0.00** **137.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11268671	07/05/2017 13:43:32	07/05/2017 14:13:32	0.50	\$28.75
03-32-002	REPLACE NEW BATTERY	11268671	07/05/2017 13:43:32	07/05/2017 14:13:32	(0.50)	(\$28.75)
66-79-002	PERFORM SERVICE CALL	11268671	07/05/2017 13:43:25	07/05/2017 14:43:25	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11758845	07/05/2017 13:43:32	07/05/2017 14:13:32	0.50	\$28.75
					LABOR	86.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	51.00	1	\$51.00
					PARTS	51.00

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 26768

Work Order Notes

(LISAPATE) JO REQUESTED A SERVICE CALL TO GALILEE HALL LIGHT ON DASH SAYS CHECK CHARGING SYSTEM. VAN WILL CRANK BUT WILL NOT MOVE STERING IS LOCKED

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) BATTERY FAILED. REPLACED BATTERY

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED. JUMPED OFF AND BROUGHT TO THE GARAGE

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA WORK ORDER NO: 27117

USING DEPT NO:	209317	OPENED DATE:	08/15/2017 09:49:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2017 11:11:31	METER 1 - M:	32866	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/21/2017 11:11:32	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.42	\$0.00	\$41.25

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 23.42 0.00 41.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11268671	08/16/2017 07:00:00	08/16/2017 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	6	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
					PARTS	23.42

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 27117

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY TB/IF

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 27988

USING DEPT NO: 209317	OPENED DATE: 10/31/2017 08:51:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/01/2017 10:27:17	METER 1 - M: 38117 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 11/01/2017 10:27:18	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.68	\$23.38	\$0.00	\$59.06

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.62** **35.68** **23.38** **0.00** **59.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/31/2017 10:42:42	10/31/2017 11:01:20	0.31	\$17.86
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/31/2017 10:59:30	10/31/2017 11:18:06	0.31	\$17.83
					LABOR	35.69

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	6	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	1	\$2.11
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.59	1	\$4.59
					PARTS	23.38

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 27988

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH PERFORMED PM

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 28948

USING DEPT NO: 209317	OPENED DATE: 02/21/2018 09:33:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2018 10:28:51	METER 1 - M: 43176 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/25/2018 10:28:52	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$36.91	\$23.77	\$0.00	\$60.68

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.64** **36.91** **23.77** **0.00** **60.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2018 08:04:16	02/22/2018 08:42:47	0.64	\$36.91
					LABOR	36.91

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.77	7	\$19.39
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.38	1	\$4.38
					PARTS	23.77

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 28948

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -45'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 29693

USING DEPT NO: 209317	OPENED DATE: 05/04/2018 14:35:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/14/2018 08:06:12	METER 1 - M: 46859 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/14/2018 08:06:14	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.83	\$0.00	\$51.66

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **50.89** **0.00** **83.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2018 06:00:00	05/10/2018 06:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/10/2018 06:18:36	05/10/2018 06:33:36	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	8.06	1	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.06	7	\$21.42
					PARTS	50.89

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 29693

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/SH
REPLACED AIR FILTER
COOLANT -20'

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA WORK ORDER NO: 30296

USING DEPT NO:	209317	OPENED DATE:	07/19/2018 10:07:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/23/2018 11:17:55	METER 1 - M:	47862	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/23/2018 11:17:57	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.40	\$0.00	\$6.50	\$0.00	\$6.50	
JOB COUNT: 1						WORK ORDER TOTAL:	0.40	0.00	6.50	0.00	6.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	07/19/2018 11:35:07	07/19/2018 11:59:07	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	1.75	1	\$1.75
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.33	1	\$2.33
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.03	7	\$0.21
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	2.21	1	\$2.21
					PARTS	6.50

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 30296

Work Order Notes

(RTUNAITI) TPMS light on

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) REMOVED AND PATCHED LR TIRE FROM THE INSIDE. RECHECKED OK

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 30964

USING DEPT NO: 209317	OPENED DATE: 09/27/2018 09:25:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2018 15:39:24	METER 1 - M: 51986 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2018 15:39:26	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.52	\$0.00	\$10.03	\$0.00	\$10.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$0.00	\$31.49	\$0.00	\$31.49
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$559.40	\$559.40

JOB COUNT: 3	WORK ORDER TOTAL:	1.19	0.00	41.52	559.40	600.92
---------------------	--------------------------	-------------	-------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	1138074	0045237	\$279.70
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11078167	1138147	0045247	\$279.70
COMML					559.40

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/27/2018 10:31:17	09/27/2018 11:10:57	0.66	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/27/2018 10:44:39	09/27/2018 11:12:57	0.47	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/27/2018 11:13:56	09/27/2018 11:25:50	0.20	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/28/2018 08:36:24	09/28/2018 09:15:00	0.64	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/28/2018 09:30:00	09/28/2018 09:37:36	0.13	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/28/2018 08:36:24	09/28/2018 09:15:00	(0.64)	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/28/2018 09:15:00	09/28/2018 09:49:39	(0.58)	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/28/2018 08:36:18	09/28/2018 09:00:00	0.40	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/28/2018 09:15:00	09/28/2018 09:49:39	0.58	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:13	09/28/2018 14:54:17	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:13	09/28/2018 14:54:17	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:27	09/28/2018 14:54:31	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:27	09/28/2018 14:54:31	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:39	09/28/2018 14:54:43	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:39	09/28/2018 14:54:43	0.00	\$0.00

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:47	09/28/2018 14:54:58	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:54:47	09/28/2018 14:54:58	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:02	09/28/2018 14:55:07	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:02	09/28/2018 14:55:07	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:23	09/28/2018 14:55:28	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:23	09/28/2018 14:55:28	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:42	09/28/2018 14:55:48	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:42	09/28/2018 14:55:48	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:52	09/28/2018 14:55:56	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:55:52	09/28/2018 14:55:56	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:24	09/28/2018 15:56:24	1.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:24	09/28/2018 14:56:34	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:24	09/28/2018 14:56:34	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:24	09/28/2018 15:56:24	(1.00)	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:44	09/28/2018 15:56:44	1.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:44	09/28/2018 14:56:48	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:44	09/28/2018 14:56:48	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/27/2018 10:31:17	09/27/2018 11:10:57	(0.66)	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 14:56:44	09/28/2018 15:56:44	(1.00)	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/28/2018 15:20:10	09/28/2018 15:20:15	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/28/2018 15:20:10	09/28/2018 15:20:15	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:32	09/28/2018 15:21:36	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:32	09/28/2018 15:21:36	0.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:32	09/28/2018 16:21:32	(1.00)	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:32	09/28/2018 16:21:32	1.00	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:40	09/28/2018 16:21:40	(1.00)	\$0.00
09-15	ALIGN STEERING	11213180	09/28/2018 15:22:45	09/28/2018 15:22:49	0.00	\$0.00
09-15	ALIGN STEERING	11213180	09/28/2018 15:22:45	09/28/2018 15:22:49	0.00	\$0.00
09-15	ALIGN STEERING	11213180	09/28/2018 15:22:45	09/28/2018 15:22:49	0.00	\$0.00
09-15	ALIGN STEERING	11213180	09/28/2018 15:22:45	09/28/2018 15:22:49	0.00	\$0.00

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	09/28/2018 14:50:41	09/28/2018 15:23:19	0.54	\$0.00
09-15	ALIGN STEERING	11310047	09/28/2018 14:50:41	09/28/2018 15:23:19	(0.54)	\$0.00
09-15	ALIGN STEERING	11170580	09/28/2018 15:21:40	09/28/2018 16:21:40	1.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	7	\$27.16
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	4	\$8.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.03	16	\$0.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.03	(16)	(\$0.48)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.03	31	\$0.93
					PARTS	41.52

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 30964

Work Order Notes

(LISAPATE) PM

Job Notes

09-15 - ALIGN STEERING

(LISAPATE) alignment not done yet

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH

Coolant -35'

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Purchased 4 Tires from Warren Tire. Pd by CC

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 31012

USING DEPT NO: 209317	OPENED DATE: 10/02/2018 10:36:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/04/2018 13:36:32	METER 1 - M: 51986 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/04/2018 13:36:39	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/W	DON	O	N	GARAGE	2.00	\$0.00	\$27.34	\$0.00	\$27.34

JOB COUNT: 2 **WORK ORDER TOTAL:** **4.00** **0.00** **27.34** **0.00** **27.34**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	11213180	10/02/2018 15:11:29	10/02/2018 17:11:29	2.00	\$0.00
09-15	ALIGN STEERING	11213180	10/02/2018 15:11:25	10/02/2018 17:11:25	2.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	2643643	CAMBER COLT 2PK	9.68	1	\$9.68
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	2643645	CAMBER BOLT 2PK	10.26	(1)	(\$10.26)
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	2643645	CAMBER BOLT 2PK	10.26	1	\$10.26
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	K72643	REAR WHEEL ALIGNMENT SHIM	8.78	1	\$8.78
14-15-026	INSTALL CAM/CONTROL ARM BOLT W/WASHER	K72641	REAR WHEEL ALIGNMENT SHIM	8.88	1	\$8.88
					PARTS	27.34

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 31012

Work Order Notes

(LISAPATE) Tires were replaced on previous WO alignment was not completed prior to fiscal year end

Job Notes

09-15 - ALIGN STEERING

(LISAPATE) MS performed alignment.

14-15-026 - INSTALL CAM/CONTROL ARM BOLT W/WASHER

(LISAPATE) Installed new shims and adjustable strut bolts

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 31320

USING DEPT NO:	209317	OPENED DATE:	10/29/2018 10:21:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/31/2018 11:57:44	METER 1 - M:	53404	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/31/2018 11:57:46	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.52	\$0.00	\$0.52

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.50** **0.00** **0.52** **0.00** **0.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11915538	10/29/2018 15:27:38	10/29/2018 16:27:38	1.00	\$0.00
CH-32-002	CHARGE BATTERY	11915538	10/29/2018 15:27:43	10/29/2018 15:57:43	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.22	1	\$0.22
CH-32-002	CHARGE BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.30	1	\$0.30
					PARTS	0.52

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 31320

Work Order Notes

(EKIMBREL) Dead Battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed. Jumped off and brought to the shop

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery rechecked ok added washers. Charging at 14+ volts

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 31411

USING DEPT NO: 209317	OPENED DATE: 11/06/2018 11:52:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/09/2018 07:58:33	METER 1 - M: 53409 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/09/2018 07:58:35	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.50** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11268671	11/07/2018 08:00:00	11/07/2018 08:30:00	0.50	\$0.00
66-79-002	PERFORM SERVICE CALL	11268671	11/07/2018 07:00:00	11/07/2018 08:00:00	1.00	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 31411

Work Order Notes

(EKIMBREL) Service call; wont start

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed jumped off and brought to the shop

CH-32-002 - CHARGE BATTERY

(LISAPATE) Charged battery. Rechecked ok

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 31435

USING DEPT NO:	209317	OPENED DATE:	11/09/2018 13:59:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/14/2018 11:41:17	METER 1 - M:	53817	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2018 11:41:19	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$0.00	\$75.24	\$0.00	\$75.24
06-00	INSPECT COMPLETE VEHICLE	DON	P	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.00	0.00	75.24	0.00	75.24
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11268671	11/13/2018 07:00:00	11/13/2018 08:00:00	1.00	\$0.00
06-00	INSPECT COMPLETE VEHICLE	11268671	11/13/2018 07:00:00	11/13/2018 07:30:00	0.50	\$0.00
03-32-002	REPLACE NEW BATTERY	11268671	11/12/2018 07:00:00	11/12/2018 07:30:00	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.24	1	\$75.24
					PARTS	75.24

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 31435

Work Order Notes

(LISAPATE) Lindsey requested a service call to Russell Hall van is dead again

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) IF replaced battery

(RWINTERS) noticed squirrels had been under hood again on transmission.

06-00 - INSPECT COMPLETE VEHICLE

(IFALLS) IF checked engine compartment and under van for chewed wires and hoses (possible squirrel damage) nothing was found

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 32025

USING DEPT NO:	209317	OPENED DATE:	01/25/2019 09:10:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/29/2019 09:03:11	METER 1 - M:	55719	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/29/2019 09:03:13	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$0.00	\$31.56	\$0.00	\$31.56
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	1.00	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.40** **0.00** **36.45** **0.00** **36.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	01/25/2019 09:47:40	01/25/2019 10:47:47	1.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/25/2019 09:17:22	01/25/2019 09:41:21	0.40	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
					PARTS	36.45

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 32025

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,EK/AG
Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 32843

USING DEPT NO: 209317	OPENED DATE: 05/07/2019 14:51:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/09/2019 14:28:58	METER 1 - M: 61114 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2019 14:29:01	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$0.00	\$23.38	\$0.00	\$23.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$0.00	\$35.77	\$0.00	\$35.77

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.62** **0.00** **59.15** **0.00** **59.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	10208562	05/08/2019 07:00:00	05/08/2019 07:15:00	0.25	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/08/2019 07:39:24	05/08/2019 08:01:44	0.37	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW2801P	28" WIPERS	9.46	(1)	(\$9.46)
03-51-038	REPLACE NEW WIPER BLADES	WW2801P	28" WIPERS	9.46	1	\$9.46
03-51-038	REPLACE NEW WIPER BLADES	60-016-A	WIPER -TOYOTA SIENNA	6.33	1	\$6.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.52	1	\$8.52
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	59.15

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 32843

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced front and rear wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG
Coolant -20'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 33836

USING DEPT NO: 209317	OPENED DATE: 08/23/2019 08:55:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/28/2019 09:24:17	METER 1 - M: 66335 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/28/2019 09:24:17	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$0.00	\$31.56	\$0.00	\$31.56

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.41** **0.00** **31.56** **0.00** **31.56**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/23/2019 14:04:58	08/23/2019 14:29:36	0.41	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					PARTS	31.56

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 33836

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 34396

USING DEPT NO: 209317	OPENED DATE: 10/09/2019 13:25:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/14/2019 14:02:45	METER 1 - M: 71178 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/14/2019 14:02:46	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.06	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.61	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.78	\$0.00	\$285.04	\$0.00	\$285.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.39	\$0.00	\$43.68	\$0.00	\$43.68

JOB COUNT: 4 **WORK ORDER TOTAL:** **3.83** **0.00** **328.72** **0.00** **328.72**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2019 07:01:26	10/10/2019 07:53:12	0.86	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/10/2019 11:25:36	10/10/2019 11:57:59	0.54	\$0.00
06-15	INSPECT STEERING	12052187	10/11/2019 09:29:16	10/11/2019 09:29:16	0.00	\$0.00
06-15	INSPECT STEERING	12052187	10/11/2019 09:30:00	10/11/2019 09:33:30	0.06	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/11/2019 09:33:30	10/11/2019 10:47:52	1.24	\$0.00
09-15	ALIGN STEERING	11310047	10/11/2019 15:15:46	10/11/2019 15:52:23	0.61	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/09/2019 15:22:36	10/09/2019 15:53:58	0.52	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	7	\$27.16
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.17	1	\$4.17
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	8.06	1	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.42	1	\$2.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	38169	TIRE P235/60R17 MIC PRIM MXV4	139.85	2	\$279.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	2	\$4.42
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.42	(1)	(\$2.42)
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	23	\$0.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.20	2	\$4.40

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.20	(2)	(\$4.40)
					PARTS	328.72

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 34396

Work Order Notes

(LISAPATE) PM

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) JW/EK Checked front end no issues found at this time

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 2 new tires. Installed on the rear

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 34908

USING DEPT NO: 209317	OPENED DATE: 11/18/2019 15:02:51	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/25/2019 07:25:07	METER 1 - M: 75740 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/25/2019 07:25:09	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$297.95	\$297.95
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.08	\$0.00	\$18.39	\$0.00	\$18.39
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.57	\$0.00	\$31.49	\$0.00	\$31.49

JOB COUNT: 4 **WORK ORDER TOTAL:** **2.15** **0.00** **49.88** **297.95** **347.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11078716	270390		\$297.95
					COMML 297.95

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/19/2019 10:10:35	11/19/2019 10:26:14	0.26	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11915538	11/19/2019 08:49:10	11/19/2019 09:15:00	0.43	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/19/2019 09:59:08	11/19/2019 10:51:57	0.88	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	10208562	11/19/2019 14:10:27	11/19/2019 14:15:00	0.08	\$0.00
35-31	DIAGNOSE CHARGING SYSTEM	11901357	11/21/2019 07:00:00	11/21/2019 07:30:00	0.50	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	7	\$27.16
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
03-51-038	REPLACE NEW WIPER BLADES	60281	WIPER BLADE 28 IN CONV	9.86	1	\$9.86
					PARTS	49.88

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 34908

Work Order Notes

(LISAPATE) PM due-windshield has a crack running-check charging system on display

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield.
Pd by CC

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

35-31 - DIAGNOSE CHARGING SYSTEM

(LISAPATE) Checked charging system is good shows charging at 13.9 volts

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/JW
Coolant -35'

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 35813

USING DEPT NO: 209317	OPENED DATE: 02/27/2020 14:04:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/06/2020 13:28:14	METER 1 - M: 81125 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/06/2020 13:28:16	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.02	\$0.00	\$24.87	\$0.00	\$24.87
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.48	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.75	\$0.00	\$570.76	\$0.00	\$570.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.02	\$0.00	\$27.67	\$0.00	\$27.67
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.30	\$0.00	\$4.89	\$0.00	\$4.89
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.28	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **7.34** **0.00** **628.19** **0.00** **628.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/28/2020 07:02:13	02/28/2020 07:48:12	0.77	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/28/2020 07:02:19	02/28/2020 07:50:45	0.81	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	02/28/2020 09:08:20	02/28/2020 09:15:00	0.11	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	02/28/2020 09:30:00	02/28/2020 11:40:05	2.17	\$0.00
09-15	ALIGN STEERING	11310047	03/03/2020 06:39:51	03/03/2020 07:08:27	0.48	\$0.00
06-15	INSPECT STEERING	12052187	03/04/2020 07:00:00	03/04/2020 07:30:00	0.50	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	03/04/2020 06:00:00	03/04/2020 06:18:00	0.30	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/02/2020 13:23:42	03/02/2020 15:08:50	1.75	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/27/2020 14:52:27	02/27/2020 15:18:58	0.44	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/27/2020 14:51:29	02/27/2020 14:52:27	0.02	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60281	WIPER BLADE 28 IN CONV	9.86	1	\$9.86
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
03-51-038	REPLACE NEW WIPER BLADES	60-016-A	WIPER -TOYOTA SIENNA	6.48	1	\$6.48
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	38169	TIRE P235/60R17 MIC PRIM MXV4	139.85	4	\$559.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.20	4	\$8.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.30	2	\$0.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	49	\$1.96
PARTS						628.19

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 35813

Work Order Notes

(LISAPATE) PM-Replace wipers-Trac light came on and went back off made steering feel tight

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

06-15 - INSPECT STEERING

(LISAPATE) JW/SH-Checked front end no issues found

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,SH/JW

Coolant -34'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out-Found communication code for the ABS module. Checked ABS connector at module. Checked ok Checked for TSB's found none. All wheel speed sensors operating correctly. All ABS PIP's looked good. Was used as a chase vehicle and no issues were had.

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 37678

USING DEPT NO: 209317	OPENED DATE: 09/22/2020 09:10:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/24/2020 13:53:40	METER 1 - M: 82208 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/25/2020 10:51:22	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$0.00	\$75.70	\$0.00	\$75.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.40** **0.00** **75.70** **0.00** **75.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2020 13:14:33	09/22/2020 13:29:51	0.26	\$0.00
CH-32-002	CHARGE BATTERY	11074414	09/23/2020 15:13:28	09/23/2020 15:14:05	0.01	\$0.00
CH-32-002	CHARGE BATTERY	11074414	09/23/2020 15:13:28	09/23/2020 15:14:05	(0.01)	\$0.00
03-32-002	REPLACE NEW BATTERY	11074414	09/23/2020 15:04:25	09/23/2020 15:13:12	0.15	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.70	1	\$75.70
					PARTS	75.70

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 37678

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Replaced battery ALT charging 14.1 SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1083 miles. Checked fluids,battery,tire pressure and updated oil change sticker. SH

CH-32-002 - CHARGE BATTERY

(SHARBIN) Charged battery rechecked bad. SH

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 38916

USING DEPT NO:	209317	OPENED DATE:	01/26/2021 11:18:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2021 14:30:39	METER 1 - M:	82270	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2021 08:05:34	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.76	\$207.42	\$50.35	\$0.00	\$257.77

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.76** **207.42** **50.35** **0.00** **257.77**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/27/2021 10:12:26	01/27/2021 10:43:13	0.51	\$60.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2021 10:04:17	01/27/2021 11:18:58	1.24	\$146.88
					LABOR	207.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	7	\$44.21
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.14	1	\$6.14
					PARTS	50.35

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 38916

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 82271. SH/AMG Performed PM. SH washed vacuumed and filled with gas.

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 39517

USING DEPT NO:	209317	OPENED DATE:	03/30/2021 08:40:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2021 11:32:05	METER 1 - M:	86944	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2021 07:32:23	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$122.10	\$34.55	\$0.00	\$156.65

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.03** **122.10** **34.55** **0.00** **156.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/30/2021 10:19:10	03/30/2021 10:57:51	0.64	\$76.08
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/30/2021 10:26:56	03/30/2021 10:50:20	0.39	\$46.02
					LABOR	122.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	34.55

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 39517

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-86944

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 39941

USING DEPT NO:	209317	OPENED DATE:	05/12/2021 14:24:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/13/2021 10:58:09	METER 1 - M:	91961	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2021 12:51:58	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$90.73	\$67.72	\$0.00	\$158.45

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.77** **90.73** **67.72** **0.00** **158.45**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/12/2021 14:41:10	05/12/2021 15:09:21	0.47	\$55.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/12/2021 14:34:51	05/12/2021 14:52:48	0.30	\$35.30
					LABOR	90.73

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	27.29	1	\$27.29
					PARTS	67.72

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 39941

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 91961. JW AMG/SH Performed PM.

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 40748

USING DEPT NO:	209317	OPENED DATE:	08/13/2021 10:15:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2021 13:21:32	METER 1 - M:	96753	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/24/2021 07:54:46	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.28	\$31.48	\$0.00	\$36.76
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.56	\$66.38	\$0.00	\$0.00	\$66.38
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.53	\$61.95	\$0.00	\$0.00	\$61.95
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.59	\$69.98	\$530.36	\$0.00	\$600.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$87.03	\$39.17	\$0.00	\$126.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.46	290.62	601.01	2.00	893.63
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/18/2021 13:57:48	08/18/2021 14:15:00	0.29	\$33.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/16/2021 10:52:40	08/16/2021 11:36:55	0.74	\$87.03
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/16/2021 11:37:09	08/16/2021 11:39:50	0.04	\$5.28
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/18/2021 14:30:00	08/18/2021 14:48:23	0.31	\$36.15
66-17-013	PERFORM ALIGNMENT	11310047	08/18/2021 15:37:30	08/18/2021 15:50:20	0.21	\$25.24
66-17-013	PERFORM ALIGNMENT	11310047	08/19/2021 07:08:36	08/19/2021 07:27:16	0.31	\$36.71
06-15	INSPECT STEERING	11310047	08/19/2021 07:27:28	08/19/2021 08:01:13	0.56	\$66.38
					LABOR	290.62

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19280	WIPER BLADE 28IN OE BEAM	12.09	1	\$12.09
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	16A	16" REAR WIPER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	5	\$2.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	40	\$2.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.87	4	\$15.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	40877	TIRE 235/60R17 UNI TP A/S TOUR	127.50	4	\$510.00
PARTS						601.01

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 40748

Work Order Notes

(LISAPATE) PM-replace wipers
(EKIMBREL)

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) JW Mounted SH balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 96753. SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 40949

USING DEPT NO: 209317	OPENED DATE: 09/07/2021 10:06:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2021 11:30:55	METER 1 - M: 96753 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/09/2021 07:32:38	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-067	REPLACE NEW FENDER LINER	DON	O	N	GARAGE	0.51	\$60.44	\$140.91	\$0.00	\$201.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.51** **60.44** **140.91** **2.00** **203.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-067	REPLACE NEW FENDER LINER	11213180	09/07/2021 10:14:29	09/07/2021 10:45:13	0.51	\$60.44
LABOR					60.44	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-067	REPLACE NEW FENDER LINER	53805-08030	FENDER LINER	128.19	1	\$128.19
03-02-067	REPLACE NEW FENDER LINER	90189-A0008	GROMMET FENDER LINER	1.59	8	\$12.72
PARTS					140.91	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 40949

Work Order Notes

(IFALLS) Right front fender liner is damaged, replace as needed.

Job Notes

03-02-067 - REPLACE NEW FENDER LINER

(MSIDES) Replaced passenger front fender liner. MS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 41127

USING DEPT NO: 209317	OPENED DATE: 09/27/2021 09:33:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/27/2021 15:00:55	METER 1 - M: 101318 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2021 10:55:04	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.74	\$39.17	\$0.00	\$89.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.43** **50.74** **39.17** **2.00** **91.91**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/27/2021 13:52:58	09/27/2021 14:18:46	0.43	\$50.74
LABOR					50.74	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	6	\$27.00
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.61	1	\$5.61
PARTS					39.17	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 41127

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-101318

(EKIMBREL) CANCELLED WIPER JOB DUE TO VEHICLE GETTING PREMIUM WIPERS LAST TIME.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 42170

USING DEPT NO: 209317	OPENED DATE: 01/26/2022 07:11:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/01/2022 10:56:52	METER 1 - M: 106125 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/01/2022 13:55:45	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONI	DON	O	N	GARAGE	0.07	\$8.78	\$49.08	\$0.00	\$57.86
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.17	\$19.83	\$31.82	\$0.00	\$51.65
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.07	\$7.83	\$0.00	\$0.00	\$7.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.31	\$39.52	\$0.00	\$101.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.84	98.75	120.42	2.00	221.17
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	11074414	01/31/2022 08:49:54	01/31/2022 08:54:22	0.07	\$8.78
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/31/2022 08:45:43	01/31/2022 08:49:42	0.07	\$7.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/31/2022 07:40:13	01/31/2022 07:50:18	0.17	\$19.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/31/2022 07:08:22	01/31/2022 07:40:03	0.53	\$62.31
					LABOR	98.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	16A	16" REAR WIPER	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	21360	TPMS DUAL FREQ UNIV STEM	49.08	1	\$49.08
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	(1)	(\$12.43)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19280	WIPER BLADE 28IN OE BEAM	12.43	1	\$12.43
					PARTS	120.42

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 42170

Work Order Notes

(LISAPATE) PM

Job Notes

03-17-016 - REPLACE NEW TIRE PRESSURE MONITOR/SENSOR

(SHARBIN) Replaced right rear TPMS. Used TPMS tool to reset tire light. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. Check brakes on next PM may need to be replaced. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Tire light flashing right rear sensor not reading. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 42757

USING DEPT NO: 209317	OPENED DATE: 03/29/2022 10:56:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/05/2022 07:39:03	METER 1 - M: 111827 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/18/2022 09:59:41	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	0.99	\$116.49	\$261.14	\$0.00	\$377.63
03-13-002	REPLACE NEW REAR BRAKES & DRUM	DON	O	N	GARAGE	0.24	\$27.96	\$155.15	\$0.00	\$183.11
06-13	INSPECT BRAKES	DON	P	N	GARAGE	0.16	\$18.98	\$0.00	\$0.00	\$18.98
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.74	\$32.96	\$0.00	\$83.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.32	273.17	449.25	2.00	724.42
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-13-130	PERFORM Burnish Brakes	11213180	04/18/2022 07:00:00	04/18/2022 07:30:00	0.50	\$59.00
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	11213180	04/01/2022 15:43:49	04/01/2022 15:58:02	0.24	\$27.96
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11213180	04/01/2022 14:44:29	04/01/2022 15:43:43	0.99	\$116.49
06-13	INSPECT BRAKES	11074414	03/29/2022 15:18:34	03/29/2022 15:28:13	0.16	\$18.98
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/29/2022 14:33:26	03/29/2022 14:59:14	0.43	\$50.74
					LABOR	273.17

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	435120E030	FRONT ROTORS	95.61	2	\$191.22
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB980757	REAR ROTORS	44.73	2	\$89.46
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR171324	FRONT BRAKE PADS	63.36	1	\$63.36
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PWR171391	REAR PADS	65.69	1	\$65.69

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR171324	FRONT BRAKE PADS	63.36	(1)	(\$63.36)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR171324	FRONT BRAKE PADS	69.92	1	\$69.92
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB980757	REAR ROTORS	44.73	(2)	(\$89.46)
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	FBRSB980757	REAR ROTORS	44.73	2	\$89.46
					PARTS	449.25

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 42757

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(MSIDES) Replaced front brake pads and rotors. MS

03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(MSIDES) Replaced rear brake pads and rotors. MS

06-13 - INSPECT BRAKES

(SHARBIN) Inspected per work order notes from last PM. All outer pads are at 4MM suggest pads and rotors all around. SH EH

66-13-130 - PERFORM Burnish Brakes

(LISAPATE) MS burnished brakes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 43379

USING DEPT NO: 209317	OPENED DATE: 05/24/2022 11:51:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/26/2022 14:01:22	METER 1 - M: 67723 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/27/2022 14:15:58	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.25	\$40.19	\$0.00	\$88.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.41** **48.25** **40.19** **2.00** **90.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/24/2022 15:11:10	05/24/2022 15:33:44	0.38	\$44.38
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/25/2022 07:26:38	05/25/2022 07:28:36	0.03	\$3.87
LABOR					48.25	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
PARTS					40.19	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 43379

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,RC/AMG
MILEAGE-116317

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 44865

USING DEPT NO:	209317	OPENED DATE:	10/04/2022 15:36:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/06/2022 08:11:36	METER 1 - M:	117024	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2022 09:41:18	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.44	\$0.00	\$0.00	\$19.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.16** **19.44** **0.00** **5.00** **24.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2022 10:54:31	10/05/2022 11:04:24	0.16	\$19.44
LABOR					0.16	19.44

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 44865

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 707 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 46153

USING DEPT NO: 209317	OPENED DATE: 02/14/2023 15:16:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/20/2023 08:11:02	METER 1 - M: 117570 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/20/2023 10:23:48	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$29.11	\$32.72	\$0.00	\$61.83
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$14.00	\$0.00	\$0.00	\$14.00
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.38	\$44.81	\$0.00	\$0.00	\$44.81
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.33	\$157.50	\$0.00	\$0.00	\$157.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	P	N	GARAGE	0.31	\$35.99	\$329.55	\$0.00	\$365.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$7.05	\$48.87	\$0.00	\$55.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **2.44** **288.46** **411.14** **5.00** **704.60**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	12052187	02/17/2023 07:49:24	02/17/2023 07:56:31	0.12	\$14.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	02/16/2023 11:41:42	02/16/2023 12:00:00	0.31	\$35.99
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	02/15/2023 13:25:15	02/15/2023 13:48:02	0.38	\$44.81
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/15/2023 13:10:18	02/15/2023 13:25:06	0.25	\$29.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/15/2023 13:06:31	02/15/2023 13:10:06	0.06	\$7.05
66-17-013	PERFORM ALIGNMENT	11310047	02/17/2023 10:35:27	02/17/2023 11:55:32	1.33	\$157.50
LABOR					288.46	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.81	6	\$40.86
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	8.01	1	\$8.01
03-51-038	REPLACE NEW WIPER BLADES	19280	WIPER BLADE 28IN OE BEAM	12.78	1	\$12.78
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	16A	16" REAR WIPER	9.47	1	\$9.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	2	\$0.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.96	2	\$13.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	1	\$0.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	40877	TIRE 235/60R17 UNI TP A/S TOUR	157.34	2	\$314.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	(2)	(\$0.33)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.13	5	\$0.67
					PARTS	411.14

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 46153

Work Order Notes

(EHANNAH) pm- drive states tires shakes while driving

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

06-15 - INSPECT STEERING

(JWRIGHT) Front end good. JAW

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(JWRIGHT) Found the RR tire is worn below spec. The rf tire is worn funny on shoulder. Recommend replacing both tires and rotating to the front. Brake pads are 11mm all around. JAW

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Set front toe. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Performed mount and balance 2 tires- GC

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-117570

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 47240

USING DEPT NO:	209317	OPENED DATE:	06/01/2023 14:28:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/05/2023 09:18:19	METER 1 - M:	118266	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/05/2023 10:43:54	IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.19	\$22.35	\$0.00	\$0.00	\$22.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.19** **22.35** **0.00** **5.00** **27.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-13	INSPECT BRAKES	12052187	06/02/2023 08:33:59	06/02/2023 08:45:21	0.19	\$22.35
LABOR						22.35

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 47240

Work Order Notes

(EHANNAH) inspect break, making noises.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-13 - INSPECT BRAKES

(JWRIGHT) Inspected brakes and test drove. Found no issues. All pads and rotors look new. No rust built up. No noises heard while stopping and no shimmy while stopping.
JAW

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 47690

USING DEPT NO: 209317	OPENED DATE: 07/21/2023 08:44:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/25/2023 14:21:07	METER 1 - M: 118266 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/25/2023 14:21:12	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.49	\$57.82	\$0.00	\$0.00	\$57.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.78	\$54.49	\$0.00	\$73.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.13	\$15.08	\$0.00	\$0.00	\$15.08

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.78** **91.68** **54.49** **5.00** **151.17**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	07/21/2023 14:30:00	07/21/2023 14:37:40	0.13	\$15.08
WA-00	WASH COMPLETE VEHICLE	12201267	07/21/2023 14:15:52	07/21/2023 14:15:52	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/21/2023 14:05:27	07/21/2023 14:15:00	0.16	\$18.78
66-79-003	PERFORM SAFETY INSPECTION	12201267	07/21/2023 14:37:40	07/21/2023 15:07:04	0.49	\$57.82
					LABOR 91.68	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
03-21-005	REPLACE NEW CV AXLE BOOT	5412013	BOOT KIT	35.37	(1)	(\$35.37)
03-21-005	REPLACE NEW CV AXLE BOOT	5412013	BOOT KIT	35.37	1	\$35.37
					PARTS 54.49	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 47690

Work Order Notes

(LISAPATE) PM-Do SI-wash

Job Notes

03-21-005 - REPLACE NEW CV AXLE BOOT

(EKIMBREL) will bring vehicle back for boot

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection-GC, Found no issues at this time.
Brake pads are front 8mm and Rear 8mm
Miles, 118,287

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 118,287

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 49125

USING DEPT NO: 209317	OPENED DATE: 12/01/2023 10:33:31	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/05/2023 10:10:33	METER 1 - M: 118382 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/05/2023 13:14:47	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.39	\$0.00	\$0.00	\$14.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$45.76	\$0.00	\$0.00	\$45.76

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.51** **60.15** **0.00** **5.00** **65.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/01/2023 15:14:58	12/01/2023 15:22:17	0.12	\$14.39
WA-00	WASH COMPLETE VEHICLE	11074414	12/04/2023 07:01:48	12/04/2023 07:25:04	0.39	\$45.76
LABOR					60.15	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 49125

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 49457

USING DEPT NO: 209317	OPENED DATE: 01/11/2024 15:35:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2024 09:53:05	METER 1 - M: 118382 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2024 14:27:08	IN-SERVICE DATE: 09/02/2015
TECH SPEC NO: 15TOYSIENNA 2015 Toyota Sienna	UNIT SERIAL NO: 5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.15	\$17.31	\$199.98	\$0.00	\$217.29
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.65	76.31	199.98	5.00	281.29
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12201267	01/12/2024 10:42:40	01/12/2024 10:51:28	0.15	\$17.31
66-79-002	PERFORM SERVICE CALL	12201267	01/12/2024 12:01:19	01/12/2024 12:01:19	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	12201267	01/17/2024 07:00:00	01/17/2024 07:30:00	0.50	\$59.00
LABOR					76.31	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F3	BATTERY	199.98	1	\$199.98
PARTS					199.98	

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 49457

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GRCOOK) Replaced battery, unit had service call for dead battery, tested battery and battery tested bad, replaced battery, tested volts and volts was 14.14 all good. -GC

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(GRCOOK) CW and RC went on service call for dead battery, jumped unit off and brought back to shop to inspect battery. -GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241535 **2015 TOYOTA SIENNA** **WORK ORDER NO:** 49936

USING DEPT NO:	209317	OPENED DATE:	02/23/2024 15:29:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	118382	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	09/02/2015	
TECH SPEC NO:	15TOYSIENNA	2015 Toyota Sienna		UNIT SERIAL NO:	5TDZK3DC4FS624395	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.09	\$10.42	\$0.00	\$0.00	\$10.42

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.09** **10.42** **0.00** **0.00** **10.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	02/28/2024 09:53:05	02/28/2024 09:58:23	0.09	\$10.42
					LABOR	10.42

Work Order Charge Detail

UNIT NO: 241535 2015 TOYOTA SIENNA

WORK ORDER NO: 49936

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Mar 01 2024 13:27:31 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '241535') //Q=