

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 20452

USING DEPT NO:	505101	OPENED DATE:	06/03/2015 08:11:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2015 07:04:25	METER 1 - M:	161	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2015 07:04:27	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	06/03/2015 08:11:52	06/03/2015 08:41:52	0.50	\$28.75
					LABOR	28.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 20452

## Work Order Notes

(LPATE) PDI NEW UNIT

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 21736

USING DEPT NO:	505101	OPENED DATE:	10/16/2015 15:44:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/19/2015 10:53:15	METER 1 - M:	5682	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2015 10:53:16	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$39.22	\$0.00	\$57.05

JOB COUNT: 2	WORK ORDER TOTAL:	0.81	46.58	39.22	0.00	85.80
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11338644	10/16/2015 15:44:54	10/16/2015 16:03:30	0.31	\$17.83
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11338644	10/16/2015 15:44:59	10/16/2015 16:14:59	0.50	\$28.75
					LABOR	46.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.17	1	\$4.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.85	1	\$6.85
					PARTS	39.22

# Work Order Charge Detail

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 21736

Work Order Notes

(LISAPATE) PM-ROTATE TIRES

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY BG,RS/RS

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 22736

USING DEPT NO:	505101	OPENED DATE:	02/29/2016 10:17:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/01/2016 13:26:25	METER 1 - M:	10324	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2016 13:26:27	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$49.18	\$29.48	\$0.00	\$78.66

JOB COUNT: 1	WORK ORDER TOTAL:	0.86	49.18	29.48	0.00	78.66
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/29/2016 10:19:25	02/29/2016 11:10:44	0.86	\$49.18
					<b>LABOR</b>	<b>49.18</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
					<b>PARTS</b>	<b>29.48</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 22736

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH-USED 1/2QT OF OIL ALREADY CHARGED OUT

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 24280

USING DEPT NO:	505101	OPENED DATE:	09/01/2016 15:15:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2016 12:09:13	METER 1 - M:	10324	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2016 12:09:15	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$47.01	\$0.00	\$64.84

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	47.01	0.00	64.84
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/01/2016 15:15:33	09/01/2016 15:34:09	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
					PARTS	47.01

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 24280

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 25828

USING DEPT NO:	505101	OPENED DATE:	02/22/2017 09:03:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2017 14:16:36	METER 1 - M:	19600	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/02/2017 14:16:38	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$1.15	\$32.73	\$0.00	\$33.88

JOB COUNT: 1	WORK ORDER TOTAL:	0.02	1.15	32.73	0.00	33.88
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/23/2017 06:08:14	02/23/2017 11:09:35	(5.02)	(\$288.79)
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/23/2017 06:08:14	02/23/2017 11:09:35	5.02	\$288.79
66-PM-PMA	PERFORM OIL CHANGE	11170580	02/23/2017 06:08:14	02/23/2017 06:09:26	0.02	\$1.15
					<b>LABOR</b>	<b>1.15</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.66	4	\$22.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
					<b>PARTS</b>	<b>32.73</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 25828

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB  
COOLANT -45'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 27291

USING DEPT NO:	505101	OPENED DATE:	08/29/2017 08:39:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2017 13:02:30	METER 1 - M:	23996	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2017 13:02:32	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$42.84	\$0.00	\$60.67
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.30	\$17.25	\$7.33	\$0.00	\$24.58

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	35.08	50.17	0.00	85.25
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	08/29/2017 10:42:04	08/29/2017 11:00:04	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/29/2017 10:41:58	08/29/2017 11:00:34	0.31	\$17.83
					LABOR	35.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	50.17

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 27291

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 28788

USING DEPT NO:	505101	OPENED DATE:	02/05/2018 09:06:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2018 09:24:22	METER 1 - M:	28204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2018 09:24:27	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.22	\$12.78	\$25.58	\$0.00	\$38.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.60	\$27.78	\$0.00	\$45.38

JOB COUNT: 2	WORK ORDER TOTAL:	0.53	30.38	53.36	0.00	83.74
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/05/2018 09:51:31	02/05/2018 10:04:51	0.22	\$12.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/05/2018 09:33:04	02/05/2018 09:51:26	0.31	\$17.60
					LABOR	30.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	53.36

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 28788

## Work Order Notes

(LISAPATE) PM

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) FRONT WIPERS REPLACED BY SH

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/AG

COOLANT -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 29825

USING DEPT NO:	505101	OPENED DATE:	05/17/2018 07:40:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2018 13:28:35	METER 1 - M:	28204	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2018 13:28:36	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$46.00	\$46.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	46.00	46.00
--------------	-------------------	------	------	------	-------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	350628	0043404	\$46.00
COMML					46.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 29825

## Work Order Notes

(LISAPATE) CAROLYN WAS IN BIRMINGHAM NOT COMING BACK TO TUSCALOOSA FOR A FEW WEEKS. HAD A ROCK HIT AND CHIPPED THE WINDSHIELD

## Job Notes

### 24-02-061 - REPAIR WINDSHIELD

(LISAPATE) GLASS DR WENT TO CAROLYN IN BIRMINGHAM AND REPAIRED WINDSHIELD. PD BY CC



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 30011

USING DEPT NO:	505101	OPENED DATE:	06/13/2018 08:32:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2018 10:11:54	METER 1 - M:	32459	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	06/13/2018 10:11:55	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$54.02	\$0.00	\$71.85

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	54.02	0.00	71.85
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/13/2018 08:33:50	06/13/2018 08:52:26	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.44	1	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.55	5	\$27.75
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	54.02

# Work Order Charge Detail

UNIT NO: 241360 2015 TOYOTA CAMRY WORK ORDER NO: 30011

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG PERFORMED PM  
(RTUNAITI) PM by AG/SH  
Coolant -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 30546

USING DEPT NO:	505101	OPENED DATE:	08/13/2018 14:18:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2018 14:45:03	METER 1 - M:	33248	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2018 14:45:04	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 30546

## Work Order Notes

(LISAPATE) CAROLYN HAD A DEAD BATTERY WHILE IN BIRMINGHAM. JUMPED CAR OFF AND TOOK TO FIRESTONE TO HAVE BATTERY CHECKED

## Job Notes

### 03-32-002 - REPLACE NEW BATTERY

(LISAPATE) FIRESTONE CHECKED BATTERY WAS BAD. IINSTALLED NEW BATTERY.  
DRIVER PAID WITH FLEET WIX CARD THIS WO IS FOR OUR RECORDS ONLY.

FIRESTONE 460 GREENSPRINGS HWY  
BIRMINGHAM AL 35209  
INVOICE 245129 DATED 8-8-18

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 31268

USING DEPT NO:	505101	OPENED DATE:	10/24/2018 10:26:28	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2018 09:53:37	METER 1 - M:	33248	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2018 09:53:39	IN-SERVICE DATE:	06/02/2015						
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY			UNIT SERIAL NO:	4T1BF1FK1FU063479					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-017	REPLACE NEW FUEL TANK CAP	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 31268

## Work Order Notes

(LISAPATE) Driver had check engine light come on while in Birmingham she could not get to Tuscaloosa. Took to Hoover Toyota to be checked

## Job Notes

### 03-44-017 - REPLACE NEW FUEL TANK CAP

(LISAPATE) Hoover Toyota scanned and found gas cap was bad installed new gas cap. Driver paid for repair with her Fleet card. Sent us the invoice just for record purposes. See attached

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 32275

USING DEPT NO:	505101	OPENED DATE:	02/26/2019 08:26:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/01/2019 12:25:04	METER 1 - M:	36891	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2019 12:25:05	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$58.00	\$521.57	\$0.00	\$579.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.81	\$58.79	\$41.90	\$0.00	\$100.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.85	\$7.33	\$0.00	\$29.18

JOB COUNT: 4	WORK ORDER TOTAL:	2.91	211.14	570.80	0.00	781.94
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/27/2019 06:00:00	02/27/2019 06:24:00	0.40	\$29.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11268671	02/27/2019 07:00:00	02/27/2019 07:24:00	0.40	\$29.00
09-15	ALIGN STEERING	11310047	02/27/2019 07:00:00	02/27/2019 08:00:00	1.00	\$72.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	02/26/2019 09:59:33	02/26/2019 10:17:38	0.30	\$21.85
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/26/2019 09:30:00	02/26/2019 09:59:11	0.49	\$35.26
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/26/2019 08:55:32	02/26/2019 09:15:00	0.32	\$23.52
					LABOR	211.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	126.59	4	\$506.34
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	5	\$2.03
					PARTS	570.80

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 32275

## Work Order Notes

(EKIMBREL) pm

## Job Notes

### **09-15 - ALIGN STEERING**

(EKIMBREL) EH performed front end check and alignment

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(EKIMBREL) SH and IF balanced and mounted 4 new tires

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) AG performed oil change

Top and Bot: AG

Coolant -35

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(EKIMBREL) AG replaced cabin filter



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 35392

USING DEPT NO:	505101	OPENED DATE:	01/14/2020 10:08:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/17/2020 06:39:46	METER 1 - M:	41261	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/17/2020 06:39:48	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$45.68	\$35.68	\$0.00	\$81.36

JOB COUNT: 1	WORK ORDER TOTAL:	0.63	45.68	35.68	0.00	81.36
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/14/2020 10:14:31	01/14/2020 10:35:31	0.35	\$25.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/14/2020 10:14:01	01/14/2020 10:30:49	0.28	\$20.30
					LABOR	45.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					PARTS	35.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 35392

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/SH

Coolant -34'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 36789

USING DEPT NO:	505101	OPENED DATE:	06/11/2020 14:23:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/12/2020 09:38:23	METER 1 - M:	43583	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2020 09:10:13	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$67.57	\$35.68	\$0.00	\$103.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.93	67.57	35.68	0.00	103.25
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/12/2020 07:46:47	06/12/2020 08:04:51	0.30	\$21.83
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/12/2020 07:14:33	06/12/2020 07:25:40	0.19	\$13.43
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/11/2020 15:27:34	06/11/2020 15:54:18	0.45	\$32.30
					LABOR	67.56

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					PARTS	35.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 36789

## Work Order Notes

(EKIMBREL) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH,RC/JW performed pm. Coolant -35

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 38541

USING DEPT NO:	505101	OPENED DATE:	12/03/2020 09:33:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/07/2020 10:34:48	METER 1 - M:	43736	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/07/2020 12:54:11	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.69	\$80.90	\$56.95	\$0.00	\$137.85

JOB COUNT: 1	WORK ORDER TOTAL:	0.69	80.90	56.95	0.00	137.85
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2020 13:08:52	12/04/2020 13:50:00	0.69	\$80.90
					LABOR	80.90

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.33	1	\$12.33
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.26	5	\$31.28
					PARTS	56.95

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 38541

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM. SH Washed vacuumed and filled with gas.

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 39849

USING DEPT NO:	505101	OPENED DATE:	04/30/2021 14:25:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2021 15:11:27	METER 1 - M:	43877	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2021 14:26:41	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.09	\$14.16	\$0.00	\$56.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.36	42.09	14.16	0.00	56.25
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/03/2021 07:57:58	05/03/2021 08:19:22	0.36	\$42.09
					<b>LABOR</b>	<b>42.09</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	14.16	1	\$14.16
					<b>PARTS</b>	<b>14.16</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 39849

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 141 miles since last pm. Updated sticker. Checked all fluids and tires. Topped off coolant, found no leaks. Coolant -34°. JAW  
MILEAGE-43877



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 39956

USING DEPT NO:	505101	OPENED DATE:	05/14/2021 15:02:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2021 07:40:25	METER 1 - M:	43877	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2021 07:32:15	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.02	\$2.72	\$2.73	\$0.00	\$5.45

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.02</b>	<b>2.72</b>	<b>2.73</b>	<b>0.00</b>	<b>5.45</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	11170580	05/14/2021 15:52:14	05/14/2021 15:53:37	0.02	\$2.72
					<b>LABOR</b>	<b>2.72</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.73	1	\$2.73
					<b>PARTS</b>	<b>2.73</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 39956

## Work Order Notes

(LISAPATE) Key fob battery is dead

## Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(ABBLACK) AB installed a new keyfob battery

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 41457

USING DEPT NO:	505101	OPENED DATE:	10/29/2021 12:18:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 07:42:47	METER 1 - M:	43980	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/04/2021 07:42:52	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$17.90	\$0.00	\$41.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.70	\$34.32	\$0.00	\$62.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.43	51.30	52.22	2.00	105.52
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/01/2021 09:19:56	11/01/2021 09:19:56	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/01/2021 09:19:56	11/01/2021 09:19:56	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/01/2021 09:19:56	11/01/2021 09:31:56	0.20	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/01/2021 09:00:55	11/01/2021 09:15:00	0.23	\$27.70
				LABOR		51.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
					PARTS	52.22

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 41457

## Work Order Notes

(CHANNELL) PM\wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH Performed PM.

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 42106

USING DEPT NO:	505101	OPENED DATE:	01/19/2022 10:35:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/20/2022 14:43:55	METER 1 - M:	43980	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/21/2022 07:32:15	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.06	\$6.92	\$0.00	\$0.00	\$6.92
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.21	24.62	0.00	2.00	26.62
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11915538	01/20/2022 08:13:45	01/20/2022 08:22:45	0.15	\$17.70
66-79-002	PERFORM SERVICE CALL	11915538	01/20/2022 08:10:14	01/20/2022 08:13:45	0.06	\$6.92
					LABOR	24.62

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 42106

## Work Order Notes

(LISAPATE) Mackenzie Reed requested a service call to rear of Fresh Foods car has a dead battery

## Job Notes

### **66-79-002 - PERFORM SERVICE CALL**

(GARAGE) jumped off brought back to shop\CW\RC

### **CH-32-002 - CHARGE BATTERY**

(EKIMBREL) rc charged battery. Battery checked good. Charging at 14.5V

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 43144

USING DEPT NO:	505101	OPENED DATE:	05/05/2022 08:22:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/10/2022 10:45:07	METER 1 - M:	44096	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2022 13:55:43	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.98	\$17.90	\$0.00	\$22.88
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.48	\$56.31	\$0.00	\$0.00	\$56.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.99	\$0.00	\$0.00	\$39.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.86	101.28	17.90	2.00	121.18
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	05/05/2022 15:07:56	05/05/2022 15:36:34	0.48	\$56.31
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/05/2022 14:37:41	05/05/2022 14:58:01	0.34	\$39.99
03-51-038	REPLACE NEW WIPER BLADES	11901357	05/05/2022 14:34:44	05/05/2022 14:37:16	0.04	\$4.98
				LABOR		101.28

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
					PARTS	17.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 43144

## Work Order Notes

(LISAPATE) pm-replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 44096 Vehicle has been 98 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 44931

USING DEPT NO:	505101	OPENED DATE:	10/10/2022 10:09:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2022 12:02:46	METER 1 - M:	44226	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 09:18:08	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.54	\$23.10	\$0.00	\$32.64
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.63	\$42.19	\$0.00	\$73.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	41.17	65.29	5.00	111.46
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/10/2022 10:33:21	10/10/2022 10:38:12	0.08	\$9.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/10/2022 10:17:06	10/10/2022 10:33:11	0.27	\$31.63
					LABOR	41.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.38	1	\$10.38
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
					PARTS	65.29

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 44931

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 45242

USING DEPT NO:	505101	OPENED DATE:	11/11/2022 13:08:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2022 07:42:17	METER 1 - M:	44273	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2022 09:57:53	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-43	INSPECT EXHAUST SYSTEM	DON	N	N	GARAGE	0.20	\$23.63	\$0.00	\$0.00	\$23.63
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.20	23.63	0.00	5.00	28.63
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-43	INSPECT EXHAUST SYSTEM	11310047	11/11/2022 15:25:46	11/11/2022 15:37:47	0.20	\$23.63
06-43	INSPECT EXHAUST SYSTEM	11310047	11/11/2022 15:25:46	11/11/2022 15:37:47	(0.20)	(\$23.63)
06-43	INSPECT EXHAUST SYSTEM	11310047	11/11/2022 15:25:46	11/11/2022 15:37:47	0.20	\$23.63
LABOR						23.63

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 45242

## Work Order Notes

(LISAPATE) Per driver hearing a rattling noise in the right rear wheel area

## Job Notes

### **06-43 - INSPECT EXHAUST SYSTEM**

(IFALLS) The heat shield over the rear muffler was bent slightly and rubber against the muffler causing a noise. Gently bent shield away from muffler. Examined exhaust hangers and exhaust pipe and did not see any damage. EH .25hrs

(AJONES) Visit Reason Changed On 11/18/2022 1:31 PM By AJONES

### **CH-SP - CHARGE Shop Supplies**

(AJONES) Visit Reason Changed On 11/18/2022 1:31 PM By AJONES

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 46212

USING DEPT NO:	505101	OPENED DATE:	02/21/2023 09:32:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2023 14:29:52	METER 1 - M:	44347	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 07:20:00	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.55	\$64.64	\$0.00	\$0.00	\$64.64
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.46	\$0.00	\$0.00	\$12.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.08	\$9.34	\$0.00	\$0.00	\$9.34

JOB COUNT: 4	WORK ORDER TOTAL:	0.73	86.44	0.00	5.00	91.44
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	03/24/2023 10:33:24	03/24/2023 10:38:09	0.08	\$9.34
66-79-003	PERFORM SAFETY INSPECTION	11074414	03/24/2023 10:00:18	03/24/2023 10:33:10	0.55	\$64.64
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2023 09:53:46	03/24/2023 10:00:06	0.11	\$12.46
				LABOR		86.44

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 46212

## Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH  
Front brake pads measure 10MM  
Rear brake pads measure 9MM

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 121miles since the last PM. CW Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed vehicle. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 48303

USING DEPT NO:	505101	OPENED DATE:	09/22/2023 09:17:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2023 15:10:58	METER 1 - M:	44503	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 15:10:59	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.08	\$29.98	\$0.00	\$37.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.04	\$4.59	\$43.70	\$0.00	\$48.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.05	\$5.80	\$0.00	\$0.00	\$5.80

JOB COUNT: 4	WORK ORDER TOTAL:	0.15	17.47	73.68	5.00	96.15
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	09/22/2023 11:33:39	09/22/2023 11:36:36	0.05	\$5.80
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/22/2023 11:30:22	09/22/2023 11:32:42	0.04	\$4.59
03-51-038	REPLACE NEW WIPER BLADES	12395904	09/22/2023 11:22:29	09/22/2023 11:26:05	0.06	\$7.08
				LABOR	17.47	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	12.35	1	\$12.35
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
				PARTS	73.68	

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 48303

## Work Order Notes

(EHANNAH) pm - wipers- wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) 48303

Perform oil change filter new wipers fluid check tires pressure tread

(GARAGE) Replaced wipers. FC

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Performed oil changed

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed vehicle. FC



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 49735

USING DEPT NO:	505101	OPENED DATE:	02/07/2024 11:20:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/07/2024 12:36:10	METER 1 - M:	44647	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/07/2024 15:16:07	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 3	WORK ORDER TOTAL:	0.43	50.74	0.00	5.00	55.74
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 11:31:27	02/07/2024 11:35:49	(0.07)	(\$8.59)
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 11:31:27	02/07/2024 11:35:49	0.07	\$8.59
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 11:31:27	02/07/2024 11:51:15	0.33	\$38.94
WA-00	WASH COMPLETE VEHICLE	12395904	02/07/2024 11:36:13	02/07/2024 11:56:00	0.33	\$38.91
WA-00	WASH COMPLETE VEHICLE	12395904	02/07/2024 11:36:13	02/07/2024 11:56:00	(0.33)	(\$38.91)
WA-00	WASH COMPLETE VEHICLE	12395904	02/07/2024 11:36:13	02/07/2024 11:42:13	0.10	\$11.80
				LABOR		50.74

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 49735

## Work Order Notes

(LRUSHING) pm and wash

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) was fc

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/22/2024 11:39:36 By User: GLOBETTI

UNIT NO: 241360 2015 TOYOTA CAMRY

WORK ORDER NO: 50148

USING DEPT NO:	505101	OPENED DATE:	03/19/2024 07:31:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2024 10:54:51	METER 1 - M:	44647	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2024 11:48:15	IN-SERVICE DATE:	06/02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU063479	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	5.00	123.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	03/19/2024 11:45:40	03/19/2024 11:46:44	(0.02)	(\$2.10)
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	03/19/2024 11:45:40	03/19/2024 11:46:44	0.02	\$2.10
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	03/19/2024 11:45:40	03/19/2024 12:45:40	1.00	\$118.00
				LABOR		118.00

# Work Order Charge Detail

UNIT NO:	241360	2015 TOYOTA CAMRY	WORK ORDER NO:	50148
----------	--------	-------------------	----------------	-------

Work Order Notes

(EHANNAH) prep for sale

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) prepare unit for disposal FC

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Mar 22 2024 11:39:36 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '241360') //Q=