

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 24994

USING DEPT NO:	209317	OPENED DATE:	11/16/2016 07:30:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2016 14:36:30	METER 1 - M:	73	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2016 14:36:32	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11758845	11/16/2016 07:31:48	11/16/2016 07:49:48	(0.30)	(\$17.25)
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11758845	11/16/2016 07:31:48	11/16/2016 07:49:48	0.30	\$17.25
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11758845	11/16/2016 07:31:48	11/16/2016 08:01:48	0.50	\$28.75
					LABOR	28.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 24994

---

## Work Order Notes

(LISAPATE) DO PDI NEW UNIT

---

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 26574

USING DEPT NO:	209317	OPENED DATE:	06/12/2017 10:22:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/19/2017 07:38:34	METER 1 - M:	1582	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/19/2017 07:38:48	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$20.97	\$0.00	\$38.80

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	20.97	0.00	38.80
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/13/2017 15:07:41	06/13/2017 15:07:56	0.00	\$0.24
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/13/2017 15:07:41	06/13/2017 15:07:56	0.00	(\$0.24)
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/13/2017 15:07:41	06/13/2017 15:26:17	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.77	6	\$16.62
					PARTS	20.97

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 26574

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS  
COOLANT -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 28878

USING DEPT NO:	209317	OPENED DATE:	02/14/2018 07:20:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2018 10:43:43	METER 1 - M:	3301	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2018 10:43:45	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.11	\$0.00	\$40.94

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	23.11	0.00	40.94
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/14/2018 10:19:08	02/14/2018 10:37:44	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	1	\$2.11
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.38	1	\$4.38
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.77	6	\$16.62
					PARTS	23.11

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 28878

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH  
COOALNT -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 30563

USING DEPT NO:	209317	OPENED DATE:	08/15/2018 10:49:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2018 10:14:47	METER 1 - M:	5321	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/20/2018 10:14:48	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$27.45	\$0.00	\$27.45

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	0.00	27.45	0.00	27.45
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/15/2018 15:44:56	08/15/2018 16:03:32	0.31	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.85	6	\$23.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
					<b>PARTS</b>	<b>27.45</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 30563

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC/SH  
COOLANT -35'



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 33815

USING DEPT NO:	209317	OPENED DATE:	08/22/2019 10:11:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2019 10:39:05	METER 1 - M:	8505	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2019 10:39:07	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.34	\$0.00	\$27.67	\$0.00	\$27.67
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2	WORK ORDER TOTAL:	1.64	0.00	32.56	0.00	32.56
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/22/2019 11:31:41	08/22/2019 11:49:41	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/22/2019 10:42:26	08/22/2019 11:31:41	0.82	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/22/2019 10:55:40	08/22/2019 11:26:58	0.52	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
					PARTS	32.56

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 33815

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW,AG/JW

Coolant -35'

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LISAPATE) Replaced cabin filter

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 34471

USING DEPT NO:	209317	OPENED DATE:	10/16/2019 10:35:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2019 06:46:50	METER 1 - M:	13616	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2019 06:46:52	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.97	\$0.00	\$27.67	\$0.00	\$27.67

JOB COUNT: 1	WORK ORDER TOTAL:	0.97	0.00	27.67	0.00	27.67
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/16/2019 13:04:17	10/16/2019 13:24:52	0.34	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/16/2019 11:14:26	10/16/2019 11:51:50	0.62	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					PARTS	27.67

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 34471

---

## Work Order Notes

(EKIMBREL) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Coolant -35'

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 35173

USING DEPT NO:	209317	OPENED DATE:	12/12/2019 13:47:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2019 07:16:16	METER 1 - M:	17870	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2019 07:16:17	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$0.00	\$31.96	\$0.00	\$31.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.68	0.00	31.96	0.00	31.96
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2019 08:39:59	12/13/2019 09:02:17	0.37	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/13/2019 08:42:18	12/13/2019 09:00:45	0.31	\$0.00
					<b>LABOR</b>	<b>0.00</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.29	1	\$4.29
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
					<b>PARTS</b>	<b>31.96</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 35173

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EK/SH. Coolant -35

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 35981

USING DEPT NO:	209317	OPENED DATE:	03/11/2020 09:40:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/11/2020 14:17:13	METER 1 - M:	22469	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/13/2020 15:00:14	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.11	\$0.00	\$31.56	\$0.00	\$31.56

JOB COUNT: 1	WORK ORDER TOTAL:	1.11	0.00	31.56	0.00	31.56
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2020 09:54:10	03/11/2020 10:37:39	0.72	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/11/2020 09:46:26	03/11/2020 10:09:18	0.38	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					<b>PARTS</b>	<b>31.56</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 35981

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW

Coolant -35'

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 37682

USING DEPT NO:	209317	OPENED DATE:	09/22/2020 10:01:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2020 15:51:36	METER 1 - M:	23116	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2020 08:48:38	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.45	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2020 15:09:50	09/22/2020 15:36:32	0.45	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 37682

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has need driven 647 miles. Checked fluids,battery,tire pressure and updated oil change sticker. SH

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 38915

USING DEPT NO:	209317	OPENED DATE:	01/26/2021 11:17:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2021 14:36:17	METER 1 - M:	23195	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2021 08:01:05	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$83.91	\$50.35	\$0.00	\$134.26

JOB COUNT: 1	WORK ORDER TOTAL:	0.71	83.91	50.35	0.00	134.26
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/27/2021 13:00:00	01/27/2021 13:10:20	0.17	\$20.32
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/27/2021 12:31:57	01/27/2021 12:31:57	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/27/2021 11:20:51	01/27/2021 11:42:05	0.35	\$41.76
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/27/2021 10:43:35	01/27/2021 10:54:41	0.19	\$21.83
					<b>LABOR</b>	<b>83.91</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.14	1	\$6.14
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	7	\$44.21
					<b>PARTS</b>	<b>50.35</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 38915

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 23195 Completed PM bottom side Scott was top side, vacuumed and washed no fuel needed. AMG SH Completed checklist. SH

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 40032

USING DEPT NO:	209317	OPENED DATE:	05/26/2021 09:31:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2021 14:27:03	METER 1 - M:	29339	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/02/2021 07:50:01	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.41	\$48.02	\$0.00	\$0.00	\$48.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.70	\$82.47	\$44.92	\$0.00	\$127.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.12	\$14.65	\$16.22	\$0.00	\$30.87

JOB COUNT: 3	WORK ORDER TOTAL:	1.23	145.14	61.14	0.00	206.28
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	05/27/2021 10:03:26	05/27/2021 10:27:51	0.41	\$48.02
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	05/27/2021 09:55:44	05/27/2021 10:03:11	0.12	\$14.65
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/27/2021 09:08:33	05/27/2021 09:50:29	0.70	\$82.47
					LABOR	145.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	TYC800108C	CABIN FILTER TOYOTA	16.22	1	\$16.22
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	7	\$31.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	61.14

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 40032

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(AGUERRA) Rotated tires and checked brakes, no issues found, AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: Completed PM top and bottom side. Completed checklist and vacuumed out vehicle. AMG/AMG

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 41054

USING DEPT NO:	209317	OPENED DATE:	09/17/2021 09:32:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2021 07:56:25	METER 1 - M:	34107	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	09/20/2021 12:15:26	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.17	\$20.26	\$27.08	\$0.00	\$47.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.05	\$83.67	\$0.00	\$143.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.68	80.31	110.75	2.00	193.06
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/17/2021 10:18:14	09/17/2021 10:28:32	0.17	\$20.26
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/17/2021 10:07:22	09/17/2021 10:09:21	0.03	\$3.90
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/17/2021 09:38:25	09/17/2021 10:06:58	0.48	\$56.15
				LABOR		80.31

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	7	\$44.21
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.18	1	\$9.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.61	1	\$5.61
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	27.29	1	\$27.29
				PARTS		110.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 41054

## Work Order Notes

(IFALLS) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Andrew and Scott replaced front and rear wipers. SH AB

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 34107 Completed PM bottom side, Andrew and Scott were top side. Completed checklist. AB SH/AMG

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 41604

USING DEPT NO:	209317	OPENED DATE:	11/12/2021 09:31:55	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2021 14:21:23	METER 1 - M:	39412	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/22/2021 08:20:39	IN-SERVICE DATE:	11/15/2016						
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander									
			UNIT SERIAL NO:	5TDKKRFH6GS178233							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.12	\$14.62	\$2.13	\$0.00	\$16.75
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.88	\$104.20	\$0.00	\$0.00	\$104.20
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$94.73	\$630.71	\$0.00	\$725.44
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.28	\$32.55	\$0.00	\$0.00	\$32.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.70	\$43.39	\$0.00	\$120.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.74	322.80	676.23	2.00	1,001.03
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11310047	11/18/2021 09:30:00	11/18/2021 10:22:59	0.88	\$104.20
66-17-013	PERFORM ALIGNMENT	11310047	11/18/2021 09:25:59	11/18/2021 09:25:59	0.00	\$0.00
03-51-042	REPLACE NEW KEY FOB BATTERY	11901357	11/18/2021 08:27:21	11/18/2021 08:34:47	0.12	\$14.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	11/18/2021 08:19:15	11/18/2021 08:20:18	0.02	\$2.07
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	11/17/2021 14:35:52	11/17/2021 15:22:59	0.79	\$92.66
66-79-003	PERFORM SAFETY INSPECTION	11213180	11/15/2021 13:54:49	11/15/2021 14:11:22	0.28	\$32.55
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/15/2021 13:00:00	11/15/2021 13:39:00	0.65	\$76.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/15/2021 12:45:59	11/15/2021 12:45:59	0.00	\$0.00
					LABOR	322.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006508	TIRE P245/60R18 DUEL ECOPIA422	309.48	2	\$618.96
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2032	BUTTON CELL BATTERY 3V	2.13	1	\$2.13
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	2	\$8.61

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	12	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	1	\$0.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.44	2	\$0.87
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	7	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					<b>PARTS</b>	<b>676.23</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 41604

## Work Order Notes

(LISAPATE) PM-Do annual SI

## Job Notes

### **03-51-042 - REPLACE NEW KEY FOB BATTERY**

(AGUERRA) Replaced key fob battery and checked for proper operation, all good. AMG

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Performed alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(AGUERRA) Replaced and balanced 2 rear tires. AMG

### **66-79-003 - PERFORM SAFETY INSPECTION**

(MSIDES) Performed SI. MS

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW  
MILEAGE-39412

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 42566

USING DEPT NO:	209317	OPENED DATE:	03/04/2022 08:52:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2022 14:52:48	METER 1 - M:	45613	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/11/2022 07:58:01	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.77	\$90.79	\$0.00	\$0.00	\$90.79
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.44	\$52.41	\$0.00	\$0.00	\$52.41
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.63	\$73.98	\$440.74	\$0.00	\$514.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$104.20	\$37.45	\$0.00	\$141.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.72	321.38	478.19	2.00	801.57
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	03/07/2022 07:28:38	03/07/2022 07:55:17	0.44	\$52.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/07/2022 07:04:11	03/07/2022 07:04:52	0.01	\$1.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	03/04/2022 15:32:26	03/04/2022 15:41:14	0.15	\$17.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	03/04/2022 14:08:15	03/04/2022 14:37:04	0.48	\$56.67
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/04/2022 09:59:05	03/04/2022 10:51:23	0.87	\$102.86
06-15	INSPECT STEERING	11310047	03/07/2022 08:41:01	03/07/2022 09:15:00	0.57	\$66.83
06-15	INSPECT STEERING	11310047	03/07/2022 09:30:00	03/07/2022 09:42:11	0.20	\$23.96
				LABOR		321.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	7	\$31.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.83	2	\$9.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	14	\$2.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	B006508	TIRE P245/60R18 DUELER HL	214.17	2	\$428.34
PARTS						478.19

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 42566

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 06-15 - INSPECT STEERING

(EHOWELL) Front end good. JAW

### 09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced front tires. Torqued to spec. JAW

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -64°. JAW  
MILEAGE-45613

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 43030

USING DEPT NO:	209317	OPENED DATE:	04/25/2022 13:43:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2022 13:17:41	METER 1 - M:	50924	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2022 14:50:24	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$6.29	\$0.00	\$18.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.55	\$44.43	\$0.00	\$72.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.35	50.72	2.00	93.07
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	11213180	04/28/2022 07:00:00	04/28/2022 07:06:00	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/25/2022 14:00:29	04/25/2022 14:15:00	0.24	\$28.55
					LABOR	40.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2032	BUTTON CELL BATTERY 3V	6.29	1	\$6.29
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	7	\$31.40
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
					PARTS	50.72

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 43030

## Work Order Notes

(LISAPATE) PM-Key fob battery is dead

## Job Notes

**03-51-042 - REPLACE NEW KEY FOB BATTERY**

(LISAPATE) MS installed new key fob battery

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/JW Performed PM.

**CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 43353

USING DEPT NO:	209317	OPENED DATE:	05/23/2022 10:50:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/26/2022 14:29:14	METER 1 - M:	53490	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2022 14:12:46	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.72	\$84.73	\$7.06	\$0.00	\$91.79
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.22	143.73	7.06	2.00	152.79
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11915538	05/26/2022 07:00:00	05/26/2022 07:30:00	0.50	\$59.00
66-17-030	PERFORM TIRE PATCH	11074414	05/24/2022 09:30:00	05/24/2022 10:12:15	0.70	\$83.09
66-17-030	PERFORM TIRE PATCH	11074414	05/24/2022 09:28:48	05/24/2022 09:28:48	0.00	\$0.00
66-17-030	PERFORM TIRE PATCH	11074414	05/24/2022 09:05:06	05/24/2022 09:05:56	0.01	\$1.64
				LABOR		143.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	8	\$1.32
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	2.58	1	\$2.58
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
66-17-030	PERFORM TIRE PATCH	58121	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
				PARTS		7.06

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 43353

## Work Order Notes

(LISAPATE) Lindsey requested a service call to Univ Hall unit has a flat tire on the LR

## Job Notes

### **66-17-030 - PERFORM TIRE PATCH**

(HHARBIN) Patched left rear tire. SH

### **66-79-002 - PERFORM SERVICE CALL**

(EKIMBREL) JW/RC PERFORMED SERVICE CALLED. AIRED TIRE UP AND BROUGHT TO SHOP.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 44290

USING DEPT NO:	209317	OPENED DATE:	08/15/2022 11:28:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2022 11:16:54	METER 1 - M:	55434	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/18/2022 13:53:24	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.27	\$32.19	\$27.57	\$0.00	\$59.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.06	\$125.38	\$47.12	\$0.00	\$172.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.34	157.57	74.69	2.00	234.26
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/15/2022 13:09:52	08/15/2022 13:26:14	0.27	\$32.19
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/15/2022 12:46:44	08/15/2022 13:08:56	0.37	\$43.66
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/15/2022 12:21:34	08/15/2022 13:03:07	0.69	\$81.72
				LABOR		157.57

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	(7)	(\$40.43)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.47	1	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.52	1	\$7.52
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.58	1	\$10.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	7	\$40.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
					PARTS	74.69

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 44290

---

## Work Order Notes

(LRUSHING) PM

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced wipers. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) miles: 55434 Completed PM topside, Josh was bottom side. AMG/JW

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 45789

USING DEPT NO:	209317	OPENED DATE:	01/12/2023 15:39:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/19/2023 09:04:54	METER 1 - M:	58813	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/19/2023 10:27:17	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.54	\$27.88	\$0.00	\$35.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.41	\$55.44	\$0.00	\$111.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$6.23	\$13.17	\$0.00	\$19.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.59	70.18	96.49	5.00	171.67
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/13/2023 12:46:30	01/13/2023 13:15:11	0.48	\$56.41
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/13/2023 12:42:24	01/13/2023 12:46:14	0.06	\$7.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	01/13/2023 12:38:59	01/13/2023 12:42:09	0.05	\$6.23
				LABOR		70.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.47	1	\$9.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
				PARTS		96.49

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 45789

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 58813 Completed PM topside, Gregg was bottomside. AMG/GC

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 46918

USING DEPT NO:	209317	OPENED DATE:	05/01/2023 09:48:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2023 14:51:08	METER 1 - M:	62088	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2023 11:50:06	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.15	\$60.87	\$0.00	\$115.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.09	\$10.06	\$0.00	\$0.00	\$10.06

JOB COUNT: 3	WORK ORDER TOTAL:	0.54	64.21	60.87	5.00	130.08
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	05/02/2023 07:45:20	05/02/2023 07:50:27	0.09	\$10.06
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/02/2023 07:17:24	05/02/2023 07:44:56	0.46	\$54.15
				LABOR		64.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	7	\$43.79
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	(6)	(\$37.53)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
				PARTS		60.87

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 46918

## Work Order Notes

(EHANNAH) pm- replace wipers-wash

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- RC,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 62,088

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-CW



# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 48309

USING DEPT NO:	209317	OPENED DATE:	09/22/2023 15:15:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2023 07:48:45	METER 1 - M:	64484	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2023 08:16:10	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.32	\$62.14	\$0.00	\$84.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.02	\$2.13	\$0.00	\$0.00	\$2.13

JOB COUNT: 3	WORK ORDER TOTAL:	0.21	24.45	62.14	5.00	91.59
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/25/2023 07:38:30	09/25/2023 07:49:51	0.19	\$22.32
WA-00	WASH COMPLETE VEHICLE	12395904	09/25/2023 07:49:51	09/25/2023 07:50:56	0.02	\$2.13
				LABOR		24.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	12.35	1	\$12.35
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	7	\$43.89
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
					PARTS	62.14

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 48309

## Work Order Notes

(EHANNAH) pm- wash

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm fc

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) car wash closed

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 49847

USING DEPT NO:	209317	OPENED DATE:	02/19/2024 07:32:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/19/2024 12:26:23	METER 1 - M:	67808	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2024 12:45:03	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	P	N	GARAGE	0.04	\$4.95	\$199.98	\$0.00	\$204.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.39	\$60.67	\$0.00	\$85.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.31	\$36.65	\$0.00	\$0.00	\$36.65

JOB COUNT: 4	WORK ORDER TOTAL:	0.56	65.99	260.65	5.00	331.64
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	02/19/2024 11:33:43	02/19/2024 11:52:21	0.31	\$36.65
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2024 11:21:19	02/19/2024 11:33:43	0.21	\$24.39
03-32-002	REPLACE NEW BATTERY	11074414	02/19/2024 11:52:21	02/19/2024 11:54:52	0.04	\$4.95
				LABOR		65.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.67	1	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	7	\$48.09
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	(7)	(\$48.09)
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
03-32-002	REPLACE NEW BATTERY	24F3	BATTERY	199.98	1	\$199.98
					PARTS	260.65

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 49847

## Work Order Notes

(EHANNAH) pm- wash

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(GARAGE) Battery tested bad. Installed a new battery ALT charging at 13.9. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed full of gas. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 49937

USING DEPT NO:	209317	OPENED DATE:	02/23/2024 15:35:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	OPEN	COMPLETED DATE:		METER 1 - M:	67808	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	16TOYHIGHLAND	2016 toyota highlander		UNIT SERIAL NO:	5TDKKRFH6GS178233	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.07	\$8.82	\$0.00	\$0.00	\$8.82

JOB COUNT: 1	WORK ORDER TOTAL:	0.07	8.82	0.00	0.00	8.82
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	02/28/2024 09:48:36	02/28/2024 09:53:05	0.07	\$8.82
					<u>LABOR</u>	<u>8.82</u>

# Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 13:20:15 By User: GLOBETTI

UNIT NO: 242137 2016 TOYOTA HIGHLANDER

WORK ORDER NO: 49937

## Work Order Notes

(EHANNAH) prep for sale

## Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC  
millage 67832

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Mar 01 2024 13:20:15 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '5TDKKRFH6GS178233') //Q=