

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 24991

USING DEPT NO:	218142	OPENED DATE:	11/16/2016 07:22:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/17/2016 14:33:52	METER 1 - M:	226	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2016 14:33:54	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	11/16/2016 07:22:54	11/16/2016 07:52:54	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 24991

Work Order Notes

(LISAPATE) DO PDI NEW UNIT

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 26102

USING DEPT NO:	218142	OPENED DATE:	04/07/2017 13:59:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2017 07:31:22	METER 1 - M:	5140	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	04/11/2017 07:31:24	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.88	\$50.62	\$30.95	\$0.00	\$81.57

JOB COUNT: 1	WORK ORDER TOTAL:	0.88	50.62	30.95	0.00	81.57
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/10/2017 07:03:17	04/10/2017 07:56:06	0.88	\$50.62
					LABOR	50.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
					PARTS	30.95

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 26102

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH PERFORMED PM COOLANT CHECKED GOOD TO-45

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 26611

USING DEPT NO:	218142	OPENED DATE:	06/14/2017 15:49:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/21/2017 13:26:09	METER 1 - M:	9694	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2017 13:26:11	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$39.49	\$0.00	\$57.32

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	39.49	0.00	57.32
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/16/2017 07:00:00	06/16/2017 07:18:36	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.15	5	\$20.77
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.84	1	\$6.84
					PARTS	39.49

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 26611

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/14/2017 3:50 PM By LISAPATE

(LISAPATE) PM BY EK/CS

COOLANT -27'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 27273

USING DEPT NO:	218142	OPENED DATE:	08/28/2017 08:01:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2017 15:01:41	METER 1 - M:	15067	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2017 15:01:42	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$18.64	\$35.49	\$0.00	\$54.13

JOB COUNT: 1	WORK ORDER TOTAL:	0.32	18.64	35.49	0.00	54.13
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/29/2017 15:02:26	08/29/2017 15:03:17	0.01	\$0.81
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/29/2017 07:00:00	08/29/2017 07:18:36	0.31	\$17.83
					LABOR	18.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	4	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
					PARTS	35.49

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 27273

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS-REPLACED AIR FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 27833

USING DEPT NO:	218142	OPENED DATE:	10/16/2017 09:55:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2017 07:19:20	METER 1 - M:	19564	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2017 07:19:22	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.97	\$55.54	\$35.31	\$0.00	\$90.85
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$7.33	\$0.00	\$24.58

JOB COUNT: 2	WORK ORDER TOTAL:	1.27	72.79	42.64	0.00	115.43
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	10/16/2017 15:42:41	10/16/2017 16:00:41	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/16/2017 14:41:48	10/16/2017 15:39:45	0.97	\$55.54
					LABOR	72.79

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	4	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.75	1	\$6.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
					PARTS	42.64

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 27833

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 28185

USING DEPT NO:	218142	OPENED DATE:	11/17/2017 10:00:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/20/2017 08:05:31	METER 1 - M:	23977	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/20/2017 08:05:33	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.54	\$0.00	\$41.37

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	23.54	0.00	41.37
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 13:43:12	11/17/2017 14:01:48	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 13:43:12	11/17/2017 13:43:22	0.00	(\$0.16)
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/17/2017 13:43:12	11/17/2017 13:43:22	0.00	\$0.16
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.16	4	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
					PARTS	23.54

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 28185

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 28973

USING DEPT NO:	218142	OPENED DATE:	02/22/2018 10:24:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2018 10:41:09	METER 1 - M:	28599	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/25/2018 10:41:12	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$22.98	\$23.19	\$0.00	\$46.17

JOB COUNT: 1	WORK ORDER TOTAL:	0.40	22.98	23.19	0.00	46.17
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2018 11:31:37	02/22/2018 11:55:36	0.40	\$22.98
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2018 13:08:06	02/22/2018 13:10:16	0.04	\$2.08
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2018 13:08:06	02/22/2018 13:10:16	(0.04)	(\$2.08)
					LABOR	22.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.16	4	\$16.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.57	1	\$6.57
					PARTS	23.19

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 28973

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 29353

USING DEPT NO:	218142	OPENED DATE:	04/09/2018 10:40:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2018 07:05:06	METER 1 - M:	33601	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2018 07:05:07	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.93	\$0.00	\$59.76

JOB COUNT: 3	WORK ORDER TOTAL:	1.81	104.08	41.93	0.00	146.01
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11213180	05/04/2018 07:30:00	05/04/2018 08:30:00	1.00	\$57.50
06-13	INSPECT BRAKES	11213180	05/04/2018 07:00:00	05/04/2018 07:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2018 10:41:00	04/09/2018 10:59:36	0.31	\$17.83
					LABOR	104.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
					PARTS	41.93

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 29353

Work Order Notes

(LISAPATE) PM

4/20/18-CUSTOMER COMPLAINED OF NOISE WHEN BREAKING AND TURNING. NOISE STARTED AFTER LEFT REAR TIRE BLEW OUT.

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) FOUND BACKING PLATE RIGHT FRONT PUSHED INTO ROTOR

STRAIGHTENED OUT RIGHT FRONT BACKING PLATE INSPECTED ALL BRAKES AND UNDERCARRIAGE FOR MORE DAMAGE. TEST DROVE VEHICLE ALL GOOD. AG

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) MS PERFORMED ALIGNMENT ADJUSTED FRONT AND REAR TOE

66-00-098 - PERFORM Safety Inspection

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY RC/AG

COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 29943

USING DEPT NO:	218142	OPENED DATE:	05/31/2018 15:34:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2018 06:52:50	METER 1 - M:	37486	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	06/08/2018 06:52:51	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-071	REPLACE NEW FUEL DOOR LEVER/RE	DON	O	N	GARAGE	0.30	\$17.25	\$123.91	\$0.00	\$141.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$47.44	\$0.00	\$65.27

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	35.08	171.35	0.00	206.43
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-071	REPLACE NEW FUEL DOOR LEVER/RELEASE HANDL	11758845	06/07/2018 07:00:00	06/07/2018 07:18:00	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/07/2018 07:00:00	06/07/2018 07:18:36	0.31	\$17.83
					LABOR	35.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.57	5	\$27.83
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.09	1	\$13.09
03-02-071	REPLACE NEW FUEL DOOR LEVER/RELEASE HANDL	64606-06020	TRUNK AND FUEL RELEASE HANDLE	119.56	1	\$119.56
03-02-071	REPLACE NEW FUEL DOOR LEVER/RELEASE HANDL	64648-12020	GROMMET	4.35	1	\$4.35
					PARTS	171.35

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 29943

Work Order Notes

(IFALLS) PM . GAS CAP LEVER/TRUNK LEVER LOOSE

Job Notes

03-02-071 - REPLACE NEW FUEL DOOR LEVER/RELEASE HANDLE

(IFALLS) CS REPLACED FUEL DOOR RELEASE HANDLE

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) Visit Reason Changed On 5/31/2018 3:36 PM By IFALLS

(IFALLS) AG PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30366

USING DEPT NO:	218142	OPENED DATE:	07/25/2018 13:45:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/30/2018 07:30:05	METER 1 - M:	41422	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2018 07:30:07	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$35.32	\$0.00	\$53.15

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	35.32	0.00	53.15
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/26/2018 07:00:00	07/26/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.76	5	\$28.80
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
					PARTS	35.32

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30366

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 7/25/2018 1:45 PM By LISAPATE

(LISAPATE) PM BY EK/AG

COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30561

USING DEPT NO:	218142	OPENED DATE:	08/15/2018 09:50:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/20/2018 10:09:23	METER 1 - M:	42973	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/20/2018 10:09:24	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.58	\$0.00	\$39.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.25	14.38	25.58	0.00	39.96
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/15/2018 15:42:26	08/15/2018 15:57:26	0.25	\$14.38
					LABOR	14.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
					PARTS	25.58

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30561

Work Order Notes

(LISAPATE) PER FLEET REPLACE WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30869

USING DEPT NO:	218142	OPENED DATE:	09/18/2018 14:49:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2018 07:52:24	METER 1 - M:	45460	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2018 07:52:27	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.56	\$89.60	\$15.60	\$0.00	\$105.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.72	\$41.34	\$49.22	\$0.00	\$90.56
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$484.24	\$484.24

JOB COUNT: 4	WORK ORDER TOTAL:	3.28	188.44	64.82	484.24	737.50
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	248704	0045120	\$484.24
	COMML				484.24

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/19/2018 06:12:35	09/19/2018 06:31:33	0.32	\$18.18
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/19/2018 06:07:00	09/19/2018 06:31:10	0.40	\$23.16
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/19/2018 14:06:36	09/19/2018 15:26:54	1.34	\$76.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/19/2018 14:06:12	09/19/2018 14:19:24	0.22	\$12.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/19/2018 14:06:12	09/20/2018 06:19:13	16.22	\$932.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/19/2018 14:06:12	09/20/2018 06:19:13	(16.22)	(\$932.47)
09-15	ALIGN STEERING	11310047	09/25/2018 07:00:00	09/25/2018 08:00:00	1.00	\$57.50
	LABOR					188.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.61	1	\$13.61
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.51	1	\$6.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	4	\$13.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	6	\$2.34
	PARTS					64.82

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 30869

Work Order Notes

(LISAPATE) PM

Job Notes

09-15 - ALIGN STEERING

(LISAPATE) EH performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) SH/AG Mounted and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 9/18/2018 2:49 PM By LISAPATE

(LISAPATE) PM by EK,SH/AG

Coolant -20'

Replaced air filter

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Purchased 4 tires from Firestone. Pd by cc

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 31385

USING DEPT NO:	218142	OPENED DATE:	11/02/2018 13:13:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2018 07:11:45	METER 1 - M:	49136	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/06/2018 07:11:47	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$30.95	\$35.66	\$0.00	\$66.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.11	\$8.30	\$7.33	\$0.00	\$15.63

JOB COUNT: 2	WORK ORDER TOTAL:	0.54	39.25	42.99	0.00	82.24
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/05/2018 07:02:24	11/05/2018 07:09:16	0.11	\$8.30
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/05/2018 06:27:54	11/05/2018 06:39:19	0.19	\$13.80
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/02/2018 14:38:49	11/02/2018 14:53:01	0.24	\$17.16
					LABOR	39.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
					PARTS	42.99

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 31385

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG/SH
Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 32438

USING DEPT NO:	218142	OPENED DATE:	03/25/2019 10:06:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2019 10:18:12	METER 1 - M:	57735	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2019 10:18:13	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.04	\$75.58	\$35.59	\$0.00	\$111.17

JOB COUNT: 1	WORK ORDER TOTAL:	1.04	75.58	35.59	0.00	111.17
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/25/2019 10:49:58	03/25/2019 11:52:31	1.04	\$75.58
					LABOR	75.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
					PARTS	35.59

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 32438

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by RC/AG

Coolant -35'

Previous oil change was done at Express Oil Change

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 32958

USING DEPT NO:	218142	OPENED DATE:	05/20/2019 09:19:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2019 06:22:11	METER 1 - M:	62066	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/23/2019 06:22:13	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$55.56	\$57.17	\$0.00	\$112.73

JOB COUNT: 1	WORK ORDER TOTAL:	0.77	55.56	57.17	0.00	112.73
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/20/2019 14:30:00	05/20/2019 14:47:28	0.29	\$21.11
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/20/2019 13:46:29	05/20/2019 14:15:00	0.48	\$34.46
					LABOR	55.57

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	15.20	1	\$15.20
					PARTS	57.17

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 32958

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,EK/AG

Replaced air filter

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 33059

USING DEPT NO:	218142	OPENED DATE:	06/03/2019 13:19:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/21/2019 08:49:05	METER 1 - M:	63229	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2019 08:49:06	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.55	\$39.73	\$0.00	\$0.00	\$39.73
15-17	WARRANTY TIRES, TUBES, LINERS & V	DON	O	N	GARAGE	0.00	\$0.00	\$76.32	\$0.00	\$76.32
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.20	\$14.50	\$1.08	\$0.00	\$15.58

JOB COUNT: 5	WORK ORDER TOTAL:	1.75	126.73	77.40	0.00	204.13
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11310047	06/19/2019 07:00:00	06/19/2019 07:30:00	0.50	\$36.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	06/19/2019 07:30:00	06/19/2019 07:42:00	0.20	\$14.50
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11213180	06/19/2019 07:00:00	06/19/2019 07:30:00	0.50	\$36.25
09-15	ALIGN STEERING	11310047	06/07/2019 08:02:35	06/07/2019 08:35:28	0.55	\$39.73
					LABOR	126.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.31	1	\$3.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	023206	TIRE 205/65R16 ECOPIA EP422+	178.71	1	\$178.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.31	(1)	(\$3.31)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	2	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21097	TPMS NICKEL VALVE CORE	0.27	1	\$0.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	023206	TIRE 205/65R16 ECOPIA EP422+	178.71	(1)	(\$178.71)
15-17	WARRANTY TIRES, TUBES, LINERS & VALVES	023206	TIRE 205/65R16 ECOPIA EP422+	76.32	1	\$76.32
					PARTS	77.40

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 33059

Work Order Notes

(LISAPATE) Per Fleet customer complained of noise at 65mph coming from rear end

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) EH checked front end parts all ok at this time

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Found car has been 30,000 miles since last alignment and noise was due to wear on LR tire. Installed new tire

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

15-17 - WARRANTY TIRES, TUBES, LINERS & VALVES

(RTUNAITI) LR tire replacement cost prorated under warranty.

Original vendor: Firestone invoice 248704, 09/19/2018

Original WO 30869

Mileage: 17,000

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced LR tire

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 33599

USING DEPT NO:	218142	OPENED DATE:	08/01/2019 09:32:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/05/2019 07:16:37	METER 1 - M:	66210	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/05/2019 07:16:39	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$68.21	\$35.60	\$0.00	\$103.81

JOB COUNT: 1	WORK ORDER TOTAL:	0.94	68.21	35.60	0.00	103.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/01/2019 11:43:59	08/01/2019 11:57:01	0.22	\$15.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/01/2019 13:00:37	08/01/2019 13:44:02	0.72	\$52.46
					LABOR	68.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					PARTS	35.60

Work Order Charge Detail

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 33599

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG
Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34212

USING DEPT NO:	218142	OPENED DATE:	09/23/2019 11:35:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2019 07:06:44	METER 1 - M:	70536	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2019 07:06:45	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$67.87	\$35.44	\$0.00	\$103.31

JOB COUNT: 1	WORK ORDER TOTAL:	0.94	67.87	35.44	0.00	103.31
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/23/2019 14:57:15	09/23/2019 15:53:25	0.94	\$67.87
					LABOR	67.87

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.26	1	\$6.26
					PARTS	35.44

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34212

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW. Coolant -34

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34367

USING DEPT NO:	218142	OPENED DATE:	10/08/2019 08:51:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/09/2019 14:55:58	METER 1 - M:	71668	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	10/09/2019 14:56:01	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.85	\$61.83	\$182.90	\$0.00	\$244.73

JOB COUNT: 1	WORK ORDER TOTAL:	0.85	61.83	182.90	0.00	244.73
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/08/2019 13:00:24	10/08/2019 13:22:12	0.36	\$26.34
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/08/2019 11:30:38	10/08/2019 12:00:00	0.49	\$35.48
					LABOR	61.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	023206	TIRE 205/65R16 ECOPIA EP422+	178.71	1	\$178.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.44	2	\$0.87
					PARTS	182.90

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: **242139** **2017 TOYOTA CAMRY**

WORK ORDER NO: **34367**

Work Order Notes

(LISAPATE) Nail in LR tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Could not patch removed and replaced LR tire. rechecked ok

66-17-030 - PERFORM TIRE PATCH

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34809

USING DEPT NO:	218142	OPENED DATE:	11/11/2019 11:28:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/14/2019 13:36:06	METER 1 - M:	75355	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2019 13:36:06	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$42.31	\$42.11	\$0.00	\$84.42
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.75	\$7.33	\$0.00	\$29.08

JOB COUNT: 2	WORK ORDER TOTAL:	0.88	64.06	49.44	0.00	113.50
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/12/2019 06:37:55	11/12/2019 06:55:55	0.30	\$21.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/12/2019 06:02:54	11/12/2019 06:37:55	0.58	\$42.31
					LABOR	64.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	4	\$23.28
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	12.33	1	\$12.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
					PARTS	49.44

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34809

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Coolant -35'

Replaced air filter

**** will need tires next PM****

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34882

USING DEPT NO:	218142	OPENED DATE:	11/14/2019 15:20:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2019 14:54:19	METER 1 - M:	75691	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/19/2019 14:54:20	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	2.51	\$181.85	\$0.00	\$0.00	\$181.85
10-13	SERVICE BRAKES	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 2	WORK ORDER TOTAL:	3.01	218.10	0.00	0.00	218.10
--------------	-------------------	------	--------	------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
10-13	SERVICE BRAKES	11213180	11/18/2019 08:53:03	11/18/2019 09:23:03	0.50	\$36.25
06-13	INSPECT BRAKES	11213180	11/18/2019 06:22:33	11/18/2019 08:53:03	2.51	\$181.85
					LABOR	218.10

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 34882

Work Order Notes

(LISAPATE) Per fleet customer brakes are rough and noisy, braking ok

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) Found pads to have proof of oxidation.

10-13 - SERVICE BRAKES

(LISAPATE) Cleaned pads and test drove. No noise found. All brake parts have plenty of wear material

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 35745

USING DEPT NO:	218142	OPENED DATE:	02/24/2020 09:09:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2020 10:43:52	METER 1 - M:	80796	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2020 10:43:53	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.30	\$21.87	\$0.00	\$0.00	\$21.87
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.49	\$35.53	\$582.30	\$0.00	\$617.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$62.75	\$68.56	\$0.00	\$131.31

JOB COUNT: 4	WORK ORDER TOTAL:	2.16	156.40	650.86	0.00	807.26
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	02/25/2020 10:18:47	02/25/2020 10:48:11	0.49	\$35.53
09-15	ALIGN STEERING	11213180	02/25/2020 13:56:54	02/25/2020 14:15:00	0.30	\$21.87
06-15	INSPECT STEERING	11074414	02/26/2020 06:00:00	02/26/2020 06:30:00	0.50	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/24/2020 11:02:15	02/24/2020 11:54:11	0.87	\$62.75
					LABOR	156.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	7031682	OIL FILTER HOUSING CAP	32.96	1	\$32.96
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	141.38	4	\$565.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	8	\$3.60
					PARTS	650.86

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 35745

Work Order Notes

(LISAPATE) PM-Rotate tires

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) SH/AG Checked front end no issues found

09-15 - ALIGN STEERING

(LISAPATE) MS Performed alignment

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 36436

USING DEPT NO:	218142	OPENED DATE:	05/14/2020 13:17:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/15/2020 07:23:06	METER 1 - M:	82467	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/15/2020 07:23:09	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$34.90	\$35.60	\$0.00	\$70.50

JOB COUNT: 1	WORK ORDER TOTAL:	0.48	34.90	35.60	0.00	70.50
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11915538	05/14/2020 15:14:27	05/14/2020 15:38:27	0.40	\$29.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/14/2020 15:14:41	05/14/2020 15:19:34	0.08	\$5.90
					LABOR	34.90

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
					PARTS	35.60

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 36436

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC/JW performed pm. Coolant -34

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 38188

USING DEPT NO:	218142	OPENED DATE:	10/28/2020 09:27:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/29/2020 09:34:36	METER 1 - M:	82473	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/29/2020 10:01:18	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.01	\$1.61	\$114.48	\$0.00	\$116.09
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$106.33	\$0.00	\$0.00	\$106.33

JOB COUNT: 2	WORK ORDER TOTAL:	0.91	107.94	114.48	0.00	222.42
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	10/28/2020 13:58:54	10/28/2020 13:59:43	0.01	\$1.61
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/28/2020 13:04:36	10/28/2020 13:58:40	0.90	\$106.33
					LABOR	107.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	0.93	1	\$0.93
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	114.48

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 38188

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Battery tested bad. Replaced battery. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 82473. Vehicle has been driven 6 miles since last PM. Checked fluids, replaced battery adjusted tire pressures and updated oil change sticker. Vacuumed inside of vehicle and washed vehicle. Vehicle was full of gas. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 39292

USING DEPT NO:	218142	OPENED DATE:	03/04/2021 10:42:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/26/2021 11:58:22	METER 1 - M:	84471	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2021 14:44:17	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$90.79	\$36.63	\$0.00	\$127.42

JOB COUNT: 1	WORK ORDER TOTAL:	0.77	90.79	36.63	0.00	127.42
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2021 14:49:21	03/24/2021 15:30:13	0.68	\$80.37
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2021 14:30:00	03/24/2021 14:35:18	0.09	\$10.42
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/24/2021 14:17:21	03/24/2021 14:17:21	0.00	\$0.00
					LABOR	90.79

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	36.63

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 39292

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 84471. SH/AMG Performed PM. SH Washed vacuumed and filled with gas.

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 40538

USING DEPT NO:	218142	OPENED DATE:	07/26/2021 13:23:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2021 10:27:28	METER 1 - M:	89567	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/29/2021 12:23:19	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.80	\$21.71	\$0.00	\$33.51
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.73	\$86.60	\$0.00	\$0.00	\$86.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.36	\$47.23	\$0.00	\$102.59
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.06	\$6.62	\$21.74	\$0.00	\$28.36

JOB COUNT: 4	WORK ORDER TOTAL:	1.36	160.38	90.68	0.00	251.06
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/28/2021 07:19:47	07/28/2021 08:03:49	0.73	\$86.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/27/2021 15:42:39	07/27/2021 15:42:56	0.00	(\$0.56)
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/27/2021 15:42:39	07/27/2021 15:48:39	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/27/2021 15:42:39	07/27/2021 15:42:56	0.00	\$0.56
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	07/27/2021 15:39:04	07/27/2021 15:42:26	0.06	\$6.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/27/2021 15:10:36	07/27/2021 15:38:45	0.47	\$55.36

LABOR 160.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	9.74	1	\$9.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	21.74	1	\$21.74
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.84	1	\$17.84

PARTS 90.68

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 40538

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 89567. SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 41671

USING DEPT NO:	218142	OPENED DATE:	11/19/2021 09:43:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/25/2022 14:00:26	METER 1 - M:	93245	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2022 10:13:03	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.29	\$22.54	\$0.00	\$28.83
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$71.30	\$71.30
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$13.34	\$27.75	\$0.00	\$41.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.17	19.63	50.29	2,373.30	2,443.22
--------------	-------------------	------	-------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	5569647	5585		\$2,300.00
20-00	TOWING COMPLETE VEHICLE	11076249	2102139		\$71.30
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2373.30

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/24/2022 10:37:14	01/24/2022 10:40:26	0.05	\$6.29
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/24/2022 10:30:18	01/24/2022 10:37:05	0.11	\$13.34
					LABOR	19.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.11	1	\$10.11
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
					PARTS	50.29

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 41671

Work Order Notes

(LISAPATE) Driver hit a deer. Car is being towed to Browns Fleet Center to repair. State Auto has been filed.

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wiper blades

20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Bambarger towed car from Almon Bldg to Browns. Pd by CC

24-71 - REPAIR BODY

(LISAPATE) UA pd \$2000.00 ded. State Auto paid remaining balance.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° JAW,CW,RC/JAW

MILEAGE-93245

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 43523

USING DEPT NO:	218142	OPENED DATE:	06/06/2022 07:36:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/09/2022 10:16:58	METER 1 - M:	93245	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2022 08:33:47	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$22.60	\$0.00	\$40.30
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.17	\$109.72	\$0.00	\$136.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.38	44.87	132.32	2.00	179.19
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/07/2022 09:14:14	06/07/2022 09:23:14	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/07/2022 09:00:10	06/07/2022 09:13:59	0.23	\$27.17
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/07/2022 09:14:14	06/07/2022 09:14:14	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/07/2022 09:14:14	06/07/2022 09:14:14	0.00	\$0.00
				LABOR		44.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	28.59	1	\$28.59
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.17	1	\$10.17
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.22	1	\$5.22
66-PM-PMA	PERFORM OIL CHANGE	DOR917016	OIL FILTER CAP	45.59	1	\$45.59
				PARTS		132.32

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 43523

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM. The oil filter housing cap fell apart during removal and had to be replaced.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 44932

USING DEPT NO:	218142	OPENED DATE:	10/10/2022 10:17:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/17/2022 11:47:35	METER 1 - M:	103841	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/17/2022 14:23:29	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.64	\$74.96	\$23.10	\$0.00	\$98.06
35-02-077	DIAGNOSE WASHER FLUID PUMP	DON	N	N	GARAGE	0.51	\$60.38	\$0.00	\$0.00	\$60.38
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.77	\$90.86	\$0.00	\$0.00	\$90.86
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.90	\$106.53	\$689.35	\$0.00	\$795.88
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	2.34	\$276.48	\$0.00	\$0.00	\$276.48
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$86.89	\$62.62	\$0.00	\$149.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	5.90	696.10	775.07	5.00	1,476.17
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:14:07	10/14/2022 09:14:07	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:30:00	10/14/2022 09:46:12	0.27	\$31.86
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:14:07	10/14/2022 09:14:07	0.00	\$0.00
35-02-077	DIAGNOSE WASHER FLUID PUMP	11310047	10/10/2022 10:58:36	10/10/2022 11:29:18	0.51	\$60.38
35-02-077	DIAGNOSE WASHER FLUID PUMP	11310047	10/10/2022 10:58:36	10/10/2022 11:29:18	(0.51)	(\$60.38)
35-02-077	DIAGNOSE WASHER FLUID PUMP	11310047	10/10/2022 10:58:36	10/10/2022 11:29:18	0.51	\$60.38
66-79-003	PERFORM SAFETY INSPECTION	11310047	10/10/2022 11:43:14	10/10/2022 11:55:22	0.20	\$23.86
66-79-003	PERFORM SAFETY INSPECTION	11310047	10/10/2022 13:08:10	10/10/2022 15:16:37	2.14	\$252.62
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/11/2022 09:37:45	10/11/2022 10:21:56	0.74	\$86.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:30:00	10/14/2022 09:46:12	(0.27)	(\$31.86)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:14:07	10/14/2022 09:14:07	0.00	\$0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 09:30:00	10/14/2022 09:46:12	0.27	\$31.86
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 10:12:12	10/14/2022 10:50:10	0.63	\$74.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 10:12:12	10/14/2022 10:50:10	(0.63)	(\$74.67)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/14/2022 10:12:12	10/14/2022 10:50:10	0.63	\$74.67
66-17-013	PERFORM ALIGNMENT	11310047	10/14/2022 12:48:58	10/14/2022 13:35:10	0.77	\$90.86
66-17-013	PERFORM ALIGNMENT	11310047	10/14/2022 12:48:58	10/14/2022 13:35:10	(0.77)	(\$90.86)
66-17-013	PERFORM ALIGNMENT	11310047	10/14/2022 12:48:58	10/14/2022 13:35:10	0.77	\$90.86
03-51-038	REPLACE NEW WIPER BLADES	11310047	10/14/2022 13:41:46	10/14/2022 14:19:53	0.64	\$74.96
					LABOR	696.10

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.38	1	\$10.38
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	20.43	1	\$20.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	4	\$23.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	2	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	1	\$0.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	4	\$662.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	(4)	(\$23.58)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	(2)	(\$0.90)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	(1)	(\$0.59)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	(1)	(\$0.63)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	(1)	(\$0.89)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	(4)	(\$662.76)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	4	\$23.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	2	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	1	\$0.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	165.69	4	\$662.76
					PARTS	775.07

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 44932

Work Order Notes

(LISAPATE) PM-Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) Wipers were replaced.

35-02-077 - DIAGNOSE WASHER FLUID PUMP

(EHOWELL) The washer pump was not plugged in. Plugged in washer pump, but it still did not push fluid. The valve between the two washer nozzles was installed backwards. Removed valve and installed it in the right direction. The washer pump is now working properly. EH .5 HR

(AJONES) Visit Reason Changed On 10/31/2022 2:04 PM By AJONES

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

(AJONES) Visit Reason Changed On 10/31/2022 2:05 PM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

(AJONES) Visit Reason Changed On 10/31/2022 2:05 PM By AJONES

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Inspected vehicle. EH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-103841

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 45388

USING DEPT NO:	218142	OPENED DATE:	11/30/2022 13:38:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2022 13:42:12	METER 1 - M:	103841	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 08:56:01	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.30	\$35.40	\$5.46	\$0.00	\$40.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.30	35.40	5.46	5.00	45.86
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	11237753	11/30/2022 13:39:29	11/30/2022 13:57:29	0.30	\$35.40
					LABOR	35.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.73	2	\$5.46
					PARTS	5.46

Work Order Charge Detail

UNIT NO:	242139	2017 TOYOTA CAMRY	WORK ORDER NO:	45388
----------	--------	-------------------	----------------	-------

Work Order Notes

(LISAPATE) Batteries dead in all key fobs

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(LISAPATE) LP installed new batteries in 2 key fobs

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 45911

USING DEPT NO:	218142	OPENED DATE:	01/25/2023 14:53:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2023 15:25:40	METER 1 - M:	109756	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2023 08:28:44	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.62	\$23.20	\$0.00	\$27.82
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.99	\$67.10	\$0.00	\$113.09
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.80	\$13.17	\$0.00	\$18.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.48	56.41	103.47	5.00	164.88
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/26/2023 08:36:35	01/26/2023 08:38:56	0.04	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/26/2023 08:12:56	01/26/2023 08:36:19	0.39	\$45.99
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	01/26/2023 08:09:39	01/26/2023 08:12:36	0.05	\$5.80
				LABOR		56.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM STYLE 18"	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
				PARTS		103.47

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 45911

Work Order Notes

(EHANNAH) pm-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 109756 Completed PM topside, Gregg was bottomside. AMG/GC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 47178

USING DEPT NO:	218142	OPENED DATE:	05/25/2023 13:22:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/30/2023 10:07:06	METER 1 - M:	114487	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 11:32:53	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.00	\$23.96	\$0.00	\$29.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.71	\$48.43	\$0.00	\$79.14
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.03	\$3.64	\$20.27	\$0.00	\$23.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.02	\$2.92	\$0.00	\$0.00	\$2.92

JOB COUNT: 5	WORK ORDER TOTAL:	0.37	43.27	92.66	5.00	140.93
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	05/26/2023 13:00:00	05/26/2023 13:01:29	0.02	\$2.92
WA-00	WASH COMPLETE VEHICLE	12201267	05/26/2023 12:47:46	05/26/2023 12:47:46	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/26/2023 12:25:06	05/26/2023 12:25:06	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/26/2023 11:36:41	05/26/2023 11:52:18	0.26	\$30.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/26/2023 11:34:38	05/26/2023 11:36:29	0.03	\$3.64
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/26/2023 11:31:23	05/26/2023 11:34:26	0.05	\$6.00
				LABOR		43.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM STYLE 18"	10.73	1	\$10.73
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	20.27	1	\$20.27

Work Order Charge Detail

PARTS	92.66
-------	-------

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 47178

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-SH,GC, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure.
Miles, 114,487

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 47823

USING DEPT NO:	218142	OPENED DATE:	08/03/2023 10:16:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/08/2023 13:51:46	METER 1 - M:	114487	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2023 07:46:03	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$350.75	\$350.75
16-02	TRANSPORT CAB & SHEET METAL	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	355.75	414.75
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2111159		\$350.75
03-02-061	REPLACE NEW WINDSHIELD	11078716	2111159		(\$350.75)
03-02-061	REPLACE NEW WINDSHIELD	11078716	2111159		\$350.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML
					355.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11399745	08/08/2023 07:00:00	08/08/2023 07:30:00	0.50	\$59.00
16-02	TRANSPORT CAB & SHEET METAL	11399745	08/08/2023 07:00:00	08/08/2023 07:30:00	(0.50)	(\$59.00)
16-02	TRANSPORT CAB & SHEET METAL	11399745	08/08/2023 07:00:00	08/08/2023 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 47823

Work Order Notes

(LISAPATE) Take to Glass Dr to have windshield replaced it is cracked and running

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed new windshield. Pd by CC

(LRUSHING) Visit Reason Changed On 8/25/2023 1:12 PM By LRUSHING

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by Cw

(LRUSHING) Visit Reason Changed On 8/25/2023 1:13 PM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/25/2023 1:13 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 48434

USING DEPT NO:	218142	OPENED DATE:	10/09/2023 07:05:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/11/2023 08:01:43	METER 1 - M:	119144	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/11/2023 11:57:38	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.24	\$24.08	\$0.00	\$29.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.07	\$48.06	\$0.00	\$109.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.24	\$28.81	\$0.00	\$0.00	\$28.81

JOB COUNT: 4	WORK ORDER TOTAL:	0.81	95.12	72.14	5.00	172.26
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	10/10/2023 11:39:38	10/10/2023 11:54:17	0.24	\$28.81
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/10/2023 11:06:19	10/10/2023 11:37:22	0.52	\$61.07
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/10/2023 11:18:51	10/10/2023 11:21:31	0.04	\$5.24
				LABOR		95.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	16.56	1	\$16.56
					PARTS	72.14

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 48434

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed fluid check fc-sh

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 49878

USING DEPT NO:	218142	OPENED DATE:	02/21/2024 07:06:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2024 14:08:37	METER 1 - M:	119144	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2024 14:08:41	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-18-006	REPLACE NEW HUB CAPS	DON	N	N	GARAGE	0.03	\$3.90	\$150.32	\$0.00	\$154.22
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.11	\$24.08	\$0.00	\$25.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.33	\$53.80	\$0.00	\$103.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$45.82	\$0.00	\$0.00	\$45.82

JOB COUNT: 5	WORK ORDER TOTAL:	0.85	100.16	228.20	5.00	333.36
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/21/2024 10:56:28	02/21/2024 11:21:33	0.42	\$49.33
03-51-038	REPLACE NEW WIPER BLADES	12395904	02/21/2024 11:21:57	02/21/2024 11:22:31	0.01	\$1.11
WA-00	WASH COMPLETE VEHICLE	12395904	02/21/2024 11:22:55	02/21/2024 11:46:13	0.39	\$45.82
03-18-006	REPLACE NEW HUB CAPS	12395904	02/21/2024 15:31:23	02/21/2024 15:33:22	0.03	\$3.90
				LABOR		100.16

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.67	1	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
03-18-006	REPLACE NEW HUB CAPS	4260206070	HUB CAP	150.32	1	\$150.32
				PARTS		228.20

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 49878

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-18-006 - REPLACE NEW HUB CAPS

(FCONTRER) Replaced new hub caps f- r fc

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 49902

USING DEPT NO:	218142	OPENED DATE:	02/22/2024 14:09:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2024 08:30:16	METER 1 - M:	122613	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2024 13:51:50	IN-SERVICE DATE:	11/15/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU280510	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.80	\$1.80
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$1.80	\$0.00	\$0.00	\$1.80

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	1.80	0.00	1.80	3.60
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$1.80
				COMML	1.80

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	02/23/2024 13:18:04	02/23/2024 13:18:59	0.02	\$1.80
					LABOR	1.80

Work Order Charge Detail

The University of Alabama

Report Printed: 03/01/2024 14:54:49 By User: GLOBETTI

UNIT NO: 242139 2017 TOYOTA CAMRY

WORK ORDER NO: 49902

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Remove wordmarks and tag. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Mar 01 2024 14:54:49 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242139') //Q=