

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 26610

USING DEPT NO:	507201	OPENED DATE:	06/14/2017 15:21:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/19/2017 06:52:15	METER 1 - M:	225	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/19/2017 06:52:18	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$449.99	\$0.00	\$478.74
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	57.50	449.99	0.00	507.49
--------------	-------------------	--	--	--	--	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	06/14/2017 15:22:30	06/14/2017 15:52:30	0.50	\$28.75
14-78-044	INSTALL TOOLBOX ASSY	11758845	06/14/2017 15:22:39	06/14/2017 15:52:39	0.50	\$28.75
					LABOR	57.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-78-044	INSTALL TOOLBOX ASSY	TBS63ALP	TOOLBOX	449.99	1	\$449.99
					PARTS	449.99

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 26610

Work Order Notes

(LISAPATE) DO PSI-INSTALL TOOLBOX

Job Notes

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) INSTALLED TOOLBOX

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 27045

USING DEPT NO:	507201	OPENED DATE:	08/09/2017 14:44:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2017 08:25:29	METER 1 - M:	661	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/15/2017 08:25:30	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	12.57	\$722.66	\$1,290.62	\$0.00	\$2,013.28

JOB COUNT: 1	WORK ORDER TOTAL:	12.57	722.66	1,290.62	0.00	2,013.28
--------------	-------------------	-------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	08/11/2017 07:10:51	08/11/2017 11:44:24	4.56	\$262.15
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	08/10/2017 08:36:14	08/10/2017 16:36:46	8.01	\$460.51
					LABOR	722.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	DORBOLT	BOLT	1.49	10	\$14.85
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	MMM06133	ELECTRICAL TAPE	6.57	1	\$6.57
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.59	1	\$0.59
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609C	WHITE STROBE LIGHT KIT	121.50	2	\$243.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONC	ION WIDE ANGLE STROBE CLEAR	162.00	2	\$324.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	03MFP3011	HEAT SHRINK	7.49	2	\$14.97
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0950PT	FUSE HOLDER	3.24	1	\$3.24
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	7.50	1	\$7.50
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	6.00	1	\$6.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SWITCH	ACCELERATOR SWITCH	7.50	1	\$7.50
					PARTS	1290.62

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 27045

Work Order Notes

(LISAPATE) INSTALL STROBES

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) INSTALLED AMBER STROBES INSIDE OF TRUCK AND WHITE STROBES ON THE OUTSIDE.

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 28203

USING DEPT NO:	507201	OPENED DATE:	11/20/2017 08:31:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/22/2017 13:07:06	METER 1 - M:	2301	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/22/2017 13:07:07	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.22	\$0.00	\$59.05

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	41.22	0.00	59.05
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/20/2017 13:55:07	11/20/2017 13:55:15	0.00	(\$0.13)
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/20/2017 13:55:07	11/20/2017 13:55:15	0.00	\$0.13
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/20/2017 13:55:07	11/20/2017 14:13:43	0.31	\$17.83
					LABOR	17.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SYN0W20	NAPA 0W20	5.75	6	\$34.47
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.75	1	\$6.75
					PARTS	41.22

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 28203

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG PERFORMED PM AND USED OIL PURCHASED FROM NAPA

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 29759

USING DEPT NO:	507201	OPENED DATE:	05/10/2018 11:38:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2018 07:53:33	METER 1 - M:	4135	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2018 07:53:34	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$34.12	\$0.00	\$51.95

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	34.12	0.00	51.95
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/14/2018 07:00:00	05/14/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.58	1	\$6.58
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	6	\$27.54
					PARTS	34.12

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 29759

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/AG
COOLANT -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 31056

USING DEPT NO:	507201	OPENED DATE:	10/04/2018 09:15:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2018 06:42:03	METER 1 - M:	6477	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2018 06:42:05	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11310047	10/05/2018 07:14:32	10/05/2018 07:24:03	0.16	\$11.50
03-32-002	REPLACE NEW BATTERY	11310047	10/05/2018 13:26:44	10/05/2018 14:10:42	0.73	\$53.13
03-32-002	REPLACE NEW BATTERY	11310047	10/05/2018 13:26:44	10/05/2018 14:10:42	(0.73)	(\$53.13)
03-32-002	REPLACE NEW BATTERY	11310047	10/08/2018 07:02:59	10/08/2018 07:05:33	0.04	\$3.10
03-32-002	REPLACE NEW BATTERY	11310047	10/08/2018 07:02:59	10/08/2018 07:05:33	(0.04)	(\$3.10)
03-32-002	REPLACE NEW BATTERY	11310047	10/05/2018 07:14:32	10/05/2018 07:24:03	(0.16)	(\$11.50)
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	112.17	1	\$112.17
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	1	\$0.35
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	(1)	(\$0.35)
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.35	(1)	(\$0.35)
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	112.17	(1)	(\$112.17)
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 31056

Work Order Notes

(LISAPATE) Check battery-jumped off twice

Job Notes

03-32-002 - REPLACE NEW BATTERY

15-32-002 - WARRANTY BATTERY

(LISAPATE) Visit Reason Changed On 10/23/2018 9:05 AM By LISAPATE

(LISAPATE) Took battery to Toyota Paul Hardin the Service Manager verified the battery was bad. Swapped battery out with us at no charge. Warranty. There is no invoice. reinstalled in vehicle checked ok

(IFALLS) EH INSTALLED WARRANTIED BATTERY

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 31275

USING DEPT NO:	507201	OPENED DATE:	10/25/2018 07:12:16	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2018 14:46:04	METER 1 - M:	6805	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2018 14:46:06	IN-SERVICE DATE:	06/13/2017				
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
17-01-004	RECALL BLOWER MOTOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.14	\$82.31	\$396.90	\$0.00	\$479.21
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$41.59	\$0.00	\$64.07

JOB COUNT: 6	WORK ORDER TOTAL:	3.95	286.04	438.49	0.00	724.53
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-01-004	RECALL BLOWER MOTOR	11076422	6013423	0045693	\$0.00
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11213180	11/20/2018 07:00:00	11/20/2018 07:30:00	0.50	\$36.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	11/19/2018 14:34:08	11/19/2018 15:42:15	1.14	\$82.31
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	11/01/2018 07:00:00	11/01/2018 08:00:00	1.00	\$72.50
09-15	ALIGN STEERING	11213180	11/20/2018 07:00:00	11/20/2018 08:00:00	1.00	\$72.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/20/2018 06:00:00	11/20/2018 06:18:36	0.31	\$22.48
LABOR						286.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.58	1	\$6.58
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	194.16	4	\$776.64
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	194.16	(4)	(\$776.64)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	194.16	2	\$388.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	2	\$6.63

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	5	\$1.95
PARTS						438.49

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 31275

Work Order Notes

(EKIMBREL) PM
(LISAPATE) Recall from Toyota possible defect blower motor hub
(LISAPATE) Truck needs 2 tires

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) MS checked the front end

09-15 - ALIGN STEERING

(LISAPATE) MS performed alignment

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Toyota by RC

17-01-004 - RECALL BLOWER MOTOR

(LISAPATE) Tuscaloosa Toyota completed Recall installed new blower motor assy

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 2 new tires adjusted all tires pressures. Light went off

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH
Coolant -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 33917

USING DEPT NO:	507201	OPENED DATE:	08/29/2019 14:33:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/06/2019 11:19:42	METER 1 - M:	10516	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2019 11:19:44	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.17	\$12.16	\$0.00	\$0.00	\$12.16
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.60	\$43.42	\$0.00	\$0.00	\$43.42
15-13-001	WARRANTY FRONT BRAKES & ROTOR:	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-13	TRANSPORT BRAKES	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.61	\$116.85	\$413.25	\$0.00	\$530.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.67	\$48.33	\$41.51	\$0.00	\$89.84
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.75	\$13.59	\$0.00	\$35.34

JOB COUNT: 7	WORK ORDER TOTAL:	4.35	315.01	468.35	0.00	783.36
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-13-001	WARRANTY FRONT BRAKES & ROTORS	11076422	6050314		\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	12052187	08/30/2019 07:09:59	08/30/2019 07:20:03	0.17	\$12.16
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/30/2019 06:40:04	08/30/2019 07:20:04	0.67	\$48.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	08/30/2019 07:20:04	08/30/2019 07:46:30	0.44	\$31.94
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/30/2019 07:20:03	08/30/2019 07:50:22	0.51	\$36.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/30/2019 08:01:46	08/30/2019 08:22:25	0.34	\$24.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	08/30/2019 08:03:28	08/30/2019 08:22:46	0.32	\$23.32
09-15	ALIGN STEERING	11310047	08/30/2019 10:03:48	08/30/2019 10:39:44	0.60	\$43.42
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	09/04/2019 07:00:00	09/04/2019 07:18:00	0.30	\$21.75
16-13	TRANSPORT BRAKES	10208562	09/04/2019 07:00:00	09/04/2019 08:00:00	1.00	\$72.50
				LABOR		315.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	202.50	2	\$405.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	2	\$6.63
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEHT976H	FRONT BRAKE PADS	69.05	1	\$69.05
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEHT976H	FRONT BRAKE PADS	69.05	(1)	(\$69.05)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	4	\$1.62
					PARTS	468.35

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 33917

Work Order Notes

(LISAPATE) PM

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

06-15 - INSPECT STEERING

(LISAPATE) Checked front end no issues found AG/JW

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment only adjusted toe

15-13-001 - WARRANTY FRONT BRAKES & ROTORS

(RWINTERS) Tuscaloosa Toyota found front rotors uneven thickness. Turned front rotors under warranty

16-13 - TRANSPORT BRAKES

(LISAPATE) Taken to Toyota by EK

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 2 new tires installed on the rear

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG

Coolant -34'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 36366

USING DEPT NO:	507201	OPENED DATE:	05/11/2020 07:06:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2020 10:55:32	METER 1 - M:	13331	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/13/2020 08:10:37	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.57	\$41.24	\$0.00	\$0.00	\$41.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$44.39	\$55.68	\$0.00	\$100.07
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.10	\$7.17	\$13.59	\$0.00	\$20.76

JOB COUNT: 3	WORK ORDER TOTAL:	1.28	92.80	69.27	0.00	162.07
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/11/2020 07:39:10	05/11/2020 07:52:57	0.23	\$16.65
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/11/2020 07:52:57	05/11/2020 07:58:53	0.10	\$7.17
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/11/2020 07:39:27	05/11/2020 08:02:24	0.38	\$27.73
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/11/2020 07:58:53	05/11/2020 08:33:01	0.57	\$41.24
					LABOR	92.79

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	14.19	1	\$14.19
					PARTS	69.27

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 36366

Work Order Notes

(EKIMBREL) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(EKIMBREL) SH rotated tires.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW,SH/AG performed pm. Coolant -34

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) SH laced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 37946

USING DEPT NO:	507201	OPENED DATE:	10/09/2020 10:55:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/09/2020 15:19:27	METER 1 - M:	15765	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/12/2020 12:22:53	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$41.49	\$0.00	\$80.43

JOB COUNT: 1	WORK ORDER TOTAL:	0.33	38.94	41.49	0.00	80.43
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/09/2020 12:12:14	10/09/2020 12:12:14	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/09/2020 12:12:14	10/09/2020 12:12:14	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/09/2020 12:12:14	10/09/2020 12:32:02	0.33	\$38.94
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
					PARTS	41.49

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 37946

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34° AMG,JAW/JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 38106

USING DEPT NO:	507201	OPENED DATE:	10/21/2020 13:47:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/22/2020 08:08:21	METER 1 - M:	16070	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/22/2020 10:33:47	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	A	N	GARAGE	0.03	\$3.47	\$0.00	\$0.00	\$3.47
66-17-017	PERFORM BALANCE TIRES	DON	O	N	GARAGE	0.10	\$11.80	\$0.84	\$0.00	\$12.64

JOB COUNT: 2	WORK ORDER TOTAL:					0.13	15.27	0.84	0.00	16.11
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-017	PERFORM BALANCE TIRES	12052187	10/22/2020 07:00:00	10/22/2020 07:06:00	0.10	\$11.80
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	10/21/2020 14:02:54	10/21/2020 14:04:40	0.03	\$3.47
					LABOR	15.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	2	\$0.84
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	(2)	(\$0.84)
66-17-017	PERFORM BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	2	\$0.84
					PARTS	0.84

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 38106

Work Order Notes

(LISAPATE) Inspect RR wheel area form damage unit was backed into

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Inspected tire. Found no damage to wheel or tire. JAW

66-17-017 - PERFORM BALANCE TIRES

(LISAPATE) Balanced RR tire

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 38659

USING DEPT NO:	507201	OPENED DATE:	12/15/2020 07:37:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2020 11:35:31	METER 1 - M:	16824	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2021 10:02:13	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-31	INSPECT CHARGING SYSTEM	DON	O	N	GARAGE	0.04	\$4.59	\$0.00	\$0.00	\$4.59

JOB COUNT: 1	WORK ORDER TOTAL:	0.04	4.59	0.00	0.00	4.59
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-31	INSPECT CHARGING SYSTEM	11170580	12/18/2020 10:46:55	12/18/2020 10:49:15	0.04	\$4.59
					LABOR	4.59

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 38659

Work Order Notes

(LISAPATE) Per Dale Cole truck has been jumped off numerous times will not stay charged. Requested check for a draw from LVA camera system.

Job Notes

06-31 - INSPECT CHARGING SYSTEM

(ABLACK) AB found fuse that powers the cameras was tapped into the fuel injector fuse. Removed fuse for the cameras and dept. is planning on us installing a toggle switch to cut the camera system on and off after the first of the year

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 38762

USING DEPT NO:	507201	OPENED DATE:	01/12/2021 13:34:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/13/2021 14:20:06	METER 1 - M:	16824	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2021 11:07:51	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
19-52-007	WIRE/REWIRE CAMERA	DON	O	N	GARAGE	1.90	\$224.76	\$29.34	\$0.00	\$254.10

JOB COUNT: 1	WORK ORDER TOTAL:	1.90	224.76	29.34	0.00	254.10
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
19-52-007	WIRE/REWIRE CAMERA	11170580	01/13/2021 09:37:58	01/13/2021 11:32:15	1.90	\$224.76
					LABOR	224.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
19-52-007	WIRE/REWIRE CAMERA	WPS67702	HD SOLENOID CONTINUOUS DUTY	29.34	1	\$29.34
					PARTS	29.34

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: **242326** **2017 TOYOTA TACOMA**

WORK ORDER NO: **38762**

Work Order Notes

(LISAPATE) Rewire cameras so it will quit pulling down the battery

Job Notes

19-52-007 - WIRE/REWIRE CAMERA

(ABlack) AB installed a continuous duty solenoid for the camera system in order to stop the battery drain.

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 39455

USING DEPT NO:	507201	OPENED DATE:	03/22/2021 10:13:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2021 15:14:52	METER 1 - M:	18184	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/23/2021 19:41:01	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.43	\$50.74	\$0.00	\$0.00	\$50.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.84	\$33.41	\$0.00	\$82.25

JOB COUNT: 2	WORK ORDER TOTAL:	0.84	99.58	33.41	0.00	132.99
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/22/2021 13:24:35	03/22/2021 13:38:24	0.23	\$27.17
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	03/22/2021 14:02:23	03/22/2021 14:14:22	0.20	\$23.57
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/22/2021 14:14:35	03/22/2021 14:14:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/22/2021 14:30:00	03/22/2021 14:42:39	0.21	\$24.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/22/2021 13:12:11	03/22/2021 13:24:22	0.20	\$23.96
					LABOR	99.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	33.41

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 39455

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 18184. SH/JW performed PM. SH Washed vacuumed and filled with gas.

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 40929

USING DEPT NO:	507201	OPENED DATE:	09/03/2021 09:28:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2021 10:43:25	METER 1 - M:	20661	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2021 13:37:30	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	0.24	\$27.93	\$69.05	\$0.00	\$96.98
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.34	\$39.73	\$15.18	\$0.00	\$54.91
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.39	\$45.59	\$0.00	\$0.00	\$45.59
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.21	\$143.04	\$820.67	\$0.00	\$963.71
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.48	\$56.31	\$0.00	\$0.00	\$56.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.84	\$39.83	\$0.00	\$102.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
CU-13-001	CUT FRONT BRAKES & ROTORS	DON	O	N	GARAGE	0.80	\$93.88	\$0.00	\$0.00	\$93.88

JOB COUNT: 9	WORK ORDER TOTAL:	4.48	528.32	944.73	2.00	1,475.05
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-13-130	PERFORM Burnish Brakes	11170580	09/14/2021 07:00:00	09/14/2021 07:30:00	0.50	\$59.00
CU-13-001	CUT FRONT BRAKES & ROTORS	11170580	09/08/2021 14:30:00	09/08/2021 15:09:50	0.66	\$78.34
CU-13-001	CUT FRONT BRAKES & ROTORS	11170580	09/08/2021 14:07:06	09/08/2021 14:15:00	0.13	\$15.54
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	09/08/2021 08:02:16	09/08/2021 09:15:00	1.21	\$143.04
66-79-003	PERFORM SAFETY INSPECTION	12052187	09/03/2021 15:23:59	09/03/2021 15:48:33	0.41	\$48.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/07/2021 07:20:29	09/07/2021 07:52:26	0.53	\$62.84
66-79-003	PERFORM SAFETY INSPECTION	12052187	09/07/2021 07:52:37	09/07/2021 07:56:41	0.07	\$8.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/07/2021 07:56:49	09/07/2021 08:17:01	0.34	\$39.73
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11170580	09/08/2021 15:10:00	09/08/2021 15:24:12	0.24	\$27.93

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	09/09/2021 13:50:33	09/09/2021 14:13:44	0.39	\$45.59
					LABOR	528.32

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	6	\$27.00
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	6.38	1	\$6.38
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.15	1	\$5.15
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	11	\$5.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	4	\$17.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	199.50	4	\$798.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWRZ36-976	BRAKE PADS	63.90	1	\$63.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	199.50	(4)	(\$798.00)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	199.50	4	\$798.00
					PARTS	944.73

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 40929

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(ABBLACK) AB installed new front brake pads. Test drove bedded in brakes. Rechecked ok.

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades.

66-13-130 - PERFORM Burnish Brakes

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all 4 tires and balanced. Aired to spec. Unit is waiting on brake job now. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI and found all 4 tires need replaced and the front brakes need replaced also cut rotors. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-20661

CH-SP - CHARGE Shop Supplies

CU-13-001 - CUT FRONT BRAKES & ROTORS

(ABBLACK) AB cut both front rotors

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 41036

USING DEPT NO:	507201	OPENED DATE:	09/15/2021 14:49:47	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2021 15:15:26	METER 1 - M:	20754	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2021 10:58:59	IN-SERVICE DATE:	06/13/2017				
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma			UNIT SERIAL NO:	5TFRX5GN0HX091632			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.52	\$61.33	\$0.00	\$0.00	\$61.33
06-40	INSPECT ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.41	\$48.05	\$0.00	\$0.00	\$48.05
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.54	\$63.92	\$202.71	\$0.00	\$266.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.47	291.30	202.71	2.00	496.01
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-40	INSPECT ENGINE / MOTOR SYSTEMS	11310047	09/28/2021 07:00:00	09/28/2021 08:00:00	1.00	\$118.00
09-15	ALIGN STEERING	11310047	09/17/2021 15:30:33	09/17/2021 15:54:59	0.41	\$48.05
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	09/16/2021 07:13:40	09/16/2021 09:08:11	(1.91)	(\$225.22)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	09/16/2021 07:13:40	09/16/2021 09:08:11	1.91	\$225.22
06-15	INSPECT STEERING	11310047	09/16/2021 09:08:11	09/16/2021 09:39:22	0.52	\$61.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	09/17/2021 07:37:08	09/17/2021 08:09:38	0.54	\$63.92
LABOR						291.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	2	\$0.96
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	201.75	1	\$201.75
PARTS						202.71

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 41036

Work Order Notes

(LISAPATE) Driver hit a curb and took a chunk out of RF tire-also Dale Cole can hear a roaring noise when accelerating on quick acceleration.

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

06-40 - INSPECT ENGINE / MOTOR SYSTEMS

(LISAPATE) Performed a road test. Did not find any obvious problems relating to noise concern. Verified bolts were tight at exhaust manifold flange. Examined engine mounts for damage. EH

09-15 - ALIGN STEERING

(EHOWELL) Checked Alignment. No adjustments needed. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) miles: 20754 Replaced and balanced R/F tire. Did re-use valve stem kit tires were recently replaced. AMG

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE)

(LISAPATE) cancelled job did not scan out

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 41957

USING DEPT NO:	507201	OPENED DATE:	01/04/2022 13:29:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2022 07:53:02	METER 1 - M:	21545	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2022 11:08:19	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.02	\$2.56	\$113.55	\$0.00	\$116.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.56	113.55	2.00	118.11
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11213180	01/04/2022 13:53:51	01/04/2022 13:55:09	0.02	\$2.56
					LABOR	2.56

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	113.55

Work Order Charge Detail

UNIT NO:2423262017 TOYOTA TACOMA

WORK ORDER NO:41957

Work Order Notes

(LISAPATE) Per driver check battery had to jump off

Job Notes

03-32-002 - REPLACE NEW BATTERY

(MSIDES) Found battery to test bad. Replaced battery. MS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 42374

USING DEPT NO:	507201	OPENED DATE:	02/15/2022 14:07:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2022 15:13:41	METER 1 - M:	21922	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 08:21:08	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$2.98	\$15.18	\$0.00	\$18.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$21.96	\$0.00	\$0.00	\$21.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.21	24.94	15.18	2.00	42.12
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/15/2022 15:29:43	02/15/2022 15:31:14	0.03	\$2.98
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/15/2022 15:12:43	02/15/2022 15:23:53	0.19	\$21.96
LABOR						24.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
PARTS						15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 42374

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1261 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 43883

USING DEPT NO:	507201	OPENED DATE:	07/08/2022 08:17:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2022 14:10:58	METER 1 - M:	23899	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/12/2022 07:34:13	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.39	\$46.32	\$0.00	\$0.00	\$46.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$37.99	\$42.29	\$0.00	\$80.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.71	84.31	42.29	2.00	128.60
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/08/2022 10:51:47	07/08/2022 10:54:08	0.04	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/08/2022 10:17:16	07/08/2022 10:34:14	0.28	\$33.37
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/08/2022 10:54:20	07/08/2022 11:17:53	0.39	\$46.32
LABOR						84.31

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.48	1	\$8.48
PARTS						42.29

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 43883

Work Order Notes

(IFALLS) pm

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(HHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 45538

USING DEPT NO:	507201	OPENED DATE:	12/12/2022 13:23:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2022 09:05:13	METER 1 - M:	26165	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2022 12:39:03	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.46	\$15.64	\$0.00	\$18.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$37.14	\$42.27	\$0.00	\$79.41
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	39.60	57.91	5.00	102.51
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/12/2022 15:18:23	12/12/2022 15:37:16	0.31	\$37.14
03-51-038	REPLACE NEW WIPER BLADES	12201267	12/12/2022 15:37:16	12/12/2022 15:38:31	0.02	\$2.46
				LABOR		39.60

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.73	1	\$5.73
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
					PARTS	57.91

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 45538

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM changed oil and oil filter-GC checked fluids and tires and tire pressure, battery good,
Miles- 26,165

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 46902

USING DEPT NO:	507201	OPENED DATE:	04/28/2023 10:27:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2023 14:40:20	METER 1 - M:	26998	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/04/2023 11:54:18	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.80	\$16.61	\$0.00	\$28.41
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.89	\$0.00	\$0.00	\$35.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.10	\$11.80	\$0.00	\$0.00	\$11.80

JOB COUNT: 5	WORK ORDER TOTAL:	0.60	71.29	16.61	5.00	92.90
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	05/01/2023 11:06:07	05/01/2023 11:08:55	0.05	\$5.51
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/01/2023 10:47:38	05/01/2023 11:05:53	0.30	\$35.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	05/01/2023 11:06:07	05/01/2023 11:08:55	(0.05)	(\$5.51)
66-79-003	PERFORM SAFETY INSPECTION	12052187	05/02/2023 12:09:34	05/02/2023 12:15:34	0.10	\$11.80
66-79-003	PERFORM SAFETY INSPECTION	12052187	05/02/2023 12:09:34	05/02/2023 12:09:34	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	05/02/2023 12:09:34	05/02/2023 12:09:34	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/02/2023 12:18:31	05/02/2023 12:24:31	0.10	\$11.80
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/02/2023 12:18:31	05/02/2023 12:18:31	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/02/2023 12:18:31	05/02/2023 12:18:31	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	12052187	05/02/2023 12:23:05	05/02/2023 12:29:05	0.10	\$11.80
WA-00	WASH COMPLETE VEHICLE	12052187	05/02/2023 12:23:05	05/02/2023 12:23:05	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	12052187	05/02/2023 12:23:05	05/02/2023 12:23:05	0.00	\$0.00
					LABOR	71.29

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.28	1	\$8.28
					PARTS	16.61

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 46902

Work Order Notes

(EHANNAH) pm- replace wipers - Do SI - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI. Found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Performed PM-GC, Fluid check only, vehicle drive 833 miles, air filter good, checked tires and tire pressure. Miles, 26,998

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced cabin filter- 5-1-23- GC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Hand washed unit. JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 47959

USING DEPT NO:	507201	OPENED DATE:	08/23/2023 09:06:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2023 09:33:20	METER 1 - M:	28050	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2023 12:39:32	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-52-007	INSPECT CAMERA	DON	O	N	GARAGE	1.01	\$119.31	\$0.00	\$0.00	\$119.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.01	119.31	0.00	5.00	124.31
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-52-007	INSPECT CAMERA	11310047	08/23/2023 09:49:01	08/23/2023 10:13:51	0.41	\$48.84
06-52-007	INSPECT CAMERA	11310047	08/23/2023 11:22:22	08/23/2023 11:52:56	0.51	\$60.11
06-52-007	INSPECT CAMERA	11310047	08/23/2023 09:30:00	08/23/2023 09:33:32	0.06	\$6.95
06-52-007	INSPECT CAMERA	11310047	08/23/2023 09:13:16	08/23/2023 09:15:00	0.03	\$3.41
LABOR						119.31

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 47959

Work Order Notes

(EHANNAH) inspect laptop for not getting power to it

Job Notes

06-52-007 - INSPECT CAMERA

(IFALLS) Examined fuses at under hood fuse block, but did not find any blown. The LPR processing unit is receiving power and ground from the vehicle battery, but the lights on the unit are not illuminating.

Did not find power on the fuse at the module near the center console.

Also, checked the two chords for power and ground at the module near the center console/laptop, but no power and ground were found on the chords. (Checked AC and DC voltage.) EH .5

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 48161

USING DEPT NO:	507201	OPENED DATE:	09/11/2023 11:35:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2023 11:02:45	METER 1 - M:	28255	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2023 13:28:01	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$71.01	\$0.00	\$109.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.33	38.94	71.01	5.00	114.95
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/14/2023 07:00:00	09/14/2023 07:19:48	0.33	\$38.94
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	27.18	1	\$27.18
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
					PARTS	71.01

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 48161

Work Order Notes

(LRUSHING) pm-wash vehicle

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Wash bay is down FC

Work Order Charge Detail

The University of Alabama

Report Printed: 03/11/2024 13:34:39 By User: GLOBETTI

UNIT NO: 242326 2017 TOYOTA TACOMA

WORK ORDER NO: 49934

USING DEPT NO:	507201	OPENED DATE:	02/23/2024 14:46:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2024 11:38:13	METER 1 - M:	28793	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 09:35:46	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN0HX091632	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$118.00	\$42.27	\$0.00	\$160.27

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	42.27	5.00	165.27
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/04/2024 09:19:05	03/04/2024 09:19:05	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/04/2024 09:19:05	03/04/2024 09:19:05	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	03/04/2024 09:19:05	03/04/2024 10:19:05	1.00	\$118.00
				LABOR		118.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	42.00	1	\$42.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.14	2	\$0.27
					PARTS	42.27

Work Order Charge Detail

UNIT NO:	242326	2017 TOYOTA TACOMA	WORK ORDER NO:	49934
----------	--------	--------------------	----------------	-------

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks and tag. No GPS. Miles 28,864 CW/RC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Mar 11 2024 13:34:39 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242326') //Q=