The University of Alabama

UNIT NO:		242524	2018 TOY	OTA C	AMRY	,			WORK OF	RDER NO):	28169		
USING DEP	PT NO:	750201		OPENE	D DAT	E:	11/15/201	17 15:50:42	LOCATION:	GARAGE	- Unive	rsity Automotive	Services	
WO STATUS	S:	CLOSED		COMPL	ETED	DATE:	11/17/201	7 11:27:13	METER 1 - N	I: 57		METER 2 - N:	0	
WO VISIT R	REASON:	SCHEDULED		CLOSE	D DAT	E:	11/17/201	17 11:27:15	IN-SERVICE	DATE:	11/11/	2017		
TECH SPEC	C NO:	18TOYOTACAMR	2018	Toyota C	amry				UNIT SERIA	L NO:	4T1B ²	11HK1JU533286		
JOB CODE	<u> </u>	JOB DESCRIPTIC	N	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL	COST
66-00-001	PERFOR	RM NEW UNIT IN-SE	RVICE INSF	DON	С	Ν	GARAGE	0.50	\$28.75	\$0.00		\$0.00	\$28.75	
JOB COUN	IT: 1				WO	RK OR	DER TOTAL:	0.50) 28.	75	0.00	0.00)	28.75
Job Code		Job Descripti	<u>on</u>		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		<u>Quantity</u>	<u>Total</u>	<u>Cost</u>
66-00-001	PERFORM	NEW UNIT IN-SERVIC	E INSPECTIO	N 1	1213180)	11,	/16/2017 07:00:00	11/16/201	7 07:30:00		0.50	1	\$28.75
												LABOR		28.75

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	28169
Work Order Note	<u>es</u>			
(LISAPATE) NEW UN	NIT DO PDI			
Job Notes				
66-00-001 - PERFOR	RM NEW UNIT IN-S	ERVICE INSPECTION		
(LISAPATE) PDI COI	MPLETED			

The University of Alabama

UNIT NO:		242524	2018 ТОҮОТА С	AMRY			WORK OR	DER NO:	29137	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	COMP	ED DATE: LETED DATE: ED DATE: Camry	03/27/201	18 14:08:47 18 13:28:12 18 13:28:15	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 4150 DATE : 11/ [.]	versity Automotive METER 2 - N: 11/2017 IB11HK1JU533286	0
JOB CODE	_	JOB DESCRIPTION	N STAT DON	<u>RSN</u> WRT PN	Y JOB LOC GARAGE	LABOR HRS 0.31		<u>MATERIAL</u> \$49.86	COMMERCIAL \$0.00	TOTAL COST \$67.69
JOB COUN	IT: 1			WORK OI	RDER TOTAL:	0.31	17.8	33 49.8	36 0.0	67.69
Job Code 66-PM-PMA	PERFORM	Job Descriptio DIL CHANGE		<u>Employe</u> 11074414		<u>Start</u> /20/2018 15:24:04		i nish 3 15:42:40	Quantity 0.3 ⁷ LABOR	Total Cost \$17.83 17.83
Job Code		Job Descriptio	on	Part N	<u>o.</u>	Des	scription	<u>Unit F</u>	Price Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	()W16T	OI	L 0W16 CAM2 LS	PI SN4+ QT		8.33 5	\$41.63
66-PM-PMA	PERFORM	OIL CHANGE	١	WIX51394	OI	L FILTER			8.23 PARTS	\$8.23 49.86

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	29137
Work Order Notes	<u>8</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(LISAPATE) PM BY SI COOLANT -45'	Н			

The University of Alabama

UNIT NO:		242524 2	018 TOY	OTA C	AMRY				WORK OR	DER NO	D :	29674		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	2018	OPENE COMPL CLOSE Toyota C	ETED I	DATE:	05/07/201	8 09:22:38 8 10:08:26 8 10:08:27	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 8098 DATE:	11/11/	rsity Automotive METER 2 - N: 2017 11HK1JU533286	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>1</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL	COMMERCIAL	TOTAL COS	т
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.31	\$17.83	\$55.89		\$0.00	\$73.72	
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.31	17.8	33	55.89	0.00) 73.	.72
Job Code		Job Descriptio	<u>n</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	Fi	<u>nish</u>		Quantity	Total Cost	<u>t</u>
66-PM-PMA	PERFORM	DIL CHANGE		1	1758845		05/	03/2018 13:48:05	05/03/2018	8 14:06:41		0.31	\$17	7.83
												LABOR	17	.83
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>	Des	cription		Unit Pri	ce Quantity	Total Cost	<u>t</u>
66-PM-PMA	PERFORM (DIL CHANGE		0	W16T		OII	0W16 CAM2 LSI	PI SN4+ QT		8	.29 5	\$41	1.47
66-PM-PMA	PERFORM	DIL CHANGE		V	/IX51394	1	OII	FILTER			8	.11 1	\$8	8.11
66-PM-PMA	PERFORM (DIL CHANGE		0	5089		BR	AKE CLEAN NON	N-FLAMMABLE 1	40Z	6	.31 1	\$6	6.31
												PARTS	55	5.89

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER N	IO: 29674
Work Order Notes	<u>s</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(LISAPATE) Visit Rea (LISAPATE) PM BY S COOLANT -20'	•	3/2018 9:23 AM By LISAPATE		

The University of Alabama

UNIT NO:		242524	2018 TOYO	OTA C	AMRY					WORK ORDER	R NO:	300 ⁻	10		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED PREVENTIVE M 18TOYOTACAMI	AINT	OPENE COMPL CLOSE	ETED D DATI	DATE:	06/13/202	18 07:39:50 18 11:58:51 18 11:58:55		LOCATION: GAP METER 1 - M: 1 ⁷ IN-SERVICE DATI UNIT SERIAL NO	1270 E: 11/ ²	MET I 1/2017	utomotive \$ E R 2 - N: IJU533286		
JOB CODE		JOB DESCRIPT		<u>STAT</u> DON	<u>rsn</u> P	WRTY N	JOB LOC	LABOR HI				<u>CON</u> \$0.00	IMERCIAL	TOTAL \$14.82	COST
PU-17	_	SED TIRES, TUB	-	DON	P	N	GARAGE				.32 .00	\$0.00 \$167.		\$14.82 \$167.01	
JOB COUN	IT: 2				wo	rk ori		C	.20	11.50	3.3	32	167.01		181.83
Job Code		Job Descrip	otion		V	endor N	<u>o.</u>	Invoice N	<u>lo.</u>	Purchase Ore	der No.			<u>Total</u>	Cost
PU-17	PURCHASE	D TIRES, TUBES, LI	INERS & VALVES	6 1	1122732		24	4275		0043755		_			\$167.01
													COMML		167.01
Job Code		Job Descrip	otion		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>			Quantity	Total	Cost
66-17-028	PERFORM N	MOUNT AND BALAN	ICE TIRES	1	1074414		06	/13/2018 07:4	1:58	06/13/2018 07:5	3:58		0.20		\$11.50
												_	LABOR		11.50
Job Code		Job Descrip	otion			Part No	<u>.</u>	l	Desc	cription	<u>Unit F</u>	rice	<u>Quantity</u>	<u>Total</u>	Cost
66-17-028	PERFORM N	MOUNT AND BALAN	ICE TIRES	6	3001		1/4	OZ STICK O	N TAI	PE WEIGHT		0.04	7		\$0.31
66-17-028	PERFORM N	MOUNT AND BALAN	ICE TIRES	6	-111		TF	MS SERVICE	KIT (6-111		3.01	1		\$3.01
													PARTS		3.32

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

30010

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:
Work Order Note	<u>s</u>		
(IFALLS) FLAT TIRE (RTUNAITI) Hole in s	idewall		
Job Notes			
66-17-028 - PERFOR		ALANCE TIRES	

(IFALLS) SH INSTALLED LR TIRE AND PERFORMED MOUNT AND BALANCE

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(RTUNAITI) One Bridgestone Ecopia EP422 Plus, P215/55R17 purchased from Firestone

The University of Alabama

UNIT NO:		242524	2018 TOYOTA	CAMR	(WORK OF		D :	30110		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	750201 CLOSED SCHEDULED 18TOYOTACAMR`	COM	NED DA ^T PLETED SED DAT a Camry	DATE:	06/27/20	18 10:39:51 18 09:26:44 18 09:26:46	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 11850 DATE:	11/11/	rsity Automotive S METER 2 - N: 2017 I1HK1JU533286		
JOB CODE 66-PM-PMA	-	JOB DESCRIPTIC	DN <u>STA</u> DO		<u>WRTY</u> N	JOB LOC	LABOR HRS 0.31	LABOR \$17.83	<u>MAT</u> \$49.58	ERIAL	COMMERCIAL \$0.00	TOTAL CO \$67.41	<u>DST</u>
JOB COUN	-					DER TOTAL				49.58	0.00		67.41
Job Code 66-PM-PMA	PERFORM (Job Descripti DIL CHANGE	<u>on</u>	<u>E</u> 1 1107441	nployee 4		<u>Start</u> /26/2018 13:13:45	-	inish 8 13:32:21		<u>Quantity</u> 0.31	<u>Total Co</u> s \$	<u>st</u> 17.83
											LABOR	1	17.83
Job Code		Job Descripti	on		Part No	<u>).</u>	Des	scription		Unit Pri	<u>ce</u> <u>Quantity</u>	Total Co	<u>st</u>
03-34-002	REPLACE N	EW LAMPS-REAR,TA	IL,STOP,TURN,ETC	912		BL	JLB-BRAKE-3RD			0	.37 (1)	(\$	\$0.37)
03-34-002	REPLACE N	EW LAMPS-REAR,TA	IL,STOP,TURN,ETC	912		Bl	JLB-BRAKE-3RD			0	.37 1		\$0.37
66-PM-PMA	PERFORM	DIL CHANGE		0W16T		OI	L 0W16 CAM2 LS	PI SN4+ QT		8	.29 5	\$	641.47
66-PM-PMA	PERFORM	DIL CHANGE		WIX5139	94	OI	L FILTER			8	.11 1		\$8.11
											PARTS	4	49.58

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	30110
Work Order Note	es			
(LISAPATE) PM				
Job Notes				
03-34-002 - REPLA	CE NEW LAMPS-RE	EAR,TAIL,STOP,TURN,ETC		
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) PM BY COOLANT -30'	EK,RC/SH			

The University of Alabama

UNIT NO:		242524 2	2018 ТОҮОТА С	AMRY			WORK OR	DER NO:	30516			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	COMPL	ED DATE: .ETED DATE: ED DATE: Camry	08/15/201	8 10:04:01 8 12:38:19 8 12:38:20	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 15463 DATE: 11,	iversity Auto METER /11/2017 1B11HK1JL	2 - N:	ervices 0	
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION RM OIL CHANGE	N STAT DON	<u>RSN</u> <u>WRT</u> P N	Y JOB LOC GARAGE	LABOR HRS 0.31	LABOR \$17.83	<u>MATERIAI</u> \$50.41	<u>COMM</u> \$0.00	ERCIAL	TOTAL COS \$68.24	<u>ST</u>
JOB COUN	IT: 1			WORK OF	RDER TOTAL:	0.31	17.8	33 50.	.41	0.00	68	8.24
Job Code 66-PM-PMA	PERFORM	Job Descriptio OIL CHANGE		<u>Employe</u> 1074414		<u>Start</u> /09/2018 15:02:48		i nish 3 15:21:24		uantity 0.31 ABOR		5 <u>t</u> 7.83 7.83
Job Code		Job Descriptio	on	Part N	<u>o.</u>	Des	cription	<u>Unit</u>	Price Q	uantity	Total Cos	<u>st</u>
66-PM-PMA	PERFORM	OIL CHANGE	0	W16T	OII	_0W16 CAM2 LSI	PI SN4+ QT		8.46	5	\$4	12.30
66-PM-PMA	PERFORM	OIL CHANGE	V	VIX51394	OII	_ FILTER			8.11 P	1 ARTS		\$8.11 0.41

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	30516
Work Order Note	<u>es</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) Visit Rea (LISAPATE) PM BY I COOLANT -20'	-	9/2018 10:04 AM By LISAPATE		

The University of Alabama

UNIT NO:		242524	2018 TOY	OTA C	AMRY				WORK ORD	ER NO:	31	762		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	2018	OPENE COMPL CLOSE Toyota C	ETED I	DATE:	12/18/201	8 15:57:52 8 09:12:12 8 09:12:14	LOCATION: (METER 1 - M: IN-SERVICE D UNIT SERIAL I	25167 ATE: 1 [°]	ME 1/11/201	y Automotive S E TER 2 - N: I7 IK1JU533286	ervices 0	
JOB CODE	<u> </u>	JOB DESCRIPTIO	N	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIA		OMMERCIAL	TOTAL (COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.31	\$22.48	\$88.23	\$0.	.00	\$110.71	
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.31	22.48	8	3.23	0.00		110.71
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fin</u>	<u>ish</u>		Quantity	Total (<u>Cost</u>
66-PM-PMA	PERFORM	DIL CHANGE		1	1758845		12/	17/2018 07:00:00	12/17/2018 0	07:18:36		0.31		\$22.48
												LABOR		22.48
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	Des	cription	<u>Uni</u>	t Price	Quantity	Total (<u>Cost</u>
66-PM-PMA	PERFORM C	DIL CHANGE		1	7801F00	50	AIF	R FILTER 2018 CA	MRY		37.26	1		\$37.26
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		OIL	0W16 CAM2 LSI	PI SN4+ QT		8.58	5		\$42.90
66-PM-PMA	PERFORM C	DIL CHANGE		V	/IX51394	Ļ	OIL	FILTER			8.07	1		\$8.07
												PARTS		88.23

UNIT NO:	242524	2018 TOYOTA CAMRY	V	WORK ORDER NO:	31762
Work Order Notes					
(LISAPATE) PM					
Job Notes					
66-PM-PMA - PERFOR	M OIL CHANGE				
(LISAPATE) PM by CS Coolant -32' Replaced air filter					

The University of Alabama

UNIT NO:		242524	2018 TOYOTA C	AMRY			WORK OR	DER NO:	32304	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	COMPL	ED DATE: LETED DATE: ED DATE: Camry	03/05/201	9 09:19:15 9 10:25:29 9 10:25:30	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	30493 DATE: 11/1	ersity Automotive \$ METER 2 - N: 1/2017 311HK1JU533286	0
JOB CODE 66-PM-PMA		JOB DESCRIPTIO	N STAT DON	<u>RSN</u> <u>WRT</u> P N	<u>JOB LOC</u> GARAGE	LABOR HRS 0.77	LABOR \$55.97	<u>MATERIAL</u> \$50.30	COMMERCIAL \$0.00	TOTAL COST \$106.27
JOB COUN	IT: 1			WORK OF	RDER TOTAL:	0.77	55.9	7 50.3	0 0.00	106.27
Job Code 66-PM-PMA	PERFORM	Job Descriptic DIL CHANGE		<u>Employee</u> 1074414		<u>Start</u> 01/2019 07:13:29		<u>nish</u> 07:59:48	Quantity 0.77 LABOR	Total Cost \$55.97 55.97
Job Code		Job Descriptio	<u>on</u>	Part N	<u>o.</u>	Des	cription	<u>Unit P</u>	rice Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	V	VIX51394	OIL	FILTER			7.17 1	\$7.17
66-PM-PMA	PERFORM	OIL CHANGE	0	W16T	OII	. 0W16 CAM2 LSI	PI SN4+ QT		8.63 5 PARTS	\$43.13 50.30

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	32304
Work Order Notes				
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFOR	N OIL CHANGE			
(LISAPATE) PM by SH,F	RC/SH			

The University of Alabama

UNIT NO:		242524 2	018 TOY	OTA C	AMRY				WORK ORI	DER NO:	32	2543		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	2018	OPENE COMPL CLOSE	ETED I	DATE:	04/11/201	9 10:59:37 9 08:12:00 9 08:12:02	LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL	34374 DATE: 1	MI 1/11/20 ⁻		ervices 0	
JOB CODE	L	JOB DESCRIPTION	1	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIA	<u> </u>	OMMERCIAL	<u>TOTAL</u>	<u>COST</u>
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.87	\$62.89	\$49.96	\$0	0.00	\$112.85	
JOB COUN	Т: 1				wo	RK ORI	DER TOTAL:	0.87	62.89	94	9.96	0.00		112.85
Job Code		Job Descriptio	<u>n</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fir</u>	<u>nish</u>		Quantity	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		04/	08/2019 08:34:47	04/08/2019	09:00:00		0.42		\$30.47
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		04/	08/2019 08:34:34	04/08/2019	09:01:24		0.45		\$32.42
												LABOR		62.89
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>	Des	cription	<u>Uni</u>	t Price	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		OIL	0W16 CAM2 LSI	PI SN4+ QT		8.63	5 5		\$43.13
66-PM-PMA	PERFORM (DIL CHANGE		V	VIX51394	ŀ	OIL	FILTER			6.83	5 1		\$6.83
												PARTS		49.96

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	32543
Work Order Note	<u>es</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	ORM OIL CHANGE			
(LISAPATE) PM by A Coolant -35'	G/SH			

The University of Alabama

UNIT NO:		242524 2	018 TOYOTA CAMRY		WORK ORDER NO:	330	14	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2018 Toyota Camry	05/29/2019 08:06:44 05/31/2019 06:24:41 05/31/2019 06:24:43		MET 11/11/2017	ER 2 - N:	ervices 0
JOB CODE 66-PM-PMA		JOB DESCRIPTION	<u>STAT</u> <u>RSN</u> <u>WRTY</u> DON P N	JOB LOCLABOR HRSGARAGE0.31	LABOR MATER \$22.48 \$36.47	IAL <u>CON</u> \$0.00	MMERCIAL D	TOTAL COST \$58.95
JOB COUN	IT: 1		WORK ORI	DER TOTAL: 0.31	22.48	36.47	0.00	58.95
Job Code 66-PM-PMA	PERFORM	Job Description OIL CHANGE	n <u>Employee</u> 11074414	No. <u>Start</u> 05/30/2019 06:00:00	<u>Finish</u> 05/30/2019 06:18:36	-	Quantity 0.31 LABOR	<u>Total Cost</u> \$22.48 22.48
Job Code		Job Descriptio	<u>n</u> <u>Part No</u>	. Des	cription Ur	nit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	WIX51394	OIL FILTER		6.69	1	\$6.69
66-PM-PMA	PERFORM	OIL CHANGE	0W16T	OIL 0W16 CAM2 LSI	PI SN4+ QT	5.96 _	5 PARTS	\$29.78 36.47

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	33014
Work Order Notes	<u>8</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(LISAPATE) PM by Eł Coolant -35'	<td></td> <td></td> <td></td>			

The University of Alabama

UNIT NO: 242524 2018 TOY			2018 TOYO	DTA C	AMRY				WORK ORDER NO: 33			33291		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAM		COMPL	ED DATI	DATE:	07/09/20	19 08:49:50 19 08:37:07 19 08:37:08	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	42603 DATE:	11/11/2	sity Automotive METER 2 - N: 2017 1HK1JU533286		
JOB CODE	L	JOB DESCRIP	TION	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL (COST
06-17	INSPECT	TIRES, TUBES,	LINERS & VAL	DON	0	Ν	GARAGE	0.50	\$36.25	\$0.00		\$0.00	\$36.25	
09-15	ALIGN STEERING			DON	0	Ν	GARAGE	3.50	\$253.75	\$0.00		\$0.00	\$253.75	
66-17-028	PERFOR	M MOUNT AND I	BALANCE TIRE	DON	0	N	GARAGE	0.80	\$58.00	\$643.20		\$0.00	\$701.20	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.38	\$27.39	\$36.47		\$0.00	\$63.86	
JOB COUNT: 4					WO	rk ori	DER TOTAL	: 5.18	375.3	9	679.67	0.00) 1 ,	,055.06
Job Code	Job Description				Em	ployee	<u>No.</u>	<u>Start</u>	Fir	nish		Quantity	Total C	<u>Cost</u>
06-17	INSPECT TI	RES, TUBES, LINE	RS & VALVES	1	1074414		07	7/08/2019 06:00:00	07/08/2019	06:30:00		0.50		\$36.25
66-17-028	PERFORM	MOUNT AND BALA	NCE TIRES	1	1901357		07	7/08/2019 07:00:00	07/08/2019	07:48:00		0.80		\$58.00
09-15	ALIGN STEE	ERING		1	1213180		07	7/08/2019 07:00:00	07/08/2019	10:30:00		3.50		\$253.75
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		07	7/01/2019 11:25:14	07/01/2019	11:47:54		0.38		\$27.39
												LABOR		375.39
Job Code		Job Descri	<u>ption</u>			Part No	<u>.</u>	Des	cription		Unit Pric	<u>ce</u> <u>Quantity</u>	Total C	Cost
66-17-028	PERFORM	MOUNT AND BALA	NCE TIRES	1	1711		ТІ	RE 215/55R17 MIC	CH DEFEND T+H		156.	57 4		\$626.28
66-17-028	PERFORM	MOUNT AND BALA	NCE TIRES	2	1030		TI	PMS SERVICE KIT	6-116		3.	30 4		\$13.20
66-17-028	PERFORM	MOUNT AND BALA	NCE TIRES	6	63001 1/4 OZ STICK ON T			APE WEIGHT		0.	06 20		\$1.20	
66-17-028	PERFORM MOUNT AND BALANCE TIRES			V	VHEEL V	/EIGHT	W	HEEL WEIGHT KN	NOCK ON		0.	42 6		\$2.52
66-PM-PMA	PERFORM OIL CHANGE 0W16T OIL 0W16 CAM		IL 0W16 CAM2 LS	PI SN4+ QT		5.	96 5		\$29.78					
66-PM-PMA	PERFORM	DIL CHANGE		V	VIX51394	Ļ	0	IL FILTER			6.	69 1		\$6.69
												PARTS		679.67

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

242524 2018 TOYOTA CAMRY UNIT NO:

WORK ORDER NO: 33291

Work Order Notes

(LISAPATE) Per Fleet loud noise coming from front tires

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Needs 4 tires and align

09-15 - ALIGN STEERING

(LISAPATE) MS Performed alignment it was difficult to complete due to vehicle had been struck in front passenger area. Added 2.0 for camber adjustment and rear toe added 0.5 to reset LDA (Lane departure alert)system

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG Coolant -35'

The University of Alabama

UNIT NO:		242524 2	018 TOYOTA	CAMR	Y			WORK ORI	DER NO	:	33633		
USING DEPT	NO:	750201	OPE	NED DA	TE:	08/06/201	19 08:02:21	LOCATION:	GARAGE	- Univer	sity Automotive	Services	
WO STATUS:		CLOSED	CON	PLETED	DATE:	08/09/201	19 09:47:16	METER 1 - M:	44837		METER 2 - N:	0	
WO VISIT RE	ASON:	SCHEDULED	CLC	SED DA	TE:	08/09/201	19 09:47:18	IN-SERVICE	DATE:	11/11/2	2017		
TECH SPEC	NO:	18TOYOTACAMRY	2018 Toyot	a Camry				UNIT SERIAL	NO:	4T1B1	1HK1JU533286		
JOB CODE		JOB DESCRIPTION	<u>ST/</u>	<u>T RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	<u>TOTAL</u>	COST
06-13	INSPECT	BRAKES	DO	N O	Ν	GARAGE	5.90	\$427.81	\$0.00		\$0.00	\$427.81	
JOB COUNT	: 1			w	ORK OR	DER TOTAL:	5.90	427.8	1	0.00	0.00)	427.81
Job Code		Job Description	<u>1</u>	<u>E</u>	mployee	No.	<u>Start</u>	<u>Fir</u>	<u>nish</u>		Quantity	<u>Total</u>	Cost
06-13 I	INSPECT BF	RAKES		1121318	30	08	/07/2019 06:01:14	08/07/2019	11:55:17		5.90		\$427.81
											LABOR		427.81

242524 2018 TOYOTA CAMRY UNIT NO:

WORK ORDER NO:

33633

Work Order Notes

(LISAPATE) Per Fleet check brakes driver says feel like they are slipping

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) Test drove vehicle several times only issue found was when ABS engages it seemed a little bit more noisy than most other vehicles. Also lifted vehicle and inspected all parts for wear or being loose no issue found. Test drove 2 other 2018 Camrys to compare and both other cars sounded and felt the same. Therefore the "slipping" felt is normal operation of the vehicle.

The University of Alabama

UNIT NO:		242524	2018 ТОҮОТА С	AMRY			WORK ORDE	R NO:	34020	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	COMPI	ED DATE: LETED DATE: ED DATE: Camry	09/12/201	9 09:28:46 9 06:29:55 9 06:29:56		6787 I E: 11/11/2	sity Automotive S METER 2 - N: 2017 1HK1JU533286	Services 0
JOB CODE 66-PM-PMA		JOB DESCRIPTIO	<u>N</u> <u>STAT</u> DON	<u>RSN</u> WRTY PN	<u>JOB LOC</u> GARAGE	LABOR HRS 0.79			COMMERCIAL \$0.00	TOTAL COST \$92.88
JOB COUN	NT: 1			WORK ORI	DER TOTAL:	0.79	57.09	35.79	0.00	92.88
Job Code 66-PM-PMA	PERFORM	Job Descriptic DIL CHANGE		<u>Employee</u> 12052187		<u>Start</u> 09/2019 10:38:15	<u>Finish</u> 09/09/2019 11:2	-	Quantity 0.79 LABOR	<u>Total Cost</u> \$57.09 57.09
Job Code		Job Description	on	Part No	<u>.</u>	Des	cription	<u>Unit Pric</u>	<u>e Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	C)W16T	OIL	0W16 CAM2 LSI	PI SN4+ QT	5.8	35 5	\$29.25
66-PM-PMA	PERFORM	OIL CHANGE	٧	WIX51394	OIL	FILTER		6.5	54 1 PARTS	\$6.54 35.79

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	34020
Work Order Notes				
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFOR	M OIL CHANGE			
(LISAPATE) PM by JW Coolant -25'				

The University of Alabama

UNIT NO:	242524 20	18 TOYOTA CAMRY		WORK ORDER NO:	34248	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2018 Toyota Camry	09/26/2019 08:29:00 09/30/2019 08:24:16 09/30/2019 08:24:18	LOCATION: GARAGE - METER 1 - M: 49410 IN-SERVICE DATE: UNIT SERIAL NO:	University Automotive S METER 2 - N: 11/11/2017 4T1B11HK1JU533286	ervices 0
JOB CODE 06-13 INSPEC JOB COUNT: 1	JOB DESCRIPTION T BRAKES	<u>STAT</u> <u>RSN</u> <u>WRTY</u> DON O N WORK ORD	JOB LOC LABOR HRS GARAGE 3.56 ER TOTAL: 3.56	• • • • • • • • • • • • • • • • • • • •		TOTAL COST \$257.98 257.98
Job Code 06-13 INSPECT B 06-13 INSPECT B 06-13 INSPECT B	RAKES	Employee N 11213180 11213180 11213180		<u>Finish</u> 09/27/2019 09:02:10 09/26/2019 14:56:40	Quantity 2.90 0.44 0.21	Total Cost \$210.39 \$32.22 \$15.37 257.98

UNIT NO: 242524 2018 TOYOTA CAMRY

WORK ORDER NO: 34248

Work Order Notes

(LISAPATE) Per Fleet brakes are scrubbing and noisy

Job Notes

06-13 - INSPECT BRAKES

(EKIMBREL) Test drove no noise found. Put car on a rack and inspected brakes and brake pads, no issue found. Test drove several more times and vehicle never acted up. Will need customer to make issue reoccur and bring back and show us.

EH drove vehicle 125 miles and listened for noises. He removed tires and inspected brakes at all four corners of vehicle. Brakes look good. He rotated tires and relearned tire positions.

The University of Alabama

UNIT NO:		242524	2018 TOYO	DTA C	AMRY				WORK OI		D: 3	34497		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMR		OPENE COMPL CLOSE	ETED	DATE:	10/23/20	019 10:24:38 019 08:04:23 019 08:04:24	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 51440 E DATE:	N 11/11/2	sity Automotive S METER 2 - N: 017 IHK1JU533286		
JOB CODE	_	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC			MATE		COMMERCIAL	<u>TOTAL</u>	COST
66-PM-PMA 66-PM-PMC	-	M OIL CHANGE M CABIN FILTER F	REPLACEMEI	DON DON	P O	N N	GARAGE GARAGE	1.04 0.18	• • •	\$35.70 \$43.77		\$0.00 \$0.00	\$111.14 \$56.78	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	.: 1.2	2 88	.45	79.47	0.00		167.92
Job Code		Job Descript	ion		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	l	<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-PM-PMC	PERFORM	CABIN FILTER REPLA	ACEMENT	1	1074414		1	0/18/2019 11:22:4	4 10/18/201	19 11:33:30		0.18		\$13.01
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		1	0/18/2019 10:59:5	2 10/18/201	19 11:31:27		0.53		\$38.16
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		1	0/18/2019 10:51:5	3 10/18/201	19 11:22:44		0.51		\$37.28
												LABOR		88.45
Job Code		Job Descript	ion			Part No	<u>-</u>	De	scription		Unit Price	<u>e</u> <u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM (DIL CHANGE		0	W16T		C	OIL OW16 CAM2 L	SPI SN4+ QT		5.8	34 5		\$29.18
66-PM-PMA	PERFORM (DIL CHANGE		V	/IX51394	4	C	IL FILTER			6.5	52 1		\$6.52
66-PM-PMC	PERFORM (ABIN FILTER REPLA	ACEMENT	8	00208C ⁻	ΓYC	C	ABIN AIR FILTER			43.7	771		\$43.77
												PARTS		79.47

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	34497
Work Order Notes	<u>6</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(EKIMBREL) SH/AG.	Coolant -35			
66-PM-PMC - PERFO	RM CABIN FILTER	REPLACEMENT		
(EKIMBREL) SH repla	aced cabin filter.			

The University of Alabama

UNIT NO:		242524 201	18 TOYO	TA C	AMRY	,			WORK ORDER NO:			35018		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	(OPENE COMPL CLOSE	ETED D DAT	DATE:	12/05/2	019 08:56:09 019 07:09:11 019 07:09:13	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 56187 DATE :	N 11/11/2	sity Automotive S METER 2 - N: 017 IHK1JU533286	Services 0	
JOB CODE	E	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	WRTY	JOB LO	C LABOR HRS	LABOR	MATE	RIAL (COMMERCIAL	<u>TOTAL</u>	COST
03-51-038	REPLAC	E NEW WIPER BLADES	3	DON	0	Ν	GARAGE	0.11	\$7.85	\$25.58	\$	50.00	\$33.43	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.50	\$36.09	\$35.69	\$	50.00	\$71.78	
JOB COUN	IT: 2				wo	RK OR	DER TOTA	L: 0.61	43.9	94	61.27	0.00		105.21
Job Code		Job Description			<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	inish		<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		1′	1074414			2/02/2019 13:34:05	5 12/02/2019) 13:40:35		0.11		\$7.85
66-PM-PMA	PERFORM	DIL CHANGE		11	1074414			2/02/2019 13:04:13	3 12/02/2019	9 13:34:05		0.50		\$36.09
												LABOR		43.94
Job Code		Job Description				Part No) <u>.</u>	Des	scription		Unit Price	e <u>Quantity</u>	Total	Cost
03-51-038	REPLACE N	EW WIPER BLADES		V	/W-2600)-PC	١	VIPER BLADE 26"			12.7	' 9 1		\$12.79
03-51-038	REPLACE N	EW WIPER BLADES		V	/W-2000)-PC	١	VIPER BLADE 20"			12.7	' 9 1		\$12.79
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		(DIL 0W16 CAM2 LS	PI SN4+ QT		5.8	34 5		\$29.18
66-PM-PMA	PERFORM	DIL CHANGE		V	/IX5139	4	(DIL FILTER			6.5	511		\$6.51
												PARTS		61.27

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	35018
Work Order Note	<u>es</u>			
(EKIMBREL) pm				
Job Notes				
03-51-038 - REPLAC	E NEW WIPER BL	ADES		
(EKIMBREL) Replace	ed both wipers.			
66-PM-PMA - PERFO	ORM OIL CHANGE			
(EKIMBREL) SH/SH.	. Coolant -50			

The University of Alabama

UNIT NO:		242524	2018 TOY	ΌΤΑ Ο	AMRY				WORK OR	DER NO:	3	5614	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMR`	Y 2018	OPENE COMPL CLOSE Toyota C	ETED I D DATE	DATE:	02/13/202	0 09:08:22 0 09:22:59 0 09:23:00	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	60575 DATE:	M 11/11/20		ervices O
JOB CODE	<u> </u>	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL C	OMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.47	\$33.83	\$46.03	\$0	0.00	\$79.86
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.47	33.8	3	46.03	0.00	79.8
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fii</u>	<u>nish</u>		Quantity	<u>Total Cost</u>
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		02/	10/2020 13:11:29	02/10/2020	13:39:29		0.47	\$33.8
												LABOR	33.8
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	cription	U	nit Price	Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		BR	AKE CLEAN NON	I-FLAMMABLE 14	4OZ	6.44	4 1	\$6.4
66-PM-PMA	PERFORM	DIL CHANGE		V	/IX51394		OIL	FILTER			6.51	1 1	\$6.5
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		OIL	. 0W16 CAM2 LSI	PI SN4+ QT		6.62	2 5	\$33.0
												PARTS	46.0

UNIT NO:	242524	2018 TOYOTA CAMRY	10:	35614
Work Order Notes				
(EKIMBREL) pm				
Job Notes				
66-PM-PMA - PERFOR	RM OIL CHANGE			
(EKIMBREL) SH/AG. C	oolant -50			

The University of Alabama

UNIT NO:		242524 2	018 TOYOTA CAMRY			WORK ORDER	NO: 3	86350	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	OPENED DATE: COMPLETED DATE CLOSED DATE: 2018 Toyota Camry	05/07/2020 E: 05/08/2020 05/08/2020	08:42:11	LOCATION: GARA METER 1 - M: 639 IN-SERVICE DATE: UNIT SERIAL NO:	04 N 11/11/20		ervices 0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION	<u>I stat rsn wr</u> Don p n		LABOR HRS 0.27	LABOR M \$19.64 \$36.		COMMERCIAL 50.00	TOTAL COST \$55.69
JOB COUN	IT: 1		WORK	ORDER TOTAL:	0.27	19.64	36.05	0.00	55.69
Job Code 66-PM-PMA	PERFORM	Job Description DIL CHANGE	n <u>Employ</u> 12052187		<u>Start</u> 7/2020 13:47:28	<u>Finish</u> 05/07/2020 14:03:4	13	Quantity 0.27 LABOR	<u>Total Cost</u> \$19.64 19.64
Job Code		Job Description	<u>n</u> <u>Part</u>	No.	Des	cription	Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	WIX51394	OIL F	ILTER		6.5	0 1	\$6.50
66-PM-PMA	PERFORM	OIL CHANGE	0W16T	OIL 0	W16 CAM2 LSF	PI SN4+ QT	5.9	1 5 PARTS	\$29.55 36.05

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	36350
Work Order Note	<u>es</u>			
(EKIMBREL) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(EKIMBREL) JW/JW	n aufauma al ail abaura	ra Caalant 24		

The University of Alabama

UNIT NO:	242524 201	18 TOYOTA CAMRY		WORK ORDER NO:	37877
USING DEPT NO:	750201	OPENED DATE:	10/05/2020 14:46:33	LOCATION: GARAGE - Univ	versity Automotive Services
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2020 11:16:23	METER 1 - M: 63937	METER 2 - N : 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/07/2020 12:32:34	IN-SERVICE DATE: 11/1	1/2017
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO: 4T1	B11HK1JU533286
JOB CODE	JOB DESCRIPTION	<u>STAT</u> <u>RSN</u> <u>WRTY</u>	JOB LOC LABOR HRS	LABOR MATERIAL	COMMERCIAL TOTAL CO
66-PM-PMA PERFOR	RM OIL CHANGE	DON P N	GARAGE 0.05	\$6.13 \$0.00	\$0.00 \$6.13
JOB COUNT: 1		WORK ORD	ER TOTAL: 0.05	6.13 0.0	0 0.00
Job Code	Job Description	Employee I	<u>No. Start</u>	<u>Finish</u>	Quantity Total Cos
66-PM-PMA PERFORM	OIL CHANGE	11170580	10/06/2020 11:50:07	10/06/2020 11:53:14	0.05 \$
					LABOR

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO: 242524	2018 TOYOTA CAMRY
-----------------	-------------------

WORK ORDER NO: 37877

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(ABLACK) AB checked fluids. Vehicle has only been driven 33 miles since last oil change.

The University of Alabama

UNIT NO:		242524	2018 TOYOTA C	AMRY				WORK OR	RDER NO:	39	9260		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	COMPL	ED DATE: LETED DAT ED DATE: Camry	E: 03	/04/202	1 08:40:14 1 11:19:14 1 13:21:50	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 68746 DATE:	MI 11/11/20	ty Automotive S ETER 2 - N: 17 HK1JU533286	Services 0	
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION	N STAT DON			B LOC RAGE	LABOR HRS 0.61	LABOR \$72.14	<u>MATEF</u> \$35.68		OMMERCIAL	TOTAL (\$107.82	<u>COST</u>
JOB COUN	IT: 1			WORK	ORDER	TOTAL:	0.61	72.	14	35.68	0.00		107.82
Job Code 66-PM-PMA	PERFORM	Job Descriptic OIL CHANGE		<u>Emplo</u> 1901357	<u>yee No.</u>	03/0	<u>Start</u> 03/2021 08:52:38		' inish 1 09:29:19		Quantity 0.61 LABOR	<u>Total (</u>	<u>Cost</u> \$72.14 72.14
Job Code		Job Descriptio	on	<u>Par</u>	t No.		Des	cription	<u>U</u>	nit Price	<u>Quantity</u>	Total C	<u>Cost</u>
66-PM-PMA	PERFORM	OIL CHANGE	0	W16T		OIL	0W16 CAM2 LSI	PI SN4+ QT		5.84	5		\$29.18
66-PM-PMA	PERFORM	OIL CHANGE	V	VIX51394		OIL	FILTER			6.50	PARTS		\$6.50 35.68

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	39260	

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 68746 Completed PM top and bottom side. Completed checklist. AMG

The University of Alabama

UNIT NO:		242524	2018 TOYOTA CAMRY WORK ORDER			D: 4	10356						
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY		OPENE COMPL CLOSE	ETED	DATE:	07/20/202	21 10:57:17 21 08:02:51 21 13:34:43	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 73344 DATE:	N 11/11/2	ity Automotive S IETER 2 - N: 017 HK1JU533286	
JOB CODE	<u>.</u>	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL (COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLAD	DES	DON	Ρ	Ν	GARAGE	0.10	\$11.80	\$20.60	\$	60.00	\$32.40
06-15	INSPEC	STEERING		DON	0	Ν	GARAGE	0.37	\$43.07	\$0.00	\$	60.00	\$43.07
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	0.63	\$74.37	\$0.00	\$	0.00	\$74.37
66-17-028	PERFOR	M MOUNT AND BAL	ANCE TIRE	DON	0	Ν	GARAGE	1.46	\$172.25	\$315.30) \$	60.00	\$487.55
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.72	\$84.93	\$43.58	\$	0.00	\$128.51
JOB COUN	T: 5				wo		DER TOTAL:	3.27	386.4	42	379.48	0.00	765.90
Job Code		Job Descriptio	on		Em	nployee	No.	<u>Start</u>	F	inish		Quantity	Total Cost
06-15	INSPECT ST			1	1310047			/08/2021 15:28:26	_			0.37	\$43.07
09-15	ALIGN STEE	ERING		1	1310047		07	/08/2021 14:39:17	07/08/202	15:17:06		0.63	\$74.37
66-17-028	PERFORM	MOUNT AND BALANCE	E TIRES	1	1074414		07	/08/2021 13:29:11	07/08/202 ²	14:15:00		0.76	\$90.11
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	1	1901357		07	/08/2021 13:39:30	07/08/202	14:21:16		0.70	\$82.14
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187		07	/06/2021 14:52:48	07/06/202	14:53:03		0.00	(\$0.49)
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187	,	07	/06/2021 14:52:48	07/06/202 ²	14:53:03		0.00	\$0.49
03-51-038	REPLACE N	IEW WIPER BLADES		1	2052187		07	/06/2021 14:52:48	07/06/202	14:58:48		0.10	\$11.80
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	,	07	/06/2021 14:09:25	07/06/202 ²	14:52:36		0.72	\$84.93
												LABOR	386.42
Job Code		Job Descriptio	on			Part No	<u>.</u>	Des	cription		Unit Price	<u>Quantity</u>	Total Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	9200		WI	PER BLADE OE E	BEAM STYLE 20	IN	9.6	6 1	\$9.66
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	1	1711		TIF	RE 215/55R17 MIC	CH DEFEND T+H	4	153.5	7 2	\$307.14
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	1	1711		TIF	RE 215/55R17 MIC	CH DEFEND T+H	ł	153.5	7 (2)	(\$307.14)
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	11711		TIF	RE 215/55R17 MIC	CH DEFEND T+H	4	153.5	7 2	\$307.14	
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	6	3001		1/4	OZ STICK ON TA	APE WEIGHT		0.0	6 9	\$0.54
66-17-028	PERFORM N	MOUNT AND BALANCE	E TIRES	V	VHEEL V	VEIGHT	WI	HEEL WEIGHT KN	IOCK ON		0.5	1 2	\$1.02
66-17-028	PERFORM	MOUNT AND BALANCE	E TIRES	2	1030		TP	MS SERVICE KIT	6-116		3.3	0 2	\$6.60

The University of Alabama

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	10.94	1	\$10.94
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	1	\$9.23
					PARTS	379.48

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	40356
Work Order Not	tes			
(LISAPATE) PM				
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(JWRIGHT) Replace	ed wiper blades			
06-15 - INSPECT S	TEERING			
(EHOWELL) Front e	end good. JAW/AMG			
09-15 - ALIGN STE	ERING			
(EHOWELL) Perform	med Alignment. EH			
66-17-028 - PERFC	ORM MOUNT AND BA	LANCE TIRES		
(AGUERRA) Replac	ced and balanced rea	r tires. Moved new tires to the front. AMG SH		
66-PM-PMA - PERF	FORM OIL CHANGE			
(JWRIGHT) Perform MILEAGE-73344	ned pm service. Coola	ant -34°. JAW/JAW		
Needs both rear tire	es replaced and aligne	d. Tires are bad chopped and worn below 2/32 in sp	pots	

The University of Alabama

UNIT NO:		242524	2018 ТОҮОТ	A CA	AMRY				WORK		D: 4	1065		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	CC	OMPL LOSE	D DATE ETED D D DATE amry	DATE:	09/27/20	21 08:22:11 21 10:46:54 21 13:53:00	METER IN-SERV	ON: GARAGI 1 - M: 77572 /ICE DATE: RIAL NO:	N 11/11/20		0	
JOB CODE	L	JOB DESCRIPTIO	<u>N S</u>	TAT	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LAB	<u>OR MAT</u>	<u>ERIAL</u>	COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	DES E	ON	Р	Ν	GARAGE	0.20	\$23.60	\$22.62	\$	0.00	\$46.22	
66-PM-PMA	PERFOR	M OIL CHANGE	C	ON	Р	Ν	GARAGE	0.66	5 \$78.34	\$44.90	\$	0.00	\$123.24	
CH-SP	CHARGE	Shop Supplies	[ON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	2.00	\$2.00	
JOB COUN	IT: 3				WOI	rk ori	DER TOTAL	: 0.8	6	101.94	67.52	2.00)	171.46
Job Code		Job Descriptio	on		Ve	ndor N	lo.	Invoice No.	Pure	chase Order N	lo.		Total	Cost
CH-SP	CHARGE SI	nop Supplies		50	03163		1							\$2.00
												COMML	_	2.00
Job Code		Job Description	on		Em	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		11	1901357		09	9/20/2021 14:30:0	0 09/20	/2021 15:09:50		0.66		\$78.34
66-PM-PMA	PERFORM	OIL CHANGE		11	1901357		09	9/20/2021 14:22:1	6 09/20	/2021 14:22:16		0.00		\$0.00
03-51-038	REPLACE N	IEW WIPER BLADES		11	1901357		09	9/20/2021 14:19:1	5 09/20	/2021 14:19:15		0.00		\$0.00
03-51-038	REPLACE N	IEW WIPER BLADES		11	1901357		09	9/20/2021 14:19:1	5 09/20	/2021 14:19:15		0.00		\$0.00
03-51-038	REPLACE N	IEW WIPER BLADES		11	1901357		09	9/20/2021 14:19:1	5 09/20	/2021 14:31:15		0.20		\$23.60
												LABOR		101.94
Job Code		Job Description	<u>on</u>		<u> </u>	Part No) <u>.</u>	De	scription		Unit Price	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	OIL CHANGE		W	/IX51394		0	IL FILTER			9.2	7 1		\$9.27
03-51-038	REPLACE N	IEW WIPER BLADES		19	9200		W	IPER BLADE OE	BEAM STYL	_E 20IN	10.1	9 1		\$10.19
66-PM-PMA	PERFORM	DIL CHANGE		0\	N16T		0	IL 0W16 CAM2 L	SPI SN4+ Q1	Г	7.1	3 5		\$35.63
03-51-038	REPLACE N	IEW WIPER BLADES		19	9260		W	IPER BLADE 26	IN OE BEAN	1	12.4			\$12.43
												PARTS		67.52

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO: 242524 2018 TOYOTA CAMRY

WORK ORDER NO: 41065

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 77572 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:		242524 2	2018 TOYO	DTA C	AMRY	,			WORK OR	DER NO	: 41	913	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY		OPENE COMPL CLOSE	ETED	DATE:	12/22/202	21 13:52:18 21 08:37:02 22 09:02:00	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 84422 DATE :	ME 11/11/201	TER 2 - N:	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	N	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL COST
06-15	INSPEC	STEERING		DON	0	Ν	GARAGE	0.50	\$58.51	\$0.00	\$0.	00	\$58.51
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	0.59	\$69.29	\$0.00	\$0.	00	\$69.29
66-17-028	PERFOR	M MOUNT AND BAL	ANCE TIRE	DON	Ο	N	GARAGE	0.74	\$86.73	\$323.17	\$0.	00	\$409.90
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.43	\$50.90	\$44.98	\$0.	00	\$95.88
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.	00	\$2.00
JOB COUN	IT: 5				wo		DER TOTAL:	2.25	265.4	13	368.15	2.00	635.5
Job Code CH-SP	CHARGE Sr	Job Descriptio	<u>n</u>	5	<u>v</u> 03163	endor N	l <mark>o.</mark> 1	Invoice No.	Purchas	e Order No	<u>).</u>		<u>Total Cost</u> \$2.
												COMML	2.0
Job Code		Job Descriptio	<u>n</u>		En	nployee	<u>No.</u>	<u>Start</u>	Fi	inish		<u>Quantity</u>	Total Cost
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	1	1074414	1	12	/17/2021 15:03:41	12/17/2021	15:28:05		0.41	\$47.9
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	1	1074414	1	12	/17/2021 14:31:48	12/17/2021	14:51:30		0.33	\$38.
09-15	ALIGN STEE	ERING		1	1310047	7	12	/21/2021 08:33:37	12/21/2021	09:08:51		0.59	\$69.2
06-15	INSPECT ST	EERING		1	1074414	1	12	/16/2021 09:44:14	12/16/2021	10:13:59		0.50	\$58.
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414	1	12	/16/2021 09:30:00	12/16/2021	09:42:51		0.21	\$25.2
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414	1	12	/16/2021 09:01:58	12/16/2021	09:15:00		0.22	\$25.6
												LABOR	265.4
Job Code		Job Descriptio	<u>n</u>			Part No	<u>.</u>	Des	cription	<u>।</u>	<u>Unit Price</u>	Quantity	Total Cost
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	5	8122		.75	5 OZ WHEEL WEI	GHT		0.43	1	\$0.4
66-17-028	PERFORM N	MOUNT AND BALANCE	TIRES	1	1711		TI	RE 215/55R17 MIC	CH DEFEND T+H	ł	156.57	2	\$313.
66-17-028	PERFORM	MOUNT AND BALANCE	TIRES	6	3001		1/4	4 OZ STICK ON TA	APE WEIGHT		0.17	6	\$0.
66-17-028	PERFORM	MOUNT AND BALANCE	TIRES	2	1030		TP	MS SERVICE KIT	6-116		4.31	2	\$8.
66-PM-PMA	PERFORM	DIL CHANGE		V	VIX5139	4	OI	L FILTER			9.24	1	\$9.1
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		BF	RAKE CLEAN NON	N-FLAMMABLE 1	40Z	6.56	1	\$6.

The University of Alabama

Work Order Charge Detail

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	368.15

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO: 242524 2018 TOYOTA CAMRY WORK ORDER NO: 41913 Work Order Notes 41913

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(SHARBIN) Inspected brakes and steering found no issues. SH

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires put new tires on the front. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Needs 2 rear tires they are at 2/32 & 3/32.

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:		242524	2018 TOYO	ОТА С	AMRY				WORK ORDER NO):	43223		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMR\		OPENE COMPL CLOSE	ETED I D DATI	DATE:	05/13/20	022 09:08:42 022 15:36:27 022 15:36:02	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	I: 85199 DATE:	l 11/11/2	sity Automotive \$ METER 2 - N: 2017 1HK1JU533286		
JOB CODE	<u> </u>	JOB DESCRIPTIO	N	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOO	LABOR HRS	LABOR	MATE	ERIAL	COMMERCIAL	TOTAL C	COST
03-51-038	REPLAC	E NEW WIPER BLA	DES	DON	Р	Ν	GARAGE	0.05	\$5.67	\$22.62	:	\$0.00	\$28.29	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.22	\$25.96	\$75.78	:	\$0.00	\$101.74	
66-PM-PMC	PERFOR	M CABIN FILTER R	EPLACEMEI	DON	Р	Ν	GARAGE	0.06	\$6.82	\$18.57		\$0.00	\$25.39	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	:	\$2.00	\$2.00	
JOB COUN					WO		DER TOTAI	_: 0.33	38.4	45	116.97	2.00		157.42
								0.00	50.		110.57	2.00		
Job Code		Job Description	<u>on</u>			endor N		Invoice No.	Purchas	e Order N	<u>lo.</u>		<u>Total C</u>	
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Description	on		Em	ployee	<u>No.</u>	<u>Start</u>	<u></u>	<u>inish</u>		<u>Quantity</u>	Total C	<u>cost</u>
66-PM-PMC	PERFORM	CABIN FILTER REPLA	CEMENT	1	1074414		C	5/13/2022 09:59:29	05/13/2022	2 10:02:57		0.06		\$6.82
03-51-038	REPLACE N	EW WIPER BLADES		1'	1074414		C	5/13/2022 09:56:17	05/13/2022	2 09:59:10		0.05		\$5.67
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		C	5/13/2022 09:42:54	05/13/2022	2 09:56:06		0.22		\$25.96
												LABOR		38.45
Job Code		Job Description	on			Part No	<u>.</u>	Des	cription		Unit Pric	<u>e</u> <u>Quantity</u>	<u>Total C</u>	<u>Cost</u>
66-PM-PMA	PERFORM (DIL CHANGE		W	/A10859		A	IR FILTER CAMRY			33.1	12 1		\$33.12
66-PM-PMC	PERFORM	CABIN FILTER REPLA	CEMENT	Р	C99237	0	C	ABIN FILTER 2020	CAMRY		18.5	57 1		\$18.57
66-PM-PMA	PERFORM	DIL CHANGE		W	/IX51394	1	C	DIL FILTER			5.3	31 1		\$5.31
03-51-038	REPLACE N	EW WIPER BLADES		1	9200		v	VIPER BLADE OE E	BEAM STYLE 20	IN	10.1	19 1		\$10.19
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		C	DIL 0W16 CAM2 LS	PI SN4+ QT		7.4	47 5		\$37.35
03-51-038	REPLACE N	EW WIPER BLADES		1	9260		V	VIPER BLADE 26 I	N OE BEAM		12.4	43 1		\$12.43
												PARTS		116.97

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	43223
Work Order Note	es			
(LISAPATE) PM-repl	ace wipers			
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(HHARBIN) Replace	d the wipers. SH			
66-PM-PMA - PERF	ORM OIL CHANGE			
(HHARBIN) SH/AMO	Performed PM.			
66-PM-PMC - PERF	ORM CABIN FILTE	R REPLACEMENT		
(HHARBIN) Replace	d the cabin air filter.	SH		
CH-SP - CHARGE S	hop Supplies			

The University of Alabama

UNIT NO:		242524 20 ⁷	18 TOYOTA C	AMRY	,			WORK O	RDER NO:	4	45470	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	OPENE COMPL CLOSE 2018 Toyota C	ETED	DATE:	12/08/202	2 10:30:22 2 08:15:49 2 09:32:28	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 87150 DATE:	N 11/11/2	iity Automotive S /ETER 2 - N: 017 IHK1JU533286	Services 0
JOB CODE	<u>.</u>	JOB DESCRIPTION	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	<u>RIAL</u>	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	Ν	GARAGE	0.24	\$28.68	\$0.00	\$	50.00	\$28.68
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00
JOB COUN	T: 2			WO		DER TOTAL:	0.24	28	.68	0.00	5.00	33.68
Job Code		Job Description		v	endor N	<u>o.</u>	Invoice No.	Purcha	se Order No	<u>.</u>		Total Cost
CH-SP	CHARGE Sh	nop Supplies	5	03163		1						\$5.00
											COMML	5.00
Job Code		Job Description		En	nployee	No.	<u>Start</u>	<u> </u>	-inish		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	1	1901357	,	12/	07/2022 10:41:42	12/07/202	2 10:56:17		0.24	\$28.68
											LABOR	28.68

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO: 242524 2018 TOYOTA CAMRY

WORK ORDER NO: 45470

Work Order Notes

(EHANNAH) pm- Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 87150 Vehicle has been 1951 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG SH

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:		242524 201	8 TOYO	TA C	AMRY				WORK OF	DER NO	: 4	6794		
USING DEF WO STATU WO VISIT F TECH SPE	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	С	OMPL	ED DATE ETED I D DATE Camry	DATE:	04/24/202	23 07:35:54 23 10:54:02 23 13:14:01	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	: 88688 DATE :	M 11/11/20	ty Automotive 5 ETER 2 - N: 17 HK1JU533286		
JOB CODI	<u>E</u>	JOB DESCRIPTION	-	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL <u>C</u>	OMMERCIAL	TOTAL	<u>COST</u>
03-51-038	REPLAC	E NEW WIPER BLADES		DON	Ρ	Ν	GARAGE	0.04	\$5.11	\$23.96	\$0).00	\$29.07	
66-79-003	PERFOR	RM SAFETY INSPECTION	١	DON	Y	Ν	GARAGE	0.50	\$59.00	\$0.00	\$0).00	\$59.00	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.07	\$8.33	\$41.36	\$0).00	\$49.69	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
WA-00	WASH C	OMPLETE VEHICLE		DON	Ρ	Ν	GARAGE	0.10	\$11.80	\$0.00	\$0).00	\$11.80	
JOB COUN	NT: 5				wo	RK OR	DER TOTAL	. 0.71	84.	24	65.32	5.00)	154.56
Job Code		Job Description			V	endor N	<u>lo.</u>	Invoice No.	Purchas	e Order No) <u>.</u>		Total	Cost
CH-SP	CHARGE SI	hop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Description			Em	ployee	<u>No.</u>	<u>Start</u>	E	<u>inish</u>		Quantity	Total	Cost
03-51-038	REPLACE N	NEW WIPER BLADES		1	2201267		04	/24/2023 10:48:54	04/24/2023	3 10:51:30		0.04		\$5.11
66-79-003	PERFORM	SAFETY INSPECTION		1	2201267		04	/21/2023 12:40:35	04/21/202	3 12:40:35		0.00		\$0.00
66-79-003	PERFORM	SAFETY INSPECTION		1	2201267		04	/21/2023 12:40:35	04/21/2023	3 12:40:35		0.00		\$0.00
66-79-003	PERFORM	SAFETY INSPECTION		1	2201267		04	/21/2023 12:40:35	04/21/2023	3 13:10:35		0.50		\$59.00
WA-00	WASH COM	IPLETE VEHICLE		1	2201267		04	/21/2023 12:37:31	04/21/2023	3 12:37:31		0.00		\$0.00
WA-00	WASH COM	IPLETE VEHICLE		1	2201267		04	/21/2023 12:37:31	04/21/202	3 12:37:31		0.00		\$0.00
WA-00	WASH COM	IPLETE VEHICLE		1	2201267		04	/21/2023 12:37:31	04/21/2023	3 12:43:31		0.10		\$11.80
66-PM-PMA	PERFORM	OIL CHANGE		1	2201267		04	/21/2023 10:46:24	04/21/2023	3 10:50:38		0.07		\$8.33
												LABOR		84.24
Job Code		Job Description				Part No	<u>).</u>	Des	scription	l	<u> Jnit Price</u>	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	OIL CHANGE		V	VIX51394	Ļ	O	L FILTER			5.81	1		\$5.81
03-51-038	REPLACE N	NEW WIPER BLADES		1	9200		W	IPER BLADE OE E	BEAM STYLE 20	DIN	10.74	• 1		\$10.74
66-PM-PMA		OIL CHANGE			W16T			L 0W16 CAM2 LSI			7.11			\$35.55
03-51-038	REPLACE N	NEW WIPER BLADES		1	9260		W	IPER BLADE 26 IN	N OE BEAM		13.22	2 1		\$13.22
FleetFocus M5	5 - WODETAIL	- Work Order Detail v20.0												Page:1

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

242524 2018 TOYOTA CAMRY UNIT NO:

WORK ORDER NO:

46794

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection, no issues were found at this time.-GC Brake pads are all 7mm on all four wheels Miles, 88,868

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, JW- Changed oil and oil filter, checked fluids, filters good, tires and tire pressure. Miles, 88,688

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Wash Bay was down-GC

The University of Alabama

UNIT NO:		242524	2018 TOYO	ОТА С	AMRY	,			WORK O	RDER NO	: 48	351		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMF		OPENE COMPL CLOSE	ETED	DATE:	09/28/202	23 10:51:47 23 08:21:23 23 11:14:14	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M : 91155 E DATE :	ME 11/11/201	y Automotive S E TER 2 - N: I7 IK1JU533286		
JOB CODE		JOB DESCRIPTI	ON	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE		OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	N	GARAGE	0.04	\$4.23	\$24.08	\$0.	.00	\$28.31	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.31	\$37.10	\$50.09	\$0.	.00	\$87.19	
66-PM-PMC	PERFOR	M CABIN FILTER I	REPLACEMEI	DON	Р	N	GARAGE	0.10	\$11.80	\$22.73	\$0.	.00	\$34.53	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.	00	\$5.00	
WA-00		OMPLETE VEHICL	E	DON	P	N	GARAGE		\$3.05	\$0.00	\$0.		\$3.05	
JOB COUN					wo		DER TOTAL:			.18	96.90	5.00		158.08
Job Code		Job Descript	tion		v	endor N	0.	Invoice No.	Purcha	se Order No	<u>.</u>		Total	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1				_			\$5.00
												COMML		5.00
Job Code		Job Descript	tion		Em	nployee	<u>No.</u>	<u>Start</u>	ļ	Finish		Quantity	<u>Total</u>	Cost
66-PM-PMC	PERFORM	CABIN FILTER REPL	ACEMENT	1	1074414		09	/28/2023 07:00:00	09/28/202	23 07:06:00		0.10		\$11.80
WA-00	WASH COM	PLETE VEHICLE		1	1074414		09	/27/2023 11:40:12	09/27/202	23 11:41:45		0.03		\$3.05
03-51-038	REPLACE N	IEW WIPER BLADES	5	1	1074414		09	/27/2023 11:37:52	09/27/202	23 11:40:01		0.04		\$4.23
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414		09	/27/2023 11:18:48	09/27/202	23 11:37:40		0.31		\$37.10
												LABOR		56.18
Job Code		Job Descript	tion			Part No	<u>.</u>	Des	cription	ļ	Unit Price	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	OIL CHANGE		V	/IX51394	4	OI	L FILTER			6.14	1		\$6.14
66-PM-PMA	PERFORM	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LSI	PI SN4+ QT		8.79	5		\$43.95
66-PM-PMC	PERFORM	CABIN FILTER REPL	ACEMENT	P	C99237	С	CA	ABIN FILTER 2020	CAMRY		22.73	1		\$22.73
03-51-038	REPLACE N	IEW WIPER BLADES	5	1	9200		W	PER BLADE OE E	BEAM STYLE 2	0IN	10.85	1		\$10.85
03-51-038	REPLACE N	IEW WIPER BLADES	5	1	9260		W	PER BLADE 26 IN	N OE BEAM		13.23	1		\$13.23
												PARTS		96.90

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	48351
Work Order Not	ies			
(EHANNAH) pm- w	pers- wash			
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(SHARBIN) Wipers	were replaced.			
66-PM-PMA - PERI	FORM OIL CHANGE			
(SHARBIN) IF FC E	H/SH Performed PM	. SH		
66-PM-PMC - PER	FORM CABIN FILTE	R REPLACEMENT		
(LISAPATE) Replac	ed cabin filter SH			
CH-SP - CHARGE	Shop Supplies			
WA-00 - WASH CO	MPLETE VEHICLE			
(SHARBIN) Washed	d the vehicle. SH			

The University of Alabama

UNIT NO:		242524 2	018 ТОҮОТА	CAMR	Y			WORK C	RDER NO	: 49	987	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	750201 CLOSED SCHEDULED 18TOYOTACAMRY	СОМ	SED DA	D DATE: TE:	02/29/202	24 10:38:36 24 13:37:07 24 14:50:47		M: 92808 E DATE:	ME 11/11/201	y Automotive S E TER 2 - N: I7 IK1JU533286	Services 0
JOB CODE		JOB DESCRIPTION	<u>I</u> <u>STA</u>	<u>r</u> <u>rs</u> i	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL CO	OMMERCIAL	TOTAL COS
66-PM-PMA	PERFOR	RM OIL CHANGE	DO	I P	Ν	GARAGE	0.19	\$22.65	\$0.00	\$0.	.00	\$22.65
CH-SP	CHARGE	E Shop Supplies	DOM	1 2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.	.00	\$5.00
WA-00	WASH C	OMPLETE VEHICLE	DO	I P	Ν	GARAGE	0.35	\$41.60	\$0.00	\$0.	.00	\$41.60
JOB COUN	IT: 3			W	ORK OR	DER TOTAL:	0.54	6	4.25	0.00	5.00	69.
Job Code CH-SP	CHARGE SI	Job Description	<u>n</u>	503163	<u>Vendor N</u>	<u>lo.</u> 1	<u>Invoice No.</u>	Purch	ase Order No	<u>).</u>		<u>Total Cost</u> \$5
				000100							COMML	5.
Job Code		Job Description	<u>1</u>	E	mployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE		110744	14	02/	/28/2024 10:45:10	02/28/20	24 10:56:41		0.19	\$22
WA-00	WASH CON	IPLETE VEHICLE		110744	14	02/	/28/2024 10:57:30	02/28/20	24 11:18:39		0.35	\$41
											LABOR	64.

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO:	242524	2018 TOYOTA CAMRY	WOR

RK ORDER NO: 49987

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 1653 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed and filled with gas. SH

The University of Alabama

UNIT NO:	242524	2018 TOYO	ОТА С	AMRY	,			WORK OR	DER NO:	505	44		
USING DEPT NO:	750201		OPENE	ED DAT	E:	04/11/2024	4 14:18:41	LOCATION:	GARAGE	- University A	utomotive	Services	
WO STATUS:	CLOSED		СОМРІ	LETED	DATE:	04/17/2024	4 14:46:32	METER 1 - M	: 93690	MET	ER 2 - N:	0	
WO VISIT REASON:	SCHEDULED		CLOSE	ED DAT	E:	04/18/202	4 07:10:11	IN-SERVICE	DATE:	11/11/2017			
TECH SPEC NO:	18TOYOTACAMF	RY 2018 T	ōyota C	Camry				UNIT SERIAI	NO:	4T1B11HK	1JU533286	;	
JOB CODE	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL COM	MERCIAL	TOTAL	COST
PD-00-999 PREP	DISPOSE PREPARE	UNIT FOR DI	DON	D	Ν	GARAGE	0.00	\$0.00	\$0.00	\$0.00)	\$0.00	
JOB COUNT: 1				wo		DER TOTAL:	0.00	0.0	00	0.00	0.00)	0.00

The University of Alabama Report Printed: 04/19/2024 13:44:15 By User: GLOBETTI

UNIT NO:	242524	2018 TOYOTA CAMRY	WORK ORDER NO:	50544
Work Order Note	<u>es</u>			
(EHANNAH) prep for	sale			
Job Notes				
PD-00-999 - PREP D	ISPOSE PREPARE	E UNIT FOR DISPOSAL		
(LISAPATE) Prep for	sale done by FC			

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

Data Extracted: Fr	E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1 Fri Apr 19 2024 13:44:15 Report User: GLOBETTI Central Standard Time
Report Comments: 6/ Fc	2021.02.23 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 Parameters and Selection Filters
First Grouping: Second Grouping: Third Grouping: Sorted By: From Date: To Date: Option 1: Option 2: Selection Filters:	VIEW_WO_WORKSHEET.WO_NO VIEW_JOB_WORKSHEET.JOB