

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 10301

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 02/10/2012 14:49:33	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/15/2012 11:29:56	<b>METER 1 - M:</b> 84701 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/15/2012 11:29:58	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.25	\$72.02	\$28.11	\$0.00	\$100.13

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **3.05**      **175.52**      **28.11**      **0.00**      **203.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/10/2012 15:10:51	02/10/2012 15:58:11	0.79	\$45.36
66-PM-PMA	PERFORM OIL CHANGE	11413680	02/13/2012 07:28:18	02/13/2012 07:56:07	0.46	\$26.66
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/13/2012 07:00:00	02/13/2012 08:00:00	1.00	\$57.50
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	02/13/2012 07:30:00	02/13/2012 07:48:00	0.30	\$17.25
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	02/13/2012 07:00:00	02/13/2012 07:30:00	0.50	\$28.75

**LABOR**      **175.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	194	BULB-TAG/MARKER	0.60	1	\$0.60

**PARTS**      **28.11**

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 10301

---

## Work Order Notes

(LPATE) FLEET REQUESTED SAFETY INSPECTION BEFORE CAR IS USED AS A RENTAL VEHICLE. PM-ROTATE TIRES-RIGHT REAR TAILLIGHT BULB IS OUT

---

## Job Notes

**03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC**

(LPATE) REPLACED RIGHT REAR TAIL LIGHT BULB

**31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LPATE) ROTATED TIRES

**66-79-003 - PERFORM SAFETY INSPECTION**

(LPATE) SAFETY INSPECTION COMPLETE

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY RT

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 11001

USING DEPT NO:	505161	OPENED DATE:	05/10/2012 13:10:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/10/2012 15:06:11	METER 1 - M:	86279	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2012 15:06:13	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-43-007	REPAIR HANGERS & BRACKETS	DON	O	N	GARAGE	0.75	\$43.13	\$0.00	\$0.00	\$43.13

JOB COUNT: 1 WORK ORDER TOTAL: 0.75 43.13 0.00 0.00 43.13

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-43-007	REPAIR HANGERS & BRACKETS	11413680	05/10/2012 17:00:00	05/10/2012 17:45:00	0.75	\$43.13
					<b>LABOR</b>	<b>43.13</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 11001

---

**Work Order Notes**

(LPATE) PER DONALD HAS A RATTLE IN REAR END-COMING FROM EXHAUST LOOKS LIKE IT WAS BACKED INTO A CURB.

---

**Job Notes**

**24-43-007 - REPAIR HANGERS & BRACKETS**

(RWINTERS) RT AND RW HEATED PIPE THEN BENT MOUNTS FOR MUFFLER BACK INTO POSITION.

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 118

USING DEPT NO:	505161	OPENED DATE:	09/26/2007 06:30:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2007 06:51:00	METER 1 - M:	3959	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2007 07:27:08	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$25.14	\$0.00	\$39.09

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 13.95 25.14 0.00 39.09

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	09/26/2007 07:00:00	09/26/2007 07:18:36	0.31	\$13.95
					<b>LABOR</b>	<b>13.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	10.74	1	\$10.74
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	192	\$14.40
					<b>PARTS</b>	<b>25.14</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 118

---

**Work Order Notes**

(RWINTERS) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS) PM PERFORMED

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 11894

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 09/13/2012 08:24:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/14/2012 11:55:34	<b>METER 1 - M:</b> 87316 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 09/14/2012 11:55:36	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNT0YSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$39.60	\$0.00	\$57.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.25	\$14.38	\$24.78	\$0.00	\$39.16

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.56**      **32.21**      **64.38**      **0.00**      **96.59**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11338644	09/13/2012 08:58:36	09/13/2012 09:13:36	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/13/2012 08:40:00	09/13/2012 08:58:36	0.31	\$17.83
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	24.78	1	\$24.78
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
					<b>PARTS</b>	<b>64.38</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 11894

---

**Work Order Notes**

(GMANNING) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(GMANNING)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(GMANNING) RS PERFORMED PM

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(RWINTERS) REPLACED THE CABIN FILTER.

---



# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 1257

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 05/02/2008 14:33:24	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/05/2008 15:56:29	<b>METER 1 - M:</b> 18940 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 05/05/2008 15:56:29	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$14.05	\$26.16	\$0.00	\$40.21

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **14.05**      **26.16**      **0.00**      **40.21**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	05/02/2008 15:55:34	05/02/2008 15:55:42	0.00	\$0.10
66-PM-PMA	PERFORM OIL CHANGE	11088474	05/02/2008 14:35:00	05/02/2008 14:53:36	0.31	\$13.95
					<b>LABOR</b>	<b>14.05</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	8.88	1	\$8.88
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	192	\$17.28
					<b>PARTS</b>	<b>26.16</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 1257

---

**Work Order Notes**

(LOBRIEN) PM.

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LOBRIEN) PM BY JASON ELMORE.

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 14003

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 05/30/2013 14:22:49	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/31/2013 14:45:00	<b>METER 1 - M:</b> 89734 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/31/2013 14:45:03	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.06	\$3.63	\$45.34	\$0.00	\$48.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$3.02	\$52.81	\$0.00	\$55.83

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.12**      **6.65**      **98.15**      **0.00**      **104.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	05/31/2013 08:43:14	05/31/2013 08:46:23	0.05	\$3.02
03-51-038	REPLACE NEW WIPER BLADES	11338644	05/31/2013 08:39:09	05/31/2013 08:42:56	0.06	\$3.63
					<b>LABOR</b>	<b>6.65</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	16.49	1	\$16.49
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.79	1	\$6.79
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	28.85	1	\$28.85
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 20OZ FUEL ADDITIVE	12.09	1	\$12.09
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	6	\$33.93
					<b>PARTS</b>	<b>98.15</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 14003

---

**Work Order Notes**

(LPATE) PM-REPLACE WIPERS

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.7675

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY GM/RS

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 1587

USING DEPT NO:	505161	OPENED DATE:	06/30/2008 11:21:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2008 11:24:06	METER 1 - M:	21761	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/30/2008 11:24:09	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$25.49	\$0.00	\$39.44

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 13.95 25.49 0.00 39.44

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	06/30/2008 11:23:00	06/30/2008 11:41:36	0.31	\$13.95
					<b>LABOR</b>	<b>13.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.85	1	\$7.85
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	196	\$17.64
					<b>PARTS</b>	<b>25.49</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 1587

---

## Work Order Notes

(RWINTERS) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 196  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(RWINTERS) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 16375

<b>USING DEPT NO:</b>	505161	<b>OPENED DATE:</b>	03/13/2014 07:30:16	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	03/17/2014 11:34:03	<b>METER 1 - M:</b>	91280	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	03/17/2014 11:34:04	<b>IN-SERVICE DATE:</b>	05/11/2007	
<b>TECH SPEC NO:</b>	07VNTTOYSIENNA	2007 Toyota Sienna		<b>UNIT SERIAL NO:</b>	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-33	TRANSPORT IGNITION SYSTEM	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
17-33-011	RECALL SHIFT LOCK SOLENOID	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.00**      **57.50**      **0.00**      **0.00**      **57.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-33-011	RECALL SHIFT LOCK SOLENOID	11076422	TOCS617761	0023090	\$0.00
<b>COMML</b>					<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-33	TRANSPORT IGNITION SYSTEM	11074414	03/14/2014 06:00:00	03/14/2014 07:00:00	1.00	\$57.50
<b>LABOR</b>						<b>57.50</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 16375

---

**Work Order Notes**

(LPATE) TAKE TO TOYOTA FOR RECALL POSSIBLE DEFECTIVE SHIFT LOCK SOLENOID

---

**Job Notes**

**16-33 - TRANSPORT IGNITION SYSTEM**

(LPATE) TAKEN TO TOYOTA BY SH

**17-33-011 - RECALL SHIFT LOCK SOLENOID**

(LPATE) TUSCALOOSA TOYOTA COMPLETED RECALL

---



# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 16507

USING DEPT NO:	505161	OPENED DATE:	04/03/2014 13:55:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2014 07:02:40	METER 1 - M:	91342	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/07/2014 07:02:43	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.22	\$0.00	\$59.05

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 41.22 0.00 59.05

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/04/2014 06:00:00	04/04/2014 06:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.66	1	\$6.66
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	6	\$34.56
					<b>PARTS</b>	<b>41.22</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 16507

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY GM

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 1915

USING DEPT NO:	505161	OPENED DATE:	09/02/2008 11:38:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2008 11:42:02	METER 1 - M:	25182	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	09/02/2008 11:42:04	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$24.96	\$0.00	\$38.91

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 13.95 24.96 0.00 38.91

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	09/02/2008 11:40:00	09/02/2008 11:58:36	0.31	\$13.95
					<b>LABOR</b>	<b>13.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.32	1	\$7.32
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	196	\$17.64
					<b>PARTS</b>	<b>24.96</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 1915

---

## Work Order Notes

(AJONES) PM BY JE

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(AJONES) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 196  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(AJONES) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 19935

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 04/03/2015 10:05:26	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/06/2015 09:15:11	<b>METER 1 - M:</b> 94348 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/06/2015 09:15:14	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$40.77	\$0.00	\$58.60

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **40.77**      **0.00**      **58.60**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	04/03/2015 11:40:42	04/03/2015 11:59:18	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	6	\$33.84
					<b>PARTS</b>	<b>40.77</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 19935

---

## Work Order Notes

(LPATE) PM

---

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY GM/RS-CHECKED OIL FILTER LEAKING, ORING DEFECTIVE REMOVED AND INSTALLED NEW FILER. RECHECKED OK

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 21525

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 09/24/2015 07:47:53	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/25/2015 06:36:15	<b>METER 1 - M:</b> 95920 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/25/2015 06:36:17	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-40-415	REPLACE NEW OIL COOLER LINES	DON	O	N	GARAGE	1.30	\$74.75	\$98.88	\$0.00	\$173.63
06-40	INSPECT ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$55.62	\$0.00	\$73.45

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **2.11**      **121.33**      **154.50**      **0.00**      **275.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11213180	09/24/2015 08:48:04	09/24/2015 09:06:40	0.31	\$17.83
06-40	INSPECT ENGINE / MOTOR SYSTEMS	11213180	09/24/2015 08:47:49	09/24/2015 09:17:49	0.50	\$28.75
03-40-415	REPLACE NEW OIL COOLER LINES	11213180	09/24/2015 08:47:58	09/24/2015 10:05:58	1.30	\$74.75
					<b>LABOR</b>	<b>121.33</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	128	\$15.36
03-40-415	REPLACE NEW OIL COOLER LINES	0400429131	OIL COOLER PIPE	98.88	1	\$98.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.42	1	\$6.42
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	6	\$33.84
					<b>PARTS</b>	<b>154.50</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 21525

## Work Order Notes

(LISAPATE) PER DRIVER VAN IS LOW ON OIL. CHECK FOR OIL LEAKING

## Job Notes

### **03-40-415 - REPLACE NEW OIL COOLER LINES**

(RWINTERS) TOYOTA UPDATED COOLER LINES TO ALL METAL. REMOVED AND INSTALLED NEW LINES. RECHECKED OK  
(RWINTERS) TEST DROVE AND CLEARED CAM SENSORS CODES POO24 AND PO500 VSS.

### **06-40 - INSPECT ENGINE / MOTOR SYSTEMS**

(RWINTERS) CHECKED OUT FOUND OIL COOLER LINE LEAKING, VAN IS LOW ON OIL (1QT IN PAN)  
(RWINTERS) FILTER HAD FINE METAL IN IT, NO LARGE FLAKES OR PEELS.

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

The following parts are included with the standard job:

Part No : 04152-YZZA1

Qty : 1

Description : FILTER-OIL

Manufacturer :

Part No : 5W20FS

Qty : 6

Description : HAVOLINE 5W20 FULL SYN. OIL QT

Manufacturer :

(LISAPATE) PM BY MS-RECHECKED OK



# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 2289

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 11/03/2008 15:04:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/04/2008 07:10:13	<b>METER 1 - M:</b> 30225 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 11/04/2008 07:10:14	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA 2007 Toyota Sienna		<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.90	\$0.00	\$68.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	N	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.61** **35.08** **50.90** **0.00** **85.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11088474	11/03/2008 16:18:36	11/03/2008 16:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/03/2008 16:00:00	11/03/2008 16:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>35.08</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	4883	FILTER-CABIN	24.81	1	\$24.81
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.37	1	\$7.37
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	208	\$18.72
					<b>PARTS</b>	<b>50.90</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 2289

---

**Work Order Notes**

(LPATE) PM REPLACE CABIN FILTER

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 57047 FILTER-OIL Qty 1 Cost 0

Part 10W-30 OIL BULK Qty 192 Cost 0

(LPATE) PM BY JE

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LPATE) REPLACED CABIN FILTER

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 24638

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 10/14/2016 09:14:04	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/28/2016 08:41:52	<b>METER 1 - M:</b> 97425 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/28/2016 08:41:53	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.80	\$103.60	\$76.50	\$0.00	\$180.10
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.10	\$63.44	\$0.00	\$0.00	\$63.44
17-17-018	RECALL SPARE TIRE HOIST	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$23.00	\$1.65	\$0.00	\$24.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	18.22	\$1,047.87	\$45.15	\$0.00	\$1,093.02
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$161.53	\$161.53

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>21.53</b>	<b>1,237.91</b>	<b>123.30</b>	<b>161.53</b>	<b>1,522.74</b>
---------------------	--------------------------	--------------	-----------------	---------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-17-018	RECALL SPARE TIRE HOIST	11076422	TOCS736485	0036047	\$0.00
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	218336	0036046	\$161.53
<b>COMML</b>					<b>161.53</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11213180	10/26/2016 07:00:00	10/26/2016 07:24:00	0.40	\$23.00
03-32-002	REPLACE NEW BATTERY	11170580	10/25/2016 14:30:00	10/25/2016 15:55:30	1.43	\$81.94
03-32-002	REPLACE NEW BATTERY	11170580	10/25/2016 13:52:24	10/25/2016 14:15:00	0.38	\$21.66
66-PM-PMA	PERFORM OIL CHANGE	11170580	10/17/2016 13:29:03	10/18/2016 07:42:29	18.22	\$1,047.87
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	10/17/2016 08:54:09	10/17/2016 10:00:21	1.10	\$63.44
<b>LABOR</b>					<b>1237.91</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	76.50	1	\$76.50
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.15	208	\$31.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	7.02	1	\$7.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.36	3	\$1.08

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21097	TPMS NICKEL VALVE CORE	0.29	2	\$0.57
					<b>PARTS</b>	<b>123.30</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 24638

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) BATTERY FAILED, REPLACED BATTERY

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LISAPATE) TAKEN TO TOYOTA BY EK

### **17-17-018 - RECALL SPARE TIRE HOIST**

(LISAPATE) TOYOTA COMPLETED RECALL FOR EXCESSIVE SPARE TIRE CORROSION. REPLACED SPARE TIRE CARRIER KIT

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) MOUNTED AND BALANCED 2 NEW TIRES

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM BY AB-REPLACED AIR FILTER-USED 3 INCHES OF 1/4 IN RUBBER HOSE TO REPAIR AIR INTAKE LINE

### **PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES**

(LISAPATE) PURCHASED 2 NEW TIRES FROM FIRESTONE. PD BY CC

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 2528

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 12/02/2008 10:19:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/03/2008 06:47:10	<b>METER 1 - M:</b> 34752 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 12/03/2008 06:47:12	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNT0YSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.42	\$0.00	\$48.25

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **30.42**      **0.00**      **48.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11128904	12/02/2008 11:00:00	12/02/2008 11:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	192	\$23.04
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.38	1	\$7.38
					<b>PARTS</b>	<b>30.42</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 2528

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(LPATE) PM BY CM

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 25923

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 03/06/2017 15:34:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/10/2017 10:41:03	<b>METER 1 - M:</b> 98334 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/10/2017 10:41:05	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna		<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-02-101	WARRANTY DASH ASSY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.20	\$69.06	\$0.00	\$0.00	\$69.06

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.20**      **69.06**      **0.00**      **0.00**      **69.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-02-101	WARRANTY DASH ASSY	11076422	TOCS753722	0037730	\$0.00
					<b>COMML</b> <b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	10208562	03/07/2017 08:09:17	03/07/2017 09:21:21	1.20	\$69.06
					<b>LABOR</b> <b>69.06</b>	



# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 25923

---

**Work Order Notes**

(LISAPATE) TOYOTA ORDERED DASH PAD FOR VAN DUE TO POOR MATERIAL DASH PAD WAS STICKY

---

**Job Notes**

**15-02-101 - WARRANTY DASH ASSY**

(LISAPATE) TUSCALOOSA TOYOTA REPLACED DASH PAD

**16-02 - TRANSPORT CAB & SHEET METAL**

(LISAPATE) TAKEN TO TOYOTS BY EK

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 2824

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 01/29/2009 08:04:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/30/2009 13:27:11	<b>METER 1 - M:</b> 35753 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 01/30/2009 13:27:12	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$450.47	\$450.47
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **1.00**      **57.50**      **0.00**      **450.47**      **507.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	107408	0003462	\$450.47
					<b>COMML</b> <b>450.47</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11088858	01/30/2009 09:00:00	01/30/2009 10:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>57.50</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 2824

---

**Work Order Notes**

(LPATE) LEFT FRONT TIRE WAS LOW--CHECKED TIRES WERE AT TREAD BAR SENT TO HAVE NEW TIRES PUT ON AND ALIGNED

---

**Job Notes**

**03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED P0019397

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO FIRESTONE BY RSW

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 3030

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 03/05/2009 15:03:00	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/09/2009 10:12:56	<b>METER 1 - M:</b> 38918 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 03/09/2009 10:12:57	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNT0YSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.23	\$0.00	\$47.06
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	0.50	\$28.75	\$24.84	\$0.00	\$53.59

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.81**      **46.58**      **54.07**      **0.00**      **100.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11088474	03/05/2009 16:18:36	03/05/2009 16:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11088474	03/05/2009 16:00:00	03/05/2009 16:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>46.58</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM TRANSMISSION SERVICE	ATF T-IV	TOYOTA ATF T-IV	6.21	4	\$24.84
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
					<b>PARTS</b>	<b>54.07</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 3030

---

## Work Order Notes

(AJONES) PM-TRANS SVC

## Job Notes

### **66-PM-PMA - PERFORM OIL CHANGE**

(AJONES) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(AJONES) PM BY JE

### **66-PM-PMT - PERFORM TRANSMISSION SERVICE**

(AJONES) DRAINED DIRTY FLUID AND REFILLED WITH NEW FLUID--DID NOT CHANGE FILTER PER TOYOTA METAL DOES NOT NEED TO BE CHANGED

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 3083

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 03/13/2009 09:46:45	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/13/2009 10:03:00	<b>METER 1 - M:</b> 39099 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 03/13/2009 10:03:02	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-046	REPLACE NEW KEY BLANK(S)	DON	O	N	GARAGE	0.00	\$0.00	\$5.97	\$0.00	\$5.97

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **5.97**      **0.00**      **5.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-046	REPLACE NEW KEY BLANK(S)	MIS KEY	KEY BLANK	2.99	2	\$5.97
					<b>PARTS</b>	<b>5.97</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 3083

---

**Work Order Notes**

(RWINTERS) 2 EXTRA KEYS CUT

---

**Job Notes**

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) RANDALL RCVD 2 KEY BLANKS FROM NPORT AUTO AND WE CUT TO FIT VEHICLE

---

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 31373

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 11/01/2018 15:22:34	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/19/2018 06:44:01	<b>METER 1 - M:</b> 104726 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/19/2018 06:44:02	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA 2007 Toyota Sienna		<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$145.00	\$187.56	\$0.00	\$332.56
03-40-415	REPLACE NEW OIL COOLER LINES	DON	O	N	GARAGE	1.30	\$94.25	\$89.35	\$0.00	\$183.60
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$38.36	\$0.00	\$56.49
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
06-40-433	INSPECT OIL LEAK	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.17	\$85.09	\$0.00	\$0.00	\$85.09
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	DON	O	N	GARAGE	1.00	\$72.50	\$13.42	\$0.00	\$85.92
24-15-022	REPAIR RACK & PINION	DON	O	N	GARAGE	4.51	\$327.22	\$63.54	\$0.00	\$390.76
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$58.00	\$15.93	\$0.00	\$73.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$48.08	\$0.00	\$70.56
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$331.25	\$331.25

**JOB COUNT: 11** **WORK ORDER TOTAL: 12.35 895.17 456.24 331.25 1,682.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	250837	0045734	\$331.25
				<b>COMML</b>	<b>331.25</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	11/13/2018 07:00:00	11/13/2018 07:18:36	0.31	\$22.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	11/13/2018 09:30:00	11/13/2018 10:18:00	0.80	\$58.00
24-15-022	REPAIR RACK & PINION	11758845	11/13/2018 07:00:00	11/13/2018 08:24:00	1.40	\$101.50
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	11310047	11/13/2018 07:00:00	11/13/2018 08:00:00	1.00	\$72.50
06-40-433	INSPECT OIL LEAK	11310047	11/13/2018 07:00:00	11/13/2018 07:30:00	0.50	\$36.25
06-13	INSPECT BRAKES	11758845	11/13/2018 07:00:00	11/13/2018 07:30:00	0.50	\$36.25
03-51-038	REPLACE NEW WIPER BLADES	11915538	11/13/2018 07:00:00	11/13/2018 07:15:00	0.25	\$18.13



# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-40-415	REPLACE NEW OIL COOLER LINES	11310047	11/13/2018 07:00:00	11/13/2018 08:18:00	1.30	\$94.25
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11758845	11/13/2018 07:30:00	11/13/2018 09:30:00	2.00	\$145.00
24-15-022	REPAIR RACK & PINION	11310047	11/10/2018 10:04:13	11/10/2018 13:11:01	3.11	\$225.72
09-15	ALIGN STEERING	11310047	11/08/2018 07:59:15	11/08/2018 09:09:40	1.17	\$85.09
					<b>LABOR</b>	<b>895.17</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-16-032	INSTALL ADJUSTABLE CAM BUSHINGS	K72642	REAR WHEEL WALIGNMENT SHIM	13.42	1	\$13.42
24-15-022	REPAIR RACK & PINION	9046719021	CLAMP, RACK AND PINION BOOT	2.06	2	\$4.11
24-15-022	REPAIR RACK & PINION	9008046340	CLAMP, RACK AND PINION BOOT	8.37	2	\$16.74
24-15-022	REPAIR RACK & PINION	4553508010	BOOT, STEERING RACK	21.35	2	\$42.69
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	12.78	1	\$12.78
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-40-415	REPLACE NEW OIL COOLER LINES	4 CLAMP	HOSE CLAMPS	0.53	1	\$0.53
03-40-415	REPLACE NEW OIL COOLER LINES	1570731030	PIPE SUB ASSY OIL COOLER	69.54	1	\$69.54
03-40-415	REPLACE NEW OIL COOLER LINES	9043016016	GASKET OIL COOLER HOSE	1.80	1	\$1.80
03-40-415	REPLACE NEW OIL COOLER LINES	9043016012	GASKET OIL COOLER HOSE	1.65	1	\$1.65
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB980077R	BRAKE ROTOR FRONT	52.17	2	\$104.34
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEH906AH	FRONT PADS	83.22	1	\$83.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	6.31	1	\$6.31
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	1	\$3.17
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	(1)	(\$3.17)
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	2	\$6.33
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	(2)	(\$6.33)
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	4	\$12.66
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.04	7	\$35.28
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.39	7	\$2.73
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	(4)	(\$12.66)
03-40-415	REPLACE NEW OIL COOLER LINES	C111	RED BRAKE CLEANER	3.17	5	\$15.83
					<b>PARTS</b>	<b>456.24</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 31373

---

**Work Order Notes**

(EKIMBREL) PM; inspect oil leak; check tires and brakes

---

**Job Notes**

# Work Order Charge Detail

## 03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) Replaced front pads and rotors. test drove ok

## 03-40-415 - REPLACE NEW OIL COOLER LINES

(LISAPATE) Replaced oil line running to the right head. Rechecked ok

## 03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

## 06-13 - INSPECT BRAKES

(LISAPATE) IF found front brakes worn. rear brakes look ok

## 06-17-005 - INSPECT TIRE - SOLID

## 06-40-433 - INSPECT OIL LEAK

(LISAPATE) Used brake clean to clean off excessive oil. Found oil cooler line leaking

## 09-15 - ALIGN STEERING

(LISAPATE) EH performed alignment. Relearned tire positions

## 14-16-032 - INSTALL ADJUSTABLE CAM BUSHINGS

(LISAPATE) While doing the alignment installed a shim behind left rear backing plate.

## 24-15-022 - REPAIR RACK & PINION

(LISAPATE) Replaced both rack and pinion boots and 4 clamps. Rechecked ok

## 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires.

## 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM by CS

Coolant -24'

## PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Purchased 4 tires from Firestone. Pd by cc

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 32997

USING DEPT NO:	505161	OPENED DATE:	05/24/2019 13:47:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/29/2019 07:29:39	METER 1 - M:	106659	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/29/2019 07:29:41	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$113.55	\$0.00	\$113.55

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 113.55 0.00 113.55

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					<b>PARTS</b>	<b>113.55</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 32997

---

**Work Order Notes**

(LISAPATE) Dept removed their own battery and brought to the shop to be swapped out.

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Swapped 24F battery with driver

---

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 3375

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 05/08/2009 07:12:22	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/08/2009 11:29:19	<b>METER 1 - M:</b> 41053 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> UNSCHEDULED	<b>CLOSED DATE:</b> 05/08/2009 11:29:20	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNT0YSIENNA 2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$47.07	\$0.00	\$61.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$17.52	\$29.23	\$0.00	\$46.75

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.55** **31.90** **76.30** **0.00** **108.20**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11088474	05/08/2009 07:45:28	05/08/2009 08:00:28	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11088474	05/08/2009 07:27:11	05/08/2009 07:45:28	0.30	\$17.52
					<b>LABOR</b>	<b>31.90</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	12.21	1	\$12.21
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	12.96	1	\$12.96
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	21.90	1	\$21.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
					<b>PARTS</b>	<b>76.30</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 3375

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS

---

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(LPATE) PM BY JE

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA WORK ORDER NO: 339

USING DEPT NO:	505161	OPENED DATE:	11/02/2007 08:58:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2007 09:02:54	METER 1 - M:	8365	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/02/2007 09:02:58	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$25.14	\$0.00	\$39.09

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 13.95 25.14 0.00 39.09

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/02/2007 09:00:00	11/02/2007 09:18:36	0.31	\$13.95
					<b>LABOR</b>	<b>13.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	10.74	1	\$10.74
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	192	\$14.40
					<b>PARTS</b>	<b>25.14</b>



# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 339

---

**Work Order Notes**

(RWINTERS) NEEDS PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS) PM BY JE.

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 34540

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 10/22/2019 09:27:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/30/2019 07:48:50	<b>METER 1 - M:</b> 108875 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/30/2019 07:48:52	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.01	\$0.52	\$25.58	\$0.00	\$26.10
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$8.82	\$0.00	\$0.00	\$8.82
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.02	\$74.05	\$0.00	\$0.00	\$74.05
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.67	\$48.23	\$229.77	\$0.00	\$278.00
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.74	\$53.95	\$0.00	\$0.00	\$53.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.26	\$91.21	\$53.79	\$0.00	\$145.00

**JOB COUNT: 6**      **WORK ORDER TOTAL:**      **3.82**      **276.78**      **309.14**      **0.00**      **585.92**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	10/24/2019 14:30:00	10/24/2019 15:31:17	1.02	\$74.05
09-15	ALIGN STEERING	11310047	10/24/2019 14:27:00	10/24/2019 14:27:00	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/23/2019 14:30:00	10/23/2019 14:38:31	0.14	\$10.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/23/2019 13:43:36	10/23/2019 14:15:00	0.52	\$37.94
06-15	INSPECT STEERING	12052187	10/23/2019 13:36:18	10/23/2019 13:43:36	0.12	\$8.82
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/23/2019 07:33:38	10/23/2019 07:34:04	0.01	\$0.52
66-79-003	PERFORM SAFETY INSPECTION	12052187	10/23/2019 07:03:45	10/23/2019 07:33:38	0.50	\$36.11
66-79-003	PERFORM SAFETY INSPECTION	12052187	10/22/2019 14:41:45	10/22/2019 14:56:31	0.25	\$17.84
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/22/2019 14:30:00	10/22/2019 14:40:31	0.18	\$12.71
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/22/2019 13:10:02	10/22/2019 14:15:00	1.08	\$78.50
					<b>LABOR</b>	<b>276.78</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	014859	TIRE 215/65R16 FS CHAMP FUEL F	110.69	2	\$221.37
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	4	\$1.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.84	7	\$40.85
					<b>PARTS</b>	<b>309.14</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 34540

---

## Work Order Notes

(LISAPATE) PM-Do SI

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) Replaced wipers

### **06-15 - INSPECT STEERING**

(LISAPATE) JW/SH Checked front end no issues found at this time

### **09-15 - ALIGN STEERING**

(LISAPATE) EH Performed alignment

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Mount and balanced 2 new tires installed on the rear

### **66-79-003 - PERFORM SAFETY INSPECTION**

(LISAPATE) Safety Inspection completed. See attached

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM by EK/Jw

Coolant -35'

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 35104

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 12/09/2019 09:14:43	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/10/2019 07:51:59	<b>METER 1 - M:</b> 109340 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/10/2019 07:52:01	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNT0YSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.68	\$49.24	\$7.70	\$0.00	\$56.94

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.68**      **49.24**      **7.70**      **0.00**      **56.94**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	12/09/2019 09:17:31	12/09/2019 09:58:16	0.68	\$49.24
					<b>LABOR</b>	<b>49.24</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.50	1	\$3.50
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	2	\$0.90
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.30	1	\$3.30
					<b>PARTS</b>	<b>7.70</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 35104

---

## Work Order Notes

(LISAPATE) LR tire has a nail in it

---

## Job Notes

**66-17-030 - PERFORM TIRE PATCH**

(LISAPATE) Removed and patched LR tire from the inside. Rechecked ok

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 37510

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 09/03/2020 14:29:24	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/04/2020 14:15:42	<b>METER 1 - M:</b> 111312 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/09/2020 10:49:42	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-21-005	REPAIR CV AXLE BOOT	DON	O	N	GARAGE	0.80	\$58.00	\$0.00	\$0.00	\$58.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.75	\$54.64	\$37.58	\$0.00	\$92.22
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.30	\$21.75	\$8.75	\$0.00	\$30.50

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.85</b>	<b>134.39</b>	<b>46.33</b>	<b>0.00</b>	<b>180.72</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-21-005	REPAIR CV AXLE BOOT	11213180	09/04/2020 07:00:00	09/04/2020 07:30:00	(0.50)	(\$36.25)
24-21-005	REPAIR CV AXLE BOOT	11213180	09/04/2020 07:00:00	09/04/2020 07:30:00	0.50	\$36.25
24-21-005	REPAIR CV AXLE BOOT	11213180	09/04/2020 07:00:00	09/04/2020 07:48:00	0.80	\$58.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/04/2020 07:10:11	09/04/2020 07:16:32	0.11	\$7.67
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	09/04/2020 07:09:42	09/04/2020 07:09:57	0.00	(\$0.30)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	09/04/2020 07:09:42	09/04/2020 07:09:57	0.00	\$0.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	09/04/2020 07:09:42	09/04/2020 07:27:42	0.30	\$21.75
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/03/2020 15:11:31	09/03/2020 15:50:23	0.65	\$46.96
					<b>LABOR</b>	<b>134.38</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.75	1	\$8.75
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					<b>PARTS</b>	<b>46.33</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 37510

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### **24-21-005 - REPAIR CV AXLE BOOT**

(LISAPATE) Found CV axle boot clamp to be loose letting grease sling from axle. Removed clamp and tightened clamp, cleaned area and rechecked ok at this time.

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Found grease slung all over passenger side axle area. Cleaned off to be further inspected. Coolant -34 JAW,SH/JAW

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(JWRIGHT) Replaced filter

---



# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 39208

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 02/25/2021 10:42:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/26/2021 07:19:02	<b>METER 1 - M:</b> 112049 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/01/2021 15:27:12	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.43	\$0.00	\$0.00	\$51.43

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.44**      **51.43**      **0.00**      **0.00**      **51.43**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2021 13:00:00	02/25/2021 13:26:09	0.44	\$51.43
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2021 12:56:35	02/25/2021 12:56:35	0.00	\$0.00
					<b>LABOR</b>	<b>51.43</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 39208

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has only been 737 miles. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW,SH  
MILEAGE-112049

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 4010

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 08/03/2009 08:13:20	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/03/2009 08:17:31	<b>METER 1 - M:</b> 48383 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/04/2009 08:36:23	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.23	\$0.00	\$47.06

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **29.23**      **0.00**      **47.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	08/03/2009 17:00:00	08/03/2009 17:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
					<b>PARTS</b>	<b>29.23</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 4010

---

**Work Order Notes**

(LPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0

Part 57047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 40390

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 07/08/2021 13:06:46	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/16/2021 09:48:11	<b>METER 1 - M:</b> 112686 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/19/2021 13:36:47	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.52	\$24.09	\$0.00	\$32.61
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.16	\$18.95	\$0.00	\$0.00	\$18.95
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.28	\$33.53	\$0.00	\$0.00	\$33.53
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.68	\$79.98	\$231.39	\$0.00	\$311.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.89	\$105.02	\$40.05	\$0.00	\$145.07

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>2.08</b>	<b>246.00</b>	<b>295.53</b>	<b>0.00</b>	<b>541.53</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	07/15/2021 09:30:00	07/15/2021 09:47:03	0.28	\$33.53
66-17-013	PERFORM ALIGNMENT	11310047	07/15/2021 09:28:33	07/15/2021 09:28:33	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	07/14/2021 13:03:21	07/14/2021 13:44:01	0.68	\$79.98
06-15	INSPECT STEERING	11074414	07/08/2021 15:10:46	07/08/2021 15:20:24	0.16	\$18.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/08/2021 14:47:15	07/08/2021 15:07:48	0.34	\$40.42
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/08/2021 14:33:51	07/08/2021 15:06:42	0.55	\$64.61
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/08/2021 14:37:08	07/08/2021 14:41:28	0.07	\$8.52

**LABOR      246.01**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	014859	TIRE 215/65R16 FS CHAMP FUEL F	111.38	2	\$222.75
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	(7)	(\$31.08)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	4	\$2.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	6.92	1	\$6.92
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.84	1	\$9.84
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.33	1	\$7.33

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
					<b>PARTS</b>	<b>295.53</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 40390

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected steering and brakes found no issues. SH

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Adjusted front toe. The right rear camber measurement is in the red, but this particular measurement is within spec. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 2 tires. Put the new tires on the front. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 112686 Completed PM bottomside, Scott was topside. Completed checklist. SH/AMG

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 41530

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 11/05/2021 12:46:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/19/2021 14:11:38	<b>METER 1 - M:</b> 113464 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/22/2021 08:18:53	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-21-002	REPLACE NEW CV AXLES/SEALS	DON	O	N	GARAGE	3.13	\$368.98	\$265.57	\$0.00	\$634.55
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.05	\$6.13	\$113.55	\$0.00	\$119.68
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.05	\$6.33	\$17.89	\$0.00	\$24.22
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.34	\$40.51	\$0.00	\$0.00	\$40.51
35-00	DIAGNOSE COMPLETE VEHICLE	DON	O	N	GARAGE	0.26	\$30.71	\$0.00	\$0.00	\$30.71
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.39	\$45.73	\$0.00	\$0.00	\$45.73
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.55	\$183.39	\$0.00	\$0.00	\$183.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
CU-13-001	CUT FRONT BRAKES & ROTORS	DON	O	N	GARAGE	0.74	\$87.58	\$0.00	\$0.00	\$87.58

**JOB COUNT: 9**      **WORK ORDER TOTAL:**      **6.52**      **769.36**      **397.01**      **2.00**      **1,168.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11310047	11/16/2021 10:18:14	11/16/2021 10:21:21	0.05	\$6.13
03-21-002	REPLACE NEW CV AXLES/SEALS	11310047	11/16/2021 09:30:00	11/16/2021 10:18:14	0.80	\$94.86
03-21-002	REPLACE NEW CV AXLES/SEALS	11310047	11/16/2021 09:22:33	11/16/2021 09:22:33	0.00	\$0.00
03-21-002	REPLACE NEW CV AXLES/SEALS	11310047	11/16/2021 07:49:24	11/16/2021 08:49:38	1.00	\$118.46
03-21-002	REPLACE NEW CV AXLES/SEALS	11310047	11/12/2021 13:02:11	11/12/2021 14:15:38	1.22	\$144.45
03-21-002	REPLACE NEW CV AXLES/SEALS	11310047	11/12/2021 11:46:19	11/12/2021 11:52:01	0.10	\$11.21
66-13-130	PERFORM Burnish Brakes	11310047	11/18/2021 07:42:37	11/18/2021 08:05:52	0.39	\$45.73
06-32-002	INSPECT BATTERY	11310047	11/16/2021 13:04:56	11/16/2021 13:25:32	0.34	\$40.51
35-00	DIAGNOSE COMPLETE VEHICLE	11310047	11/16/2021 13:00:00	11/16/2021 13:04:56	0.08	\$9.70



# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-00	DIAGNOSE COMPLETE VEHICLE	11310047	11/16/2021 11:49:19	11/16/2021 12:00:00	0.18	\$21.01
03-51-038	REPLACE NEW WIPER BLADES	11310047	11/16/2021 11:46:06	11/16/2021 11:49:19	0.05	\$6.33
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	11/16/2021 10:38:58	11/16/2021 11:23:30	0.74	\$87.58
66-79-003	PERFORM SAFETY INSPECTION	11310047	11/08/2021 07:24:33	11/08/2021 08:57:48	1.55	\$183.39
					<b>LABOR</b>	<b>769.36</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-21-002	REPLACE NEW CV AXLES/SEALS	WONTO8184	CV AXLE	124.50	1	\$124.50
03-21-002	REPLACE NEW CV AXLES/SEALS	WONTO8183	NEW CV AXLE ASSY LH	123.44	1	\$123.44
03-21-002	REPLACE NEW CV AXLES/SEALS	C111	RED BRAKE CLEANER	5.63	2	\$11.25
03-21-002	REPLACE NEW CV AXLES/SEALS	C111	RED BRAKE CLEANER	5.63	(1)	(\$5.63)
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
03-21-002	REPLACE NEW CV AXLES/SEALS	VV324	TRANS FLUID QT	6.38	1	\$6.38
03-21-002	REPLACE NEW CV AXLES/SEALS	C111	RED BRAKE CLEANER	5.63	1	\$5.63
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.58	1	\$7.58
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
					<b>PARTS</b>	<b>397.01</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 41530

---

## Work Order Notes

(EHOWELL) inspect battery \check engine light on

---

## Job Notes

### **03-21-002 - REPLACE NEW CV AXLES/SEALS**

(EHOWELL) Replaced both CV axles because they were leaking grease. Topped off transmission fluid after repair. EH

### **03-32-002 - REPLACE NEW BATTERY**

(EHOWELL) Replaced battery. EH

### **03-51-038 - REPLACE NEW WIPER BLADES**

(EHOWELL) Replaced wipers. EH

### **06-32-002 - INSPECT BATTERY**

(EHOWELL) Battery bad. EH

### **35-00 - DIAGNOSE COMPLETE VEHICLE**

(EHOWELL) The check engine light was not on. Low tire light was on. Pressures were low. Topped off air pressures. The low tire light is no longer illuminated. EH

### **66-13-130 - PERFORM Burnish Brakes**

(EHOWELL) Made hard stops after brake job was performed. EH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(EHOWELL) Performed Safety Inspection. EH

### **CH-SP - CHARGE Shop Supplies**

### **CU-13-001 - CUT FRONT BRAKES & ROTORS**

(EHOWELL) Resurfaced front brake rotors using the on car brake lathe. Did not replace pads. Performed a road test after repairs and made hard stops. EH

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 42039

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 01/11/2022 08:49:16	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/11/2022 15:21:05	<b>METER 1 - M:</b> 114033 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/12/2022 12:48:27	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$25.49	\$0.00	\$43.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.48**      **56.64**      **25.49**      **2.00**      **84.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/11/2022 12:31:29	01/11/2022 12:51:17	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/11/2022 12:31:29	01/11/2022 12:31:29	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/11/2022 12:31:29	01/11/2022 12:31:29	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/11/2022 12:28:21	01/11/2022 12:37:21	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/11/2022 12:28:21	01/11/2022 12:28:21	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/11/2022 12:28:21	01/11/2022 12:28:21	0.00	\$0.00
<b>LABOR</b>					<b>56.64</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.59	1	\$7.59
<b>PARTS</b>					<b>25.49</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 42039

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has been 1347 miles. Checked fluids and tires. Coolant -34°. JAW  
MILEAGE-114033

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 43551

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 06/07/2022 13:32:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/08/2022 15:37:03	<b>METER 1 - M:</b> 115387 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/09/2022 10:28:25	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.64	\$25.81	\$0.00	\$29.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.91	\$38.97	\$0.00	\$83.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.41</b>	<b>48.55</b>	<b>64.78</b>	<b>2.00</b>	<b>115.33</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	06/08/2022 07:34:29	06/08/2022 07:36:20	0.03	\$3.64
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/08/2022 07:11:27	06/08/2022 07:34:17	0.38	\$44.91
<b>LABOR</b>					<b>48.55</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.22	1	\$5.22
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.40	1	\$10.40
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	6	\$33.75
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.82	1	\$7.82
<b>PARTS</b>					<b>64.78</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 43551

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) replaced wipers

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW  
MILEAGE-115387

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 4391

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 09/28/2009 07:34:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/28/2009 14:58:21	<b>METER 1 - M:</b> 52374 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/28/2009 14:58:23	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$47.07	\$0.00	\$61.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$51.08	\$0.00	\$68.91

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.56**      **32.21**      **98.15**      **0.00**      **130.36**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11268671	09/28/2009 16:18:36	09/28/2009 16:36:36	(0.30)	(\$17.25)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11268671	09/28/2009 16:18:36	09/28/2009 16:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11268671	09/28/2009 16:00:00	09/28/2009 16:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11268671	09/28/2009 16:18:36	09/28/2009 16:33:36	0.25	\$14.38
					<b>LABOR</b>	<b>32.21</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	12.96	1	\$12.96
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	21.90	1	\$21.90
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	16.81	1	\$16.81
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	12.21	1	\$12.21
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	16.81	(1)	(\$16.81)
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	16.81	1	\$16.81
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	20.79	1	\$20.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	20.79	(1)	(\$20.79)
					<b>PARTS</b>	<b>98.15</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 4391

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS  
(LPATE) REPLACED CABIN FILTER

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED ALL 3 WIPERS

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE) The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 57047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(LPATE) PM BY IF-REPLACED AIR FILTER

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LPATE) REPLACED CABIN FILTER  
(LPATE) CANCELLED JOB ADDED ON WRONG WO

---



# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 45163

<b>USING DEPT NO:</b>	505161	<b>OPENED DATE:</b>	11/03/2022 09:30:50	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	12/06/2022 07:47:44	<b>METER 1 - M:</b>	117941	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	12/06/2022 10:27:07	<b>IN-SERVICE DATE:</b>	05/11/2007	
<b>TECH SPEC NO:</b>	07VNTTOYSIENNA	2007 Toyota Sienna		<b>UNIT SERIAL NO:</b>	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15-027	INSPECT GEAR SHIFT CABLE ASSY	DON	O	N	GARAGE	0.33	\$39.33	\$0.00	\$0.00	\$39.33
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.34	\$158.61	\$0.00	\$0.00	\$158.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.50	\$58.59	\$0.00	\$98.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 4**      **WORK ORDER TOTAL:**      **2.01**      **237.44**      **58.59**      **5.00**      **301.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/05/2022 10:35:40	12/05/2022 10:37:14	0.03	\$3.08
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/05/2022 09:42:06	12/05/2022 10:00:37	0.31	\$36.42
66-79-003	PERFORM SAFETY INSPECTION	11310047	11/03/2022 10:27:25	11/03/2022 11:48:04	1.34	\$158.61
06-15-027	INSPECT GEAR SHIFT CABLE ASSY	11310047	11/03/2022 10:02:39	11/03/2022 10:22:39	0.33	\$39.33
					<b>LABOR</b> <b>237.44</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	13.29	1	\$13.29
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
					<b>PARTS</b> <b>58.59</b>	

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 45163

---

## Work Order Notes

(LISAPATE) PM-Do annual SI-Van is stuck in reverse

---

## Job Notes

### **06-15-027 - INSPECT GEAR SHIFT CABLE ASSY**

(EHOWELL) Manually shifted the transmission into gear and drove the vehicle in the shop. The shift cable was broken where it attaches to the shifter. The shift cable was not available. Drilled a hole into the shifter and ran a piece of mechanic's wire through the shifter to hold the cable on. Verified operation after repair. EH 1.0 HR

### **66-79-003 - PERFORM SAFETY INSPECTION**

(EHOWELL) Inspected vehicle. The vehicle is leaking oil. Uncertain where the oil is coming from at this time. The vehicle will be sprayed off with brake cleaner. EH

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,CW/GC  
MILEAGE-117941

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 46885

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 04/27/2023 13:51:28	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/02/2023 14:56:15	<b>METER 1 - M:</b> 119783 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/04/2023 12:12:03	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.11	\$26.93	\$0.00	\$32.04
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.29	\$34.15	\$0.00	\$0.00	\$34.15
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.29	\$152.48	\$572.55	\$0.00	\$725.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.82	\$0.00	\$0.00	\$16.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$46.05	\$0.00	\$0.00	\$46.05

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>2.16</b>	<b>254.61</b>	<b>599.48</b>	<b>5.00</b>	<b>859.09</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12052187	05/02/2023 10:01:55	05/02/2023 10:25:20	0.39	\$46.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	05/02/2023 09:30:00	05/02/2023 10:01:44	0.53	\$62.41
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	05/02/2023 08:29:12	05/02/2023 09:15:00	0.76	\$90.07
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/28/2023 11:28:55	04/28/2023 11:31:31	0.04	\$5.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2023 11:00:28	04/28/2023 11:09:01	0.14	\$16.82
06-15	INSPECT STEERING	11074414	04/28/2023 11:33:23	04/28/2023 11:50:45	0.29	\$34.15
					<b>LABOR</b>	<b>254.61</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	18477	BFG ADVANTAGW 216\65R18	135.84	4	\$543.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	18477	BFG ADVANTAGW 216\65R18	131.34	(4)	(\$525.36)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.23	2	\$2.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.01	2	\$2.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.75	2	\$1.50

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.66	3	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.31	4	\$21.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	18477	BFG ADVANTAGW 216\65R18	131.34	4	\$525.36
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.03	1	\$11.03
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	8.13	1	\$8.13
					<b>PARTS</b>	<b>599.48</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 46885

---

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected the steering found no issues at this time. SH

### **66-17-013 - PERFORM ALIGNMENT**

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced all 4 tires. Torqued lug nuts to spec. JAW

(LISAPATE) Unit will come back for alignment

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 1842 miles since the last PM. Checked fluids battery and updated the oil change sticker. Vehicle needs 4 tires due to excessive shoulder wear. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(JWRIGHT) Washed unit

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 47072

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 05/16/2023 10:17:01	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/21/2023 15:02:22	<b>METER 1 - M:</b> 119895 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/21/2023 15:03:17	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.15	\$135.70	\$80.56	\$0.00	\$216.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **1.65**      **194.70**      **80.56**      **5.00**      **280.26**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-00	ALIGN COMPLETE VEHICLE	12052187	06/09/2023 14:14:48	06/09/2023 14:49:21	(0.58)	(\$67.95)
09-00	ALIGN COMPLETE VEHICLE	12052187	06/09/2023 14:14:48	06/09/2023 14:49:21	0.58	\$67.95
09-00	ALIGN COMPLETE VEHICLE	12052187	06/09/2023 10:11:03	06/09/2023 10:52:50	0.70	\$82.17
09-00	ALIGN COMPLETE VEHICLE	12052187	06/09/2023 10:11:03	06/09/2023 10:52:50	(0.70)	(\$82.17)
09-00	ALIGN COMPLETE VEHICLE	11310047	05/17/2023 07:38:11	05/17/2023 08:05:19	(0.45)	(\$53.36)
09-00	ALIGN COMPLETE VEHICLE	11310047	05/17/2023 07:38:11	05/17/2023 08:05:19	0.45	\$53.36
06-13	INSPECT BRAKES	12052187	06/20/2023 07:00:00	06/20/2023 07:30:00	0.50	\$59.00
66-17-013	PERFORM ALIGNMENT	11310047	06/16/2023 07:00:00	06/16/2023 07:27:00	0.45	\$53.10
66-17-013	PERFORM ALIGNMENT	12052187	06/16/2023 07:00:00	06/16/2023 07:42:00	0.70	\$82.60
<b>LABOR</b>					<b>194.70</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	71730	SHIM REAR #1	25.28	1	\$25.28
66-17-013	PERFORM ALIGNMENT	75970	SHIM	55.28	1	\$55.28
<b>PARTS</b>					<b>80.56</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 47072

---

## Work Order Notes

(EHANNAH) alignment

(LISAPATE) James requested check the brakes they are noisy

---

## Job Notes

### **06-13 - INSPECT BRAKES**

(EKIMBREL) jw drove vehicle and removed tires to look at brakes. Found no issues.

### **09-00 - ALIGN COMPLETE VEHICLE**

(JWRIGHT) Performed alignment. JAW

### **66-17-013 - PERFORM ALIGNMENT**

(EKIMBREL) Performed alignment. JAW

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 48377

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 10/02/2023 10:00:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/03/2023 15:40:49	<b>METER 1 - M:</b> 121781 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/04/2023 07:30:41	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.74	\$27.34	\$0.00	\$33.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.11	\$75.48	\$0.00	\$96.59
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$6.16	\$16.10	\$0.00	\$22.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.24	\$27.96	\$0.00	\$0.00	\$27.96

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.52</b>	<b>60.97</b>	<b>118.92</b>	<b>5.00</b>	<b>184.89</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	10/02/2023 13:41:29	10/02/2023 13:44:37	0.05	\$6.16
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/02/2023 13:38:34	10/02/2023 13:41:29	0.05	\$5.74
WA-00	WASH COMPLETE VEHICLE	12052187	10/02/2023 14:40:44	10/02/2023 14:54:57	0.24	\$27.96
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/02/2023 14:30:00	10/02/2023 14:40:44	0.18	\$21.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/02/2023 14:28:23	10/02/2023 14:28:23	0.00	\$0.00
<b>LABOR</b>					<b>60.97</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5479	CABIN FILTER	16.10	1	\$16.10
66-PM-PMA	PERFORM OIL CHANGE	PA5432F	AIR FILTER	19.52	1	\$19.52
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	12.35	1	\$12.35
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.24	1	\$11.24



# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	8.33	1	\$8.33
<b>PARTS</b>						<b>118.92</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 48377

---

**Work Order Notes**

(EHANNAH) pm- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced front and rear wiper blades. JAW

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed pm service. EH drained and refilled oil. FC checked tires and fluids. JAW replaced air filter and changed pm sticker. Coolant -34  
Mileage-12178

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GARAGE) Replaced cabin filter. JAW

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed unit. JAW

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 49951

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 02/27/2024 07:45:59	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/04/2024 09:12:54	<b>METER 1 - M:</b> 125180 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/04/2024 14:08:19	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$80.44	\$80.44
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.40	\$47.00	\$0.00	\$0.00	\$47.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.57	\$53.38	\$0.00	\$113.95
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.01	\$1.25	\$16.10	\$0.00	\$17.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.36	\$42.19	\$0.00	\$0.00	\$42.19

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>1.28</b>	<b>151.01</b>	<b>69.48</b>	<b>85.44</b>	<b>305.93</b>
---------------------	--------------------------	-------------	---------------	--------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-02-061	REPAIR WINDSHIELD	11078716	2116275		\$80.44
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>85.44</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	02/27/2024 11:37:16	02/27/2024 11:58:43	0.36	\$42.19
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	02/27/2024 11:12:54	02/27/2024 11:36:48	0.40	\$47.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	02/27/2024 11:11:56	02/27/2024 11:12:34	0.01	\$1.25
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/27/2024 10:40:41	02/27/2024 11:11:29	0.51	\$60.57
<b>LABOR</b>					<b>151.01</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5479	CABIN FILTER	16.10	1	\$16.10
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.67	1	\$7.67
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
<b>PARTS</b>					<b>69.48</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 49951

---

## Work Order Notes

(EHANNAH) pm- wash

---

## Job Notes

### **24-02-061 - REPAIR WINDSHIELD**

(LISAPATE) Glass Dr repaired ding in the windshield. PD by CC

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(FCONTRER) Rotate tires and check Brakes f 6 m r 5 m fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes fc

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced cabin filter fc

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(FCONTRER) Wash fc

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 50485

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 04/09/2024 10:03:37	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/10/2024 10:38:36	<b>METER 1 - M:</b> 125541 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/10/2024 12:24:57	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.48	\$56.90	\$0.00	\$0.00	\$56.90

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.48**      **56.90**      **0.00**      **5.00**      **61.90**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/09/2024 10:32:46	04/09/2024 11:01:42	0.48	\$56.90
					<b>LABOR</b>	<b>56.90</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 50485

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) prepare unit for disposal fc

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 5349

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 02/26/2010 15:13:58	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/01/2010 09:34:30	<b>METER 1 - M:</b> 57454 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/01/2010 09:34:31	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-02-017	ADJUST DOOR PANELS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.02	\$0.99	\$46.81	\$0.00	\$47.80
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.91	\$0.00	\$48.74

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.33</b>	<b>76.32</b>	<b>77.72</b>	<b>0.00</b>	<b>154.04</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
01-02-017	ADJUST DOOR PANELS	11268671	03/01/2010 07:19:18	03/01/2010 07:19:36	0.01	\$0.29
01-02-017	ADJUST DOOR PANELS	11268671	03/01/2010 07:19:18	03/01/2010 07:19:36	(0.01)	(\$0.29)
66-PM-PMA	PERFORM OIL CHANGE	11274660	03/01/2010 07:00:00	03/01/2010 07:18:36	0.31	\$17.83
01-02-017	ADJUST DOOR PANELS	11268671	03/01/2010 07:19:18	03/01/2010 08:19:18	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11274660	02/26/2010 15:55:33	02/26/2010 15:56:35	0.02	\$0.99
					<b>LABOR</b>	<b>76.32</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	224	\$23.52
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	21.90	1	\$21.90
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	13.14	1	\$13.14
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	11.77	1	\$11.77
					<b>PARTS</b>	<b>77.72</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 5349

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS-DOOR PANEL RATTLES BOTH SIDES REAR

---

## Job Notes

### **01-02-017 - ADJUST DOOR PANELS**

(RWINTERS) R AND R LEFT SLIDING DOOR-DOOR PANEL TIGHTEND PLASTIC COVER AND CABLE AND OUTSIDE FRONT BELTLINE TRIM.

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS FRONT AND REAR

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 57047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY TF

---



# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 5834

USING DEPT NO:	505161	OPENED DATE:	05/13/2010 11:39:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2010 06:59:56	METER 1 - M:	60519	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/19/2010 06:59:58	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$72.44	\$72.44
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.51	\$0.00	\$51.34

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.31</b>	<b>75.33</b>	<b>33.51</b>	<b>72.44</b>	<b>181.28</b>
---------------------	--------------------------	-------------	--------------	--------------	--------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost	
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	123713	0007789	\$72.44	
					<b>COMML</b>	<b>72.44</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11328035	05/13/2010 17:00:00	05/13/2010 17:18:36	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11328035	05/17/2010 07:00:00	05/17/2010 08:00:00	1.00	\$57.50
					<b>LABOR</b>	<b>75.33</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	6.63	1	\$6.63
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
					<b>PARTS</b>	<b>33.51</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 5834

---

**Work Order Notes**

(LPATE) PM-CHECK ALIGNMENT

---

**Job Notes**

**09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE ALIGNED TIRES P0028250

**16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO FIRESTONE BY ANGEL

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 57047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY TM

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 625

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 01/09/2008 14:43:17	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/11/2008 08:06:28	<b>METER 1 - M:</b> 11194 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/11/2008 08:06:29	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-17-016	TRANSPORT TIRE PRESSURE MONITO	DON	W	N	GARAGE	0.00	\$0.19	\$0.00	\$0.00	\$0.19
35-17-016	DIAGNOSE TIRE PRESSURE MONITOR.	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.21	\$25.14	\$0.00	\$25.35

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.01</b>	<b>0.40</b>	<b>25.14</b>	<b>0.00</b>	<b>25.54</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
35-17-016	DIAGNOSE TIRE PRESSURE MONITOR/SENSOR	11076422	TOCS326408	00738	\$0.00
<b>COMML</b>					<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17-016	TRANSPORT TIRE PRESSURE MONITOR/SENSOR	11128904	01/10/2008 09:48:12	01/10/2008 09:48:27	0.00	\$0.19
66-PM-PMA	PERFORM OIL CHANGE	11088474	01/10/2008 10:12:26	01/10/2008 10:12:43	0.00	\$0.21
<b>LABOR</b>					<b>0.40</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	192	\$14.40
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	10.74	1	\$10.74
<b>PARTS</b>					<b>25.14</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 625

---

**Work Order Notes**

(RWINTERS) PM AND TIRE MONITOR LIGHT IS ON AND WILL NOT RESET.

---

**Job Notes**

**16-17-016 - TRANSPORT TIRE PRESSURE MONITOR/SENSOR**

(RWINTERS) TAKEN TO TOYOTA

**35-17-016 - DIAGNOSE TIRE PRESSURE MONITOR/SENSOR**

(LOBRIEN) CUSTOMER STATES LOW TIRE PRESSURE LIGHT IS ON. INSPECTED TIRE PRESSURE ON ALL 5 TIRES. RECORD CURRENT PSI FOR EACH TIRE AND ADD AIR AS NECESSARY. ADJUSTED TIRE PRESSURE AND INSPECTED FOR ANY LEAKS. NO PROBLEMS FOUND.

**66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS) PM BY JE

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 6793

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 09/17/2010 11:44:44	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/17/2010 13:57:38	<b>METER 1 - M:</b> 65845 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/17/2010 13:57:41	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$66.90	\$0.00	\$95.65
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$40.98	\$0.00	\$55.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$27.96	\$0.00	\$45.79

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **1.06**      **60.96**      **135.84**      **0.00**      **196.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11268671	09/17/2010 16:00:00	09/17/2010 16:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11268671	09/17/2010 16:48:36	09/17/2010 17:03:36	0.25	\$14.38
03-32-002	REPLACE NEW BATTERY	11268671	09/17/2010 16:18:36	09/17/2010 16:48:36	0.50	\$28.75
					<b>LABOR</b>	<b>60.96</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	6.12	1	\$6.12
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	208	\$18.72
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	(208)	(\$18.72)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
03-32-002	REPLACE NEW BATTERY	24F-6	BATTERY TOP POST	66.90	1	\$66.90
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	24.63	1	\$24.63
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.35	1	\$16.35
					<b>PARTS</b>	<b>135.84</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 6793

---

## Work Order Notes

(LPATE) PM-REPLACE WIPERS-TESTED BATTERY FAILED REPLACE BATTERY

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LPATE) REPLACED BATTERY COVERED WITH ACID TESTED BAD

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

### **03-51-046 - REPLACE NEW KEY BLANK(S)**

(LPATE) CANCELLED WRONG JOB CODE

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY IF

---

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 7231

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 11/23/2010 13:24:04	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/23/2010 13:34:08	<b>METER 1 - M:</b> 71313 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/23/2010 13:34:09	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-17	REPAIR TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$25.83	\$0.00	\$43.66

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.31**      **17.83**      **25.83**      **0.00**      **43.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/23/2010 14:00:00	11/23/2010 14:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	192	\$17.28
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	(192)	(\$17.28)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	192	\$20.16
					<b>PARTS</b>	<b>25.83</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 7231

---

## Work Order Notes

(RWINTERS) PM AND TIRE LIGHT IS ON

---

## Job Notes

### **24-17 - REPAIR TIRES, TUBES, LINERS & VALVES**

(RWINTERS) RF TIRE HAD BEEN PLUGGED BEFORE. TAKEN TO FIRESTONE AND THEY PATCHED IT FROM THE INSIDE AT NO CHARGE. TM REINSTALLED WHEEL. N/C LABOR

### **66-PM-PMA - PERFORM OIL CHANGE**

(RWINTERS)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY JM/TM/RS

---



# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 7702

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 02/07/2011 13:24:10	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/09/2011 07:01:30	<b>METER 1 - M:</b> 72182 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/09/2011 07:01:32	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-17-018	RECALL SPARE TIRE HOIST	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-40-424	RECALL OIL SUPPLY HOSE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$24.90	\$27.25	\$0.00	\$52.15

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.43</b>	<b>24.90</b>	<b>27.25</b>	<b>0.00</b>	<b>52.15</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-17-018	RECALL SPARE TIRE HOIST	11076422	TOCS445627	0010688	\$0.00
<b>COMML</b>					<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10230946	02/08/2011 13:39:12	02/08/2011 14:05:11	0.43	\$24.90
<b>LABOR</b>					<b>24.90</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.41	1	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
<b>PARTS</b>					<b>27.25</b>	

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 7702

---

**Work Order Notes**

(LPATE) PM-TAKE TO TUSCALOOSA TOYOTA FOR RECALLS LSC 90K OIL HOSE KIT AND SSC A7E SPARE TIRE CARRIER CABLE.

---

**Job Notes**

**17-17-018 - RECALL SPARE TIRE HOIST**

(LPATE) TOYOTA INSTALLED FLOOR SEAL KIT

**17-40-424 - RECALL OIL SUPPLY HOSE**

(LPATE) INSTALLED OIL HOSE KIT

**66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

---

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 7766

<b>USING DEPT NO:</b>	505161	<b>OPENED DATE:</b>	02/17/2011 07:40:40	<b>LOCATION:</b>	GARAGE - University Automotive Services	
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	03/09/2011 10:55:14	<b>METER 1 - M:</b>	72182	<b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	03/09/2011 10:55:16	<b>IN-SERVICE DATE:</b>	05/11/2007	
<b>TECH SPEC NO:</b>	07VNTTOYSIENNA	2007 Toyota Sienna		<b>UNIT SERIAL NO:</b>	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
05-40-413	REPLACE USED ENGINE ASSEMBLY BL	DON	B	N	GARAGE	21.21	\$1,219.74	\$5,469.68	\$0.00	\$6,689.42
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$78.19	\$78.19
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & I	DON	B	N	GARAGE	10.33	\$593.89	\$23.52	\$0.00	\$617.41
20-00	TOWING COMPLETE VEHICLE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$215.05	\$215.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$67.62	\$0.00	\$67.62

<b>JOB COUNT:</b> 5	<b>WORK ORDER TOTAL:</b>	<b>31.54</b>	<b>1,813.63</b>	<b>5,560.82</b>	<b>293.24</b>	<b>7,667.69</b>
---------------------	--------------------------	--------------	-----------------	-----------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	133812	0011065	\$78.19
20-00	TOWING COMPLETE VEHICLE	11076249	31662	0011066	\$215.05
<b>COMML</b>					<b>293.24</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	02/18/2011 10:15:39	02/21/2011 06:03:02	67.79	\$3,897.91
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/01/2011 13:04:07	03/01/2011 14:00:00	0.93	\$53.56
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/01/2011 14:15:00	03/01/2011 14:58:48	0.73	\$41.98
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	03/01/2011 14:59:21	03/01/2011 16:01:04	1.03	\$59.14
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	03/02/2011 06:02:56	03/02/2011 07:04:58	1.03	\$59.45
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/02/2011 07:35:13	03/02/2011 09:00:00	1.41	\$81.25
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/02/2011 09:15:00	03/02/2011 14:00:00	4.75	\$273.13
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/02/2011 14:15:00	03/02/2011 15:04:01	0.82	\$46.97
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	03/02/2011 13:07:29	03/02/2011 15:51:49	2.74	\$157.49
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/03/2011 06:50:32	03/03/2011 09:00:00	2.16	\$124.07
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/03/2011 09:15:00	03/03/2011 10:29:37	1.24	\$71.51
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/03/2011 13:02:16	03/03/2011 14:00:00	0.96	\$55.33
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/03/2011 14:15:00	03/03/2011 14:55:06	0.67	\$38.43

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/04/2011 13:55:29	03/04/2011 14:00:00	0.08	\$4.33
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	03/04/2011 14:15:00	03/04/2011 14:58:32	0.73	\$41.72
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	02/18/2011 10:15:39	02/21/2011 06:03:02	(67.79)	(\$3,897.91)
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	02/17/2011 15:31:39	02/17/2011 15:32:14	0.01	\$0.56
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	11338644	02/17/2011 09:59:50	02/17/2011 15:30:53	5.52	\$317.26
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	02/17/2011 14:15:00	02/17/2011 14:58:54	0.73	\$42.07
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	02/17/2011 09:15:00	02/17/2011 14:00:00	4.75	\$273.13
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	11268671	02/17/2011 07:44:35	02/17/2011 09:00:00	1.26	\$72.27
					<b>LABOR</b>	<b>1813.65</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	1.23	(1)	(\$1.23)
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	5.48	4	\$21.90
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	5.48	(4)	(\$21.90)
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	\$NA369131	USED ENGINE ASSY	4830.00	1	\$4,830.00
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	9091901247	SPARK PLUG	15.23	6	\$91.35
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	171730P020	EXHAUST GASKET	21.99	2	\$43.98
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	1610009441	WATERPUMP ASSY	219.60	1	\$219.60
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	171760P020	AIR SURGE GASKET	11.91	3	\$35.73
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	9030107033	O RING	3.83	6	\$22.95
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	309MM12X37	FENDER WASHER	2.28	4	\$9.12
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	2329123010	INSULATOR INJECTOR	4.55	6	\$27.27
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	90916A3002	THERMOSTAT	26.91	1	\$26.91
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	9008043036	EXHAUST GASKET	13.98	2	\$27.96
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	FEL61106	EXHAUST PIPE	24.73	1	\$24.73
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	113MM12X125X120	METRIC HEXHEAD CAPSCREW	3.77	4	\$15.07
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		FLAT WASHERS	0.32	8	\$2.52
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	1.23	1	\$1.23
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	00272SLLC2	TOYOTA ANTIFREEZE	25.38	2	\$50.76
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	5.48	4	\$21.90
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	1632562010	THERMOSTAT GASKET	7.35	1	\$7.35
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		BRAKE FLUID DOT 3 12OZ	2.52	1	\$2.52
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	C111	RED BRAKE CLEANER	4.37	1	\$4.37

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		INTAKE BOLTS	1.23	1	\$1.23
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		FLAT WASHERS	0.32	(8)	(\$2.52)
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS		FLAT WASHERS	0.32	8	\$2.52
14-40-413	INSTALL ENGINE ASSEMBLY BLOCK & HEADS	5W20	OIL BOTTLE	0.11	224	\$23.52
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	C111	RED BRAKE CLEANER	4.37	(1)	(\$4.37)
05-40-413	REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS	C111	RED BRAKE CLEANER	4.37	2	\$8.73
66-PM-PMA	PERFORM OIL CHANGE	6902	FILTER-AIR	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	416	\$43.68
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.42	2	\$10.83
					<b>PARTS</b>	<b>5560.82</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 7766

## Work Order Notes

(AJONES) WRONG AIR FILTER WAS BILLED- THE CORRECT AIR FILTER IS 6673

## Job Notes

### **05-40-413 - REPLACE USED ENGINE ASSEMBLY BLOCK & HEADS**

(LPATE) USED MOTOR INSTALLED ADD \$420.00 FOR WARRANTY 6 MONTHS + LABOR-

### **09-17 - ALIGN TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE COMPLETED ALIGNEMENT. PD BY CC.

### **14-40-413 - INSTALL ENGINE ASSEMBLY BLOCK & HEADS**

### **20-00 - TOWING COMPLETE VEHICLE**

(LPATE) BAMBARGER PICKED VEHICLE UP AT UA GARAGE AND TOOK TO BESSEMER TO SWAP OUT FOR BROKEN DOWN VEHICLE. PICKED THAT VEHICLE UP AND BROUGHT TO UA GARAGE

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 7047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(LPATE) OIL CHANGE WAS DONE TWICE

# Work Order Charge Detail

**UNIT NO:** 237335      **2007 TOYOTA SIENNA**      **WORK ORDER NO:** 7905

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 03/21/2011 08:01:40	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/21/2011 10:36:46	<b>METER 1 - M:</b> 72404 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/21/2011 10:36:48	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA      2007 Toyota Sienna	<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$97.44	\$0.00	\$212.44

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **2.00**      **115.00**      **97.44**      **0.00**      **212.44**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11268671	03/21/2011 16:00:00	03/21/2011 18:00:00	2.00	\$115.00
					<b>LABOR</b>	<b>115.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABATD906AC	FRONT PADS	97.44	1	\$97.44
					<b>PARTS</b>	<b>97.44</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 7905

---

**Work Order Notes**

(LPATE) BRAKES ARE PULSATING

---

**Job Notes**

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LPATE) REPLACED FRONT BRAKE PADS AND TURNED ROTORS

---



# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 9215

USING DEPT NO:	505161	OPENED DATE:	09/22/2011 11:08:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2011 07:32:13	METER 1 - M:	76979	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/23/2011 07:32:15	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$44.94	\$0.00	\$59.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$16.66	\$42.35	\$0.00	\$59.01
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.54</b>	<b>31.04</b>	<b>87.29</b>	<b>0.00</b>	<b>118.33</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/22/2011 13:18:46	09/22/2011 13:33:46	0.25	\$14.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/22/2011 13:01:23	09/22/2011 13:18:46	0.29	\$16.66
					<b>LABOR</b>	<b>31.04</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.65	1	\$5.65
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	9.95	1	\$9.95
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	1	\$16.74
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	28.20	1	\$28.20
					<b>PARTS</b>	<b>87.29</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 9215

---

## Work Order Notes

(LPATE) PM-PER TRISH CHECK ENGINE LIGHT IS ON

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(LPATE) REPLACED WIPERS

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY SH-REPLACED AIR FILTER

### **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LPATE) CHECK ENGINE LIGHT WAS NOT ON IT WAS MAINT REQUIRED LIGHT. COMPLETED OIL CHANGE AND RESET DISPLAY.

---

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 9705

<b>USING DEPT NO:</b> 505161	<b>OPENED DATE:</b> 11/16/2011 08:40:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/18/2011 06:56:47	<b>METER 1 - M:</b> 82262 <b>METER 2 - N:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/18/2011 06:56:48	<b>IN-SERVICE DATE:</b> 05/11/2007
<b>TECH SPEC NO:</b> 07VNTTOYSIENNA 2007 Toyota Sienna		<b>UNIT SERIAL NO:</b> 5TDZK23C87S041857

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$450.24	\$450.24
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$19.55	\$40.58	\$0.00	\$60.13

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.34</b>	<b>77.05</b>	<b>40.58</b>	<b>450.24</b>	<b>567.87</b>
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	142908	0013896	\$450.24
					<b>COMML 450.24</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 17:00:00	11/17/2011 17:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 17:00:00	11/17/2011 17:18:36	(0.31)	(\$17.83)
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10260422	11/17/2011 17:18:36	11/17/2011 18:18:36	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 07:54:37	11/17/2011 08:15:01	0.34	\$19.55
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 07:54:37	11/17/2011 09:15:00	1.34	\$77.03
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 07:54:37	11/17/2011 09:15:00	(1.34)	(\$77.03)
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 14:30:00	11/18/2011 06:52:36	16.38	\$941.66
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 09:30:00	11/17/2011 14:15:00	4.75	\$273.13
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 14:30:00	11/18/2011 06:52:36	(16.38)	(\$941.66)
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/17/2011 09:30:00	11/17/2011 14:15:00	(4.75)	(\$273.13)
					<b>LABOR</b>	<b>77.05</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	208	\$18.72
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	9.95	1	\$9.95
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	(208)	(\$18.72)

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	208	\$24.96
<b>PARTS</b>						<b>40.58</b>

# Work Order Charge Detail

**UNIT NO:** 237335 2007 TOYOTA SIENNA

**WORK ORDER NO:** 9705

---

## Work Order Notes

(LPATE) PM-NEEDS 4 NEW TIRES AND ALIGN

---

## Job Notes

### **03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES**

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED. PD BY CC.

### **16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES**

(LPATE) TAKEN TO FIRESTONE BY GM

### **66-PM-PMA - PERFORM OIL CHANGE**

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30  
Qty : 192  
Description : OIL BULK  
Manufacturer :

Part No : 7047  
Qty : 1  
Description : FILTER-OIL  
Manufacturer :

(LPATE) PM BY GM-REPLACED AIR FILTER

---

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 991

USING DEPT NO:	505161	OPENED DATE:	03/13/2008 13:27:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/13/2008 13:31:55	METER 1 - M:	15218	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/13/2008 13:31:57	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C87S041857	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$25.14	\$0.00	\$25.14

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 25.14 0.00 25.14

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	192	\$14.40
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	10.74	1	\$10.74
					<b>PARTS</b>	<b>25.14</b>

# Work Order Charge Detail

UNIT NO: 237335 2007 TOYOTA SIENNA

WORK ORDER NO: 991

---

**Work Order Notes**

(RWINTERS) PM

---

**Job Notes**

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) PM BY CS

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Thu Apr 11 2024 16:40:43 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '5TDZK23C87S041857') //Q=