

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 1100

USING DEPT NO: 505161	OPENED DATE: 04/08/2008 07:45:52	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/08/2008 10:50:17	METER 1 - M: 7875 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/08/2008 10:50:18	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONI	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-17-016	TRANSPORT TIRE PRESSURE MONITO	DON	O	N	GARAGE	1.00	\$45.00	\$0.00	\$0.00	\$45.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$21.84	\$0.00	\$35.79

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.31** **58.95** **21.84** **0.00** **80.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17-016	REPLACE NEW TIRE PRESSURE MONITOR/SENSOR	11076422	TOCS335584	01293	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11128904	04/08/2008 07:46:00	04/08/2008 08:04:36	0.31	\$13.95
16-17-016	TRANSPORT TIRE PRESSURE MONITOR/SENSOR	11088858	04/08/2008 07:46:00	04/08/2008 08:46:00	1.00	\$45.00
LABOR						58.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	144	\$12.96
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	8.88	1	\$8.88
PARTS						21.84

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 1100

Work Order Notes

(LOBRIEN) PM AND TIRE PRESSURE LIGHT (UNDER WARRANTY).

Job Notes

03-17-016 - REPLACE NEW TIRE PRESSURE MONITOR/SENSOR

(LOBRIEN) R&R TPWS ECM.

16-17-016 - TRANSPORT TIRE PRESSURE MONITOR/SENSOR

(LOBRIEN) TAKEN TO TUSCALOOSA TOYOTA.

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY CHRIS MCRAE.

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 11233

USING DEPT NO: 505161	OPENED DATE: 06/14/2012 14:25:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/18/2012 13:18:33	METER 1 - M: 56640 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/18/2012 13:18:34	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-18-007	REPLACE NEW WHEEL STUD /NUT	DON	O	N	GARAGE	0.00	\$0.00	\$6.91	\$0.00	\$6.91
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$39.60	\$0.00	\$57.43

JOB COUNT: 3	WORK ORDER TOTAL:	1.31	75.33	46.51	0.00	121.84
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	06/15/2012 14:25:13	06/15/2012 14:25:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11338644	06/15/2012 14:25:13	06/15/2012 14:25:13	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11338644	06/15/2012 14:25:13	06/15/2012 14:43:49	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/15/2012 14:21:31	06/15/2012 14:21:31	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/15/2012 14:21:31	06/15/2012 14:21:31	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11338644	06/15/2012 14:21:31	06/15/2012 15:21:31	1.00	\$57.50
					LABOR	75.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-18-007	REPLACE NEW WHEEL STUD /NUT	DOR610266	WHEEL STUD	1.83	1	\$1.83
03-18-007	REPLACE NEW WHEEL STUD /NUT	DOR610266	WHEEL STUD	1.75	(1)	(\$1.75)
03-18-007	REPLACE NEW WHEEL STUD /NUT	DOR610266	WHEEL STUD	1.75	1	\$1.75
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	6	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
03-18-007	REPLACE NEW WHEEL STUD /NUT	DOR611066	WHEEL NUT	1.69	3	\$5.08
					PARTS	46.51

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 11233

Work Order Notes

(LPATE) PM-CHECK BRAKES ARE SCRUBBING-DO SAFETY INSPECTION

Job Notes

03-18-007 - REPLACE NEW WHEEL STUD /NUT

(RWINTERS) REPLACED 1 LR WHELL STUD AND 3 NUTS

06-13 - INSPECT BRAKES

(RWINTERS) CANCEL JOB-PART OF SAFETY INSPECTION.

66-79-003 - PERFORM SAFETY INSPECTION

(RWINTERS) PERFORMED SAFETY INSPECTION AND TEST DROVE, EVERYTHING IS GOOD.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY RT/RS

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 12138

USING DEPT NO: 505161	OPENED DATE: 10/15/2012 15:26:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/17/2012 06:47:30	METER 1 - M: 61517 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2012 06:47:32	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$3.39	\$70.04	\$0.00	\$73.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.36** **20.64** **70.04** **0.00** **90.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11338644	10/16/2012 08:41:47	10/16/2012 08:59:47	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11338644	10/16/2012 08:38:15	10/16/2012 08:41:47	0.06	\$3.39
					LABOR	20.64

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	4883	FILTER-CABIN	24.78	1	\$24.78
					PARTS	70.04

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 12138

Work Order Notes

(LPATE) PM-REPLACE CABIN FILTER

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30
Qty : 192
Description : OIL BULK
Manufacturer :

Part No : 7047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(RWINTERS) PM BY RS/GM

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(RWINTERS) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 13447

USING DEPT NO: 505161	OPENED DATE: 04/05/2013 14:16:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/09/2013 13:09:18	METER 1 - M: 66506 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/09/2013 13:09:20	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17-008	REPLACE NEW VALVE ASSEMBLY	DON	O	N	GARAGE	0.50	\$28.75	\$129.39	\$75.44	\$233.58
16-17-008	TRANSPORT VALVE ASSEMBLY	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$68.40	\$0.00	\$86.23

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.81** **104.08** **197.79** **75.44** **377.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17-008	REPLACE NEW VALVE ASSEMBLY	11076422	TOCS535434	0019342	\$75.44
COMML					75.44

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17-008	TRANSPORT VALVE ASSEMBLY	11413680	04/08/2013 07:00:00	04/08/2013 08:00:00	1.00	\$57.50
03-17-008	REPLACE NEW VALVE ASSEMBLY	11074414	04/08/2013 06:18:36	04/08/2013 06:48:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/08/2013 06:00:00	04/08/2013 06:18:36	0.31	\$17.83
LABOR					104.08	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	T20	TECHRON 200Z FUEL ADDITIVE	12.11	1	\$12.11
03-17-008	REPLACE NEW VALVE ASSEMBLY	426070C070	TIRE MONITOR SENSOR	129.39	1	\$129.39
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	9.91	1	\$9.91
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.66	7	\$39.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.79	1	\$6.79
PARTS					197.79	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 13447

Work Order Notes

(GMANNING) PM

Job Notes

03-17-008 - REPLACE NEW VALVE ASSEMBLY

(RWINTERS) SH REPLACED VALVE STEM/TIRE PRESSURE SENSOR ON RIGHT FRONT. VALVE STEM CRACKED AROUND STEM. TUSCALOOSA TOYOTA RESET MONITORING SYSTEM.

16-17-008 - TRANSPORT VALVE ASSEMBLY

(GMANNING) RT TOOK UNIT TO TUSCALOOSA TOYOTA

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.7675

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(GMANNING) PM BY SH

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 13686

USING DEPT NO:	505161	OPENED DATE:	05/01/2013 15:28:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2013 09:15:46	METER 1 - M:	66603	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2013 09:15:48	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$69.21	\$0.00	\$97.96

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 69.21 0.00 97.96

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11413680	05/01/2013 15:29:10	05/01/2013 15:59:10	0.50	\$28.75
					LABOR	28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	69.21	1	\$69.21
					PARTS	69.21

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 13686

Work Order Notes

(LPATE) CHECK BATTERY PER FLEET HAD TO JUMP OFF

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 13880

USING DEPT NO:	505161	OPENED DATE:	05/17/2013 14:26:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2013 08:04:37	METER 1 - M:	66732	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2013 08:04:38	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNT0YSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-32-002	CHARGE BATTERY	DON	B	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 28.75 0.00 0.00 28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11074414	05/17/2013 14:27:40	05/17/2013 14:57:40	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 13880

Work Order Notes

(LPATE) PER FLEET CHECK BATTERY IS DEAD.

Job Notes

CH-32-002 - CHARGE BATTERY

(LPATE) CHARGED BATTERY, CHECKED GOOD, ALT IS CHARGING 14 VOLTS LET SIT OVER NIGHT RECHECKED BATTERY, CHECKED GOOD ALT CHECKED GOOD. COULD NOT FIND ANYTHING LEFT ON. SH

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 15322

USING DEPT NO: 505161	OPENED DATE: 11/05/2013 09:27:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2013 09:30:44	METER 1 - M: 69992 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2013 09:30:46	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$44.48	\$0.00	\$58.86
06-43	INSPECT EXHAUST SYSTEM	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$40.95	\$0.00	\$58.78

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.56** **89.71** **85.43** **0.00** **175.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	11/06/2013 06:00:00	11/06/2013 06:18:36	0.31	\$17.83
06-43	INSPECT EXHAUST SYSTEM	10260422	11/06/2013 06:18:36	11/06/2013 07:18:36	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	10260422	11/06/2013 07:18:36	11/06/2013 07:33:36	0.25	\$14.38
					LABOR	89.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	40718A	WIPER BLADE 18"	15.63	1	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.67	6	\$34.02
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	28.85	1	\$28.85
					PARTS	85.43

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 15322

Work Order Notes

(LPATE) PM-CHECK EXHAUST AND REAR END AREA DRIVER BACKED INTO SOMETHING DEPT REQUESTED DO NOT REPAIR BUMPER EXHAUST ONLY.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

06-43 - INSPECT EXHAUST SYSTEM

(RWINTERS) HEATED AND BENT (3 areas) EXHAUST BACK TO CORRECT POSITION. RECHECKED OK (GM/RW)

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 16363

USING DEPT NO: 505161	OPENED DATE: 03/12/2014 09:47:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/17/2014 13:05:52	METER 1 - M: 71751 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/17/2014 13:05:53	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-33	TRANSPORT IGNITION SYSTEM	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
17-33-011	RECALL SHIFT LOCK SOLENOID	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$32.02	\$52.11	\$0.00	\$84.13

JOB COUNT: 3	WORK ORDER TOTAL:	1.56	89.52	52.11	0.00	141.63
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-33-011	RECALL SHIFT LOCK SOLENOID	11076422	TOCS617695	0023089	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-33	TRANSPORT IGNITION SYSTEM	11074414	03/14/2014 06:00:00	03/14/2014 07:00:00	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/12/2014 11:20:47	03/12/2014 11:54:12	0.56	\$32.02
LABOR					89.52	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	7	\$40.32
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
PARTS					52.11	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 16363

Work Order Notes

(LPATE) PM AND RECALL FROM TOYOTA POSSIBLE DEFECTIVE SHIFT LOCK SOLENOID. TAKE TO TOYOTA TO HAVE RECALL PERFORMED

Job Notes

16-33 - TRANSPORT IGNITION SYSTEM

(LPATE) TAKEN TO TOYOTA BY SH

17-33-011 - RECALL SHIFT LOCK SOLENOID

(LPATE) TUSCALOOSA TOYOTA PERFORMED RECALL

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY SH/GM

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 16456

USING DEPT NO: 505161	OPENED DATE: 03/31/2014 07:13:25	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/01/2014 11:58:32	METER 1 - M: 71768 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/01/2014 11:58:33	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	W	J	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	10260422	04/01/2014 06:00:00	04/01/2014 06:30:00	0.50	\$28.75
03-32-002	REPLACE NEW BATTERY	10260422	03/31/2014 07:16:45	03/31/2014 07:46:45	(0.50)	(\$28.75)
03-32-002	REPLACE NEW BATTERY	10260422	03/31/2014 07:16:45	03/31/2014 07:46:45	0.50	\$28.75
					LABOR	28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	69.21	1	\$69.21
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	69.21	(1)	(\$69.21)
					PARTS	0.00

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 16456

Work Order Notes

(GMANNING) BATTERY DEAD. CHECK BATTERY AND TEST FOR DRAW ON SYSTEM.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(RWINTERS) REPLACED BATTERY, CLEANED TERMINALS, AND CHECKED FOR A DRAW. NO DRAW ON BATTERY DETECTED. NO LIGHTS LEFT ON. REPLACEMENT BATTERY WAS A 24FA. WARRANTY

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 16697

USING DEPT NO:	505161	OPENED DATE:	04/22/2014 10:43:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2014 15:07:22	METER 1 - M:	72253	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2014 15:07:24	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-019	REPLACE NEW OXYGEN SENSOR	DON	O	N	GARAGE	1.00	\$57.50	\$199.16	\$0.00	\$256.66
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.92	\$52.84	\$0.00	\$0.00	\$52.84

JOB COUNT: 2 WORK ORDER TOTAL: 1.92 110.34 199.16 0.00 309.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-05-019	REPLACE NEW OXYGEN SENSOR	11397026	04/23/2014 07:53:28	04/23/2014 08:53:28	1.00	\$57.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	04/23/2014 06:58:20	04/23/2014 07:53:28	0.92	\$52.84
					LABOR	110.34

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-05-019	REPLACE NEW OXYGEN SENSOR	DEN2349049	OXYGEN SENSOR	199.16	1	\$199.16
					PARTS	199.16

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 16697

Work Order Notes

(LPATE) PER FLEET CHECK ENGINE LIGHT IS ON

Job Notes

03-05-019 - REPLACE NEW OXYGEN SENSOR

(LPATE) CHECKED OUT WENT THRU PINPOINT TEST, REPLACED AIR FUEL SENSOR BANK 2 SENSOR 1. CLEARED CODE RECHECKED AND TEST DROVE OK

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LPATE) SCAN OUT P2197 AIR FUEL SENSOR BANK 2 SENSOR 1 IS STUCK LEAN

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 1698

USING DEPT NO: 505161	OPENED DATE: 07/22/2008 13:13:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/22/2008 13:20:04	METER 1 - M: 10711 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/22/2008 13:20:05	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	N	N	GARAGE	0.50	\$22.50	\$0.00	\$0.00	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$24.85	\$0.00	\$38.80

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **36.45** **24.85** **0.00** **61.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11088474	07/22/2008 13:34:36	07/22/2008 14:04:36	0.50	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	11088474	07/22/2008 13:16:00	07/22/2008 13:34:36	0.31	\$13.95
					LABOR	36.45

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.57	1	\$7.57
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	192	\$17.28
					PARTS	24.85

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 1698

Work Order Notes

(RWINTERS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(RWINTERS) ROTATED TIRES.

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) The following parts are included with the standard job:

Part No : 10W-30
Qty : 196
Description : OIL BULK
Manufacturer :

Part No : 57047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(RWINTERS) PM BY JE.

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 18291

USING DEPT NO:	505161	OPENED DATE:	10/02/2014 10:18:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2014 06:43:06	METER 1 - M:	75957	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/03/2014 06:43:08	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$39.16	\$41.34	\$0.00	\$80.50

JOB COUNT: 1 WORK ORDER TOTAL: 0.68 39.16 41.34 0.00 80.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/02/2014 10:42:54	10/02/2014 11:23:46	0.68	\$39.16
					LABOR	39.16

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.76	6	\$34.56
					PARTS	41.34

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 18291

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY SH,NT/SH-USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 18677

USING DEPT NO:	505161	OPENED DATE:	11/07/2014 14:43:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/10/2014 09:35:34	METER 1 - M:	76620	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2014 09:35:36	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	W	J	GARAGE	0.00	\$0.00	\$72.51	\$0.00	\$72.51

JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 72.51 0.00 72.51

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	72.51	1	\$72.51
					PARTS	72.51

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 18677

Work Order Notes

(LPATE) PER FLEET BATTERY IS DEAD

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) BATTERY FAILED REPLACED BATTERY AS WARRANTY. RECHECKED OK ALT IS CHARGING NO DRAW FOUND.

(LPATE) DUE TO DATE BATTERY WAS NOT WARRANTY IT WAS OUT OF TIME. BILLED 24FA BATTERY

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 20520

USING DEPT NO: 505161	OPENED DATE: 06/11/2015 11:35:11	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/17/2015 07:57:36	METER 1 - M: 81315 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/17/2015 07:57:37	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$498.95	\$498.95
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.09	\$5.28	\$49.71	\$0.00	\$54.99
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.15	\$66.02	\$0.00	\$0.00	\$66.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$46.91	\$62.25	\$0.00	\$109.16
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	1.02	\$58.68	\$10.29	\$0.00	\$68.97

JOB COUNT: 5	WORK ORDER TOTAL:	3.08	176.89	122.25	498.95	798.09
---------------------	--------------------------	-------------	---------------	---------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	194398	0028860	\$498.95	
					COMML	498.95

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/12/2015 07:11:43	06/12/2015 08:12:57	1.02	\$58.68
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/12/2015 07:06:07	06/12/2015 07:11:38	0.09	\$5.28
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/12/2015 06:17:01	06/12/2015 07:05:58	0.82	\$46.91
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	06/12/2015 13:51:12	06/12/2015 14:15:00	0.40	\$22.81
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10337093	06/12/2015 14:30:00	06/12/2015 15:15:05	0.75	\$43.21
					LABOR	176.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	15.84	1	\$15.84
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	7	\$39.48
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
03-51-038	REPLACE NEW WIPER BLADES	40716A	WIPER BLADE 16"	15.59	1	\$15.59
03-51-038	REPLACE NEW WIPER BLADES	40726	WIPER BLADE 26"	21.33	1	\$21.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	10.29	1	\$10.29
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79

Work Order Charge Detail

PARTS

122.25

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 20520

Work Order Notes

(LPATE) PM-REPLACE CABIN FILTER-REPLACE WIPERS-NEEDS 4 TIRES AND ALIGN

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED. PD BY CC

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY AY

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.78

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.62

(LPATE) PM BY SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 2126

USING DEPT NO: 505161	OPENED DATE: 10/08/2008 13:13:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/09/2008 13:28:15	METER 1 - M: 12199 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/09/2008 13:28:16	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.31	\$17.83	\$0.00	\$0.00	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.04	\$0.00	\$43.87

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.62** **35.66** **26.04** **0.00** **61.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	11089300	10/08/2008 14:57:26	10/08/2008 14:57:57	(0.01)	(\$0.49)
66-79-003	PERFORM SAFETY INSPECTION	11089300	10/08/2008 14:57:26	10/08/2008 14:57:57	0.01	\$0.49
66-79-003	PERFORM SAFETY INSPECTION	11089300	10/08/2008 14:57:26	10/08/2008 15:16:02	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11089300	10/08/2008 14:57:13	10/08/2008 14:57:26	0.00	(\$0.21)
66-PM-PMA	PERFORM OIL CHANGE	11089300	10/08/2008 14:57:13	10/08/2008 14:57:26	0.00	\$0.21
66-PM-PMA	PERFORM OIL CHANGE	11089300	10/08/2008 14:57:13	10/08/2008 15:15:49	0.31	\$17.83
					LABOR	35.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.32	1	\$7.32
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	208	\$18.72
					PARTS	26.04

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 2126

Work Order Notes

(LPATE) PM - FLAT REPAIR - SAFETY INSPECTION
SUBMERGED ALL 4 TIRES COULD NOT FIND ANY LEAKS AT THIS TIME

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) PERFORMED SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 10W-30
Qty : 196
Description : OIL BULK
Manufacturer :

Part No : 57047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(LPATE) PM BY MS

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 2259

USING DEPT NO: 505161	OPENED DATE: 10/30/2008 09:44:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/31/2008 11:10:30	METER 1 - M: 13252 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/31/2008 11:10:32	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$339.70	\$339.70
16-02-061	TRANSPORT WINDSHIELD	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.30** **17.25** **0.00** **339.70** **356.95**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-061	REPLACE NEW WINDSHIELD	11070709	6923	0002730	\$339.70
COMML					339.70

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02-061	TRANSPORT WINDSHIELD	11088474	10/31/2008 09:12:57	10/31/2008 09:30:57	0.30	\$17.25
16-02-061	TRANSPORT WINDSHIELD	11088474	10/31/2008 09:12:57	10/31/2008 09:13:11	0.00	(\$0.22)
16-02-061	TRANSPORT WINDSHIELD	11088474	10/31/2008 09:12:57	10/31/2008 09:13:11	0.00	\$0.22
LABOR					17.25	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 2259

Work Order Notes

(LPATE) WINDSHIELD HAD DING ON LEFT SIDE IS NOW RUNNING ALL THE WAY ACROSS RIGHT IN DRIVERS LINE OF SIGHT

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LPATE) RELIABLE GLASS REPLACED WINDSHIELD P0017931

16-02-061 - TRANSPORT WINDSHIELD

(LPATE) TAKEN TO RELIABLE BY JE

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 23039

USING DEPT NO: 505161	OPENED DATE: 04/08/2016 14:06:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/12/2016 07:22:18	METER 1 - M: 83634 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/12/2016 07:22:19	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna		UNIT SERIAL NO: 5TDZK23C07S055039

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.00	\$115.00	\$90.41	\$0.00	\$205.41
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$44.94	\$0.00	\$62.77

JOB COUNT: 3	WORK ORDER TOTAL:	2.31	132.83	135.35	0.00	268.18
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11397026	04/09/2016 00:00:00	04/09/2016 00:18:36	0.31	\$17.83
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11397026	04/09/2016 00:00:00	04/09/2016 02:00:00	2.00	\$115.00
					LABOR	132.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEHT906AH	FRONT PADS	90.41	1	\$90.41
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.17	1	\$4.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	5.64	6	\$33.84
					PARTS	135.35

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 23039

Work Order Notes

(LISAPATE) PM-CHECK FOR BRAKE NOISE

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) REPLACED FRONT PADS AND TURNED FRONT ROTORS ON THE VEHICLE. REAR BRAKES LOOK GOOD

06-13 - INSPECT BRAKES

(LISAPATE) CHECKED BRAKES NEEDS FRONT PADS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULL SYN. OIL QT Qty 6 Cost 3.780000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM BY BG

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 24598

USING DEPT NO: 505161	OPENED DATE: 10/12/2016 09:01:12	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/17/2016 07:52:49	METER 1 - M: 85128 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/17/2016 07:52:50	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.32	\$18.45	\$76.35	\$0.00	\$94.80
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.15	\$8.47	\$0.00	\$0.00	\$8.47
17-17-018	RECALL SPARE TIRE HOIST	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$16.98	\$41.25	\$0.00	\$58.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	1.50	\$86.07	\$8.76	\$0.00	\$94.83

JOB COUNT: 5	WORK ORDER TOTAL:	2.26	129.97	126.36	0.00	256.33
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-17-018	RECALL SPARE TIRE HOIST	11076422	TOCS736201	0035799	\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	10/12/2016 13:00:26	10/12/2016 13:09:16	0.15	\$8.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/14/2016 09:15:00	10/14/2016 09:47:10	0.54	\$30.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/14/2016 08:02:21	10/14/2016 09:00:00	0.96	\$55.25
03-32-002	REPLACE NEW BATTERY	11074414	10/14/2016 07:43:02	10/14/2016 08:02:17	0.32	\$18.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/14/2016 07:25:14	10/14/2016 07:42:57	0.30	\$16.98
LABOR					129.98	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	8.76	1	\$8.76
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	5W20FS	HAVOLINE 5W20 FULLSYN OIL BULK	0.17	208	\$34.32
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	76.35	1	\$76.35
PARTS					126.36	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 24598

Work Order Notes

(LISAPATE) PM-TOYOTA RECALL EXCESSIVE CORROSION OF THE SPARE TIRE CARRIER

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) REPLACED BATTERY

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO TOYOTA BY EK

17-17-018 - RECALL SPARE TIRE HOIST

(LISAPATE) TOYOTA COMPLETED RECALL REPLACED SPARE TIRE CARRIER KIT

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM BY SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 2574

USING DEPT NO: 505161	OPENED DATE: 12/05/2008 11:04:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/05/2008 11:47:22	METER 1 - M: 14700 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 12/05/2008 11:47:25	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-17-011	INSTALL TIRE PLUG	DON	O	N	GARAGE	0.40	\$23.00	\$0.00	\$0.00	\$23.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.40** **80.50** **0.00** **0.00** **80.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11088474	12/05/2008 12:00:00	12/05/2008 13:00:00	1.00	\$57.50
14-17-011	INSTALL TIRE PLUG	11088474	12/05/2008 13:00:00	12/05/2008 13:24:00	0.40	\$23.00
					LABOR	80.50

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 2574

Work Order Notes

(LPATE) SVC CALL FLAT TIRE LEFT REAR BHIND MOODY HALL

Job Notes

14-17-011 - INSTALL TIRE PLUG

(LPATE) INSTALLED PLUG IN LEFT REAR TIRE

66-79-002 - PERFORM SERVICE CALL

(LPATE) SVC CALL TO BEHIND MOODY HALL FLAT TIRE

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 2809

USING DEPT NO: 505161	OPENED DATE: 01/27/2009 11:31:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/28/2009 06:28:43	METER 1 - M: 17956 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/28/2009 06:28:46	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$47.07	\$0.00	\$61.45
66-17-015	PERFORM TIRE ROTATION	DON	N	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-003	PERFORM SAFETY INSPECTION	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$49.16	\$0.00	\$66.99
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$24.81	\$0.00	\$42.06

JOB COUNT: 5	WORK ORDER TOTAL:	2.36	135.71	121.04	0.00	256.75
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11088474	01/27/2009 12:18:36	01/27/2009 12:36:36	0.30	\$17.25
66-79-003	PERFORM SAFETY INSPECTION	11088474	01/27/2009 13:21:36	01/27/2009 14:21:36	1.00	\$57.50
66-17-015	PERFORM TIRE ROTATION	11088474	01/27/2009 12:51:36	01/27/2009 13:21:36	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11088474	01/27/2009 12:00:00	01/27/2009 12:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11088474	01/27/2009 12:36:36	01/27/2009 12:51:36	0.25	\$14.38
					LABOR	135.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	12.96	1	\$12.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	4883	FILTER-CABIN	24.81	1	\$24.81
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	21.90	1	\$21.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	208	\$24.96
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	16.81	1	\$16.81
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	12.21	1	\$12.21
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
					PARTS	121.04

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 2809

Work Order Notes

(LPATE) PM-REPLACE WIPERS-ROTATE TIRES-REPLACE CABIN FILTER-PERFORM SAFETY CHECK

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-17-015 - PERFORM TIRE ROTATION

(LPATE) ROTATED TIRES -MISSING ONE HUBCAP AND TWO ARE VERY SCUFFED UP

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) PERFORMED SAFETY CHECK-REMOVED WHEELS AND CHECKED BRAKES

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 10W-30
Qty : 192
Description : OIL BULK
Manufacturer :

Part No : 57047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(LPATE) PM BY JE

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 28798

USING DEPT NO: 505161	OPENED DATE: 02/05/2018 13:29:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/08/2018 11:44:00	METER 1 - M: 87096 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/08/2018 11:44:02	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.58	\$0.00	\$39.96
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.14	\$8.13	\$0.00	\$0.00	\$8.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.74	\$42.34	\$28.41	\$0.00	\$70.75

JOB COUNT: 3	WORK ORDER TOTAL:	1.13	64.85	53.99	0.00	118.84
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	02/06/2018 08:38:57	02/06/2018 08:39:06	0.00	(\$0.14)
03-51-038	REPLACE NEW WIPER BLADES	11901357	02/06/2018 08:38:57	02/06/2018 08:39:06	0.00	\$0.14
03-51-038	REPLACE NEW WIPER BLADES	11901357	02/06/2018 08:38:57	02/06/2018 08:53:57	0.25	\$14.38
35-32	DIAGNOSE CRANKING SYSTEM	11901357	02/06/2018 08:30:11	02/06/2018 08:38:40	0.14	\$8.13
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/06/2018 07:19:16	02/06/2018 08:03:27	0.74	\$42.34
					LABOR	64.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.11	208	\$21.84
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.57	1	\$6.57
					PARTS	53.99

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 28798

Work Order Notes

(LISAPATE) BATTERY KEEPS GOING DEAD
PM DUE

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED FRONT WIPER BLADES

35-32 - DIAGNOSE CRANKING SYSTEM

(LISAPATE) BATTERY CHECKED GOOD, FOUND POOR CONNECTION AT CLAMPS.
CLEANED BATTERY POSTS AND CLAMPS, CHECKED CHARGING SYSTEM
CHARGING GOOD AT 14.3v, STARTING GOOD

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM BY SH, AG/SH

COOLANT -35'

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 34084

USING DEPT NO: 505161	OPENED DATE: 09/12/2019 15:35:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/18/2019 10:27:17	METER 1 - M: 89651 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/18/2019 10:27:19	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-17-016	DIAGNOSE TIRE PRESSURE MONITOR	DON	O	N	GARAGE	0.11	\$7.71	\$0.00	\$0.00	\$7.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.33	\$96.73	\$44.60	\$0.00	\$141.33

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.44** **104.44** **44.60** **0.00** **149.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/13/2019 14:30:00	09/13/2019 14:55:30	0.43	\$30.81
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/13/2019 14:05:50	09/13/2019 14:15:00	0.15	\$11.08
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/13/2019 14:30:00	09/13/2019 14:39:36	0.16	\$11.60
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/13/2019 13:39:13	09/13/2019 14:15:00	0.60	\$43.24
35-17-016	DIAGNOSE TIRE PRESSURE MONITOR/SENSOR	11310047	09/16/2019 07:44:32	09/16/2019 07:50:55	0.11	\$7.71
					LABOR	104.44

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	7.02	1	\$7.02
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
					PARTS	44.60

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 34084

Work Order Notes

(LISAPATE) PM

Job Notes

35-17-016 - DIAGNOSE TIRE PRESSURE MONITOR/SENSOR

(LISAPATE) All tires were 7lbs low, adjusted tire pressures. TPMS light reset itself after pressures were adjusted.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) PM by AG/JW

Coolant -35'

Replaced air filter

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 3444

USING DEPT NO:	505161	OPENED DATE:	05/19/2009 13:09:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2009 14:59:59	METER 1 - M:	21074	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	05/19/2009 15:00:00	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.23	\$0.00	\$47.06

JOB COUNT: 1 WORK ORDER TOTAL: 0.31 17.83 29.23 0.00 47.06

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	05/19/2009 15:00:00	05/19/2009 15:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
					PARTS	29.23

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 3444

Work Order Notes

(LPATE) PM-MISSING A HUBCAP RF TIRE S/W SUSAN CAPLES SHE ORDERED REPLACEMENT

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0

Part 57047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JE

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LPATE) CANCELLED JOB ON WRONG WORK ORDER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 36947

USING DEPT NO: 505161	OPENED DATE: 06/24/2020 11:09:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/25/2020 07:17:43	METER 1 - M: 90652 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/25/2020 09:35:11	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.14	\$10.19	\$114.81	\$0.00	\$125.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$44.14	\$0.00	\$0.00	\$44.14

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.75** **54.33** **114.81** **0.00** **169.14**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11901357	06/24/2020 14:39:52	06/24/2020 14:48:18	0.14	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/24/2020 14:03:02	06/24/2020 14:39:34	0.61	\$44.14
					LABOR	54.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.63	2	\$1.26
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	114.81

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 36947

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery failed, replaced battery checked alt is now charging at 14.2 volts

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 5W20FS HAVOLINE 5W20 FULLSYN OIL BULK Qty 6 Cost 0.100000

Part 04152-YZZA1 FILTER-OIL Qty 1 Cost 4.620000

(LISAPATE) Did not change oil at this time. Checked fluids battery and tires pressures. Updated sticker
Coolant -35'

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 37550

USING DEPT NO: 505161	OPENED DATE: 09/10/2020 09:18:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/10/2020 11:10:51	METER 1 - M: 90671 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2020 14:24:20	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$23.93	\$0.00	\$0.00	\$23.93

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.33** **23.93** **0.00** **0.00** **23.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/10/2020 09:24:23	09/10/2020 09:24:23	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/10/2020 09:24:23	09/10/2020 09:24:23	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/10/2020 09:24:23	09/10/2020 09:44:11	0.33	\$23.93
					LABOR	23.93

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 37550

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Vehicle has been driven 1020 miles. Checked fluids and tire pressures. Updated oil change sticker. AMG Ronny assisted.

(AGUERRA) Performed checklist. AMG

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 39216

USING DEPT NO: 505161	OPENED DATE: 02/25/2021 15:13:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/05/2021 14:16:20	METER 1 - M: 90833 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/06/2021 10:28:13	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.01	\$0.82	\$33.17	\$0.00	\$33.99
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.01	\$1.08	\$0.00	\$0.00	\$1.08
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.41	\$166.54	\$15.21	\$0.00	\$181.75
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.13	\$132.82	\$410.33	\$0.00	\$543.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$110.89	\$32.85	\$0.00	\$143.74

JOB COUNT: 5	WORK ORDER TOTAL:	3.49	412.15	491.56	0.00	903.71
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/25/2021 07:01:41	03/25/2021 07:02:06	0.01	\$0.82
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/22/2021 09:30:00	03/22/2021 10:14:04	0.73	\$86.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/22/2021 08:51:32	03/22/2021 09:15:00	0.39	\$46.15
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/26/2021 08:04:36	02/26/2021 09:00:59	0.94	\$110.89
09-15	ALIGN STEERING	11170580	03/25/2021 06:59:40	03/25/2021 07:30:16	0.51	\$60.18
06-15	INSPECT STEERING	12052187	03/25/2021 07:02:37	03/25/2021 07:03:10	0.01	\$1.08
09-15	ALIGN STEERING	11170580	03/23/2021 07:00:47	03/23/2021 07:54:52	0.90	\$106.36

LABOR 412.14

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	K72642	REAR WHEEL WALIGNMENT SHIM	15.21	1	\$15.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	53849	TIRE 215/65R16 UNI TIGER PAW	98.70	4	\$394.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.47	5	\$2.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	6	\$26.64
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	6.58	1	\$6.58
03-51-038	REPLACE NEW WIPER BLADES	25-260	BEAM WIPER BLADE	19.67	1	\$19.67
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	6.92	1	\$6.92

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.21	1	\$6.21
PARTS						491.56

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 39216

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

06-15 - INSPECT STEERING

(JWRIGHT) Steering good. JAW,SH

09-15 - ALIGN STEERING

(ABLACK) AB performed alignment. Had to put a shim in on the right rear.

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted and balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Found tires are dry rotted and out of date needs replaced. Coolant -34°. JAW/JAW
MILEAGE-90833

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 40372

USING DEPT NO: 505161	OPENED DATE: 07/06/2021 14:45:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/08/2021 13:34:05	METER 1 - M: 91259 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/09/2021 08:18:34	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.75	\$24.09	\$0.00	\$26.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.46	\$0.00	\$0.00	\$8.46

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.10** **11.21** **24.09** **0.00** **35.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/08/2021 07:40:41	07/08/2021 07:42:05	0.02	\$2.75
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/08/2021 07:36:12	07/08/2021 07:40:30	0.07	\$8.46
					LABOR	11.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	6.92	1	\$6.92
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.84	1	\$9.84
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.33	1	\$7.33
					PARTS	24.09

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 40372

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades front and rear. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 426 miles since last pm. Updated sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-91259

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 42050

USING DEPT NO: 505161	OPENED DATE: 01/11/2022 15:06:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2022 10:38:39	METER 1 - M: 91446 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/14/2022 08:08:18	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.44	\$25.49	\$0.00	\$28.93
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$71.42	\$38.36	\$0.00	\$109.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.13** **133.86** **63.85** **2.00** **199.71**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	01/12/2022 12:31:51	01/12/2022 13:01:51	0.50	\$59.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	01/12/2022 12:31:51	01/12/2022 12:31:51	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	12052187	01/12/2022 12:31:51	01/12/2022 12:31:51	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	01/12/2022 08:58:57	01/12/2022 09:00:42	0.03	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/12/2022 08:22:29	01/12/2022 08:58:48	0.61	\$71.42
LABOR					133.86	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	6	\$26.55
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.59	1	\$7.59
PARTS					63.85	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 42050

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-91446

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 43574

USING DEPT NO: 505161	OPENED DATE: 06/08/2022 11:46:38	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/10/2022 14:19:36	METER 1 - M: 92115 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/13/2022 09:07:38	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.88	\$25.95	\$0.00	\$28.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$19.73	\$0.00	\$0.00	\$19.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.38	\$15.71	\$0.00	\$21.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.24** **27.99** **41.66** **2.00** **71.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/09/2022 08:19:52	06/09/2022 08:22:36	0.05	\$5.38
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/09/2022 07:44:54	06/09/2022 07:46:22	0.02	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/09/2022 07:34:41	06/09/2022 07:44:43	0.17	\$19.73
					LABOR 27.99	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5479	CABIN FILTER	15.71	1	\$15.71
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.73	1	\$7.73
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.40	1	\$10.40
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.82	1	\$7.82
					PARTS 41.66	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 43574

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 669 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(HHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 45154

USING DEPT NO: 505161	OPENED DATE: 11/02/2022 13:02:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/08/2022 07:13:18	METER 1 - M: 95131 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/09/2022 13:48:45	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.24	\$27.86	\$0.00	\$0.00	\$27.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.64	\$55.98	\$0.00	\$98.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.60	70.50	55.98	5.00	131.48
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/02/2022 14:30:00	11/02/2022 14:36:16	0.10	\$12.32
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/02/2022 14:07:06	11/02/2022 14:15:00	0.13	\$15.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2022 13:44:52	11/02/2022 14:06:33	0.36	\$42.64
LABOR					70.50	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
PARTS					55.98	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 45154

Work Order Notes

(CWIGLEY) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 46548

USING DEPT NO: 505161	OPENED DATE: 03/28/2023 15:25:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/31/2023 07:59:10	METER 1 - M: 96194 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/04/2023 13:57:24	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	O	N	GARAGE	0.12	\$14.03	\$0.00	\$0.00	\$14.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.33	\$0.00	\$0.00	\$10.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$45.89	\$0.00	\$0.00	\$45.89

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.60** **70.25** **0.00** **5.00** **75.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11310047	03/30/2023 09:38:01	03/30/2023 09:45:09	0.12	\$14.03
WA-00	WASH COMPLETE VEHICLE	12201267	03/29/2023 07:24:05	03/29/2023 07:47:25	0.39	\$45.89
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/29/2023 07:18:11	03/29/2023 07:23:26	0.09	\$10.33
					LABOR 70.25	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 46548

Work Order Notes

(EHANNAH) pm- replace wipers- wash- air not working

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(EHOWELL) The AC is blowing cold in the front and the back of the vehicle. EH

(LISAPATE) I spoke with Nick the A/C is cooling at this time. Told them when it stops cooling to call me it probably needs freon could be leaking somewhere.

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, tires and tire pressure, filters are good.

Miles, 96,194

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 47882

USING DEPT NO: 505161	OPENED DATE: 08/10/2023 15:35:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/23/2023 10:13:59	METER 1 - M: 98449 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2023 12:03:23	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	1.21	\$142.68	\$27.34	\$0.00	\$170.02
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	N	N	GARAGE	0.22	\$26.16	\$0.00	\$0.00	\$26.16
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	N	N	GARAGE	1.47	\$174.02	\$18.84	\$0.00	\$192.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.54	\$54.45	\$0.00	\$100.99
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.05	\$5.34	\$16.10	\$0.00	\$21.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.17	\$19.50	\$0.00	\$0.00	\$19.50

JOB COUNT: 7 **WORK ORDER TOTAL:** **3.51** **414.24** **116.73** **5.00** **535.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	08/14/2023 12:01:15	08/14/2023 12:01:15	0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11310047	08/14/2023 08:52:18	08/14/2023 10:20:47	1.47	\$174.02
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11310047	08/14/2023 08:39:00	08/14/2023 08:52:18	0.22	\$26.16
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/11/2023 10:43:10	08/11/2023 11:55:43	1.21	\$142.68
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/11/2023 10:40:27	08/11/2023 10:43:10	0.05	\$5.34
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11310047	08/11/2023 09:20:28	08/11/2023 09:20:28	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	08/11/2023 08:30:18	08/11/2023 08:37:49	0.13	\$14.78
WA-00	WASH COMPLETE VEHICLE	11074414	08/11/2023 08:27:54	08/11/2023 08:30:18	0.04	\$4.72
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/11/2023 08:04:14	08/11/2023 08:27:54	0.39	\$46.54
LABOR					414.24	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
-----------------	------------------------	-----------------	--------------------	-------------------	-----------------	-------------------

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	(6)	(\$37.62)
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.11	1	\$1.11
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.99	16	\$15.84
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5479	CABIN FILTER	16.10	1	\$16.10
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.24	1	\$11.24
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.00	1	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.74	1	\$10.74
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	14	\$1.89
					PARTS	116.73

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 47882

Work Order Notes

(EHANNAH) pm- wash- a/c is not working well

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(GARAGE) The AC system was low on refrigerant. Inspected front and rear lines with a black light, but did not find any leaks. (The system has oil with dye in it.) Sprayed multiple locations with bubbly cleaner in an attempt to find a slight leak, but found none. The AC is currently cooling in the front and rear. EH .5 HR

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(GARAGE) Recovered .9 lb. of Freon. Drained .3 oz. of oil. Pulled vacuum and charged to 1.91 lb. Injected 1.0 oz. of oil with dye. EH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/GC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE)

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 48357

USING DEPT NO: 505161	OPENED DATE: 09/28/2023 13:04:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2023 15:23:23	METER 1 - M: 98919 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2023 15:44:35	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-27	REPAIR TRANSMISSION - MAIN, AUTOM	DON	O	N	GARAGE	0.29	\$34.68	\$42.86	\$0.00	\$77.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.29** **34.68** **42.86** **5.00** **82.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-27	REPAIR TRANSMISSION - MAIN, AUTOMATIC	12052187	09/28/2023 13:53:28	09/28/2023 14:11:06	0.29	\$34.68
LABOR						34.68

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-27	REPAIR TRANSMISSION - MAIN, AUTOMATIC	FIXCH1KIT	SHIFT LINKAGE REPAIR KIT	42.86	1	\$42.86
PARTS						42.86

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 48357

Work Order Notes

(EHANNAH) REPAIR TRANSMISSTION SHIFT LINKAGAE

Job Notes

24-27 - REPAIR TRANSMISSION - MAIN, AUTOMATIC

(GARAGE) replaced bushing in shift tower. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 49449

USING DEPT NO: 505161	OPENED DATE: 01/11/2024 09:25:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2024 09:49:46	METER 1 - M: 100055 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2024 14:33:47	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.87	\$19.07	\$0.00	\$22.94
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.15	\$17.14	\$0.00	\$0.00	\$17.14
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.77	\$0.00	\$0.00	\$76.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.14	\$16.82	\$0.00	\$0.00	\$16.82

JOB COUNT: 5	WORK ORDER TOTAL:	0.97	114.60	19.07	5.00	138.67
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	01/12/2024 09:34:22	01/12/2024 09:42:55	0.14	\$16.82
06-13	INSPECT BRAKES	12201267	01/12/2024 09:30:00	01/12/2024 09:34:09	0.07	\$8.16
06-13	INSPECT BRAKES	12201267	01/12/2024 09:10:26	01/12/2024 09:15:00	0.08	\$8.98
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/12/2024 08:12:38	01/12/2024 08:14:36	0.03	\$3.87
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/12/2024 07:14:54	01/12/2024 07:36:10	0.35	\$41.82
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/11/2024 15:17:39	01/11/2024 15:35:25	0.30	\$34.94
LABOR					114.59	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.28	1	\$11.28
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.79	1	\$7.79
PARTS					19.07	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 49449

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

06-13 - INSPECT BRAKES

(GRCOOK) Inspected brakes, also had JW look at brakes also. Found no issues at this time, front brake pads are 6mm and rear shoes are good, test drove and all is good.
-GC

Miles, 100,055

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 1,606 miles, fluids good, filters good, tires and tire pressure, updated oil change sticker.

Miles, 100,055

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 4954

USING DEPT NO: 505161	OPENED DATE: 12/11/2009 09:32:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2009 13:20:54	METER 1 - M: 25925 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/14/2009 13:20:56	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$450.47	\$450.47
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$47.40	\$0.00	\$61.78
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-003	PERFORM SAFETY INSPECTION	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$45.01	\$0.00	\$62.84

JOB COUNT: 5	WORK ORDER TOTAL:	2.56	147.21	92.41	450.47	690.09
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	118459	0006603	\$450.47	
					COMML	450.47

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10041963	12/11/2009 17:00:00	12/11/2009 17:18:36	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11268671	12/11/2009 17:00:00	12/11/2009 18:00:00	1.00	\$57.50
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11268671	12/11/2009 16:00:00	12/11/2009 17:00:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	10041963	12/11/2009 17:18:36	12/11/2009 17:33:36	0.25	\$14.38
					LABOR	147.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	13.14	1	\$13.14
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	21.90	1	\$21.90
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	15.78	1	\$15.78
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	12.36	1	\$12.36
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
					PARTS	92.41

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 4954

Work Order Notes

(LPATE) PM-DO SAFETY INSPECTION GOING TO CHICAGO NEXT WEEK-REPLACE TIRES AND WIPERS

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) FIRESTONE REPLACED 4 TIRES AND ALIGNED P0025720

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY IF

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) PERFORMED SAFETY INSPECTION, NEEDS TIRES, BRAKES ARE GOOD, NEEDS WIPERS, ADDED REGULAR WASHER FLUID, EVERYTHING ELSE LOOKS GOOD AND SAFE

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0

Part 57047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY FC-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 50464

USING DEPT NO: 505161	OPENED DATE: 04/08/2024 07:47:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/09/2024 11:24:25	METER 1 - M: 100785 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/09/2024 13:31:55	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.83	\$98.07	\$0.00	\$0.00	\$98.07

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.83** **98.07** **0.00** **5.00** **103.07**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/09/2024 07:16:39	04/09/2024 07:52:57	0.61	\$71.39
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/09/2024 08:35:17	04/09/2024 08:48:51	0.23	\$26.68
LABOR					98.07	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 50464

Work Order Notes

(EHANNAH) prep for sale

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) Prepare unit for disposal fc

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 539

USING DEPT NO: 505161	OPENED DATE: 12/14/2007 11:37:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/14/2007 15:55:00	METER 1 - M: 4431 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/14/2007 16:00:00	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$27.59	\$0.00	\$41.54

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **13.95** **27.59** **0.00** **41.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	12/14/2007 15:30:00	12/14/2007 15:48:36	0.31	\$13.95
					LABOR	13.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	7.43	1	\$7.43
					PARTS	27.59

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 539

Work Order Notes

(LOBRIEN) PM.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE.

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 5611

USING DEPT NO:	505161	OPENED DATE:	04/14/2010 14:09:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2010 07:32:24	METER 1 - M:	31249	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2010 07:32:25	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$66.90	\$0.00	\$95.65
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$32.78	\$0.00	\$47.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$24.67	\$0.00	\$42.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	60.96	124.35	0.00	185.31
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11046945	04/14/2010 17:00:00	04/14/2010 17:18:36	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11046945	04/14/2010 17:18:36	04/14/2010 17:33:36	0.25	\$14.38
03-32-002	REPLACE NEW BATTERY	11046945	04/14/2010 17:33:36	04/14/2010 18:03:36	0.50	\$28.75
					LABOR	60.96

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	7.39	1	\$7.39
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	192	\$17.28
03-32-002	REPLACE NEW BATTERY	24-6	BATTERY TOP POST	66.90	1	\$66.90
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	20.63	1	\$20.63
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	12.15	1	\$12.15
03-32-002	REPLACE NEW BATTERY	24-6	BATTERY TOP POST	66.90	(1)	(\$66.90)
03-32-002	REPLACE NEW BATTERY	24F-6	BATTERY TOP POST	66.90	1	\$66.90
					PARTS	124.35

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 5611

Work Order Notes

(LPATE) PM-REPALCE WIPERS-TESTED BATTERY DUE TO LEAKING ACID FROM NEAGATIVE POST-FAILED-REPLACE BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30
Qty : 192
Description : OIL BULK
Manufacturer :

Part No : 57047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(LPATE) PM BY BB

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 563

USING DEPT NO: 505161	OPENED DATE: 12/14/2007 09:00:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/19/2007 14:44:39	METER 1 - M: 4431 METER 2 - N: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 12/19/2007 14:44:43	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$13.95	\$26.34	\$0.00	\$40.29

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.31** **13.95** **26.34** **0.00** **40.29**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11088474	12/19/2007 07:00:00	12/19/2007 07:18:36	0.31	\$13.95
					LABOR	13.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	10.74	1	\$10.74
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.08	208	\$15.60
					PARTS	26.34

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 563

Work Order Notes

(LOBRIEN) PM.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LOBRIEN) WHILE CHECKING TIRE PRESSURE, VALVE STEM BROKE (GARAGE TO PAY FOR PART) AND WAS TAKEN TO TUSCALOOSA TOYOTA-REPAIRED. COULD NO GET TO PROGRAM CORRECTLY--TO BE TAKEN BACK TO TOYOTA DEALERSHIP--UNDER WARRANTY--TAKEN BACK TO DEALERSHIP 12/18/07.

(LOBRIEN) 12/19/07 - DEALERSHIP INSTALLED NEW ECM (TIRE PRESSURE)--UNDER WARRANTY.

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE.

(LOBRIEN)

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 6254

USING DEPT NO: 505161	OPENED DATE: 07/19/2010 08:52:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/20/2010 07:53:14	METER 1 - M: 34466 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/20/2010 07:53:16	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$20.02	\$27.96	\$0.00	\$47.98

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.35** **20.02** **27.96** **0.00** **47.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	07/19/2010 08:56:20	07/19/2010 09:17:13	0.35	\$20.02

LABOR **20.02**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	6.12	1	\$6.12
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	208	\$18.72
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	(208)	(\$18.72)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84

PARTS **27.96**

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 6254

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 57047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY JM/TM

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 687

USING DEPT NO:	505161	OPENED DATE:	01/17/2008 14:08:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/18/2008 14:08:35	METER 1 - M:	5700	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/18/2008 14:08:37	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-71-023	REPLACE NEW WINDSHIELD REPLACE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$384.35	\$384.35
16-71-023	TRANSPORT WINDSHIELD REPLACEMI	DON	O	N	GARAGE	0.00	\$0.21	\$0.00	\$0.00	\$0.21

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.21** **0.00** **384.35** **384.56**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-71-023	REPLACE NEW WINDSHIELD REPLACEMENT	11070709	11379	00808	\$384.35
					COMML 384.35

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71-023	TRANSPORT WINDSHIELD REPLACEMENT	11088474	01/18/2008 13:58:31	01/18/2008 13:58:48	0.00	\$0.21
					LABOR	0.21

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 687

Work Order Notes

(RWINTERS) NEEDS WINDSHIELD

Job Notes

03-71-023 - REPLACE NEW WINDSHIELD REPLACEMENT

(RWINTERS) RELIABLE GLASS REPLACED THE WINDSHIELD AND MOULDING

16-71-023 - TRANSPORT WINDSHIELD REPLACEMENT

(RWINTERS) TAKEN TO RELIABLE GLASS.

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 7030

USING DEPT NO:	505161	OPENED DATE:	10/19/2010 15:51:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/22/2010 07:56:10	METER 1 - M:	37661	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/22/2010 07:56:11	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	2.50	\$143.75	\$325.23	\$0.00	\$468.98
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$114.71	\$114.71
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$32.55	\$0.00	\$50.38

JOB COUNT: 5	WORK ORDER TOTAL:	3.81	219.08	357.78	114.71	691.57
---------------------	--------------------------	-------------	---------------	---------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	129406	0009548	\$126.60
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	129409	0009549	(\$92.21)
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	129410	0009550	\$80.32
COMML					114.71

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	10/21/2010 17:00:00	10/21/2010 17:18:36	0.31	\$17.83
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11328035	10/21/2010 17:18:36	10/21/2010 18:18:36	1.00	\$57.50
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11274660	10/21/2010 07:00:00	10/21/2010 09:30:00	2.50	\$143.75
66-79-003	PERFORM SAFETY INSPECTION	11328035	10/20/2010 08:00:25	10/20/2010 08:19:17	(0.31)	(\$18.08)
66-79-003	PERFORM SAFETY INSPECTION	11328035	10/20/2010 08:00:25	10/20/2010 08:19:17	0.31	\$18.08
LABOR					219.08	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	192	\$20.16
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	4.41	1	\$4.41
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	(192)	(\$20.16)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	WOR0841556	HARDWARE KIT	43.98	1	\$43.98
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAB980077	BRAKE ROTOR	90.62	2	\$181.23
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABPGD906AC	FRONT BRAKE PADS	95.61	1	\$95.61
					PARTS	357.78

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 7030

Work Order Notes

(LPATE) PM-SAFETY INSPECTION GOING ON ROAD

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LPATE) REPLACED FRONT PADS AND ROTORS, REAR BRAKES WERE FINE JUST NEEDED CLEANED AND ADJUSTED.

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) WE REMOVED 1 TIRE AND TOOK TO FIRESTONE TO BE REPLACED. P0031736. BILLING ON TIRE WAS DONE WRONG FIRESTONE HAD TO CREDIT AND REBIL TIRE.

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO FIRESTONE BY RS

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) SAFETY INSPECTION COMPLETE NEEDS 1 TIRE REPLACED LEFT FRONT IS AN ODDBALL TIRE AND IS WORN. BRAKES ARE PULSATING DUE TO PADS ARE WORN AND ROTORS ARE WARPED

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY RS/TM

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 7336

USING DEPT NO: 505161	OPENED DATE: 12/09/2010 11:51:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/13/2010 10:14:26	METER 1 - M: 39438 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/13/2010 10:14:28	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$41.25	\$0.00	\$55.63
66-79-003	PERFORM SAFETY INSPECTION	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$30.43	\$0.00	\$48.26

JOB COUNT: 3	WORK ORDER TOTAL:	1.56	89.71	71.68	0.00	161.39
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11338644	12/09/2010 17:00:00	12/09/2010 17:18:36	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11268671	12/09/2010 16:00:00	12/09/2010 17:00:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11338644	12/09/2010 17:00:00	12/09/2010 17:15:00	0.25	\$14.38
					LABOR	89.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.47	1	\$5.47
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	208	\$24.96
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	24.63	1	\$24.63
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.62	1	\$16.62
					PARTS	71.68

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 7336

Work Order Notes

(LPATE) PM-REPLACE WIPERS-DO SAFETY INSPECTION GOING TO CHICAGO NEXT WEEK.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) INSPECTION COMPLETE NO PROBLEMS FOUND

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY RS

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA WORK ORDER NO: 7609

USING DEPT NO:	505161	OPENED DATE:	01/27/2011 10:23:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/28/2011 09:59:17	METER 1 - M:	42251	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/28/2011 09:59:19	IN-SERVICE DATE:	05/11/2007	
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-17-022	RECALL SPARE TIRE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-40-424	RECALL OIL SUPPLY HOSE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-40-424	RECALL OIL SUPPLY HOSE	11076422	TOCS443084	0010543	\$0.00
				COMML	0.00

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 7609

Work Order Notes

(LPATE) RECALLS FROM TOYOTA-LSC 90K-INSTALL OIL HOSE KIT-AND SSE A7E-REPLACE SPARE TIRE CABLE FOR POSSIBLE CORROSION. TRANSPORT TO AND FROM TOYOTA BY FLEET

Job Notes

17-17-022 - RECALL SPARE TIRE

(LPATE) REPLACED FLOOR SEAL KIT. CAMPAIGN COMPLETE

17-40-424 - RECALL OIL SUPPLY HOSE

(LPATE) INSTALLED OIL HOSE KIT. CAMPAIGN COMPLETE

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 8310

USING DEPT NO: 505161	OPENED DATE: 05/09/2011 11:41:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/10/2011 07:48:01	METER 1 - M: 45856 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/10/2011 07:48:03	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$36.72	\$0.00	\$54.55

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **36.72** **0.00** **54.55**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11328035	05/09/2011 17:00:00	05/09/2011 17:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.40	1	\$5.40
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	46673	FILTER-AIR	9.48	1	\$9.48
					PARTS	36.72

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 8310

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY TM-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 8955

USING DEPT NO: 505161	OPENED DATE: 08/18/2011 08:53:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/23/2011 10:21:55	METER 1 - M: 46212 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/23/2011 10:21:59	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.78	\$44.95	\$60.77	\$0.00	\$105.72
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$5.19	\$30.59	\$0.00	\$35.78

JOB COUNT: 3 **WORK ORDER TOTAL:** **1.37** **78.89** **91.36** **0.00** **170.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11338644	08/22/2011 10:46:18	08/22/2011 11:33:12	0.78	\$44.95
03-32-002	REPLACE NEW BATTERY	11338644	08/22/2011 10:46:02	08/22/2011 10:46:08	0.00	(\$0.10)
03-32-002	REPLACE NEW BATTERY	11338644	08/22/2011 10:46:02	08/22/2011 10:46:08	0.00	\$0.10
03-32-002	REPLACE NEW BATTERY	11338644	08/22/2011 10:46:02	08/22/2011 11:16:02	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11338644	08/22/2011 10:40:27	08/22/2011 10:45:52	0.09	\$5.19
					LABOR	78.89

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.63	1	\$5.63
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	208	\$24.96
03-32-002	REPLACE NEW BATTERY	24F-6	BATTERY TOP POST	66.90	1	\$66.90
03-51-038	REPLACE NEW WIPER BLADES	60-2640	WIPER BLADE 26"	27.29	1	\$27.29
03-51-038	REPLACE NEW WIPER BLADES	60-1640	WIPER BLADE	16.74	1	\$16.74
03-51-038	REPLACE NEW WIPER BLADES	41918	WIPER BLADE	16.74	1	\$16.74
03-32-002	REPLACE NEW BATTERY	24F-6	BATTERY TOP POST	66.90	(1)	(\$66.90)
					PARTS	91.36

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 8955

Work Order Notes

(LPATE) PM-REPLACE WIPERS-REPLACE BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY

(RWINTERS) BATTERY WILL BE WARRANTY (16 MONTHS OLD-18 MONTH WARRANTY) 9-6-11 PER RSW. ANGEL WILL DO A SEPT. BILLING ADJUSTMENT. BATTERY WA:
DELETED ON THIS WORK ORDER TO CORRECT INVENTORY.

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED ALL 3 WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(LPATE) PM BY SH/RS

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 9745

USING DEPT NO:	505161	OPENED DATE:	11/22/2011 13:59:46	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	11/23/2011 13:52:26	METER 1 - M:	48336	METER 2 - N:	0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/23/2011 13:52:27	IN-SERVICE DATE:	05/11/2007		
TECH SPEC NO:	07VNTTOYSIENNA	2007 Toyota Sienna		UNIT SERIAL NO:	5TDZK23C07S055039		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$414.91	\$414.91
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	N	N	GARAGE	0.42	\$24.07	\$0.00	\$0.00	\$24.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$35.79	\$32.42	\$0.00	\$68.21

JOB COUNT: 3	WORK ORDER TOTAL:	1.04	59.86	32.42	414.91	507.19
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11122732	143116	0013994	\$414.91
COMML					414.91

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11413680	11/22/2011 14:38:17	11/22/2011 15:03:24	0.42	\$24.07
66-PM-PMA	PERFORM OIL CHANGE	11413680	11/22/2011 15:20:02	11/22/2011 15:57:23	0.62	\$35.79
LABOR					59.86	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.11	208	\$21.84
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
PARTS					32.42	

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 9745

Work Order Notes

(RWINTERS) PM AND ROTATE TIRES

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(RWINTERS) FIRESTONE REPLACED 3 TIRES AND ALIGNED FRONT END.

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(RWINTERS) TAKEN TO FIRESTONE.

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(RWINTERS) CANCEL JOB-NEEDS TIRES

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

Parts For Job Include:

Part 10W-30 OIL BULK Qty 192 Cost 0.06

Part 7047 FILTER-OIL Qty 1 Cost 0

(RWINTERS) PM BY RT

Work Order Charge Detail

UNIT NO: 238240 **2007 TOYOTA SIENNA** **WORK ORDER NO:** 9933

USING DEPT NO: 505161	OPENED DATE: 12/20/2011 14:53:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/03/2012 08:18:58	METER 1 - M: 49556 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/03/2012 08:19:00	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNT0YSIENNA 2007 Toyota Sienna	UNIT SERIAL NO: 5TDZK23C07S055039	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$32.55	\$0.00	\$50.38

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.81** **46.58** **32.55** **0.00** **79.13**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-13	INSPECT BRAKES	11268671	12/20/2011 16:00:00	12/20/2011 16:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11413680	12/20/2011 17:00:00	12/20/2011 17:18:36	0.31	\$17.83
					LABOR	46.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	5.67	1	\$5.67
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	224	\$23.52
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	(224)	(\$23.52)
66-PM-PMA	PERFORM OIL CHANGE	5W20	OIL BOTTLE	0.12	224	\$26.88
					PARTS	32.55

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 9933

Work Order Notes

(LPATE) PM-CHECK BRAKES PER DRIVER HAVE BEEN GRINDING EVERY SINCE HAD TO LOCK UP ABS A FEW WEEKS AGO.

Job Notes

06-13 - INSPECT BRAKES

(LPATE) CHECKED BRAKES, FRONT AND REAR BRAKES CHECKED GOOD, TEST DROVE NO NOISE, CLEANED AND ADJUSTED REDROVE OK.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30
Qty : 192
Description : OIL BULK
Manufacturer :

Part No : 7047
Qty : 1
Description : FILTER-OIL
Manufacturer :

(LPATE) PM BY RT

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 9958

USING DEPT NO: 505161	OPENED DATE: 01/03/2012 14:51:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/05/2012 10:52:33	METER 1 - M: 49556 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/05/2012 10:52:35	IN-SERVICE DATE: 05/11/2007
TECH SPEC NO: 07VNTTOYSIENNA 2007 Toyota Sienna		UNIT SERIAL NO: 5TDZK23C07S055039

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2 **WORK ORDER TOTAL: 1.50 86.25 0.00 0.00 86.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11413680	01/03/2012 17:00:00	01/03/2012 18:00:00	1.00	\$57.50
CH-32-002	CHARGE BATTERY	11413680	01/03/2012 18:00:00	01/03/2012 18:30:00	0.50	\$28.75
					LABOR	86.25

Work Order Charge Detail

UNIT NO: 238240 2007 TOYOTA SIENNA

WORK ORDER NO: 9958

Work Order Notes

Job Notes

66-79-002 - PERFORM SERVICE CALL

(RWINTERS) SVC CALL BEHIND ALUMNI HALL JUMPED OFF VAN AND BROUGHT TO GARAGE.

CH-32-002 - CHARGE BATTERY

(LPATE) CHARGED AND RECHECKED BATTERY IS OK. RIGHT SIDE SLIDING DOOR WAS NOT CLOSED.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Apr 11 2024 16:41:58 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '5TDZK23C07S055039') //Q=