

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 25210

USING DEPT NO:	209301	OPENED DATE:	12/07/2016 08:58:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2016 11:14:46	METER 1 - M:	56	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2016 11:14:47	IN-SERVICE DATE:	12/06/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11170580	12/07/2016 09:03:06	12/07/2016 09:33:06	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 25210

Work Order Notes

(LISAPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 26580

USING DEPT NO: 209301	OPENED DATE: 06/12/2017 13:40:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/26/2017 11:40:34	METER 1 - M: 1699 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/26/2017 11:40:36	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-032	INSTALL TRIM, MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$28.75	\$68.45	\$0.00	\$97.20

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	68.45	0.00	97.20
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-032	INSTALL TRIM, MISCELLANEOUS	11758845	06/22/2017 07:00:00	06/22/2017 08:00:00	(1.00)	(\$57.50)
14-02-032	INSTALL TRIM, MISCELLANEOUS	11758845	06/22/2017 07:00:00	06/22/2017 08:00:00	1.00	\$57.50
14-02-032	INSTALL TRIM, MISCELLANEOUS	11758845	06/22/2017 07:00:00	06/22/2017 07:30:00	0.50	\$28.75
					LABOR	28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-032	INSTALL TRIM, MISCELLANEOUS	PT74703150	REAR BUMPER PROTECTOR	48.45	1	\$48.45
14-02-032	INSTALL TRIM, MISCELLANEOUS	0001632017	BUMPER PROTECTOR	20.00	1	\$20.00
					PARTS	68.45

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 26580

Work Order Notes

(LISAPATE) INSTALL BUMPER PROTECTOR AND BUFF SCRATCHES IN PAINT

Job Notes

14-02-032 - INSTALL TRIM, MISCELLANEOUS

(LISAPATE) INSTALLED PROTECTIVE WRAP ON REAR BUMPER, CLEAR. DRIVER WANTED BLACK. INSTALLED BLACK PROTECTOR ALSO. REMOVED SCUFFS AND SCRATCHES FROM SIDE OF CAR

(RWINTERS) DEALER DISCOUNTED PRICING ON MOLDED BUMPER PROTECTOR.

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 26896

USING DEPT NO: 209301	OPENED DATE: 07/21/2017 16:44:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/24/2017 14:12:35	METER 1 - M: 3836 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/24/2017 14:12:37	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.31	\$17.83	\$0.00	\$0.00	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.44	\$0.00	\$44.27

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.62** **35.66** **26.44** **0.00** **62.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11170580	07/21/2017 16:46:10	07/21/2017 17:04:46	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11170580	07/21/2017 16:45:06	07/21/2017 17:03:42	0.31	\$17.83
					LABOR	35.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	5	\$13.90
					PARTS	26.44

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 26896

Work Order Notes

(LISAPATE) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AB

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 28144

USING DEPT NO: 209301	OPENED DATE: 11/14/2017 10:34:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/17/2017 06:28:41	METER 1 - M: 8831 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/17/2017 06:28:43	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$18.46	\$0.00	\$36.29

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	18.46	0.00	36.29
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/14/2017 10:39:00	11/14/2017 12:59:03	(2.33)	(\$134.21)
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/14/2017 10:39:00	11/14/2017 12:59:03	2.33	\$134.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/14/2017 10:39:00	11/14/2017 10:57:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.77	5	\$13.85
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
					PARTS	18.46

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 28144

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH/CS

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 29460

USING DEPT NO: 209301	OPENED DATE: 04/18/2018 07:40:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/07/2018 09:42:35	METER 1 - M: 13159 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/07/2018 09:42:37	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.75	\$0.00	\$41.58

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	60.96	40.81	0.00	101.77
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/03/2018 06:00:00	05/03/2018 06:18:36	0.31	\$17.83
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11074414	05/03/2018 06:18:36	05/03/2018 06:48:36	0.50	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/03/2018 06:48:36	05/03/2018 07:03:36	0.25	\$14.38
					LABOR	60.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
					PARTS	40.81

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 29460

Work Order Notes

(LISAPATE) PM-ROTATE TIRES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH
COOLANT -35'

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 31379

USING DEPT NO: 209301	OPENED DATE: 11/02/2018 09:25:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/06/2018 06:31:50	METER 1 - M: 18232 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2018 06:31:54	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.70	\$0.00	\$33.04	\$0.00	\$33.04

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.70** **0.00** **33.04** **0.00** **33.04**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/02/2018 09:30:02	11/02/2018 10:12:08	0.70	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	9.26	1	\$9.26
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					PARTS	33.04

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 31379

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Replaced air filter

Coolant -35'

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 32657

USING DEPT NO:	209301	OPENED DATE:	04/17/2019 11:46:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2019 14:02:50	METER 1 - M:	21175	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	04/22/2019 14:02:52	IN-SERVICE DATE:	12/06/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.20	\$0.00	\$0.47	\$0.00	\$0.47
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	4.00	\$0.00	\$0.00	\$0.00	\$0.00
PU-18-003	PURCHASED WHEELS	DON	O	N	GARAGE	0.00	\$0.00	\$73.86	\$0.00	\$73.86

JOB COUNT: 3	WORK ORDER TOTAL:	4.20	0.00	74.33	0.00	74.33
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11074414	04/19/2019 06:00:00	04/19/2019 10:00:00	4.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/19/2019 08:00:00	04/19/2019 08:12:00	0.20	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-18-003	PURCHASED WHEELS	STL69602U45	WHEEL PLAIN STEEL 16X6.5TOYOTA	73.86	1	\$73.86
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	1	\$0.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.20	1	\$0.20
					PARTS	74.33

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 32657

Work Order Notes

(LISAPATE) Danielle requested a service call to the Birmingham Airport. Driver had a flat on the way there. He put the spare on and parked in airport parking prior to flying out for the week. Requested tire be repaired prior to driver returning.

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 1 full size tire to put on car. put spare back in trunk. Rechecked all ok
(RWINTERS) INSTALLED NONSTOCK USED TIRE THAT WAS GOOD. NO CHARGE FOR TIRE.

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SH and EK completed service call left our shop at 5 am in order to miss morning traffic. Went to Birmingham airport and returned.

PU-18-003 - PURCHASED WHEELS

(LISAPATE) Purchased 1 full size wheel to replace donut spare

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 32703

USING DEPT NO: 209301	OPENED DATE: 04/22/2019 14:17:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/25/2019 14:38:13	METER 1 - M: 21258 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/25/2019 14:38:15	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-18	INSPECT WHEELS, RIMS, HUBS & BEAI	DON	O	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.37	\$0.00	\$97.00	\$0.00	\$97.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$0.00	\$23.78	\$0.00	\$23.78

JOB COUNT: 3	WORK ORDER TOTAL:	1.44	0.00	120.78	0.00	120.78
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	04/23/2019 13:37:39	04/23/2019 14:00:00	0.37	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/23/2019 10:19:58	04/23/2019 11:01:00	0.68	\$0.00
06-18	INSPECT WHEELS, RIMS, HUBS & BEARINGS	11074414	04/23/2019 09:56:31	04/23/2019 10:19:44	0.39	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	42830	TIRE P205/65R16 MICH ENERGY S	94.25	1	\$94.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	1	\$2.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
					PARTS	120.78

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 32703

Work Order Notes

(LISAPATE) Vehicle returned from Airport requested we inspect all tires and PM is due

Job Notes

06-18 - INSPECT WHEELS, RIMS, HUBS & BEARINGS

(LISAPATE) Inspected all tires and wheels

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 1 tire. This tire was used for the original rim on LR. Dept asked to keep full size spare.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY**

WORK ORDER NO: 33816

USING DEPT NO: 209301	OPENED DATE: 08/22/2019 11:02:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/27/2019 09:15:19	METER 1 - M: 25802 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/27/2019 09:15:20	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.35	\$0.00	\$36.68	\$0.00	\$36.68
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.26	\$0.00	\$4.89	\$0.00	\$4.89

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.61** **0.00** **41.57** **0.00** **41.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/22/2019 13:57:05	08/22/2019 14:12:40	0.26	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/22/2019 13:14:50	08/22/2019 13:57:05	0.70	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/22/2019 13:14:31	08/22/2019 13:53:12	0.64	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	8.69	1	\$8.69
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
					PARTS	41.57

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 33816

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/AG

Coolant -35'

Replaced air filter

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 35031

USING DEPT NO: 209301	OPENED DATE: 12/03/2019 10:40:45	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/05/2019 07:23:30	METER 1 - M: 31008 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 12/05/2019 07:23:32	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.13	\$0.00	\$17.06	\$0.00	\$17.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.91	\$0.00	\$23.78	\$0.00	\$23.78

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.04** **0.00** **40.84** **0.00** **40.84**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/03/2019 11:16:16	12/03/2019 11:24:14	0.13	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/03/2019 10:48:41	12/03/2019 11:20:52	0.54	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/03/2019 10:53:44	12/03/2019 11:16:16	0.38	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
					PARTS	40.84

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 35031

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW
Coolant -35'

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY WORK ORDER NO: 36776

USING DEPT NO:	209301	OPENED DATE:	06/11/2020 08:06:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/11/2020 10:41:25	METER 1 - M:	33207	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2020 08:13:05	IN-SERVICE DATE:	12/06/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$0.00	\$23.78	\$0.00	\$23.78	
JOB COUNT: 1						WORK ORDER TOTAL:	0.34	0.00	23.78	0.00	23.78

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/11/2020 09:19:48	06/11/2020 09:39:58	0.34	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
					PARTS	23.78

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 36776

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH EK Performed PM. Coolant -35

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 38452

USING DEPT NO: 209301	OPENED DATE: 11/23/2020 07:48:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/24/2020 08:43:50	METER 1 - M: 33212 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/25/2020 07:59:13	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.98	\$0.00	\$0.00	\$12.98

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.11** **12.98** **0.00** **0.00** **12.98**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/23/2020 12:16:15	11/23/2020 12:22:51	0.11	\$12.98
					LABOR	12.98

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 38452

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 5 miles since last pm. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW

MILEAGE 8575

(JWRIGHT) MILEAGE 33212

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 39589

USING DEPT NO:	209301	OPENED DATE:	04/07/2021 13:39:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/08/2021 13:28:54	METER 1 - M:	33217	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/09/2021 10:28:09	IN-SERVICE DATE:	12/06/2016		
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.18	\$20.72	\$113.55	\$0.00	\$134.27
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$86.37	\$30.07	\$0.00	\$116.44

JOB COUNT: 3	WORK ORDER TOTAL:	1.41	166.09	143.62	0.00	309.71
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11915538	04/08/2021 07:00:00	04/08/2021 07:30:00	0.50	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/08/2021 07:07:10	04/08/2021 07:51:05	0.73	\$86.37
03-32-002	REPLACE NEW BATTERY	11074414	04/07/2021 15:34:08	04/07/2021 15:44:40	0.18	\$20.72
					LABOR	166.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
					PARTS	143.62

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 39589

Work Order Notes

(LISAPATE) PM-Mandy requested a service call to University Hall car has a dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Battery was 4 years old original battery tested bad. Installed a new battery. SH

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Drivers jumped off and brought car to the shop

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH,RC/JAW
MILEAGE-33217

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 41011

USING DEPT NO: 209301	OPENED DATE: 09/14/2021 07:56:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/20/2021 08:38:27	METER 1 - M: 34188 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/20/2021 12:10:38	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.70	\$17.90	\$0.00	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.37	\$0.00	\$0.00	\$43.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	49.07	17.90	2.00	68.97
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/16/2021 14:20:25	09/16/2021 14:42:28	0.37	\$43.37
03-51-038	REPLACE NEW WIPER BLADES	11901357	09/16/2021 14:17:15	09/16/2021 14:20:09	0.05	\$5.70
LABOR					49.07	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
PARTS					17.90	

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 41011

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 34188 Vehicle has been 971 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 42367

USING DEPT NO: 209301	OPENED DATE: 02/15/2022 08:40:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/16/2022 15:14:58	METER 1 - M: 34789 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/18/2022 08:03:49	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.21	\$17.90	\$0.00	\$23.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.71	\$49.55	\$0.00	\$108.26
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$0.69	\$12.23	\$0.00	\$12.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.55	64.61	79.68	2.00	146.29
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/15/2022 15:02:51	02/15/2022 15:03:12	0.01	\$0.69
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/15/2022 15:00:01	02/15/2022 15:02:40	0.04	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/15/2022 14:30:00	02/15/2022 14:59:51	0.50	\$58.71
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/15/2022 14:27:17	02/15/2022 14:27:17	0.00	\$0.00
					LABOR	64.61

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	14.51	1	\$14.51
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	12.23	1	\$12.23
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
					PARTS	79.68

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 42367

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 44122

USING DEPT NO:	209301	OPENED DATE:	07/29/2022 11:56:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/08/2022 08:59:25	METER 1 - M:	36269	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/08/2022 14:21:54	IN-SERVICE DATE:	12/06/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.42	\$18.33	\$0.00	\$24.75
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.51	\$60.67	\$0.00	\$0.00	\$60.67
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.60	\$71.23	\$0.00	\$0.00	\$71.23
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.85	\$100.53	\$510.33	\$0.00	\$610.86
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.26	\$34.90	\$0.00	\$90.16
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.49	294.11	563.56	2.00	859.67
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	08/04/2022 09:43:15	08/04/2022 10:19:28	0.60	\$71.23
06-15	INSPECT STEERING	11901357	08/03/2022 15:16:10	08/03/2022 15:47:01	0.51	\$60.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	08/03/2022 14:24:48	08/03/2022 15:15:55	0.85	\$100.53
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/01/2022 09:26:53	08/01/2022 09:54:59	0.47	\$55.26
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/01/2022 09:23:23	08/01/2022 09:26:39	0.05	\$6.42
					LABOR	294.11

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	2	\$1.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	76774	TIRE UNIROYAL P205/65R15	120.87	4	\$483.48

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.52	4	\$22.08
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.56	1	\$10.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.77	1	\$7.77
PARTS						563.56

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 44122

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

06-15 - INSPECT STEERING

(AGUERRA) Checked steering, no issues found. AMG

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed 4-wheel alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Mounted and balanced 4 new tires. AMG SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 36269 Completed PM top and bottom side. Completed checklist. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 45758

USING DEPT NO: 209301	OPENED DATE: 01/11/2023 08:17:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2023 14:00:59	METER 1 - M: 37648 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/17/2023 09:24:08	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.80	\$0.00	\$0.00	\$25.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.22** **25.80** **0.00** **5.00** **30.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/11/2023 15:22:35	01/11/2023 15:35:42	0.22	\$25.80
LABOR						25.80

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 45758

Work Order Notes

(EHANNAH) pm- replace wipers
(GARAGE) wipers good-GC

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC fluid check only, battery good filters good, tires and tire pressure good
Miles- 37,648

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 47185

USING DEPT NO: 209301	OPENED DATE: 05/30/2023 08:11:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/02/2023 15:29:19	METER 1 - M: 38849 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/05/2023 10:45:33	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry	UNIT SERIAL NO: 4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.03	\$23.96	\$0.00	\$25.99
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.44	\$52.02	\$0.00	\$0.00	\$52.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$48.43	\$0.00	\$87.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.44	\$51.36	\$0.00	\$0.00	\$51.36

JOB COUNT: 5	WORK ORDER TOTAL:	1.22	144.35	72.39	5.00	221.74
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12201267	05/30/2023 09:57:32	05/30/2023 10:23:59	0.44	\$52.02
WA-00	WASH COMPLETE VEHICLE	12201267	05/30/2023 09:31:14	05/30/2023 09:57:21	0.44	\$51.36
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/30/2023 09:30:00	05/30/2023 09:31:02	0.02	\$2.03
03-51-038	REPLACE NEW WIPER BLADES	12201267	05/30/2023 09:27:30	05/30/2023 09:27:30	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/30/2023 09:16:37	05/30/2023 09:36:25	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/30/2023 09:16:37	05/30/2023 09:16:37	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/30/2023 09:16:37	05/30/2023 09:16:37	0.00	\$0.00
					LABOR	144.35

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.73	1	\$10.73
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32

Work Order Charge Detail

PARTS

72.39

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 47185

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed Safety inspection, found no issues at this time-GC
Brake pads are all 8mm on all 4 wheels.
Miles, 38,849

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 38,849

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 242168 **2017 TOYOTA CAMRY** **WORK ORDER NO:** 48495

USING DEPT NO:	209301	OPENED DATE:	10/10/2023 13:03:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2023 15:29:17	METER 1 - M:	42810	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/16/2023 07:45:59	IN-SERVICE DATE:	12/06/2016	
TECH SPEC NO:	17TOYOTACAMRY	2017 Toyota Camry		UNIT SERIAL NO:	4T1BF1FK9HU361023	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$29.50	\$24.08	\$0.00	\$53.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.42	\$76.73	\$0.00	\$109.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.64	\$75.55	\$0.00	\$0.00	\$75.55

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.17** **137.47** **100.81** **5.00** **243.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/12/2023 10:10:33	10/12/2023 10:48:58	0.64	\$75.55
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/12/2023 09:19:01	10/12/2023 09:19:01	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/12/2023 09:19:01	10/12/2023 09:19:01	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/12/2023 09:19:01	10/12/2023 09:34:01	0.25	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/12/2023 08:58:31	10/12/2023 09:15:00	0.27	\$32.42
					LABOR 137.47	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.92	1	\$10.92
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	16.56	1	\$16.56
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
					PARTS 100.81	

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 48495

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Did not wash. Buses lined up to be washed. SH

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 50389

USING DEPT NO: 209301	OPENED DATE: 04/02/2024 13:02:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/09/2024 11:21:35	METER 1 - M: 45775 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/09/2024 13:31:27	IN-SERVICE DATE: 12/06/2016
TECH SPEC NO: 17TOYOTACAMRY 2017 Toyota Camry		UNIT SERIAL NO: 4T1BF1FK9HU361023

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.44	\$52.12	\$0.00	\$0.00	\$52.12

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.44** **52.12** **0.00** **5.00** **57.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/09/2024 08:58:44	04/09/2024 09:15:00	0.27	\$31.99
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	04/09/2024 09:30:00	04/09/2024 09:40:14	0.17	\$20.13
LABOR					52.12	

Work Order Charge Detail

UNIT NO: 242168 2017 TOYOTA CAMRY

WORK ORDER NO: 50389

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) Prepare unit for disposal FC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Apr 11 2024 11:37:53 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1BF1FK9HU361023') //Q=