

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 35204

USING DEPT NO: 507201	OPENED DATE: 12/16/2019 13:57:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/19/2019 06:52:24	METER 1 - M: 57 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/19/2019 06:52:26	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN8LX169759	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11170580	12/16/2019 13:58:54	12/16/2019 14:28:54	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 35204

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) AB completed PDI

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 36090

USING DEPT NO:	507201	OPENED DATE:	04/02/2020 13:07:05	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/06/2020 08:54:43	METER 1 - M:	904	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2020 09:16:35	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	P	N	GARAGE	6.36	\$461.26	\$623.11	\$0.00	\$1,084.37

JOB COUNT: 1	WORK ORDER TOTAL:					6.36	461.26	623.11	0.00	1,084.37
---------------------	--------------------------	--	--	--	--	-------------	---------------	---------------	-------------	-----------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11901357	04/02/2020 14:15:29	04/02/2020 15:57:23	1.70	\$123.13
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/03/2020 10:09:22	04/03/2020 11:21:45	1.21	\$87.46
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/03/2020 13:00:32	04/03/2020 15:31:47	2.52	\$182.76
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 07:29:31	04/06/2020 08:22:26	0.88	\$63.94
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11901357	04/02/2020 13:48:45	04/02/2020 13:52:02	0.05	\$3.97
					LABOR	461.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	6.81	1	\$6.81
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5141A	3/8 CONVOLUTED TUBING 50FT	16.46	2	\$32.91
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	122.55	2	\$245.10
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	147.90	2	\$295.80
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.57	1	\$0.57
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81187S	PRIMARY WIRE 18 GA WHITE 100'	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8222A	3/8IN BLACK SHRINK TUBE 4FT	5.52	2	\$11.04
					PARTS	623.11

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 36090

Work Order Notes

(IFALLS) INSTALL STROBE LIGHTS

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(IFALLS) AG/AB installed front and rear strobe lights

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 36255

USING DEPT NO:	507201	OPENED DATE:	04/29/2020 08:38:08	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2020 11:42:08	METER 1 - M:	960	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2020 08:28:25	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$31.54	\$53.77	\$0.00	\$85.31

JOB COUNT: 1 **WORK ORDER TOTAL: 0.44 31.54 53.77 0.00 85.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/29/2020 10:05:51	04/29/2020 10:31:57	0.44	\$31.54
					LABOR	31.54

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	7	\$40.85
					PARTS	53.77

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 36255

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) JW performed pm service

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 37735

USING DEPT NO: 507201	OPENED DATE: 09/24/2020 10:33:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2020 08:50:20	METER 1 - M: 2776 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2020 10:07:50	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN8LX169759

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$29.08	\$41.49	\$0.00	\$70.57
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.06	\$4.67	\$13.59	\$0.00	\$18.26

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.47** **33.75** **55.08** **0.00** **88.83**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/25/2020 14:30:00	09/25/2020 14:32:06	0.04	\$2.54
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/25/2020 14:50:56	09/25/2020 15:04:13	0.22	\$16.05
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	09/25/2020 14:32:29	09/25/2020 14:36:21	0.06	\$4.67
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/25/2020 14:06:19	09/25/2020 14:15:00	0.14	\$10.49
					LABOR	33.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
					PARTS	55.08

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 37735

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Completed checklist. AMG Josh was bottom side.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter 4871

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 39094

USING DEPT NO:	507201	OPENED DATE:	02/12/2021 07:26:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2021 09:50:31	METER 1 - M:	4251	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2021 12:33:07	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$6.46	\$0.00	\$0.00	\$6.46

JOB COUNT: 1	WORK ORDER TOTAL:					0.05	6.46	0.00	0.00	6.46
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/12/2021 10:34:36	02/12/2021 10:37:53	0.05	\$6.46
					LABOR	6.46

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 39094

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1475 miles since last pm. Updated pm sticker. Checked all tires and fluids. MS,JAW

Coolant-34

MILEAGE-4251

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 40380

USING DEPT NO:	507201	OPENED DATE:	07/07/2021 11:48:57	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2021 13:46:12	METER 1 - M:	5768	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/09/2021 08:13:31	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.83	\$14.66	\$0.00	\$26.49
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.04	\$4.75	\$7.53	\$0.00	\$12.28
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.31	\$36.06	\$0.00	\$0.00	\$36.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$61.98	\$42.29	\$0.00	\$104.27

JOB COUNT: 4	WORK ORDER TOTAL:	0.97	114.62	64.48	0.00	179.10
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11901357	07/07/2021 13:07:53	07/07/2021 13:10:18	0.04	\$4.75
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/07/2021 14:03:42	07/07/2021 14:09:43	0.10	\$11.83
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	07/07/2021 14:09:59	07/07/2021 14:28:19	0.31	\$36.06
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/07/2021 12:35:56	07/07/2021 13:07:27	0.53	\$61.98
					LABOR	114.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.33	1	\$7.33
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	7.53	1	\$7.53
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	6	\$37.89
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.40	1	\$4.40
					PARTS	64.48

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 40380

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter.AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5768 Completed PM bottom and topside, Josh filled with oil. Completed checklist and vacuumed out vehicle. AMG JW/ AMG

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 41839

USING DEPT NO: 507201	OPENED DATE: 12/10/2021 07:13:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/13/2021 07:57:33	METER 1 - M: 8314 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/13/2021 13:34:53	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN8LX169759

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.02	\$15.18	\$0.00	\$18.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.83	\$31.49	\$0.00	\$71.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.36	42.85	46.67	2.00	91.52
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/10/2021 09:26:25	12/10/2021 09:27:57	0.03	\$3.02
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/10/2021 09:05:59	12/10/2021 09:26:14	0.34	\$39.83
LABOR					42.85	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.58	1	\$4.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	(1)	(\$7.59)
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.58	1	\$7.58
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.58	(1)	(\$7.58)
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
PARTS					46.67	

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 41839

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW
MILEAGE-8314

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 43184

USING DEPT NO:	507201	OPENED DATE:	05/10/2022 12:40:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2022 14:29:29	METER 1 - M:	10325	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2022 13:31:03	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.59	\$15.18	\$0.00	\$15.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.23	\$31.97	\$0.00	\$101.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.59	69.82	47.15	2.00	118.97
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/10/2022 14:30:16	05/10/2022 14:50:43	0.34	\$40.22
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/10/2022 14:45:40	05/10/2022 14:45:58	0.01	\$0.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2022 14:30:44	05/10/2022 14:45:29	0.25	\$29.01
LABOR					69.82	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
PARTS					47.15	

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 43184

Work Order Notes

(CWIGLEY) PM-Replace Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) JW Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH JW/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 44589

USING DEPT NO:	507201	OPENED DATE:	09/07/2022 08:14:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2022 10:25:41	METER 1 - M:	11882	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 13:47:37	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.62	\$0.00	\$33.32
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.75	\$88.70	\$0.00	\$0.00	\$88.70
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.80	\$94.40	\$811.79	\$0.00	\$906.19
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.31	\$36.94	\$0.00	\$0.00	\$36.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7 **WORK ORDER TOTAL: 2.84 335.68 827.41 5.00 1,168.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12296277	09/12/2022 07:09:00	09/12/2022 07:28:48	0.33	\$38.94
03-51-038	REPLACE NEW WIPER BLADES	12296277	09/12/2022 07:00:00	09/12/2022 07:09:00	0.15	\$17.70
66-17-013	PERFORM ALIGNMENT	11310047	09/09/2022 07:16:16	09/09/2022 08:01:22	0.75	\$88.70
66-79-003	PERFORM SAFETY INSPECTION	12296277	09/07/2022 10:49:43	09/07/2022 11:08:30	0.31	\$36.94
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	09/12/2022 07:00:00	09/12/2022 07:48:00	0.80	\$94.40
06-15	INSPECT STEERING	12296277	09/12/2022 07:00:00	09/12/2022 07:30:00	0.50	\$59.00
					LABOR	335.68

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	3	\$1.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	2	\$1.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	3	\$2.43

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.80	1	\$7.80
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04504620000	GEN GRABBER 245/75R16	195.75	4	\$783.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.88	4	\$23.52
PARTS						827.41

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 44589

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI-TPMS light keeps coming on
(GARAGE) checker replaced wiper blades tire light on needs 4 tires cause of wear

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blades jdm.

06-15 - INSPECT STEERING

(GARAGE) inspected steering all boots are good none are torn JDM

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) replaced all 4 tires and balanced them JDM

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) 4 tires and alignmentjdm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) checker checked all fluids jdm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 46145

USING DEPT NO:	507201	OPENED DATE:	02/14/2023 09:31:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/16/2023 10:00:01	METER 1 - M:	14037	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/16/2023 10:48:03	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN8LX169759	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.39	\$15.64	\$0.00	\$20.03
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.28	\$33.53	\$0.00	\$0.00	\$33.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$26.03	\$73.34	\$0.00	\$99.37
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.03	\$3.74	\$11.79	\$0.00	\$15.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.57	67.69	100.77	5.00	173.46
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/14/2023 11:16:11	02/14/2023 11:25:15	0.15	\$17.83
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/14/2023 10:36:05	02/14/2023 10:44:04	0.13	\$15.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/14/2023 10:28:22	02/14/2023 10:30:16	0.03	\$3.74
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/14/2023 10:25:57	02/14/2023 10:28:11	0.04	\$4.39
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/14/2023 10:12:31	02/14/2023 10:25:45	0.22	\$26.03
					LABOR	67.69

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.09	1	\$6.09
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.81	6	\$40.86
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	11.79	1	\$11.79
					PARTS	100.77

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 46145

Work Order Notes

(EHANNAH) pm- Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 47490

USING DEPT NO: 507201	OPENED DATE: 06/30/2023 08:53:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/06/2023 09:56:58	METER 1 - M: 15544 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2023 10:30:16	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN8LX169759

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.13	\$26.94	\$0.00	\$82.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.47	55.13	26.94	5.00	87.07
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11310047	06/30/2023 11:15:35	06/30/2023 11:15:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11310047	06/30/2023 10:31:58	06/30/2023 11:00:00	0.47	\$55.13
LABOR					55.13	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
PARTS					26.94	

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 47490

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Mileage-15544

The vehicle has been driven 1507 miles and the oil was dropped on the last visit.

Checked fluids, tire pressures, battery, and updated sticker. EH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(EHOWELL) Washed vehicle. EH

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 49136

USING DEPT NO: 507201	OPENED DATE: 12/04/2023 07:41:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/06/2023 13:08:20	METER 1 - M: 17653 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/06/2023 13:57:50	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN8LX169759	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.97	\$16.66	\$0.00	\$22.63
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.40	\$47.20	\$0.00	\$0.00	\$47.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.63	\$44.01	\$0.00	\$83.64
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.15	\$17.70	\$11.79	\$0.00	\$29.49
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.47	\$55.20	\$0.00	\$0.00	\$55.20

JOB COUNT: 6	WORK ORDER TOTAL:	1.40	165.70	72.46	5.00	243.16
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	12/04/2023 11:42:50	12/04/2023 11:54:01	0.19	\$21.99
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	12/04/2023 11:18:38	12/04/2023 11:42:38	0.40	\$47.20
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/04/2023 11:11:24	12/04/2023 11:14:26	0.05	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2023 10:51:03	12/04/2023 11:11:12	0.34	\$39.63
WA-00	WASH COMPLETE VEHICLE	11074414	12/04/2023 12:58:09	12/04/2023 12:58:09	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	12/04/2023 13:00:00	12/04/2023 13:16:53	0.28	\$33.20
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	12/05/2023 07:00:00	12/05/2023 07:09:00	0.15	\$17.70
					LABOR	165.69

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	24871	CABIN FILTER-TACOMA	11.79	(1)	(\$11.79)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	(1)	(\$11.79)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
					PARTS	72.46

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 49136

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) SH REPLACED CABIN FILTER

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed and filled with gas. SH

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 50584

USING DEPT NO: 507201	OPENED DATE: 04/16/2024 07:40:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/17/2024 11:48:25	METER 1 - M: 18654 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/18/2024 07:09:07	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN8LX169759

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.29	\$2.29
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.29	\$0.00	\$0.00	\$2.29

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.02** **2.29** **0.00** **2.29** **4.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.29
				COMML	2.29

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11074414	04/16/2024 11:11:22	04/16/2024 11:12:32	0.02	\$2.29
					LABOR	2.29

Work Order Charge Detail

UNIT NO: 243617 2020 TOYOTA TACOMA

WORK ORDER NO: 50584

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Performed a prep for sale. Removed the tag insurance cards and word marks. SH

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Apr 19 2024 13:29:09 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '5TFRX5GN8LX169759') //Q=