

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 35999

USING DEPT NO: 507201	OPENED DATE: 03/11/2020 15:37:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/11/2020 15:38:37	METER 1 - M: 144 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/06/2020 15:00:23	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.50	\$36.25	\$7.35	\$0.00	\$43.60
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **72.50** **7.35** **0.00** **79.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	11074414	03/11/2020 16:00:00	03/11/2020 16:30:00	0.50	\$36.25
14-02-013	INSTALL FLOOR COVERINGS	11074414	03/12/2020 06:00:00	03/12/2020 06:30:00	(0.50)	(\$36.25)
14-02-013	INSTALL FLOOR COVERINGS	11074414	03/12/2020 06:00:00	03/12/2020 06:30:00	0.50	\$36.25
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11915538	03/11/2020 15:37:56	03/11/2020 16:07:56	0.50	\$36.25
					LABOR	72.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-02-013	INSTALL FLOOR COVERINGS	W715120SSA	FLOOR MAT RETAINER FORD	3.68	2	\$7.35
					PARTS	7.35

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 35999

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(LISAPATE) Installed clips for driver floor mat

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 37040

USING DEPT NO: 507201	OPENED DATE: 07/07/2020 09:05:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/07/2020 11:01:58	METER 1 - M: 1419 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/08/2020 08:16:40	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$37.72	\$0.00	\$0.00	\$37.72

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.52** **37.72** **0.00** **0.00** **37.72**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/07/2020 09:36:23	07/07/2020 10:07:36	0.52	\$37.72
					LABOR	37.72

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 37040

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Did not drop oil at this time. Checked fluids, tire pressures and battery. Updated sticker

Coolant -34'

SH/JW

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 38217

Work Order Notes

(LISAPATE) Per driver Back up camera is inop

Contact BJ 8-4555

Job Notes

06-52-024 - INSPECT BACK UP CAMERA

(ABLACK) AB found backup camera not working. tapped on back up camera and it started working. Suspect vehicle will need a new backup camera. If it goes out again we will send vehicle to dealer to have it warrantied.

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 38394

USING DEPT NO: 507201	OPENED DATE: 11/16/2020 12:21:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/17/2020 11:43:12	METER 1 - M: 2591 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/18/2020 07:40:44	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.33	\$157.37	\$48.33	\$0.00	\$205.70

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.33** **157.37** **48.33** **0.00** **205.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/16/2020 14:30:00	11/16/2020 15:03:21	0.56	\$65.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/16/2020 13:52:25	11/16/2020 14:15:00	0.38	\$44.41
66-PM-PMA	PERFORM OIL CHANGE	11170580	11/16/2020 13:50:55	11/16/2020 14:15:00	0.40	\$47.36
					LABOR	157.36

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	8.37	1	\$8.37
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	9	\$39.96
					PARTS	48.33

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 38394

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(ABLACK) AB did top SH did bottom, was vacuumed, fueled up and washed.

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 38821

USING DEPT NO: 507201	OPENED DATE: 01/19/2021 08:48:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/21/2021 15:05:24	METER 1 - M: 2777 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/22/2021 14:35:57	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-52	TRANSPORT ELECTRICAL ACCESSORI	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
17-52-024	RECALL BACK UP CAMERA	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **0.00** **118.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-52-024	RECALL BACK UP CAMERA	4910000	609631		\$0.00
					COMML 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-52	TRANSPORT ELECTRICAL ACCESSORIES	10208562	01/21/2021 07:00:00	01/21/2021 08:00:00	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 38821

Work Order Notes

(LISAPATE) Take to Town and Country Ford for Recall 20C19 the rear view camera could intermittently display a blank or distorted image

Job Notes

16-52 - TRANSPORT ELECTRICAL ACCESSORIES

(LISAPATE) Taken to Town and Country by drivers

17-52-024 - RECALL BACK UP CAMERA

(LISAPATE) Town and Country completed recall for 20C19 rear view camera improper function

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 39775

USING DEPT NO:	507201	OPENED DATE:	04/22/2021 08:38:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2021 15:08:09	METER 1 - M:	3285	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2021 08:20:24	IN-SERVICE DATE:	03/10/2020	
TECH SPEC NO:	20FORDF1504X4	2020 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$59.69	\$0.00	\$0.00	\$59.69

JOB COUNT: 1 WORK ORDER TOTAL: 0.51 59.69 0.00 0.00 59.69

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2021 09:30:00	04/22/2021 09:41:18	0.19	\$22.22
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2021 08:55:57	04/22/2021 09:15:00	0.32	\$37.47
					LABOR	59.69

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 39775

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 3285. Vehicle has been driven 694 miles since last PM. Checked fluids battery tire pressure updated oil change sticker washed and vacuumed. SH

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 40425

USING DEPT NO: 507201	OPENED DATE: 07/14/2021 08:34:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/15/2021 13:54:04	METER 1 - M: 3564 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/16/2021 11:41:10	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	DON	O	N	GARAGE	0.59	\$69.88	\$0.00	\$0.00	\$69.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.14	\$16.49	\$37.46	\$0.00	\$53.95
CL-01-010	CLEANED EVAPORATOR	DON	O	N	GARAGE	0.97	\$114.98	\$24.68	\$0.00	\$139.66

JOB COUNT: 3	WORK ORDER TOTAL:	1.71	201.35	62.14	0.00	263.49
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CL-01-010	CLEANED EVAPORATOR	11213180	07/14/2021 09:38:30	07/14/2021 10:36:58	0.97	\$114.98
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11213180	07/14/2021 09:30:00	07/14/2021 09:38:23	0.14	\$16.49
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11213180	07/14/2021 09:22:07	07/14/2021 09:22:07	0.00	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11213180	07/14/2021 08:39:28	07/14/2021 09:15:00	0.59	\$69.88
					LABOR	201.35

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	WP10266	CABIN AIR FILTER	37.46	1	\$37.46
CL-01-010	CLEANED EVAPORATOR	7656000	A/C VENT DEODORIZER	8.33	1	\$8.33
CL-01-010	CLEANED EVAPORATOR	FJC5914	EVAPORATOR CLEANER	16.35	1	\$16.35
					PARTS	62.14

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 40425

Work Order Notes

(LISAPATE) Per driver smelling a weird smell thru the vents almost like vinegar smell.

Job Notes

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(MSIDES) Found cabin filter to be dirty also recommend evaporator clean and A/C duct deodorizer to help clean duct work. MS

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(MSIDES) Replaced cabin filter. MS

CL-01-010 - CLEANED EVAPORATOR

(MSIDES) Cleaned evaporator core and deodorize all duct work in dash. MS

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 41311

USING DEPT NO: 507201	OPENED DATE: 10/13/2021 11:25:16	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/14/2021 07:53:38	METER 1 - M: 4558 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/14/2021 09:11:22	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.61	\$15.18	\$0.00	\$18.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$45.17	\$44.68	\$0.00	\$89.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.41** **48.78** **59.86** **2.00** **110.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/13/2021 12:58:24	10/13/2021 13:00:14	0.03	\$3.61
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/13/2021 12:35:15	10/13/2021 12:58:13	0.38	\$45.17
LABOR					48.78	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	4.85	1	\$4.85
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	9	\$39.83
PARTS					59.86	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 41311

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. AB/JAW
MILEAGE-4558

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 42049

USING DEPT NO: 507201	OPENED DATE: 01/11/2022 14:59:37	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2022 10:37:29	METER 1 - M: 5683 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/14/2022 08:10:39	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-016	REPLACE NEW TAIL&LIFT GATE	DON	O	N	GARAGE	0.50	\$59.00	\$750.00	\$0.00	\$809.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.00** **750.00** **2.00** **811.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-016	REPLACE NEW TAIL&LIFT GATE	11915538	01/12/2022 09:24:50	01/12/2022 09:39:50	(0.25)	(\$29.50)
03-02-016	REPLACE NEW TAIL&LIFT GATE	11915538	01/12/2022 09:24:50	01/12/2022 09:39:50	0.25	\$29.50
03-02-016	REPLACE NEW TAIL&LIFT GATE	11915538	01/12/2022 09:24:50	01/12/2022 09:24:50	0.00	\$0.00
03-02-016	REPLACE NEW TAIL&LIFT GATE	11915538	01/12/2022 09:24:50	01/12/2022 09:24:50	0.00	\$0.00
03-02-016	REPLACE NEW TAIL&LIFT GATE	11915538	01/12/2022 09:24:50	01/12/2022 09:54:50	0.50	\$59.00
LABOR						59.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-016	REPLACE NEW TAIL&LIFT GATE	FORD F150 TAILGATE	TAILGATE	750.00	1	\$750.00
PARTS						750.00

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 42049

Work Order Notes

(IFALLS) Dept damaged tailgate of truck remove and install used new tailgate assy
(IFALLS) Issac had to change the internal parts from the old gate to the new gate

Job Notes

03-02-016 - REPLACE NEW TAIL&LIFT GATE

(GARAGE) replaced tailgate \\F\RC\CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 42636

USING DEPT NO: 507201	OPENED DATE: 03/10/2022 09:28:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/10/2022 13:52:09	METER 1 - M: 8208 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/11/2022 08:06:00	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.92	\$15.18	\$0.00	\$20.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.05	\$45.58	\$0.00	\$105.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.55** **64.97** **60.76** **2.00** **127.73**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/10/2022 10:23:33	03/10/2022 10:26:03	0.04	\$4.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/10/2022 09:52:50	03/10/2022 10:23:22	0.51	\$60.05
LABOR					64.97	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.75	1	\$5.75
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	9	\$39.83
PARTS					60.76	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 42636

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) JW/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 44234

USING DEPT NO: 507201	OPENED DATE: 08/10/2022 07:08:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/15/2022 13:11:51	METER 1 - M: 13252 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 08/18/2022 14:44:21	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$18.06	\$15.15	\$0.00	\$33.21
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.44	\$51.59	\$0.00	\$0.00	\$51.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$65.06	\$72.99	\$0.00	\$138.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	1.49	\$175.89	\$0.00	\$0.00	\$175.89

JOB COUNT: 5	WORK ORDER TOTAL:	2.63	310.60	88.14	2.00	400.74
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-00	SCAN OUT COMPLETE VEHICLE	11213180	08/10/2022 07:45:34	08/10/2022 09:15:00	1.49	\$175.89
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/10/2022 08:13:53	08/10/2022 08:40:07	0.44	\$51.59
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/10/2022 08:04:29	08/10/2022 08:13:40	0.15	\$18.06
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/10/2022 07:37:27	08/10/2022 08:05:25	0.47	\$55.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2022 07:59:08	08/10/2022 08:04:15	0.09	\$10.06
					LABOR	310.60

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.58	2	\$15.15
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	10.92	1	\$10.92
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	9	\$54.81
					PARTS	88.14

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 44234

Work Order Notes

(LRUSHING) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(HHARBIN) Rotated tires relearned tire positions and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(MSIDES) Scanned vehicle and found code P0390 - Camshaft position sensor "B" circuit (Bank 2) stored in the PCM. Could not find and diag info on repair manuals will need to be sent to dealer. MS

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 44298

USING DEPT NO: 507201	OPENED DATE: 08/15/2022 13:12:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/19/2022 11:32:33	METER 1 - M: 13390 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2022 08:56:21	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-33	DIAGNOSE IGNITION SYSTEM	DON	O	N	GARAGE	1.10	\$129.60	\$0.00	\$0.00	\$129.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.41	\$166.22	\$0.00	\$0.00	\$166.22

JOB COUNT: 3 **WORK ORDER TOTAL:** **2.51** **295.82** **0.00** **2.00** **297.82**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	08/16/2022 09:27:20	08/16/2022 10:51:51	1.41	\$166.22
35-33	DIAGNOSE IGNITION SYSTEM	11213180	08/16/2022 08:21:26	08/16/2022 09:27:20	1.10	\$129.60
LABOR					2.51	295.82

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 44298

Work Order Notes

(CWIGLEY) Key stuck in ignition switch. Also running rough.

Job Notes

35-33 - DIAGNOSE IGNITION SYSTEM

(MSIDES) Repaired ignition switch rechecked ok. MS 1.0HRS

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(MSIDES) Scanned vehicle and found no codes stored to history or current. Test drove truck and found no rough idle or shifting issues. MS

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 45548

USING DEPT NO: 507201	OPENED DATE: 12/12/2022 15:35:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/16/2022 07:33:24	METER 1 - M: 18121 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/16/2022 12:24:35	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.15	\$15.63	\$0.00	\$18.78
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.00	\$88.71	\$0.00	\$163.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$7.90	\$29.52	\$0.00	\$37.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PR-05-034	PROGRAM ECM/ENGINE CONTROL MODULE	DON	O	N	GARAGE	0.72	\$84.93	\$0.00	\$0.00	\$84.93
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	DON	O	N	GARAGE	1.77	\$208.86	\$0.00	\$0.00	\$208.86

JOB COUNT: 6	WORK ORDER TOTAL:	3.22	379.84	133.86	5.00	518.70
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-05-034	PROGRAM ECM/ENGINE CONTROL MODULE	11310047	12/15/2022 09:30:00	12/15/2022 10:11:13	0.69	\$81.06
PR-05-034	PROGRAM ECM/ENGINE CONTROL MODULE	11310047	12/15/2022 09:13:02	12/15/2022 09:15:00	0.03	\$3.87
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	12/15/2022 07:26:50	12/15/2022 09:13:02	1.77	\$208.86
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/13/2022 11:45:54	12/13/2022 11:47:30	0.03	\$3.15
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2022 11:07:34	12/13/2022 11:45:42	0.64	\$75.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	12/13/2022 11:03:18	12/13/2022 11:07:19	0.07	\$7.90
					LABOR	379.84

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	9883	FILTER-AIR	24.30	1	\$24.30
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	FP92	CABIN FILTER	29.52	1	\$29.52
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	8.25	1	\$8.25
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	9	\$56.16
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63

Work Order Charge Detail

PARTS

133.86

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 45548

Work Order Notes

(EHANNAH) pm- replace wipers
Check engine light is coming on

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. There was approximately a quart and a half of oil in the motor when I pulled the oil drain plug. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

PR-05-034 - PROGRAM ECM/ENGINE CONTROL MODULE

(IFALLS) Programmed the Powertrain Control Module per TSB to help reduce oil consumption. EH .5HR

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P0390:00-28 Camshaft Position Sensor 'B' Circuit Bank 2. The DTC was not current, and the check engine light was off. This DTC was stored before the oil change. The vehicle was about 7 quarts low on oil, but there is no visible oil leak. Found bulletin #19-2365 stating to reprogram the Powertrain Control Module to help with excessive oil consumption. While this may contribute to this vehicle's concern, it is not all to blame. This vehicle has idled approximately 45% of its life and the oil change interval needs to be monitored more carefully. The window sticker has been changed to every 3 months, 3,000 miles, or 300 idle hours. Also, the customer needs to return the vehicle in a couple of weeks so we can perform an oil consumption test. The oil level is currently at the top of the hatch mark. EH

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 46039

USING DEPT NO: 507201	OPENED DATE: 02/03/2023 07:13:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/10/2023 08:42:07	METER 1 - M: 19542 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/10/2023 11:11:55	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	2.27	\$267.76	\$9.85	\$0.00	\$277.61
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.12	\$14.42	\$24.75	\$0.00	\$39.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.39	282.18	34.60	5.00	321.78
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11310047	02/03/2023 08:52:13	02/03/2023 11:08:22	2.27	\$267.76
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	12052187	02/03/2023 07:15:49	02/03/2023 07:23:09	0.12	\$14.42
LABOR					282.18	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.25	1	\$5.25
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.16	1	\$2.16
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20TQT	QUART CAM2 SYN 5W20 32OZ	8.25	3	\$24.75
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.65	2	\$1.29
66-17-030	PERFORM TIRE PATCH	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-030	PERFORM TIRE PATCH	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
PARTS					34.60	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 46039

Work Order Notes

(EKIMBREL) add oil
(EHOWELL) Customer states: check left front tire for leak
(EHOWELL) Miles-19542
Hours-2412
Idle-1148

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EHOWELL) Removed screw and patched left front tire. Balanced and rechecked for a leak. EH

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(EHOWELL) The vehicle was 2.3 quarts low on oil. The vehicle has idled 85 hours since last PM. The vehicle has been driven 1421 miles since last PM. If the idle hours are converted to miles and then added to the actual miles driven, then this vehicle has been between 3500 and 4000 miles since the last PM. The Powertrain Control Module has already been reprogrammed to help address oil consumption. The engine oil dipstick is the correct part according to the build date of the vehicle. We need to monitor the oil level of this vehicle every 100 idle hours. According to Ford service information, it appears that they allow 1 quart of oil to be burned in 3,000 miles. Topped the oil level off to the top of the hatch mark. The customer needs to return the vehicle in about a month so that the oil level can be checked. EH .5 HR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 46530

USING DEPT NO:	507201	OPENED DATE:	03/27/2023 07:42:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2023 13:33:45	METER 1 - M:	21223	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 07:35:40	IN-SERVICE DATE:	03/10/2020	
TECH SPEC NO:	20FORDF1504X4	2020 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1E50LKD80917	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.58	\$68.18	\$0.00	\$0.00	\$68.18
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.80	\$62.06	\$0.00	\$87.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.04	\$5.11	\$0.00	\$0.00	\$5.11

JOB COUNT: 4	WORK ORDER TOTAL:	0.84	99.09	62.06	5.00	166.15
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12052187	03/27/2023 09:09:20	03/27/2023 09:11:56	0.04	\$5.11
66-79-003	PERFORM SAFETY INSPECTION	12052187	03/27/2023 08:34:30	03/27/2023 09:09:10	0.58	\$68.18
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/27/2023 08:21:11	03/27/2023 08:34:18	0.22	\$25.80
					LABOR 99.09	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	9	\$56.30
					PARTS 62.06	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 46530

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/GC
MILEAGE-21223

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(JWRIGHT) Washed unit. JAW

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 47389

USING DEPT NO: 507201	OPENED DATE: 06/20/2023 09:55:55	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/21/2023 14:55:37	METER 1 - M: 24267 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/21/2023 14:55:39	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.05	\$16.65	\$0.00	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.05	\$67.57	\$0.00	\$113.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.09	\$10.23	\$0.00	\$0.00	\$10.23

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.50** **59.33** **84.22** **5.00** **148.55**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/20/2023 13:25:45	06/20/2023 13:30:57	0.09	\$10.23
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/20/2023 13:23:58	06/20/2023 13:25:31	0.03	\$3.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/20/2023 13:00:20	06/20/2023 13:23:45	0.39	\$46.05
					LABOR 59.33	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	11.27	1	\$11.27
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	9	\$56.30
					PARTS 84.22	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 47389

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Wash bay was occupied. SH

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 47483

USING DEPT NO:	507201	OPENED DATE:	06/30/2023 07:32:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2023 12:01:35	METER 1 - M:	24267	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2023 13:19:56	IN-SERVICE DATE:	03/10/2020	
TECH SPEC NO:	20FORDF1504X4	2020 Ford F150 4X4		UNIT SERIAL NO:	1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,300.00	\$2,300.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.00	118.00	0.00	2,305.00	2,423.00
---------------------	--------------------------	-------------	---------------	-------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-71	REPAIR BODY	11150605	1697632		\$2,300.00
COMML					2305.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	08/23/2023 07:00:00	08/23/2023 07:30:00	0.50	\$59.00
66-79-002	PERFORM SERVICE CALL	11074414	08/23/2023 07:00:00	08/23/2023 07:30:00	0.50	\$59.00
LABOR					118.00	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 47483

Work Order Notes

(EHANNAH) hit a pole on right front.
(EHANNAH) picked up by Anders on rollback to go to body shop- not driveable
(IFALLS) issac had to pull bumper off of tire

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by Billy Andrews

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage to the RF bumper area per the State Auto estimate. UA paid \$2000 ded on PO. CK # 100135720 pd \$959.61 8/17/23 supplement ck# 1001369698 pd \$3745.67 on 8/17/23

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 48544

USING DEPT NO: 507201	OPENED DATE: 10/16/2023 08:05:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2023 09:56:57	METER 1 - M: 26793 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/18/2023 12:10:20	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-001	REPLACE NEW HEADLAMPS	DON	N	N	GARAGE	1.73	\$203.98	\$26.95	\$0.00	\$230.93
06-34	INSPECT LIGHTING SYSTEM	DON	O	N	GARAGE	0.79	\$93.74	\$0.00	\$0.00	\$93.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.52	297.72	26.95	5.00	329.67
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	11310047	10/17/2023 07:27:24	10/17/2023 09:11:07	1.73	\$203.98
06-34	INSPECT LIGHTING SYSTEM	11074414	10/16/2023 09:30:00	10/16/2023 10:16:26	0.77	\$91.32
06-34	INSPECT LIGHTING SYSTEM	11074414	10/16/2023 09:13:46	10/16/2023 09:15:00	0.02	\$2.43
LABOR					297.73	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-001	REPLACE NEW HEADLAMPS	PIC5340PT	HEADLIGHT SOCKET	6.20	1	\$6.20
03-34-001	REPLACE NEW HEADLAMPS	1255H11	BULB-HALOGEN	11.36	1	\$11.36
03-34-001	REPLACE NEW HEADLAMPS	06133	ELECTRICAL TAPE 3M SUPER 33+	9.39	1	\$9.39
PARTS					26.95	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 48544

Work Order Notes

(EHANNAH) inspect Pass. headlight

Job Notes

03-34-001 - REPLACE NEW HEADLAMPS

(EHOWELL) Installed a new right low beam bulb. Soldered in a new pigtail harness for the bulb. Used heat shrink and wrapped wires with electrical tape. EH

06-34 - INSPECT LIGHTING SYSTEM

(SHARBIN) Had to remove the grill to remove the head light assembly because the wires are burnt and will have to be repaired. SH 1 hour labor.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 48725

USING DEPT NO: 507201	OPENED DATE: 10/26/2023 09:38:48	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/30/2023 09:06:55	METER 1 - M: 27183 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/30/2023 10:56:03	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.41	\$16.65	\$0.00	\$20.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.37	\$69.82	\$0.00	\$109.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.24	\$28.35	\$0.00	\$0.00	\$28.35

JOB COUNT: 4	WORK ORDER TOTAL:	0.60	71.13	86.47	5.00	162.60
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	10/26/2023 13:10:40	10/26/2023 13:25:05	0.24	\$28.35
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/26/2023 13:04:27	10/26/2023 13:06:11	0.03	\$3.41
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2023 13:00:00	10/26/2023 13:04:15	0.07	\$8.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2023 12:58:21	10/26/2023 12:58:21	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2023 11:36:38	10/26/2023 11:52:24	0.26	\$31.01
					LABOR	71.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	9	\$56.30
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
					PARTS	86.47

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 48725

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed. SH

Work Order Charge Detail

UNIT NO: 243707 **2020 FORD F150 4X4** **WORK ORDER NO:** 49801

USING DEPT NO: 507201	OPENED DATE: 02/14/2024 12:32:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/01/2024 09:15:27	METER 1 - M: 30488 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2024 13:04:10	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4	UNIT SERIAL NO: 1FTEW1E50LKD80917	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-40	WARRANTY ENGINE / MOTOR SYSTEM	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-40	TRANSPORT ENGINE / MOTOR SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.04	\$5.28	\$0.00	\$0.00	\$5.28

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.54** **64.28** **0.00** **5.00** **69.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-40	WARRANTY ENGINE / MOTOR SYSTEMS	11078175	122402		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-00	SCAN OUT COMPLETE VEHICLE	12052187	02/15/2024 07:40:16	02/15/2024 07:42:57	0.04	\$5.28
16-40	TRANSPORT ENGINE / MOTOR SYSTEMS	11399745	03/07/2024 07:00:00	03/07/2024 07:30:00	0.50	\$59.00
LABOR					64.28	

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 49801

Work Order Notes

(EHANNAH) Scan out- driver reports check engine light is on, low oil light is on, and a valve rattling
(EHANNAH) inspect charging system- driver reports keeps going dead.
(LISAPATE)

Job Notes

06-31 - INSPECT CHARGING SYSTEM

15-40 - WARRANTY ENGINE / MOTOR SYSTEMS

(LISAPATE) Took to Tuscaloosa Ford for oil consumption. Truck was 6 qts low on oil. Performed relative compression test. no problem found. added 6 qts of oil.. Vehicle will return at a future date (1000 miles) for oil consumption.

Truck came back from Ford and broke down. Per dept do not repair. Surplus this unit

16-40 - TRANSPORT ENGINE / MOTOR SYSTEMS

(LISAPATE) Taken to Ford by RC/CW

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

SO-00 - SCAN OUT COMPLETE VEHICLE

(GARAGE) scanned unit and found codes p0300, p0316, p0345, p0349, p0390, p0394, p06e9 all for both camshaft position sensors and camshaft variable timing solenoids. Checked and found no oil on dipstick. Found no oil leaks. Unit is burning oil. Sending to dealer under warranty. JAW

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 50023

USING DEPT NO: 507201	OPENED DATE: 03/01/2024 09:15:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2024 07:33:35	METER 1 - M: 30488 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2024 12:54:27	IN-SERVICE DATE: 03/10/2020
TECH SPEC NO: 20FORDF1504X4 2020 Ford F150 4X4		UNIT SERIAL NO: 1FTEW1E50LKD80917

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.00** **118.00** **0.00** **5.00** **123.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-40	WARRANTY ENGINE / MOTOR SYSTEMS	11078175	122402		\$0.00
15-40	WARRANTY ENGINE / MOTOR SYSTEMS	11078175	122402		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	03/06/2024 09:18:12	03/06/2024 10:18:12	1.00	\$118.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	03/06/2024 09:18:12	03/06/2024 09:18:12	0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	03/06/2024 09:18:12	03/06/2024 09:18:12	0.00	\$0.00
LABOR						118.00

Work Order Charge Detail

UNIT NO: 243707 2020 FORD F150 4X4

WORK ORDER NO: 50023

Work Order Notes

(LISAPATE) \Prep for sale

Job Notes

15-40 - WARRANTY ENGINE / MOTOR SYSTEMS

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed tag and window decal\RC
millage 30509
no GPS

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Apr 08 2024 16:01:55 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FTEW1E50LKD80917') //Q=