The University of Alabama

UNIT NO:	243851	2020 TOY	OTA R	AV4				WORK OF		: 3	37785	
USING DEPT NO:	507143		OPENE	ED DATI	E:	09/28/202	0 08:10:05	LOCATION:	GARAGE	- Univers	sity Automotive	Services
WO STATUS:	CLOSED		COMPL	ETED I	DATE:	09/28/202	0 08:11:36	METER 1 - N	: 60	N	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED		CLOSE	D DATE	E:	09/28/202	0 10:10:17	IN-SERVICE	DATE:	09/25/2	2020	
TECH SPEC NO:	20TOYOTARAV4	2020	Toyota R	av4				UNIT SERIA	L NO:	2T3H1	RFV5LC084812	
JOB CODE	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (COMMERCIAL	TOTAL COST
PS-00-001 PREP S	ERVICE NEW UNIT I	N-SERVICE	DON	С	Ν	GARAGE	0.50	\$0.00	\$0.00	9	50.00	\$0.00
JOB COUNT: 1				wo	RK OR	DER TOTAL:	0.50	0.	00	0.00	0.00	0.0
Job Code	Job Description	<u>on</u>		<u>Em</u>	nployee	No.	<u>Start</u>	E	<u>inish</u>		<u>Quantity</u>	Total Cost
PS-00-001 PREP SER	/ICE NEW UNIT IN-SEF	RVICE INSPE	CTION 1	2052187	,	09/	28/2020 08:10:44	09/28/2020	0 08:40:44		0.50	\$0.0
											LABOR	0.0

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	37785
Work Order Note	es			
(LISAPATE) New un	it do PDI			
Job Notes				
PS-00-001 - PREP \$		FIN-SERVICE INSPECTION		
(LISAPATE) PDI con	npleted			

The University of Alabama

UNIT NO:		243851	2020 TOYOTA R	RAV4				DER NO:	38715	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	COMP	ED DATE: PLETED DATE: ED DATE: Rav4	01/08/202	1 09:57:37 1 07:40:09 1 09:58:28	LOCATION: 0 METER 1 - M: IN-SERVICE D UNIT SERIAL	1512 • ATE: 09/2	versity Automotive METER 2 - H: 25/2020 3H1RFV5LC08481	0
JOB CODE 66-17-030	_	JOB DESCRIPTIC	<u>DN STAT</u> DON		JOB LOC GARAGE	LABOR HRS 0.13	LABOR \$15.21	MATERIAL \$4.35	COMMERCIA \$0.00	L TOTAL COST \$19.56
JOB COUN	IT: 1			WORK OR	DER TOTAL:	0.13	15.21	4.3	35 0.0	0 19.56
<u>Job Code</u> 66-17-030	PERFORM	Job Descripti TIRE PATCH		<u>Employee</u> 12052187		<u>Start</u> 07/2021 10:25:40		l ish 10:33:24	Quantity 0.1 LABOR	<u>Total Cost</u> 3 \$15.21 15.21
Job Code		Job Descripti	on	Part No) <u>.</u>	Des	cription	<u>Unit F</u>		Total Cost
66-17-030	PERFORM	TIRE PATCH		14041	PA	TCH 1/4 PILOT W	IRE		3.51	1 \$3.51
66-17-030	PERFORM ⁻	TIRE PATCH	,	WHEEL WEIGHT	WH	IEEL WEIGHT KN	IOCK ON		0.42 PARTS	2 \$0.84 4.35

243851 **2020 TOYOTA RAV4** UNIT NO:

WORK ORDER NO:

38715

Work Order Notes

(EKIMBREL) LR tire has screw

Job Notes

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired or tire and balanced. Aired and torqued to spec. Did not replace valve stem due to it still being new and good. JAW

The University of Alabama

UNIT NO:		243851	2020 TOY	OTA RA	V 4				wo		DER NO	D:	39099			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	2020	OPENE COMPL CLOSE	ETED I D DATE	DATE:	02/17/20	21 08:28:11 21 09:49:36 21 12:33:42	MET IN-S	CATION: ER 1 - M: ERVICE D T SERIAL	2373 DATE:	09/25/	rsity Automotiv METER 2 - H /2020 1RFV5LC0848	:		
JOB CODE 66-PM-PMA		JOB DESCRIPTIC M OIL CHANGE	<u>DN</u>	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HR 1.0	_	_ABOR 7.44	<u>MAT</u> \$29.84	ERIAL	COMMERCI \$0.00		TOTAL \$147.28	<u>COST</u>
JOB COUN	T: 1				wo	RK ORI	DER TOTAL	: 1.0	00	117.44	4	29.84	0	.00		147.28
Job Code 66-PM-PMA	PERFORM (Job Descripti DIL CHANGE	<u>on</u>	12	<u>Em</u> 2052187	ployee		<u>Start</u> 2/12/2021 09:33:	47 (<u>Fir</u> 02/12/2021	<u>nish</u> 10:33:30		Quantii 1 LABOI	.00	<u>Total</u>	<u>Cost</u> \$117.44 117.44
Job Code		Job Descripti	on			Part No	<u>.</u>	D	escripti	ion		Unit Pri	<u>ce Quantit</u>	ty	Total	Cost
66-PM-PMA	PERFORM C	DIL CHANGE		0\	V16T		C	IL 0W16 CAM2 I	SPI SN4	1+ QT		5	.84	4		\$23.34
66-PM-PMA	PERFORM C	DIL CHANGE		0\	V16T		C	IL 0W16 CAM2 I	_SPI SN4	1+ QT		5	.85	(5)		(\$29.25)
66-PM-PMA	PERFORM C	DIL CHANGE		W	IX51394	Ļ	C	IL FILTER				6	.50	1		\$6.50
66-PM-PMA	PERFORM C	DIL CHANGE		0\	V16T		C	IL 0W16 CAM2 I	_SPI SN4	1+ QT		5	.85	5		\$29.25
													PARTS	5		29.84

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	39099
Work Order Note	<u>es</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	ORM OIL CHANGE			
(JWRIGHT) Performe	ed pm service. Coola	ant -34°. MS/JAW		

MILEAGE-2373

The University of Alabama

UNIT NO:		243851	2020 TOY	OTA R	AV4				WORK O	RDER NO	D: 39	9575		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4		OPENE COMPL CLOSE	ETED I	DATE:	04/07/202	21 15:41:48 21 11:01:06 21 07:38:52	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 3767 E DATE:	MI 09/25/20	y Automotive S E TER 2 - H: 20 FV5LC084812	0	
JOB CODE	<u>.</u>	JOB DESCRIPTIC	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL <u>C</u>	OMMERCIAL	TOTAL O	COST
66-17-030	PERFOR	M TIRE PATCH		DON	0	Ν	GARAGE	0.78	\$92.40	\$4.97	\$0	.00	\$97.37	
66-17-033	PERFOR	M TIRE ROTATION	AND BRAKE	DON	0	Ν	GARAGE	0.01	\$1.28	\$0.00	\$0	.00	\$1.28	
JOB COUN	T: 2				wo	RK ORI	DER TOTAL:	0.79	9:	3.68	4.97	0.00		98.65
Job Code		Job Description	on		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	Total C	<u>Cost</u>
66-17-033	PERFORM 1	TIRE ROTATION AND	BRAKE INSPE	CTION 1	2052187		04	/07/2021 08:33:29	04/07/20	21 08:34:08		0.01		\$1.28
66-17-030	PERFORM 1	TIRE PATCH		1	2052187		04	/07/2021 07:46:20	04/07/20	21 08:33:19		0.78		\$92.40
												LABOR		93.68
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	scription		Unit Price	<u>Quantity</u>	Total C	<u>Cost</u>
66-17-030	PERFORM 1	TIRE PATCH		1	4041		PA	TCH 1/4 PILOT W	/IRE		4.01	1		\$4.01
66-17-030	PERFORM 1	TIRE PATCH		V	VHEEL V	/EIGHT	WI	HEEL WEIGHT KN	NOCK ON		0.48	2		\$0.96
												PARTS		4.97

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4
----------	--------	------------------

WORK ORDER NO:	39575
----------------	-------

Work Order Notes

(LISAPATE) Screw in LR tire and rotate tires

Job Notes

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired or tire. Aired to spec and balanced. JAW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires. Torqued all lugs to 76ft lbs. All brake pads are 10mm. JAW

The University of Alabama

UNIT NO:		243851	2020 TOY	DTA R/	AV4					WORK ORDER	NO:	39633	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4		OPENE COMPL CLOSE	ETED I D DATI	DATE:	04/19/202	21 08:10:44 21 08:49:33 21 15:30:01	3	LOCATION: GARA METER 1 - M: 399 IN-SERVICE DATE: UNIT SERIAL NO:	1 09/25	METER 2 - H:	
JOB CODE 66-17-028	-	JOB DESCRIPTION		<u>STAT</u> DON	<u>RSN</u> O	WRTY N	JOB LOC GARAGE	LABOR	HRS 0.20	LABOR M \$23.60 \$252	ATERIAL 76	COMMERCIAL \$0.00	TOTAL COST \$276.36
JOB COUN	IT: 1				wo		DER TOTAL		0.20	23.60	252.76	0.00	276.36
Job Code		Job Descript	<u>ion</u>		Em	nployee	<u>No.</u>	<u>Star</u>	<u>t</u>	<u>Finish</u>		<u>Quantity</u>	Total Cost
66-17-028	PERFORM N	OUNT AND BALANC	CE TIRES	1:	2052187	,	04	/19/2021 07:	:00:00	04/19/2021 07:12:0	00	0.20	\$23.60
66-17-030	PERFORM T	IRE PATCH		1:	2052187	,	04	/12/2021 12:	21:47	04/12/2021 12:53:	38	0.53	\$62.64
66-17-030	PERFORM T	IRE PATCH		1:	2052187	,	04	/12/2021 12:	:21:47	04/12/2021 12:53:	38	(0.53)	(\$62.64)
												LABOR	23.60
Job Code		Job Descript	ion			Part No	<u>.</u>		Des	cription	<u>Unit Pri</u>	<u>ce Quantity</u>	Total Cost
66-17-028	PERFORM N	OUNT AND BALANC	CE TIRES	F	005359		22	5/65R17 FIF	RESTO	NE DEST LE3	249	.27 1	\$249.27
66-17-030	PERFORM T	IRE PATCH		6	-111		TF	MS SERVIC	E KIT	6-111	3	.01 (1)	(\$3.01)
66-17-028	PERFORM N	OUNT AND BALANC	CE TIRES	6	-111		TF	MS SERVIC	E KIT	6-111	3	.01 1	\$3.01
66-17-030	PERFORM T	IRE PATCH		6	-111		TF	MS SERVIC	E KIT	6-111	3	.01 1	\$3.01
66-17-028	PERFORM N	OUNT AND BALANC	CE TIRES	W	/HEEL V	VEIGHT	W	HEEL WEIG	HT KN	OCK ON	0	.481	\$0.48
												PARTS	252.76

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 39633

Work Order Notes

(LISAPATE) Per driver LF tire was low had to add air.

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Inspected tire If tire and found it has already been repaired 2 times and not safe to repair again. Replaced with new tire and valve stem kit. Aired to spec. Balanced and torqued to 76ft lbs. JAW

66-17-030 - PERFORM TIRE PATCH

(LISAPATE)

The University of Alabama

UNIT NO:		243851	2020 TOYOTA RAV4		WORK ORDER NO:	40267	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2020 Toyota Rav4	06/28/2021 09:02:30 06/29/2021 09:07:35 07/06/2021 07:16:45	METER 1 - M: 6907 IN-SERVICE DATE: 09/2	versity Automotive S METER 2 - H: 25/2020 H1RFV5LC084812	0
JOB CODE 66-PM-PMA		JOB DESCRIPTIC	DN <u>STAT RSN WRTY</u> DON P N	JOB LOCLABOR HRSGARAGE0.58	LABOR MATERIAL \$68.05 \$43.58	COMMERCIAL \$0.00	TOTAL COST \$111.63
JOB COUN	IT: 1		WORK ORE	DER TOTAL: 0.58	68.05 43.5	68 0.00	111.63
Job Code 66-PM-PMA	PERFORM	Job Descripti OIL CHANGE	on <u>Employee</u> 11901357	No. <u>Start</u> 06/28/2021 15:02:26	<u>Finish</u> 06/28/2021 15:37:02	Quantity 0.58	Total Cost \$68.05 68.05
Job Code		Job Descripti	on Part No.	Des	cription Unit P		Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	WIX51394	OIL FILTER		9.23 1	\$9.23
66-PM-PMA	PERFORM	OIL CHANGE	0W16T	OIL 0W16 CAM2 LS	PI SN4+ QT	6.87 5 PARTS	\$34.35 43.58

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO: 243851	2020 TOYOTA RAV4
-----------------	------------------

WORK ORDER NO: 40267

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 6907 Completed PM bottomside, Matt was topside. Completed checklist. MS/AMG

The University of Alabama

UNIT NO: 243851 2020 TOYO			DTA R	AV4				WORK O	RDER NO): 41	156			
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4		СОМРІ	ED DAT _ETED ED DAT Rav4	DATE:	10/12/20	21 08:18:26 21 10:48:19 21 11:06:37	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 9857 E DATE:	ME 09/25/202	y Automotive \$ E TER 2 - H: 20 FV5LC084812	0	
JOB CODE	<u>E</u>	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Р	Ν	GARAGE	0.15	\$17.70	\$17.90	\$0.	.00	\$35.60	
66-17-028	PERFOR	RM MOUNT AND BA	LANCE TIRE	DON	0	Ν	GARAGE	0.64	\$74.96	\$256.01	\$0.	.00	\$330.97	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	Ν	GARAGE	1.26	\$148.52	\$61.81	\$0.	.00	\$210.33	
66-PM-PMC	PERFOR	RM CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.01	\$0.59	\$18.57	\$0.	.00	\$19.16	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.	.00	\$2.00	
JOB COUN	NT: 5				wc		DER TOTAL	.: 2.05	5 24 ⁻	1.77	354.29	2.00		598.06
Job Code		Job Descript	ion		V	/endor N	<u>lo.</u>	Invoice No.	Purcha	ase Order N	<u>0.</u>		Total	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	<u>ion</u>		En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	<u>Total</u>	Cost
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	1	1074414	1	10	0/04/2021 13:01:03	10/04/20	21 13:22:52		0.36		\$42.91
66-17-028	PERFORM I	MOUNT AND BALANC	CE TIRES	1	1074414	1	1	0/04/2021 11:33:00	10/04/20	21 11:49:18		0.27		\$32.06
66-PM-PMC	PERFORM	CABIN FILTER REPLA	ACEMENT	1	1310047	7	10	0/01/2021 10:56:25	10/01/20	21 10:56:43		0.01		\$0.59
03-51-038	REPLACE N	IEW WIPER BLADES		1	1310047	7	10	0/01/2021 10:56:12	10/01/20	21 11:05:12		0.15		\$17.70
03-51-038	REPLACE N	IEW WIPER BLADES		1	1310047	7	10	0/01/2021 10:56:12	10/01/20	21 10:56:25		0.00		(\$0.43)
03-51-038	REPLACE N	IEW WIPER BLADES		1	1310047	7	1	0/01/2021 10:56:12	10/01/20	21 10:56:25		0.00		\$0.43
66-PM-PMA	PERFORM	OIL CHANGE		1	1310047	7	10	0/01/2021 10:11:12	10/01/20	21 10:56:12		0.75		\$88.50
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414	1	10	0/01/2021 10:10:37	10/01/20	21 10:41:08		0.51		\$60.02
												LABOR		241.78
Job Code		Job Descript	<u>ion</u>			Part No	<u>).</u>	Des	<u>scription</u>		<u>Unit Price</u>	<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		0	W16T		0	IL 0W16 CAM2 LS	PI SN4+ QT		7.13	1		\$7.13
66-PM-PMA	PERFORM	OIL CHANGE		V	VIX5139	4	0	IL FILTER			9.26	1		\$9.26
03-51-038	REPLACE N	IEW WIPER BLADES			W16T			IL 0W16 CAM2 LS			7.13	(1))	(\$7.13)
03-51-038	REPLACE N	IEW WIPER BLADES		0	W16T		0	IL 0W16 CAM2 LS	PI SN4+ QT		7.13	5		\$35.63
FleetFocus M5	- WODETAIL	- Work Order Detail v2	20.0											Page:1

The University of Alabama

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.57	1	\$18.57
03-51-038	REPLACE NEW WIPER BLADES	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.13	(5)	(\$35.63)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.13	5	\$35.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	1	\$4.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.47	2	\$0.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	005359	FSTONE DEST LE3 225/65R17	250.77	1	\$250.77
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	16.92	1	\$16.92
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	16.92	(1)	(\$16.92)
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	16.92	1	\$16.92
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	161	WIPERS 16"	7.59	1	\$7.59
					PARTS	354.29

Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

The University of Alabama

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	41156
Work Order Not	es			
(LISAPATE) PM-rep	lace wipers			
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(EHOWELL) Replac	ed wiper blades. EH			
66-17-028 - PERFO	RM MOUNT AND BA	ALANCE TIRES		
(SHARBIN) Mounte	d and balanced 1 tire	. Right front. SH		
66-PM-PMA - PERF	ORM OIL CHANGE			
(EHOWELL) EH -to SH-bottom	р			
66-PM-PMC - PERF	FORM CABIN FILTER	RREPLACEMENT		
(EHOWELL) Replac	ced cabin filter. EH			
CH-SP - CHARGE	Shop Supplies			

The University of Alabama

UNIT NO: 243851 202		2020 TO	020 TOYOTA RAV4						DER NO): 4	42018			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	202	OPENE COMPL CLOSE 0 Toyota R	ETED	DATE:	01/10/20	22 07:35:48 22 14:25:05 22 09:41:05	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	12469 DATE:	N 09/25/2	ity Automotive S /ETER 2 - H: 020 RFV5LC084812	0	
JOB CODE	L	JOB DESCRIPTI	ON	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (COMMERCIAL	<u>TOTAL</u>	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.06	\$7.64	\$80.90	\$	60.00	\$88.54	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	52.00	\$2.00	
JOB COUN	IT: 2				WC		DER TOTAL	: 0.06	5 7.64	4	80.90	2.00		90.54
Job Code		Job Descript	tion		<u>v</u>	/endor N	<u>lo.</u>	Invoice No.	Purchase	Order N	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	tion		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>Fir</u>	<u>nish</u>		<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM	DIL CHANGE		1	2052187	7	01	/10/2022 10:42:45	01/10/2022	10:46:38		0.06		\$7.64
												LABOR		7.64
Job Code		Job Descript	tion			Part No	<u>.</u>	Des	scription		Unit Price	e Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM	DIL CHANGE		V	VIX5139	4	O	L FILTER			9.2	.4 1		\$9.24
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		BF	RAKE CLEAN NO	N-FLAMMABLE 14	4OZ	6.5	6 1		\$6.56
66-PM-PMA	PERFORM	DIL CHANGE		0	W16T		O	L 0W16 CAM2 LS	PI SN4+ QT		13.0	2 5		\$65.10
												PARTS		80.90

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	42018
Work Order Notes	<u> </u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(JWRIGHT) Performed MILEAGE-12469	d pm service. Coola	ant -34°. JAW/SH		
CH-SP - CHARGE Sh	op Supplies			

The University of Alabama

UNIT NO:	JNIT NO: 243851 2020 TC		2020 TOY	OTA R	AV4				WORK O	RDER NO	: 4	42865		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4 2		OPENED DATE: COMPLETED DATE: CLOSED DATE: 2020 Toyota Rav4			04/13/202	04/08/2022 09:41:48 04/13/2022 13:30:16 04/14/2022 07:26:08		: GARAGE M: 13819 E DATE: AL NO:	E - University Automotive METER 2 - H: 09/25/2020 2T3H1RFV5LC084812		0	
JOB CODE	<u> </u>	JOB DESCRIPTIC	<u>NC</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	ADES	DON	Ρ	Ν	GARAGE	0.34	\$39.66	\$27.10	\$	0.00	\$66.76	
66-PM-PMA	PERFOF	M OIL CHANGE		DON	Р	Ν	GARAGE	0.15	\$17.67	\$0.00	\$	0.00	\$17.67	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	2.00	\$2.00	
JOB COUN	IT: 3				WC	RK ORI		0.49	57	7.33	27.10	2.00		86.43
Job Code		Job Descript	ion		v	endor N	<u>o.</u>	Invoice No.	Purcha	ase Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descripti	ion		En	nployee	<u>No.</u>	<u>Start</u>		Finish		Quantity	Total	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1:	2052187	,	04	/08/2022 13:31:32	04/08/20	22 13:51:42		0.34		\$39.66
66-PM-PMA	PERFORM	OIL CHANGE		1:	2052187	,	04	/08/2022 13:22:23	04/08/20	22 13:31:22		0.15		\$17.67
												LABOR		57.33
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription	<u> </u>	Jnit Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	2A		12	" WIPER BLADE			9.20	0 1		\$9.20
03-51-038	REPLACE N	IEW WIPER BLADES		2	6-1		W	IPER BLADE			10.3	1 1		\$10.31
03-51-038	REPLACE N	IEW WIPER BLADES		1	61		W	IPERS 16"			7.59	91		\$7.59
												PARTS		27.10

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 42865

Work Order Notes

(CHANNELL) pm

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1300 miles. Checked fluids and tires. Coolant -34°. JAW MILEAGE-13819

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:	NIT NO: 243851 2020 TOY		OTA R	AV4				WORK (ORDER NO:	436	43675			
WO STATUS WO VISIT R	USING DEPT NO: 507143 WO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 20TOYOTAR			COMPL	OMPLETED DATE:		07/01/2022 11:22:28 07/01/2022 14:06:59				-	ER 2 - H:	0	
JOB CODE		JOB DESCRIPTIO	<u>ON</u>	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABO	<u>R MATERI</u>	AL CON	IMERCIAL	TOTAL	COST
15-01-048	WARRAI	NTY HEATER CONT	ROL VALVE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00		\$0.00	
16-00	TRANSF	PORT COMPLETE V	'EHICLE	DON	S	Ν	GARAGE	0.50	\$59.00	\$0.00	\$0.00		\$59.00	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.00		\$2.00	
JOB COUN	IT: 3				WC	RK ORI	DER TOTAL:	0.50) 5	59.00	0.00	2.00		61.00
Job Code		Job Descripti	ion		V	endor N	0.	Invoice No.	Purch	ase Order No.			Total	Cost
CH-SP	CHARGE S	hop Supplies		5	03163		1							\$2.00
15-01-048	WARRANT	Y HEATER CONTROL	VALVE	1	1076422		616	64263						\$0.00
											_	COMML		2.00
Job Code		Job Descript	ion		En	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total	Cost
16-00	TRANSPOR	RT COMPLETE VEHIC	LE	1	1915538		07/	/01/2022 07:00:00	07/01/2	022 07:30:00		0.50		\$59.00
												LABOR		59.00

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 43675

Work Order Notes

(LISAPATE) Engine Maint required light will not reset take to the dealer

Job Notes

15-01-048 - WARRANTY HEATER CONTROL VALVE

(LISAPATE) Toyota removed and replaced engine coolant bypass valve hose assy under warranty

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Taken to Toyota by RC

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:	NIT NO: 243851 2020 TO				AV4				WORK OF	RDER NO:	43	43823		
WO STATUS WO VISIT R	VO VISIT REASON:SCHEDULEDECH SPEC NO:20TOYOTARAV42			OPENE COMPL CLOSE	ETED D DATI	DATE:	07/07/202	07/05/2022 09:04:01 07/07/2022 14:09:08 07/11/2022 09:56:40		GARAGE - 1: 15251 DATE: L NO:	E - University Automotive METER 2 - H: 09/25/2020 2T3H1RFV5LC08481		0	
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATER	RIAL <u>Co</u>	OMMERCIAL	TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.22	\$25.83	\$43.52	\$0.	00	\$69.35	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	Р	Ν	GARAGE	0.03	\$3.05	\$20.52	\$0.	00	\$23.57	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.	00	\$2.00	
JOB COUN	IT: 3				wo			0.24	28.	88	64.04	2.00		94.92
Job Code		Job Descript	ion		v	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No	<u>.</u>		Total	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$2.00
												COMML		2.00
Job Code		Job Descript	ion		Em	nployee	<u>No.</u>	<u>Start</u>	<u> </u>	inish		<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMC	PERFORM	CABIN FILTER REPLA	ACEMENT	1:	2052187	,	07	/05/2022 10:16:15	07/05/202	2 10:17:48		0.03		\$3.05
66-PM-PMA	PERFORM	DIL CHANGE		1:	2052187	,	07	/05/2022 10:02:57	07/05/202	2 10:16:05		0.22		\$25.83
												LABOR		28.88
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription	<u>U</u>	Init Price	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		0'	W16T		OI	L 0W16 CAM2 LSI	PI SN4+ QT		7.47	5		\$37.35
66-PM-PMA	PERFORM	DIL CHANGE		W	/IX51394	4	OI	L FILTER			6.17	1		\$6.17
66-PM-PMC	PERFORM	CABIN FILTER REPLA	ACEMENT	Р	C99237	С	CA	BIN FILTER 2020	CAMRY		20.52	1		\$20.52
												PARTS		64.04

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	43823
Work Order Notes	<u>.</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(JWRIGHT) Performed MILEAGE-15251	l pm service. Coola	ant -34°. JAW,AMG/JAW		
66-PM-PMC - PERFO	RM CABIN FILTER	RREPLACEMENT		
(JWRIGHT) Replaced	cabin filter			
CH-SP - CHARGE Sh	op Supplies			

The University of Alabama

UNIT NO:	JNIT NO: 243851 202		2020 TOYO	20 TOYOTA RAV4): 4	44050		
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	C	COMPL	D DAT ETED D DAT av4	DATE:	07/22/20	22 10:41:38 22 15:09:14 22 13:24:05	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 15816 DATE:	M 09/25/20	ity Automotive S IETER 2 - H: 020 RFV5LC084812	0	
JOB CODE				STAT	<u>RSN</u>	<u>WRTY</u>	JOB LOC		LABOR	MATE			TOTAL	<u>COST</u>
66-17-030 CH-SP	-	RM TIRE PATCH		DON DON	0 2	N N	GARAGE GARAGE	0.29 0.00	• -	\$4.94 \$0.00	·	0.00 2.00	\$39.16 \$2.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	: 0.29	34.	22	4.94	2.00		41.16
Job Code CH-SP	CHARGE S	Job Description	on	50	<u>V</u> 03163	endor N	l <mark>o.</mark> 1	Invoice No.	Purchas	e Order N	<u>o.</u>		<u>Total</u>	<u>Cost</u> \$2.00
												COMML		2.00
Job Code		Job Descripti	on		En	nployee	<u>No.</u>	<u>Start</u>	F	<u>inish</u>		<u>Quantity</u>	Total	Cost
66-17-030	PERFORM	TIRE PATCH		12	2052187	,	07	7/22/2022 13:03:47	07/22/202	2 13:21:11		0.29		\$34.22
												LABOR		34.22
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	scription		Unit Price	Quantity	Total	Cost
66-17-030	PERFORM	TIRE PATCH		14	4041		PA	ATCH 1/4 PILOT W	/IRE		4.3	1 1		\$4.31
66-17-030	PERFORM	TIRE PATCH		58	3104		1.	25 OZ WHEEL WE	EIGHT		0.63	31		\$0.63
												PARTS		4.94

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	44050
Work Order Not	es			
(LISAPATE) Screw i	n RF tire			
Job Notes				
66-17-030 - PERFO	RM TIRE PATCH			
(JWRIGHT) Repaire	d RF tire. Aired and	balanced. Torqued to spec. JAW		
CH-SP - CHARGE	Shop Supplies			

The University of Alabama

UNIT NO:	IT NO: 243851 2020 TOY			DTA R	AV4				WORK OF		4289			
WO STATUS WO VISIT R	O VISIT REASON:SCHEDULEDCH SPEC NO:20TOYOTARAV42020			COMPLETED DATE: 08/1			08/19/20	22 09:55:21 22 14:12:53 22 09:45:11	LOCATION: GARAGE METER 1 - M: 16576 IN-SERVICE DATE: UNIT SERIAL NO:		E - University Automotive METER 2 - H: 09/25/2020 2T3H1RFV5LC08481		0	
JOB CODE	<u> </u>	JOB DESCRIPT	ION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL C	OMMERCIAL	TOTAL	COST
06-15	INSPEC [®]	T STEERING		DON	0	Ν	GARAGE	0.11	\$12.91	\$0.00	\$0	0.00	\$12.91	
06-17	INSPEC	T TIRES, TUBES, I	LINERS & VAL	DON	Р	Ν	GARAGE	0.18	\$21.37	\$0.00	\$0	0.00	\$21.37	
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	0.64	\$75.62	\$0.00	\$0	0.00	\$75.62	
66-17-028	PERFOF	M MOUNT AND B	ALANCE TIRE	DON	0	N	GARAGE	0.19	\$22.94	\$275.81	\$0	0.00	\$298.75	
CH-SP	-	E Shop Supplies		DON	2	N	GARAGE	0.00	• -	\$0.00	• •	5.00	\$5.00	
JOB COUN							DER TOTAL				275.81	5.00		413.65
Job Code CH-SP	CHARGE S	Job Descrip	<u>ition</u>	5	<u>∨</u> 03163	endor N	lo. 1	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total</u>	l Cost \$5.00
												COMML		5.00
Job Code		Job Descrip	<u>otion</u>		<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	<u>-inish</u>		<u>Quantity</u>	<u>Total</u>	Cost
09-15	ALIGN STE	ERING		1	1310047	,	30	8/16/2022 08:33:48	08/16/202	2 09:12:15		0.64		\$75.62
06-15	INSPECT S	TEERING		1	1074414	Ļ	30	/15/2022 14:42:32	08/15/202	2 14:49:06		0.11		\$12.91
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	1	1074414	Ļ	80	/15/2022 14:30:00	08/15/202	2 14:41:40		0.19		\$22.94
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	1	1074414	Ļ	80	3/15/2022 14:17:28	08/15/202	2 14:17:28		0.00		\$0.00
06-17	INSPECT T	RES, TUBES, LINEF	RS & VALVES	1	1074414	ļ	80	/15/2022 10:07:56	08/15/202	2 10:18:48		0.18		\$21.37
												LABOR		132.84
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	cription		<u>Unit Price</u>	Quantity	<u>Total</u>	Cost
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	2	1030		TF	MS SERVICE KIT	6-116		5.88	1		\$5.88
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	5	8104		1.:	25 OZ WHEEL WE	IGHT		0.63	1		\$0.63
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	58106			1.	1.75 OZ WHEEL WEIGHT			0.81	1		\$0.81
66-17-028	PERFORM	ERFORM MOUNT AND BALANCE TIRES		005359		FS	FSTONE DEST LE3 2			268.49	1		\$268.49	
												PARTS		275.81

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 44289

Work Order Notes

(CWIGLEY) Inspect driver side front tire. Drivers says that it has excessive wear.

Job Notes

06-15 - INSPECT STEERING

(GARAGE) inspected steering found no issues at this time. SH

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(GARAGE) left front tire is at 2/32 with excessive shoulder wear possibly from use in parking decks. recommend 1 tire. SH

09-15 - ALIGN STEERING

(EHOWELL) Performed four-wheel alignment. Reset steering angle sensor. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balanced 1 tire for the left front. SH

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO:		243851 2	020 TOY	OTA R/	AV4				WORK OF	RDER NO	: 4	4820		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	2020 -	OPENE COMPL CLOSE Toyota R	ETED	DATE:	10/06/20	22 09:18:02 22 08:51:08 22 09:30:03	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	I: 16941 DATE:	N 09/25/2	ity Automotive S IETER 2 - H: 020 RFV5LC084812	0	
JOB CODE	L	JOB DESCRIPTION	L	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL O	COMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLAD	ES	DON	Р	Ν	GARAGE	0.06	\$7.05	\$27.87	\$	0.00	\$34.92	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.32	\$38.02	\$52.10	\$	0.00	\$90.12	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL	: 0.38	45.	07	79.97	5.00		130.04
Job Code		Job Descriptior	<u>1</u>		V	endor N	<u>lo.</u>	Invoice No.	Purchas	e Order No	<u>o.</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	op Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descriptior	<u>1</u>		Em	nployee	<u>No.</u>	<u>Start</u>	<u></u>	<u>inish</u>		<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	1901357		10	/03/2022 13:51:59	10/03/2022	2 13:55:34		0.06		\$7.05
66-PM-PMA	PERFORM (DIL CHANGE		1	1901357		10	/03/2022 13:32:22	10/03/2022	2 13:51:42		0.32		\$38.02
												LABOR		45.07
Job Code		Job Descriptior	<u>1</u>			Part No	<u>.</u>	Des	cription		Unit Price	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		W	/IX51394	4	0	L FILTER			10.2	8 1		\$10.28
03-51-038	REPLACE N	EW WIPER BLADES		1:	2A		12	" WIPER BLADE			9.4	7 1		\$9.47
03-51-038	REPLACE N	EW WIPER BLADES		2	6-1		W	IPER BLADE			10.5	8 1		\$10.58
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		BI	RAKE CLEAN NON	N-FLAMMABLE	14OZ	7.7	7 1		\$7.77
66-PM-PMA	PERFORM	DIL CHANGE		0'	W16T		0	L 0W16 CAM2 LSF	PI SN4+ QT		6.8	1 5		\$34.05
03-51-038	REPLACE N	EW WIPER BLADES		1	61		W	IPERS 16"			7.8	2 1		\$7.82
												PARTS		79.97

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WORK ORDER NO:	44820
Work Order Note	es			
(LISAPATE) PM				
Job Notes				
03-51-038 - REPLAC	CE NEW WIPER BL	ADES		
(AGUERRA) Replace	ed wipers. AMG			
66-PM-PMA - PERF	ORM OIL CHANGE			
(AGUERRA) miles: 1	6941 Completed PM	/l top and bottom side. AMG/AMG		
CH-SP - CHARGE S	hop Supplies			

The University of Alabama

UNIT NO:		243851	2020 TOYO	DTA R	AV4				WORK C	RDER NO	: 45	5657		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4		OPENE COMPL CLOSE	ETED	DATE:	01/06/20	23 07:47:52 23 13:36:43 23 13:36:46			ME 09/25/20	ETER 2 - H:	0	
JOB CODE		JOB DESCRIPT	ION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>		OMMERCIAL	TOTAL	COST
66-17-028	PERFOR	M MOUNT AND B	BALANCE TIRE	DON	Р	Ν	GARAGE	0.55	\$65.00	\$285.94	\$0	.00	\$350.94	
66-79-002	PERFOR	M SERVICE CALI	L	DON	В	Ν	GARAGE	0.23	\$26.85	\$0.00	\$0	.00	\$26.85	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.23	\$27.30	\$0.00	\$0	.00	\$27.30	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5	.00	\$5.00	
JOB COUN	T: 4				wo	RK ORI	DER TOTAL	: 1.01	11	9.15	285.94	5.00)	410.09
Job Code		Job Descrip	otion		v	endor N	<u>o.</u>	Invoice No.	Purch	ase Order No	<u>).</u>		Total	Cost
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	<u>otion</u>		Em	ployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414		0	1/04/2023 08:34:19	01/04/20	023 08:48:12		0.23		\$27.30
66-79-002	PERFORM	SERVICE CALL		1	1074414		0	1/04/2023 07:52:07	01/04/20	023 08:05:46		0.23		\$26.85
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	1	1901357		0	1/05/2023 08:10:39	01/05/20	023 08:16:00		0.09		\$10.52
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	1	1901357		0	1/05/2023 07:21:06	01/05/20)23 07:48:48		0.46		\$54.48
												LABOR		119.15
Job Code		Job Descrip	<u>otion</u>			Part No	<u>.</u>	Des	scription	<u>l</u>	<u> Jnit Price</u>	<u>Quantity</u>	<u>Total</u>	Cost
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	0	05359		F	STONE DEST LE3	225/65R17		277.50	1		\$277.50
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	0	05359		F	STONE DEST LE3	225/65R17		277.50	(1)	(\$277.50)
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	0	05359		F	STONE DEST LE3	225/65R17		277.50	1		\$277.50
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	5	8106		1.	75 OZ WHEEL WE	EIGHT		0.81	1		\$0.81
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	5	8104		1.	25 OZ WHEEL WE	EIGHT		0.65	1		\$0.65
66-17-028	PERFORM	MOUNT AND BALAN	ICE TIRES	2	1030		Т	PMS SERVICE KIT	6-116		6.98	1		\$6.98
												PARTS		285.94

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 45657

Work Order Notes

(EHANNAH) Service call and tire patch

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Replaced and balanced R/F tire. AMG

66-17-030 - PERFORM TIRE PATCH

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Performed a service call to the 600 building for a flat tire. Put the spare on and drove the vehicle back to the shop. Broke the tire down and discovered the tire has been driven flat and can not be repaired. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1920 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

The University of Alabama

UNIT NO:		243851	2020 TO	YOTA R	AV4				WORK OR	DER NO	: 4	6773		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	202	OPENE COMPI CLOSE 0 Toyota R	ETED	DATE:	04/24/20	23 08:31:19 23 11:25:53 23 13:04:41	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 19446 DATE :	M 09/25/20	ty Automotive S I ETER 2 - H: D20 RFV5LC084812	0	
JOB CODE	<u>.</u>	JOB DESCRIPTIC	<u>NO</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	<u>RIAL</u> C	OMMERCIAL	<u>TOTAL</u>	COST
03-51-038	REPLAC	E NEW WIPER BLA	DES	DON	Ρ	Ν	GARAGE	0.01	\$1.48	\$28.63	\$0	0.00	\$30.11	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.41	\$47.99	\$52.06	\$0	0.00	\$100.05	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$:	5.00	\$5.00	
JOB COUN	T: 3				WO		DER TOTAL	: 0.42	49.4	17	80.69	5.00		135.16
Job Code		Job Descripti	on		v	endor N	<u>lo.</u>	Invoice No.	Purchase	e Order No	<u>o.</u>		Total	Cost
CH-SP	CHARGE SH	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descripti	on		Em	nployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	nish		Quantity	Total	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	2201267	,	04	/20/2023 10:19:07	04/20/2023	10:19:52		0.01		\$1.48
66-PM-PMA	PERFORM	OIL CHANGE		1	2201267	,	04	/20/2023 09:54:28	04/20/2023	10:18:52		0.41		\$47.99
												LABOR		49.47
Job Code		Job Descripti	on			Part No	<u>.</u>	Des	scription		Unit Price	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		V	VIX51394	4	0	IL FILTER			5.81	1 1		\$5.81
66-PM-PMA	PERFORM	OIL CHANGE		0	5089		BI	RAKE CLEAN NON	N-FLAMMABLE 1	40Z	10.70	0 1		\$10.70
66-PM-PMA	PERFORM	OIL CHANGE		0	W16T		0	L 0W16 CAM2 LSI	PI SN4+ QT		7.1	1 5		\$35.55
03-51-038	REPLACE N	IEW WIPER BLADES		1	2A		12	" WIPER BLADE			9.47	7 1		\$9.47
03-51-038	REPLACE N	IEW WIPER BLADES		2	6-1		W	IPER BLADE			11.03	3 1		\$11.03
03-51-038	REPLACE N	IEW WIPER BLADES		1	61		W	IPERS 16"			8.13	31		\$8.13
												PARTS		80.69

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 46773

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-SH,GC- Changed oil and oil filter, checked fluids, tires and tire pressure, filters are good. Miles, 19,446

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

The University of Alabama

UNIT NO:		243851 20	20 TOYOTA R	AV4				WORK OF	RDER NO:	474	93	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4	OPENE COMPL CLOSE 2020 Toyota R	ETED D DAT	DATE:	07/03/202	23 11:11:17 23 10:03:23 23 08:28:32	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	n: 20782 DATE:	ME1 09/25/2020	TER 2 - H:	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERI	<u>AL CO</u>	MMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	Ν	GARAGE	0.20	\$23.67	\$0.00	\$0.0	0	\$23.67
CH-SP	CHARGE	E Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.0	0	\$5.00
JOB COUN	T: 2			WC		DER TOTAL:	0.20	23.	67	0.00	5.00	28.67
Job Code		Job Description		v	endor N	<u>o.</u>	Invoice No.	Purchas	se Order No.			Total Cost
CH-SP	CHARGE SI	hop Supplies	5	03163		1						\$5.00
											COMML	5.00
Job Code		Job Description		En	nployee	No.	<u>Start</u>	Ē	<u>inish</u>		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	1	1074414	Ļ	06/	30/2023 11:30:21	06/30/202	3 11:42:23		0.20	\$23.67
											LABOR	23.67

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

243851 **2020 TOYOTA RAV4** UNIT NO:

WORK ORDER NO:

47493

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1336 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH EH

CH-SP - CHARGE Shop Supplies

The University of Alabama

		243851	2020 TOYO	DTA R	AV4				WORK OR	DER NO:	48694	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	507143 CLOSED SCHEDULED 20TOYOTARAV4		OPENE COMPL CLOSE	ETED	DATE:	10/30/202	3 11:39:29 3 09:49:20 3 10:16:38	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 22650 DATE: 0	Jniversity Automotive METER 2 - H: 09/25/2020 2T3H1RFV5LC0848	0
JOB CODE	L	JOB DESCRIPTIC	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATERIA	AL <u>COMMERCIA</u>	L TOTAL COST
06-15	INSPECT	STEERING		DON	Ν	Ν	GARAGE	0.08	\$9.60	\$0.00	\$0.00	\$9.60
66-17-013	PERFORM	ALIGNMENT		DON	Ν	Ν	GARAGE	3.74	\$440.80	\$0.00	\$0.00	\$440.80
66-17-028	PERFORM	/ MOUNT AND BA	LANCE TIRE	DON	Ν	Ν	GARAGE	0.67	\$79.45	\$313.37	\$0.00	\$392.82
66-PM-PMA	PERFORM	/ OIL CHANGE		DON	Р	Ν	GARAGE	0.32	\$38.09	\$87.51	\$0.00	\$125.60
66-PM-PMC	PERFORM	A CABIN FILTER R	REPLACEMEI	DON	Р	Ν	GARAGE	0.30	\$35.40	\$22.73	\$0.00	\$58.13
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
JOB COUN	IT: 6				WC		DER TOTAL:	5.11	603.3	4 42	3.61 5.0	0 1,031.95
Job Code		Job Descripti	ion		V	/endor N	<u>o.</u>	Invoice No.	Purchase	e Order No.		Total Cost
CH-SP	CHARGE Sho	op Supplies		5	03163		1					\$5.00
											COMML	5.00
Job Code		Job Descripti	ion			nployee		<u>Start</u>		<u>nish</u>	Quantity	Total Cost
<u>Job Code</u> 66-17-013	PERFORM AL		ion	1	<u>En</u> 1310047			<u>Start</u> 27/2023 13:23:08				Total Cost
	PERFORM AL	IGNMENT	ion			7	10/		10/27/2023	14:39:04	Quantity	Total Cost 7 \$149.34
66-17-013	PERFORM AL	IGNMENT		1	1310047	7	10/ 10/	27/2023 13:23:08	10/27/2023 10/26/2023	14:39:04 15:51:53	Quantity	Total Cost 7 \$149.34 7 \$291.46
66-17-013 66-17-013	PERFORM AL	LIGNMENT LIGNMENT OUNT AND BALANC		1	1310 <mark>047</mark> 1310047	7	10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41	10/27/2023 10/26/2023 10/26/2023	14:39:04 15:51:53 07:42:55	<mark>Quantity</mark> 1.2 2.4	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45
66-17-013 66-17-013 66-17-028	PERFORM AL	LIGNMENT LIGNMENT OUNT AND BALANC EERING		1 1 1	1310047 1310047 1074414	7 7 1	10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31	10/27/2023 10/26/2023 10/26/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53	<u>Quantity</u> 1.2 2.4 0.6	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60
66-17-013 66-17-013 66-17-028 06-15	PERFORM AL PERFORM M INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING		1 1 1 1	1310047 1310047 1074414 1074414	7 7 1 1	10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20	Quantity 1.2 2.4 0.6 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00
66-17-013 66-17-013 66-17-028 06-15 06-15	PERFORM AL PERFORM M INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING EERING		1 1 1 1 1	1310047 1310047 1074414 1074414 1074414	7 7 1 1 1	10/ 10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00 24/2023 14:20:20	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20 14:34:53	Quantity 1.2 2.4 0.6 0.0 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00 8 \$9.60
66-17-013 66-17-013 66-17-028 06-15 06-15 06-15	PERFORM AL PERFORM M INSPECT STE INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING EERING EERING		1 1 1 1 1 1	1310047 1310047 1074414 1074414 1074414 1074414	7 7 1 1 1	10/ 10/ 10/ 10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20 14:34:53 14:20:20	Quantity 1.2 2.4 0.6 0.0 0.0 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00
66-17-013 66-17-013 66-17-028 06-15 06-15 06-15 06-15	PERFORM AL PERFORM M INSPECT STE INSPECT STE INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING EERING EERING EERING		1 1 1 1 1 1 1 1	1310047 1310047 1074414 1074414 1074414 1074414 1074414	7 7 1 1 1 1 1	10/ 10/ 10/ 10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00 24/2023 14:20:20	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20 14:34:53 14:20:20 14:34:53	Quantity 1.2 2.4 0.6 0.0 0.0 0.0 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00
66-17-013 66-17-013 66-17-028 06-15 06-15 06-15 06-15 06-15	PERFORM AL PERFORM M INSPECT STE INSPECT STE INSPECT STE INSPECT STE INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING EERING EERING EERING	E TIRES	1 1 1 1 1 1 1 1 1	1310047 1310047 1074414 1074414 1074414 1074414 1074414 1074414	7 7 1 1 1 1 1	10/ 10/ 10/ 10/ 10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20 14:34:53 14:20:20 14:34:53 14:20:20	Quantity 1.2 2.4 0.6 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00
66-17-013 66-17-013 66-17-028 06-15 06-15 06-15 06-15 06-15 06-15	PERFORM AL PERFORM M INSPECT STE INSPECT STE INSPECT STE INSPECT STE INSPECT STE PERFORM C/	LIGNMENT LIGNMENT OUNT AND BALANC EERING EERING EERING EERING EERING EERING	CEMENT	1 1 1 1 1 1 1 1 1 1	1310047 1310047 1074414 1074414 1074414 1074414 1074414 1074414	7 7 1 1 1 1 1 1	10/ 10/ 10/ 10/ 10/ 10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00 24/2023 14:20:20 24/2023 14:30:00 24/2023 14:20:20	10/27/2023 10/26/2023 10/26/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53 14:20:20 14:34:53 14:20:20 14:34:53 14:20:20 14:36:33	Quantity 1.2 2.4 0.6 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	Total Cost 7 \$149.34 7 \$291.46 7 \$79.45 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$9.60 0 \$0.00 8 \$35.40
66-17-013 66-17-013 66-17-028 06-15	PERFORM AL PERFORM M INSPECT STE	LIGNMENT LIGNMENT OUNT AND BALANC EERING		1 1 1	1310047 1310047 1074414 1074414	7 7 1	10/ 10/ 10/ 10/	27/2023 13:23:08 26/2023 13:23:41 26/2023 07:02:31 24/2023 14:30:00	10/27/2023 10/26/2023 10/26/2023 10/24/2023	14:39:04 15:51:53 07:42:55 14:34:53	Quantity 1.2 2.4 0.6 0.0	Total Cos 7 \$14 7 \$29 7 \$29 7 \$3 8 \$

The University of Alabama

Work Order Charge Detail

<u>Job Code</u> 66-PM-PMA	Job Description PERFORM OIL CHANGE	Employee No. 11074414	<u>Start</u> <u>F</u> 10/24/2023 13:55:38 10/24/2023	inish 3 14:15:00	<u>Quantity</u> 0.32	<u>Total Cost</u> \$38.09
					LABOR	603.34
Job Code	Job Description	Part No.	Description	<u>Unit Price</u>	<u>Quantity</u>	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	005359	FSTONE DEST LE3 225/65R17	151.76	2	\$303.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.80	2	\$9.60
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.55	1	\$11.55
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	35.61	1	\$35.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.07	5	\$40.35
					PARTS	423.61

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

243851 **2020 TOYOTA RAV4** UNIT NO:

WORK ORDER NO:

48694

Work Order Notes

(LRUSHING) pm

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering. Found no issues at this time. SH (IFALLS) Visit Reason Changed On 10/30/2023 10:15 AM By IFALLS

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment, reset code link, and performed a road test after repair. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires. Put new tires on the front. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH (SHARBIN) Needs 2 rear tires due to 2/32 tread depth. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO: 243851 2020			2020 TOY	OYOTA RAV4						WORK ORDER NO: 49398				
USING DEPT NO:507143WO STATUS:CLOSEDWO VISIT REASON:SCHEDULEDTECH SPEC NO:20TOYOTARAV4		2020	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2020 Toyota Rav4			01/09/2024 08:27:11 01/10/2024 09:38:44 01/11/2024 09:26:11		LOCATION: GARAGE METER 1 - M: 23743 IN-SERVICE DATE: UNIT SERIAL NO:		E - University Automotive METER 2 - H: 09/25/2020 2T3H1RFV5LC084812		0		
JOB CODE	<u> </u>	JOB DESCRIPTI	ON	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL <u>C</u>	OMMERCIAL	TOTAL (COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Ρ	Ν	GARAGE	0.04	\$4.98	\$19.61	\$0).00	\$24.59	
66-PM-PMA	PERFOF	M OIL CHANGE		DON	Р	Ν	GARAGE	0.19	\$22.45	\$0.00	\$0).00	\$22.45	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 3				WO		DER TOTAL:	0.23	27.	43	19.61	5.00		52.04
Job Code		Job Descript	ion		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purchas	e Order No) <u>.</u>		<u>Total (</u>	<u>Cost</u>
CH-SP	CHARGE SI	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		En	nployee	<u>No.</u>	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total (<u>Cost</u>
03-51-038	REPLACE N	IEW WIPER BLADES		1	1074414		01/	/09/2024 10:51:20	01/09/202	4 10:53:52		0.04		\$4.98
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414	ļ	01/	/09/2024 10:39:33	01/09/202	4 10:50:58		0.19		\$22.45
												LABOR		27.43
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription	<u> </u>	<u> Jnit Price</u>	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	61		WI	PERS 16"			8.33	5 1		\$8.33
03-51-038	REPLACE N	IEW WIPER BLADES		2	6-1		WI	PER BLADE			11.28	3 1		\$11.28
												PARTS		19.61

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4		WORK ORDER NO:	49398
Work Order Notes	<u>5</u>				
(EHANNAH) pm					
Job Notes					
03-51-038 - REPLAC	E NEW WIPER BLA	ADES			
(SHARBIN) Replaced	the wipers. SH				
66-PM-PMA - PERFO	RM OIL CHANGE				
(SHARBIN) Driven 10	93 miles. Checked f	luids tire pressure and updated the	oil change sticker. SH		

CH-SP - CHARGE Shop Supplies

The University of Alabama

UNIT NO: 243851 2020 TOYO)TA R	AV4					DER NO:	49588			
WO STATUS WO VISIT R	USING DEPT NO: 507143 NO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 20TOYOTARAV4 2020			COMPLETED DATE: 0			02/13/20	24 07:57:49 24 11:05:32 24 09:18:35	LOCATION: 0 METER 1 - M: IN-SERVICE D UNIT SERIAL	23905 DATE: 09/25	ersity Automotive METER 2 - H: 5/2020 11RFV5LC084812	0
JOB CODE	<u>E</u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-023	REPLAC	E NEW HANDLES	- INNER & OL	DON	0	Ν	GARAGE	1.34	\$157.63	\$19.25	\$0.00	\$176.88
06-05	INSPEC	FELECTRONIC EN	IGINE EEC S'	DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00	\$103.44	\$103.44
16-05	TRANSP	ORT ELECTRONIC		DON	0	Ν	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN O	UT ELECTRONIC E		DON	0	Ν	GARAGE	1.23	\$144.68	\$0.00	\$0.00	\$144.68
JOB COUN	IT: 5				wo	RK ORI	DER TOTAL	: 3.06	361.31	1 19.25	5 108.44	489.
Job Code		Job Descript	tion		V	endor N	<u>o.</u>	Invoice No.	Purchase	Order No.		Total Cost
06-05	INSPECT EI	ECTRONIC ENGINE	EEC SYSTEM	1	1076422		62	36474				\$103
06-05	INSPECT EI	ECTRONIC ENGINE	EEC SYSTEM	1	1076422		62	37457				(\$103.4
06-05	INSPECT EI	ECTRONIC ENGINE	EEC SYSTEM	1	1076422		62	37457				\$103
CH-SP	CHARGE SH	nop Supplies		5	03163		1					\$5.
											COMML	108.
Job Code		Job Descript	tion		Em	nployee	<u>No.</u>	<u>Start</u>	<u>Fin</u>	<u>iish</u>	<u>Quantity</u>	Total Cost
16-05	TRANSPOR	T ELECTRONIC ENG	GINE EEC SYSTE	EM 1	1399745		02	2/13/2024 07:00:00	02/13/2024 (07:30:00	0.50	\$59.
03-02-023	REPLACE N	IEW HANDLES - INNI	ER & OUTER	1	1310047		01	/31/2024 14:09:57	01/31/2024	15:30:06	1.34	\$157.
SO-05	SCAN OUT	ELECTRONIC ENGIN	NE EEC SYSTEM	1 1	1310047		01	/26/2024 09:46:26	01/26/2024	11:00:00	1.23	\$144.
											LABOR	361.
Job Code		Job Descript	tion			Part No	<u>.</u>	Des	cription	<u>Unit Pr</u>	ice Quantity	Total Cost
03-02-023	REPLACE N	IEW HANDLES - INNI	ER & OUTER	7	24950R0	040CO	SI	EAT BACK HANDL	E	1	9.251	\$19
											PARTS	19.

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 49588

Work Order Notes

(EHANNAH) trouble starting- and missing the driver side seat handle

Job Notes

03-02-023 - REPLACE NEW HANDLES - INNER & OUTER

(EHOWELL) Installed a new plastic handle to raise and lower the driver's seat. EH .1 HR

06-05 - INSPECT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Tuscaloosa Toyota ran health check history codes from 1/25 x0810 x0800 engine difficult to start and engine stalled no present codes. (LISAPATE) Tuscaloosa Toyota ran health check performed active test on power steering no codes present no history codes tested battery.

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Taken to Toyota by CW

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Checked for DTCs. Called the dealership and asked about open recalls, but there was not a related recall. Browsed through TSBs to see if anything sounded related. The vehicle is not acting up at this time. There are no warning lights on, and we have driven the vehicle 41 miles in an attempt to duplicate the concern. Also, examined under the hood and raise the vehicle on a rack to examine underneath. No obvious damage was found. We are sending the vehicle to the dealership for them to inspect, since this is a safety related concern. The customer's complaint has been given in writing for an aid to the technician. EH

The University of Alabama

UNIT NO:		243851	2020 TOY	OTA R	AV4	WORK ORDER NO:			:	49886				
WO STATU WO VISIT F	SING DEPT NO:507143/O STATUS:CLOSED/O VISIT REASON:SCHEDULEDECH SPEC NO:20TOYOTARAV42020		2020 -	OPENED DATE: COMPLETED DATE: CLOSED DATE: Toyota Rav4			03/04/202			LOCATION: GARAGE METER 1 - M: 24311 IN-SERVICE DATE: UNIT SERIAL NO:		- University Automotive S METER 2 - H: 09/25/2020 2T3H1RFV5LC084812		۶
JOB CODE	JOB CODE JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL		<u>ь тот</u>	AL COST	
06-15-028	INSPEC [®]	T GEAR SHIFT LEV	VER	DON	Ν	Ν	GARAGE	3.00	\$353.51	\$0.00		\$0.00	\$353.5	51
14-52-021	INSTALL	GPS SYSTEM		DON	0	Ν	GARAGE	0.54	\$64.05	\$0.00		\$0.00	\$64.05	j.
16-00	TRANSF	ORT COMPLETE	VEHICLE	DON	0	Ν	GARAGE	0.50	\$59.00	\$0.00		\$0.00	\$59.00)
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
SO-00	SCAN O	UT COMPLETE VE	HICLE	DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00		\$103.44	\$103.4	4
SO-05	SCAN O	UT ELECTRONIC I		DON	0	Ν	GARAGE	1.00	\$118.00	\$13.11		\$0.00	\$131.1	.1
JOB COUN	IT: 6				wc	RK OR	DER TOTAL:	5.04	59	4.56	13.11	108.4	14	716.11
Job Code		Job Descrip	tion		v	endor N	lo.	Invoice No.	Purch	ase Order No) <u>.</u>		To	tal Cost
SO-00	SCAN OUT	COMPLETE VEHICL	.E	1	1076422	2	62	37457						\$103.44
CH-SP	CHARGE SI	hop Supplies		5	03163		1							\$5.00
												COMML		108.44
<u>Job Code</u>		Job Descrip	<u>tion</u>		En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u> </u>	tal Cost
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/21/2024 12:48:00	02/21/20	24 12:48:00		0.0	00	\$0.00
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/21/2024 13:00:00	02/21/20	24 14:07:39		1.1	3	\$133.05
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/21/2024 12:48:00	02/21/20	24 12:48:00		0.0	00	\$0.00
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/21/2024 13:00:00	02/21/20	24 14:07:39		(1.1	3)	(\$133.05)
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/26/2024 07:48:22	02/26/20	24 07:53:10		0.0	8	\$9.44
SO-00	SCAN OUT	COMPLETE VEHICL	E	1	2052187	7	02	/26/2024 07:48:22	02/26/20	24 07:53:10		(0.0	8)	(\$9.44)
14-52-021	INSTALL GF	PS SYSTEM		1	1074414	Ļ	02	/26/2024 08:17:02	02/26/20	24 08:49:36		0.5	54	\$64.05
06-15-028	INSPECT G	EAR SHIFT LEVER		1	2052187	7	02	/26/2024 07:53:10	02/26/20	24 10:52:55		3.0	00	\$353.51
16-00	TRANSPOR	RT COMPLETE VEHIC	CLE	1	1399745	5	03/	/04/2024 07:00:00	03/04/20	24 07:30:00		0.5	50	\$59.00
SO-05	SCAN OUT	ELECTRONIC ENGI	NE EEC SYSTEM	VI 1	2052187	7	03	/04/2024 07:00:00	03/04/20	24 08:00:00		1.0	00	\$118.00
												LABOR		594.56

The University of Alabama

Job Code	Job Description	Part No.	Description	<u>Unit Price</u>	<u>Quantity</u>	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
SO-00	SCAN OUT COMPLETE VEHICLE	SF16	SEA FOAM 16OZ	13.11	(1)	(\$13.11)
SO-00	SCAN OUT COMPLETE VEHICLE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	13.11

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 49886

Work Order Notes

(EHANNAH) scan out due to check engine light being on- inspect gear shift due to hard to shift gears. (EHANNAH) install GPS

Job Notes

06-15-028 - INSPECT GEAR SHIFT LEVER

(GARAGE) Inspected gear shift and removed panels to inspect linkages. Found no issues. Unit was shifting into each gear with no problem. Lubricated the linkages to be sure it was not trying to hang at all. JAW

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240051. SH

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Taken to Toyota by CW

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(IFALLS) Tuscaloosa Toyota ran health check performed active test on power steering no codes present no history codes. tested battery. Pd by CC not warranty

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) scanned unit and has code p0505 idle control system and p117b fuel performance direct injector. Tested everything with mitchel and common cause is mass air flow sensor. Cleaned sensor and ran seafoam in gas. Test drove using unit to make runs all day and also drove on interstate. Also let unit idle for an hour. Engine light did not return and found no other issues. JAW

The University of Alabama

UNIT NO: 243851 2		2020 TOYOTA RAV4							DER NO	: 5	50191			
WO STATUS WO VISIT R	USING DEPT NO: 507143 WO STATUS: CLOSED WO VISIT REASON: SCHEDULED TECH SPEC NO: 20TOYOTARAV4		OPENED DATE: COMPLETED DATE: CLOSED DATE: 2020 Toyota Rav4			03/25/202	24 11:25:45 24 11:11:27 24 13:14:44	LOCATION: GARAGE - METER 1 - M: 24788 IN-SERVICE DATE: UNIT SERIAL NO:		- University Automotive S METER 2 - H: 09/25/2020 2T3H1RFV5LC084812		0		
JOB CODE	L	JOB DESCRIPTION	<u>NC</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C		TOTAL	COST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.21	\$25.04	\$55.96	\$	0.00	\$81.00	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00	
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	0.21	25.04	Ļ	55.96	5.00		86.00
Job Code		Job Descript	<u>ion</u>		v	endor N	0.	Invoice No.	Purchase	Order No	<u>).</u>		<u>Total</u>	<u>Cost</u>
CH-SP	CHARGE SH	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descript	<u>ion</u>		En	nployee	<u>No.</u>	<u>Start</u>	<u>Fin</u>	<u>ish</u>		<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		1	2395904	ļ	03	/22/2024 09:21:16	03/22/2024 0	09:21:16		0.00		\$0.00
66-PM-PMA	PERFORM	OIL CHANGE		1	2395904	Ļ	03	/22/2024 09:30:00	03/22/2024 0)9:42:44		0.21		\$25.04
												LABOR		25.04
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	cription	<u>L</u>	Jnit Price	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		0	5089		BF	RAKE CLEAN NON	N-FLAMMABLE 14	oz	7.6	5 1		\$7.65
66-PM-PMA	PERFORM	OIL CHANGE		0	W16T		OI	L 0W16 CAM2 LSI	PI SN4+ QT		8.1	8 5		\$40.88
66-PM-PMA	PERFORM	OIL CHANGE		Р	G4476F		OI	L FILTER			7.4	3 1		\$7.43
												PARTS		55.96

The University of Alabama Report Printed: 04/25/2024 14:49:37 By User: GLOBETTI

UNIT NO:	243851	2020 TOYOTA RAV4	WO	ORK ORDER NO:	50191
Work Order Notes	<u>.</u>				
(CWIGLEY) PM					
Job Notes					
66-PM-PMA - PERFO	RM OIL CHANGE				
(FCONTRER) perform	oil changes FC - a	ah			
CH-SP - CHARGE Sh	op Supplies				

The University of Alabama

UNIT NO:		243851	2020 TOYO	DTA R	AV4				WORK C	RDER NO	: {	50570		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	507143 COMPLETED SCHEDULED 20TOYOTARAV4		OPENE COMPL CLOSE	ETED	DATE:		24 08:08:31 24 08:39:36	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 25345 E DATE:	N 09/25/2	sity Automotive S METER 2 - H: 2020 RFV5LC084812	0	
JOB CODE		JOB DESCRIPTIO	NC	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOF	<u>MATE</u>	RIAL (COMMERCIAL	TOTAL	COST
06-32-002	INSPEC ⁻	FBATTERY		DON	Ν	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	50.00	\$0.00	
66-00-999	PERFOR	M PREPARE UNIT	FOR DISPOS	DON	D	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	50.00	\$0.00	
SO-05	SCAN O	UT ELECTRONIC E		DON	0	Ν	GARAGE	0.10	\$12.23	\$0.00	\$	\$0.00	\$12.23	
JOB COUN	IT: 3				WO		DER TOTAL:	0.10	1	2.23	0.00	0.00		12.23
Job Code		Job Descript	ion		Em	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
SO-05	SCAN OUT	ELECTRONIC ENGIN	E EEC SYSTEM	1 1	1310047	,	04	/15/2024 09:52:23	04/15/20	024 09:58:36		0.10		\$12.23
												LABOR		12.23

UNIT NO: 243851 2020 TOYOTA RAV4

WORK ORDER NO: 50570

Work Order Notes

(EHANNAH) inspect battery- scan out.- Driver report smelling gas

Job Notes

06-32-002 - INSPECT BATTERY

(EHOWELL) The vehicle is starting properly. EH

66-00-999 - PERFORM PREPARE UNIT FOR DISPOSAL

(LISAPATE) Prep for sale completed. FC

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) The check engine light is not on. Did not perform a scan out. Inspected the high-pressure fuel pump for leaks. Looked beneath the vehicle for fuel on the ground. The vehicle is now a Prep for Sale. EH

Report Title:	WODETAIL - Work Order Detail v20.0
Report Author:	FleetFocus M5
File Path:	E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~1
Data Extracted:	Thu Apr 25 2024 14:49:37 Report User: GLOBETTI
TZ:	Central Standard Time
DLL Version:	2021.02.23
Report Comments:	6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 Parameters and Selection Filters
First Grouping:	VIEW_WO_WORKSHEET.WO_NO
Second Grouping:	VIEW_JOB_WORKSHEET.JOB
Third Grouping:	
Sorted By:	
From Date:	
To Date:	
Option 1:	
Option 2:	
Selection Filters:	isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '2T3H1RFV5LC084812') //Q=