

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 19280

USING DEPT NO: 510101	OPENED DATE: 01/21/2015 08:31:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/22/2015 13:56:36	METER 1 - M: 57 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/22/2015 13:56:37	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK1FU488734

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **28.75** **0.00** **0.00** **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10260422	01/21/2015 08:31:38	01/21/2015 09:01:38	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 19280

Work Order Notes

(LPATE) PDI NEW CAR

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 19884

USING DEPT NO:	510101	OPENED DATE:	03/27/2015 10:41:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2015 11:56:23	METER 1 - M:	4395	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2015 11:56:25	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.72	\$41.64	\$29.67	\$0.00	\$71.31

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.72** **41.64** **29.67** **0.00** **71.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/27/2015 13:59:23	03/27/2015 14:42:50	0.72	\$41.64
					LABOR	41.64

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.69	4	\$22.74
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	29.67

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 19884

Work Order Notes

(GMANNING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 20352

USING DEPT NO: 510101	OPENED DATE: 05/25/2015 10:56:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/27/2015 14:43:58	METER 1 - M: 9645 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/27/2015 14:43:59	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$18.83	\$29.54	\$0.00	\$48.37

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.33** **18.83** **29.54** **0.00** **48.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	05/25/2015 14:48:56	05/25/2015 15:08:35	0.33	\$18.83
					LABOR	18.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.77	4	\$15.08
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	(1)	(\$4.61)
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.77	(4)	(\$15.08)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.66	4	\$22.62
					PARTS	29.54

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 20352

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY GM

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY WORK ORDER NO: 20869

USING DEPT NO:	510101	OPENED DATE:	07/23/2015 08:20:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/24/2015 11:21:35	METER 1 - M:	14206	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/24/2015 11:21:36	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$1.74	\$29.34	\$0.00	\$31.08

JOB COUNT: 1 WORK ORDER TOTAL: 0.03 1.74 29.34 0.00 31.08

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	07/23/2015 11:47:53	07/23/2015 11:49:42	0.03	\$1.74
					LABOR	1.74

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	4	\$22.56
					PARTS	29.34

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 20869

Work Order Notes

(LPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY WORK ORDER NO: 21488

USING DEPT NO:	510101	OPENED DATE:	09/21/2015 09:44:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2015 10:38:50	METER 1 - M:	18891	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2015 10:38:51	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$21.79	\$29.67	\$0.00	\$51.46

JOB COUNT: 1 WORK ORDER TOTAL: 0.38 21.79 29.67 0.00 51.46

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	09/21/2015 11:30:59	09/21/2015 11:53:43	0.38	\$21.79
					LABOR	21.79

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20NP	OIL 0W-20 SYN NAPA	5.69	4	\$22.74
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
					PARTS	29.67

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 21488

Work Order Notes

(LISAPATE) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM/RS

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY WORK ORDER NO: 22027

USING DEPT NO:	510101	OPENED DATE:	11/18/2015 07:47:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/20/2015 08:24:53	METER 1 - M:	23908	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/20/2015 08:24:54	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.75	\$43.00	\$47.07	\$0.00	\$90.07

JOB COUNT: 1 WORK ORDER TOTAL: 0.75 43.00 47.07 0.00 90.07

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/18/2015 09:40:20	11/18/2015 10:25:12	0.75	\$43.00
					LABOR	43.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.92	1	\$6.92
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.95	1	\$11.95
					PARTS	47.07

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 22027

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH-REPLACED AIR FILTER

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 22545

USING DEPT NO: 510101	OPENED DATE: 02/15/2016 13:14:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/17/2016 07:33:48	METER 1 - M: 28431 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/17/2016 07:33:49	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK1FU488734

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$25.58	\$0.00	\$39.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$35.01	\$0.00	\$52.84

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.56** **32.21** **60.59** **0.00** **92.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/15/2016 15:52:50	02/15/2016 16:11:26	0.31	\$17.83
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/15/2016 15:52:57	02/15/2016 16:07:57	0.25	\$14.38
					LABOR	32.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.81	1	\$6.81
					PARTS	60.59

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 22545

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 23310

USING DEPT NO: 510101	OPENED DATE: 05/06/2016 09:33:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/09/2016 10:39:06	METER 1 - M: 33711 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2016 10:39:08	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK1FU488734

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$30.08	\$35.13	\$0.00	\$65.21
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$3.87	\$7.35	\$0.00	\$11.22

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.59** **33.95** **42.48** **0.00** **76.43**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/09/2016 08:46:00	05/09/2016 08:50:02	0.07	\$3.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/09/2016 08:14:28	05/09/2016 08:45:51	0.52	\$30.08
					LABOR	33.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.35	1	\$7.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
					PARTS	42.48

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 23310

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 24148

USING DEPT NO:	510101	OPENED DATE:	08/16/2016 11:48:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/19/2016 08:21:24	METER 1 - M:	39191	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/19/2016 08:21:25	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.04	\$59.78	\$35.13	\$0.00	\$94.91

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.04** **59.78** **35.13** **0.00** **94.91**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/18/2016 07:00:52	08/18/2016 08:03:15	1.04	\$59.78
					LABOR	59.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
					PARTS	35.13

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 24148

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 25668

USING DEPT NO: 510101	OPENED DATE: 02/06/2017 08:31:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/20/2017 13:36:05	METER 1 - M: 43474 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/20/2017 13:36:07	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK1FU488734

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.66	\$38.14	\$0.00	\$0.00	\$38.14
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,134.18	\$1,134.18
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$20.13	\$50.21	\$0.00	\$70.34

JOB COUNT: 3	WORK ORDER TOTAL:	1.01	58.27	50.21	1,134.18	1,242.66
---------------------	--------------------------	-------------	--------------	--------------	-----------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	165560	0037479	\$1,134.18
24-71	REPAIR BODY	11150605	165560	0037479	\$1,134.19
24-71	REPAIR BODY	11150605	165560	0037479	(\$1,134.19)
COMML					1134.18

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/10/2017 06:15:59	02/10/2017 06:36:59	0.35	\$20.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/10/2017 06:15:59	02/10/2017 13:36:50	(7.35)	(\$422.48)
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/10/2017 06:15:59	02/10/2017 13:36:50	7.35	\$422.48
16-71	TRANSPORT BODY	10208562	02/07/2017 10:08:34	02/07/2017 10:48:22	0.66	\$38.14
LABOR					58.27	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.95	1	\$6.95
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	5.64	5	\$28.20
PARTS					50.21	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 25668

Work Order Notes

(IFALLS) ANDREWS BODY SHOP FOR REPAIRS/ PM

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) TAKEN TO ANDREWS BY EK

24-71 - REPAIR BODY

(LISAPATE) ANDREW'S REPAIRED FRONT BUMPER DAMAGE PER THE ESTIMATE. PD BY CC INVOICE AND ESTIMATE ATTACHED

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH
REPLACED AIR FILTER
COOLANT -40'

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 26376

USING DEPT NO:	510101	OPENED DATE:	05/18/2017 13:01:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2017 06:52:30	METER 1 - M:	48299	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	05/23/2017 06:52:31	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.30	\$74.72	\$42.70	\$0.00	\$117.42

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.30** **74.72** **42.70** **0.00** **117.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	05/19/2017 07:20:15	05/19/2017 08:38:13	1.30	\$74.72
					LABOR	74.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.79	1	\$6.79
					PARTS	42.70

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 26376

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) CS PERFORMED THE OIL CHANGE. COOLANT TESTED GOOD @ -30F

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 27203

USING DEPT NO:	510101	OPENED DATE:	08/20/2017 13:32:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/22/2017 09:20:47	METER 1 - M:	52524	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/22/2017 09:20:48	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$23.00	\$6.18	\$0.00	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.79	\$0.00	\$44.62
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$205.64	\$205.64

JOB COUNT: 3	WORK ORDER TOTAL:	0.71	40.83	32.97	205.64	279.44
---------------------	--------------------------	-------------	--------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	231802	0039767	\$205.64
COMML					205.64

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	08/20/2017 13:33:30	08/20/2017 13:52:06	0.31	\$17.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	08/20/2017 13:33:36	08/20/2017 13:57:36	0.40	\$23.00
LABOR					40.83	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.36	4	\$1.44
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	2.37	2	\$4.74
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	4	\$16.68
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	3.18	1	\$3.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.93	1	\$6.93
PARTS					32.97	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 27203

Work Order Notes

(LISAPATE) PM-NEEDS 2 TIRES

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNTED AND BALANCED 2 NEW TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY TB/CS

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 2 TIRES FROM FIRESTONE. PD BY CC

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 27866

USING DEPT NO: 510101	OPENED DATE: 10/18/2017 09:44:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/20/2017 14:52:50	METER 1 - M: 57568 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/20/2017 14:52:52	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$39.62	\$0.00	\$57.45
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$17.25	\$7.33	\$0.00	\$24.58

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.61** **35.08** **46.95** **0.00** **82.03**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	10/19/2017 07:18:36	10/19/2017 07:36:36	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/19/2017 07:00:00	10/19/2017 07:18:36	0.31	\$17.83
					LABOR	35.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	11.88	1	\$11.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.17	5	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.89	1	\$6.89
					PARTS	46.95

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 27866

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS-REPLACED AIR FILTER

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 28720

USING DEPT NO:	510101	OPENED DATE:	01/26/2018 09:45:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/05/2018 06:51:34	METER 1 - M:	60378	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/05/2018 06:51:36	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-05-029	REPLACE NEW PURGE SOLENOID/CAN	DON	O	N	GARAGE	3.20	\$184.00	\$689.99	\$0.00	\$873.99
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.55	\$31.69	\$0.00	\$0.00	\$31.69
66-44-061	PERFORM SMOKE TEST	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$69.00	\$69.00
PU-78-036	PURCHASED TOUCH UP PAINT	DON	O	N	GARAGE	0.00	\$0.00	\$13.27	\$0.00	\$13.27
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 5	WORK ORDER TOTAL:	5.25	301.94	703.26	69.00	1,074.20
---------------------	--------------------------	-------------	---------------	---------------	--------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
66-44-061	PERFORM SMOKE TEST	11122732	238710	0041987	\$69.00
				COMML	69.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	02/01/2018 07:00:00	02/01/2018 09:00:00	(2.00)	(\$115.00)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	02/01/2018 07:00:00	02/01/2018 09:00:00	2.00	\$115.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	02/01/2018 07:00:00	02/01/2018 08:30:00	1.50	\$86.25
03-05-029	REPLACE NEW PURGE SOLENOID/CANISTER	11213180	02/01/2018 07:00:00	02/01/2018 10:12:00	3.20	\$184.00
16-44	TRANSPORT FUEL SYSTEM	10208562	01/29/2018 14:30:00	01/29/2018 15:03:04	0.55	\$31.69
16-44	TRANSPORT FUEL SYSTEM	10208562	01/29/2018 13:00:00	01/29/2018 14:15:00	1.25	\$71.88
16-44	TRANSPORT FUEL SYSTEM	10208562	01/29/2018 10:22:09	01/29/2018 12:00:00	1.63	\$93.77
16-44	TRANSPORT FUEL SYSTEM	10208562	01/29/2018 13:00:00	01/29/2018 14:15:00	(1.25)	(\$71.88)
16-44	TRANSPORT FUEL SYSTEM	10208562	01/29/2018 10:22:09	01/29/2018 12:00:00	(1.63)	(\$93.77)
					LABOR	301.94

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-05-029	REPLACE NEW PURGE SOLENOID/CANISTER	7774006180	EVAP CANISTER ASSY	689.99	1	\$689.99
PU-78-036	PURCHASED TOUCH UP PAINT	002580004021	WHITE TOUCH UP PAINT	13.27	1	\$13.27

Work Order Charge Detail

PARTS

703.26

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 28720

Work Order Notes

(LISAPATE) MIL ON
DRIVER REQUESTED TOUCH-UP PAINT

Job Notes

03-05-029 - REPLACE NEW PURGE SOLENOID/CANISTER

(LISAPATE) PERFORMED BY MS/AB
FUEL TANK REMOVAL REQUIRED TO REPLACE CANISTER
RESCAN ALL OK, CODES CLEAR

16-44 - TRANSPORT FUEL SYSTEM

(LISAPATE) TRANSPORT BY EK

66-44-061 - PERFORM SMOKE TEST

(LISAPATE) PERFORMED BY FIRESTONE, PAID BY CC
NEW CANISTER RECOMMENDED,

PU-78-036 - PURCHASED TOUCH UP PAINT

(LISAPATE) PURCHASED AT TOYOTA, GAVE TO DAN

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) PERFORMED BY MS
P0441,P0455 - EVAP SYSTEM

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 29550

USING DEPT NO:	510101	OPENED DATE:	04/24/2018 13:07:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/07/2018 11:00:11	METER 1 - M:	61029	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	05/07/2018 11:00:13	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$29.80	\$0.00	\$47.63

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.31** **17.83** **29.80** **0.00** **47.63**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/03/2018 07:00:00	05/03/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.52	1	\$6.52
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	4	\$23.28
					PARTS	29.80

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 29550

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/AG
COOLANT -20'

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 31106

USING DEPT NO: 510101	OPENED DATE: 10/08/2018 14:35:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2018 13:44:03	METER 1 - M: 61264 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/18/2018 13:44:05	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T1BF1FK1FU488734

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.71	\$123.98	\$8.22	\$0.00	\$132.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$72.50	\$41.97	\$0.00	\$114.47
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$181.36	\$181.36

JOB COUNT: 4 **WORK ORDER TOTAL:** **3.71** **268.98** **50.19** **181.36** **500.53**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	249804	0045442	\$181.36
				COMML	181.36

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 09:30:00	10/11/2018 12:00:00	(2.50)	(\$181.25)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 14:30:00	10/11/2018 09:15:00	(18.75)	(\$1,359.38)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 09:30:00	10/10/2018 12:00:00	(2.50)	(\$181.25)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 14:30:00	10/10/2018 09:15:00	(18.75)	(\$1,359.38)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 13:00:00	10/09/2018 14:15:00	(1.25)	(\$90.63)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 10:20:49	10/09/2018 12:00:00	(1.65)	(\$119.85)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 14:30:00	10/12/2018 09:15:00	(18.75)	(\$1,359.38)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 09:30:00	10/12/2018 12:00:00	(2.50)	(\$181.25)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 13:00:00	10/12/2018 14:15:00	1.25	\$90.63
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 09:30:00	10/12/2018 12:00:00	2.50	\$181.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 14:30:00	10/12/2018 09:15:00	18.75	\$1,359.38
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 13:00:00	10/11/2018 14:15:00	1.25	\$90.63
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 09:30:00	10/11/2018 12:00:00	2.50	\$181.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 14:30:00	10/11/2018 09:15:00	18.75	\$1,359.38
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 13:00:00	10/10/2018 14:15:00	1.25	\$90.63

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 09:30:00	10/10/2018 12:00:00	2.50	\$181.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 14:30:00	10/10/2018 09:15:00	18.75	\$1,359.38
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 13:00:00	10/09/2018 14:15:00	1.25	\$90.63
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/09/2018 10:20:49	10/09/2018 12:00:00	1.65	\$119.85
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/15/2018 07:00:00	10/15/2018 08:00:00	1.00	\$72.50
09-15	ALIGN STEERING	11213180	10/15/2018 07:00:00	10/15/2018 08:00:00	1.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/15/2018 08:33:02	10/15/2018 10:15:38	1.71	\$123.98
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 13:00:00	10/12/2018 14:15:00	(1.25)	(\$90.63)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2018 13:00:00	10/10/2018 14:15:00	(1.25)	(\$90.63)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/11/2018 13:00:00	10/11/2018 14:15:00	(1.25)	(\$90.63)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 14:30:00	10/15/2018 14:05:26	71.59	\$5,190.32
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/12/2018 14:30:00	10/15/2018 14:05:26	(71.59)	(\$5,190.32)
					LABOR	268.98

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	4	\$1.62
					PARTS	50.19

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 31106

Work Order Notes

(LISAPATE) @40 mph hearing a scrubbing noise when coasting in rear end-PM due

Job Notes

06-13 - INSPECT BRAKES

09-15 - ALIGN STEERING

(LISAPATE) MS performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) IF/CS mounted and balanced 2 new rear tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Pm by CS

Coolant -27'

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) Purchased 2 tires from Firestone. Pd by cc

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 31961

USING DEPT NO: 510101	OPENED DATE: 01/17/2019 10:43:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/22/2019 14:26:43	METER 1 - M: 61476 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/22/2019 14:26:45	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$40.22	\$41.97	\$0.00	\$82.19

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.55** **40.22** **41.97** **0.00** **82.19**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/17/2019 13:26:08	01/17/2019 13:43:17	0.29	\$20.72
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/17/2019 13:25:04	01/17/2019 13:41:12	0.27	\$19.49
					LABOR	40.21

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.83	5	\$29.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.49	1	\$6.49
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
					PARTS	41.97

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 31961

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,RC/SH
Coolant -35'

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 32202

USING DEPT NO:	510101	OPENED DATE:	02/15/2019 13:38:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2019 11:37:40	METER 1 - M:	61555	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2019 11:37:43	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-44-061	PERFORM SMOKE TEST	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.00	\$145.00	\$0.00	\$0.00	\$145.00

JOB COUNT: 2 **WORK ORDER TOTAL: 3.00 217.50 0.00 0.00 217.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-44-061	PERFORM SMOKE TEST	11213180	02/21/2019 07:00:00	02/21/2019 08:00:00	1.00	\$72.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	02/19/2019 07:00:00	02/19/2019 09:00:00	2.00	\$145.00
					LABOR	217.50

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 32202

Work Order Notes

(LISAPATE) Check engine light on- steady-running fine

Job Notes

66-44-061 - PERFORM SMOKE TEST

(LISAPATE) Performed smoke test to check system

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out (OTC Evolve) P0441 Evap incorrect purge flow-P0455 Evap leak detected(gross leak)

Found gas cap was not fully sealed to the filler neck it was cross threaded and still loose. Properly installed cap and rechecked ok. Checked proper function of vent valve and purge solenoid both good and checked lines for leaks.

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 33670

USING DEPT NO:	510101	OPENED DATE:	08/08/2019 15:07:36	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/13/2019 07:48:36	METER 1 - M:	62070	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/13/2019 07:48:38	IN-SERVICE DATE:	01/20/2015		
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.31	\$22.52	\$114.90	\$0.00	\$137.42
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.08	\$5.44	\$25.58	\$0.00	\$31.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.49	\$108.09	\$35.68	\$0.00	\$143.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.04	\$3.04	\$7.33	\$0.00	\$10.37

JOB COUNT: 4	WORK ORDER TOTAL:	1.92	139.09	183.49	0.00	322.58
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2019 09:26:29	08/09/2019 10:13:47	0.79	\$57.15
03-32-002	REPLACE NEW BATTERY	11901357	08/09/2019 09:07:51	08/09/2019 09:26:29	0.31	\$22.52
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2019 08:41:05	08/09/2019 09:07:51	0.45	\$32.34
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/09/2019 08:38:34	08/09/2019 08:41:05	0.04	\$3.04
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/09/2019 08:34:04	08/09/2019 08:38:34	0.08	\$5.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/09/2019 08:18:41	08/09/2019 08:34:04	0.26	\$18.59
					LABOR	139.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.68	2	\$1.35
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	183.49

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 33670

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Battery failed, Replaced battery and checked charging system is good at 14.1 volts

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 36603

USING DEPT NO: 510101	OPENED DATE: 05/27/2020 10:59:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/28/2020 09:43:08	METER 1 - M: 62346 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/28/2020 13:55:47	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.86	\$135.15	\$39.07	\$0.00	\$174.22

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.86** **135.15** **39.07** **0.00** **174.22**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11915538	05/27/2020 13:38:48	05/27/2020 13:54:30	0.26	\$18.97
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/27/2020 11:23:40	05/27/2020 12:59:49	1.60	\$116.18
					LABOR	135.15

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	3.39	1	\$3.39
					PARTS	39.07

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 36603

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/AG performed pm. coolant -34.

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 38075

USING DEPT NO: 510101	OPENED DATE: 10/20/2020 08:25:28	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/21/2020 08:47:49	METER 1 - M: 62372 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/22/2020 07:44:59	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.29	\$0.00	\$0.00	\$28.29

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.24** **28.29** **0.00** **0.00** **28.29**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/20/2020 13:00:00	10/20/2020 13:14:23	0.24	\$28.29
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/20/2020 12:58:54	10/20/2020 12:58:54	0.00	\$0.00
					LABOR	28.29

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 38075

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Vehicle has been 26 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. AMG Scott assisted.

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 38792

USING DEPT NO: 510101	OPENED DATE: 01/14/2021 12:57:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/14/2021 13:41:17	METER 1 - M: 62372 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/14/2021 15:04:43	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$3.26	\$0.00	\$15.06

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.10** **11.80** **3.26** **0.00** **15.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	10321076	01/14/2021 15:04:23	01/14/2021 15:10:23	0.10	\$11.80
					LABOR	11.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.26	1	\$3.26
					PARTS	3.26

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 38792

Work Order Notes

(EKIMBREL) Replace key fob battery

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(LISAPATE) Replaced key fob battery. RT

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY WORK ORDER NO: 39472

USING DEPT NO:	510101	OPENED DATE:	03/23/2021 10:02:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2021 14:59:14	METER 1 - M:	63617	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2021 07:37:55	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.79	\$25.58	\$0.00	\$75.37

JOB COUNT: 1 WORK ORDER TOTAL: 0.42 49.79 25.58 0.00 75.37

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/23/2021 15:11:00	03/23/2021 15:36:19	0.42	\$49.79
					LABOR	49.79

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	4	\$17.94
					PARTS	25.58

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 39472

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW
MILEAGE-63617

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 40618

USING DEPT NO: 510101	OPENED DATE: 08/03/2021 09:06:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/09/2021 09:37:39	METER 1 - M: 64002 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/09/2021 15:14:27	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.36	\$17.28	\$0.00	\$23.64
06-15	INSPECT STEERING	DON	O	N	GARAGE	2.07	\$244.69	\$0.00	\$0.00	\$244.69
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.76	\$90.01	\$0.00	\$0.00	\$90.01
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.79	\$93.06	\$275.61	\$0.00	\$368.67
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.03	\$3.28	\$0.00	\$0.00	\$3.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$32.32	\$0.00	\$0.00	\$32.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7 **WORK ORDER TOTAL:** **3.98** **469.72** **292.89** **2.00** **764.61**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	08/06/2021 14:23:05	08/06/2021 14:24:45	0.03	\$3.28
06-15	INSPECT STEERING	11310047	08/05/2021 13:01:42	08/05/2021 15:06:07	2.07	\$244.69
09-15	ALIGN STEERING	11310047	08/05/2021 12:08:59	08/05/2021 12:54:45	0.76	\$90.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/05/2021 07:10:50	08/05/2021 07:58:09	0.79	\$93.06
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/03/2021 11:43:08	08/03/2021 11:46:22	0.05	\$6.36
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/03/2021 11:26:20	08/03/2021 11:42:46	0.27	\$32.32
LABOR					469.72	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.95	1	\$9.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	FIR003196	TIRE P205/65R16 FIRESTON FT140	134.00	2	\$267.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.51	2	\$1.02

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
					PARTS	292.89

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 40618

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(EHOWELL) Check front end. No issues found. AMG

09-15 - ALIGN STEERING

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires put new tires on the front. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotation not needed, front tires were replaced due to excessive wear on the shoulders. AMG SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 64002. Vehicle has been driven 385 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

(SHARBIN) Needs 2 front tires they are dry rotted and go out of date in 5 months. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 42213

USING DEPT NO: 510101	OPENED DATE: 01/28/2022 08:46:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/31/2022 11:08:53	METER 1 - M: 64067 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/31/2022 12:57:23	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.69	\$17.90	\$0.00	\$22.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.75	\$89.02	\$28.48	\$0.00	\$117.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.79	93.71	46.38	2.00	142.09
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/28/2022 11:11:03	01/28/2022 11:13:26	0.04	\$4.69
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/28/2022 10:25:37	01/28/2022 11:10:53	0.75	\$89.02
LABOR					93.71	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
PARTS					46.38	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 42213

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 43300

USING DEPT NO: 510101	OPENED DATE: 05/18/2022 13:12:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2022 14:59:35	METER 1 - M: 64446 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2022 08:06:35	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.23	\$17.90	\$0.00	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.01	\$0.00	\$0.00	\$23.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.23	27.24	17.90	2.00	47.14
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/18/2022 14:49:43	05/18/2022 14:51:52	0.04	\$4.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2022 14:37:50	05/18/2022 14:49:32	0.20	\$23.01
LABOR					27.24	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
PARTS					17.90	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 43300

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 379 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 45339

USING DEPT NO: 510101	OPENED DATE: 11/21/2022 12:56:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/23/2022 13:35:18	METER 1 - M: 64520 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/28/2022 10:58:15	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.79	\$92.89	\$0.00	\$0.00	\$92.89
06-17-013	INSPECT ALIGNMENT	DON	O	N	GARAGE	1.19	\$140.22	\$0.00	\$0.00	\$140.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$45.20	\$49.89	\$0.00	\$95.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **2.36** **278.31** **49.89** **5.00** **333.20**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11310047	11/22/2022 13:39:03	11/22/2022 14:26:17	0.79	\$92.89
06-17-013	INSPECT ALIGNMENT	11310047	11/22/2022 09:42:10	11/22/2022 10:53:28	1.19	\$140.22
66-PM-PMA	PERFORM OIL CHANGE	12201267	11/21/2022 13:37:25	11/21/2022 14:00:24	0.38	\$45.20
					LABOR	278.31

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
					PARTS	49.89

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 45339

Work Order Notes

(CWIGLEY) PM. Driver says its pulling to the left.

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

06-17-013 - INSPECT ALIGNMENT

(IFALLS) Checked alignment. The front toe was out of specification. Adjusted front toe. Performed road test after repair and verified that the steering wheel is straight while driving. EH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm- changed oil and oil filter, checked fluids, battery and tire pressure= GRC
Miles 64,520

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 46755

USING DEPT NO: 510101	OPENED DATE: 04/18/2023 11:51:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/19/2023 15:20:18	METER 1 - M: 64595 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/20/2023 07:50:44	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.22	\$25.89	\$0.00	\$0.00	\$25.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$25.08	\$0.00	\$0.00	\$25.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.61	\$0.00	\$0.00	\$44.61

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.81** **95.58** **0.00** **5.00** **100.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	04/18/2023 14:55:04	04/18/2023 15:17:45	0.38	\$44.61
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/18/2023 14:51:16	04/18/2023 14:54:42	0.06	\$6.75
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/18/2023 14:05:16	04/18/2023 14:15:00	0.16	\$19.14
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/18/2023 13:52:12	04/18/2023 14:04:57	0.21	\$25.08
					LABOR 95.58	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 46755

Work Order Notes

(LISAPATE) PM-DO SI-replace wipers-Wash-Going out of town

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front and rear pads measure 7MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 75 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 48363

USING DEPT NO: 510101	OPENED DATE: 10/02/2023 07:21:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/02/2023 14:52:00	METER 1 - M: 65897 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/02/2023 15:46:08	IN-SERVICE DATE: 01/20/2015
TECH SPEC NO: 15TOYOTACAMRY 2015 TOYOTA CAMRY	UNIT SERIAL NO: 4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.59	\$19.54	\$0.00	\$30.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.10	\$49.60	\$0.00	\$98.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$45.63	\$0.00	\$0.00	\$45.63

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.89** **105.32** **69.14** **5.00** **179.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12395904	10/02/2023 08:00:07	10/02/2023 08:23:19	0.39	\$45.63
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/02/2023 07:48:01	10/02/2023 08:12:59	0.42	\$49.10
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/02/2023 07:54:44	10/02/2023 08:00:07	0.09	\$10.59
					LABOR 105.32	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.24	1	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	12.35	1	\$12.35
03-51-038	REPLACE NEW WIPER BLADES	181	WIPER BLADE 18"	8.30	1	\$8.30
					PARTS 69.14	

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 48363

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 65,897

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) WASHED BAY CLOSED- FC

Work Order Charge Detail

UNIT NO: 241048 **2015 TOYOTA CAMRY** **WORK ORDER NO:** 50538

USING DEPT NO:	510101	OPENED DATE:	04/11/2024 09:17:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/17/2024 14:48:36	METER 1 - M:	66352	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2024 07:09:35	IN-SERVICE DATE:	01/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK1FU488734	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 241048 2015 TOYOTA CAMRY

WORK ORDER NO: 50538

Work Order Notes

(LISAPATE) Prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(LISAPATE) Prep for sale completed by FC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Apr 19 2024 13:48:15 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '4T1BF1FK1FU488734')//Q=