The University of Alabama

UNIT NO:	241363 2	2015 TOYOTA (	CAMRY				0:	20455	
USING DEPT NO:	218142	OPEN	IED DATE:	06/03/201	5 08:15:27	LOCATION: GARAC	GE - Univers	sity Automotive S	Services
WO STATUS:	CLOSED	COMF	PLETED DATE	E: 06/04/201	5 07:08:24	METER 1 - M: 60	I	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOS	ED DATE:	06/04/201	5 07:08:25	IN-SERVICE DATE:	06/02/2	2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOT	A CAMRY			UNIT SERIAL NO:	4T4BF	1FK1FR497262	
JOB CODE	JOB DESCRIPTIO	<u>N STAT</u>	RSN WR	TY JOB LOC	LABOR HRS	LABOR MA	<u> TERIAL</u>	COMMERCIAL	TOTAL COST
PS-00-001 PREP	SERVICE NEW UNIT I	N-SERVICE DON	C N	GARAGE	0.50	\$28.75 \$0.00	:	\$0.00	\$28.75
JOB COUNT: 1			WORK C	ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
Job Code	Job Descriptio	on	Employ	vee No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost
PS-00-001 PREP SE	RVICE NEW UNIT IN-SER	RVICE INSPECTION	11338644	06/	03/2015 08:16:55	06/03/2015 08:46:55	j	0.50	\$28.75
								LABOR	28.75

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	20455
Work Order Notes	<u>s</u>			
(LPATE) DO PDI				
Job Notes				
PS-00-001 - PREP SE		IN-SERVICE INSPECTION		
(LPATE) PDI COMPLI	ETED			

The University of Alabama

UNIT NO:		241363 2	015 TOYOTA C	AMRY			WORK ORD	ER NO:	21601	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	COMPI	ED DATE: LETED DAT ED DATE: A CAMRY	<b>E:</b> 10/05/2	015 13:10:39 015 07:31:30 015 07:31:32	LOCATION: 0 METER 1 - M: IN-SERVICE DA UNIT SERIAL M	5251 ATE: 06/02	ersity Automotive S METER 2 - N: 2/2015 3F1FK1FR497262	Services O
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION	<u>I</u> <u>STAT</u> DON	<u>RSN</u> <u>WR</u> P N			<b>LABOR</b> \$3.64	<b>MATERIAL</b> \$34.91	COMMERCIAL \$0.00	<u>TOTAL COST</u> \$38.55
JOB COUN	IT: 1			WORK	ORDER TOTA	L: 0.06	3.64	34.91	0.00	38.55
Job Code 66-PM-PMA	PERFORM	Job Description	-	<u>Employ</u> 1074414		<u>Start</u> 10/01/2015 13:53:46	Fini 3 10/01/2015 1		Quantity 0.06 LABOR	<u>Total Cost</u> \$3.64 <b>3.64</b>
Job Code		Job Description	<u>1</u>	Part	No.	Des	scription	<u>Unit Pr</u>		Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	0	W20NP	(	DIL 0W-20 SYN NAI	PA		5.69 5	\$28.43
66-PM-PMA	PERFORM	OIL CHANGE	0	4152-YZZA1	ł	FILTER-OIL		1	6.48 1 PARTS	\$6.48 <b>34.91</b>

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER	NO:	21601
Work Order Notes					
(LISAPATE) PM					
Job Notes					
66-PM-PMA - PERFOR	M OIL CHANGE				
(LISAPATE) PM BY SH					

The University of Alabama

UNIT NO:		241363 20	15 TOYO	DTA C	AMRY	,			WORK OI	RDER NO	D: 2	22510	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED	DATE: E:	02/12/20	16 09:29:48 16 06:26:05 16 06:26:07	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 11255 E DATE:	<b>N</b> 06/02/2	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	0
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL (	COMMERCIAL	TOTAL COST
31-17	ROTATE	TIRES, TUBES, LINER	RS & VALV	DON	Ρ	Ν	GARAGE	0.51	\$29.42	\$0.00	\$	50.00	\$29.42
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.37	\$21.31	\$29.37	\$	50.00	\$50.68
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL	.: 0.88	3 50	.73	29.37	0.00	80.10
Job Code		Job Description			<u>En</u>	nployee	<u>No.</u>	<u>Start</u>	ļ	- inish		Quantity	Total Cost
31-17	ROTATE TIR	RES, TUBES, LINERS & VA	ALVES	1	1074414		02	2/11/2016 13:13:18	02/11/201	6 13:44:00		0.51	\$29.42
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		02	2/11/2016 09:20:33	02/11/201	6 09:42:47		0.37	\$21.31
												LABOR	50.73
Job Code		Job Description				Part No	<u>.</u>	Des	scription		Unit Price	<u>e</u> <u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		0'	W20S		Н	AVOLINE OW20 S	YNTHETIC OIL	QT	5.6	64 4	\$22.56
66-PM-PMA	PERFORM	DIL CHANGE		04	4152-YZ	ZA1	F	LTER-OIL			6.8	311	\$6.81
												PARTS	29.37

*The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI* 

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	22510
Work Order Notes				

(LISAPATE) PM-ROTATE TIRES

#### Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

#### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH-USED 1/2QT OF OIL ALREADY CHARGED OUT

The University of Alabama

UNIT NO:		241363	2015 TOYOTA	CAMF	RY			WORK ORDER	NO:	24654	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	CON	SED DA	D DATE:	10/21/20	16 13:30:04 16 07:44:29 16 07:44:31	LOCATION: GAR, METER 1 - M: 165 IN-SERVICE DATE UNIT SERIAL NO:	502 : 06/02/2	METER 2 - N:	0
JOB CODE 66-PM-PMA		JOB DESCRIPTIO	<u>n st</u> do		N WRTY	<b>JOB LOC</b> GARAGE	LABOR HRS 0.88			COMMERCIAL \$0.00	<b>TOTAL COST</b> \$97.53
JOB COUN	IT: 1			v	VORK OR		0.88	50.52	47.01	0.00	97.53
<u>Job Code</u> 66-PM-PMA	PERFORM	Job Description DIL CHANGE	<u>on</u>	<u> </u> 111705	<b>Employee</b> 80		<u>Start</u> /18/2016 10:53:57	<u>Finish</u> 7 10/18/2016 11:46:	40	Quantity 0.88 LABOR	Total Cost \$50.52 50.52
Job Code		Job Description	on		Part No	<u>).</u>	Des	scription	Unit Pric	<u>e Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		49223		AI	R FILTER REPL 9	223	11.	88 1	\$11.88
66-PM-PMA	PERFORM	DIL CHANGE		0W20S	5	HA	VOLINE OW20 S	YNTHETIC OIL QT	5.	64 1	\$5.64
66-PM-PMA	PERFORM	DIL CHANGE		0W20S	;	HA	VOLINE OW20 S	YNTHETIC OIL QT	5.	64 4	\$22.56
66-PM-PMA	PERFORM	DIL CHANGE		04152-	YZZA1	FI	TER-OIL		6.	93 1	\$6.93
										PARTS	47.01

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO	): 24654
Work Order Notes				
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFORM	I OIL CHANGE			
(LISAPATE) PM BY AB				

The University of Alabama

UNIT NO:		241363 20	015 TOYOTA CA	MRY				WORK ORD	ER NO	: 2	6140	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED PREVENTIVE MAIN <sup>®</sup> 15TOYOTACAMRY	OPENE COMPL T CLOSE 2015 TOYOTA	ETED I D DATE	DATE: E:	04/18/201	7 15:05:41 7 11:47:27 7 11:47:29	LOCATION: ( METER 1 - M: IN-SERVICE D UNIT SERIAL I	21402 <b>ATE:</b>	<b>M</b> 06/02/20	IETER 2 - N:	
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION M OIL CHANGE	<u>STAT</u> DON	<u>RSN</u> P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.31		<u>MATE</u> \$46.98		COMMERCIAL 0.00	<b>TOTAL COST</b> \$64.81
JOB COUN	IT: 1			wo	rk ori	DER TOTAL:	0.31	l 17.83		46.98	0.00	64.81
Job Code		Job Description	<u>l</u>	Em	ployee	<u>No.</u>	<u>Start</u>	<u>Fin</u>	<u>ish</u>		<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE	11	758845		04/	17/2017 06:59:37	7 04/17/2017 1	1:28:44		(4.49)	(\$257.90)
66-PM-PMA	PERFORM	DIL CHANGE	11	758845		04/	17/2017 06:59:37	7 04/17/2017 1	1:28:44		4.49	\$257.90
66-PM-PMA	PERFORM	DIL CHANGE	11	758845		04/	17/2017 06:59:37	7 04/17/2017 0	7:18:13		0.31	\$17.83
											LABOR	17.83
Job Code		Job Description	<u>l</u>		Part No	<u>.</u>	Des	scription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE	0\	V20T		0W	20 SYN OIL THO	OMAS CAM2 QT		4.1	7 5	\$20.85
66-PM-PMA	PERFORM	DIL CHANGE	49	223		AIF	R FILTER REPL 9	223		11.88	8 1	\$11.88
66-PM-PMA	PERFORM	DIL CHANGE	80	0012C		CA	BIN AIR FILTER	REPL 4483		7.33	3 1	\$7.33
66-PM-PMA	PERFORM	DIL CHANGE	04	152-YZ	ZA1	FIL	TER-OIL			6.92	2 1	\$6.92
											PARTS	46.98

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	26140
Work Order Note	<u>s</u>			
(IFALLS) PM				
Job Notes				
66-PM-PMA - PERFC	ORM OIL CHANGE			
(IFALLS) CS PERFO	RMED PM COOLA	NT CHECKED GOOD TO -45		

The University of Alabama

UNIT NO:		241363	2015 TOY	OTA C	AMRY				WORK ORD	ER NO	):	26861	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	2015	OPENE COMPL CLOSE TOYOTA	ETED I D DATE	DATE: E:	07/21/201	17 15:39:20 17 11:24:13 17 11:24:15	LOCATION: ( METER 1 - M: IN-SERVICE D UNIT SERIAL I	27546 <b>ATE:</b>	06/02/	rsity Automotive \$ <b>METER 2 - N:</b> /2015 F1FK1FR497262	0
JOB CODE 66-PM-PMA		JOB DESCRIPTION M OIL CHANGE	<u>N</u>	<u>STAT</u> DON	<u>RSN</u> P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.31	<b>LABOR</b> \$17.83	<u>MATE</u> \$35.49		COMMERCIAL \$0.00	<b>TOTAL COST</b> \$53.32
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.31	17.83		35.49	0.00	53.32
Job Code		Job Descriptio	<u>on</u>		Em	ployee	<u>No.</u>	<u>Start</u>	<u>Fin</u>	<u>ish</u>		<u>Quantity</u>	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		11	1758845		07	/19/2017 07:18:36	6 07/19/2017 0	7:33:36		(0.25)	(\$14.38)
66-PM-PMA	PERFORM	DIL CHANGE		11	1758845		07	/19/2017 07:00:00	07/19/2017 0	7:18:36		0.31	\$17.83
03-51-038	REPLACE N	EW WIPER BLADES		11	1758845		07	/19/2017 07:18:36	6 07/19/2017 0	7:33:36		0.25	\$14.38
												LABOR	17.83
Job Code		Job Descriptio	<u>n</u>			Part No	<u>-</u>	Des	scription		Unit Pric	<u>ce</u> <u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		49	9223		All	R FILTER REPL 9	223		11.	.88 1	\$11.88
66-PM-PMA	PERFORM (	DIL CHANGE		0\	W20T		0V	/20 SYN OIL THO	MAS CAM2 QT		4.	.17 4	\$16.68
66-PM-PMA	PERFORM (	DIL CHANGE		04	4152-YZ	ZA1	FIL	TER-OIL			6.	.931	\$6.93
												PARTS	35.49

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	26861
Work Order Notes				
(LISAPATE) PM				
Job Notes				
03-51-038 - REPLACE	NEW WIPER BLAD	ES		
66-PM-PMA - PERFOR	M OIL CHANGE			

(LISAPATE) PM BY CS-REPLACED AIR FILTER

The University of Alabama

UNIT NO:		241363 20	15 TOYOTA CAMRY		WORK ORDER NO:	27763	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2015 TOYOTA CAMRY	10/11/2017 08:25:01 10/17/2017 15:59:20 10/17/2017 15:59:22		niversity Automotive S METER 2 - N: 6/02/2015 T4BF1FK1FR497262	Services 0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION RM OIL CHANGE	<u>STAT RSN WRTY</u> DON P N		LABOR MATERIA   \$10.70 \$23.43	L <u>COMMERCIAL</u> \$0.00	<b>TOTAL COST</b> \$34.13
JOB COUN	IT: 1		WORK OR	DER TOTAL: 0.19	10.70 23	3.43 0.00	34.13
Job Code 66-PM-PMA	PERFORM	Job Description OIL CHANGE	<u>Employee</u> 11074414	No. <u>Start</u> 10/11/2017 09:16:55	<b>Finish</b> 10/11/2017 09:28:05	Quantity 0.19 LABOR	Total Cost \$10.70
Job Code		Job Description	Part No	<u>.</u> <u>Des</u>	cription Unit	t Price Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	0W20T	0W20 SYN OIL THO	MAS CAM2 QT	4.17 4	\$16.68
66-PM-PMA	PERFORM	OIL CHANGE	04152-YZZA1	FILTER-OIL		6.75 1 PARTS	\$6.75 <b>23.43</b>

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	27763
Work Order Notes	<u>5</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	RM OIL CHANGE			
(LISAPATE) USED 1/2 (LISAPATE) PM BY SI		ADY CHARGED OUT		

The University of Alabama

UNIT NO:		241363	2015 TOYOTA CAMRY		WORK ORDER N	O: 28	3770	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	OPENED DATE: COMPLETED DATE CLOSED DATE: 2015 TOYOTA CAMRY	02/01/2018 14:05:46 02/07/2018 08:20:45 02/07/2018 08:20:47	LOCATION: GARAG METER 1 - M: 3707 IN-SERVICE DATE: UNIT SERIAL NO:	5 <b>ME</b> 06/02/20 <sup>-</sup>	ETER 2 - N:	ervices 0
JOB CODE 66-PM-PMA		JOB DESCRIPTION	<u>n stat rsn wrt</u> Don p n		S LABOR MA   '2 \$41.45 \$27.78		OMMERCIAL .00	<b>TOTAL COST</b> \$69.23
JOB COUN	IT: 1		WORK O	RDER TOTAL: 0.	72 41.45	27.78	0.00	69.23
Job Code 66-PM-PMA	PERFORM	Job Descriptio OIL CHANGE	on <u>Employe</u> 11901357	ee No. <u>Start</u> 02/02/2018 14:40	<u>Finish</u> 23 02/02/2018 15:23:38		Quantity 0.72 LABOR	Total Cost \$41.45 41.45
Job Code		Job Descriptio	on Part I	<u>No.</u>	escription	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	04152-YZZA1	FILTER-OIL		6.93	1	\$6.93
66-PM-PMA	PERFORM	OIL CHANGE	0W20T	0W20 SYN OIL T	HOMAS CAM2 QT	4.17	5 PARTS	\$20.85 <b>27.78</b>

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	28770
Work Order Notes	<u>s</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFO	ORM OIL CHANGE			
(LISAPATE) PM BY A COOLANT -45'	G/SH			

The University of Alabama

UNIT NO:		241363 20	15 TOYOTA C	AMRY				WORK OR		<b>):</b> 2	28897	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	COMPL	ED DATE ETED D D DATE CAMRY	DATE:	02/21/201	8 13:45:34 8 11:09:25 8 11:09:26	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	I: 38116 DATE:	<b>I</b> 06/02/2	sity Automotive S <b>METER 2 - N:</b> 2015 1FK1FR497262	ervices 0
JOB CODE	Ē	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	ERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFOR	M TIRE PATCH	DON	0	Ν	GARAGE	0.40	\$23.00	\$7.22	9	\$0.00	\$30.22
JOB COUN	IT: 1			WOF	rk ori	DER TOTAL:	0.40	23.	00	7.22	0.00	30.2
Job Code		Job Description		<u>Em</u> j	ployee	<u>No.</u>	<u>Start</u>	<u></u>	<u>inish</u>		<u>Quantity</u>	Total Cost
66-17-030	PERFORM T	IRE PATCH	1	1074414		02/	19/2018 06:00:00	02/19/2018	3 06:24:00		0.40	\$23.0
											LABOR	23.0
Job Code		Job Description		<u> </u>	Part No	<u>.</u>	Des	cription		Unit Pric	<u>e Quantity</u>	Total Cost
66-17-030	PERFORM T	IRE PATCH	1	4041		PAT	TCH 1/4 PILOT W	IRE		3.4	19 1	\$3.4
66-17-030	PERFORM T	IRE PATCH	V	VHEEL W	EIGHT	WH	IEEL WEIGHT KN	IOCK ON		0.3	36 2	\$0.7
66-17-030	PERFORM T	IRE PATCH	6	-111		TPI	MS SERVICE KIT	6-111		3.0	01 1	\$3.0
											PARTS	7.2

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	28897
Work Order Not	tes			
(LISAPATE) NAIL IN	N LF TIRE			
Job Notes				
66-17-030 - PERFC	ORM TIRE PATCH			
(LISAPATE) PATCH	IED LF TIRE FRONT	THE INSIDE . REBALANCED RECHECKED OK		
66-PM-PMA - PERF	FORM OIL CHANGE			
(LISAPATE) Visit Re	eason Changed On 2	/16/2018 1:47 PM By LISAPATE		

The University of Alabama

UNIT NO:		241363 2	015 TOYO	DTA CA	AMRY				WORK OR	DER NO	: 2	29483		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED I D DATE	DATE: E:	05/07/201	8 15:35:30 8 09:38:44 8 09:38:47	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 41069 <b>DATE</b> :	<b>1</b> 06/02/2	sity Automotive S <b>METER 2 - N:</b> 2015 1FK1FR497262	ervices 0	
JOB CODE	_	JOB DESCRIPTION	<u> </u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>		LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	TOTAL CO	) <u>ST</u>
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.31	\$17.83	\$41.68	9	\$0.00	\$59.51	
JOB COUN	IT: 1				wo	RK ORI	DER TOTAL:	0.31	17.8	3	41.68	0.00	5	59.51
Job Code		Job Description	<u>1</u>		<u>Em</u>	ployee	<u>No.</u>	<u>Start</u>	<u>Fi</u>	<u>nish</u>		<u>Quantity</u>	Total Cos	<u>st</u>
66-PM-PMA	PERFORM	DIL CHANGE		11	1074414		05/	03/2018 06:00:00	05/03/2018	06:18:36		0.31	\$	517.83
												LABOR	1	17.83
Job Code		Job Description	<u>1</u>			Part No	<u>.</u>	Des	cription	ļ	Unit Pric	<u>e Quantity</u>	Total Cos	st
66-PM-PMA	PERFORM (	DIL CHANGE		04	4152-YZ	ZA1	FIL	TER-OIL			6.5	52 1		\$6.52
66-PM-PMA	PERFORM	DIL CHANGE		49	9223		AIF	R FILTER REPL 92	223		11.8	38 1	\$	\$11.88
66-PM-PMA	PERFORM	DIL CHANGE		0\	W20T		0W	20 SYN OIL THO	MAS CAM2 QT		5.8	82 4	\$	\$23.28
												PARTS	4	41.68

The University of Alabama

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	29483
Work Order Note	<u>s</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFC	ORM OIL CHANGE			
(LISAPATE) PM BY S COOLANT -10' USED 1/2 QT OF OIL CLEANED BATTERY	ALREADY CAHRO	GED OUT		

The University of Alabama

UNIT NO:		241363 20	15 TOYOTA CAMRY		WORK ORDER NO:	30131	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	OPENED DATE: COMPLETED DATE: CLOSED DATE: 2015 TOYOTA CAMRY	06/28/2018 10:07:32 06/29/2018 09:59:53 06/29/2018 09:59:55	METER 1 - M: 44917   IN-SERVICE DATE: 0	Iniversity Automotive S METER 2 - N: 6/02/2015 T4BF1FK1FR497262	0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION MOIL CHANGE	<u>STAT</u> <u>RSN</u> <u>WRTY</u> DON P N	JOB LOCLABOR HRSGARAGE0.31	LABOR MATERIA   \$17.83 \$28.72	AL COMMERCIAL \$0.00	<u>TOTAL COST</u> \$46.55
JOB COUN	IT: 1		WORK ORE	DER TOTAL: 0.31	17.83 23	8.72 0.00	46.55
Job Code 66-PM-PMA	PERFORM	Job Description DIL CHANGE	<u>Employee</u> 11901357	No. <u>Start</u> 06/28/2018 14:58:14	<u>Finish</u> 06/28/2018 15:16:50	Quantity 0.31 LABOR	<u>Total Cost</u> \$17.83 <b>17.83</b>
Job Code		Job Description	<u>Part No.</u> 0W20T	. Des 0W20 SYN OIL THO		t Price Quantity 5.55 4	<u>Total Cost</u> \$22.20
66-PM-PMA		OIL CHANGE	04152-YZZA1	FILTER-OIL		6.52 1 PARTS	\$6.52 28.72

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	30131
Work Order Note	<u>s</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFC	ORM OIL CHANGE			
(LISAPATE) Visit Rea (LISAPATE) PM BY E COOLANT -35'	-	/28/2018 10:08 AM By LISAPATE		

The University of Alabama

UNIT NO:		241363	2015 TOYO	OTA C	AMRY					WORK ORD	ER NO	: 3	80722		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMR		OPENE COMPL CLOSE	ETED D DATI	DATE: E:	09/05/20	18 13:45:04 18 08:31:23 18 08:31:25		LOCATION: G METER 1 - M: IN-SERVICE D/ UNIT SERIAL N	48769 <b>ATE:</b>	N 06/02/2	NETER 2 - N:	0	
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR H	IRS	LABOR	MATE	<u>RIAL</u>	COMMERCIAL	TOTAL C	:OST
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	(	0.42	\$24.39	\$48.85	\$	60.00	\$73.24	
66-PM-PMC	PERFOR	M CABIN FILTER F	REPLACEMEI	DON	0	Ν	GARAGE	(	0.30	\$17.25	\$7.33	\$	60.00	\$24.58	
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	:	0.72	41.64		56.18	0.00		97.82
Job Code		Job Descript	ion		En	nployee	<u>No.</u>	<u>Start</u>	<u>.</u>	<u>Fini</u>	sh		<u>Quantity</u>	Total C	ost
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414		30	8/31/2018 06:0	03:53	08/31/2018 0	6:20:01		0.27		\$15.46
66-PM-PMC	PERFORM	CABIN FILTER REPL	ACEMENT	1	1074414		30	8/31/2018 06:0	00:00	08/31/2018 0	6:18:00		0.30		\$17.25
66-PM-PMA	PERFORM (	DIL CHANGE		1	1901357		30	8/30/2018 14:4	40:42	08/30/2018 1	4:50:01		0.16		\$8.93
													LABOR		41.64
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>		Des	<u>cription</u>	<u> </u>	Unit Price	<u>Quantity</u>	<u>Total C</u>	;ost
66-PM-PMA	PERFORM	DIL CHANGE		0	W20T		0\	V20 SYN OIL	THO	MAS CAM2 QT		5.7	4 5		\$28.72
66-PM-PMA	PERFORM	DIL CHANGE		04	4152-YZ	ZA1	FI	LTER-OIL				6.5	2 1		\$6.52
66-PM-PMA	PERFORM	DIL CHANGE		4	9223		AI	R FILTER RE	EPL 92	223		13.6	1 1		\$13.61
66-PM-PMC	PERFORM (	CABIN FILTER REPLA	ACEMENT	8	00012C		C	ABIN AIR FILT	TER F	REPL 4483		7.3			\$7.33
													PARTS		56.18

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	30722
Work Order Note	es			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) Visit Re (LISAPATE) PM BY I COOLANT -25' REPLACED AIR FIL	BY SH,EK/SH	/30/2018 1:45 PM By LISAPATE		
66-PM-PMC - PERF	ORM CABIN FILTE	R REPLACEMENT		
(LISAPATE) REPLAC	CED CABIN FILTER			

The University of Alabama

UNIT NO:	241363	2015 TO	ΥΟΤΑ Ο	AMRY				WORK OF	RDER NO:	: :	30785		
USING DEPT	<b>NO:</b> 218142		OPENE		E:	09/07/201	8 11:04:49	LOCATION:	GARAGE	- Univers	sity Automotive	Services	
WO STATUS:	CLOSED		COMPL	ETED I	DATE:	09/11/201	8 10:16:10	METER 1 - N	<b>1:</b> 49351	I	METER 2 - N:	0	
WO VISIT REA	SCHEDU	ILED	CLOSE	D DATE	Ξ:	09/11/201	8 10:16:12	IN-SERVICE	DATE:	06/02/2	2015		
TECH SPEC N	<b>O:</b> 15TOYO	TACAMRY 201	5 ΤΟΥΟΤΑ		Y			UNIT SERIA	L NO:	4T4BF	1FK1FR497262	2	
JOB CODE	JOB DE	SCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL	COMMERCIAL	TOTAL C	COST
35-52-003	DIAGNOSE RADIC		DON	0	Ν	GARAGE	0.50	\$28.75	\$0.00	:	\$0.00	\$28.75	
JOB COUNT:	1			wo	RK OR	DER TOTAL:	0.50	28.	75	0.00	0.00	)	28.75
Job Code	Job	<b>Description</b>		<u>Em</u>	ployee	No.	<u>Start</u>	E	<u>inish</u>		Quantity	<u>Total C</u>	Cost
35-52-003 D	IAGNOSE RADIO		11	1170580		09/	10/2018 07:00:00	09/10/201	8 07:30:00		0.50		\$28.75
											LABOR	-	28.75

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

#### UNIT NO: 241363 2015 TOYOTA CAMRY

WORK ORDER NO: 30785

Work Order Notes

(LISAPATE) Per Fleet touch screen is not working, customer complaint

#### Job Notes

35-52-003 - DIAGNOSE RADIO

(LISAPATE) The touch screen works fine. Tested out different parts of the screen and all working ok.

The University of Alabama

UNIT NO:		241363 20	015 TOYOTA CAMR	ſ			WORK OR	DER NO:	31	357	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	OPENED DA COMPLETED CLOSED DA 2015 TOYOTA CAMI	DATE: E:	11/02/201	8 10:30:37 8 11:59:25 8 11:59:26	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 52529 <b>DATE</b> :	ME 06/02/201	/ Automotive S E <b>TER 2 - N:</b> I5 K1FR497262	ervices 0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION	<u>STAT</u> <u>RSN</u> DON P	<u>WRTY</u> N	JOB LOC GARAGE	LABOR HRS 0.31	<b>LABOR</b> \$22.48	<u>MATERI</u> \$35.66	AL <u>CC</u> \$0.0	DMMERCIAL 00	<b>TOTAL COST</b> \$58.14
JOB COUN	IT: 1		W		DER TOTAL:	0.31	22.4	18 3	35.66	0.00	58.14
Job Code 66-PM-PMA	PERFORM	Job Descriptior OIL CHANGE	<u>E</u> 1190135	<b>nployee</b> 7		<u>Start</u> 01/2018 07:00:00		i <b>nish</b> 07:18:36		Quantity 0.31 LABOR	<u>Total Cost</u> \$22.48 <b>22.48</b>
Job Code		Job Descriptior	1	Part No	) <u>.</u>	Des	cription	<u>Un</u>	<u>it Price</u>	Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	0W20T		0W	20 SYN OIL THO	MAS CAM2 QT		5.83	5	\$29.17
66-PM-PMA	PERFORM	OIL CHANGE	04152-Y	ZZA1	FIL	TER-OIL			6.49	1 PARTS	\$6.49 <b>35.66</b>

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	31357
Work Order Note	<u>es</u>			
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) Visit Re (LISAPATE) PM by ( Coolant -33'		0/31/2018 10:31 AM By LISAPATE		

The University of Alabama

UNIT NO:		241363	2015 TOYO	DTA C	AMRY				WORK OR	DER NO	): 3	32129		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMF		OPENE COMPL CLOSE	ETED I D DATE	DATE: E:	02/13/20	019 08:49:20 019 08:15:03 019 08:15:05	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 55958 <b>DATE</b> :	N 06/02/2	ity Automotive <b>/ETER 2 - N:</b> 015 IFK1FR497262	0	
JOB CODE	L	JOB DESCRIPTI	ON	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MAT	ERIAL (		<u>TOTAL CO</u>	)ST
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	1.00	\$72.50	\$0.00	\$	60.00	\$72.50	
66-17-028	PERFOR	M MOUNT AND B	ALANCE TIRE	DON	0	Ν	GARAGE	1.39	\$100.69	\$291.79	\$	60.00	\$392.48	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.11	\$8.12	\$41.97	\$	60.00	\$50.09	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL	.: 2.50	181.3	31	333.76	0.00	51	15.07
Job Code		Job Descrip	tion		Em	ployee	<u>No.</u>	<u>Start</u>	Fi	nish		Quantity	Total Cos	<u>st</u>
09-15	ALIGN STEE	ERING		1	1170580		0	2/11/2019 07:00:00	02/11/2019	08:00:00		1.00	\$	72.50
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	1	1901357		0	2/07/2019 06:08:46	02/07/2019	07:32:06		1.39	\$10	00.69
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		0	2/06/2019 11:44:01	02/06/2019	11:50:44		0.11	:	\$8.12
												LABOR	18	81.31
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	Des	scription		Unit Price	e Quantity	Total Cos	<u>st</u>
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	4	2830		т	IRE P205/65R16 M	IICH ENERGY S		141.9	9 2	\$2	283.98
66-PM-PMA	PERFORM	DIL CHANGE		0	W20T		0	W20 SYN OIL THO	MAS CAM2 QT		5.8	3 5	\$	629.17
66-PM-PMA	PERFORM	DIL CHANGE		0	4152-YZ	ZA1	F	ILTER-OIL			6.4	9 1		\$6.49
66-PM-PMA	PERFORM	DIL CHANGE		0	5089		В	RAKE CLEAN NOM	N-FLAMMABLE 1	4OZ	6.3	1 1	:	\$6.31
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	2	1030		Т	PMS SERVICE KIT	6-116		3.3	0 2		\$6.60
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	V	/HEEL W	/EIGHT	V	HEEL WEIGHT KN	NOCK ON		0.4	0 3	:	\$1.21
66-17-028	PERFORM	MOUNT AND BALAN	CE TIRES	2	1030		Т	PMS SERVICE KIT	6-116		3.3	0 2	:	\$6.60
66-17-028	PERFORM	MOUNT AND BALAN	CE TIRES	2	1030		Т	PMS SERVICE KIT	6-116		3.3	0 (2	)(\$	\$6.60)
												PARTS	33	33.76

Coolant -35

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	32129
Work Order Not	es			
(LISAPATE) PM				
Job Notes				
09-15 - ALIGN STE	ERING			
(LISAPATE) AB perf	ormed alignment			
66-17-028 - PERFO	RM MOUNT AND BA	ALANCE TIRES		
(LISAPATE) Mount a	and balanced 2 new f	ront tires		
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) Visit Re (LISAPATE) PM by I	•	/6/2019 8:49 AM By LISAPATE		

The University of Alabama

UNIT NO:		241363	2015 TOYOTA C	AMRY				DER NO:	33505	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMR`	COMPL	ED DATE: LETED DATE: ED DATE: A CAMRY	07/25/201	9 10:37:19 9 06:42:25 9 06:42:31	LOCATION: 0 METER 1 - M: IN-SERVICE D UNIT SERIAL	68723 ATE: 06/02	ersity Automotive S METER 2 - N: 2/2015 3F1FK1FR497262	Services 0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTIC	DN STAT DON	<u>RSN</u> <u>WRTY</u> P N	<u>JOB LOC</u> GARAGE	LABOR HRS 0.31	<b>LABOR</b> \$22.48	<u>MATERIAL</u> \$35.60	COMMERCIAL \$0.00	<u>TOTAL COST</u> \$58.08
JOB COUN	IT: 1			WORK ORI	DER TOTAL:	0.31	22.48	35.60	0.00	58.08
Job Code 66-PM-PMA	PERFORM	<u>Job Descripti</u> DIL CHANGE		<u>Employee</u> 1901357		<u>Start</u> 23/2019 11:46:21	<u>Fin</u> 07/23/2019 <sup>-</sup>	<u>ish</u> 12:04:57	Quantity 0.31 LABOR	<u>Total Cost</u> \$22.48 <b>22.48</b>
Job Code		Job Descripti	on	Part No	<u>.</u>	Des	cription	<u>Unit Pr</u>	rice Quantity	Total Cost
66-PM-PMA	PERFORM	OIL CHANGE	0	4152-YZZA1	FIL	TER-OIL			6.50 1	\$6.50
66-PM-PMA	PERFORM	OIL CHANGE	0	W20T	0W	20 SYN OIL THO	MAS CAM2 QT		5.82 5 PARTS	\$29.10 <b>35.60</b>

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	33505
Work Order Notes				
(LISAPATE) PM				
Job Notes				
66-PM-PMA - PERFOR	M OIL CHANGE			
(LISAPATE) PM by JW// Coolant -34'	AG			

The University of Alabama

UNIT NO:		241363	2015 TOYO	DTA C	AMRY				WORK OR	DER NO	: 34	4395		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMR		OPENE COMPL CLOSE	ETED I	DATE: E:	10/11/20	19 11:15:27 19 07:59:40 19 07:59:42	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 72618 <b>DATE</b> :	<b>ME</b> 06/02/20	y Automotive S E <b>TER 2 - N:</b> 15 <sup>-</sup> K1FR497262	0	
JOB CODE	<u> </u>	JOB DESCRIPTIC	<u>DN</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL	COST
06-15	INSPECT	<b>STEERING</b>		DON	0	Ν	GARAGE	0.50	\$36.25	\$0.00	\$0	.00	\$36.25	
09-15	ALIGN S	TEERING		DON	0	Ν	GARAGE	0.18	\$12.87	\$0.00	\$0	.00	\$12.87	
66-17-028	PERFOR	M MOUNT AND BA	LANCE TIRE	DON	0	Ν	GARAGE	0.80	\$58.00	\$581.32	\$0	.00	\$639.32	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.45	\$32.67	\$41.87	\$0	.00	\$74.54	
JOB COUN	IT: 4				WO	rk ori	DER TOTAL	: 1.93	139.7	79	623.19	0.00		762.98
Job Code		Job Descripti	on		Em	ployee	No.	<u>Start</u>	F	<u>inish</u>		<u>Quantity</u>	Total	Cost
66-17-028	PERFORM I	MOUNT AND BALANC	E TIRES	1	2052187		10	/10/2019 07:00:00	10/10/2019	9 07:48:00		0.80		\$58.00
06-15	INSPECT ST	TEERING		1	1074414		10	/10/2019 06:00:00	10/10/2019	9 06:30:00		0.50		\$36.25
09-15	ALIGN STEE	ERING		1	1213180		10	/10/2019 07:17:57	10/10/2019	9 07:28:36		0.18		\$12.87
66-PM-PMA	PERFORM	OIL CHANGE		1	1074414		10	/09/2019 13:02:25	10/09/2019	9 13:29:27		0.45		\$32.67
												LABOR		139.79
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	Des	cription	ļ	<u>Unit Price</u>	<u>Quantity</u>	<u>Total</u>	Cost
66-PM-PMA	PERFORM	OIL CHANGE		0	W20T		01	V20 SYN OIL THO	MAS CAM2 QT		5.82	4		\$23.28
66-PM-PMA	PERFORM	OIL CHANGE		0	4152-YZ	ZA1	FI	LTER-OIL			6.26	1		\$6.26
66-PM-PMA	PERFORM	OIL CHANGE		4	9223		AI	R FILTER REPL 92	223		12.33	1		\$12.33
66-17-028	PERFORM	MOUNT AND BALANC	E TIRES	2	1030		TF	MS SERVICE KIT	6-116		3.32	4		\$13.26
66-17-028	PERFORM	MOUNT AND BALANC	E TIRES	4	2830		TI	RE P205/65R16 M	IICH ENERGY S		141.26	4		\$565.02
66-17-028	PERFORM I	MOUNT AND BALANC	ETIRES	V	HEEL W	/EIGHT	W	HEEL WEIGHT KN	NOCK ON		0.43	7		\$3.04
												PARTS		623.19

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	34395
Work Order Not	es			
(LISAPATE) PM				
Job Notes				
06-15 - INSPECT S	TEERING			
(LISAPATE) JW/SH	-Checked front end ne	o issues found at this time		
09-15 - ALIGN STE	ERING			
(LISAPATE) MS Per	formed alignment			
66-17-028 - PERFO	RM MOUNT AND BA	ALANCE TIRES		
(LISAPATE) Mounte	ed and balanced 4 nev	<i>w</i> tires		
66-PM-PMA - PERF	ORM OIL CHANGE			
(LISAPATE) PM by / Coolant -35' Replaced air filter	AG,EK/SH			

The University of Alabama

UNIT NO:		241363	2015 TOYO	DTA C	AMRY				WORK ORI		: 3	5507		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED I	DATE: E:	02/05/202	20 09:11:04 20 14:38:22 20 14:38:25	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	77720 DATE:	M 06/02/20	ty Automotive S I <b>ETER 2 - N:</b> 015 FK1FR497262	Services 0	
JOB CODE	L	JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		DON	0	Ν	GARAGE	0.90	\$64.97	\$114.81	\$0	0.00	\$179.78	
06-34-001	INSPECT	HEADLAMPS		DON	0	Ν	GARAGE	0.27	\$19.84	\$0.00	\$0	0.00	\$19.84	
24-02-061	REPAIR	WINDSHIELD		DON	0	Ν	GARAGE	0.00	\$0.00	\$0.00	\$4	46.00	\$46.00	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.76	\$55.24	\$29.84	\$0	0.00	\$85.08	
66-PM-PMC	PERFOR	M CABIN FILTER R	EPLACEMEI	DON	0	N	GARAGE	0.04	\$2.82	\$19.66	\$0	0.00	\$22.48	
CL-34-012	CLEANE	D HEADLAMP ASSE	EMBLY	DON	0	Ν	GARAGE	0.50	\$36.25	\$0.00	\$0	0.00	\$36.25	
JOB COUN	IT: 6				WO	RK ORI	DER TOTAL:	2.47	179.1	2	164.31	46.00		389.43
<u>Job Code</u> 24-02-061	REPAIR WIN	Job Descriptio	<u>on</u>	1	<b>Ve</b> 1078716	endor N		Invoice No. 2192	Purchase	Order No	<u>).</u>	COMML	<u>Total</u>	<u>Cost</u> \$46.00 <b>46.00</b>
Job Code		Job Descriptio	on		Em	ployee	No.	Start	Fir	nish		Quantity	Total	Cost
03-32-002	REPLACE N	EW BATTERY		1	1901357	,		/29/2020 07:43:48				0.16		\$11.66
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		01/	/29/2020 07:20:53	01/29/2020	07:43:48		0.38		\$27.69
66-PM-PMC	PERFORM	CABIN FILTER REPLA	CEMENT	1	1901357		01/	/29/2020 07:18:33	01/29/2020	07:20:53		0.04		\$2.82
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		01/	/29/2020 07:02:44	01/29/2020	07:18:33		0.26		\$19.11
06-34-001	INSPECT HE	EADLAMPS		1	1915538		01/	/28/2020 09:52:07	01/28/2020	10:08:32		0.27		\$19.84
03-32-002	REPLACE N	EW BATTERY		1	1901357		01/	/29/2020 08:21:21	01/29/2020	09:05:28		0.74		\$53.31
66-PM-PMA	PERFORM	DIL CHANGE		1	1901357		01/	/29/2020 09:05:28	01/29/2020	09:12:27		0.12		\$8.44
CL-34-012	CLEANED H	EADLAMP ASSEMBLY	(	1	1901357		01/	/31/2020 07:00:00	01/31/2020	07:30:00		0.50		\$36.25
												LABOR		179.12
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	Des	<u>scription</u>	<u>L</u>	<u> Jnit Price</u>	<u>Quantity</u>	Total	Cost
66-PM-PMA	PERFORM	DIL CHANGE		0	W20T		0W	/20 SYN OIL THO	MAS CAM2 QT		5.84	4 4		\$23.34
66-PM-PMA	PERFORM	DIL CHANGE		0	4152-YZ	ZA1	FIL	TER-OIL			6.50	) 1		\$6.50
66-PM-PMC		CABIN FILTER REPLAC		4	9223		AIF	R FILTER REPL 9	223		12.33	3 1		\$12.33
FleetFocus M5	- WODETAIL	- Work Order Detail v20	0.0											Page:1

#### The University of Alabama

# Work Order Charge Detail

Job Code	Job Description	Part No.	Description	Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	7.33	1	\$7.33
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.63	2	\$1.26
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	164.31

### UNIT NO: 241363 2015 TOYOTA CAMRY

#### WORK ORDER NO: 35507

Work Order Notes

(LISAPATE) PM-Check headlights very dim at night-repair ding in windshield

#### Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and added corrosion washers

#### 06-34-001 - INSPECT HEADLAMPS

(LISAPATE) Found headlight assy were very scratched up

#### 24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr came to the shop and repaired the windshield. Pd by CC

#### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG Coolant -35' Replaced air filter Used .5 qts of oil already charged out

#### 66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

#### CL-34-012 - CLEANED HEADLAMP ASSEMBLY

(LISAPATE) Buffed and cleaned both headlight assy. headlights are brighter now

The University of Alabama

UNIT NO:		241363 2	015 TOYOTA (	AMR	Y			WORK OR	DER NO	):	36435	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	COMF	ED DA	D DATE: TE:	05/15/20	20 13:15:58 20 07:24:01 20 07:24:08	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 79181 <b>DATE</b> :	06/02/	rsity Automotive S <b>METER 2 - N:</b> 2015 F1FK1FR497262	0
JOB CODE 66-PM-PMA	_	JOB DESCRIPTION M OIL CHANGE	<u>I STAT</u> DON	RSN P	N WRTY	GARAGE	LABOR HRS 0.91		<u>MATE</u> \$36.22		COMMERCIAL \$0.00	<b>TOTAL COST</b> \$102.13
JOB COUN	T: 1			W	ORK OR	DER TOTAL	.: 0.91	65.9	)1	36.22	0.00	102.13
Job Code 66-PM-PMA 66-PM-PMA		Job Description DIL CHANGE DIL CHANGE	-	<u>E</u> 120521 119013		0	<u>Start</u> 5/14/2020 15:19:34	4 05/14/2020			<u>Quantity</u> 0.36	<u>Total Cost</u> \$25.84
00-PIVI-PIVIA	PERFORM	JE CHANGE		119013:	10	U	5/14/2020 15:07:24	4 05/14/2020	15.40.34		0.55 LABOR	\$40.08 <b>65.92</b>
Job Code		Job Description	<u>n</u>		Part No	<u>o.</u>	Des	scription		Unit Pric	ce Quantity	Total Cost
66-PM-PMA	PERFORM	DIL CHANGE		05089		В	RAKE CLEAN NOI	N-FLAMMABLE 1	40Z	6.	.44 1	\$6.44
66-PM-PMA	PERFORM	DIL CHANGE		04152-1	ZZA1	F	ILTER-OIL			6.	.50 1	\$6.50
66-PM-PMA	PERFORM	DIL CHANGE		0W20T		0'	W20 SYN OIL THC	MAS CAM2 QT		5.	.82 4	\$23.28
											PARTS	36.22

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	36435
Work Order Note	<u>s</u>			
(EKIMBREL) PM				
Job Notes				
66-PM-PMA - PERFC	ORM OIL CHANGE			
(EKIMBREL) AG/JW used 1/2 qt of charge		olant -35		

The University of Alabama

UNIT NO:		241363 207	15 TOYC	DTA C	AMRY				WORK C	RDER NO	: :	38190	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED	DATE: E:	12/02/202	0 09:29:05 0 09:09:09 0 12:09:34		M: 79181 E DATE:	<b>I</b> 06/02/2	sity Automotive S <b>METER 2 - N:</b> 2015 1FK1FR497262	0
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	<u>MATE</u>	RIAL	COMMERCIAL	TOTAL COST
15-71-044	WARRAN	NTY PAINT /CORROSIC	N PROT	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	9	\$0.00	\$0.00
16-71	TRANSP	ORT BODY		DON	0	Ν	GARAGE	0.50	\$59.00	\$0.00	9	\$0.00	\$59.00
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Ρ	Ν	GARAGE	0.18	\$21.44	\$0.00	S	\$0.00	\$21.44
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL:	0.68	8	0.44	0.00	0.00	80.44
Job Code		Job Description			<u>v</u>	endor N	<u>o.</u>	Invoice No.	Purch	ase Order No	<u>).</u>		Total Cost
15-71-044	WARRANTY	PAINT /CORROSION PRO	OTECTION	1	1076422		609	98321					\$0.00
												COMML	0.00
Job Code		Job Description			En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total Cost</u>
16-71	TRANSPOR	T BODY		1	0208562	2	12/	02/2020 07:00:00	12/02/20	020 07:30:00		0.50	\$59.00
66-PM-PMA	PERFORM	DIL CHANGE		1	2052187	,	10/	28/2020 12:08:38	10/28/20	)20 12:19:32		0.18	\$21.44
												LABOR	80.44

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

#### 241363 2015 TOYOTA CAMRY UNIT NO:

### WORK ORDER NO:

38190

### **Work Order Notes**

(LISAPATE) PM

(LISAPATE) Take to Tuscloosa Toyota to inspect for possible paint peeling covered under Special bulletin

### Job Notes

#### 15-71-044 - WARRANTY PAINT /CORROSION PROTECTION

(LISAPATE) Tuscaloosa Toyota completed special service campaign repainted car as needed where paint was peeling

#### 16-71 - TRANSPORT BODY

(LISAPATE) Taken to Toyota by EK

#### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 23 miles since last pm. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW

The University of Alabama

UNIT NO:		241363 20	15 TOYO	ОТА С	AMRY	,				DER NO:	39	306		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED	DATE: E:	03/10/202	21 07:49:26 21 07:47:58 21 14:02:32	LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL	79227 DATE:	ME 06/02/20	ETER 2 - N:	0	
JOB CODE	L	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CO	OMMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLADE	S	DON	0	Ν	GARAGE	0.10	\$11.80	\$19.25	\$0	.00	\$31.05	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	Ν	GARAGE	0.02	\$2.07	\$35.00	\$0	.00	\$37.07	
CH-32-002	CHARGE	BATTERY		DON	0	Ν	GARAGE	0.21	\$25.34	\$0.00	\$0	.00	\$25.34	
JOB COUN	IT: 3				WO	RK ORI	DER TOTAL:	0.33	39.21	1	54.25	0.00		93.46
Job Code		Job Description				nployee		<u>Start</u>		<u>iish</u>		Quantity	Total	
03-51-038		IEW WIPER BLADES			2052187			/10/2021 07:00:00				0.10		\$11.80
CH-32-002	CHARGE B/	ATTERY		1:	2052187	,	03/	/08/2021 15:30:05	03/08/2021	15:30:46		0.01		\$1.34
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	,	03/	/08/2021 15:28:51	03/08/2021	15:29:54		0.02		\$2.07
CH-32-002	CHARGE B	ATTERY		1	1901357	,	03/	/05/2021 14:59:53	03/05/2021	15:12:05		0.20		\$23.99
												LABOR		39.20
Job Code		Job Description				Part No	<u>.</u>	Des	<u>cription</u>	<u>U</u>	Init Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	IEW WIPER BLADES		1	9260		WI	PER BLADE 26 IN	I OE BEAM		10.41	1		\$10.41
66-PM-PMA	PERFORM	OIL CHANGE		5	7047		FIL	TER-OIL			12.57	1		\$12.57
66-PM-PMA	PERFORM	OIL CHANGE		0	W20BT		BL	ILK OIL 0W20 FS			4.49	5		\$22.43
03-51-038	REPLACE N	IEW WIPER BLADES		1	9180		WI	PER BLADE BEA	M SYLE 18"		8.84	1		\$8.84
												PARTS		54.25

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	39306
Work Order Not	es			
(LISAPATE) PM				
Job Notes				
03-51-038 - REPLA	CE NEW WIPER BL	ADES		
(IFALLS) josh replac	ed wiper blades			
66-PM-PMA - PERF	ORM OIL CHANGE			
(JWRIGHT) Perform MILEAGE79227	ned pm service. Coola	ant -34°. JAW/JAW,AMG		
CH-32-002 - CHAR	GE BATTERY			

(JWRIGHT) Charged over weekend. Good battery

The University of Alabama

UNIT NO:		241363 20	15 TOYO1	TA C/	AMRY				WORK OR	DER NO	): 4	0566	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	C	OMPL LOSE	D DAT ETED D DATI CAMR	DATE: E:	07/29/202	21 07:26:14 21 11:47:55 21 12:11:09	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAI	: 79437 <b>DATE</b> :	<b>M</b> 06/02/20	ty Automotive \$ I <b>ETER 2 - N:</b> 015 FK1FR497262	0
JOB CODE	_	JOB DESCRIPTION		STAT DON	<u>rsn</u> P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.10	<b>LABOR</b> \$11.80	<u>MATE</u> \$17.25		OMMERCIAL	<b>TOTAL COST</b> \$29.05
66-PM-PMA	PERFOR	M OIL CHANGE	[	DON	Ρ	Ν	GARAGE	0.30	\$35.47	\$0.00	\$0	0.00	\$35.47
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	: 0.40	47.2	27	17.25	0.00	64.52
Job Code		Job Description			<u>Em</u>	nployee	<u>No.</u>	<u>Start</u>	<u>F</u>	inish		Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		11	074414		07	7/29/2021 09:14:14	07/29/2021	09:14:14		0.00	\$0.0
03-51-038	REPLACE N	EW WIPER BLADES		11	074414		07	//29/2021 09:14:14	07/29/2021	09:14:14		0.00	\$0.0
03-51-038	REPLACE N	EW WIPER BLADES		11	074414		07	//29/2021 09:14:14	07/29/2021	09:20:14		0.10	\$11.8
66-PM-PMA	PERFORM	DIL CHANGE		11	074414		07	/29/2021 08:55:52	07/29/2021	09:13:54		0.30	\$35.4
												LABOR	47.2
Job Code		Job Description				Part No	<u>.</u>	Des	scription		Unit Price	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		18	31		W	IPER BLADE 18"			7.33	3 1	\$7.3
03-51-038	REPLACE N	EW WIPER BLADES		26	6-1		W	IPER BLADE			9.92	2 1	\$9.9
												PARTS	17.2

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

### UNIT NO: 241363 2015 TOYOTA CAMRY

WORK ORDER NO: 40566

#### Work Order Notes

(LISAPATE) PM-Replace wipers

#### Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

#### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 79437. Vehicle has been driven 210 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

The University of Alabama

UNIT NO:										DER NO	: 42	160		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	218142 CLOSED SCHEDULED 15TOYOTACAMR		COMPI CLOSE	ED DAT ETED D DAT	DATE: E:	01/27/20	22 14:36:53 22 10:15:00 22 07:32:32	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	: 80672 <b>DATE:</b>	<b>ME</b> 06/02/201	TER 2 - N:	0	
JOB CODE	<u>.</u>	JOB DESCRIPTIC	<u>N</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<b>LABOR</b>	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-51-038	REPLAC	E NEW WIPER BLA	DES	DON	Ρ	Ν	GARAGE	0.04	\$4.62	\$17.90	\$0.	00	\$22.52	
03-51-042	REPLAC	E NEW KEY FOB B	ATTERY	DON	0	Ν	GARAGE	0.11	\$13.44	\$2.73	\$0.	00	\$16.17	
10-13-001	SERVICE	FRONT BRAKES &	& ROTORS	DON	0	Ν	GARAGE	0.80	\$94.40	\$1.82	\$0.	00	\$96.22	
66-17-033	PERFOR	M TIRE ROTATION	AND BRAKE	DON	Р	Ν	GARAGE	1.17	\$138.39	\$0.00	\$0.	00	\$138.39	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.58	\$68.18	\$34.31	\$0.	00	\$102.49	
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2.	00	\$2.00	
JOB COUN	T: 6				WO		DER TOTAL	: 2.70	319.	03	56.76	2.00	1	377.79
Job Code		Job Descripti	<u>on</u>		v	endor N	<u>lo.</u>	Invoice No.	Purchas	e Order No	<u>).</u>		Total	Cost
CH-SP	CHARGE Sh	nop Supplies		5	03163		1							\$2.00
												COMML		2.00
<u>Job Code</u>		Job Descripti	on		En	nployee	<u>No.</u>	<u>Start</u>	<u></u>	<u>inish</u>		<u>Quantity</u>	<u>Total</u>	Cost
10-13-001	SERVICE F	RONT BRAKES & ROT	ORS	1	1310047	,	0	1/27/2022 07:00:00	01/27/2022	2 07:48:00		0.80		\$94.40
03-51-042	REPLACE N	EW KEY FOB BATTER	RY	1	1074414	Ļ	0	1/25/2022 15:07:25	01/25/2022	2 15:14:15		0.11		\$13.44
03-51-038	REPLACE N	EW WIPER BLADES		1	1074414	ŀ	0	1/25/2022 15:04:53	01/25/2022	2 15:07:14		0.04		\$4.62
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414	Ļ	0	1/25/2022 14:30:00	01/25/2022	2 15:04:40		0.58		\$68.18
66-PM-PMA	PERFORM	DIL CHANGE		1	1074414	Ļ	0	1/25/2022 14:26:28	01/25/2022	2 14:26:28		0.00		\$0.00
66-17-033	PERFORM	FIRE ROTATION AND	BRAKE INSPEC	CTION 1	1074414	ļ	0	1/25/2022 15:21:21	01/25/2022	2 15:34:12		0.21		\$25.27
66-17-033	PERFORM	FIRE ROTATION AND	BRAKE INSPEC	CTION 1	1074414	Ļ	0	1/26/2022 08:17:29	01/26/2022	2 09:15:00		0.96		\$113.12
												LABOR		319.03
Job Code		Job Descripti	on			Part No	<u>).</u>	Des	<u>scription</u>	<u>l</u>	<u> Jnit Price</u>	<b>Quantity</b>	<u>Total</u>	Cost
03-51-038		EW WIPER BLADES			81			IPER BLADE 18"			7.59	1		\$7.59
66-PM-PMA		DIL CHANGE		0	5089			RAKE CLEAN NO		14OZ	6.56	1		\$6.56
66-PM-PMA					W20BT			ULK OIL 0W20 FS			4.50	5		\$22.50
03-51-038		EW WIPER BLADES		2	6-1		V	IPER BLADE			10.31	1		\$10.31
FleetFocus M5	- WODETAIL	- Work Order Detail v2	0.0											Page:1

#### The University of Alabama

Job Code	Job Description	Part No.	<b>Description</b>	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.73	1	\$2.73
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.82	1	\$1.82
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.82	(1)	(\$1.82)
10-13-001	SERVICE FRONT BRAKES & ROTORS	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.82	1	\$1.82
				_	PARTS	56.76

### UNIT NO: 241363 2015 TOYOTA CAMRY

### WORK ORDER NO: 42160

Work Order Notes

(LISAPATE) PM-replace wipers-key fob battery is dead-check brakes are scrubbing could be due to car was sitting for awhile

#### Job Notes

#### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

#### 03-51-042 - REPLACE NEW KEY FOB BATTERY

(SHARBIN) Replaced key fob battery. Remote is now working properly. SH

#### 10-13-001 - SERVICE FRONT BRAKES & ROTORS

(IFALLS) Removed front and rear brake pads and reconditioned them using sandpaper. There is still some noise when stopping. We plan to release the vehicle to the customer and let them try it. If they want to take further action, then the vehicle will need pads and rotors. EH for scuffing pads

#### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(LISAPATE) Rotated tires and inspected brakes. Brake pads are at 8MM. Test drove the vehicle and the brakes are working properly. The rotors are covered in rust and the brake pads will need to be removed and scuffed to get rid of the scrubbing noise. SH

#### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

**CH-SP - CHARGE Shop Supplies** 

The University of Alabama

UNIT NO:		241363	2015 TOYO	TA C	AMRY				WORK OF	RDER NO:	43	3541		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMR	(	COMPL	D DAT	DATE: E:	06/08/202	22 08:07:46 22 15:35:02 22 10:29:28	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 81594 DATE:	<b>ME</b> 06/02/20	y Automotive S E <b>TER 2 - N:</b> 15 K1FR497262	0	
JOB CODE	<u>E</u>	JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATER	RIAL CO	OMMERCIAL	<u>TOTAL</u>	COST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Ρ	Ν	GARAGE	0.03	\$2.95	\$18.13	\$0	.00	\$21.08	
66-PM-PMA	PERFOF	RM OIL CHANGE		DON	Р	Ν	GARAGE	0.18	\$21.60	\$0.00	\$0	.00	\$21.60	
CH-SP	CHARGE	E Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$2	.00	\$2.00	
JOB COUN	IT: 3				wo	RK ORI	DER TOTAL	0.21	24.	55	18.13	2.00		44.68
Job Code		Job Descript	ion		V	endor N	<u>o.</u>	Invoice No.	Purchas	se Order No	<u>-</u>		Total	<u>Cost</u>
CH-SP	CHARGE SI	hop Supplies		5	03163		1						- <u> </u>	\$2.00
												COMML		2.00
Job Code		Job Descript	ion		Em	ployee	<u>No.</u>	<u>Start</u>	<u>E</u>	<u>inish</u>		<u>Quantity</u>	<u>Total</u>	Cost
03-51-038	REPLACE N	NEW WIPER BLADES		1:	2052187		06	/07/2022 13:37:34	06/07/202	2 13:39:04		0.03		\$2.95
66-PM-PMA	PERFORM	OIL CHANGE		1:	2052187	,	06	/07/2022 13:26:24	06/07/202	2 13:37:23		0.18		\$21.60
												LABOR		24.55
Job Code		Job Descript	ion			Part No	<u>.</u>	Des	scription	<u>U</u>	nit Price	Quantity	<u>Total</u>	Cost
03-51-038	REPLACE N	NEW WIPER BLADES		2	6-1		W	IPER BLADE			10.40	1		\$10.40
03-51-038	REPLACE N	NEW WIPER BLADES		18	81		W	IPER BLADE 18"			7.73	1		\$7.73
												PARTS		18.13

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

#### 241363 2015 TOYOTA CAMRY UNIT NO:

### WORK ORDER NO:

43541

#### Work Order Notes

(LISAPATE) PM-replace wipers

#### Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

#### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been driven 832 miles. Checked fluids and tires. Coolant -34°. JAW MILEAGE-81594

**CH-SP - CHARGE Shop Supplies** 

The University of Alabama

UNIT NO:		241363 2015	ΤΟΥΟΤΑ Ο	AMRY	,			WORK O		: 4	15930	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY	OPENE COMPL CLOSE 2015 TOYOTA	ETED	DATE: E:	01/26/202	23 14:02:34 23 14:06:59 23 10:13:31	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 81594 E DATE:	N 06/02/2	ity Automotive S <b>IETER 2 - N:</b> 015 IFK1FR497262	0
JOB CODE	E	JOB DESCRIPTION	<u>STAT</u>	RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL COST
16-00	TRANSP	ORT COMPLETE VEHICL	E DON	Р	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	0.00	\$0.00
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	60.00	\$0.00
CH-SP	CHARGE	Shop Supplies	DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00	\$	5.00	\$5.00
JOB COUN	IT: 3			WC	RK ORI	DER TOTAL:	0.00	) (	0.00	0.00	5.00	5.00
Job Code		Job Description		v	endor N	0.	Invoice No.	Purcha	ase Order No	) <u>.</u>		Total Cost
CH-SP	CHARGE Sh	op Supplies	5	03163		1						\$5.0
66-PM-PMA	PERFORM C	DIL CHANGE	6	211859		402	2981					\$0.0
											COMML	5.00
Job Code		Job Description		En	nployee	<u>No.</u>	<u>Start</u>		<u>Finish</u>		<u>Quantity</u>	Total Cost
16-00	TRANSPOR	COMPLETE VEHICLE	1	1399745	5	01/	/27/2023 07:00:00	01/27/20	23 07:19:48		(0.33)	(\$38.94
16-00	TRANSPOR	COMPLETE VEHICLE	1	1399745	5	01/	/27/2023 07:00:00	01/27/20	23 07:19:48		0.33	\$38.94
											LABOR	0.00

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

#### 241363 2015 TOYOTA CAMRY UNIT NO:

### WORK ORDER NO:

45930

#### Work Order Notes

(LISAPATE) PM done by Express Oil driver stays in South Alabama

#### Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(IFALLS)

(IFALLS) customer carried to express oil change no transport charged.

#### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM done by Express oil driver paid with their pcard. invoice attached

**CH-SP - CHARGE Shop Supplies** 

The University of Alabama

UNIT NO:	241363 20	15 TOYOTA CAMRY		WORK ORDER NO:	48136	
USING DEPT NO:	218142	OPENED DATE:	09/08/2023 11:13:15	LOCATION: GARAGE - Uni	versity Automotive S	Services
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2023 11:16:23	METER 1 - M: 81594	METER 2 - N:	0
WO VISIT REASO	N: SCHEDULED	CLOSED DATE:	09/11/2023 10:30:35	IN-SERVICE DATE: 06/	02/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO: 4T4	BF1FK1FR497262	
JOB CODE	JOB DESCRIPTION	<u>STAT RSN WRTY</u>	JOB LOC LABOR HRS	LABOR MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA PEF	RFORM OIL CHANGE	DON P N	GARAGE 0.00	\$0.00 \$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORD	ER TOTAL: 0.00	0.00 0.0	0.00	0.00
Job Code	Job Description	Vendor No	o. Invoice No.	Purchase Order No.		Total Cost
66-PM-PMA PERF	ORM OIL CHANGE	6211859	01903-51968			\$0.00
					COMML	0.00

#### 241363 **2015 TOYOTA CAMRY** UNIT NO:

#### WORK ORDER NO: 48136

Work Order Notes

(LISAPATE) Driver works in Foley car will not be in town. Had PM done in Foley by Express Oil Change

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) See attached. Pd by Dept

The University of Alabama

UNIT NO:		241363 20	015 TOYC	DTA C	AMRY				WORK O	RDER NO	):	50461		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	218142 CLOSED SCHEDULED 15TOYOTACAMRY		OPENE COMPL CLOSE	ETED D D DATE	DATE: E:	04/05/202	4 13:57:43 4 14:51:34 4 07:23:43	LOCATION METER 1 - I IN-SERVICE UNIT SERIA	MI: 88178 E DATE:	06/02	rsity Automotive 3 METER 2 - N: /2015 F1FK1FR497262	0	
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	LABOR	MATE	RIAL	COMMERCIAL	<u>TOTAL</u>	COST
CH-SP	CHARGE	Shop Supplies		DON	2	Ν	GARAGE	0.00	\$0.00	\$0.00		\$5.00	\$5.00	
PD-00-999	PREP DI	SPOSE PREPARE UN	IT FOR DI	DON	D	Ν	GARAGE	1.00	\$118.00	\$0.00		\$0.00	\$118.00	
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL:	1.00	118	.00	0.00	5.00	)	123.00
Job Code CH-SP	CHARGE St	Job Description		50	<u>Ve</u> 03163	endor N	<b>lo.</b> 1	Invoice No.	<u>Purcha</u>	se Order N	<u>o.</u>		<u>Total</u>	<u>Cost</u> \$5.00
												COMML		5.00
Job Code		Job Description			Em	ployee	<u>No.</u>	<u>Start</u>	<u> </u>	Finish		Quantity	Total	Cost
PD-00-999	PREP DISP	OSE PREPARE UNIT FO	R DISPOSAL	. 11	1074414		04/	05/2024 14:12:43	04/05/202	24 14:15:00		0.04		\$4.49
PD-00-999	PREP DISP	DSE PREPARE UNIT FO	R DISPOSAL	. 11	1074414		04/	05/2024 14:12:43	04/05/202	24 14:15:00		(0.04	)	(\$4.49)
PD-00-999	PREP DISP	DSE PREPARE UNIT FO	R DISPOSAL	. 11	1074414		04/	05/2024 14:12:43	04/05/202	24 15:12:43		1.00		\$118.00
												LABOR		118.00

The University of Alabama Report Printed: 04/09/2024 14:07:15 By User: GLOBETTI

UNIT NO:	241363	2015 TOYOTA CAMRY	WORK ORDER NO:	50461	

#### Work Order Notes

(EHANNAH) prep for sale

#### Job Notes

CH-SP - CHARGE Shop Supplies

#### PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(SHARBIN) Prepped for sale. Removed the tag insurance cards and RFID sticker. SH

Report Title: Report Author: File Path:	WODETAIL - Work Order Detail v20.0 FleetFocus M5 E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~				
Data Extracted:	Tue Apr 09 2024 14:07:15 Report User: GLOBETTI				
TZ:	Central Standard Time				
DLL Version:	2021.02.23				
Report Comments:	6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773 Parameters and Selection Filters				
First Grouping:	VIEW_WO_WORKSHEET.WO_NO				
Second Grouping:	VIEW_JOB_WORKSHEET.JOB				
Third Grouping:					
Sorted By:					
From Date:					
To Date:					
Option 1:					
Option 2:					
Selection Filters:	isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and( {view_udc_main.serial_no} = '4T4BF1FK1FR497262') //Q=				