

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 37789

USING DEPT NO:	507121	OPENED DATE:	09/28/2020 08:18:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2020 08:21:44	METER 1 - M:	56	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2020 10:13:03	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	09/28/2020 10:12:45	09/28/2020 10:42:45	0.50	\$0.00
					LABOR	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 37789

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 39081

USING DEPT NO:	507121	OPENED DATE:	02/10/2021 14:10:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/12/2021 08:40:04	METER 1 - M:	348	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/12/2021 14:46:37	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.69	\$0.00	\$0.00	\$10.69

JOB COUNT: 1	WORK ORDER TOTAL:	0.09	10.69	0.00	0.00	10.69
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/11/2021 13:00:00	02/11/2021 13:05:26	0.09	\$10.69
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/11/2021 12:06:04	02/11/2021 12:06:04	0.00	\$0.00
					<b>LABOR</b>	<b>10.69</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 39081

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 348 New vehicle, has only been 348 total miles, checked fluids and updated oil change sticker. completed checklist and vacuumed out vehicle no fuel or wash needed. AMG

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 40433

USING DEPT NO:	507121	OPENED DATE:	07/14/2021 11:27:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/15/2021 10:58:43	METER 1 - M:	945	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/16/2021 11:47:24	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.10	\$11.80	\$21.80	\$0.00	\$33.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.29	\$50.13	\$0.00	\$113.42

JOB COUNT: 2	WORK ORDER TOTAL:	0.64	75.09	71.93	0.00	147.02
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/14/2021 13:36:38	07/14/2021 13:36:53	0.00	\$0.49
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/14/2021 13:36:38	07/14/2021 13:36:53	0.00	(\$0.49)
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/14/2021 13:36:38	07/14/2021 13:42:38	0.10	\$11.80
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/14/2021 13:37:09	07/14/2021 14:09:20	0.54	\$63.29
					LABOR	75.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	11.97	1	\$11.97
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	9.83	1	\$9.83
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
					PARTS	71.93

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 40433

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/AMG  
MILEAGE-945

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 40948

USING DEPT NO:	507121	OPENED DATE:	09/07/2021 09:00:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2021 09:54:38	METER 1 - M:	1566	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/09/2021 07:44:13	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$230.00	\$230.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	230.00	289.00
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
14-78-028	INSTALL WINDOW TINT	8616313	1276		\$230.00
				COMML	230.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11901357	09/08/2021 07:00:00	09/08/2021 07:30:00	0.50	\$59.00
					LABOR	59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 40948

## Work Order Notes

(LISAPATE) Take to Custom Films to have all windows tinted and a windshield strip.

## Job Notes

### 14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Custom Films completed tint. Pd by CC

### 16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) Taken to Custom Films by AG

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 42529

USING DEPT NO:	507121	OPENED DATE:	03/02/2022 11:31:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/02/2022 14:48:20	METER 1 - M:	2433	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/03/2022 08:08:24	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.69	\$22.62	\$0.00	\$25.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.80	\$39.78	\$0.00	\$49.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.11	12.49	62.40	2.00	76.89
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/02/2022 12:57:18	03/02/2022 12:58:40	0.02	\$2.69
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/02/2022 12:52:10	03/02/2022 12:57:09	0.08	\$9.80
					LABOR	12.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
					PARTS	62.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 42529

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,MS/JAW  
MILEAGE-2433

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 44439

USING DEPT NO:	507121	OPENED DATE:	08/24/2022 07:35:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2022 14:19:43	METER 1 - M:	4567	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2022 10:04:04	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.13	\$52.85	\$0.00	\$101.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.42	49.13	52.85	5.00	106.98
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/24/2022 08:40:56	08/24/2022 09:05:55	0.42	\$49.13
					LABOR	49.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	10.56	1	\$10.56
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.03
					PARTS	52.85

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 44439

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 4567 Completed PM top and bottom side. AMG/AMG

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 45895

USING DEPT NO:	507121	OPENED DATE:	01/25/2023 07:56:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/26/2023 15:36:19	METER 1 - M:	8884	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2023 09:52:05	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$23.26	\$0.00	\$40.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.44	\$83.00	\$0.00	\$108.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.37	43.14	106.26	5.00	154.40
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/25/2023 09:30:00	01/25/2023 09:42:56	0.22	\$25.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/25/2023 09:19:48	01/25/2023 09:19:48	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/25/2023 09:16:57	01/25/2023 09:25:57	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/25/2023 09:16:57	01/25/2023 09:16:57	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/25/2023 09:16:57	01/25/2023 09:16:57	0.00	\$0.00
				LABOR		43.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	5	\$36.30
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.58	1	\$13.58
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.58	(1)	(\$13.58)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.58	5	\$67.88
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	(5)	(\$36.30)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	1	\$7.26
				PARTS		106.26

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 45895

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/AMG Performed PM.

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 47558

USING DEPT NO:	507121	OPENED DATE:	07/10/2023 09:28:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/12/2023 11:58:21	METER 1 - M:	13221	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/12/2023 13:59:22	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$24.08	\$0.00	\$41.78
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.32	\$64.24	\$0.00	\$106.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.76	89.52	88.32	5.00	182.84
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	07/10/2023 12:11:13	07/10/2023 12:11:13	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	07/10/2023 12:11:13	07/10/2023 12:11:13	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	07/10/2023 12:11:13	07/10/2023 12:26:13	0.25	\$29.50
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/10/2023 12:01:49	07/10/2023 12:01:49	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/10/2023 12:01:49	07/10/2023 12:01:49	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/10/2023 12:01:49	07/10/2023 12:10:49	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/10/2023 10:29:53	07/10/2023 10:51:24	0.36	\$42.32
				LABOR		89.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.31	5	\$41.55
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.93	1	\$11.93
				PARTS		88.32

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 47558

## Work Order Notes

(EHANNAH) pm- replace wipers.

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated tires and inspected the brakes, found no issues at this time-GC  
Brake pads are all 7mm on front and rear.

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 13,221

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 49203

USING DEPT NO:	507121	OPENED DATE:	12/11/2023 08:12:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/13/2023 10:33:17	METER 1 - M:	16904	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2023 13:01:37	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-02-063	DIAGNOSE REAR WINDOW/BACK GLASS	DON	N	N	GARAGE	1.25	\$147.34	\$0.00	\$0.00	\$147.34
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	4.93	\$582.00	\$0.00	\$0.00	\$582.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.11	\$46.96	\$0.00	\$68.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	6.36	750.45	46.96	5.00	802.41
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12395904	12/11/2023 14:30:00	12/11/2023 15:54:45	1.41	\$166.68
66-79-003	PERFORM SAFETY INSPECTION	12395904	12/11/2023 13:00:00	12/11/2023 14:15:00	1.25	\$147.50
66-79-003	PERFORM SAFETY INSPECTION	12395904	12/11/2023 10:13:55	12/11/2023 12:00:00	1.77	\$208.63
35-02-063	DIAGNOSE REAR WINDOW/BACK GLASS	11310047	12/11/2023 13:00:00	12/11/2023 13:01:56	0.03	\$3.80
35-02-063	DIAGNOSE REAR WINDOW/BACK GLASS	11310047	12/11/2023 10:47:01	12/11/2023 12:00:00	1.22	\$143.53
66-79-003	PERFORM SAFETY INSPECTION	11074414	12/11/2023 09:30:00	12/11/2023 10:00:06	0.50	\$59.20
66-79-003	PERFORM SAFETY INSPECTION	11074414	12/11/2023 09:25:05	12/11/2023 09:25:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/11/2023 09:04:16	12/11/2023 09:15:00	0.18	\$21.11
				LABOR		750.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.91	5	\$39.53
					PARTS	46.96

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 49203

## Work Order Notes

(EHANNAH) pm- do SI- Wash

## Job Notes

### **35-02-063 - DIAGNOSE REAR WINDOW/BACK GLASS**

(EHOWELL) The right rear window would not go down using either switch. Found DTCs: B2323 Rear Door Motor ECU Communication Stop and B2313 Glass Position Initialization Incomplete. The window motor was not receiving power due to a faulty connection/broken wire inside the rubber pass-through grommet. This is located in the door jam where the wires constantly bend when the door is opened and closed. The customer needed the vehicle to drive home. Installed door panel and released the vehicle. EH 1.0 HR

### **66-79-003 - PERFORM SAFETY INSPECTION**

(IFALLS) fc performed safety inspection

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 50202

USING DEPT NO:	507121	OPENED DATE:	03/22/2024 08:21:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2024 14:08:28	METER 1 - M:	18603	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2024 07:30:58	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.38	\$44.51	\$0.00	\$0.00	\$44.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.38	44.51	0.00	5.00	49.51
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	12201267	03/22/2024 08:28:49	03/22/2024 08:51:27	0.38	\$44.51
					LABOR	44.51

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 50202

## Work Order Notes

(EHANNAH) install GPS

## Job Notes

### 14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240170 in unit 8594B -GC

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:38:40 By User: GLOBETTI

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 50714

USING DEPT NO:	507121	OPENED DATE:	04/30/2024 14:43:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2024 12:16:53	METER 1 - M:	19311	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2024 11:23:28	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU959992	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.00	\$0.00	\$0.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.00	0.00	2.00	4.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	05/01/2024 10:38:40	05/01/2024 10:39:41	0.02	\$2.00
LABOR						2.00

# Work Order Charge Detail

UNIT NO: 243762 2020 TOYOTA CAMRY

WORK ORDER NO: 50714

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) prepare unit for disposal fc

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon May 20 2024 22:38:40 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243762') //Q=