

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 35089

USING DEPT NO:	507121	OPENED DATE:	12/06/2019 14:39:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2019 07:23:51	METER 1 - M:	55	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2019 07:23:53	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	12/06/2019 14:40:24	12/06/2019 15:10:24	0.50	\$0.00
					LABOR	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 35089

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 35186

USING DEPT NO:	507121	OPENED DATE:	12/13/2019 09:37:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2019 15:39:03	METER 1 - M:	55	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2019 15:39:05	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-028	INSTALL WINDOW TINT	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$210.00	\$210.00
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	0.26	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.26	0.00	0.00	210.00	210.00
--------------	-------------------	------	------	------	--------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
14-78-028	INSTALL WINDOW TINT	5564144	31968		\$210.00
				COMML	210.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	10208562	12/13/2019 11:35:18	12/13/2019 11:51:00	0.26	\$0.00
					LABOR	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 35186

## Work Order Notes

(LISAPATE) Tint windows per the driver

## Job Notes

### 14-78-028 - INSTALL WINDOW TINT

(EKIMBREL) Bama Trim installed window tint.

### 16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(EKIMBREL) Transported to and from Bama Trim.

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 36546

USING DEPT NO:	507121	OPENED DATE:	05/21/2020 13:17:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/26/2020 15:20:00	METER 1 - M:	4048	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2020 14:01:26	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.39	\$0.00	\$203.76	\$0.00	\$203.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$0.00	\$24.03	\$0.00	\$24.03

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	0.00	227.79	0.00	227.79
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-010	REPLACE NEW MIRRORS	11074414	05/26/2020 11:06:55	05/26/2020 11:30:36	0.39	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/26/2020 10:53:47	05/26/2020 11:06:55	0.22	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-010	REPLACE NEW MIRRORS	8791506131B1	COVER, OUTER MIRROR	42.91	1	\$42.91
03-02-010	REPLACE NEW MIRRORS	8791506131B1	COVER, OUTER MIRROR	42.91	(12)	(\$514.92)
03-02-010	REPLACE NEW MIRRORS	8791506131B1	COVER, OUTER MIRROR	42.91	12	\$514.92
03-02-010	REPLACE NEW MIRRORS	8791006800	MIRROR ASSY OUTER LH	160.85	1	\$160.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
					PARTS	227.79

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 36546

## Work Order Notes

(IFALLS) PM Replace passenger mirror glass and upper shell

## Job Notes

### **03-02-010 - REPLACE NEW MIRRORS**

(EKIMBREL) SH removed and replaced passenger side mirror assembly.

### **66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) RC/SH performed pm. Coolant -34

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 38362

USING DEPT NO:	507121	OPENED DATE:	11/12/2020 08:48:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/12/2020 15:35:31	METER 1 - M:	7069	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/13/2020 07:55:16	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$72.77	\$35.68	\$0.00	\$108.45

JOB COUNT: 1	WORK ORDER TOTAL:	0.62	72.77	35.68	0.00	108.45
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/12/2020 09:30:00	11/12/2020 09:45:51	0.26	\$31.17
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/12/2020 08:53:51	11/12/2020 09:15:00	0.35	\$41.60
					LABOR	72.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	35.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 38362

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 7069. SH/EH Performed PM. SH Washed RC vacuumed was full of gas.



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 39932

USING DEPT NO:	507121	OPENED DATE:	05/11/2021 13:13:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/12/2021 09:10:06	METER 1 - M:	9521	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/12/2021 12:57:25	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.28	\$33.50	\$0.00	\$0.00	\$33.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.65	\$76.24	\$35.61	\$0.00	\$111.85

JOB COUNT: 2	WORK ORDER TOTAL:	0.93	109.74	35.61	0.00	145.35
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	05/11/2021 13:41:08	05/11/2021 13:58:10	0.28	\$33.50
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/11/2021 13:29:23	05/11/2021 13:56:39	0.45	\$53.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/11/2021 13:29:24	05/11/2021 13:40:54	0.19	\$22.62
					LABOR	109.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.82	5	\$29.10
					PARTS	35.61

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 39932

## Work Order Notes

(EKIMBREL) pm

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) SH AMG Rotated tires and inspected brakes.

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 9521 Completed PM bottom side Scott was topside. Completed checklist. SH/AMG

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 41625

USING DEPT NO:	507121	OPENED DATE:	11/15/2021 08:48:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2021 14:43:31	METER 1 - M:	12375	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/22/2021 07:53:08	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.41	\$22.62	\$0.00	\$26.03
16-44	TRANSPORT FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
17-44-003	RECALL FUEL PUMP	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.88	\$103.38	\$0.00	\$0.00	\$103.38
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.25	\$29.21	\$330.53	\$0.00	\$359.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$77.72	\$38.42	\$0.00	\$116.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 7	WORK ORDER TOTAL:	2.31	272.72	391.57	2.00	666.29
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-44-003	RECALL FUEL PUMP	11076422	6138860		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-44	TRANSPORT FUEL SYSTEM	12052187	11/22/2021 07:00:00	11/22/2021 07:30:00	0.50	\$59.00
66-17-013	PERFORM ALIGNMENT	11213180	11/16/2021 14:41:17	11/16/2021 15:33:51	0.88	\$103.38
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/16/2021 13:55:28	11/16/2021 13:57:12	0.03	\$3.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/16/2021 13:15:46	11/16/2021 13:55:17	0.66	\$77.72
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	11/16/2021 13:00:00	11/16/2021 13:14:51	0.25	\$29.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	11/16/2021 12:20:16	11/16/2021 12:20:16	0.00	\$0.00
				LABOR		272.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	6.35	2	\$12.69
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1549788	TIRE GEN ALTIMAX 215/55R17	157.52	2	\$315.03
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	6.35	2	\$12.69
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	11	\$2.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	6.35	(2)	(\$12.69)
					<b>PARTS</b>	<b>391.57</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 41625

## Work Order Notes

(LISAPATE) PM-Take to Toyota for recall 20V-682 Vehicle may stall while driving-also ran over debris in the road and cut 1 tire

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

### **16-44 - TRANSPORT FUEL SYSTEM**

(LISAPATE) Taken to Toyota by JW

### **17-44-003 - RECALL FUEL PUMP**

(LISAPATE) Toyota completed recall replaced fuel pump

### **66-17-013 - PERFORM ALIGNMENT**

(MSIDES) Performed alignment.MS

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(JWRIGHT) Replaced rear tires. Aired and balanced to spec. Rotated tires put new on front. Torqued all lugs to spec. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-12493

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 42952

USING DEPT NO:	507121	OPENED DATE:	04/18/2022 13:55:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2022 15:25:08	METER 1 - M:	14800	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/20/2022 08:51:22	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.14	\$16.39	\$146.72	\$0.00	\$163.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.14	16.39	146.72	2.00	165.11
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	04/18/2022 14:06:40	04/18/2022 14:15:00	0.14	\$16.39
					LABOR	16.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	146.72	1	\$146.72
					PARTS	146.72

# Work Order Charge Detail

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 42952

Work Order Notes

(LISAPATE) Check battery had to jump off

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Customer has had intermittent start issues has had to jump vehicle off. Replaced battery ALT charging at 13.7 SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 43180

USING DEPT NO:	507121	OPENED DATE:	05/10/2022 10:51:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2022 10:24:26	METER 1 - M:	15221	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/11/2022 14:20:30	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.71	\$42.44	\$0.00	\$87.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.38	44.71	42.44	2.00	89.15
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2022 10:58:32	05/10/2022 11:21:16	0.38	\$44.71
					LABOR	44.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.43	5	\$37.13
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.31	1	\$5.31
					PARTS	42.44



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 43180

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) EH/SH Performed PM.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 44048

USING DEPT NO:	507121	OPENED DATE:	07/22/2022 10:06:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2022 15:04:28	METER 1 - M:	16664	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2022 15:33:12	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17-028	REPLACE NEW MOUNT AND BALANCE	DON	O	N	GARAGE	1.61	\$190.50	\$14.97	\$0.00	\$205.47
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.15	\$17.70	\$0.00	\$0.00	\$17.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.76	208.20	14.97	2.00	225.17
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	12052187	07/27/2022 07:00:00	07/27/2022 07:09:00	0.15	\$17.70
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	12052187	07/22/2022 10:16:36	07/22/2022 11:53:28	1.61	\$190.50
				LABOR		208.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	19	\$3.14
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.61	4	\$10.44
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	1	\$0.29
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	1	\$0.50
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	58124	1.25 OZ WHEEL WEIGHT	0.60	1	\$0.60
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	B110772A	215/55R17 MICH SURVEY TIRES	0.00	1	\$0.00
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	B110772A	215/55R17 MICH SURVEY TIRES	0.00	(1)	\$0.00
03-17-028	REPLACE NEW MOUNT AND BALANCE TIRES	B110772A	215/55R17 MICH SURVEY TIRES	0.00	4	\$0.00
					PARTS	14.97

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 44048

## Work Order Notes

(LISAPATE) Install 4 survey tires and check steering will come back for alignment when machine is back up

## Job Notes

### 03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all tires with survey tires 13-16. Aired to 35psi and balanced. Torqued all lug nuts to spec. JAW

13-LF 14-RF

15-LR 16-RR

All build dates are 4321

### 06-15 - INSPECT STEERING

(LISAPATE) JW inspected steering

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 44087

USING DEPT NO:	507121	OPENED DATE:	07/27/2022 11:21:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2022 15:44:18	METER 1 - M:	16939	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2022 12:29:49	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.26	\$30.68	\$0.00	\$0.00	\$30.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.26	30.68	0.00	2.00	32.68
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11213180	07/27/2022 14:47:58	07/27/2022 15:03:34	0.26	\$30.68
					LABOR	30.68

# Work Order Charge Detail

UNIT NO:2436062020 TOYOTA CAMRY

WORK ORDER NO:44087

Work Order Notes

(LISAPATE) 4 Survey tires installed could not align due to machine was down. Do alignment

Job Notes

09-15 - ALIGN STEERING

(MSIDES) Performed alignment. MS

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 44607

USING DEPT NO:	507121	OPENED DATE:	09/08/2022 08:31:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/09/2022 13:34:13	METER 1 - M:	19764	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 07:56:37	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$21.86	\$78.43	\$0.00	\$100.29
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.27	\$31.40	\$20.52	\$0.00	\$51.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.45	53.26	98.95	5.00	157.21
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/08/2022 13:12:29	09/08/2022 13:28:27	0.27	\$31.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2022 13:01:10	09/08/2022 13:01:57	0.01	\$1.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/08/2022 11:25:16	09/08/2022 11:35:36	0.17	\$20.32
				LABOR		53.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	10.28	1	\$10.28
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
				PARTS		98.95

# Work Order Charge Detail

UNIT NO:2436062020 TOYOTA CAMRY

WORK ORDER NO:44607

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/SH AMG Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 45254

USING DEPT NO:	507121	OPENED DATE:	11/14/2022 08:45:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2022 07:46:18	METER 1 - M:	24257	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/15/2022 09:54:29	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.70	\$82.04	\$0.00	\$0.00	\$82.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$73.42	\$41.45	\$0.00	\$114.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.32	155.46	41.45	5.00	201.91
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/14/2022 11:07:39	11/14/2022 11:49:22	0.70	\$82.04
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/14/2022 09:51:06	11/14/2022 10:28:26	0.62	\$73.42
					LABOR	155.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
					PARTS	41.45



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 45254

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm service. coolant -34. JAW,SH/JAW,GC

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 45903

USING DEPT NO:	507121	OPENED DATE:	01/25/2023 10:31:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/26/2023 15:31:35	METER 1 - M:	28207	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2023 09:54:40	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$12.23	\$23.26	\$0.00	\$35.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.57	\$75.14	\$0.00	\$90.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.24	27.80	98.40	5.00	131.20
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/25/2023 12:02:33	01/25/2023 12:02:33	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/25/2023 10:53:40	01/25/2023 10:59:53	0.10	\$12.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/25/2023 10:45:33	01/25/2023 10:53:28	0.13	\$15.57
				LABOR		27.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	13.58	5	\$67.88
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	1	\$7.26
				PARTS		98.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 45903

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 28207 Completed PM bottomside, Scott was topside. SH/AMG

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 46604

USING DEPT NO:	507121	OPENED DATE:	04/04/2023 08:05:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2023 09:26:28	METER 1 - M:	31950	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/10/2023 07:46:08	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.61	\$71.49	\$0.00	\$0.00	\$71.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$41.40	\$0.00	\$80.34
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.94	110.43	41.40	5.00	156.83
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12201267	04/04/2023 14:37:11	04/04/2023 15:03:58	0.45	\$52.67
66-79-003	PERFORM SAFETY INSPECTION	12201267	04/04/2023 13:00:00	04/04/2023 13:09:34	0.16	\$18.81
66-79-003	PERFORM SAFETY INSPECTION	12201267	04/04/2023 12:52:35	04/04/2023 12:52:35	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/04/2023 12:43:30	04/04/2023 13:03:18	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/04/2023 12:43:30	04/04/2023 12:43:30	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/04/2023 12:43:30	04/04/2023 12:43:30	0.00	\$0.00
				LABOR		110.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.85	1	\$5.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
					PARTS	41.40

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 46604

## Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash- rotate tires and inspect brakes

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection, no issues found at the time, rotated tires-GC  
Brake pads are all 6mm on all 4 wheels.  
Miles, 31,950

66-79-039 - PERFORM ANNUAL INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-CW,GC- Changed oil and oil filter, checked fluids, tires and tire pressure, filters good.  
Miles, 31,940

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) UAPD. Did not wash

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 47546

USING DEPT NO:	507121	OPENED DATE:	07/07/2023 08:19:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/10/2023 14:14:21	METER 1 - M:	36710	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/10/2023 15:27:55	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.06	\$24.08	\$0.00	\$28.14
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$41.89	\$53.48	\$0.00	\$95.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.39	45.95	77.56	5.00	128.51
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/07/2023 10:35:58	07/07/2023 10:38:02	0.03	\$4.06
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/07/2023 10:14:40	07/07/2023 10:35:58	0.36	\$41.89
					LABOR	45.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	11.93	1	\$11.93
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.31	5	\$41.55
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	77.56

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 47546

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 48373

USING DEPT NO:	507121	OPENED DATE:	10/02/2023 09:03:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/02/2023 14:41:28	METER 1 - M:	41317	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/02/2023 15:52:41	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-029	PERFORM ROTATE AND BALANCE TIRE	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$50.09	\$0.00	\$89.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.58	68.44	50.09	5.00	123.53
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/02/2023 14:05:27	10/02/2023 14:25:15	0.33	\$38.94
66-17-029	PERFORM ROTATE AND BALANCE TIRES	12395904	10/02/2023 14:40:27	10/02/2023 14:55:27	0.25	\$29.50
				LABOR		68.44

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.14	1	\$6.14
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
					PARTS	50.09



# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 48373

## Work Order Notes

(EHANNAH) pm- rotate and balance tires

## Job Notes

**66-17-029 - PERFORM ROTATE AND BALANCE TIRES**

(LISAPATE) Rotated tires FC

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by FC

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 49299

USING DEPT NO:	507121	OPENED DATE:	12/19/2023 08:02:04	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2023 15:13:54	METER 1 - M:	44831	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/21/2023 07:36:44	IN-SERVICE DATE:	12/06/2019						
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry									
			UNIT SERIAL NO:	4T1C11AK0LU860926							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-17-030	INSTALL TIRE PATCH	DON	B	N	GARAGE	0.02	\$2.85	\$0.00	\$0.00	\$2.85
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.72	\$84.99	\$0.00	\$0.00	\$84.99
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.05	\$5.83	\$449.99	\$0.00	\$455.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.79	93.67	449.99	5.00	548.66
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	12052187	12/19/2023 13:36:26	12/19/2023 14:19:39	0.72	\$84.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	12/19/2023 10:55:15	12/19/2023 10:58:13	0.05	\$5.83
14-17-030	INSTALL TIRE PATCH	12395904	12/19/2023 10:53:17	12/19/2023 10:54:44	0.02	\$2.85
					LABOR	93.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	17537	TIRE 215/55R17 MICH DEF2	220.50	2	\$441.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	9	\$1.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	2	\$7.23
					PARTS	449.99

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 49299

## Work Order Notes

(LRUSHING) right front tire blew out

## Job Notes

### **14-17-030 - INSTALL TIRE PATCH**

(EHANNAH) could not patch- needs two new tires

### **66-17-013 - PERFORM ALIGNMENT**

(JWRIGHT) Performed alignment. Adjusted front and rear toes. Test drove and found no issues. JAW

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(EHANNAH) perform balance 9 63001 and 2 21060 FC  
perform install 2 tires too F

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 50170

USING DEPT NO:	507121	OPENED DATE:	03/20/2024 09:16:25	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2024 11:53:48	METER 1 - M:	46809	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2024 10:05:59	IN-SERVICE DATE:	12/06/2019						
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry									
			UNIT SERIAL NO:	4T1C11AK0LU860926							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.04	\$4.92	\$518.13	\$0.00	\$523.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.78	\$42.46	\$0.00	\$71.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:					0.29	33.70	560.59	5.00	599.29
--------------	-------------------	--	--	--	--	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	04/22/2024 09:49:10	04/22/2024 09:51:40	0.04	\$4.92
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/20/2024 11:44:20	03/20/2024 11:58:58	0.24	\$28.78
LABOR						33.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.03
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	26370	TIRE 215/55R17 MICH PRIMACY	254.10	2	\$508.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	12	\$2.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.62	2	\$7.23
PARTS						560.59

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 50170

## Work Order Notes

(EHANNAH) pm

## Job Notes

### **06-15 - INSPECT STEERING**

(EHOWELL) Front end checked good. EH

### **09-15 - ALIGN STEERING**

(EHOWELL) Performed alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(FCONTRER) perform mounted 2 tires and balanced 100360- 12- 21060-4 fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform oil changes FC

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 05/20/2024 22:56:27 By User: GLOBETTI

UNIT NO: 243606 2020 TOYOTA CAMRY

WORK ORDER NO: 50712

USING DEPT NO:	507121	OPENED DATE:	04/30/2024 14:33:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2024 07:34:20	METER 1 - M:	46871	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2024 10:36:57	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU860926	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.84	\$1.84
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$1.84	\$0.00	\$0.00	\$1.84

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	1.84	0.00	1.84	3.68
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$1.84
				COMML	1.84

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	05/01/2024 15:13:22	05/01/2024 15:14:18	0.02	\$1.84
					LABOR	1.84

# Work Order Charge Detail

UNIT NO:2436062020 TOYOTA CAMRY

WORK ORDER NO:50712

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) prepare unit for disposal fc

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Mon May 20 2024 22:56:27 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243606') //Q=