

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 28020

USING DEPT NO:	508106	OPENED DATE:	11/02/2017 08:55:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/03/2017 08:25:55	METER 1 - M:	58	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/03/2017 08:25:57	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11213180	11/02/2017 08:57:04	11/02/2017 09:27:04	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242499 2018 TOYOTA CAMRY WORK ORDER NO: 28020

Work Order Notes

(IFALLS) NEW UNIT

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) MS PERFORMED PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 29035

USING DEPT NO:	508106	OPENED DATE:	03/01/2018 13:12:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2018 08:37:53	METER 1 - M:	4163	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	03/07/2018 08:37:55	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$50.72	\$0.00	\$68.55

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	50.72	0.00	68.55
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/02/2018 07:00:00	03/02/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.43	5	\$42.15
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.57	1	\$8.57
					PARTS	50.72

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 29035

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 29544

USING DEPT NO:	508106	OPENED DATE:	04/24/2018 09:17:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/25/2018 15:40:00	METER 1 - M:	8502	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	04/25/2018 15:40:01	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$49.70	\$0.00	\$67.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	49.70	0.00	67.53
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	04/24/2018 10:58:19	04/24/2018 11:16:55	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.31	5	\$41.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.15	1	\$8.15
					PARTS	49.70

Work Order Charge Detail

UNIT NO: 242499 2018 TOYOTA CAMRY WORK ORDER NO: 29544

Work Order Notes

(AJONES) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI) PM by CS
Coolant -37'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 31073

USING DEPT NO:	508106	OPENED DATE:	10/05/2018 09:29:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/11/2018 07:24:11	METER 1 - M:	22389	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/11/2018 07:24:13	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$50.62	\$0.00	\$73.10

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	22.48	50.62	0.00	73.10
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/05/2018 13:33:37	10/05/2018 13:52:13	0.31	\$22.48
					LABOR	22.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.51	5	\$42.53
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.09	1	\$8.09
					PARTS	50.62

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 31073

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/SH

Coolant -35'

Vehicle was serviced while out of town

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 31558

USING DEPT NO:	508106	OPENED DATE:	11/27/2018 13:57:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2018 09:49:39	METER 1 - M:	22233	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/30/2018 09:49:41	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$88.23	\$0.00	\$110.71
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$21.75	\$45.53	\$0.00	\$67.28

JOB COUNT: 2	WORK ORDER TOTAL:	0.61	44.23	133.76	0.00	177.99
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	11/28/2018 07:18:36	11/28/2018 07:36:36	0.30	\$21.75
66-PM-PMA	PERFORM OIL CHANGE	11758845	11/28/2018 07:00:00	11/28/2018 07:18:36	0.31	\$22.48
					LABOR	44.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	45.53	1	\$45.53
66-PM-PMA	PERFORM OIL CHANGE	17801F0050	AIR FILTER 2018 CAMRY	37.26	1	\$37.26
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.58	1	\$8.58
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.07	5	\$40.35
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.58	(1)	(\$8.58)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.58	5	\$42.90
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.07	(5)	(\$40.35)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	8.07	1	\$8.07
					PARTS	133.76

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 31558

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Visit Reason Changed On 11/27/2018 1:58 PM By EKIMBREL

(LISAPATE) PM by CS

Replaced air filter

Coolant -30'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 33121

USING DEPT NO:	508106	OPENED DATE:	06/11/2019 09:00:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/14/2019 08:37:30	METER 1 - M:	31561	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/14/2019 08:37:32	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$25.58	\$0.00	\$43.71
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$42.78	\$0.00	\$65.26
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.30	\$21.75	\$45.53	\$0.00	\$67.28

JOB COUNT: 3	WORK ORDER TOTAL:	0.86	62.36	113.89	0.00	176.25
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/12/2019 07:00:00	06/12/2019 07:18:36	0.31	\$22.48
03-51-038	REPLACE NEW WIPER BLADES	10208562	06/12/2019 07:00:00	06/12/2019 07:15:00	0.25	\$18.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	10208562	06/12/2019 07:15:00	06/12/2019 07:33:00	0.30	\$21.75
					LABOR	62.36

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.69	1	\$6.69
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.96	5	\$29.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	45.53	1	\$45.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.31	1	\$6.31
					PARTS	113.89

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 33121

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Coolant -35'

NOTE**** Previous oil change was done at Express Oil

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 33504

USING DEPT NO:	508106	OPENED DATE:	07/23/2019 09:18:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2019 06:38:05	METER 1 - M:	35533	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2019 06:38:07	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$35.94	\$0.00	\$58.42

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	22.48	35.94	0.00	58.42
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/23/2019 11:34:37	07/23/2019 11:53:13	0.31	\$22.48
					LABOR	22.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.69	1	\$6.69
					PARTS	35.94

Work Order Charge Detail

UNIT NO:	242499	2018 TOYOTA CAMRY	WORK ORDER NO:	33504
----------	--------	-------------------	----------------	-------

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,JW/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 34252

USING DEPT NO:	508106	OPENED DATE:	09/26/2019 09:22:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/30/2019 06:46:57	METER 1 - M:	39656	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/30/2019 06:46:59	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$19.78	\$42.23	\$0.00	\$62.01

JOB COUNT: 1	WORK ORDER TOTAL:	0.27	19.78	42.23	0.00	62.01
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/27/2019 06:21:14	09/27/2019 06:37:36	0.27	\$19.78
					LABOR	19.78

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
					PARTS	42.23

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 34252

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/AG

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 34975

USING DEPT NO:	508106	OPENED DATE:	11/25/2019 10:38:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/27/2019 10:46:14	METER 1 - M:	43224	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/27/2019 10:46:16	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.09	\$6.44	\$25.58	\$0.00	\$32.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$32.28	\$35.69	\$0.00	\$67.97

JOB COUNT: 2	WORK ORDER TOTAL:	0.53	38.72	61.27	0.00	99.99
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/25/2019 13:52:21	11/25/2019 13:57:41	0.09	\$6.44
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/25/2019 14:34:26	11/25/2019 15:00:32	0.44	\$31.54
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/25/2019 13:51:44	11/25/2019 13:52:21	0.01	\$0.75
					LABOR	38.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	12.79	1	\$12.79
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
					PARTS	61.27

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 34975

Work Order Notes

(LISAPATE) PM-Replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 35589

USING DEPT NO:	508106	OPENED DATE:	02/06/2020 09:46:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2020 11:24:20	METER 1 - M:	47389	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2020 11:24:22	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.15	\$83.40	\$39.59	\$0.00	\$122.99

JOB COUNT: 1	WORK ORDER TOTAL:	1.15	83.40	39.59	0.00	122.99
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2020 11:10:24	02/06/2020 11:57:47	0.79	\$57.25
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/06/2020 11:07:47	02/06/2020 11:29:25	0.36	\$26.14
					LABOR	83.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.62	5	\$33.08
					PARTS	39.59

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 35589

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 36305

USING DEPT NO:	508106	OPENED DATE:	05/04/2020 13:41:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2020 11:47:32	METER 1 - M:	49608	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2020 13:35:16	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$25.62	\$50.24	\$0.00	\$75.86

JOB COUNT: 2	WORK ORDER TOTAL:	0.85	61.87	50.24	0.00	112.11
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11310047	05/05/2020 07:00:00	05/05/2020 07:30:00	0.50	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/05/2020 08:27:36	05/05/2020 08:48:48	0.35	\$25.62
					LABOR	61.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	14.19	1	\$14.19
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.91	5	\$29.55
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	50.24

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 36305

Work Order Notes

(IFALLS) PM

Job Notes

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(IFALLS) EH rotated tires

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG/EK/JW performed pm

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 37879

USING DEPT NO:	508106	OPENED DATE:	10/05/2020 14:48:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/06/2020 11:43:38	METER 1 - M:	51060	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2020 12:43:52	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.41	\$35.75	\$0.00	\$104.16

JOB COUNT: 1	WORK ORDER TOTAL:	0.58	68.41	35.75	0.00	104.16
--------------	-------------------	------	-------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/06/2020 10:46:39	10/06/2020 11:21:26	0.58	\$68.41
					LABOR	68.41

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
					PARTS	35.75

Work Order Charge Detail

UNIT NO:	242499	2018 TOYOTA CAMRY	WORK ORDER NO:	37879
----------	--------	-------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) AB/SH PERFORMED PM

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 39495

USING DEPT NO:	508106	OPENED DATE:	03/26/2021 14:16:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2021 08:26:46	METER 1 - M:	54326	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/30/2021 13:10:01	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.63	\$35.68	\$0.00	\$59.31

JOB COUNT: 1	WORK ORDER TOTAL:	0.20	23.63	35.68	0.00	59.31
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/26/2021 14:30:00	03/26/2021 14:36:50	0.11	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/26/2021 14:19:20	03/26/2021 14:19:20	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/26/2021 14:30:00	03/26/2021 14:35:11	0.09	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/26/2021 14:19:35	03/26/2021 14:19:35	0.00	\$0.00
					LABOR	23.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 39495

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG
MILEAGE-54326

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 40287

USING DEPT NO:	508106	OPENED DATE:	06/29/2021 07:35:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2021 08:37:17	METER 1 - M:	58486	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2021 09:36:05	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.80	\$43.58	\$0.00	\$55.38

JOB COUNT: 1	WORK ORDER TOTAL:	0.10	11.80	43.58	0.00	55.38
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2021 12:33:19	06/29/2021 12:33:19	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2021 12:33:19	06/29/2021 12:33:19	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2021 12:33:19	06/29/2021 12:39:19	0.10	\$11.80
					LABOR	11.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	1	\$9.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
					PARTS	43.58

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 40287

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW

MILEAGE-58486

Will likely need rear tires replaced at next pm

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 41298

USING DEPT NO:	508106	OPENED DATE:	10/12/2021 14:07:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2021 09:39:15	METER 1 - M:	63138	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2021 08:11:58	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.19	\$22.13	\$17.90	\$0.00	\$40.03
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.42	\$49.99	\$0.00	\$0.00	\$49.99
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.48	\$56.80	\$0.00	\$0.00	\$56.80
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.83	\$97.61	\$603.43	\$0.00	\$701.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$118.00	\$77.58	\$0.00	\$195.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
JOB COUNT: 6		WORK ORDER TOTAL:				2.92	344.53	698.91	2.00	1,045.44

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11310047	10/14/2021 13:26:49	10/14/2021 13:52:14	0.42	\$49.99
66-17-013	PERFORM ALIGNMENT	11310047	10/14/2021 11:25:55	10/14/2021 11:54:48	0.48	\$56.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	10/14/2021 07:24:15	10/14/2021 08:13:53	0.83	\$97.61
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2021 08:39:12	10/13/2021 09:15:00	0.60	\$70.41
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/13/2021 09:08:35	10/13/2021 09:19:50	0.19	\$22.13
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/13/2021 08:43:47	10/13/2021 09:07:59	0.40	\$47.59
LABOR						344.53

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.13	5	\$35.63
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.26	1	\$9.26
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15497880000	GEN ALTIMAX 215/55R17	146.03	4	\$584.10

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58125	1.50 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	COATED 15G	COATED 15G WHEEL WEIGHT	0.11	1	\$0.11
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	7	\$0.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	4	\$17.22
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	26.15	1	\$26.15
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	698.91

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 41298

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades

06-15 - INSPECT STEERING

(EHOWELL) Front end good.

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced and balanced all 4 tires. Torqued lug nuts to spec. JAW,SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-63138

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 42393

USING DEPT NO:	508106	OPENED DATE:	02/18/2022 08:55:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2022 15:17:08	METER 1 - M:	68564	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 15:17:11	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.41	\$17.90	\$0.00	\$23.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$34.97	\$39.86	\$0.00	\$74.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.38	57.76	2.00	100.14
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/18/2022 11:00:41	02/18/2022 11:03:26	0.05	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/18/2022 10:59:55	02/18/2022 11:00:29	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/18/2022 10:04:16	02/18/2022 10:21:29	0.29	\$33.86
				LABOR		40.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.74	5	\$33.68
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
				PARTS		57.76

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 42393

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW
MILEAGE-68564

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 42869

USING DEPT NO:	508106	OPENED DATE:	04/08/2022 13:19:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/11/2022 09:19:00	METER 1 - M:	72367	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/14/2022 07:34:15	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.68	\$39.00	\$0.00	\$63.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.21	24.68	39.00	2.00	65.68
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/11/2022 08:26:18	04/11/2022 08:38:51	0.21	\$24.68
					LABOR	24.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.40	1	\$5.40
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
					PARTS	39.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 42869

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 43504

USING DEPT NO:	508106	OPENED DATE:	06/03/2022 07:58:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/03/2022 14:19:06	METER 1 - M:	75097	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2022 10:40:20	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.73	\$46.70	\$0.00	\$92.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.39	45.73	46.70	2.00	94.43
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/03/2022 10:16:32	06/03/2022 10:39:47	0.39	\$45.73
					LABOR	45.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.35	1	\$9.35
					PARTS	46.70

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 43504

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 45236

USING DEPT NO:	508106	OPENED DATE:	11/11/2022 08:35:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2022 14:08:53	METER 1 - M:	79568	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/14/2022 07:30:21	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.36	\$18.41	\$0.00	\$26.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$13.01	\$41.45	\$0.00	\$54.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.18	21.37	59.86	5.00	86.23
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/11/2022 13:16:58	11/11/2022 13:21:13	0.07	\$8.36
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/11/2022 13:10:11	11/11/2022 13:16:48	0.11	\$13.01
					LABOR	21.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.59	1	\$10.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
					PARTS	59.86

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 45236

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/AMG
MILEAGE-79568

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 45515

USING DEPT NO:	508106	OPENED DATE:	12/09/2022 11:22:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2022 09:47:39	METER 1 - M:	79961	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/14/2022 15:46:42	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	1.50	\$177.00	\$72.68	\$0.00	\$249.68
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.10	\$11.21	\$0.00	\$0.00	\$11.21
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.99	\$116.36	\$0.00	\$0.00	\$116.36
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.42	\$49.40	\$0.00	\$0.00	\$49.40
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.10	\$11.51	\$0.00	\$0.00	\$11.51
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.56	\$66.15	\$15.45	\$0.00	\$81.60
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.75	\$5.75

JOB COUNT: 7	WORK ORDER TOTAL:	3.66	431.63	88.13	5.75	525.51
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
				COMML	5.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	11310047	12/13/2022 09:40:09	12/13/2022 09:45:51	0.10	\$11.21
06-13	INSPECT BRAKES	11310047	12/13/2022 09:40:09	12/13/2022 09:45:51	(0.10)	(\$11.21)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	12/14/2022 07:00:00	12/14/2022 08:30:00	1.50	\$177.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	12/14/2022 07:00:00	12/14/2022 08:30:00	(1.50)	(\$177.00)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	12/14/2022 07:00:00	12/14/2022 08:30:00	1.50	\$177.00
06-13	INSPECT BRAKES	11310047	12/13/2022 09:40:09	12/13/2022 09:45:51	0.10	\$11.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/12/2022 13:13:18	12/12/2022 13:46:56	0.56	\$66.15
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	12/12/2022 13:02:09	12/12/2022 13:43:17	(0.69)	(\$80.90)
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	12/12/2022 13:02:09	12/12/2022 13:43:17	0.69	\$80.90
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	12/12/2022 11:03:08	12/12/2022 11:52:12	(0.82)	(\$96.50)

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	12/12/2022 11:03:08	12/12/2022 11:52:12	0.82	\$96.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/12/2022 13:13:18	12/12/2022 13:46:56	(0.56)	(\$66.15)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/12/2022 13:13:18	12/12/2022 13:46:56	0.56	\$66.15
09-15	ALIGN STEERING	11310047	12/12/2022 14:27:09	12/12/2022 14:27:09	0.00	\$0.00
09-15	ALIGN STEERING	11310047	12/12/2022 14:27:09	12/12/2022 14:27:09	0.00	\$0.00
09-15	ALIGN STEERING	11310047	12/12/2022 14:27:09	12/12/2022 14:27:09	0.00	\$0.00
09-15	ALIGN STEERING	11310047	12/12/2022 14:30:00	12/12/2022 14:55:07	0.42	\$49.40
09-15	ALIGN STEERING	11310047	12/12/2022 14:30:00	12/12/2022 14:55:07	(0.42)	(\$49.40)
09-15	ALIGN STEERING	11310047	12/12/2022 14:30:00	12/12/2022 14:55:07	0.42	\$49.40
06-15	INSPECT STEERING	11310047	12/12/2022 14:55:07	12/12/2022 15:54:17	0.99	\$116.36
06-15	INSPECT STEERING	11310047	12/12/2022 14:55:07	12/12/2022 15:54:17	(0.99)	(\$116.36)
06-15	INSPECT STEERING	11310047	12/12/2022 14:55:07	12/12/2022 15:54:17	0.99	\$116.36
66-13-130	PERFORM Burnish Brakes	11310047	12/13/2022 09:34:18	12/13/2022 09:40:09	0.10	\$11.51
66-13-130	PERFORM Burnish Brakes	11310047	12/13/2022 09:34:18	12/13/2022 09:40:09	(0.10)	(\$11.51)
66-13-130	PERFORM Burnish Brakes	11310047	12/13/2022 09:34:18	12/13/2022 09:40:09	0.10	\$11.51
					LABOR	431.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	3	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.98	2	\$13.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	(3)	(\$0.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.98	(2)	(\$13.95)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.50	(1)	(\$0.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	(1)	(\$0.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	3	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.98	2	\$13.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.50	1	\$0.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	1	\$0.50
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR172076	FRONT BRAKE PADS	66.75	1	\$66.75
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR172076	FRONT BRAKE PADS	66.75	(1)	(\$66.75)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	(1)	(\$5.93)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
CU-13-001	CUT FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	(1)	(\$5.93)
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR172076	FRONT BRAKE PADS	66.75	1	\$66.75
CU-13-001	CUT FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
					PARTS	88.13

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 45515

Work Order Notes

(EHANNAH) Per Gary brakes are pulsating when stopping

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) Verified that front rotors could be machined. Cut front rotors using the on-car brake lathe. Installed new brake pads and hardware. EH

(AJONES) Visit Reason Changed On 1/4/2023 3:46 PM By AJONES

06-13 - INSPECT BRAKES

(EHOWELL) Found front brake pad near 4mm. Rear pads and rotors looked good. EH

(AJONES) Visit Reason Changed On 1/4/2023 3:45 PM By AJONES

06-15 - INSPECT STEERING

(EHOWELL) Checked front end. EH

(AJONES) Visit Reason Changed On 1/4/2023 3:45 PM By AJONES

09-15 - ALIGN STEERING

(EHOWELL) Checked alignment. Did not make any mechanical adjustments. Reset steering angle sensor using code link. EH .5 HR

(AJONES) Visit Reason Changed On 1/4/2023 3:46 PM By AJONES

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

(AJONES) Visit Reason Changed On 1/4/2023 3:45 PM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Mounted and balanced 2 used tires from upstairs non-inventory. Put the new tires on the front. SH

General Altimax RT 43. 215/55R17

(AJONES) Visit Reason Changed On 1/4/2023 3:45 PM By AJONES

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 1/4/2023 3:46 PM By AJONES

CU-13-001 - CUT FRONT BRAKES & ROTORS

(LISAPATE)

(LISAPATE) cancel

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 46675

USING DEPT NO:	508106	OPENED DATE:	04/11/2023 09:13:59	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2023 14:46:35	METER 1 - M:	82836	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2023 09:10:26	IN-SERVICE DATE:	11/02/2017						
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry			UNIT SERIAL NO:	4T1B11HK8JU028099					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.47	\$19.25	\$0.00	\$22.72
09-16	ALIGN SUSPENSION	DON	N	N	GARAGE	1.76	\$207.48	\$0.00	\$0.00	\$207.48
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.69	\$80.96	\$391.43	\$0.00	\$472.39
66-44-061	PERFORM SMOKE TEST	DON	U	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.45	\$52.90	\$0.00	\$0.00	\$52.90
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.41	\$41.40	\$0.00	\$83.81
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$6.23	\$22.73	\$0.00	\$28.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	U	N	GARAGE	1.25	\$147.73	\$0.00	\$0.00	\$147.73

JOB COUNT: 9	WORK ORDER TOTAL:	5.59	659.18	474.81	5.00	1,138.99
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	04/12/2023 07:18:33	04/12/2023 07:59:43	0.69	\$80.96
66-79-003	PERFORM SAFETY INSPECTION	11074414	04/11/2023 14:30:22	04/11/2023 14:57:16	0.45	\$52.90
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/11/2023 14:13:14	04/11/2023 14:15:00	0.03	\$3.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/11/2023 14:09:53	04/11/2023 14:13:03	0.05	\$6.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/11/2023 13:48:06	04/11/2023 14:09:40	0.36	\$42.41
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:23:54	04/21/2023 09:23:54	0.00	\$0.00
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:30:00	04/21/2023 10:41:11	(1.19)	(\$139.99)
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:23:54	04/21/2023 09:23:54	0.00	\$0.00
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:30:00	04/21/2023 10:41:11	1.19	\$139.99

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:23:54	04/21/2023 09:23:54	0.00	\$0.00
09-16	ALIGN SUSPENSION	11310047	04/21/2023 09:30:00	04/21/2023 10:41:11	1.19	\$139.99
66-44-061	PERFORM SMOKE TEST	11310047	05/01/2023 07:00:00	05/01/2023 08:00:00	1.00	\$118.00
66-44-061	PERFORM SMOKE TEST	11310047	05/01/2023 07:00:00	05/01/2023 08:00:00	1.00	\$118.00
66-44-061	PERFORM SMOKE TEST	11310047	05/01/2023 07:00:00	05/01/2023 08:00:00	(1.00)	(\$118.00)
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/21/2023 07:59:53	04/21/2023 09:15:00	1.25	\$147.73
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/21/2023 07:59:53	04/21/2023 09:15:00	1.25	\$147.73
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	04/21/2023 07:59:53	04/21/2023 09:15:00	(1.25)	(\$147.73)
09-16	ALIGN SUSPENSION	11310047	04/21/2023 07:25:34	04/21/2023 07:59:53	0.57	\$67.49
09-16	ALIGN SUSPENSION	11310047	04/21/2023 07:25:34	04/21/2023 07:59:53	(0.57)	(\$67.49)
09-16	ALIGN SUSPENSION	11310047	04/21/2023 07:25:34	04/21/2023 07:59:53	0.57	\$67.49
					LABOR	659.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.31	2	\$10.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.14	4	\$0.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.85	1	\$5.85
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.22	1	\$8.22
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	11.03	1	\$11.03
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557627	TIRE 215/55R17 GEN ALTIMAX	189.63	2	\$379.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58162	COATED 10G WW	0.47	1	\$0.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58163	COATED 15G WW	0.54	1	\$0.54
					PARTS	474.81

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 46675

Work Order Notes

(EHANNAH) pm- replace wipers- do SI- wash
(EHANNAH) alignment only

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

09-16 - ALIGN SUSPENSION

(EHOWELL) Performed alignment. EH
(AJONES) Visit Reason Changed On 5/25/2023 1:51 PM By AJONES

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced both rear tires and installed on front. Balanced and torqued lug nuts to spec. JAW

66-44-061 - PERFORM SMOKE TEST

(EHOWELL) Performed a smoke test on the EVAP system. Found smoke coming out of the vent solenoid. EH
(LISAPATE) Parts ordered dept needed car will bring back Wednesday.
(AJONES) Visit Reason Changed On 5/25/2023 1:52 PM By AJONES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found the right rear tire at 3/32 and on the wear bar. Suggest 2 rear tires. Found no other issues at this time. Front pads measure 9MM rear pads measure 7MM. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTCs: P0455 EVAP System Leakage Detected (Large Leak) and P04417E EVAP System Purge Flow Incorrect Actuator Stuck On.
(AJONES) Visit Reason Changed On 5/25/2023 1:51 PM By AJONES

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 47360

USING DEPT NO:	508106	OPENED DATE:	06/14/2023 10:32:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/14/2023 15:00:54	METER 1 - M:	83908	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/15/2023 07:31:58	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.49	\$24.08	\$0.00	\$32.57
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.07	8.49	24.08	5.00	37.57
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	06/14/2023 10:40:41	06/14/2023 10:45:00	0.07	\$8.49
					LABOR	8.49

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	24.08

Work Order Charge Detail

UNIT NO:2424992018 TOYOTA CAMRY

WORK ORDER NO:47360

Work Order Notes

(EHANNAH) replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 47481

USING DEPT NO:	508106	OPENED DATE:	06/29/2023 15:35:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/13/2023 08:40:39	METER 1 - M:	84077	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/13/2023 11:00:48	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-02-061	REPAIR WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,556.79	\$1,556.79
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.50	59.00	0.00	1,619.29	1,678.29
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	2110062		\$57.50
24-02-061	REPAIR WINDSHIELD	11078716	2110062		(\$57.50)
24-02-061	REPAIR WINDSHIELD	11078716	2110062		\$57.50
24-71	REPAIR BODY	11150605	1697552		\$1,556.79
24-71	REPAIR BODY	11150605	1697552		(\$1,556.79)
24-71	REPAIR BODY	11150605	1697552		\$1,556.79
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 1619.29

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	07/13/2023 07:00:00	07/13/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11399745	07/13/2023 07:00:00	07/13/2023 07:30:00	0.50	\$59.00
16-71	TRANSPORT BODY	11399745	07/13/2023 07:00:00	07/13/2023 07:30:00	(0.50)	(\$59.00)
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 47481

Work Order Notes

(EHANNAH) repair and transport body- repair windshield

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by CW Pd by PO

(LRUSHING) Visit Reason Changed On 7/28/2023 8:26 AM By LRUSHING

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr repaired a ding in the windshield. PD by CC

(LRUSHING) Visit Reason Changed On 7/28/2023 8:26 AM By LRUSHING

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired front bumper and grille per the estimate. Dept pay

(LRUSHING) Visit Reason Changed On 7/28/2023 8:26 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 7/28/2023 8:26 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 48302

USING DEPT NO:	508106	OPENED DATE:	09/22/2023 09:11:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2023 15:12:09	METER 1 - M:	86532	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 15:12:10	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.06	\$7.21	\$51.39	\$0.00	\$58.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.21	\$24.94	\$0.00	\$0.00	\$24.94

JOB COUNT: 3	WORK ORDER TOTAL:	0.27	32.15	51.39	5.00	88.54
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	09/22/2023 10:29:41	09/22/2023 10:42:22	0.21	\$24.94
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/22/2023 10:25:30	09/22/2023 10:29:10	0.06	\$7.21
					LABOR	32.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.44	1	\$7.44
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
					PARTS	51.39

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 48302

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Performed oil changed filter tires pressure and tread

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 49038

USING DEPT NO:	508106	OPENED DATE:	11/21/2023 13:41:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2023 14:37:44	METER 1 - M:	87813	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/22/2023 09:55:47	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.02	\$2.10	\$221.08	\$0.00	\$223.18
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.01	\$1.64	\$0.00	\$0.00	\$1.64
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.03	3.74	221.08	5.00	229.82
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11399745	11/21/2023 14:32:52	11/21/2023 14:33:42	0.01	\$1.64
03-32-002	REPLACE NEW BATTERY	11399745	11/21/2023 14:31:32	11/21/2023 14:32:36	0.02	\$2.10
LABOR						3.74

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	221.08	1	\$221.08
PARTS						221.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 49038

Work Order Notes

(LRUSHING) dead battery-replace battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Replaced battery 11/21/2023 CW/RC

66-79-002 - PERFORM SERVICE CALL

(GARAGE) Performed service call. CW/RC

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 11/28/2023 2:09 PM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 49176

USING DEPT NO:	508106	OPENED DATE:	12/07/2023 15:18:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2023 09:24:11	METER 1 - M:	87874	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2023 12:55:06	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	0.54	\$63.36	\$0.00	\$0.00	\$63.36

JOB COUNT: 2	WORK ORDER TOTAL:	0.54	63.36	0.00	5.00	68.36
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/08/2023 07:01:21	12/08/2023 07:33:34	0.54	\$63.36
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/08/2023 07:01:21	12/08/2023 07:33:34	0.54	\$63.36
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	12/08/2023 07:01:21	12/08/2023 07:33:34	(0.54)	(\$63.36)
LABOR						63.36

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 49176

Work Order Notes

(EHANNAH) scan-out- check engine light is on

Job Notes

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 12/18/2023 8:38 AM By LRUSHING

SO-00 - SCAN OUT COMPLETE VEHICLE

(EHOWELL) The check engine light was not on and there are no engine nor transmission related DTCs. The scheduled maintenance message was displayed. Reset the maintenance monitor and verified the oil change sticker/mileage of the vehicle. EH

(LRUSHING) Visit Reason Changed On 12/18/2023 8:38 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 50026

USING DEPT NO:	508106	OPENED DATE:	03/01/2024 10:01:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2024 09:02:23	METER 1 - M:	88874	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2024 14:10:08	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.18	\$24.08	\$0.00	\$25.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$57.20	\$50.18	\$0.00	\$107.38
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.34	\$22.73	\$0.00	\$24.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.22	\$25.83	\$0.00	\$0.00	\$25.83

JOB COUNT: 5	WORK ORDER TOTAL:	0.73	85.55	96.99	5.00	187.54
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	03/01/2024 13:52:32	03/01/2024 13:53:13	0.01	\$1.34
03-51-038	REPLACE NEW WIPER BLADES	12395904	03/01/2024 13:51:26	03/01/2024 13:52:02	0.01	\$1.18
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/01/2024 13:21:59	03/01/2024 13:51:04	0.48	\$57.20
WA-00	WASH COMPLETE VEHICLE	12395904	03/04/2024 07:17:34	03/04/2024 07:30:42	0.22	\$25.83
				LABOR		85.55

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
				PARTS		96.99

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 50026

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced cabin filter fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 50905

USING DEPT NO:	508106	OPENED DATE:	05/21/2024 15:41:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2024 15:14:22	METER 1 - M:	90367	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2024 07:44:49	IN-SERVICE DATE:	11/02/2017	
TECH SPEC NO:	18TOYOTACAMRY	2018 Toyota Camry		UNIT SERIAL NO:	4T1B11HK8JU028099	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.33	\$2.33
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.33	\$0.00	\$0.00	\$2.33

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.33	0.00	2.33	4.66
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.33
				COMML	2.33

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	12395904	05/23/2024 14:03:06	05/23/2024 14:04:17	0.02	\$2.33
					LABOR	2.33

Work Order Charge Detail

The University of Alabama

Report Printed: 06/10/2024 15:34:36 By User: GLOBETTI

UNIT NO: 242499 2018 TOYOTA CAMRY

WORK ORDER NO: 50905

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) perform prepare unit for disposal fc -gc

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Jun 10 2024 15:34:36 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '242499') //Q=