Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

232451 **UNIT NO:** 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 11260 **USING DEPT NO:** 208185 OPENED DATE: 06/20/2012 10:11:32 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 06/21/2012 08:11:40 **COMPLETED DATE: METER 1 - M**: 21056 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 06/21/2012 08:11:41 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 JOB CODE JOB LOC LABOR HRS **MATERIAL** JOB DESCRIPTION STAT RSN WRTY LABOR COMMERCIAL TOTAL COST CH-01 CHARGE AIR CONDITIONING, HEAT, VE DON 0 **GARAGE** 1.00 \$57.50 \$62.77 \$120.27 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 1.00 57.50 62.77 0.00 120.27 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** CH-01 CHARGE AIR CONDITIONING, HEAT, VENT 11268671 06/20/2012 16:00:00 06/20/2012 17:00:00 1.00 \$57.50 **LABOR** 57.50 Job Code **Job Description** Part No. Description **Unit Price Total Cost** Quantity 3 CH-01 CHARGE AIR CONDITIONING, HEAT, VENT FRER134A 20.92 \$62.77 R134A FREON **PARTS** 62.77

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 11260

**Work Order Notes** 

(LPATE) REAR A/C IS NOT COLD

**Job Notes** 

**CH-01 - CHARGE AIR CONDITIONING, HEAT, VENT** 

(RWINTERS) ADDED 3 CANS FREON TO REAR A/C SYSTEMS. NO LEAK FOUND.

UNIT NO:		232451 2003	3 CHEVRO	DLE	T BL	UE BIF	RD		WORK (	ORDER NO	<b>)</b> :	12439	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED PREVENTIVE MAINT 03BUSBLUEBIRD	COI	MPLI DSEI	D DATI ETED I D DATI : Blue E	DATE: E:	11/29/20 11/29/20	12 15:12:22 12 13:28:44 12 13:28:45		- M: 22667 CE DATE:	02/20/2	sity Automotive 9 <b>METER 2 - N:</b> 2002 631R621157998	0
JOB CODE		JOB DESCRIPTION	<u>ST</u>	<u>AT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MAT	ERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFOR	M SAFETY INSPECTION	I DO	N	0	Ν	GARAGE	2.00	\$115.00	\$0.00	:	\$0.00	\$115.00
66-PM-PMA	PERFOR	M OIL CHANGE	DC	N	Р	N	GARAGE	0.31	\$17.83	\$28.15	:	\$0.00	\$45.98
JOB COUN	T: 2				WO	RK ORI	DER TOTAL	: 2.31	13	32.83	28.15	0.00	160.98
Job Code		Job Description			<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		10	260422	!	11	/29/2012 07:00:00	11/29/2	012 07:18:36		0.31	\$17.83
66-79-003	PERFORM S	SAFETY INSPECTION		10	260422	!	11	/29/2012 07:18:36	11/29/2	012 09:18:36		2.00	\$115.00
												LABOR	132.83
Job Code		Job Description				Part No	<u>.</u>	Des	cription		Unit Pric	e Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		BA	ALB142	8	LU	JBE SPIN-ON FILT	ER		5.	11 1	\$5.11
66-PM-PMA	PERFORM (	OIL CHANGE		10	W30SS	;	10	0W30 HAV SEMI-S	SYNTHETIC (	OIL	0.	12 192	\$23.04
												PARTS	28.15

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 12439

**Work Order Notes** 

(GMANNING) PM, SAFETY INSPECTION

**Job Notes** 

66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) ANNUAL BUS INSPECTION COMPLETE NO PROBLEMS FOUND

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include: Part 10W-30 OIL BULK Qty 176 Cost 0.06 Part 1061 FILTER-OIL Qty 1 Cost 3.41 (LPATE) PM BY RS,GM/GM

UNIT NO:		232451	2003 CHEV	/ROLI	ET BL	UE BIF	RD		WORK (	ORDER N	<b>O</b> :	13879		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRE		COMPL	ED DAT	DATE:	05/23/20 05/23/20	013 13:05:07 013 07:37:34 013 07:37:36		- M: 22699 CE DATE:	02/20/2	sity Automoti <b>METER 2 - N</b> 2002 331R6211579	: 0	es
JOB CODE	<u> </u>	JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABO	R MAT	ERIAL	COMMERCI	AL TO	TAL COST
03-32-002	REPLAC	E NEW BATTERY		DON	0	N	GARAGE	1.18	\$68.06	\$86.01		\$0.00	\$154.	07
03-34-002	REPLAC	E NEW LAMPS-RE	EAR,TAIL,STO	DON	0	N	GARAGE	0.60	\$34.50	\$1.04		\$0.00	\$35.5	4
66-79-027	PERFOR	RM ANNUAL SCHO	OL BUS INSP	DON	0	N	GARAGE	0.12	\$6.85	\$0.00		\$0.00	\$6.85	
66-PM-PMA	_	RM OIL CHANGE		DON	Р	N	GARAGE		\$6.05	\$42.65		\$0.00	\$48.7	
JOB COUN						RK ORI	DER TOTAL			15.46	129.70	*	.00	245.16
			_						•					
<b>Job Code</b> 03-34-002	DEDLACE N	<b>Job Descript</b> NEW LAMPS-REAR,T.		ETC 1		ployee		<b>Start</b> 5/21/2013 07:00:00	05/21/2	Finish 013 07:36:00		<u>Quanti</u>	<u>ty To</u> .60	otal Cost \$34.50
		,		,										•
03-34-002		IEW LAMPS-REAR,T						5/21/2013 07:00:00		013 07:18:00		•	.30)	(\$17.25)
03-34-002	REPLACE N	IEW LAMPS-REAR,T	AIL,STOP,TURN,	ETC 1	1338644		0:	5/21/2013 07:00:00	05/21/2	013 07:18:00		0	.30	\$17.25
66-79-027	PERFORM	ANNUAL SCHOOL BU	JS INSPECTION	1	1338644		0:	5/21/2013 15:00:07	05/21/2	013 15:00:14		0	.00	\$0.11
66-79-027	PERFORM	ANNUAL SCHOOL BU	JS INSPECTION	1	1338644		0	5/20/2013 14:36:24	05/20/2	013 14:43:26		0	.12	\$6.74
03-32-002	REPLACE N	IEW BATTERY		1	1338644		0:	5/20/2013 13:24:54	05/20/2	013 14:35:55		1	.18	\$68.06
66-PM-PMA	PERFORM	OIL CHANGE		1	1338644		0:	5/20/2013 13:17:46	05/20/2	013 13:24:05		C	.11	\$6.05
												LABO	₹	115.46
Job Code		Job Descript	<u>tion</u>			Part No	<u>.</u>	Des	cription		Unit Pric	e Quanti	t <u>y To</u>	otal Cost
03-34-002	REPLACE N	NEW LAMPS-REAR,T	AIL,STOP,TURN,	ETC 1	157		В	ULB-BRAKE/TURI	١		0.5	55	1	\$0.55
03-34-002	REPLACE N	NEW LAMPS-REAR,T	AIL,STOP,TURN,	ETC 1	94		В	ULB-TAG/MARKE	₹		0.4	49	1	\$0.49
66-PM-PMA	PERFORM	OIL CHANGE		Т	20		Т	ECHRON 200Z FU	JEL ADDITIVE	Ξ	12.	11	1	\$12.11
03-32-002	REPLACE N	IEW BATTERY		7	8DT		В	ATTERY DUAL BC	I 34/78 800 C	CA	86.	01	1	\$86.01
03-32-002	REPLACE N	IEW BATTERY		7	81		В	ATTERY BCI 78 77	0 CCA		76.	92	(1)	(\$76.92)
03-32-002	REPLACE N	IEW BATTERY		7	81		В	ATTERY BCI 78 77	0 CCA		76.	92	1	\$76.92
66-PM-PMA	PERFORM	OIL CHANGE		1	0W30SS	;	1	0W30 HAV SEMI-S	SYNTHETIC (	OIL	0.	12	192	\$23.04
66-PM-PMA	PERFORM	OIL CHANGE		В	BALB142	8	L	UBE SPIN-ON FILT	ΓER		7.	50	1	\$7.50
												PARTS	3	129.70

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 13879

**Work Order Notes** 

(LPATE) PM-PERFORM ANNUAL BUS INSPECTION

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BATTERY HAD TO JUMP WOULD NOT STAY RUNNING

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED RIGHT FRONT MARKER LIGHT AND LEFT REAR BRAKE LIGHT. RECHECKED OK

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) CANCELLED DID NOT ROTATE TIRES.

66-79-027 - PERFORM ANNUAL SCHOOL BUS INSPECTION

(LPATE) ANNUAL INSPECTION COMPLETE. DRIVER WILL REINSTALL FIRST AID KIT IS AT THEIR LOCATION.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 1061 FILTER-OIL Qty 1 Cost 3.41 (LPATE) PM BY RS/SH

## The University of Alabama

# Work Order Charge Detail

UNIT NO:		232451 20	003 CHEVROL	ET BLU	E BIR	RD			WORK OR	DER NO	: 16	012	
USING DEPT	Γ ΝΟ:	208185	OPENI	D DATE:		02/06/201	4 13:47:30	)	LOCATION:	GARAGE	- University	/ Automotive S	Services
WO STATUS	:	CLOSED	COMP	ETED D	ATE:	02/07/201	4 07:08:11		METER 1 - M	24078	ME	TER 2 - N:	0
WO VISIT RE	EASON:	SCHEDULED	CLOSE	D DATE:		02/07/201	4 07:08:13	3	IN-SERVICE	DATE:	02/20/200	02	
TECH SPEC	NO:	03BUSBLUEBIRD	2003 Chevrole	et Blue Bir	d Bus				UNIT SERIAL	NO:	1GBJG31	IR621157998	
JOB CODE		JOB DESCRIPTION	STAT	RSN \	<u>WRTY</u>	JOB LOC	LABOR I	HRS	LABOR	MATE	RIAL CO	OMMERCIAL	TOTAL COST
03-51-046	REPLAC	E NEW KEY BLANK(S	S) DON	0	N	GARAGE		0.00	\$0.00	\$2.55	\$0.	00	\$2.55
JOB COUNT	Г: 1			WOR	K ORD	ER TOTAL:		0.00	0.0	0	2.55	0.00	2.5
Job Code		Job Description	<u>l</u>	<u>P</u>	art No.	<u>.</u>		Des	<u>cription</u>	<u> </u>	Jnit Price	Quantity	Total Cost
03-51-046	REPLACE N	NEW KEY BLANK(S)	ŀ	EY BLAN	(	KE'	Y BLANK				2.55	1	\$2.5
												PARTS	2.5

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 16012

**Work Order Notes** 

(LPATE) KEITH REQUESTED AN EXTRA KEY

**Job Notes** 

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) CUT 1 KEY

Page:1

# Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		232451	2003 CHEV	/ROL	ET BL	UE BIF	RD		WORK OF	RDER NO	): 1	1607	
USING DEP WO STATUS WO VISIT RI TECH SPEC	S: EASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	•	COMP	ED DATI LETED I ED DATI et Blue E	DATE: E:	07/07/20 07/07/20	08 10:24:10 08 13:52:01 08 13:52:03	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 15317 DATE:	N 02/20/2	ity Automotive 9 <b>METER 2 - N:</b> 1002 31R621157998	0
JOB CODE		JOB DESCRIPTIO	<u>DN</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL (	COMMERCIAL	TOTAL COST
03-01	REPLAC	E NEW AIR CONDIT	TIONING, HE	DON	Ο	Ν	GARAGE	0.00	\$0.18	\$17.29	\$	60.00	\$17.47
03-13-001	REPLAC	E NEW FRONT BRA	AKES & ROT	DON	0	Ν	GARAGE	2.39	\$107.54	\$111.40	\$	60.00	\$218.94
03-17	REPLAC	E NEW TIRES, TUB	SES, LINERS	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$	8809.20	\$809.20
16-17	TRANSP	ORT TIRES, TUBES	S, LINERS &	DON	0	N	GARAGE	88.82	\$3,996.69	\$0.00	\$	60.00	\$3,996.69
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	0.31	\$13.95	\$22.86	\$	60.00	\$36.81
JOB COUN	T: 5				wo	RK ORI	DER TOTAL	: 91.52	4,118.	36	151.55	809.20	5,079.11
<b>Job Code</b> 03-17	REPLACE N	<u>Job Descripti</u> IEW TIRES, TUBES, LI		ES 1	<u>V</u> 1078579	endor N		Invoice No.	<u>Purchas</u> 0001910	se Order N	<u>o.</u>	COMML	Total Cost \$809.20 809.20
Job Code		Job Description	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
16-17	TRANSPOR	T TIRES, TUBES, LINE	ERS & VALVES	1	1128904		07	7/04/2008 14:30:00	07/07/200	8 07:01:20		64.52	\$2,903.50
16-17	TRANSPOR	T TIRES, TUBES, LINE	ERS & VALVES	1	1128904		07	7/04/2008 09:30:00	07/04/200	8 14:15:00		4.75	\$213.75
16-17	TRANSPOR	T TIRES, TUBES, LINE	ERS & VALVES	1	1128904		07	7/03/2008 14:30:00	07/04/200	8 09:15:00		18.75	\$843.75
16-17	TRANSPOR	T TIRES, TUBES, LINE	ERS & VALVES	1	1128904		07	7/03/2008 13:27:25	07/03/200	8 14:15:00		0.79	\$35.69
03-01	REPLACE N	IEW AIR CONDITIONIN	NG, HEAT, VEN	T 1	1088474		07	7/03/2008 14:01:18	07/03/200	8 14:01:32		0.00	\$0.18
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	1	1089300		07	7/03/2008 11:27:24	07/03/200	8 13:39:17		2.20	\$98.91
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	1	1128904		07	7/03/2008 13:15:55	07/03/200	8 13:27:25		0.19	\$8.63
66-PM-PMA	PERFORM (	OIL CHANGE		1	1088474		07	7/03/2008 10:25:00	07/03/200	8 10:43:36		0.31	\$13.95
												LABOR	4118.36
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	Des	cription		Unit Price	e Quantity	Total Cost
03-01	REPLACE N	IEW AIR CONDITIONIN	NG, HEAT, VEN	Т 3	8005730	1	A	FILTER			17.2	29 1	\$17.29
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	8	SKF21756	3	FF	RONT GREASE SE	EAL		2.3	36 2	\$4.71
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	F	RABATD4	59C	FF	RONT BRAKE PAD	os		103.2	26 1	\$103.26
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	(	C111		RI	ED BRAKE CLEAN	IER		3.4	3 1	\$3.43

The University of Alabama

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB1428	LUBE SPIN-ON FILTER	7.02	1	\$7.02
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.09	176	\$15.84
					PARTS	151.55

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 1607

**Work Order Notes** 

(RWINTERS) PM, NEEDS 6 TIRES, ALIGNMENT, CHECK AC FILTERS, BRAKES SQUEAK.

Job Notes

03-01 - REPLACE NEW AIR CONDITIONING, HEAT, VENT

(RWINTERS) REPLACED THE AC FILTER.

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(RWINTERS) CHRIS PACKED BEARINGS, REPACED SEALS ,PADS, AND ADJUSTED UP REAR SHOES. MICHAEL TURNED ROTORS,

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(RWINTERS) GCR REPLACED ALL 6 TIRES AND ALIGNED. P0015280

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(RWINTERS) TAKEN TO GCR.

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS) PM BY JE.

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO:	232451	2003 CHEVROLET BLUE BIRD	WORK ORDER NO:	16812
USING DEPT NO:	208185	OPENED DATE: 05/0	1/2014 13:33:33 <b>LOCATION:</b> GARAGE - Uni	versity Automotive Services
WO STATUS:	CLOSED	COMPLETED DATE: 05/2	9/2014 12:00:18 <b>METER 1 - M:</b> 24497	<b>METER 2 - N:</b> 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE: 05/2	9/2014 12:00:19 <b>IN-SERVICE DATE</b> : 02/3	20/2002

WO VISIT REASON: SCHEDULED CLOSED DATE: 05/29/2014 12:00:19 IN-SERVICE DATE: 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<b>MATERIAL</b>	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	0	Ν	GARAGE	2.00	\$115.00	\$557.14	\$0.00	\$672.14
03-34-003	REPLACE NEW SIGNAL, PARKING, & BA	DON	0	Ν	GARAGE	0.90	\$51.75	\$4.76	\$0.00	\$56.51
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$36.42	\$0.00	\$50.80
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	0	N	GARAGE	1.00	\$57.50	\$615.54	\$0.00	\$673.04
14-79	INSTALL SAFETY DEVICES	DON	0	N	GARAGE	1.00	\$57.50	\$389.05	\$0.00	\$446.55
14-79-021	INSTALL SCHOOL BUS STOP ARM ASS'	DON	0	N	GARAGE	3.00	\$172.50	\$434.36	\$0.00	\$606.86
66-79-027	PERFORM ANNUAL SCHOOL BUS INSP	DON	Р	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	1.98	\$113.75	\$73.34	\$0.00	\$187.09

JOB COUNT: 8 WORK ORDER TOTAL: 11.13 639.88 2,110.61 0.00 2,750.49

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	<b>Quantity</b>	<b>Total Cost</b>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11568366	05/27/2014 07:00:00	05/27/2014 09:00:00	2.00	\$115.00
03-51-038	REPLACE NEW WIPER BLADES	11568366	05/27/2014 07:00:00	05/27/2014 07:15:00	0.25	\$14.38
03-34-003	REPLACE NEW SIGNAL, PARKING, & BACKUP LAMPS	11568366	05/27/2014 07:15:00	05/27/2014 08:09:00	0.90	\$51.75
66-79-027	PERFORM ANNUAL SCHOOL BUS INSPECTION	11568366	05/27/2014 07:00:00	05/27/2014 08:00:00	1.00	\$57.50
14-79-017	INSTALL SCHOOL BUS CROSSING ARM	11568366	05/27/2014 13:00:00	05/27/2014 15:00:00	(2.00)	(\$115.00)
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	11568366	05/27/2014 10:00:00	05/27/2014 13:00:00	3.00	\$172.50
14-79-017	INSTALL SCHOOL BUS CROSSING ARM	11568366	05/27/2014 13:00:00	05/27/2014 15:00:00	2.00	\$115.00
14-79	INSTALL SAFETY DEVICES	11568366	05/27/2014 08:00:00	05/27/2014 09:00:00	1.00	\$57.50
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11568366	05/27/2014 09:00:00	05/27/2014 10:00:00	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11568366	05/09/2014 09:15:56	05/09/2014 11:14:38	1.98	\$113.75
					LABOR	639.88

Job CodeJob DescriptionPart No.DescriptionUnit PriceQuantityTotal Cost14-79INSTALL SAFETY DEVICESMSD65007580EXIT DECALS3.752\$7.50

<b>Job Code</b> 14-79	<u>Job Description</u> INSTALL SAFETY DEVICES	<u>Part No.</u> SMA5507K	<u>Description</u> STOP ARM BLADE KIT	Unit Price 145.35	<b>Quantity</b> 1	Total Cost \$145.35
14-79	INSTALL SAFETY DEVICES	CSFS203045	FIRST AID KIT	85.20	1	\$85.20
14-79	INSTALL SAFETY DEVICES	CSFFK200900	BODY FLUID CLEAN KIT	28.68	1	\$28.68
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SPADE	SPADE TERMINAL	4.49	5	\$22.43
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	PIC2270G	CONNECTORS	25.72	1	\$25.72
14-79	INSTALL SAFETY DEVICES	RCP2541BLA	FIRE RESISTANT TRASH CAN	71.95	1	\$71.95
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SHIPPING	SHIPPING AND HANDLING	29.63	1	\$29.63
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SHIPPING	SHIPPING AND HANDLING	12.00	1	\$12.00
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SCREWS	SELF TAPING SCREWS	0.33	10	\$3.30
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SCREWS	SELF TAPING SCREWS	0.38	10	\$3.75
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKFBR35	FRONT INNER BEARINGS	21.45	2	\$42.90
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF15103S	FRONT OUTER BEARINGS	28.05	2	\$56.10
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABPGD459M	FRONT BRAKE PADS	63.30	1	\$63.30
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RAM56593R	HUB/ROTOR ASSY	173.60	2	\$347.19
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PTX20353	DISC BRAKE LUBE	7.91	1	\$7.91
14-79	INSTALL SAFETY DEVICES	SHIPPING	SHIPPING AND HANDLING	18.00	1	\$18.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PTX24240	BLUE LOCTITE 1.22 OZ	33.71	1	\$33.71
66-PM-PMA	PERFORM OIL CHANGE	VAL616	GREASE	17.57	1	\$17.57
66-PM-PMA	PERFORM OIL CHANGE	46573	FILTER-AIR	25.23	1	\$25.23
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	SKF21756	FRONT GREASE SEAL	3.02	2	\$6.03
03-51-038	REPLACE NEW WIPER BLADES	40722A	WIPER BLADE 22"	18.21	(1)	(\$18.21)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	M420C1B2	CLEAR STROBE LIGHT ASSY	146.40	1	\$146.40
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SMA78106	CROSSING ARM BASE	385.53	1	\$385.53
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SMA68150	YELLOW CROSSING ARM ROD	63.61	1	\$63.61
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SMA8070	BUMPER MOUNTING KIT	126.31	1	\$126.31
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	1947555	SWITCH	16.03	1	\$16.03
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	SMA8101	ELECTRO MAGNET KIT	123.29	1	\$123.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	CONNECTOR	CONNECTOR-NYLON	0.84	2	\$1.68
03-51-038	REPLACE NEW WIPER BLADES	40722A	WIPER BLADE 22"	18.21	2	\$36.42
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	PIC2238C	HEAT SHRINK CONNECTORS	5.16	1	\$5.16
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	PIC81121S	12 GAGE RED WIRE	51.37	1	\$51.37
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	LITUCB10	LITTLEFUSE	11.67	1	\$11.67
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	LITUCB10	LITTLEFUSE	6.65	1	\$6.65
14-79-021	INSTALL SCHOOL BUS STOP ARM ASSY	PIC5141A	3/8 CONVOLUTED TUBING 50FT	0.61	25	\$15.37
FleetFocus M5	5 - WODETAIL - Work Order Detail v20.0					Page:2

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
14-79	INSTALL SAFETY DEVICES	SHB8705	SEAT BELT CUTTER	14.39	2	\$28.77
03-51-038	REPLACE NEW WIPER BLADES	40722A	WIPER BLADE 22"	18.21	1	\$18.21
66-PM-PMA	PERFORM OIL CHANGE	BALB1428	LUBE SPIN-ON FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	10W30SS	10W30 HAV SEMI-SYNTHETIC OIL	0.12	192	\$23.04
03-34-003	REPLACE NEW SIGNAL, PARKING, & BACKUP LAMPS	3 194	BULB-TAG/MARKER	0.29	1	\$0.29
03-34-003	REPLACE NEW SIGNAL, PARKING, & BACKUP LAMPS	1156DC	BULB-(BUSES ONLY)-MINITURE	2.24	2	\$4.47
14-79	INSTALL SAFETY DEVICES	SB6	EMER EXIT DECAL RED 2"	3.60	1	\$3.60
					PARTS	2110.61

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 16812

## **Work Order Notes**

(LPATE) DO ANNUAL BUS INSPECTION-PM- REPLACE WIPERS-REPLACE FRONT BRAKES-INSTALL CROSSING ARM ASSY-MISSING SEAT BELT CUTTERS-TRASH CAN-TRIANGLES-FIRST AID KIT AND BODY FLUID KIT . INSTALL A STROBE LIGHT

### **Job Notes**

### 03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LPATE) REPLACED FRONT PADS, ROTORS, AND BEARINGS WITH HUB SEALS.

### 03-34-003 - REPLACE NEW SIGNAL, PARKING, & BACKUP LAMPS

(LPATE) REPLACED RIGHT REAR MARKER LIGHTS ON TOP

### 03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

### 14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LPATE) INSTALLED CLEAR STROBE LIGHT ASSY ON TOP OF BUS. HAD TO MOUNT AND WIRE SWITCH IN ALSO.

### 14-79 - INSTALL SAFETY DEVICES

(RWINTERS) INSTALLED 2 SEAT BELT CUTTERS, MOUNTED TRIANGLES, TRASH CAN AND FIRE EXTINGUISHER, MOUNTED NEW FIRST AID KIT AND BODY FLUID KIT. INSTALLED ALL EMERGENCY EXIT LABELS

### 14-79-017 - INSTALL SCHOOL BUS CROSSING ARM

### 14-79-021 - INSTALL SCHOOL BUS STOP ARM ASSY

(LPATE) INSTALLED CROSSING ARM ASSY AND ASSOCIATED WIRING. INSTALLED CROSSING ARM MAGNET AND WIRING. ALSO REPLACED STOP SIGN ASSY

### 66-79-027 - PERFORM ANNUAL SCHOOL BUS INSPECTION

(LPATE) ANNUAL BUS INSPECTION COMPLETE. ALL NECESSARY REPAIRS COMPLETED. INSPECTION SHEETS ATTACHED.

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include: Part 1061 FILTER-OIL Qty 1 Cost 3.41 (LPATE) PM BY CA-REPLACED AIR FILTER

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

232451 **UNIT NO:** 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 17353 **USING DEPT NO:** 208185 **OPENED DATE:** 06/20/2014 09:49:55 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 06/25/2014 14:07:27 COMPLETED DATE: METER 1 - M: 25056 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 06/25/2014 14:07:29 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 COMMERCIAL TOTAL COST JOB CODE **MATERIAL** JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS LABOR 06-13 **INSPECT BRAKES** DON 0 **GARAGE** 0.26 \$14.66 \$0.00 Ν \$0.00 \$14.66 15-13-001 WARRANTY FRONT BRAKES & ROTOR: DON W **GARAGE** 0.00 \$0.00 \$89.58 \$0.00 \$89.58 JOB COUNT: 2 **WORK ORDER TOTAL:** 0.26 14.66 89.58 0.00 104.24 **Job Code Job Description** Employee No. Start **Finish** Quantity **Total Cost** 06/20/2014 13:58:36 06-13 **INSPECT BRAKES** 11568366 06/20/2014 14:13:54 0.26 \$14.66 LABOR 14.66 **Unit Price Total Cost Job Code Job Description** Part No. Description Quantity 9.23 \$9.23 15-13-001 WARRANTY FRONT BRAKES & ROTORS MMM32115 PROD SHEET 15-13-001 WARRANTY FRONT BRAKES & ROTORS RABATD459M SUPER PREMIUM FRONT PADS 80.35 \$80.35 **PARTS** 89.58

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 17353

**Work Order Notes** 

(LPATE) PER MARCUS BRAKES ARE GETTING VERY HOT SMELL LIKE BURNING

### **Job Notes**

### 06-13 - INSPECT BRAKES

(LPATE) CHECKED BRAKES FRONT PADS ARE GLAZED, CALLED RAYBESTOS PADS INSTALLED WERE PREMIUM BUT BUS NEEDED SUPER PREMIUM FOR HEAVY DUREMOVE AND REPLACE PADS AS WARRANTY NO LABOR BILL FOR NEW PADS AND SAND PAPER ONLY. THERE WILL BE A BILLING ADJUSTMENT CREDIT FOR PREVICE PADS.

## 15-13-001 - WARRANTY FRONT BRAKES & ROTORS

(LPATE) REMOVED PADS RETURNED AS DEFECTIVE. INSTALLED SUPER PRIUM PADS, SCUFFED ROTORS, RECHECKED EVERYTHNG OK. RANDALL TEST DROVE WITMARCUS.

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

**PARTS** 

232451 **UNIT NO:** 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 17424 **USING DEPT NO:** 208185 **OPENED DATE:** 06/26/2014 13:38:42 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 06/30/2014 08:50:49 **WO STATUS:** COMPLETED DATE: METER 1 - M: 25394 METER 2 - N: **SCHEDULED** 06/30/2014 08:50:51 WO VISIT REASON: **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 COMMERCIAL TOTAL COST **MATERIAL** JOB CODE JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS LABOR 03-32-002 REPLACE NEW BATTERY DON 0 F **GARAGE** 4.10 \$235.77 \$86.01 \$0.00 \$321.78 JOB COUNT: 1 WORK ORDER TOTAL: 4.10 235.77 86.01 0.00 321.78 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 03-32-002 REPLACE NEW BATTERY 11397026 06/27/2014 07:18:44 06/27/2014 09:15:00 1.94 \$111.42 03-32-002 REPLACE NEW BATTERY 11397026 2.16 06/27/2014 09:30:00 06/27/2014 11:39:45 \$124.34 **LABOR** 235.76 **Job Code Job Description** Part No. **Unit Price** Quantity **Total Cost** Description 78DT 1 \$86.01 03-32-002 REPLACE NEW BATTERY BATTERY DUAL BCI 34/78 800 CCA 86.01 03-32-002 REPLACE NEW BATTERY 78DT 86.01 (1) (\$86.01)BATTERY DUAL BCI 34/78 800 CCA 03-32-002 REPLACE NEW BATTERY 78DT BATTERY DUAL BCI 34/78 800 CCA 86.01 1 \$86.01 03-32-002 78DT 86.01 \$86.01 REPLACE NEW BATTERY BATTERY DUAL BCI 34/78 800 CCA 03-32-002 REPLACE NEW BATTERY 78DT BATTERY DUAL BCI 34/78 800 CCA 86.01 (1) (\$86.01)

86.01

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 17424

**Work Order Notes** 

(LPATE) PER MARCUS BATTERY KEEPS GOING DEAD

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(LPATE) CHECKED OUT, REPLACED THE BATTERY, RECHECKED CHARGING SYSTEM OK REMOVED AND INSTALLED A 34/78A BATTERY.

(LPATE) Visit Reason Changed On 6/27/2014 11:39:30 AM By LPATE

(RWINTERS) BATTERY IS WARRANTY-

UNIT NO:		232451	2003 CHE\	/ROLE	T BLU	JE BIR	RD		WORK OF	RDER NO	): '	18904	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED [	DATE:	12/01/20	4 09:19:52 4 09:24:37 14 09:24:38	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 27581 <b>DATE</b> :	02/20/2	sity Automotive S <b>METER 2 - N:</b> 2002 331R621157998	Services 0
JOB CODE	<del>_</del>	JOB DESCRIPTION  M OIL CHANGE	<u>N</u>	STAT DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.89	<b>LABOR</b> \$51.16	<b>MATE</b> \$37.29		COMMERCIAL \$0.00	TOTAL COST \$88.45
JOB COUN	IT: 1						DER TOTAL:				37.29	0.00	
Job Code 66-PM-PMA	PERFORM (	<b>Job Descripti</b> on DIL CHANGE	<u>on</u>	11	<u><b>Em</b></u> 1074414	<u>ployee</u>		<u>Start</u> /26/2014 09:37:51		<u>inish</u> 4 10:31:14		<u>Quantity</u> 0.89	**Total Cost
Job Code		Job Description	on_		<u> </u>	Part No	<u>.</u>	Des	cription		Unit Pric	LABOR  e Quantity	51.16 Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		11	1562588		OI	L DRAIN PLUG M	12		3.8	37 1	\$3.87
66-PM-PMA	PERFORM (	OIL CHANGE		10	)W30SS		10	W30 HAV SEMI-S	SYNTHETIC OIL		0.1	14 192	\$25.92
66-PM-PMA	PERFORM (	OIL CHANGE		В	ALB1428	3	LU	BE SPIN-ON FILT	ER		7.5	50 1	\$7.50
												PARTS	37.29

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 18904

**Work Order Notes** 

(GMANNING) PM

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include: Part 1061 FILTER-OIL Qty 1 Cost 3.41 (GMANNING) PM BY NT/SH

**UNIT NO:** 

**Job Code** 

03-02-064

03-02-064

03-02-064

232451

**Job Description** 

REPLACE NEW DOOR PANEL/ARMREST

REPLACE NEW DOOR PANEL/ARMREST

REPLACE NEW DOOR PANEL/ARMREST

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

Quantity

**PARTS** 

1

(1)

**Total Cost** 

\$121.40

\$97.12

97.12

(\$121.40)

20129

**Unit Price** 

121.40

97.12

121.40

**WORK ORDER NO:** 

Description

**USING DEPT NO:** 208185 **OPENED DATE:** 04/28/2015 09:57:06 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 04/29/2015 08:09:09 **METER 1 - M:** 28158 **COMPLETED DATE: METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 04/29/2015 08:09:10 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 JOB CODE JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT RSN WRTY LABOR 03-02-064 REPLACE NEW DOOR PANEL/ARMRES DON 0 **GARAGE** \$97.12 0.30 \$17.25 \$0.00 \$114.37 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.30 17.25 97.12 0.00 114.37 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 03-02-064 REPLACE NEW DOOR PANEL/ARMREST 10260422 04/28/2015 09:58:07 04/28/2015 10:16:07 0.30 \$17.25 **LABOR** 17.25

**ARMREST** 

**ARMREST** 

**ARMREST** 

Part No.

12479875

12479875

12479875

2003 CHEVROLET BLUE BIRD

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 20129

**Work Order Notes** 

(LPATE) DRIVER SIDE ARMREST IS BROKEN

**Job Notes** 

03-02-064 - REPLACE NEW DOOR PANEL/ARMREST

(LPATE) REPLACED DRIVER ARMREST

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

**UNIT NO:** 232451 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 2053 **USING DEPT NO:** 208185 **OPENED DATE:** 09/29/2008 07:11:19 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 09/29/2008 07:24:01 COMPLETED DATE: **METER 1 - M:** 15350 **METER 2 - N**: 0 **WO VISIT REASON:** UNSCHEDULED 09/29/2008 07:24:04 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 COMMERCIAL TOTAL COST JOB CODE **STAT** RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL** JOB DESCRIPTION 03-51-046 DON 0 Ν **GARAGE** 0.00 \$0.00 \$3.00 \$0.00 \$3.00 REPLACE NEW KEY BLANK(S) JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 3.00 0.00 3.00 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 2 \$3.00 03-51-046 REPLACE NEW KEY BLANK(S) **KEY BLANK KEY BLANK** 1.50 **PARTS** 3.00

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 2053

**Work Order Notes** 

(LPATE) WARREN JOHNSON REQUESTED CUT 2 NEW KEYS--THERE WAS 0 MILES IN HAD TO ESTIMATE MILEAGE

**Job Notes** 

03-51-046 - REPLACE NEW KEY BLANK(S)

(LPATE) RANDALL CUT 2 NEW KEYS

UNIT NO:	232451	2003 CHEVROLI	ET BLUE BI	RD		WORK ORDER N	O: 21	981	
USING DEPT N WO STATUS: WO VISIT REA TECH SPEC N	CLOSED ASON: SCHEDULED	COMPI CLOSE	ED DATE: LETED DATE: ED DATE: et Blue Bird Bus	11/13/201 11/13/201	5 11:08:33 5 07:41:40 5 07:41:41	LOCATION: GARAG METER 1 - M: 30962 IN-SERVICE DATE: UNIT SERIAL NO:	ME 02/20/200	ETER 2 - N:	Services 0
JOB CODE	JOB DESCRIPT	ION STAT	RSN WRTY		LABOR HRS	LABOR MAT	ERIAL CO	OMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O N	GARAGE	0.50	\$28.75 \$59.75	\$0.	.00	\$88.50
JOB COUNT:	1		WORK OR	DER TOTAL:	0.50	28.75	59.75	0.00	88.50
Job Code	Job Descrip	tion			044				
		<u>illon</u>	<u>Employee</u>	<u> NO.</u>	<u>Start</u>	<u>Finish</u>		<b>Quantity</b>	Total Cost
03-32-002 RE	EPLACE NEW BATTERY		0260422		<u>Start</u> 12/2015 11:09:10	<u>Finish</u> 11/12/2015 11:39:10		Quantity 0.50	<u>Total Cost</u> \$28.75
03-32-002 RI	<u></u>				<del></del>				
03-32-002 Rf	<u></u>	1		11/	12/2015 11:09:10		Unit Price	0.50	\$28.75
Job Code	EPLACE NEW BATTERY	1 vition	0260422		12/2015 11:09:10	11/12/2015 11:39:10 cription	Unit Price 59.75	0.50  LABOR  Quantity	\$28.75 <b>28.75</b>

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 21981

**Work Order Notes** 

(LISAPATE) PER DRIVER KEEP HAVING TO JUMP START IN THE MORNINGS

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) FAILED LOAD TEST-REPLACED BATTERY-ALT CHARGING AT 14.5V

UNIT NO:		232451 20	003 CHEVROL	ET BL	UE BIF	RD		WORK O	RDER NO	): 2:	275	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED UNSCHEDULED 03BUSBLUEBIRD	COMF	ED DAT	DATE: E:	11/03/20 11/03/20	08 08:15:29 08 10:53:31 08 10:53:31	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 15351 E DATE:	<b>M</b> 02/20/20		Services 0
JOB CODE	_	JOB DESCRIPTION	STAT		WRTY		LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL COST
15-32-002	WARRAN	NTY BATTERY	DON	W	J	GARAGE	0.50	\$28.75	\$0.00	\$0	0.00	\$28.75
66-79-002	PERFOR	M SERVICE CALL	DON	В	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
JOB COUN	IT: 2			W	ORK OR	DER TOTAL	: 1.50	86	.25	0.00	0.00	86.25
Job Code		Job Description		<u>E</u> 1	mployee	No.	<u>Start</u>	į	Finish		Quantity	Total Cost
15-32-002	WARRANTY	BATTERY		1112890	4	1′	1/03/2008 10:00:00	11/03/200	08 10:30:00		0.50	\$28.75
66-79-002	PERFORM S	SERVICE CALL		1112890	4	1′	1/03/2008 09:00:00	11/03/200	08 10:00:00		1.00	\$57.50
03-32-002	REPLACE N	IEW BATTERY		1112890	4	11	1/03/2008 10:00:00	11/03/200	08 10:30:00		0.50	\$28.75
03-32-002	REPLACE N	IEW BATTERY		1112890	4	1′	1/03/2008 10:00:00	11/03/200	08 10:30:00		(0.50)	(\$28.75)
											LABOR	86.25
Job Code		Job Description			Part No	<u>).</u>	Des	cription		<u>Unit Price</u>	Quantity	Total Cost
03-32-002	REPLACE N	IEW BATTERY		778MF		В	ATTERY			109.02	2 1	\$109.02
03-32-002	REPLACE N	IEW BATTERY		778MF		В	ATTERY			109.02	2 (1)	(\$109.02)
											PARTS	0.00

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 2275

**Work Order Notes** 

(AJONES) SERVICE CALL DEAD BATTERY -BREWER PORCH

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(AJONES) REPLACED BATTERY- WARRANTY

15-32-002 - WARRANTY BATTERY

(AJONES) REPLACE BATTERY - NO CHARGE - UNDER WARRANTY

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL TO BREWER PORCH DEAD BATTERY

UNIT NO:		232451 2	003 CHEVR	OLE.	T BL	UE BIF	RD		WORK (	ORDER NO	): 2	3144		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: EASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	СО	MPLE OSEC	DATI	DATE:	04/19/20	16 13:08:50 16 07:40:46 16 07:40:48		- M: 31257 CE DATE:	<b>M</b> 02/20/20		Services 0	
JOB CODE		JOB DESCRIPTION	<u>s</u> 1	<u>rat</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABO	R MAT	ERIAL C	OMMERCIAL	TOTAL CO	)ST
03-32-002	REPLAC	E NEW BATTERY	D	ON	0	N	GARAGE	0.50	\$28.75	\$0.00	\$0	0.00	\$28.75	
66-79-002	PERFOR	M SERVICE CALL	D	ON	В	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50	
JOB COUN	T: 2				wo	RK ORI	ER TOTAL	: 1.50	8	36.25	0.00	0.00	8	36.25
Job Code		Job Description	<u>1</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Co	<u>st</u>
66-79-002	PERFORM S	SERVICE CALL		113	397026		04	1/18/2016 13:11:37	04/18/2	016 14:11:37		1.00	\$	57.50
03-32-002	REPLACE N	EW BATTERY		113	397026		04	1/18/2016 13:11:15	04/18/2	016 13:41:15		0.50	\$2	28.75
66-79-002	PERFORM S	SERVICE CALL		102	260422		04	1/18/2016 13:09:29	04/18/2	016 13:39:29		(0.50)	(\$2	28.75)
66-79-002	PERFORM S	SERVICE CALL		102	260422		04	1/18/2016 13:09:29	04/18/2	016 13:39:29		0.50	\$2	28.75
												LABOR	8	86.25
Job Code		Job Description	<u>1</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Co	<u>st</u>
<b>Job Code</b> 03-32-002	REPLACE N	Job Description	<u>1</u>	78 <sup>-</sup>		Part No	=	<u>Des</u> ATTERY BCI 78 77			Unit Price 58.68		·	<u>st</u> 558.68
			1	78 <sup>-</sup>	1	Part No	B		0 CCA			3 1	\$ (\$5	

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 23144

**Work Order Notes** 

(LISAPATE) KEITH REQUESTED A SERVICE CALL TO BREWER PORCH

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(RWINTERS) REPLACED BATTERY WITH A USED ONE REMOVED FROM A VEHICLE THAT IS BEING USED AS SALAVAGED. ORIG. BATTERY TO BE CHARGED BACK UP.

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO:	232451	2003 CHEVROLET BLUE BIRD	WORK ORDER NO:	23550

**USING DEPT NO:** 208185 **OPENED DATE:** 05/31/2016 08:26:25 **LOCATION:** GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 06/10/2016 07:12:02
 METER 1 - M:
 31257
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 06/10/2016 07:12:04
 IN-SERVICE DATE:
 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<u>MATERIAL</u>	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	Р	Ν	GARAGE	0.03	\$1.96	\$0.18	\$0.00	\$2.14
03-34-022	REPLACE NEW STROBE LIGHT/BULB/N	DON	0	N	GARAGE	0.50	\$28.75	\$138.92	\$0.00	\$167.67
03-40-415	REPLACE NEW OIL COOLER LINES	DON	0	N	GARAGE	1.20	\$69.00	\$65.34	\$0.00	\$134.34
35-32	DIAGNOSE CRANKING SYSTEM	DON	0	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-027	PERFORM ANNUAL SCHOOL BUS INSP	DON	0	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	1.50	\$86.07	\$29.85	\$0.00	\$115.92

JOB COUNT: 6	WORK ORDER TOTAL:	5.73	329.53	234.29	0.00	563.82

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	<b>Quantity</b>	<b>Total Cost</b>
03-40-415	REPLACE NEW OIL COOLER LINES	11758845	06/08/2016 10:00:00	06/08/2016 11:12:00	1.20	\$69.00
35-32	DIAGNOSE CRANKING SYSTEM	11397026	06/08/2016 09:00:00	06/08/2016 09:30:00	0.50	\$28.75
66-79-027	PERFORM ANNUAL SCHOOL BUS INSPECTION	11397026	06/08/2016 07:00:00	06/08/2016 09:00:00	2.00	\$115.00
03-40-415	REPLACE NEW OIL COOLER LINES	11397026	06/08/2016 10:00:00	06/08/2016 11:12:00	1.20	\$69.00
03-40-415	REPLACE NEW OIL COOLER LINES	11397026	06/08/2016 10:00:00	06/08/2016 11:12:00	(1.20)	(\$69.00)
03-34-022	REPLACE NEW STROBE LIGHT/BULB/MOTOR/ASSY	11397026	06/08/2016 09:30:00	06/08/2016 10:00:00	0.50	\$28.75
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	05/31/2016 14:48:46	05/31/2016 14:50:49	0.03	\$1.96
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/31/2016 13:18:18	05/31/2016 14:48:07	1.50	\$86.07
					LABOR	329.53

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	1156	BULB-BACK UP	0.18	1	\$0.18
66-PM-PMA	PERFORM OIL CHANGE	BALB1428	LUBE SPIN-ON FILTER	2.46	1	\$2.46
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.75	1	\$2.75
66-PM-PMA	PERFORM OIL CHANGE	10W30SSQT	10W30 SEMI SYN QT. BOTTLE	3.19	6	\$19.14
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.75	1	\$2.75
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.75	1	\$2.75

## The University of Alabama

# Work Order Charge Detail

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
03-40-415	REPLACE NEW OIL COOLER LINES	DOR625151	OIL COOLER LINE	13.47	1	\$13.47
03-40-415	REPLACE NEW OIL COOLER LINES	DOR625152	OIL COOLER LINE	14.01	1	\$14.01
03-40-415	REPLACE NEW OIL COOLER LINES	GAH70665	3/8 HOSE HYD/OIL/AF	2.29	3	\$6.87
03-34-022	REPLACE NEW STROBE LIGHT/BULB/MOTOR/ASSY	ECC7965C	LED BEACON LIGHT	114.43	1	\$114.43
03-34-022	REPLACE NEW STROBE LIGHT/BULB/MOTOR/ASSY	5832813	AMBER ROCKER SWITCH	24.49	1	\$24.49
03-40-415	REPLACE NEW OIL COOLER LINES	15063809	AIR FILTER ADAPTER	30.99	1	\$30.99
				_	PARTS	234.29

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 23550

## **Work Order Notes**

(LISAPATE) PM-DO ANNUAL INSPECTION-CHECK FOR DRAW BATTERY KEEPS GOING DEAD

### **Job Notes**

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) REPLACED RIGHT REAR BACK UP LIGHT

03-34-022 - REPLACE NEW STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) REPLACED THE STROBE LIGHT AND AMBER SWITCH

03-40-415 - REPLACE NEW OIL COOLER LINES

(LISAPATE) REPLACED THE OIL COOLER LINES WIH NEW ONES, THREADED THE ADAPTERS WITH LOCKTITE. TESTED FOR LEAKS NONE FOUND

### 35-32 - DIAGNOSE CRANKING SYSTEM

(LISAPATE) CHECKED OUT, CHECKED FOR A DRAW, FOUND DRAW WAS COMING FROM THE STROBE LIGHT. AFTER REPLACING THE STROBE RECHECKED DRAW WAS GONE. ALSO REPAIRED THE EMERGENCY WINDOW SWITCH ON THE RIGHT SIDE, SCREWS WERE LOOSE CAUSING THE SWITCH TO NOT MAKE COMPLETE CONTACT AND GET A GROUND.

### 66-79-027 - PERFORM ANNUAL SCHOOL BUS INSPECTION

(LISAPATE) COMPLETED ANNAUL INSPECTION. SEE ATTACHED

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (LISAPATE) PM BY AY,SH/SH

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

02/20/2002

**IN-SERVICE DATE:** 

**UNIT NO:** 232451 **2003 CHEVROLET BLUE BIRD WORK ORDER NO:** 23762

**CLOSED DATE:** 

208185 **USING DEPT NO: OPENED DATE:** 06/27/2016 09:22:45 **LOCATION:** GARAGE - University Automotive Services

**WO STATUS:** CLOSED 06/27/2016 09:29:03 **COMPLETED DATE: METER 1 - M**: 32012 **METER 2 - N**: 0 **WO VISIT REASON:** UNSCHEDULED 06/27/2016 09:29:05

03BUSBLUEBIRD **TECH SPEC NO:** 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATERIAL	COMMER	CIAL TOTAL	COST
06-40-441	INSPECT OIL CONSUMPTION TEST	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00	
JOB COUNT	: 1		WC	RK ORI	DER TOTAL:	0.00	0	.00 0.	00	0.00	0.00

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

232451 **2003 CHEVROLET BLUE BIRD WORK ORDER NO: UNIT NO:** 23762

**Work Order Notes** 

(RWINTERS) DRIVER AT PUMPS, VAN LOW ON OIL

### **Job Notes**

## 06-40-441 - INSPECT OIL CONSUMPTION TEST

(RWINTERS) CHECKED OIL LEVEL, 1/2 WAY OF SAFE CROSSHATCH ON DIPSTICK. ADDED 1/2 QT. OF OIL (ALREADY CHARGED OUT), RECHECK OIL IS AT FULL MARK. NO LEAKS DETECTED, ADVISED DRIVER TO KEEP A CHECK ON THE OIL LEVEL. LAST PM-31,257 MILES

UNIT NO:		232451 200	3 CHEVRO	ET BL	UE BIF	RD		WORK O	RDER NO	): 2	4004	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COM	IED DAT PLETED SED DAT let Blue	DATE: E:	09/01/20 <sup>-</sup>	16 10:42:05 16 14:02:26 16 14:02:28		M: 32617 E DATE:	<b>M</b> 02/20/20		Services 0
JOB CODE	Ī	JOB DESCRIPTION	STA <sup>-</sup>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-02-047	REPLAC	E NEW SEAT BELTS	DON	0	N	GARAGE	1.00	\$57.50	\$370.01	\$0	0.00	\$427.51
03-52-025	REPLAC	E NEW FAN ASSY	DON	0	N	GARAGE	1.50	\$86.25	\$23.00	\$0	0.00	\$109.25
06-13	INSPECT	ΓBRAKES	DON	0	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
35-42	DIAGNO	SE COOLING SYSTEM	DON	0	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
JOB COUN	IT: 4			wo	RK ORI	DER TOTAL	4.50	258	3.75	393.01	0.00	651.76
Job Code		Job Description		<u>Er</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		<b>Quantity</b>	Total Cost
66-79-003	PERFORM	SAFETY INSPECTION		1139702	3	08	/26/2016 08:00:00	08/26/20	16 09:00:00		1.00	\$57.50
66-79-003	PERFORM	SAFETY INSPECTION		1139702	6	08	/26/2016 08:00:00	08/26/20	16 09:00:00		(1.00)	(\$57.50)
03-52-025	REPLACE N	IEW FAN ASSY		1139702	3	08	/26/2016 10:00:00	08/26/20	16 11:30:00		1.50	\$86.25
03-02-047	REPLACE N	IEW SEAT BELTS		1139702	6	08	/26/2016 09:00:00	08/26/20	16 10:00:00		1.00	\$57.50
35-42	DIAGNOSE	COOLING SYSTEM		1139702	3	08	/26/2016 08:00:00	08/26/20	16 09:00:00		1.00	\$57.50
06-13	INSPECT BI	RAKES		1139702	3	08	/26/2016 07:00:00	08/26/20	16 08:00:00		1.00	\$57.50
											LABOR	258.75
Job Code		Job Description			Part No	<u>.</u>	Des	<u>cription</u>		Unit Price	Quantity	Total Cost
03-52-025	REPLACE N	IEW FAN ASSY		MEI3862		DA	ASH FAN ASSY 12	V		23.00	) 1	\$23.00
03-02-047	REPLACE N	IEW SEAT BELTS		8894015	7	SE	EAT BELT KIT			95.00	1	\$95.00
03-02-047	REPLACE N	IEW SEAT BELTS		8894015	3	SE	EAT BELT RETRAC	CTOR ASSY		275.01	1 1	\$275.01
03-02-047	REPLACE N	IEW SEAT BELTS		8894015	3	SE	EAT BELT RETRAC	CTOR ASSY		275.01	1 (1)	(\$275.01)
03-02-047	REPLACE N	IEW SEAT BELTS		8894015	3	SE	EAT BELT RETRAC	CTOR ASSY		275.01		\$275.01
											PARTS	393.01

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 24004

# **Work Order Notes**

(LISAPATE) PER STATE INSPECTION FORM. CHECK BRAKES-REPLACE DRIVER SEAT BELT-CHECK TEMP GAUGE IS FLUCTUATING-INSTALL NEW DASH FAN

## **Job Notes**

### 03-02-047 - REPLACE NEW SEAT BELTS

(LISAPATE) REPLACED LF FRONT SEAT BELT BUCKLE AND RETRACTOR.

#### 03-52-025 - REPLACE NEW FAN ASSY

(LISAPATE) INSTALLED NEW DASH FAN AND WIRED UP

## 06-13 - INSPECT BRAKES

(LISAPATE) CHECKED FRONT AND REAR BRAKES. ALL THE BRAKES LOOK GOOD. BRAKES WERE REPLACED IN 2014 AND ONLY HAVE 800 MILES ON THEM

## 35-42 - DIAGNOSE COOLING SYSTEM

(LISAPATE) CHECKED TEMP GAUGE FOUND WIRE WAS BROKEN AT THE CONNECTOR ENGINE SIDE OF TEMP SENDING UNIT, REPLACED CONNECTOR AND SOLDERED WIRES. RECHECKED OK

66-79-003 - PERFORM SAFETY INSPECTION

UNIT NO:		232451 200	03 CHE	VROL	ET BL	UE BIF	RD		WORK OF	RDER NO	): 2	5082	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED PREVENTIVE MAINT 03BUSBLUEBIRD		CLOSE	D DAT	DATE:	11/29/20 <sup>2</sup> 11/30/20	16 11:45:08 16 09:42:57 16 11:32:57	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	1: 32963 DATE:	<b>M</b> 02/20/20	ey Automotive 9 ETER 2 - N: 102 1R621157998	0
JOB CODE	<u> </u>	JOB DESCRIPTION		STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-17-028	REPLAC	E NEW MOUNT AND B	ALANCE	DON	Р	N	GARAGE	0.80	\$46.00	\$6.92	\$5	525.00	\$577.92
03-51-038	REPLAC	E NEW WIPER BLADES	S	DON	Р	N	GARAGE	20.79	\$1,195.20	\$17.06	\$0	0.00	\$1,212.26
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	4.61	\$265.12	\$42.37	\$0	0.00	\$307.49
JOB COUN	IT: 3				wc	ORK ORI	DER TOTAL	26.20	1,506.	32	66.35	525.00	2,097.67
<b>Job Code</b> 03-17-028	REPLACE N	Job Description  EW MOUNT AND BALANC	CE TIRES	1	<u>\</u> 1122732	/endor N		Invoice No.	<u>Purchas</u> 0036474	se Order N	<u>0.</u>		Total Cost \$525.00
												COMML	525.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>	<u>F</u>	<u>inish</u>		Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		1	1758845	5	11	/28/2016 13:08:20	11/29/2010	6 09:40:30		20.54	\$1,180.83
03-51-038	REPLACE N	EW WIPER BLADES		1	175884	5	11	/29/2016 07:00:00	11/29/2010	6 07:15:00		0.25	\$14.38
03-17-028	REPLACE N	EW MOUNT AND BALANG	CE TIRES	1	1074414	4	11	/29/2016 06:00:00	11/29/2010	6 06:48:00		0.80	\$46.00
66-PM-PMA	PERFORM (	OIL CHANGE		1	1758845	5	11	/28/2016 08:50:04	11/28/2010	6 13:08:07		4.30	\$247.30
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414	4	11	/23/2016 11:46:12	11/23/2010	6 12:04:48		0.31	\$17.83
												LABOR	1506.34
Job Code		Job Description				Part No	<u>'-</u>	Des	cription		Unit Price	Quantity	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES		٧	VW-220	0-PC	W	IPER BLADE 22"			8.53	2	\$17.06
03-17-028	REPLACE N	EW MOUNT AND BALANC	CE TIRES	٧	VHEEL \	WEIGHT	W	HEEL WEIGHT KN	NOCK ON		0.23	12	\$2.76
03-17-028	REPLACE N	EW MOUNT AND BALANC	CE TIRES	2	2000		VA	ALVE STEM CHRO	ME LOW BOLT	IN	1.04	. 4	\$4.16
66-PM-PMA	PERFORM (	OIL CHANGE		4	6573		FI	LTER-AIR			16.87	1	\$16.87
66-PM-PMA	PERFORM (	OIL CHANGE		1	1562588	3	OI	L DRAIN PLUG M	12		3.99	1	\$3.99
66-PM-PMA	PERFORM (	OIL CHANGE		1	0W30S	SQT	10	W30 SEMI SYN C	T. BOTTLE		3.23	6	\$19.38
66-PM-PMA	PERFORM (	OIL CHANGE		E	BALB142	28	LU	JBE SPIN-ON FILT	ER		2.13	1	\$2.13
												PARTS	66.35

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 25082

**Work Order Notes** 

(IFALLS) PM

# **Job Notes**

03-17-028 - REPLACE NEW MOUNT AND BALANCE TIRES

(IFALLS) SH MOUNTED AND BALANCED 4 REAR TIRES AND INSTALLED 4 NEW VALVE STEMS

03-51-038 - REPLACE NEW WIPER BLADES

(IFALLS) SH REPLACED WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (IFALLS) SH PERFORMED PM

UNIT NO:		232451 200	3 CHEVR	OLE.	TBL	UE BIF	RD		WORK	ORDER N	0: 2	2555	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	со	MPLE	DAT	DATE: E:	12/05/20 12/05/20	08 09:07:45 08 06:49:42 08 06:49:44	METER	ON: GARAG 1 - M: 15360 /ICE DATE: ERIAL NO:	02/20/2		0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>S1</u>	<u>AT</u>	<u>RSN</u>	WRTY	JOB LOC		·	OR MAT	ERIAL (	COMMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	D	NC	N	N	GARAGE	0.25	\$14.38	\$30.90	\$	\$0.00	\$45.28
66-PM-PMA	PERFOR	M OIL CHANGE	D	NC	Р	N	GARAGE	0.31	\$17.83	\$48.48	9	\$0.00	\$66.31
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	: 0.56	6	32.21	79.38	0.00	111.59
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		111	28904		12	2/04/2008 10:00:00	12/04	1/2008 10:18:36		0.31	\$17.83
03-51-038	REPLACE N	EW WIPER BLADES		111	28904		12	2/04/2008 10:18:36	6 12/04	/2008 10:33:36		0.25	\$14.38
												LABOR	32.21
Job Code		Job Description				Part No	<u>.</u>	Des	scription		Unit Price	e Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		46	573		FI	LTER-AIR			25.2	23 1	\$25.23
03-51-038	REPLACE N	EW WIPER BLADES		60-	-2240		W	IPER BLADE			15.4	45 2	\$30.90
66-PM-PMA	PERFORM (	DIL CHANGE		ВА	LB142	8	LU	JBE SPIN-ON FIL	TER		7.4	41 1	\$7.4
66-PM-PMA	PERFORM (	OIL CHANGE		10\	W-30		0	IL BULK			0.0	09 176	\$15.84
												PARTS	79.38

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 2555

**Work Order Notes** 

(LPATE) PM-REPLACE WIPERS

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:
Part 10W-30 OIL BULK Qty 176 Cost 0
Part 51061 FILTER-OIL Qty 1 Cost 0
(LPATE) PM BY CM

UNIT NO:		232451	2003 CHE	VROLE	ET BL	UE BIF	RD		WORK OF	RDER NO	<b>)</b> : :	2655	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	2003	OPENE COMPL CLOSE Chevrole	ETED D DATI	DATE: E:	12/19/20 12/19/20	008 09:42:21 008 11:51:06 008 11:51:07	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 15385 DATE:	02/20/2	sity Automotive 9 <b>METER 2 - N:</b> 2002 331R621157998	0
JOB CODE		JOB DESCRIPTIO	<u>N</u>	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LO	LABOR HRS	LABOR	MAT	<u>ERIAL</u>	COMMERCIAL	TOTAL COST
03-02-009	REPLAC	E NEW SUN VISOR		DON	0	N	GARAGE	0.25	\$14.38	\$184.53	3	\$0.00	\$198.91
03-02-018	REPLAC	E NEW DOOR MEC	HANISM	DON	0	N	GARAGE	0.25	\$14.38	\$29.97	:	\$0.00	\$44.35
JOB COUN	IT: 2				wo	RK ORI	DER TOTAL	_: 0.50	28.	76	214.50	0.00	243.26
Job Code		Job Description	<u>on</u>		<u>Em</u>	nployee	No.	<u>Start</u>	<u> </u>	<u>inish</u>		Quantity	Total Cost
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	1	1088474	ļ	1	2/19/2008 11:15:00	12/19/200	8 11:30:00		0.25	\$14.38
03-02-009	REPLACE N	EW SUN VISOR		1	1088474	ļ	1	2/19/2008 11:00:00	12/19/200	8 11:15:00		0.25	\$14.38
												LABOR	28.76
Job Code		Job Description	<u>on</u>			Part No	<u>.</u>	<u>Des</u>	scription		Unit Pric	e Quantity	Total Cost
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	1	366715		F	HANDLE-ENTRY DO	OOR BUS		3.7	75 1	\$3.75
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	1	483627		F	PIN-HANDLE			8.2	22 1	\$8.22
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	0	993261		F	PIN ROLL HANDLE			0.4	42 1	\$0.42
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	1	539147		5	PRING-HANDLE			4.8	83 1	\$4.83
03-02-009	REPLACE N	EW SUN VISOR		1	5033903	3	8	SUNSHADE			184.	53 1	\$184.53
03-02-018	REPLACE N	EW DOOR MECHANIS	SM	S	HIPPING	G	8	HIPPING AND HAI	NDLING		12.7	751	\$12.75
												PARTS	214.50

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 2655

**Work Order Notes** 

(LPATE) SPECIAL ODERED PARTS TO REPLACE BROKEN SUNVISOR AND BROKEN HANDLE THAT OPENS AND CLOSES SWINGING ENTRY DOORS

**Job Notes** 

03-02-009 - REPLACE NEW SUN VISOR

(LPATE) REPLACED SUN VISOR

03-02-018 - REPLACE NEW DOOR MECHANISM

(LPATE) REPLACED HANDLE LATCH KIT TO SWINGING DOOR

UNIT NO:		232451 20	03 CHEVROL	ET BL	UE BIF	RD		WORK OR	DER NO	): 27	733	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COMF	ED DAT LETED ED DAT let Blue	DATE:	10/18/20 10/18/20	17 09:37:29 17 11:33:08 17 11:33:09	LOCATION: METER 1 - M: IN-SERVICE I UNIT SERIAL	36107 <b>DATE</b> :	<b>ME</b> 02/20/200	TER 2 - N:	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL COST
24-02-010	REPAIR I	MIRRORS	DON	Р	N	GARAGE	1.02	\$58.91	\$0.00	\$0.	00	\$58.91
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	N	GARAGE	0.08	\$4.78	\$14.96	\$0.	00	\$19.74
JOB COUN	T: 2			wo	ORK ORI	DER TOTAL	: 1.11	63.6	9	14.96	0.00	78.65
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>nish</u>		Quantity	Total Cost
24-02-010	REPAIR MIR	RRORS		11074414	4	10	0/10/2017 07:51:34	10/10/2017	08:23:02		0.52	\$30.16
24-02-010	REPAIR MIR	RRORS		11074414	4	10	0/10/2017 06:00:00	10/10/2017	06:30:00		0.50	\$28.75
66-PM-PMA	PERFORM (	OIL CHANGE		11074414	4	10	0/09/2017 13:07:16	10/09/2017	13:12:15		0.08	\$4.78
											LABOR	63.69
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription	,	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		10W30P		Р	ROTECK10W30SE	EMI SYNTHETIC	OIL	2.14	6	\$12.84
66-PM-PMA	PERFORM (	OIL CHANGE		10W30P		Р	ROTECK10W30SE	EMI SYNTHETIC (	OIL	2.14	(1)	(\$2.14)
66-PM-PMA	PERFORM (	OIL CHANGE		10W30P		Р	ROTECK10W30SE	EMI SYNTHETIC	OIL	2.14	1	\$2.14
66-PM-PMA	PERFORM (	OIL CHANGE		BALB142	28	L	JBE SPIN-ON FILT	ER		2.12	1	\$2.12
											PARTS	14.96

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 27733

**Work Order Notes** 

(LISAPATE) PM-RIGHT HAWKEYE MIRROR IS LOOSE

**Job Notes** 

**24-02-010 - REPAIR MIRRORS** 

(IFALLS) USED PLUS NUTS TO SECURE MIRROR TO FENDER

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (IFALLS) PM BY SH

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 28520

USING DEPT NO: 208185 OPENED DATE: 01/04/2018 15:11:16 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 01/12/2018 06:42:48
 METER 1 - M:
 36325
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 01/12/2018 06:42:49
 IN-SERVICE DATE:
 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB LOC LABOR HRS **MATERIAL** JOB CODE JOB DESCRIPTION STAT RSN WRTY LABOR COMMERCIAL TOTAL COST 24-79-017 REPAIR SCHOOL BUS CROSSING ARM DON 0 **GARAGE** 2.00 \$115.00 \$361.49 \$0.00 \$476.49

JOB COUNT: 1 WORK ORDER TOTAL: 2.00 115.00 361.49 0.00 476.49 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 24-79-017 REPAIR SCHOOL BUS CROSSING ARM 11213180 01/09/2018 07:00:00 01/09/2018 09:00:00 2.00 \$115.00 **LABOR** 115.00 **Job Code** Part No. **Unit Price** Quantity Job Description Description **Total Cost** SMA7129 223.30 1 24-79-017 REPAIR SCHOOL BUS CROSSING ARM 7 SER MODULE, STOP SIGN ARM

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 28520

**Work Order Notes** 

(LISAPATE) CROSSING ARM IS INOP

**Job Notes** 

24-79-017 - REPAIR SCHOOL BUS CROSSING ARM

(LISAPATE) FOUND MOTOR TO BE BURNT DUE TO FAULTY POSITION SENSOR. REPLACED MOTOR AND SENSOR. RECHECKED OK

UNIT NO:		232451	2003 CHEV	ROLE	ET BL	UE BIF	RD		WORK	ORDER NO	O: 2	8699	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED PREVENTIVE MA 03BUSBLUEBIRD	INT (	COMPL	D DATI ETED I D DATI t Blue E	DATE: E:	01/25/201 01/25/201	18 10:32:54 18 20:00:00 18 20:00:00	METER 1	- M: 36547 CE DATE:	<b>M</b> 02/20/20		Services 0
JOB CODE	1	JOB DESCRIPTION	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABC	R MAT	ERIAL C	OMMERCIAL	TOTAL COST
03-32-002	REPLAC	E NEW BATTERY		DON	Р	Ν	GARAGE	0.50	\$28.75	\$56.91	\$0	0.00	\$85.66
66-79-002	PERFOR	RM SERVICE CALL		DON	Р	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
JOB COUN	T: 2				wo	RK ORI	DER TOTAL:	1.50		86.25	56.91	0.00	143.16
Job Code		Job Descripti	<u>on</u>		<u>Em</u>	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
03-32-002	REPLACE N	IEW BATTERY		1′	1901357		01	/25/2018 07:00:00	01/25/	2018 07:30:00		0.50	\$28.7
03-32-002	REPLACE N	IEW BATTERY		1	1901357		01	/26/2018 07:00:00	01/26/2	2018 07:30:00		(0.50)	(\$28.75
03-32-002	REPLACE N	IEW BATTERY		1	1901357		01	/26/2018 07:00:00	01/26/2	2018 07:30:00		0.50	\$28.7
03-32-002	REPLACE N	IEW BATTERY		1	1901357		01	/24/2018 10:35:58	01/24/	2018 11:05:58		(0.50)	(\$28.75
66-79-002	PERFORM S	SERVICE CALL		1	1758845		01	/24/2018 10:36:23	01/24/	2018 11:36:23		1.00	\$57.5
03-32-002	REPLACE N	IEW BATTERY		1	1901357		01	/24/2018 10:35:58	01/24/	2018 11:05:58		0.50	\$28.7
												LABOR	86.29
Job Code		Job Descripti	<u>on</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	Total Cost
03-32-002	REPLACE N	IEW BATTERY		78	81		BA	ATTERY BCI 78 77	0 CCA		56.92	! 1	\$56.9
03-32-002	REPLACE N	IEW BATTERY		78	81		BA	ATTERY BCI 78 77	0 CCA		56.92	! (1)	(\$56.92
03-32-002	REPLACE N	IEW BATTERY		78	81		BA	ATTERY BCI 78 77	0 CCA		56.91	1	\$56.9
03-32-002	REPLACE N	IEW BATTERY		78	8DT		BA	ATTERY DUAL BC	I 34/78 800 (	CCA	57.49	1	\$57.4
03-32-002	REPLACE N	IEW BATTERY		78	8DT		BA	ATTERY DUAL BC	I 34/78 800 (	CCA	57.49	(1)	(\$57.49
												PARTS	56.9

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 28699

**Work Order Notes** 

(IFALLS) KEITH REQUESTED SERVICE CALL TO BREWER PORCH BUS WONT CRANK

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(IFALLS) AG INSTALLED NEW 78 NAS BATTERY ALT CHARGING AT 14.2

66-79-002 - PERFORM SERVICE CALL

(IFALLS) CS PERFORMED SERVICE CALL

UNIT NO:		232451	2003 CHE\	/ROLE	ET BL	UE BIF	RD		WORK C	RDER NO	): 30	298	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED	DATE:	07/24/20 07/24/20	18 11:20:30 18 09:45:05 18 09:45:06		M: 39126 E DATE:	<b>ME</b> 02/20/200	Automotive 9 TER 2 - N: 02 R621157998	0
JOB CODE		JOB DESCRIPTION	<u>NC</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATE	RIAL CO	MMERCIAL	TOTAL COST
01-13-002	ADJUST	REAR BRAKES & [	DRUMS/ROT	DON	Р	Ν	GARAGE	0.50	\$0.00	\$0.00	\$0.	00	\$0.00
03-13-001	REPLAC	E NEW FRONT BR	AKES & ROT	DON	0	Ν	GARAGE	2.50	\$0.00	\$22.86	\$0.	00	\$22.86
24-79-021	REPAIR	SCHOOL BUS STO	P ARM ASSY	DON	0	N	GARAGE	1.00	\$0.00	\$0.00	\$0.	00	\$0.00
66-79-003	PERFOR	M SAFETY INSPEC	CTION	DON	Р	N	GARAGE	2.00	\$0.00	\$22.96	\$0.	00	\$22.96
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.31	\$0.00	\$13.58	\$0.	00	\$13.58
JOB COUN	IT: 5				wo	RK ORI	DER TOTAL	: 6.31		0.00	59.40	0.00	59.40
Job Code		Job Descript	<u>ion</u>		Em	ployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
01-13-002	ADJUST RE	AR BRAKES & DRUM	IS/ROTORS	1	1268671		07	7/24/2018 07:00:00	07/24/20	018 07:30:00		0.50	\$0.0
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414		07	7/20/2018 06:00:00	07/20/20	018 06:18:36		0.31	\$0.0
66-79-003	PERFORM	SAFETY INSPECTION	1	1	1074414		07	7/20/2018 06:18:36	07/20/20	018 08:18:36		2.00	\$0.0
24-79-021	REPAIR SCI	HOOL BUS STOP ARM	M ASSY	1	1074414		07	7/20/2018 07:18:36	07/20/20	018 08:18:36		1.00	\$0.0
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	1	1213180		07	7/20/2018 07:00:00	07/20/20	018 09:30:00		2.50	\$0.0
												LABOR	0.0
Job Code		Job Descripti	<u>ion</u>			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		1	0W30BT	•	В	JLK OIL 10W30 SE	EMI-SYN THO	MAS	1.91	6	\$11.4
66-PM-PMA	PERFORM (	OIL CHANGE		В	ALB142	8	LU	JBE SPIN-ON FILT	ER		2.12	1	\$2.1
03-13-001	REPLACE N	IEW FRONT BRAKES	& ROTORS	R	RABMGD	459MH	BF	RAKE PAD SET			22.86	1	\$22.8
66-79-003	PERFORM	SAFETY INSPECTION	J	2	2237180	21	SA	AFETY DECAL EM	IERGENCY E	XIT	11.48	2	
												PARTS	59.4

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 30298

# **Work Order Notes**

(LISAPATE) PM-DO SI- INSTALL STOP ARM MODULE-PART IS HERE-INSTALL EXIT STICKERS X2-GREASE FRONT END

## **Job Notes**

#### 01-13-002 - ADJUST REAR BRAKES & DRUMS/ROTORS

(IFALLS) IF INSPECTED THE REAR BRAKE LINNING AND THEY LOOKED GOOD, IF ALSO ADJUSTED REAR BRAKES

### 03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(LISAPATE) MS-REPLACED FRONT BRAKE PADS AND RESURFACED ROTORS IF-ADJUSTED REAR BRAKES

### 24-79-021 - REPAIR SCHOOL BUS STOP ARM ASSY

(LISAPATE) IF-INSTALLED EXIT STICKERS ON WINDOWS SH-INSTALLED STOP ARM MODULE

### 66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SAFETY INSPECTION COMPLETED. SEE ATTACHED

#### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (LISAPATE) PM BY SH COOLANT -20'

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

**UNIT NO:** 232451 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 3116 **USING DEPT NO:** 208185 **OPENED DATE:** 03/25/2009 13:59:36 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 03/25/2009 14:35:46 **WO STATUS: METER 1 - M**: 15385 **COMPLETED DATE: METER 2 - N**: 0 **WO VISIT REASON:** UNSCHEDULED **CLOSED DATE:** 03/25/2009 14:35:48 **IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 RSN WRTY JOB LOC LABOR HRS COMMERCIAL TOTAL COST JOB CODE <u>STAT</u> **LABOR MATERIAL** JOB DESCRIPTION 66-79-002 PERFORM SERVICE CALL DON В Ν **GARAGE** 0.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 1 WORK ORDER TOTAL: 0.00 0.00 0.00 0.00 0.00

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 3116

## **Work Order Notes**

(LPATE) ON 3/12/2009 BUS 024 WAS IN BIRMINGHAM FOR A FIELD TRIP THEY CALLED SHOP SAID THEY HAD A FLAT TIRE. WE CALLED GCR OF TUSCALOOSA THEY SA TO CALL GCR OF BIRMINGHAM THEY WOULD TAKE CARE OF US. CALLED 205-322-6602 S/W DAVID HE DISPATCHED A SVC CALL TO THE SLOSS FURNACE MUSUEM..INSTEAD OF WAITING FOR SVC TRUCK BUS DRIVER MOVED BUS 2 MILES UP ROAD TO TRAIN STATION SO STUDENTS COULD FINISH FIELD TRIP BACK TO TUSCALOOSA. THAT WAS OK'D BY WARREN JOHNSON. LISA TOLD DRIVER NOT TO MOVE THE BUS. WHEN SVC TRUCK ARRIVED HE STATED VALVE STEM CORE WAS BAD INSTALLED NEW CORE AND DID NOT CHARGE US FOR SVC CALL AT ALL. DRIVER RTND TO TUSCALOOSA WITH NO ADDT'L PROBLEMS

## **Job Notes**

#### 66-79-002 - PERFORM SERVICE CALL

(LPATE) BUS REAR TIRE WAS REPAIRED BY GCR OF BIRMINGHAM AT NO CHARGE..REPAIRED VALVE STEM

UNIT NO:		232451 2	003 CHE	<b>VROLE</b>	ET BL	UE BIF	RD		WORK	ORDER NO	D: 3	31832		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE:	01/18/20	19 09:47:05 19 09:24:08 19 09:24:10	METER IN-SERV	ON: GARAGE 1 - M: 39570 /ICE DATE: RIAL NO:	N 02/20/2	ity Automotive : <b>/IETER 2 - N:</b> 002 31R621157998	0	
JOB CODE	<u> </u>	JOB DESCRIPTION	<u> 1</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LAB</u>	OR MATI	ERIAL (	COMMERCIAL	TOTAL	COST
03-33-013	REPLAC	E NEW DISTRIBUTO	R CAP	DON	0	Ν	GARAGE	1.00	\$72.50	\$59.17	\$	0.00	\$131.67	
20-00	TOWING	COMPLETE VEHICL	.E	DON	В	N	GARAGE	0.00	\$0.00	\$0.00	\$	885.00	\$85.00	
66-79-002	PERFOR	M SERVICE CALL		DON	В	N	GARAGE	1.00	\$72.50	\$0.00	\$	60.00	\$72.50	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.43	\$31.11	\$15.38	\$	60.00	\$46.49	
JOB COUN	IT: 4				WC	RK ORI	DER TOTAL	2.43	3	176.11	74.55	85.00	l	335.66
Job Code		Job Description	<u>n</u>		<u>v</u>	endor N	<u>o.</u>	Invoice No.	Pure	chase Order N	lo.		<u>Total</u>	Cost
20-00	TOWING CO	OMPLETE VEHICLE		1	1076249	)	62	381	00464	142				\$85.00
20-00	TOWING CO	MPLETE VEHICLE		1	1076249	)	62	381	00464	142				(\$85.00)
20-00	TOWING CO	OMPLETE VEHICLE		1	1076249	)	62	381	00464	142		-		\$85.00
												COMML		85.00
Job Code		Job Description	<u>n</u>		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost
66-79-002	PERFORM	SERVICE CALL		1	1758845	5	01	/15/2019 07:00:0	0 01/15	/2019 08:00:00		1.00		\$72.50
03-33-013	REPLACE N	IEW DISTRIBUTOR CAF	<b>o</b>	1	1268671		01	/15/2019 07:00:0	0 01/15	/2019 07:54:00		(0.90	)	(\$65.25)
03-33-013	REPLACE N	IEW DISTRIBUTOR CAF	<b>D</b>	1	1268671		01	/15/2019 07:00:0	0 01/15	/2019 07:54:00		0.90		\$65.25
03-33-013	REPLACE N	IEW DISTRIBUTOR CAF	<b>&gt;</b>	1	1268671		01	/15/2019 07:00:0	0 01/15	/2019 08:00:00		1.00		\$72.50
66-PM-PMA	PERFORM (	OIL CHANGE		1	1074414	ļ	01	/09/2019 08:07:1	1 01/09	/2019 08:32:56		0.43		\$31.11
												LABOR		176.11
Job Code		Job Description	<u>n</u>			Part No	<u>.</u>	<u>De</u>	scription		Unit Price	<u>Quantity</u>	<u>Total</u>	Cost
03-33-013	REPLACE N	IEW DISTRIBUTOR CAF	<b>D</b>	D	LID329	A	DI	STRIBUTOR			47.8	4 1		\$47.84
66-PM-PMA	PERFORM (	OIL CHANGE		1	0W30B1	-	ВІ	JLK OIL 10W30 S	EMI-SYN TI	HOMAS	2.2	1 6		\$13.26
66-PM-PMA	PERFORM (	OIL CHANGE		В	ALB142	8	LU	IBE SPIN-ON FIL	TER		2.1	2 1		\$2.12
03-33-013	REPLACE N	IEW DISTRIBUTOR CAF	0	D	LID465		R	OTOR BUTTON			11.3			\$11.33
												PARTS		74.55

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 31832

# **Work Order Notes**

(LISAPATE) Keith requested a service call to BPCC bus spins over wont start

## **Job Notes**

## 03-33-013 - REPLACE NEW DISTRIBUTOR CAP

(LISAPATE) Replaced distributor cap and button. Rechecked running good

### 03-41-013 - REPLACE NEW AIR FILTER HOUSING ASSY

## 20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Visit Reason Changed On 1/15/2019 9:16 AM By LISAPATE (LISAPATE) Bambarger towed unit from BPCC to the shop. PD by CC

### 66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed could not get started call for bus to be towed to the shop

## 66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (LISAPATE) PM by SH Coolant -35'

# Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

# Work Order Charge Detail

232451 **UNIT NO:** 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 33787 **USING DEPT NO:** 208185 **OPENED DATE:** 08/20/2019 10:15:41 **LOCATION:** GARAGE - University Automotive Services **CLOSED** 08/23/2019 14:05:32 **WO STATUS:** COMPLETED DATE: METER 1 - M: 41499 METER 2 - N: **SCHEDULED** 08/23/2019 14:05:34 WO VISIT REASON: **CLOSED DATE:** IN-SERVICE DATE: 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 **MATERIAL TOTAL COST** JOB CODE JOB DESCRIPTION STAT RSN WRTY JOB LOC LABOR HRS **LABOR** COMMERCIAL 03-34-002 0 **GARAGE** 0.30 \$21.75 \$21.93 REPLACE NEW LAMPS-REAR, TAIL, STO DON Ν \$0.18 \$0.00 06-79-021 INSPECT SCHOOL BUS STOP ARM ASS DON 0 **GARAGE** 0.53 \$38.49 \$0.00 \$0.00 \$38.49 Ρ \$166.93 66-79-003 PERFORM SAFETY INSPECTION DON **GARAGE** 2.30 \$166.93 \$0.00 \$0.00 Ρ 66-PM-PMA DON **GARAGE** 2.24 \$162.34 \$23.25 \$0.00 \$185.59 PERFORM OIL CHANGE JOB COUNT: 4 WORK ORDER TOTAL: 5.37 389.51 23.43 0.00 412.94 Job Code Job Description Employee No. Start **Finish** Quantity **Total Cost** 03-34-002 REPLACE NEW LAMPS-REAR.TAIL.STOP.TURN.ETC 12052187 08/22/2019 07:00:00 08/22/2019 07:18:00 0.30 \$21.75 66-79-003 PERFORM SAFETY INSPECTION 0.49 \$35.65 11074414 08/21/2019 14:27:07 08/21/2019 14:56:37 66-79-003 PERFORM SAFETY INSPECTION 11074414 08/21/2019 07:33:48 08/21/2019 09:22:27 181 \$131.29 06-79-021 INSPECT SCHOOL BUS STOP ARM ASSY 11074414 08/20/2019 15:17:12 08/20/2019 15:49:03 0.53 \$38 49 \$91.35 66-PM-PMA PERFORM OIL CHANGE 12052187 08/20/2019 13:59:34 08/20/2019 15:15:10 1 26 66-PM-PMA PERFORM OIL CHANGE 11901357 08/20/2019 13:58:49 08/20/2019 14:57:34 0.98 \$70.99 **LABOR** 389.52 Job Code **Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 6 \$12.00 66-PM-PMA BULK OIL 10W30 SEMI-SYN THOMAS PERFORM OIL CHANGE 10W30BT 2.00 66-PM-PMA PERFORM OIL CHANGE C111 RED BRAKE CLEANER 2.11 \$2.11 \$0.18 03-34-002 REPLACE NEW LAMPS-REAR.TAIL.STOP.TURN.ETC 1156 **BULB-BACK UP** 0.18 66-PM-PMA PERFORM OIL CHANGE 05089 BRAKE CLEAN NON-FLAMMABLE 1407 4 21 \$4.21 CMP 2.81 66-PM-PMA PERFORM OIL CHANGE MOBILE CM-P TUBE GREASE \$2.81 66-PM-PMA PERFORM OIL CHANGE **BALB1428** LUBE SPIN-ON FILTER 2.12 \$2.12 **PARTS** 23.43

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 33787

# **Work Order Notes**

(LISAPATE) PM-PMF-Turn signal out-stop sign wont work at times-DO SI

## Job Notes

## 03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LISAPATE) Replaced turn signal

#### 06-79-021 - INSPECT SCHOOL BUS STOP ARM ASSY

(LISAPATE) Removed cover from stop sign and inspected wiring did not see any issues. Inspected wiring and connections on the inside control panel did not see any issues. Operated stop sign multiple times could not find the problem at this time.

## 66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Safety inspection completed. See attached

### 66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (LISAPATE) PM by AG/JW Coolant -35'

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

UNIT NO:		232451	2003 CHEV	/ROL	ET BLI	JE BIF	RD		WORK OF	RDER NO	): 3	3395	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIR	•	COMP CLOSI	ED DATE LETED I ED DATE et Blue E	DATE:	06/02/2 06/02/2	2009 08:34:28 2009 07:37:39 2009 07:37:41	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	n: 15553 DATE:	N 02/20/2	ity Automotive 9 <b>/IETER 2 - N:</b> 002 31R621157998	0
JOB CODE		JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LO	C LABOR HRS	<u>LABOR</u>	MATE	RIAL (	COMMERCIAL	TOTAL COST
03-13-002	REPLAC	E NEW REAR BRA	AKES & DRUN	DON	Ν	N	GARAGE	24.51	\$1,409.55	\$597.39	\$	27.60	\$2,034.54
03-34-002	REPLAC	E NEW LAMPS-RI	EAR,TAIL,STO	DON	N	Ν	GARAGE	0.30	\$17.25	\$0.42	\$	0.00	\$17.67
10-01	SERVICE	E AIR CONDITION	ING, HEAT, VE	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$	2,196.36	\$2,196.36
66-79-003	PERFOR	RM SAFETY INSPE	ECTION	DON	0	N	GARAGE	2.98	\$171.41	\$17.10	\$	60.00	\$188.51
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	1.78	\$102.48	\$25.89	\$	0.00	\$128.37
JOB COUN	IT: 5				wo	RK ORI	DER TOTA	L: 29.58	3 1,700.	69	640.80	2,223.96	4,565.45
<b>Job Code</b> 03-13-002 10-01		Job Descrip IEW REAR BRAKES IR CONDITIONING, I	& DRUMS/ROTO		<b>V</b> e 11074386 11077507	endor N		<u>Invoice No.</u> 780984 36976	<u>Purchas</u> 0004402 0004559	se Order N	<u>o.</u>		Total Cost \$27.60 \$2,196.36
10-01	SERVICE AI	R CONDITIONING, I	MEAI, VENI		11077507		,	30970	0004339			COMML	2223.96
Job Code		Job Descrip	tion		Em	ployee	No.	Start	F	inish		Quantity	Total Cost
03-34-002	REPLACE N	IEW LAMPS-REAR,1	<u></u>	ETC		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		05/15/2009 07:00:00	_	9 07:18:00		0.30	\$17.25
03-13-002	REPLACE N	IEW REAR BRAKES	& DRUMS/ROTO	RS	11274660			05/12/2009 14:07:52	2 05/13/200	9 14:38:42		24.51	\$1,409.55
66-79-003	PERFORM	SAFETY INSPECTIO	N		11274660			05/12/2009 11:08:45	5 05/12/200	9 14:07:37		2.98	\$171.41
66-PM-PMA	PERFORM	OIL CHANGE			11274660			05/12/2009 08:35:00	05/12/200	9 10:21:56		1.78	\$102.48
												LABOR	1700.69
Job Code		Job Descrip	tion		ļ	Part No	<u>.</u>	Des	scription_		Unit Price	<u>Quantity</u>	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		ı	BALB1428	3		LUBE SPIN-ON FIL	TER		7.4	1 1	\$7.41
66-79-003	PERFORM	SAFETY INSPECTIO	N	9	90W			OIL-GEAR OIL-AXL	E GREASE		1.6	5 2	\$3.30
03-13-002	REPLACE N	IEW REAR BRAKES	& DRUMS/ROTO	RS (	C111			RED BRAKE CLEA	NER		4.1	3 2	\$8.25
03-13-002	REPLACE N	IEW REAR BRAKES	& DRUMS/ROTO	RS I	BRAKE FI	LUID		BRAKE FLUID DOT	3 12OZ		2.7	9 1	\$2.79
66-79-003	PERFORM	SAFETY INSPECTIO	N	,	ANTIFREI	EZE DEX	(COOL	ANTIFREEZE-GM			13.8	0 1	\$13.80
66-PM-PMA	PERFORM (	OIL CHANGE			10W-30			OIL BULK			0.1	1 176	\$18.48
03-34-002	REPLACE N	IEW LAMPS-REAR,1	TAIL,STOP,TURN,	ETC	1157			BULB-BRAKE/TURI	N		0.4	2 1	\$0.42

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	SKF28426	REAR WHEEL SEALS	10.01	2	\$20.01
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABWC37337	REAR WHEEL CYLINDER	14.84	2	\$29.67
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PTX24010	LOCKTITE	17.49	1	\$17.49
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RAM2591R	REAR BRAKE DRUM	143.72	2	\$287.43
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	DOR610333	REAR WHEEL STUD	3.86	12	\$46.26
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	DOR610333	REAR WHEEL STUD	3.86	4	\$15.42
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	MONBX452R	REAR BRAKE SHOES	104.83	1	\$104.83
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABH70552	COMBINATION KIT	9.11	1	\$9.11
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABH2580	REAR ADJ KIT LEFT	22.08	1	\$22.08
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	RABH2581	REAR ADJUSTMENT KIT RIGHT	22.08	1	\$22.08
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	PTX82180	SILICONE	7.41	1	\$7.41
03-13-002	REPLACE NEW REAR BRAKES & DRUMS/ROTORS	VICJ17829	AXLE FLANGE GASKET	2.28	2	\$4.56
				•	PARTS	640.80

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 3395

## **Work Order Notes**

(LPATE) PM AND DUE FOR YEARLY SAFETY INSPECTION-REPLACE REAR BRAKES-RR TAILIGHT BULB OUT

### **Job Notes**

#### 03-13-002 - REPLACE NEW REAR BRAKES & DRUMS/ROTORS

(LPATE) NPORT AUTO TURNED DRUMS P0021179---GARAGE REPLACED WHEEL CYLINDERS, DRUMS, WHEEL STUDS, SHOES, SEALS, AND ADJUSTMENT KITS FOR BOTH SIDES

## 03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED RIGHT REAR TAILIGHT BULB

## 10-01 - SERVICE AIR CONDITIONING, HEAT, VENT

(LPATE) PER TRANSICOLD INV. CHECK SYSTEM, COMPRESSOR NOT COMING ON, CHECKED POWER IN MASTER PANEL, POWER NOT GOING THROUGH THERMOST. REPLACED THERMOSTAT. TRIED TO START COMPRESSOR TO FIND THE COMPRESSOR BAD, HAD TO ORDER COMPRESSOR, WILLHAVE TO RETURN TO BUS TO INSTALL AT ANOTHER TIME FOUND THE EXPANSION VALVE STOPPED UP, R&R VALVE RETURNED TO BUS FOR COMPRESSOR INSTALL, EVAC AND CHARGE SYSTEM WITH 4 LBS OF FREON. RAN SYSTEM FOR OPERATION, UNIT RUNNING AND COOLING PROPERLY. P0021229

### 66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) COMPLETED SAFETY INSPECTION- REPLACED REAR BRAKES HAD DRUMS TURNED BY NPORT AUTO LEFT DRUM IS 331.73MM=13.48 AND RIGHT DRUM IS 330.10MM=13.027..NO VISIBLE LEAKS-A/C WAS NOT COOLY WELL TRANSICOLD COMING TO SVC-SWEPT OUT EVERYTHING ELSE LOOKED OK---COPY OF INSPECTIO CHECKLIST ATTACHED TO WORK ORDER

#### 66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

Parts For Job Include: Part 10W-30 OIL BULK Qty 176 Cost 0 Part 51061 FILTER-OIL Qty 1 Cost 0 (LPATE) PM BY TF

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

USING DEPT NO: 208185 OPENED DATE: 11/14/2019 09:21:27 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 11/27/2019 10:02:19
 METER 1 - M:
 41694
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 11/27/2019 10:02:21
 IN-SERVICE DATE:
 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<b>RSN</b>	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABOR</u>	<b>MATERIAL</b>	COMMERCIAL	TOTAL COST
03-01-049	REPLACE NEW BLEND DOOR MOTOR/	DON	0	Ν	GARAGE	0.55	\$39.69	\$34.45	\$0.00	\$74.14
03-41-007	REPLACE NEW VACUUM LINE(S)	DON	0	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
03-42-004	REPLACE NEW WATER PUMP	DON	0	N	GARAGE	2.76	\$200.00	\$76.41	\$0.00	\$276.41
03-42-006	REPLACE NEW THERMOSTATS	DON	0	N	GARAGE	1.71	\$123.91	\$17.98	\$0.00	\$141.89
35-01	DIAGNOSE AIR CONDITIONING, HEAT,	DON	0	N	GARAGE	2.05	\$148.56	\$0.00	\$0.00	\$148.56

JOB COUNT: 5		WORK ORDER TO	OTAL: 7.56	548.41	128.84	0.00	677.25	
Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>		Quantity	Total Cost	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/20/2019 09:30:00	11/20/2019 10:07:25		0.62	\$45.21	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/20/2019 09:07:10	11/20/2019 09:15:00		0.13	\$9.47	
03-42-006	REPLACE NEW THERMOSTATS	11310047	11/20/2019 07:06:47	11/20/2019 09:07:10		(2.01)	(\$145.46)	
03-42-006	REPLACE NEW THERMOSTATS	11310047	11/20/2019 07:06:47	11/20/2019 09:07:10		2.01	\$145.46	
03-42-006	REPLACE NEW THERMOSTATS	11310047	11/20/2019 07:06:47	11/20/2019 07:36:47		0.50	\$36.25	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/19/2019 15:24:33	11/19/2019 15:52:54		0.47	\$34.26	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/19/2019 13:00:08	11/19/2019 13:42:01		0.70	\$50.61	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/19/2019 11:38:04	11/19/2019 11:57:33		0.32	\$23.54	
03-42-004	REPLACE NEW WATER PUMP	11310047	11/18/2019 15:23:20	11/18/2019 15:53:53		0.51	\$36.91	
03-42-006	REPLACE NEW THERMOSTATS	11310047	11/18/2019 10:41:20	11/18/2019 11:53:53		1.21	\$87.66	
03-41-007	REPLACE NEW VACUUM LINE(S)	11310047	11/25/2019 07:00:00	11/25/2019 07:30:00		0.50	\$36.25	
03-01-049	REPLACE NEW BLEND DOOR MOTOR/ACTUATOR	11310047	11/22/2019 07:06:13	11/22/2019 07:39:04		0.55	\$39.69	
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	11/21/2019 09:52:50	11/21/2019 11:55:47		2.05	\$148.56	
						LABOR	548.41	

**Description** 

OIL ABSORMENT MAT

Part No.

**PIGMAT** 

REPLACE NEW WATER PUMP

**Job Description** 

Job Code

03-42-004

\$2.88

**Total Cost** 

Quantity

**Unit Price** 

0.72

Job Code	Job Description	Part No.	<b>Description</b>	<b>Unit Price</b>	Quantity	<b>Total Cost</b>
03-01-049	REPLACE NEW BLEND DOOR MOTOR/ACTUATOR	FOR73007	HVAC ACTUATOR	34.45	1	\$34.45
03-42-004	REPLACE NEW WATER PUMP	GWP43315	NEW WATER PUMP	32.84	1	\$32.84
03-42-006	REPLACE NEW THERMOSTATS	DLI131151	THERMOSTAT	17.98	1	\$17.98
03-42-004	REPLACE NEW WATER PUMP	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	(2)	(\$19.58)
03-42-004	REPLACE NEW WATER PUMP	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	3	\$29.37
03-42-004	REPLACE NEW WATER PUMP	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	(3)	(\$29.37)
03-42-004	REPLACE NEW WATER PUMP	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	4	\$39.16
03-42-004	REPLACE NEW WATER PUMP	PIGMAT	OIL ABSORMENT MAT	0.72	(8)	(\$5.76)
03-42-004	REPLACE NEW WATER PUMP	20 CLAMP	CLAMP 3/4-1 3/4	0.41	1	\$0.41
03-42-004	REPLACE NEW WATER PUMP	28 CLAMP	CLAMP 1 5/16-2 1/4	0.40	1	\$0.40
03-42-004	REPLACE NEW WATER PUMP	10 CLAMP	CLAMP 9/16-1 1/16	0.36	2	\$0.72
03-42-004	REPLACE NEW WATER PUMP	PIGMAT	OIL ABSORMENT MAT	0.72	8	\$5.76
03-42-004	REPLACE NEW WATER PUMP	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	9.79	2	\$19.58
					PARTS	128.84

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 34860

**Work Order Notes** 

(LISAPATE) Heater wont heat up at all-blows cold

**Job Notes** 

03-01-049 - REPLACE NEW BLEND DOOR MOTOR/ACTUATOR

(LISAPATE) Replaced faulty temp door actuator

03-41-007 - REPLACE NEW VACUUM LINE(S)

(LISAPATE) Replaced collapsed vacuum line. Rechecked ok

03-42-004 - REPLACE NEW WATER PUMP

(LISAPATE) Replaced water pump

03-42-006 - REPLACE NEW THERMOSTATS

(LISAPATE) Replaced thermostat

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) Found water pump leaking and vacuum line collapsed. EH,MS,IF

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 35397

USING DEPT NO: 208185 OPENED DATE: 01/14/2020 11:54:04 LOCATION: GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 02/04/2020 06:43:09
 METER 1 - M:
 41801
 METER 2 - N:
 0

 WO VISIT REASON:
 SCHEDULED
 CLOSED DATE:
 02/04/2020 06:43:11
 IN-SERVICE DATE:
 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	<b>MATERIAL</b>	COMMERCIAL	TOTAL COST
03-41-008	REPLACE NEW INTAKE GASKET(S)	DON	0	Ν	GARAGE	8.58	\$621.93	\$65.12	\$0.00	\$687.05
03-42-006	REPLACE NEW THERMOSTATS	DON	0	N	GARAGE	0.50	\$36.25	\$7.69	\$0.00	\$43.94
03-42-013	REPLACE NEW HOSES, COOLING SYS	DON	0	N	GARAGE	2.36	\$170.98	\$26.86	\$0.00	\$197.84
03-42-022	REPLACE NEW RADIATOR CAP	DON	0	N	GARAGE	0.63	\$45.92	\$3.74	\$0.00	\$49.66
06-42	INSPECT COOLING SYSTEM	DON	0	N	GARAGE	0.55	\$40.14	\$0.00	\$0.00	\$40.14
66-79-003	PERFORM SAFETY INSPECTION	DON	Р	N	GARAGE	2.00	\$145.00	\$0.00	\$0.00	\$145.00
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.31	\$22.48	\$14.67	\$0.00	\$37.15

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/29/2020 07:00:00	01/29/2020 07:18:36	0.31	\$22.48

**WORK ORDER TOTAL:** 

1,082.70

118.08

14.93

66-PM-PMA	PERFORM OIL CHANGE	12052187	01/29/2020 07:00:00	01/29/2020 07:18:36	0.31	\$22.48
03-42-022	REPLACE NEW RADIATOR CAP	11310047	01/27/2020 13:00:40	01/27/2020 13:38:40	0.63	\$45.92
03-41-008	REPLACE NEW INTAKE GASKET(S)	11310047	01/27/2020 07:00:36	01/27/2020 08:15:42	1.25	\$90.75
03-41-008	REPLACE NEW INTAKE GASKET(S)	11310047	01/24/2020 13:17:39	01/24/2020 15:38:37	2.35	\$170.33
03-41-008	REPLACE NEW INTAKE GASKET(S)	11310047	01/24/2020 08:50:22	01/24/2020 12:13:39	3.39	\$245.63
03-41-008	REPLACE NEW INTAKE GASKET(S)	11310047	01/23/2020 13:58:08	01/23/2020 15:33:29	1.59	\$115.21
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	01/21/2020 13:01:38	01/21/2020 13:14:16	0.21	\$15.27
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	01/21/2020 11:44:50	01/21/2020 11:54:09	0.16	\$11.26
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	01/17/2020 14:51:00	01/17/2020 15:54:28	1.06	\$76.69
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	01/17/2020 14:30:00	01/17/2020 14:33:30	0.06	\$4.23
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	01/17/2020 13:22:25	01/17/2020 14:15:00	0.88	\$63.54
06-42	INSPECT COOLING SYSTEM	11310047	01/17/2020 07:59:41	01/17/2020 08:32:54	0.55	\$40.14
03-42-006	REPLACE NEW THERMOSTATS	11310047	01/29/2020 07:00:00	01/29/2020 07:30:00	0.50	\$36.25
66-79-003	PERFORM SAFETY INSPECTION	12052187	01/29/2020 07:00:00	01/29/2020 09:00:00	2.00	\$145.00

JOB COUNT: 7

1,200.78

0.00

1082.70	LABOR	•				
Total Cost	Quantity	Unit Price	<u>Description</u>	Part No.	Job Description	Job Code
\$0.38	1	0.38	CLAMP 9/16-1 1/4	12 CLAMP	PERFORM OIL CHANGE	66-PM-PMA
\$0.35	1	0.35	HOSE CLAMPS	4 CLAMP	PERFORM OIL CHANGE	66-PM-PMA
\$8.58	2	4.29	BRAKE CLEAN NON-FLAMMABLE 14OZ	05089	REPLACE NEW INTAKE GASKET(S)	03-41-008
\$19.58	2	9.79	ANTIFREEZE-GM	ANTIFREEZE DEXCOOL	REPLACE NEW HOSES, COOLING SYSTEM	03-42-013
(\$9.79)	(1)	9.79	ANTIFREEZE-GM	ANTIFREEZE DEXCOOL	REPLACE NEW HOSES, COOLING SYSTEM	03-42-013
\$0.72	2	0.36	CLAMP 9/16-1 1/16	10 CLAMP	REPLACE NEW HOSES, COOLING SYSTEM	03-42-013
\$9.79	1	9.79	ANTIFREEZE-GM	ANTIFREEZE DEXCOOL	REPLACE NEW HOSES, COOLING SYSTEM	03-42-013
\$6.56	1	6.56	BYPASS HOSE	11025	REPLACE NEW HOSES, COOLING SYSTEM	03-42-013
\$11.82	6	1.97	OIL QT BOTTLE 10W30SEMI THOMAS	10W30TQT	PERFORM OIL CHANGE	66-PM-PMA
\$2.12	1	2.12	LUBE SPIN-ON FILTER	BALB1428	PERFORM OIL CHANGE	66-PM-PMA
\$7.69	1	7.69	OE DESIGN TSTAT 192F JV PREM	PM1955625	REPLACE NEW THERMOSTATS	03-42-006
(\$7.60)	(1)	7.60	OE DESIGN TSTAT 192F JV PREM	PM1955625	REPLACE NEW THERMOSTATS	03-42-006
\$3.74	1	3.74	RADIATOR CAP	7031699	REPLACE NEW RADIATOR CAP	03-42-022
\$7.60	1	7.60	OE DESIGN TSTAT 192F JV PREM	PM1955625	REPLACE NEW THERMOSTATS	03-42-006
\$56.54	1	56.54	INTAKE MANIFOLD GASKET SET	MS98000T	REPLACE NEW INTAKE GASKET(S)	03-41-008
118.08	PARTS	•				

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 35397

# **Work Order Notes**

(LISAPATE) PM

## **Job Notes**

03-41-008 - REPLACE NEW INTAKE GASKET(S)

(LISAPATE) Replaced upper and lower intake manifold gaskets

03-42-006 - REPLACE NEW THERMOSTATS

(LISAPATE) Replaced thermostat

03-42-013 - REPLACE NEW HOSES, COOLING SYSTEM

(LISAPATE) Replaced bypass hose on top of the water pump. Added coolant and test drove. ok

03-42-022 - REPLACE NEW RADIATOR CAP

(LISAPATE) Installed new radiator cap

06-42 - INSPECT COOLING SYSTEM

(LISAPATE) Checked found the intake was leaking coolant

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Performed safety inspection. See attached

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include: Part 1061MP FILTER-OIL Qty 1 Cost 2.120000 (LISAPATE) PM by JW/SH Coolant -34'

UNIT NO: 232451 2003			03 CHEVROI	ET BL	UE BIF	RD		WORK ORDER NO: 3			446	
USING DEPT NO: WO STATUS: WO VISIT REASON: TECH SPEC NO:		208185 CLOSED SCHEDULED 03BUSBLUEBIRD	СОМІ	ED DAT LETED ED DAT let Blue	DATE:	05/19/202 05/21/202	05/15/2020 08:04:28 05/19/2020 15:23:26 05/21/2020 14:33:34		: GARAGE M: 41924 EDATE: ALNO:	ME 02/20/200		Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	STA	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	MMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	M OIL CHANGE	DON	Р	N	GARAGE	1.60	\$116.18	\$22.70	\$0.	00	\$138.88
CH-32-002	CHARGE	BATTERY	DON	Р	N	GARAGE	0.80	\$58.18	\$0.00	\$0.	00	\$58.18
JOB COUN	IT: 2			WC	ORK ORI	DER TOTAL:	2.41	174	.36	22.70	0.00	197.0
Job Code		Job Description		<u>Er</u>	nployee	No.	<u>Start</u>	!	<u>Finish</u>		Quantity	Total Cost
CH-32-002	CHARGE BA	TTERY		1205218	7	05/	18/2020 07:57:00	05/18/202	20 08:45:09		0.80	\$58.1
66-PM-PMA	PERFORM C	OIL CHANGE		1190135	7	05/	15/2020 11:02:04	05/15/202	20 11:52:24		0.84	\$60.8
66-PM-PMA	PERFORM C	OIL CHANGE		1205218	7	05/	15/2020 10:45:23	05/15/202	20 11:31:12		0.76	\$55.3
06-43	INSPECT EX	HAUST SYSTEM		11170580	)	05/	18/2020 08:56:37	05/18/202	20 09:15:00		(0.31)	(\$22.2
06-43	INSPECT EX	HAUST SYSTEM		11170580	)	05/	18/2020 09:30:00	05/18/202	20 09:39:23		(0.16)	(\$11.3
06-43	INSPECT EX	HAUST SYSTEM		11170580	)	05/	18/2020 09:30:00	05/18/202	20 09:39:23		0.16	\$11.3
06-43	INSPECT EX	HAUST SYSTEM		11170580	)	05/	18/2020 08:56:37	05/18/202	20 09:15:00		0.31	\$22.2
											LABOR	174.3
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription	<u> </u>	Jnit Price	Quantity	Total Cost
66-PM-PMA	PERFORM C	OIL CHANGE		10W30B	Г	BU	LK OIL 10W30 SE	EMI-SYN THON	MAS	1.99	5	\$9.9
66-PM-PMA	PERFORM C	OIL CHANGE		10001		OIL	TREATMENT- C	ONVENTIONA	L	10.04	1	\$10.0
66-PM-PMA	PERFORM C	OIL CHANGE		5W20BT		BU	LK OIL 5W20 SYI	NTHETIC THO	MAS	2.95	(6)	(\$17.7
66-PM-PMA	PERFORM C	OIL CHANGE		5W20BT		BU	LK OIL 5W20 SYI	NTHETIC THO	MAS	2.95	6	\$17.7
66-PM-PMA	PERFORM C	OIL CHANGE		BALB142	28	LU	BE SPIN-ON FILT	ER		2.71	1	\$2.7
											PARTS	22.7

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 36446

# **Work Order Notes**

(IFALLS) PM, charge battery

## **Job Notes**

## 06-43 - INSPECT EXHAUST SYSTEM

(GARAGE) Job 06-43 was added on-the-fly by 11170580 on 05/18/2020 08:57:31. (EKIMBREL) AB found no exhaust leak.

## 66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

The following parts are included with the standard job:

Part No : 1061MP

Qty : 1

Description: FILTER-OIL
Manufacturer: NAPA
Bin: D4C3

(EKIMBREL) JW,AG/JW performed oil change. Added 1qt of Lucas oil. JW did bus inspection

# 66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

#### CH-32-002 - CHARGE BATTERY

(EKIMBREL) JW charged battery over the weekend. Tested good. Alt charging at 14.2V.

UNIT NO: 232451 2003		03 CHE\	/ROLI	ET BL	UE BIF	RD		WORK ORDER NO: 37			7605		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED UNSCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE:	09/18/202	20 10:12:11 20 14:44:35 20 15:39:40	LOCATION: METER 1 - N IN-SERVICE UNIT SERIA	M: 41934 E DATE:	<b>MI</b> 02/20/20	y Automotive S ETER 2 - N: 02 1R621157998	0
JOB CODE	<u> </u>	JOB DESCRIPTION		<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL COST
03-33-002	REPLAC	E NEW DISTRIBUTOR		DON	0	N	GARAGE	1.10	\$79.75	\$116.62	\$0	0.00	\$196.37
20-00	TOWING	COMPLETE VEHICLE		DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$8	5.00	\$85.00
35-32	DIAGNO	SE CRANKING SYSTEI	М	DON	Ο	N	GARAGE	2.91	\$210.77	\$0.00	\$0	0.00	\$210.77
66-79-002	PERFOR	M SERVICE CALL		DON	В	N	GARAGE	1.16	\$84.28	\$0.00	\$0	0.00	\$84.28
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.48	\$35.04	\$0.00	\$0	0.00	\$35.04
SO-05	SCAN O	UT ELECTRONIC ENGI	INE EEC	DON	0	N	GARAGE	2.00	\$145.00	\$0.00	\$0	0.00	\$145.00
JOB COUNT: 6		WORK ORDER TOTAL: 7.69				7.65	554	.84	116.62	85.00	756.46		
Job Code		Job Description			V	endor N	<u>o.</u>	Invoice No.	Purcha	se Order No	<u>o.</u>		Total Cost
20-00	TOWING CO	OMPLETE VEHICLE		11076249		)	69924						\$85.00
												COMML	85.00
Job Code		Job Description			<u>En</u>	nployee	No.	<u>Start</u>	<u>!</u>	<u>inish</u>		Quantity	Total Cost
03-33-002	REPLACE N	IEW DISTRIBUTOR		1	1310047	7	09/	/18/2020 07:00:00	09/18/202	20 08:06:00		1.10	\$79.75
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	7	09/	/17/2020 09:59:48	09/17/202	20 10:28:48		0.48	\$35.04
SO-05	SCAN OUT	ELECTRONIC ENGINE EE	EC SYSTEM	1 1	1310047	7	09/	/18/2020 08:06:00	09/18/202	20 10:06:00		2.00	\$145.00
35-32	DIAGNOSE	CRANKING SYSTEM		1	1310047	,	09/	/17/2020 07:18:05	09/17/202	20 08:05:31		0.79	\$57.32
35-32	DIAGNOSE	CRANKING SYSTEM		1	1310047	7	09/	/16/2020 13:47:01	09/16/202	20 13:56:50		0.16	\$11.86
35-32	DIAGNOSE	CRANKING SYSTEM		1	1310047	7	09/	/15/2020 13:02:30	09/15/202	20 14:59:41		1.95	\$141.60
66-79-002	PERFORM	SERVICE CALL		1	1074414	ļ	09/	/15/2020 10:22:31	09/15/202	20 11:32:16		1.16	\$84.28
												LABOR	554.85
Job Code		Job Description				Part No	:	Des	cription	<u> </u>	Unit Price	Quantity	Total Cost
03-33-002	REPLACE N	IEW DISTRIBUTOR		C	NE8418	329	DIS	STRIBUTOR ASSI	EMBLY NEW		116.62		\$116.62
												PARTS	116.62

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 37605

# **Work Order Notes**

(LISAPATE) Herb requested a service call to BPCC for a dead battery on bus

## **Job Notes**

#### 03-33-002 - REPLACE NEW DISTRIBUTOR

(LISAPATE) Installed a new distributor assembly. The vehicle is now starting properly. (IFALLS) EH

## 20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Bambarger towed bus from BPCC to the shop PD by CC

#### 35-32 - DIAGNOSE CRANKING SYSTEM

(EHOWELL) Found corrosion inside of distributor cap and on rotor button.

Cleaned corrosion and applied a thin coat of sealant around cap. Performed road test. The vehicle is now cranking and running properly. The vehicle would not start the next day. Verified fuel pressure using a fuel pressure gauge. Also, verified that fuel pressure wasn't bleeding down. EH

## 66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Could not get vehicle started. Possibly being towed . SH

#### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 10 miles since last pm. Updated sticker and checked all fluids. Coolant -34° JAW

## **SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM**

(LISAPATE) Connected GM scan tool and verified that there were no current DTCs. Adjusted the cam retard to zero. EH

UNIT NO:	NIT NO: 232451 2003 CH			OLE	T BL	UE BIF	RD		WORK ORDER NO: 39			9170		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	со	MPL OSE	<b>D DAT</b> I ETED I D DATI t Blue E	DATE: E:	03/02/202	21 14:59:53 21 15:16:58 21 08:59:47	LOCATION METER 1 - IN-SERVIC UNIT SERIA	M: 42113 E DATE:	N 02/20/2	ity Automotive : <b>1ETER 2 - N:</b> 002 31R621157998	0	
JOB CODE		JOB DESCRIPTION	<u>S</u> T	AT_	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY	DO	NC	0	Ν	GARAGE	0.10	\$11.80	\$123.60	\$	0.00	\$135.40	
03-44-017	REPLAC	E NEW FUEL TANK CAP	DO	NC	0	Ν	GARAGE	0.10	\$11.80	\$13.42	\$	0.00	\$25.22	
66-79-003	PERFOR	M SAFETY INSPECTION	DO	NC	Υ	N	GARAGE	0.54	\$63.46	\$0.00	\$	0.00	\$63.46	
66-PM-PMA	PERFOR	M OIL CHANGE	DO	NC	Р	N	GARAGE	0.54	\$63.23	\$19.74	\$	0.00	\$82.97	
JOB COUNT: 4				wo	RK ORI	DER TOTAL:	1.27	150	).29	156.76	0.00	ı	307.05	
Job Code		Job Description		Employee No.		No.	<u>Start</u>		<u>Finish</u>		Quantity	<u>Total</u>	Cost	
66-79-003	PERFORM S	SAFETY INSPECTION		11	1901357		02/	/25/2021 15:07:41	02/25/20	21 15:39:57		0.54		\$63.46
66-PM-PMA	PERFORM (	OIL CHANGE		11	1901357		02/	/25/2021 14:34:35	02/25/20	21 15:06:44		0.54		\$63.23
03-32-002	REPLACE N	EW BATTERY		11	1901357		02/	/25/2021 12:19:08	02/25/20	21 12:25:08		0.10		\$11.80
03-32-002	REPLACE N	EW BATTERY		11	1901357		02/	/25/2021 12:19:08	02/25/20	21 12:19:08		0.00		\$0.00
03-32-002	REPLACE N	EW BATTERY		11	1901357		02/	/25/2021 12:19:08	02/25/20	21 12:19:08		0.00		\$0.00
03-44-017	REPLACE N	EW FUEL TANK CAP		11	1901357		03/	/02/2021 07:00:00	03/02/20	21 07:06:00		0.10		\$11.80
												LABOR		150.29
Job Code		Job Description				Part No	•	<u>Des</u>	cription		Unit Price	Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	EW BATTERY		78	31		ВА	TTERY BCI 78 77	0 CCA		123.6	0 1		\$123.60
66-PM-PMA	PERFORM (	OIL CHANGE		10	0001		OII	_TREATMENT- C	ONVENTIONA	<b>L</b>	15.4	2 1		\$15.42
66-PM-PMA	PERFORM (	OIL CHANGE		В	ALB142	8	LU	BE SPIN-ON FILT	ER		4.3	2 1		\$4.32
03-44-017	REPLACE N	EW FUEL TANK CAP		S	TA10836	6	FU	EL TANK CAP			13.4			\$13.42
												PARTS		156.76

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 39170

### **Work Order Notes**

(LISAPATE) PM-Per Herb unit keeps going dead had to jump off a few times-also due for annual safety inspection

#### **Job Notes**

#### 03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery and checked charging system, good at 14.4 volts. AMG

#### 03-44-017 - REPLACE NEW FUEL TANK CAP

(LISAPATE) Installed new fuel tank cap

#### 66-79-003 - PERFORM SAFETY INSPECTION

(AGUERRA) miles: 42113 Completed safety inspection, and safety inspection checklist, no issues found. Josh assisted. AMG JW

#### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 42113 Completed PM bottom side, assisted Scott top side. Completed checklist. Vacuumed drivers compartment and washed vehicle. AMG SH

UNIT NO:		232451	2003 CHE\	/ROLE	ET BL	UE BIF	RD		WORK OR	DER NO	D: 4	40055		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED I	DATE:	06/02/202 06/03/202	21 10:41:13 21 09:17:21 21 09:28:49	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 42123 <b>DATE</b> :	02/20/2		Services 0	
JOB CODE		JOB DESCRIPTI	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MAT	ERIAL	COMMERCIAL	TOTAL COS	<u>.T</u>
06-79-021	INSPECT	SCHOOL BUS ST	OP ARM ASS	DON	0	Ν	GARAGE	1.40	\$165.69	\$0.00	9	\$0.00	\$165.69	
24-79-021	REPAIR :	SCHOOL BUS STO	PARM ASSY	DON	0	N	GARAGE	0.82	\$96.53	\$58.78	9	\$0.00	\$155.31	
JOB COUN	IT: 2				WO	RK ORI	DER TOTAL	: 2.22	262.2	22	58.78	0.00	321.	.00
Job Code		Job Descript	tion_		<u>Em</u>	ployee	No.	<u>Start</u>	<u>F</u>	nish_		Quantity	Total Cost	<u>:</u>
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	1	1213180		06	8/01/2021 10:04:22	06/01/2021	10:53:27		0.82	\$96	5.53
06-79-021	INSPECT SO	CHOOL BUS STOP A	RMASSY	1	1213180		06	6/01/2021 09:30:00	06/01/2021	10:04:14		0.57	\$67	7.33
06-79-021	INSPECT SO	CHOOL BUS STOP A	RM ASSY	1	1213180		06	6/01/2021 08:24:59	06/01/2021	09:15:00		0.83	\$98	3.37
												LABOR	262	.23
Job Code		Job Descript	tion_			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	e Quantity	Total Cost	
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	Р	IC5592F	T	W	ATERPROOF REL	AY 5 PIN		8.5	58 2	\$17	7.16
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	Р	IC5653F	Т	FL	ASHER PIGTAIL			5.2	21 2	\$10	0.41
24-79-021	REPAIR SCI	HOOL BUS STOP AR	M ASSY	Р	IC2238F	T	HE	EAT SHRINK			5.8	37 1	\$5	5.87
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	S	TIDS278	BT .	DO	OOR JAMB SWITC	CH		9.7	71 1	\$9	9.71
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	Р	IC1765K	T	22	2-16GA FEMALE S	PADE INSUL 10	>	3.2	23 1	\$3	3.23
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	Р	IC2228F	T	HE	EAT SHRINK			5.2	21 1	\$5	5.21
24-79-021	REPAIR SCH	HOOL BUS STOP AR	M ASSY	8	2180		Ul	TRA BLACK RTV			7.1	191	\$7	7.19
												PARTS	58	3.78

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 40055

**Work Order Notes** 

(LISAPATE) Per Herb the top sign is not working.

### **Job Notes**

#### 06-79-021 - INSPECT SCHOOL BUS STOP ARM ASSY

(MSIDES) Found relay in stop arm housing to be corroded causing it to be inop. Found the other relay and all relay connectors to show severe corrosion. Recommend replacement of both relays and rewiring. MS

#### 24-79-021 - REPAIR SCHOOL BUS STOP ARM ASSY

(MSIDES) Replaced both relays and completely rewired.MS

UNIT NO:		3 CHEVROL	ET BL	UE BIF	RD		WORK	ORDER NO	): 40 <sub>-</sub>	495		
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	OPENI COMP CLOSI 2003 Chevrole	ETED	DATE: E:	07/23/202 07/27/202	1 09:15:26 1 10:09:42 1 15:24:17	METER 1	N: GARAGE -M: 42847 CE DATE: RIAL NO:	<b>ME</b> 02/20/200	TER 2 - N:	Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABO</u>	R MATE	RIAL CO	MMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.05	\$5.41	\$14.67	\$0.0	00	\$20.08
35-54-003	DIAGNO	SE WARNING BUZZER	DON	0	Ν	GARAGE	0.38	\$45.17	\$0.00	\$0.0	00	\$45.17
66-79-003	PERFOR	RM SAFETY INSPECTION	N DON	Υ	Ν	GARAGE	0.10	\$11.80	\$0.00	\$0.0	00	\$11.80
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.30	\$35.33	\$0.00	\$0.0	00	\$35.33
JOB COUN	IT: 4			wc	RK ORI	DER TOTAL:	0.83	!	97.71	14.67	0.00	112.38
Job Code		Job Description		<u>En</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		Quantity	Total Cost
66-79-003	PERFORM	SAFETY INSPECTION	•	1074414	1	07/	23/2021 07:00:00	07/23/2	2021 07:06:00		0.10	\$11.80
35-54-003	DIAGNOSE	WARNING BUZZER	•	1213180	)	07/	22/2021 11:59:31	07/22/2	2021 12:22:29		0.38	\$45.17
03-51-038	REPLACE N	IEW WIPER BLADES	,	1074414	1	07/	22/2021 11:36:06	07/22/2	2021 11:38:51		0.05	\$5.41
66-PM-PMA	PERFORM (	OIL CHANGE	,	1074414	1	07/	22/2021 11:17:51	07/22/2	2021 11:35:49		0.30	\$35.33
											LABOR	97.71
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	<u>cription</u>		Unit Price	Quantity	Total Cost
03-51-038	REPLACE N	IEW WIPER BLADES	2	2-1		WII	PER BLADE 22" T	RICO EXAC	СТ	7.34	2	\$14.67
											PARTS	14.67

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 40495

### **Work Order Notes**

(LISAPATE) PM-Check window buzzers go off while driving down the road

#### **Job Notes**

#### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

#### 35-54-003 - DIAGNOSE WARNING BUZZER

(IFALLS) Found driver side emergency exit window bracket to be out of adjustment causing alarm to set. Adjusted bracket and rechecked ok. MS

#### 66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) Performed safety inspection no issues found

#### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 42847. Vehicle has been driven 1734 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

232451

**2003 CHEVROLET BLUE BIRD** 

**UNIT NO:** 

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

41563

**WORK ORDER NO:** 

					<u> </u>					-			
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COMP	ED DAT LETED ED DAT et Blue	DATE: E:	11/12/202	21 10:47:22 21 15:08:57 21 09:12:18	LOCATION: METER 1 - M IN-SERVICE UNIT SERIA	1: 42990 DATE:	<b>M</b> I 02/20/20	ty Automotive S ETER 2 - N: 1002 11R621157998	0	
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-32-010	REPLAC	E NEW STARTER	DON	0	N	GARAGE	0.91	\$107.87	\$134.13	\$0	0.00	\$242.00	
03-51-038	REPLAC	E NEW WIPER BLADES	DON	Р	N	GARAGE	0.13	\$15.50	\$15.18	\$0	0.00	\$30.68	
66-79-002	PERFOR	RM SERVICE CALL	DON	В	N	GARAGE	0.97	\$114.95	\$0.00	\$0	0.00	\$114.95	
66-79-003	PERFOR	RM SAFETY INSPECTION	DON	Υ	N	GARAGE	0.50	\$59.00	\$0.00	\$0	0.00	\$59.00	
66-PM-PMA		RM OIL CHANGE	DON	Р	N	GARAGE	1.31	\$154.55	\$56.85	\$0	0.00	\$211.40	
CH-SP		E Shop Supplies	DON	2	N	GARAGE		\$0.00	\$0.00		2.00	\$2.00	
			DON										
JOB COUN	T: 6			WC	ORK ORI	DER TOTAL:	3.83	451.	.87	206.16	2.00		660.03
Job Code		Job Description		<u>v</u>	<u>/endor N</u>	<u>o.</u>	Invoice No.	Purchas	se Order N	<u>o.</u>		<u>Total</u> (	Cost
CH-SP	CHARGE S	hop Supplies		503163		1							\$2.0
											COMML		2.00
Job Code		<b>Job Description</b>		<u>En</u>	nployee	<del></del>	<u>Start</u>	_	<u>inish</u>		<b>Quantity</b>	<u>Total (</u>	<u>Cost</u>
66-79-003	PERFORM	SAFETY INSPECTION	•	11901357	7	11/	/12/2021 07:00:00	11/12/202	1 07:30:00		0.50		\$59.00
66-PM-PMA	PERFORM	OIL CHANGE		11901357	7	11/	/10/2021 13:18:20	11/10/202	1 14:03:08		0.75		\$88.1
66-PM-PMA	PERFORM	OIL CHANGE		11901357	7	11/	/10/2021 12:01:13	11/10/202	1 12:02:08		0.02		\$1.80
66-PM-PMA	PERFORM	OIL CHANGE		11901357	7	11/	/10/2021 10:21:28	11/10/202	1 10:54:20		0.55		\$64.64
03-51-038	REPLACE 1	NEW WIPER BLADES	•	11901357	7	11/	/10/2021 09:40:53	11/10/202	1 09:48:46		0.13		\$15.50
03-32-010	REPLACE 1	NEW STARTER	•	11901357	7	11/	/10/2021 08:45:20	11/10/202	1 09:40:11		0.91		\$107.87
66-79-002	PERFORM	SERVICE CALL		11901357	7	11/	/10/2021 08:26:20	11/10/202	1 08:44:38		0.31		\$35.99
66-79-002	PERFORM	SERVICE CALL		11901357	7	11/	/09/2021 15:07:11	11/09/202	1 15:47:20		0.67		\$78.96
											LABOR		451.87
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	Quantity	Total (	Cost
66-PM-PMA	PERFORM	OIL CHANGE	•	10W30T0	TÇ	OII	L QT BOTTLE 10V	W30SEMI THON	MAS	7.41	5		\$37.0
66-PM-PMA	PERFORM OIL CHANGE 10W30TQT			OII	L QT BOTTLE 10V	W30SEMI THON	MAS	7.40	(6)	)	(\$44.37		
03-32-010	REPLACE I	REPLACE NEW STARTER			35	RE	EMAN STARTER			134.13	1		\$134.1
FleetFocus M5	- WODETAIL	Work Order Detail v20.0											Page:1

### The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

**Job Description Unit Price** Job Code Part No. **Total Cost** Description Quantity 66-PM-PMA PERFORM OIL CHANGE 10001 OIL TREATMENT- CONVENTIONAL 15.48 \$15.48 2 03-51-038 REPLACE NEW WIPER BLADES 22-1 WIPER BLADE 22" TRICO EXACT 7.59 \$15.18 66-PM-PMA PERFORM OIL CHANGE **BALB1428** LUBE SPIN-ON FILTER 4.32 \$4.32 66-PM-PMA 10W30TQT OIL QT BOTTLE 10W30SEMI THOMAS 7.40 \$44.37 PERFORM OIL CHANGE **PARTS** 206.16

Work Order Charge Detail

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 41563

### **Work Order Notes**

(LISAPATE) Herb requested a service call to BPCC unit just clicks wont start

#### **Job Notes**

#### 03-32-010 - REPLACE NEW STARTER

(AGUERRA) Replaced starter and checked for proper operation, all good. AMG

#### 03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers, AMG

#### 66-79-002 - PERFORM SERVICE CALL

(AGUERRA) miles: 43075 Vehicle was found to have a bad starter, got it to start and brought back to shop for repairs. AMG

#### 66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SI completed by AG

#### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 43075 Completed PM top and bottom side. Completed checklist and bus inspection checklist. AMG/AMG

### **CH-SP - CHARGE Shop Supplies**

UNIT NO:		232451	2003 CHE\	/ROLE	ET BL	UE BIF	RD		WORK O	RDER NO:	4305	3		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRI		OPENE COMPL CLOSE Chevrole	ETED	DATE:	05/12/20 05/18/20	22 15:14:13 22 15:38:36 22 14:24:52				R 2 - N:	0	
JOB CODE		JOB DESCRIPTI	<u>ON</u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	L COMI	MERCIAL	TOTAL C	OST
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	N	GARAGE	0.05	\$5.44	\$15.18	\$0.00		\$20.62	
35-01	DIAGNO	SE AIR CONDITIO	NING, HEAT, '	DON	0	N	GARAGE	0.38	\$44.91	\$0.00	\$0.00		\$44.91	
66-01-058	PERFOR	RM EVAC AND REC	CHARGE FRE	DON	0	N	GARAGE	0.12	\$13.87	\$37.81	\$0.00		\$51.68	
66-17-013	PERFOR	RM ALIGNMENT		DON	0	N	GARAGE	1.33	\$157.24	\$0.00	\$0.00		\$157.24	
66-17-028	PERFOR	RM MOUNT AND B	ALANCE TIRE	DON	Ο	N	GARAGE	1.25	\$147.50	\$1,036.04	\$0.00		\$1,183.54	
66-PM-PMA	PERFOR	RM OIL CHANGE		DON	Р	N	GARAGE	2.46	\$290.58	\$0.00	\$0.00		\$290.58	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00		\$2.00	
JOB COUN	IT: 7				WO	RK ORI	DER TOTAL	: 5.59	659	9.54 1,089.	.03	2.00	1,7	750.57
Job Code CH-SP	CHARGE SI	Job Descrip	<u>tion</u>	5	<b>V</b> 03163	<u>endor N</u>	<b>lo.</b> 1	Invoice No.	<u>Purcha</u>	ase Order No.			Total Co	ost \$2.00
											(	COMML		2.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	ployee	No.	<u>Start</u>		<u>Finish</u>	<u>(</u>	Quantity	Total Co	<u>ost</u>
66-01-058	PERFORM	EVAC AND RECHAR	GE FREON	1	1310047	•	05	5/10/2022 13:01:04	05/10/20	22 13:08:07		0.12		\$13.87
35-01	DIAGNOSE	AIR CONDITIONING	, HEAT, VENT	1	1310047	•	05	5/10/2022 08:03:09	05/10/20	22 08:04:21		0.02		\$2.36
35-01	DIAGNOSE	AIR CONDITIONING	, HEAT, VENT	1	1310047	•	05	5/09/2022 14:26:21	05/09/20	22 14:47:59		0.36		\$42.55
66-PM-PMA	PERFORM (	OIL CHANGE		1	2052187	7	04	1/28/2022 07:39:03	04/28/20	22 07:40:14		0.02		\$2.33
03-51-038	REPLACE N	IEW WIPER BLADES	<b>3</b>	1	2052187	7	04	1/28/2022 07:36:08	04/28/20	22 07:38:54		0.05		\$5.44
66-PM-PMA	PERFORM	OIL CHANGE		1	2052187	,	04	1/27/2022 13:25:59	04/27/20	22 15:52:33		2.44	\$	288.25
66-17-013	PERFORM A	ALIGNMENT		1	1310047	•	05	5/09/2022 10:35:42	05/09/20	22 11:55:39		1.33	\$	5157.24
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	1	2052187	7	05	5/05/2022 13:00:00	05/05/20	22 14:15:00		1.25	\$	147.50
66-17-028	PERFORM I	MOUNT AND BALAN	CE TIRES	1	2052187	,	05	5/05/2022 12:57:07	05/05/20	22 12:57:07		0.00		\$0.00
												LABOR	•	659.54
Job Code		Job Descrip	tion			Part No	<u>.</u>	Des	cription	Unit	Price (	Quantity	Total Co	<u>ost</u>

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.81	2	\$1.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.57	3	\$1.71
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	2	\$0.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.84	1	\$0.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	61	\$8.24
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	(61)	(\$8.24)
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	61	\$8.24
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.08	3	\$3.24
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.98	27	\$26.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	166.91	6	\$1,001.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	166.91	(6)	(\$1,001.43)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002760	TIRE LT225/75R16 FS TRANSF HT2	166.91	6	\$1,001.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	4.79	6	\$28.71
					PARTS	1089.03

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 43053

### **Work Order Notes**

(LISAPATE) PM

#### **Job Notes**

#### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

#### 35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(EHOWELL) The vehicle was approximately 1.6 lb. low on refrigerant. EH

#### 66-01-058 - PERFORM EVAC AND RECHARGE FREON

(EHOWELL) Recovered 3.84 lb. of refrigerant from the vehicle. Drained 5.6 oz of oil. Pulled a vacuum on the vehicle. Injected 3 oz of ester oil with dye. Charged vehicle with 5.5 lb. of refrigerant. The ac is blowing cool. EH

#### 66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Adjusted right front camber, caster, and toe. Adjusted left front toe. EH

#### 66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced all 6 tires. Aired balanced and torqued to spec. JAW

#### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been driven 200 miles since last pm. Updated sticker. Checked fluids and tires. Tires are out of date consulting with department about replacing. Coolant -34°. JAW

MILEAGE-43345

### **CH-SP - CHARGE Shop Supplies**

Page:1

# Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		232451 2003 CHEV				UE BIF	RD		WORK OR	DER NO	: 4	4325		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRI		COMP	ED DAT LETED ED DAT et Blue l	DATE:	09/15/20 09/16/20	022 09:25:33 022 14:56:28 022 07:48:59	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	: 43539 <b>DATE</b> :	<b>M</b> 02/20/20	ty Automotive S IETER 2 - N: 002 31R621157998		
JOB CODE		JOB DESCRIPT	<u>ION</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATE	RIAL C	OMMERCIAL	TOTAL	COST
03-01-068	REPLAC	E NEW AUX UNIT	REAR BLOW	DON	0	N	GARAGE	2.40	\$283.23	\$478.62	\$0	0.00	\$761.85	
03-51-038	REPLAC	E NEW WIPER BL	ADES	DON	Р	Ν	GARAGE	0.05	\$5.31	\$15.54	\$0	0.00	\$20.85	
03-54-002	REPLAC	E NEW ALARM - E	BACK-UP	DON	0	N	GARAGE	0.60	\$70.87	\$48.00	\$0	0.00	\$118.87	
35-01-004	DIAGNO	SE BLOWER MOT	OR	DON	0	Ν	GARAGE	0.31	\$36.71	\$0.00	\$0	0.00	\$36.71	
66-PM-PMA	PERFOR	M OIL CHANGE		DON	Р	N	GARAGE	0.70	\$82.31	\$38.35	\$0	0.00	\$120.66	
CH-SP	CHARGE	Shop Supplies		DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00	
JOB COUN	IT: 6				WC	RK ORI	DER TOTAL	.: 4.05	478.4	13	580.51	5.00	,	1,063.94
Job Code		Job Descrip	<u>tion</u>		<u>v</u>	endor N	lo.	Invoice No.	Purchas	e Order No	<u>).</u>		<u>Total</u>	Cost
CH-SP	CHARGE Sh	nop Supplies		5	03163		1							\$5.00
												COMML		5.00
Job Code		Job Descrip	<u>tion</u>		<u>En</u>	nployee	No.	<u>Start</u>	<u>Fi</u>	<u>inish</u>		Quantity	<u>Total</u>	Cost
35-01-004	DIAGNOSE	BLOWER MOTOR		1	1310047	7	0	8/22/2022 13:10:51	08/22/2022	2 13:29:31		0.31		\$36.71
03-01-068	REPLACE N	EW AUX UNIT REAF	R BLOWER WHE	EL 1	1310047	7	0	9/14/2022 08:43:11	09/14/2022	2 09:11:46		0.48		\$56.21
03-01-068	REPLACE N	EW AUX UNIT REAF	R BLOWER WHE	EL 1	1310047	7	0	9/14/2022 07:16:18	09/14/2022	2 08:24:55		1.14		\$134.95
03-01-068	REPLACE N	EW AUX UNIT REAF	R BLOWER WHE	EL 1	1310047	7	0	9/12/2022 09:32:29	09/12/2022	2 10:19:18		0.78		\$92.07
03-54-002	REPLACE N	EW ALARM - BACK-	-UP	1	1901357	7	0	8/19/2022 14:23:54	08/19/2022	2 14:59:56		0.60		\$70.87
66-PM-PMA	PERFORM (	OIL CHANGE		1	1901357	7	0	8/19/2022 07:21:11	08/19/2022	2 07:23:04		0.03		\$3.70
66-PM-PMA	PERFORM (	OIL CHANGE		1	1901357	7	0	8/18/2022 10:12:49	08/18/2022	2 10:52:47		0.67		\$78.60
03-51-038	REPLACE N	EW WIPER BLADES	3	1	1901357	7	0	8/18/2022 10:09:49	08/18/2022	2 10:12:31		0.05		\$5.31
												LABOR		478.42
Job Code		Job Descrip	<u>tion</u>			Part No	<u>.</u>	<u>Des</u>	scription	<u> </u>	<u>Unit Price</u>	Quantity	<u>Total</u>	Cost
66-PM-PMA	PERFORM (	OIL CHANGE		E	BALB142	28	L	UBE SPIN-ON FILT	TER		5.09	9 1		\$5.09
66-PM-PMA		PERFORM OIL CHANGE			0001			OIL TREATMENT- C			15.48			\$15.48
03-51-038	REPLACE N	EW WIPER BLADES	8	2	22-1		V	VIPER BLADE 22"	TRICO EXACT		7.77	7 2		\$15.54

Job Code	Job Description	Part No.	<u>Description</u>	<b>Unit Price</b>	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10W30TQT	OIL QT BOTTLE 10W30SEMI THOMAS	3.56	5	\$17.78
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	380056450	REAR WHEEL BLOWER	215.10	1	\$215.10
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	288293	DRAIN VALVE	1.41	1	\$1.41
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	Y450000550	EVAP MOTOR	262.11	1	\$262.11
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	380056450	REAR WHEEL BLOWER	215.10	(1)	(\$215.10)
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	380056450	REAR WHEEL BLOWER	215.10	1	\$215.10
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	288293	DRAIN VALVE	1.41	(1)	(\$1.41)
03-01-068	REPLACE NEW AUX UNIT REAR BLOWER WHEEL	288293	DRAIN VALVE	1.41	1	\$1.41
03-54-002	REPLACE NEW ALARM - BACK-UP	GRO73040	BACK UP ALARM	48.00	1	\$48.00
					PARTS	580.51

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 44325

**Work Order Notes** 

(CWIGLEY) PM

#### **Job Notes**

#### 03-01-068 - REPLACE NEW AUX UNIT REAR BLOWER WHEEL

(IFALLS) Removed the blower motor/blower wheel assembly. Installed a new blower motor and wheel. The blower motor is now functioning properly. Applied adhesive to rubber seals that seal against cover. Repaired a broken water drain using epoxy. 2 HRS

#### 03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

#### 03-54-002 - REPLACE NEW ALARM - BACK-UP

(AGUERRA) Replaced backup alarm. Checked for proper operation, all good. AMG (30 min.)

#### 35-01-004 - DIAGNOSE BLOWER MOTOR

(EHOWELL) The rear, auxiliary blower wheel was defective/detached from the blower motor. EH

#### 66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 43539 Completed PM top and bottom side. Completed bus safety checklist. AMG/AMG

### **CH-SP - CHARGE Shop Supplies**

UNIT NO:				LET E	BLUE B	IRD		WORK O	RDER NO	): 45	11	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	CO	SED D	D DATE	10/12/2	2009 07:58:18 2009 11:27:55 2009 11:27:56	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 16410 E <b>DATE</b> :	ME 02/20/200		Services 0
JOB CODE		JOB DESCRIPTION	ST.	AT RS	N WRT	Y JOB LC	C LABOR HRS	<u>LABOR</u>	MATE	RIAL CO	MMERCIAL	TOTAL COST
03-51-038	REPLAC	E NEW WIPER BLADE	S DC	N N	l N	GARAGE	0.25	\$14.38	\$30.90	\$0.	00	\$45.28
66-79-002	PERFOR	M SERVICE CALL	DC	N E	N	GARAGI	≣ 1.00	\$57.50	\$0.00	\$0.	00	\$57.50
66-PM-PMA	PERFOR	M OIL CHANGE	DC	N F	N	GARAGE	€ 0.31	\$17.83	\$25.89	\$0.	00	\$43.72
JOB COUN	IT: 3			١	WORK O	RDER TOTA	AL: 1.56	89	.71	56.79	0.00	146.50
Job Code		Job Description			Employe	e No.	<u>Start</u>	ļ	Finish		Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		10041	963		10/12/2009 17:30:00	10/12/200	9 17:48:36		0.31	\$17.83
66-79-002	PERFORM S	SERVICE CALL		10041	963		10/12/2009 17:00:00	10/12/200	9 17:30:00		0.50	\$28.75
66-79-002	PERFORM S	SERVICE CALL		11088	858		10/12/2009 16:00:00	10/12/200	9 16:30:00		0.50	\$28.75
03-51-038	REPLACE N	IEW WIPER BLADES		10041	963		10/12/2009 17:48:36	3 10/12/200	9 18:03:36		0.25	\$14.38
											LABOR	89.71
Job Code		Job Description			Part N	<u>lo.</u>	<u>Des</u>	scription		Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		10W-3	0		OIL BULK			0.11	176	\$18.48
03-51-038	REPLACE N	IEW WIPER BLADES		60-22	10		WIPER BLADE			15.45	2	\$30.90
66-PM-PMA	PERFORM (	OIL CHANGE		BALB	1428		LUBE SPIN-ON FILT	TER		7.41	1	\$7.41
											PARTS	56.79

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 4511

### **Work Order Notes**

(LPATE) SVC CALL DEAD BATTERY-PM-REPLACE WIPERS

#### **Job Notes**

#### 03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

#### 66-79-002 - PERFORM SERVICE CALL

(LPATE) SVC CALL TO BREWER PORCH TO JUMP OFF DEAD BATTERY AND BRING BACK TO GARAGE TO RECHARGE

### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 10W-30 Qty : 176 Description : OIL BULK

Manufacturer:

Part No : 51061 Qty : 1

Description : FILTER-OIL

Manufacturer:

(LPATE) PM BY FC

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

232451 **UNIT NO:** 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 4532 **USING DEPT NO:** 208185 **OPENED DATE:** 10/13/2009 14:24:24 **LOCATION:** GARAGE - University Automotive Services **CLOSED WO STATUS:** 10/13/2009 14:31:15 **COMPLETED DATE: METER 1 - M**: 16410 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 10/13/2009 14:31:17 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 JOB CODE JOB LOC LABOR HRS **MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION STAT RSN WRTY LABOR 03-50-103 REPLACE NEW BELT TENSIONER DON 0 **GARAGE** 0.70 \$40.25 \$120.73 \$80.48 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.70 40.25 80.48 0.00 120.73 **Job Code Job Description** Employee No. Start Finish Quantity **Total Cost** 03-50-103 REPLACE NEW BELT TENSIONER 11268671 10/13/2009 15:00:00 10/13/2009 15:42:00 0.70 \$40.25 **LABOR** 40.25 **Job Code Job Description** Part No. Description **Unit Price** Quantity **Total Cost** 03-50-103 DAY5060975 S-BELT 32.93 \$32.93 REPLACE NEW BELT TENSIONER 03-50-103 **AUTO BELT TENSIONER** 47.55 REPLACE NEW BELT TENSIONER DAY89231 \$47.55 **PARTS** 80.48

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 4532

**Work Order Notes** 

(RWINTERS) BELT SQUEAKS

**Job Notes** 

03-50-103 - REPLACE NEW BELT TENSIONER

(RWINTERS) REPLACED THE S-BELT AND TENSIONER

UNIT NO:		232451 20	03 CHEVROL	ET BL	UE BIF	RD		WORK ORE	DER NO:	45706	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	OPENI COMPI CLOSE 2003 Chevrole	ETED D DAT	DATE: E:	01/11/202 01/11/202	3 14:49:30 3 08:08:03 3 11:16:57	LOCATION: METER 1 - M: IN-SERVICE D UNIT SERIAL	43816 <b>ATE</b> : 02/2	ersity Automotive S <b>METER 2 - N:</b> 0/2002 JG31R621157998	0
CH-SP CHARG		JOB DESCRIPTION RM OIL CHANGE E Shop Supplies	STAT DON DON	RSN P 2	WRTY N N	JOB LOC GARAGE GARAGE	0.69 0.00	<b>LABOR</b> \$81.32 \$0.00	MATERIAL \$0.00 \$0.00	**COMMERCIAL \$0.00 \$5.00	**TOTAL COST
JOB COUN	IT: 2			wo	ORK ORI	DER TOTAL:	0.69	81.32	2 0.0	0 5.00	86.32
Job Code CH-SP	CHARGE S	Job Description hop Supplies	Ę	<b>\</b> 03163	<u>/endor N</u>	l <u>o.</u> 1	Invoice No.	<u>Purchase</u>	Order No.	COMML	Total Cost \$5.00 5.00
Job Code 66-PM-PMA	PERFORM	Job Description OIL CHANGE	1	<u>Er</u> 220126	nployee 7		<u>Start</u> 09/2023 13:30:32		iish 14:11:53	Quantity 0.69 LABOR	Total Cost \$81.32 81.32

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 45706

**Work Order Notes** 

(EHANNAH) pm- replace wipers (GARAGE) wipers good-GC

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Wipers good-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- GC fluid check only, battery good, tires and tire pressure, Miles- 43,816

**CH-SP - CHARGE Shop Supplies** 

UNIT NO:		232451 200	3 CHEVROL	ET BL	UE BIF	RD		WORK O	RDER NO	): 4	<b>17095</b>		
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COMP	ED DAT LETED ED DAT et Blue l	DATE: E:	05/23/202 05/24/202	23 13:11:12 23 12:28:59 23 07:18:12	LOCATION METER 1 - IN-SERVIC UNIT SERI	M: 43974 E DATE:	02/20/2	ity Automotive \$ <b>//ETER 2 - N:</b> 1002 31R621157998	Services 0	
JOB CODE		JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL (	COMMERCIAL	TOTAL COS	<u>ST</u>
03-51-038	REPLAC	E NEW WIPER BLADES	S DON	Р	Ν	GARAGE	0.07	\$7.80	\$0.00	\$	60.00	\$7.80	
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.41	\$48.31	\$55.57	\$	60.00	\$103.88	
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$	55.00	\$5.00	
WA-00	WASH C	OMPLETE VEHICLE	DON	Р	N	GARAGE	0.28	\$32.75	\$0.00	\$	60.00	\$32.75	
JOB COUN	IT: 4			WC	RK ORI	DER TOTAL:	0.75	88	3.86	55.57	5.00	149	9.43
Job Code CH-SP	CHARGE SI	Job Description		<b><u>V</u></b> 503163	endor N	l <mark>o.</mark> 1	Invoice No.	Purcha	se Order N	<u>o.</u>			\$5.00
											COMML	5	5.00
Job Code		Job Description			nployee		<u>Start</u>		<u>Finish</u>		<b>Quantity</b>	Total Cost	
WA-00	WASH COM	IPLETE VEHICLE		12201267	7	05	/18/2023 09:30:00	05/18/20	23 09:46:39		0.28	\$32	32.75
WA-00	WASH COM	IPLETE VEHICLE		12201267	7	05	/18/2023 09:14:34	05/18/20	23 09:14:34		0.00	\$0	0.00
03-51-038	REPLACE N	IEW WIPER BLADES		12201267	7	05	/18/2023 09:04:37	05/18/20	23 09:08:35		0.07	\$7	7.80
66-PM-PMA	PERFORM (	OIL CHANGE		12201267	7	05	/18/2023 08:39:42	05/18/20	23 09:04:16		0.41	\$48	18.31
											LABOR	88	8.86
Job Code		Job Description			Part No	<u>.</u>	Des	cription		Unit Price	e Quantity	Total Cost	<u>;t</u>
66-PM-PMA	PERFORM (	OIL CHANGE		10001		OI	L TREATMENT- C	ONVENTIONA	L	15.1	4 1	\$1	15.14
66-PM-PMA	PERFORM (	OIL CHANGE		22-1		WI	PER BLADE 22" 1	TRICO EXACT		8.3	3 2	\$10	16.65
66-PM-PMA	PERFORM (	OIL CHANGE		BALB142	8	LU	BE SPIN-ON FILT	ER		6.0	00 1	\$(	\$6.00
66-PM-PMA	PERFORM (	OIL CHANGE		10W30T0	Ţ	OI	L QT BOTTLE 10W	V30SEMI THO	MAS	3.5			17.78
											PARTS	55	5.57

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 47095

**Work Order Notes** 

(EHANNAH) pm- replace wipers- wash

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure. Miles, 43,974

**CH-SP - CHARGE Shop Supplies** 

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

UNIT NO:		232451 20	03 CHEVROLE	T BLUE BIF	RD		WORK ORE	DER NO:	479	91	
USING DEPT	NO:	208185	OPENEI	D DATE:	11/18/2009	9 15:03:35	LOCATION:	GARAGE -	- University	Automotive S	Services
WO STATUS	:	CLOSED	COMPLI	ETED DATE:	11/19/2009	9 09:07:52	METER 1 - M:	16410	ME	TER 2 - N:	0
WO VISIT RE	EASON:	SCHEDULED	CLOSE	D DATE:	11/19/2009	9 09:07:54	IN-SERVICE D	ATE:	02/20/200	2	
TECH SPEC	NO:	03BUSBLUEBIRD	2003 Chevrolet	Blue Bird Bus			UNIT SERIAL	NO:	1GBJG31I	R621157998	
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL CO	MMERCIAL	TOTAL COST
PU-51-046	PURCH	ASED KEY BLANK(S)	DON	O N	GARAGE	0.00	\$0.00	\$1.50	\$0.0	00	\$1.50
JOB COUNT	·: 1			WORK ORI	DER TOTAL:	0.00	0.00	)	1.50	0.00	1.50
Job Code		Job Description		Part No	<u>.</u>	<u>Des</u>	scription	<u>U</u>	nit Price	Quantity	Total Cost
PU-51-046	PURCHASE	ED KEY BLANK(S)	KE	EY BLANK	KE	Y BLANK			1.50	1	\$1.50
										PARTS	1.50

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 4791

**Work Order Notes** 

(LPATE) WARREN REQUESTED 1 KEY

**Job Notes** 

PU-51-046 - PURCHASED KEY BLANK(S)

(LPATE) RW CUT 1 KEY

UNIT NO:		2003 CHE	VROLE	T BL	UE BIF	RD		WORK O	RDER NO	D: 4	815		
USING DEF WO STATUS WO VISIT F TECH SPEC	S: REASON:	208185 CLOSED UNSCHEDULED 03BUSBLUEBIRD		OPENE COMPL CLOSE Chevrole	ETED D DAT	DATE: E:	11/23/200 11/23/200	09 06:59:03 09 07:06:30 09 07:06:32	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 16416 E DATE:	<b>M</b> 02/20/20	ity Automotive ( IETER 2 - N: 002 31R621157998	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>ON</u>	STAT	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	<u>MATI</u>	ERIAL C	OMMERCIAL	TOTAL COST
03-31-100	REPLAC	E NEW BELT, CHA	RGING SYST	DON	N	N	GARAGE	0.60	\$34.50	\$32.93	\$0	0.00	\$67.43
66-79-002	PERFOR	RM SERVICE CALL		DON	В	N	GARAGE	1.00	\$57.50	\$0.00	\$0	0.00	\$57.50
JOB COUN	IT: 2				WC	RK ORI	DER TOTAL:	1.60	92	.00	32.93	0.00	124.93
Job Code		Job Descript	<u>ion</u>		En	nployee	No.	<u>Start</u>	<u>!</u>	<u>Finish</u>		Quantity	Total Cost
66-79-002	PERFORM	SERVICE CALL		1	1268671		11.	/20/2009 13:00:00	11/20/200	9 14:00:00		1.00	\$57.50
03-31-100	REPLACE N	IEW BELT, CHARGIN	G SYSTEM	1	1268671		11.	/20/2009 14:00:00	11/20/200	9 14:36:00		0.60	\$34.50
												LABOR	92.00
Job Code		Job Descript	<u>ion</u>			Part No	<u>.</u>	Des	cription		Unit Price	Quantity	<u>Total Cost</u>
03-31-100	REPLACE N	IEW BELT, CHARGIN	G SYSTEM	D	AY5060	975	S-	BELT			32.93	3 1	\$32.93
03-31-100	REPLACE N	IEW BELT, CHARGIN	G SYSTEM	D	AY5060	975	S-	BELT			32.93	3 (1)	(\$32.93
03-31-100	REPLACE N	IEW BELT, CHARGIN	G SYSTEM	D	AY5060	975	S-	BELT			32.93	31	\$32.93
												PARTS	32.93

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 4815

**Work Order Notes** 

(RWINTERS) SERVICE CALL, NEEDS BELT AND HAS DEAD BATTERY

**Job Notes** 

03-31-100 - REPLACE NEW BELT, CHARGING SYSTEM

(RWINTERS) REPLACED THE S-BELT

66-79-002 - PERFORM SERVICE CALL

(RWINTERS) IF AND ANGEL RAN SERVICE CALL TO BREWER PORCH. LIGHTS LEFT ON, JUMPED OFF AND PERFORMED IDLE RELEARN

UNIT NO:		232451 20	003 CHEVROL	ET BL	UE BIF	RD		WORK C	RDER NO:	4	8712	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	СОМР	ED DAT LETED ED DAT et Blue	DATE:	10/26/202 10/26/202	3 14:29:31 3 13:14:12 3 13:14:17		M: 44143 E DATE:	<b>M</b> 02/20/20		Services 0
JOB CODE	<u> </u>	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	R MATER	RIAL C	OMMERCIAL	TOTAL COST
66-PM-PMA	PERFOR	RM OIL CHANGE	DON	Р	N	GARAGE	0.26	\$31.01	\$0.00	\$0	0.00	\$31.01
CH-SP	CHARGE	Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5	5.00	\$5.00
WA-00	WASH C	OMPLETE VEHICLE	DON	Р	N	GARAGE	0.41	\$48.22	\$0.00	\$0	0.00	\$48.22
JOB COUN	T: 3			WC	ORK ORI	DER TOTAL:	0.67	7	9.23	0.00	5.00	84.23
Job Code		Job Description	ļ.	<u>\</u>	endor N	<u>lo.</u>	Invoice No.	<u>Purch</u>	ase Order No	<u>.</u>		Total Cost
CH-SP	CHARGE SI	nop Supplies		503163		1					-	\$5.00
											COMML	5.00
Job Code		Job Description		<u>Er</u>	nployee	No.	<u>Start</u>		<u>Finish</u>		<b>Quantity</b>	<b>Total Cost</b>
WA-00	WASH COM	IPLETE VEHICLE		11074414	4	10/	26/2023 08:21:00	10/26/20	023 08:45:31		0.41	\$48.22
66-PM-PMA	6-PM-PMA PERFORM OIL CHANGE			11074414			10/26/2023 08:03:09		10/26/2023 08:18:55		0.26	\$31.01
											LABOR	79.23

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 48712

**Work Order Notes** 

(EHANNAH) pm- wash

**Job Notes** 

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Driven 208 miles checked fluids tire pressure updated oil change sticker. SH

**CH-SP - CHARGE Shop Supplies** 

**WA-00 - WASH COMPLETE VEHICLE** 

(SHARBIN) Washed. SH

UNIT NO:		232451 20	003 CHEVRO	LET B	LUE BII	RD		WORK C	RDER NO:	49	629	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COM	SED DA	DATE:	02/02/202 02/06/202	24 08:14:52 24 15:15:15 24 10:05:15			<b>ME</b>	TER 2 - N:	0
JOB CODE	<u> </u>	JOB DESCRIPTION	<u>STA</u>	r RSN	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABOF</u>	R MATER	IAL CC	MMERCIAL	TOTAL COST
66-79-002	PERFOR	M SERVICE CALL	DO	l B	N	GARAGE	0.05	\$6.16	\$0.00	\$0.0	00	\$6.16
66-PM-PMA	PERFOR	M OIL CHANGE	DO	l P	N	GARAGE	0.05	\$5.51	\$0.00	\$0.0	00	\$5.51
CH-SP	CHARGE	Shop Supplies	DO	1 2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.0	00	\$5.00
JOB COUN	IT: 3			W	ORK OR	DER TOTAL:	0.10	1	1.67	0.00	5.00	16.67
Job Code	CHARGE SI	Job Description	<u>1</u>	503163	Vendor N	No.	Invoice No.	Purch	ase Order No.			Total Cost \$5.00
OH-OF	CHARGE 31	iop Supplies		303103		I					COMML	5.00
Job Code		Job Description	<u>1</u>	<u> </u>	mployee	No.	<u>Start</u>		<u>Finish</u>		<b>Quantity</b>	Total Cost
66-PM-PMA	PERFORM (	OIL CHANGE		122012	67	02/	02/2024 13:05:18	02/02/20	024 13:08:06		0.05	\$5.51
66-79-002	PERFORM	SERVICE CALL		122012	67	02/	02/2024 13:01:51	02/02/20	024 13:04:59		0.05	\$6.16
											LABOR	11.67

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 49629

### **Work Order Notes**

(LRUSHING) dead battery

#### **Job Notes**

#### 66-79-002 - PERFORM SERVICE CALL

(GRCOOK) Performed service calls-JW,GC, vehicle had dead battery, jumped vehicle off and brought back to shop, charged batter with portable charger and tested battery, battery tested good. -GC Miles, 44,202

### 66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 228 miles, fluids good, filter good, tires and tire pressure, updated oil change sticker. Miles, 44,202

### **CH-SP - CHARGE Shop Supplies**

UNIT NO:		232451 200	03 CHEVROLE	ET BL	UE BIF	RD		WORK ORI	DER NO:		5089		
USING DEPT	NO:	208185	OPENE	D DATI	E:	01/13/201	10 09:52:17	LOCATION:	GARAGE -	- Univers	sity Automotive S	Services	
WO STATUS:		CLOSED	COMPL	ETED I	DATE:	01/14/201	10 08:05:05	METER 1 - M:	16416	ľ	METER 2 - N:	0	
WO VISIT RE	ASON:	SCHEDULED	CLOSE	D DATE	≣:	01/14/201	10 08:05:07	IN-SERVICE	DATE:	02/20/2	2002		
TECH SPEC	NO:	03BUSBLUEBIRD	2003 Chevrole	t Blue E	Bird Bus			UNIT SERIAL	NO:	1GBJG	31R621157998		
JOB CODE		JOB DESCRIPTION	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<u>LABOR</u>	MATER	RIAL	COMMERCIAL	TOTAL	COST
66-79-002	PERFOR	RM SERVICE CALL	DON	В	N	GARAGE	1.00	\$57.50	\$0.00	9	\$0.00	\$57.50	
JOB COUNT	: 1			WO	RK ORI	DER TOTAL:	1.00	57.5	0	0.00	0.00		57.50
Job Code		Job Description		<u>Em</u>	ployee	No.	<u>Start</u>	<u>Fi</u>	nish		Quantity	<u>Total</u>	Cost
66-79-002 F	PERFORM	SERVICE CALL	1	1274660		01.	/13/2010 17:00:00	01/13/2010	18:00:00		1.00		\$57.50
											LABOR		57.50

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 5089

**Work Order Notes** 

(LPATE) BREWER PORCH REQUESTED SVC CALL FOR DEAD BATTERY

**Job Notes** 

66-79-002 - PERFORM SERVICE CALL

(LPATE) WENT TO BREWER PORCH JUMPED OFF BUS

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

LABOR

 UNIT NO:
 232451
 2003 CHEVROLET BLUE BIRD
 WORK ORDER NO:
 50970

 USING DEPT NO:
 208185
 OPENED DATE:
 05/30/2024 10:01:05
 LOCATION:
 GARAGE - University Automotive

 USING DEPT NO:
 208185
 OPENED DATE:
 05/30/2024 10:01:05
 LOCATION:
 GARAGE - University Automotive Services

 WO STATUS:
 CLOSED
 COMPLETED DATE:
 05/30/2024 14:29:24
 METER 1 - M:
 44428
 METER 2 - N:
 0

**WO VISIT REASON:** SCHEDULED **CLOSED DATE:** 05/31/2024 09:57:33 **IN-SERVICE DATE:** 02/20/2002

TECH SPEC NO: 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus UNIT SERIAL NO: 1GBJG31R621157998

JOB CODE STAT RSN WRTY JOB LOC LABOR HRS **LABOR MATERIAL COMMERCIAL TOTAL COST** JOB DESCRIPTION PD-00-999 PREP DISPOSE PREPARE UNIT FOR DI DON D **GARAGE** 0.00 \$0.00 \$0.00 \$0.00 \$0.00 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 0.00 0.00 0.00 **Job Code Job Description** Employee No. **Start** Finish Quantity **Total Cost** PD-00-999 PREP DISPOSE PREPARE UNIT FOR DISPOSAL 12395904 05/30/2024 14:19:33 05/30/2024 14:19:33 0.00 \$0.00

0.00

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 50970

**Work Order Notes** 

(EHANNAH) prep for sale

**Job Notes** 

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(FCONTRER) perform prepare unit for disposal FC

UNIT NO:	232451	2003 CHEVROLET BLUE BIR	D	WORK ORDER NO: 5155					
USING DEPT NO:	208185	OPENED DATE:	01/25/2010 13:23:28	LOCATION: GARAGE-U	Jniversity Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	01/25/2010 14:56:09	<b>METER 1 - M</b> : 16426	<b>METER 2 - N</b> : 0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2010 14:56:11	IN-SERVICE DATE:	02/20/2002				
TECH SPEC NO:	03BUSBLUEBIRD	2003 Chevrolet Blue Bird Bus		UNIT SERIAL NO: 1	IGBJG31R621157998				
JOB CODE	JOB DESCRIPTIO	<u>STAT RSN WRTY</u>	JOB LOC LABOR HRS	LABOR MATERIA	AL COMMERCIAL TOTAL COST				
66 DM DMA DEDEO	DM OIL CHANCE	DON D N	CARACE 0.00	00.02	00.02				

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<b>LABOR</b>	MATERIA	AL COMMER	CIAL TOTAL	COST
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	Ν	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00	
JOB COUNT: 1			wo	RK ORI	DER TOTAL:	0.00	0	.00	0.00	0.00	0.00

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 5155

### **Work Order Notes**

(LPATE) INSPECTED NO OIL CHANGE NEEDED

### **Job Notes**

#### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 10W-30 Qty : 176 Description : OIL BULK

Manufacturer:

Part No : 51061 Qty : 1

Qty . I

Description : FILTER-OIL

Manufacturer:

(LPATE) CHECKED FLUIDS AND INSPECTED VEHICLE-CHECKED LIGHTS-DID NOT CHANGE OIL DUE TO VEHICLE HAS ONLY BEEN 16 MILES SINCE LAST SVC. HAS BEEN SITTING AT BREWER PORCH

UNIT NO:		232451 200	3 CHEVROL	ET BL	UE BIF	RD		WORK OR	DER NO:	5731	
USING DEF WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD	COMP	ED DAT LETED ED DATI et Blue E	DATE: E:	05/03/20 <sup>2</sup> 05/03/20 <sup>2</sup>	10 13:07:58 10 10:06:15 10 10:06:17	LOCATION: METER 1 - M IN-SERVICE UNIT SERIAL	<b>DATE:</b> 02/2	rersity Automotiv <b>METER 2 - N</b> 0/2002 JG31R6211579	: 0
JOB CODE 66-PM-PMA	<del></del>	JOB DESCRIPTION RM OIL CHANGE	<u>STAT</u> DON	RSN P	WRTY N	JOB LOC GARAGE	LABOR HRS 0.31	<b>LABOR</b> \$17.83	<b>MATERIAL</b> \$34.02	<b>COMMERCIA</b> \$0.00	**TOTAL COST \$51.85
JOB COUN	IT: 1			wo	RK ORI	DER TOTAL:	0.31	17.8	34.02	2 0.	00 51.8
Job Code 66-PM-PMA	PERFORM (	Job Description OIL CHANGE	1	<u>Em</u> 1046945	nployee		<u><b>Start</b></u> /30/2010 17:00:00		nish 17:18:36	<b>Quantit</b>	<b>y</b> <u>Total Cost</u> 31 \$17.8
										LABOR	
Job Code		Job Description			Part No	_		<u>cription</u>	Unit P		
66-PM-PMA	PERFORM (	OIL CHANGE	E	BALB142	8	LU	IBE SPIN-ON FILT	ER		5.58	1 \$5.5
66-PM-PMA	PERFORM (	OIL CHANGE	1	0W-30		OI	L BULK			0.09 1	76 \$15.8
66-PM-PMA	PERFORM (	OIL CHANGE	A	NTIFRE	EZE DEX	COOL AN	ITIFREEZE-GM		1	12.60	1 \$12.6
										PARTS	34.02

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 5731

**Work Order Notes** 

(LPATE) PM

#### **Job Notes**

#### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 10W-30 Qty : 176 Description : OIL BULK

Manufacturer:

Part No : 51061

Qty : 1

Description : FILTER-OIL

Manufacturer:

(LPATE) PM BY TM

UNIT NO:		232451	2003 CHEVI	ROLE	T BL	UE BIR	RD		WORK O	RDER NO	: 680	0		
USING DEP WO STATUS WO VISIT R TECH SPEC	EASON:	208185 CLOSED UNSCHEDULED 03BUSBLUEBIRD	C	OPENE COMPL CLOSE	ETED   D DATI	DATE: E:	01/16/200 01/16/200	8 11:21:35 8 13:23:18 8 13:23:19	LOCATION: METER 1 - I IN-SERVICE UNIT SERIA	M: 14768 E DATE:	ME <sup>-</sup> 02/20/200	Automotive 3 <b>TER 2 - N:</b> 2 R621157998	0	
JOB CODE		JOB DESCRIPTIO	<u>N</u> :	<u>STAT</u>	<u>RSN</u>	WRTY	JOB LOC	LABOR HRS	LABOR	MATE	RIAL CO	MMERCIAL	TOTAL	COST
03-32-002	REPLAC	E NEW BATTERY		DON	0	Ν	GARAGE	0.00	\$0.00	\$95.42	\$0.0	00	\$95.42	
66-79-002	PERFOR	M SERVICE CALL	1	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$0.0	00	\$0.00	
JOB COUN	Т: 2				WO	RK ORE	ER TOTAL:	0.00	0	.00	95.42	0.00		95.42
Job Code		Job Description	<u>on</u>			Part No.	<u>-</u>	Des	<u>cription</u>	<u> </u>	Unit Price	Quantity	<u>Total</u>	Cost
03-32-002	REPLACE N	IEW BATTERY		77	8MF		BAT	ΓΤΕRΥ			95.42	1		\$95.42
												PARTS	<u> </u>	95.42

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 680

**Work Order Notes** 

(LOBRIEN) SERVICE CALL - DEAD BATTERY.

**Job Notes** 

03-32-002 - REPLACE NEW BATTERY

(LOBRIEN) REPLACED BATTERY.

66-79-002 - PERFORM SERVICE CALL

(LOBRIEN) JASON AND LYNDA RESPONDED TO SERVICE CALL.

0.00

## Work Order Charge Detail

JOB COUNT: 6

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

190.33

140.02

UNIT NO:	232451	2003 CHEVROLET BLUE BIRD		WORK ORDER NO:	8337
USING DEPT NO:	208185	OPENED DATE:	05/13/2011 10:46:45	LOCATION: GARAGE -	University Automotive Services
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2011 06:44:50	METER 1 - M: 17220	<b>METER 2 - N</b> : 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2011 06:44:52	IN-SERVICE DATE:	02/20/2002

2003 Chevrolet Blue Bird Bus **TECH SPEC NO:** 03BUSBLUEBIRD 1GBJG31R621157998 **UNIT SERIAL NO:** 

**WORK ORDER TOTAL:** 

JOB CODE	JOB DESCRIPTION	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	JOB LOC	LABOR HRS	<u>LABOR</u>	<u>MATERIAL</u>	COMMERCIAL	TOTAL COST
01-13-002	ADJUST REAR BRAKES & DRUMS/ROT	DON	0	Ν	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
03-02-010	REPLACE NEW MIRRORS	DON	0	N	GARAGE	0.50	\$28.75	\$116.67	\$0.00	\$145.42
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	0	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-003	PERFORM SAFETY INSPECTION	DON	Р	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	Р	N	GARAGE	0.31	\$17.83	\$23.35	\$0.00	\$41.18
CH-32-002	CHARGE BATTERY	DON	0	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

Job Code	Job Description	Employee No.	<u>Start</u>	<u>Finish</u>	Quantity	Total Cost
CH-32-002	CHARGE BATTERY	11328035	05/13/2011 17:30:00	05/13/2011 18:00:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11328035	05/13/2011 17:00:00	05/13/2011 17:18:36	0.31	\$17.83
66-79-003	PERFORM SAFETY INSPECTION	11268671	05/13/2011 16:00:00	05/13/2011 17:00:00	1.00	\$57.50
04.47	DOTATE TIDEO TUDEO LINEDO O VALVEO	44000074	05/40/0044 40 00 00	05/40/0044 47 00 00	0.50	A00.75

3.31

					LABOR	190.33
01-13-002	ADJUST REAR BRAKES & DRUMS/ROTORS	11268671	05/13/2011 16:00:00	05/13/2011 16:30:00	0.50	\$28.75
03-02-010	REPLACE NEW MIRRORS	11328035	05/13/2011 17:00:00	05/13/2011 17:30:00	0.50	\$28.75
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11268671	05/13/2011 16:30:00	05/13/2011 17:00:00	0.50	\$28.75

Job Code	Job Description	<u>Part No.</u>	<u>Description</u>	<b>Unit Price</b>	<b>Quantity</b>	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB1428	LUBE SPIN-ON FILTER	4.87	1	\$4.87
66-PM-PMA	PERFORM OIL CHANGE	10W-30	OIL BULK	0.11	176	\$18.48
03-02-010	REPLACE NEW MIRRORS	3365	SPOT MIRROR	49.40	2	\$98.79
03-02-010	REPLACE NEW MIRRORS	SHIPPING	SHIPPING AND HANDLING	17.88	1	\$17.88
					PARTS	140.02

330.35

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 8337

#### **Work Order Notes**

(LPATE) PM-DO ANNUAL BUS INSPECTION

#### **Job Notes**

#### 01-13-002 - ADJUST REAR BRAKES & DRUMS/ROTORS

(LPATE) CLEANED AND ADJUSTED REAR BRAKES, FRONT WERE OK

#### 03-02-010 - REPLACE NEW MIRRORS

(LPATE) REPLACED BOTH SPOT MIRRORS AT FRONT BUMPER OF TRUCK

#### 31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LPATE) CROSS ROTATED TIRES FRONT TO REAR DID NOT MOVE REAR INSIDE TIRES.

#### 66-79-003 - PERFORM SAFETY INSPECTION

(LPATE) BUS INSPECTION COMPLETE-PM DONE-ROTATED TIRES-ADJUSTED REAR BRAKES-REPLACED BOTH SPOT MIRRORS-CHARGE BATTERIES ARE DEAD

#### 66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 1061 Qty : 1

Description : FILTER-OIL

Manufacturer:

Part No : 10W-30 Qty : 176 Description : OIL BULK

Manufacturer:

(LPATE) PM BY TM

#### CH-32-002 - CHARGE BATTERY

(LPATE) BATTERIES DEAD, RECHARGED CHECKED OK

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

**UNIT NO:** 232451 2003 CHEVROLET BLUE BIRD **WORK ORDER NO:** 9119 **USING DEPT NO:** 208185 OPENED DATE: 09/13/2011 10:24:21 LOCATION: GARAGE - University Automotive Services **CLOSED WO STATUS:** 09/14/2011 13:49:07 COMPLETED DATE: **METER 1 - M**: 19444 **METER 2 - N**: 0 **WO VISIT REASON: SCHEDULED** 09/14/2011 13:49:09 **CLOSED DATE: IN-SERVICE DATE:** 02/20/2002 **TECH SPEC NO:** 03BUSBLUEBIRD 2003 Chevrolet Blue Bird Bus **UNIT SERIAL NO:** 1GBJG31R621157998 **LABOR** COMMERCIAL TOTAL COST JOB CODE RSN WRTY JOB LOC LABOR HRS **MATERIAL** JOB DESCRIPTION <u>STAT</u> 10-01-001 SERVICE AIR CONDITIONING ASSEMBL DON 0 Ν **GARAGE** 0.00 \$0.00 \$0.00 \$401.24 \$401.24 JOB COUNT: 1 **WORK ORDER TOTAL:** 0.00 0.00 0.00 401.24 401.24 **Job Code Job Description** Vendor No. Invoice No. Purchase Order No. **Total Cost** 10-01-001 SERVICE AIR CONDITIONING ASSEMBLY 11077507 33342 0013206 \$401.24 COMML 401.24

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 9119

**Work Order Notes** 

(LPATE) BUS SERVICED ON 4/26/11 INVOICE DELAYED DUE TO TORNADOS. TRANSICOLD CHECKED AND SERVICED A/C

#### **Job Notes**

#### 10-01-001 - SERVICE AIR CONDITIONING ASSEMBLY

(LPATE) PER TRANSICOLD WO CHECKED SYSTEM-COOLING-RECOVERED REFRIDGERANT R&R DRIER AND FILTER. EVAC ADDED OIL AND CHARGED. RAN BUS-COOLING OK. PD BY CC

UNIT NO:		232451 200	3 CHEVROL	ET BL	UE BIF	RD		WORK O	RDER NO	D: 9	737	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED PREVENTIVE MAINT 03BUSBLUEBIRD	COMP	ED DAT LETED ED DAT et Blue l	DATE: E:	11/22/201 11/22/201	1 15:01:19 1 08:58:08 1 08:58:10	LOCATION METER 1 - IN-SERVICI UNIT SERIA	M: 19739 E DATE:	<b>N</b> 02/20/2		0
JOB CODE 03-51-038 66-PM-PMA	REPLAC	JOB DESCRIPTION  E NEW WIPER BLADES  M OIL CHANGE	STAT DON DON	<b>RSN</b> N P	WRTY N N	JOB LOC GARAGE GARAGE		\$14.38 \$0.82	\$39.09 \$25.88	\$	0.00 0.00	**TOTAL COST \$53.47 \$26.70
JOB COUN	IT: 2			WC	RK ORI	DER TOTAL:	0.26	15	5.20	64.97	0.00	80.
<b>Job Code</b> 03-51-038 66-PM-PMA	REPLACE N	Job Description EW WIPER BLADES DIL CHANGE		<u>En</u> 1268671 0260422			<u>Start</u> 21/2011 15:05:00 22/2011 08:44:32	11/21/20	Finish 11 15:20:00 11 08:45:23		<b>Quantity</b> 0.25 0.01	·
											LABOR	15.2
Job Code		Job Description			Part No	<u>.</u>	<u>Des</u>	cription		Unit Price	<u>Quantity</u>	Total Cost
03-51-038	REPLACE N	EW WIPER BLADES	6	60-2240		WI	PER BLADE			19.5	5 2	\$39.
66-PM-PMA	PERFORM (	OIL CHANGE	•	0W-30		OII	BULK			0.0	9 192	\$17.
66-PM-PMA	PERFORM (	OIL CHANGE	E	BALB142	8	LU	BE SPIN-ON FILT	ER		4.9	2 1	\$4.
66-PM-PMA	PERFORM (	OIL CHANGE	•	1562588	3	OII	DRAIN PLUG M	12		3.6	81	\$3.
											PARTS	64.9

The University of Alabama

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 9737

**Work Order Notes** 

(RWINTERS) PM

**Job Notes** 

03-51-038 - REPLACE NEW WIPER BLADES

(RWINTERS) REPLACED THE WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(RWINTERS)

Parts For Job Include:
Part 10W-30 OIL BULK Qty 176 Cost 0.06
Part 1061 FILTER-OIL Qty 1 Cost 0
(RWINTERS) PM BY IF/GM

Page:1

# Work Order Charge Detail

FleetFocus M5 - WODETAIL - Work Order Detail v20.0

UNIT NO:		232451 2	2003 CHE	/ROLI	ET BLI	JE BIF	RD		WORK ORD	ER NO:	9894	
USING DEP WO STATUS WO VISIT R TECH SPEC	S: REASON:	208185 CLOSED SCHEDULED 03BUSBLUEBIRD		COMPI	ED DATE ETED I ED DATE et Blue E	DATE:	01/17/20 01/17/20	11 11:01:52 12 06:45:05 12 06:45:07	LOCATION: ( METER 1 - M: IN-SERVICE D UNIT SERIAL I	19739 <b>ATE:</b> 02/20	rsity Automotive S <b>METER 2 - N:</b> /2002 G31R621157998	0
JOB CODE	Ē	JOB DESCRIPTION	<u> </u>	<u>STAT</u>	RSN	WRTY	JOB LOC	LABOR HRS	<b>LABOR</b>	MATERIAL	COMMERCIAL	TOTAL COST
03-31-001	REPLAC	E NEW ALTERNATOR	R	DON	0	N	GARAGE	1.60	\$92.00	\$331.99	\$0.00	\$423.99
03-50-102	REPLAC	E NEW IDLER PULLE	ΞY	DON	0	N	GARAGE	0.00	\$0.00	\$30.26	\$0.00	\$30.26
14-01-001	INSTALL	AIR CONDITIONING	ASSEMBL'	DON	0	N	GARAGE	72.79	\$4,185.18	\$2,935.55	\$0.00	\$7,120.73
16-01	TRANSP	ORT AIR CONDITION	NING, HEAT	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-01-058	CHARGE	E EVAC AND RECHAP	RGE FREO	DON	0	N	GARAGE	0.00	\$0.00	\$0.00	\$343.32	\$343.32
JOB COUN	IT: 5				wo	RK ORI	DER TOTAL	74.39	4,277.18	3,297.80	343.32	7,918.30
<u>Job Code</u> CH-01-058	CHARGE E\	Job Description /AC AND RECHARGE F	<del></del> '	1	<u>Ve</u> 1122732	endor N		<u>Invoice No.</u> 4621	<u>Purchase</u> 0014430	Order No.	COMML	**Total Cost
Job Code		Job Description	<u>n</u>		Em	ployee	No.	<u>Start</u>	<u>Fin</u>	<u>ish</u>	<u>Quantity</u>	Total Cost
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		12	/14/2011 09:34:01	12/14/2011 1	4:00:00	4.43	\$254.90
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		12	/14/2011 14:15:00	12/14/2011 1	4:56:39	0.69	\$39.92
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		12	/16/2011 11:13:07	12/16/2011 1	4:00:00	2.78	\$159.93
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		12	/16/2011 14:15:00	12/19/2011 0	5:59:13	63.74	\$3,664.87
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		12	/19/2011 13:57:26	12/19/2011 1	3:57:42	0.00	\$0.25
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	1268671		01	/03/2012 10:26:14	01/03/2012 1	1:34:23	1.14	\$65.31
03-31-001	REPLACE N	EW ALTERNATOR		1	0260422		01	/05/2012 07:00:00	01/05/2012 0	08:36:00	1.60	\$92.00
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	0260422		01	/05/2012 07:00:00	01/05/2012 0	8:36:00	1.60	\$92.00
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	0260422		01	/05/2012 07:00:00	01/05/2012 0	8:36:00	(1.60)	(\$92.00)
											LABOR	4277.18
Job Code		Job Description	<u>n</u>		,	Part No	<u>.</u>	Des	<u>scription</u>	<u>Unit Pri</u>	ce Quantity	Total Cost
14-01-001		R CONDITIONING ASSE			SHIPPING	3		HIPPING AND HAN	NDLING		7.00 1	\$57.00
14-01-001		R CONDITIONING ASSE			CUNIT	_		RONT AC UNIT		2092		\$2,092.50
14-01-001	INSTALL AIF	R CONDITIONING ASSE	MBLY	1	2 CLAM	כ	Cl	-AMP 9/16-1 1/4		C	).78 2	\$1.56

Job Code	Job Description	Part No.	<u>Description</u>	Unit Price	Quantity	Total Cost
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	ANTIFREEZE DEXCOOL	ANTIFREEZE-GM	16.49	1	\$16.49
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	12 CLAMP	CLAMP 9/16-1 1/4	0.80	2	\$1.59
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	10 CLAMP	CLAMP 9/16-1 1/16	0.73	1	\$0.73
03-50-102	REPLACE NEW IDLER PULLEY	GAT38001	IDLER PULLEY	30.26	1	\$30.26
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	FOR84740	HEATER FITTING	4.85	1	\$4.85
03-31-001	REPLACE NEW ALTERNATOR	REM91611	ALTERNATOR	331.99	1	\$331.99
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	FOR74671	HEATER CONTROL VALVE	25.83	1	\$25.83
14-01-001	INSTALL AIR CONDITIONING ASSEMBLY	A/C HOSES	PER-FAB A/C HOSE ASSY	735.00	1	\$735.00
				·	PARTS	3297.80

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

UNIT NO: 232451 2003 CHEVROLET BLUE BIRD WORK ORDER NO: 9894

#### **Work Order Notes**

(LPATE) DEPT REQUESTED INSTALL FRONT A/C IN BUS.

#### **Job Notes**

03-31-001 - REPLACE NEW ALTERNATOR

(RWINTERS) REPLACED ALTERNATOR BY GM

03-50-102 - REPLACE NEW IDLER PULLEY

(RWINTERS) REPLACED IDLER PULLEY BY GM

#### 14-01-001 - INSTALL AIR CONDITIONING ASSEMBLY

(LPATE) INSTALLED NEW FACTORY A/C ON FRONT OF BUS. INSTALLED NEW A/C CONTROL HEAD AND A/C EVAPORATOR BOX UNDERHOOD AND ROUTED VACUUM HOSES. ALSO INSTALLED NEW HEATER CONTROL VALVE, RECEIVER DRYER ON FRONT UNIT AND REAR UNIT. INSTALLED HIGH AND LOW PRESSURE HOSES FROM NEW UNIT TO THE REAR A/C UNIT.

#### 16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LPATE) TAKEN TO FIRESTONE BY KEITH WEATHERS.

#### CH-01-058 - CHARGE EVAC AND RECHARGE FREON

(LPATE) FIRESTONE EVAC AND RECHARGED FREON FOR REAR A/C. ADDED FREON TO FRONT UNIT AFTER INSTALLED. PD BY CC.

Report Printed: 06/03/2024 10:42:53 By User: GLOBETTI

## Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0

Report Author: FleetFocus M5

File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~I

Data Extracted: Mon Jun 03 2024 10:42:53 Report User: GLOBETTI

TZ: Central Standard Time

**DLL Version:** 2021.02.23

Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 -

Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590

09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

#### **Parameters and Selection Filters**

First Grouping: VIEW\_WO\_WORKSHEET.WO\_NO
Second Grouping: VIEW\_JOB\_WORKSHEET.JOB

**Third Grouping:** 

Sorted By:

From Date:

To Date:

Option 1:

Option 2:

Selection Filters: isnull((VIEW JOB WORKSHEET.ORIG JOB ID)) and (VIEW JOB WORKSHEET.JOB STATUS) <> "CAN" and (view udc main.unit no) =

'232451') //Q=