

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35087

USING DEPT NO:	507301	OPENED DATE:	12/06/2019 14:37:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2019 07:25:44	METER 1 - M:	54	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2019 07:25:46	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	36.25	0.00	0.00	36.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	12/06/2019 14:37:38	12/06/2019 15:07:38	0.50	\$36.25
					LABOR	36.25

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35087

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36351

USING DEPT NO:	507301	OPENED DATE:	05/07/2020 11:46:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2020 08:38:42	METER 1 - M:	2914	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2020 10:13:14	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$62.09	\$35.68	\$0.00	\$97.77

JOB COUNT: 1	WORK ORDER TOTAL:	0.86	62.09	35.68	0.00	97.77
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/07/2020 13:40:33	05/07/2020 14:15:00	0.57	\$41.63
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/07/2020 13:30:32	05/07/2020 13:47:28	0.28	\$20.46
					LABOR	62.09

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					PARTS	35.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36351

---

## Work Order Notes

(EKIMBREL) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG/JW performed pm

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 37876

USING DEPT NO:	507301	OPENED DATE:	10/05/2020 14:45:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/07/2020 07:44:09	METER 1 - M:	3159	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/07/2020 12:55:57	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.89	\$0.00	\$0.00	\$33.89

JOB COUNT: 1	WORK ORDER TOTAL:	0.29	33.89	0.00	0.00	33.89
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/06/2020 13:28:41	10/06/2020 13:41:15	0.21	\$24.71
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/06/2020 13:21:34	10/06/2020 13:25:18	0.06	\$7.34
66-PM-PMA	PERFORM OIL CHANGE	11170580	10/06/2020 11:48:56	10/06/2020 11:49:52	0.02	\$1.84
					<b>LABOR</b>	<b>33.89</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 37876

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 254 miles since last PM. Checked fluids,battery, tire pressure and updated oil change sticker. SH

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39324

USING DEPT NO:	507301	OPENED DATE:	03/08/2021 07:46:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2021 07:40:38	METER 1 - M:	6241	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/12/2021 14:05:52	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.26	\$30.81	\$0.00	\$0.00	\$30.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$100.04	\$35.00	\$0.00	\$135.04

JOB COUNT: 2	WORK ORDER TOTAL:					1.11	130.85	35.00	0.00	165.85
--------------	-------------------	--	--	--	--	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/09/2021 07:07:40	03/09/2021 07:58:32	0.85	\$100.04
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	03/09/2021 08:17:20	03/09/2021 08:33:00	0.26	\$30.81
					LABOR	130.85

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	12.57	1	\$12.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	35.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39324

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotated tires and checked brakes. All pads are 12mm. Torqued all lugs to 76ft lbs. JAW

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 6241. SH Performed PM.

---



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40223

USING DEPT NO:	507301	OPENED DATE:	06/22/2021 08:29:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/23/2021 14:38:09	METER 1 - M:	11061	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/23/2021 14:38:12	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$47.95	\$41.51	\$0.00	\$89.46

JOB COUNT: 1	WORK ORDER TOTAL:	0.41	47.95	41.51	0.00	89.46
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2021 09:30:21	06/22/2021 09:54:44	0.41	\$47.95
					LABOR	47.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	12.57	1	\$12.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.51	1	\$6.51
					PARTS	41.51

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40223

## Work Order Notes

(CHANNELL) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW  
MILEAGE-11066

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40943

USING DEPT NO:	507301	OPENED DATE:	09/07/2021 07:52:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2021 09:59:04	METER 1 - M:	15063	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/09/2021 07:42:24	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.14	\$16.19	\$27.04	\$0.00	\$43.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$15.96	\$43.75	\$0.00	\$59.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.27	32.15	70.79	2.00	104.94
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/07/2021 10:31:59	09/07/2021 10:40:06	0.14	\$15.96
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/07/2021 10:08:46	09/07/2021 10:17:00	0.14	\$16.19
				LABOR		32.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	1	\$6.32
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.14	1	\$9.14
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.61	1	\$5.61
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	(1)	(\$6.32)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	5	\$31.58
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	70.79

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40943

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wipers

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW  
MILEAGE-15063

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41506

USING DEPT NO:	507301	OPENED DATE:	11/03/2021 14:15:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2021 13:52:33	METER 1 - M:	18875	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/09/2021 08:21:28	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$67.39	\$34.39	\$0.00	\$101.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.57	67.39	34.39	2.00	103.78
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/04/2021 10:18:57	11/04/2021 10:30:10	0.19	\$22.06
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/04/2021 09:34:08	11/04/2021 09:57:11	0.38	\$45.33
LABOR						67.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
PARTS						34.39

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41506

## Work Order Notes

(IFALLS) pm

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-18875

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41894

USING DEPT NO:	507301	OPENED DATE:	12/15/2021 07:36:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2021 10:13:46	METER 1 - M:	21465	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2021 09:11:50	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.11	\$13.44	\$31.82	\$0.00	\$45.26
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.71	\$83.55	\$0.00	\$0.00	\$83.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.16	\$137.01	\$62.10	\$0.00	\$199.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.98	234.00	93.92	2.00	329.92
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2021 10:23:18	12/15/2021 10:54:27	0.52	\$61.26
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/15/2021 10:15:36	12/15/2021 10:54:07	0.64	\$75.75
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/15/2021 10:15:59	12/15/2021 10:22:49	0.11	\$13.44
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/15/2021 12:19:44	12/15/2021 12:19:44	0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	11901357	12/16/2021 07:22:04	12/16/2021 08:04:33	0.71	\$83.55
				LABOR		234.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.20	1	\$9.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	27.78	1	\$27.78
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
				PARTS		93.92

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41894

## Work Order Notes

(LISAPATE) PM-replace wipers-Do SI going to Dallas Tx

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-79-003 - PERFORM SAFETY INSPECTION**

(AGUERRA) miles: 21465 Completed safety inspection, no issues found. Completed safety inspection checklist. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 21465 Completed PM topside, Josh was bottomside. Completed checklist. AMG/JW

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42234

USING DEPT NO:	507301	OPENED DATE:	01/31/2022 11:54:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/02/2022 07:36:02	METER 1 - M:	24794	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/02/2022 09:09:51	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$47.92	\$35.04	\$0.00	\$82.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.41	47.92	35.04	2.00	84.96
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/01/2022 10:23:32	02/01/2022 10:47:54	0.41	\$47.92
					LABOR	47.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
					PARTS	35.04

# Work Order Charge Detail

UNIT NO:	243602	2019 TOYOTA HIGHLANDER	WORK ORDER NO:	42234
----------	--------	------------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42590

USING DEPT NO:	507301	OPENED DATE:	03/07/2022 11:10:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2022 10:20:57	METER 1 - M:	29814	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2022 14:16:13	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.38	\$28.48	\$0.00	\$64.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.31	36.38	28.48	2.00	66.86
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/07/2022 12:19:44	03/07/2022 12:19:44	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/07/2022 11:17:03	03/07/2022 11:35:33	0.31	\$36.38
LABOR						36.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
PARTS						28.48

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42590

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(LISAPATE) cancel job

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Scott drained oil and filter. Josh installed new filter and plug. Coolant -34°. SH/SH,JAW  
Mileage-29814

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43020

USING DEPT NO:	507301	OPENED DATE:	04/25/2022 07:26:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2022 11:36:15	METER 1 - M:	32414	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2022 08:09:33	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$17.50	\$27.82	\$0.00	\$45.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$7.87	\$11.22	\$0.00	\$19.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	25.37	39.04	2.00	66.41
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/25/2022 09:04:59	04/25/2022 09:08:59	0.07	\$7.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/25/2022 08:55:54	04/25/2022 09:04:48	0.15	\$17.50
					LABOR	25.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	11.22	1	\$11.22
					PARTS	39.04

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43020

## Work Order Notes

(LISAPATE) PM

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/JW Performed PM.

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced cabin air filter. SH

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43676

USING DEPT NO:	507301	OPENED DATE:	06/16/2022 07:44:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2022 11:47:35	METER 1 - M:	38405	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/17/2022 15:26:45	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.18	\$23.00	\$0.00	\$28.18
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.65	\$34.55	\$0.00	\$57.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.24	27.83	57.55	2.00	87.38
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/16/2022 09:30:00	06/16/2022 09:33:42	0.06	\$7.28
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/16/2022 09:07:11	06/16/2022 09:15:00	0.13	\$15.37
03-51-038	REPLACE NEW WIPER BLADES	11901357	06/16/2022 09:04:20	06/16/2022 09:06:58	0.04	\$5.18
				LABOR		27.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.53	1	\$12.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.22	1	\$5.22
					PARTS	57.55

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43676

## Work Order Notes

(CWIGLEY) PM-Replace Wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 38405 Completed PM top and bottom side. Completed checklist. AMG/AMG

**CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44539

USING DEPT NO:	507301	OPENED DATE:	09/01/2022 07:06:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/02/2022 09:39:28	METER 1 - M:	42012	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/06/2022 09:33:35	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$92.99	\$41.98	\$0.00	\$134.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.79	92.99	41.98	5.00	139.97
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/01/2022 10:29:14	09/01/2022 10:31:32	0.04	\$4.52
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/01/2022 10:07:29	09/01/2022 10:28:52	0.36	\$42.05
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/01/2022 10:04:41	09/01/2022 10:28:17	0.39	\$46.41
					LABOR	92.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
					PARTS	41.98

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44539

---

## Work Order Notes

(CWIGLEY) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 42012 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45131

USING DEPT NO:	507301	OPENED DATE:	11/01/2022 10:10:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2022 10:27:42	METER 1 - M:	46235	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/02/2022 12:26:09	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.92	\$49.89	\$0.00	\$101.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.44	51.92	49.89	5.00	106.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/01/2022 10:55:28	11/01/2022 11:21:52	0.44	\$51.92
					LABOR	51.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
					PARTS	49.89

# Work Order Charge Detail

UNIT NO: 243602 2019 TOYOTA HIGHLANDER WORK ORDER NO: 45131

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45958

USING DEPT NO:	507301	OPENED DATE:	01/27/2023 10:24:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/30/2023 09:24:00	METER 1 - M:	50311	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/30/2023 10:29:40	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$23.26	\$0.00	\$40.96
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.40	\$46.77	\$0.00	\$0.00	\$46.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.54	\$72.41	\$0.00	\$128.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.03	121.01	95.67	5.00	221.68
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	01/27/2023 14:33:17	01/27/2023 14:57:04	0.40	\$46.77
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/27/2023 13:34:02	01/27/2023 13:38:35	0.08	\$8.95
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/27/2023 13:50:13	01/27/2023 14:14:25	0.40	\$47.59
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/27/2023 14:14:25	01/27/2023 14:14:25	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/27/2023 14:14:25	01/27/2023 14:14:25	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	01/27/2023 14:14:25	01/27/2023 14:23:25	0.15	\$17.70
				LABOR		121.01

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	DODGE DURANGO AIR FILTER	30.92	1	\$30.92
				PARTS		95.67

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45958

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

### 66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Performed tire rotation and brake check-GC

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, changed oil and oil filter, checked fluids, tires and tire pressure, replaced both air filter and cabin filter.  
Miles- 50,311

### 66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) GC replaced cabin filter

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46523

USING DEPT NO:	507301	OPENED DATE:	03/24/2023 08:09:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/28/2023 15:30:16	METER 1 - M:	56345	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/04/2023 07:42:22	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$80.50	\$80.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$50.12	\$38.06	\$0.00	\$88.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.42	50.12	38.06	85.50	173.68
--------------	-------------------	------	-------	-------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	2107221		\$80.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	85.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/24/2023 14:30:00	03/24/2023 14:55:29	0.42	\$50.12
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/24/2023 14:22:55	03/24/2023 14:22:55	0.00	\$0.00
				LABOR		50.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	5	\$31.28
					PARTS	38.06

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46523

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

24-02-061 - REPAIR WINDSHIELD

(EKIMBREL) GLASS DR REPAIRED WINDSHIELD

(LISAPATE) Windshield had 3 dings in it.

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM,-GC, Changed oil and oil filter, checked fluids, tires and tire pressure, filters good.

Miles, 56,345

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47129

USING DEPT NO:	507301	OPENED DATE:	05/22/2023 09:32:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/22/2023 13:44:39	METER 1 - M:	60134	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2023 10:17:11	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.13	\$14.85	\$24.06	\$0.00	\$38.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.60	\$48.43	\$0.00	\$64.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.26	30.45	72.49	5.00	107.94
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/22/2023 10:35:44	05/22/2023 10:43:17	0.13	\$14.85
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2023 10:27:37	05/22/2023 10:35:33	0.13	\$15.60
					LABOR	30.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.83	1	\$10.83
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
					PARTS	72.49

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47129

## Work Order Notes

(EHANNAH) PM- REPLACE WIPERS

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) CW Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH CW/GC Performed PM.

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47767

USING DEPT NO:	507301	OPENED DATE:	07/28/2023 07:31:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/01/2023 08:06:33	METER 1 - M:	65163	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:24:38	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.52	\$24.08	\$0.00	\$28.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.69	\$37.46	\$0.00	\$87.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	54.21	61.54	5.00	120.75
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/28/2023 14:57:21	07/28/2023 14:59:39	0.04	\$4.52
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/28/2023 14:32:05	07/28/2023 14:57:21	0.42	\$49.69
					LABOR	54.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.11	1	\$6.11
					PARTS	61.54

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47767

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

### 66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Miles, 65,163

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49145

USING DEPT NO:	507301	OPENED DATE:	12/04/2023 13:42:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2023 09:58:06	METER 1 - M:	71453	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2023 13:22:08	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.32	\$43.28	\$0.00	\$67.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.21	24.32	43.28	5.00	72.60
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	12/05/2023 07:00:43	12/05/2023 07:13:05	0.21	\$24.32
LABOR						24.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
PARTS						43.28

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49145

---

## Work Order Notes

(EHANNAH) PM

---

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure,

Note, tires are all 4 and will need to be replaced probably next PM.

Miles, 71,453

### CH-SP - CHARGE Shop Supplies

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49939

USING DEPT NO:	507301	OPENED DATE:	02/26/2024 09:11:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2024 13:43:14	METER 1 - M:	72897	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 10:16:32	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.81	\$95.45	\$0.00	\$0.00	\$95.45
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.31	\$154.65	\$924.06	\$0.00	\$1,078.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	2.87	338.60	924.06	5.00	1,267.66
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	12052187	03/01/2024 07:05:23	03/01/2024 07:20:48	0.26	\$30.32
14-52-021	INSTALL GPS SYSTEM	12395904	03/04/2024 07:00:00	03/04/2024 07:30:00	0.50	\$59.00
14-52-021	INSTALL GPS SYSTEM	12395904	03/04/2024 07:00:00	03/04/2024 07:30:00	(0.50)	(\$59.00)
14-52-021	INSTALL GPS SYSTEM	11074414	03/04/2024 07:00:00	03/04/2024 07:30:00	0.50	\$59.00
06-15	INSPECT STEERING	12395904	03/04/2024 07:00:00	03/04/2024 07:15:00	0.25	\$29.50
66-17-013	PERFORM ALIGNMENT	12052187	02/29/2024 15:02:02	02/29/2024 15:35:09	0.55	\$65.13
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	02/29/2024 14:30:00	02/29/2024 14:41:25	0.19	\$22.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	02/29/2024 13:07:47	02/29/2024 14:15:00	1.12	\$132.19
					LABOR	338.59

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04504940000	TIRE 245/60R18 GEN GRB HTS60	223.29	4	\$893.16
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	52	\$11.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.80	4	\$19.20
					PARTS	924.06

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49939

## Work Order Notes

(LISAPATE) Replace 4 tires

## Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

06-15 - INSPECT STEERING

(LISAPATE) FC checked steering was good

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) SH installed GPS 87U030240140

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Adjusted rear and front toe. Test drove and found no other issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) Mounted 4 tires and balanced 52 - 100360 - 4 - 21030 fc

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 50760

USING DEPT NO:	507301	OPENED DATE:	05/06/2024 15:43:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/08/2024 08:25:33	METER 1 - M:	75700	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/08/2024 09:48:20	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.05	\$53.78	\$0.00	\$54.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.01	1.05	53.78	5.00	59.83
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/07/2024 07:56:58	05/07/2024 07:57:30	0.01	\$1.05
					LABOR	1.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
					PARTS	53.78

# Work Order Charge Detail

UNIT NO:2436022019 TOYOTA HIGHLANDER

WORK ORDER NO:50760

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc - ah

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 50885

USING DEPT NO:	507301	OPENED DATE:	05/17/2024 12:08:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2024 13:22:31	METER 1 - M:	76455	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2024 09:34:40	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH7KS060878	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-042	INSTALL KEY FOB BATTERY	DON	N	N	GARAGE	0.15	\$17.70	\$3.41	\$0.00	\$21.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.15	17.70	3.41	5.00	26.11
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-51-042	INSTALL KEY FOB BATTERY	11399745	05/17/2024 13:27:30	05/17/2024 13:36:30	0.15	\$17.70
					LABOR	17.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-042	INSTALL KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	1	\$3.41
					PARTS	3.41

# Work Order Charge Detail

UNIT NO: 243602 2019 TOYOTA HIGHLANDER WORK ORDER NO: 50885

Work Order Notes

(EHANNAH) key fob battery

Job Notes

14-51-042 - INSTALL KEY FOB BATTERY

(EKIMBREL) cw replaced key fob battery

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		243602	2019 TOYOTA HIGHLANDER				WORK ORDER NO:		51568			
USING DEPT NO:		507301	OPENED DATE:		07/23/2024 09:00:11		LOCATION: GARAGE - University Automotive Services					
WO STATUS:		OPEN	COMPLETED DATE:				METER 1 - M: 78946		METER 2 - N: 0			
WO VISIT REASON:		SCHEDULED	CLOSED DATE:				IN-SERVICE DATE:		12/06/2019			
TECH SPEC NO:		19TOYHIGHLNDR	2019 Toyota Highlander				UNIT SERIAL NO:		5TDZARFH7KS060878			
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999		PREP DISPOSE PREPARE UNIT FOR DI		DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/06/2024 20:49:23 By User: GLOBETTI

UNIT NO: 243602 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51568

## Work Order Notes

(EHANNAH) prep for sale

## Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) EH performed prep for sale.

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Aug 06 2024 20:49:23 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '5TDZARFH7KS060878') //Q=