

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 37788

USING DEPT NO:	507143	OPENED DATE:	09/28/2020 08:14:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2020 08:15:31	METER 1 - M:	59	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2020 10:11:59	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	09/28/2020 08:15:00	09/28/2020 08:45:00	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 37788

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 38644

USING DEPT NO:	507143	OPENED DATE:	12/14/2020 08:50:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/14/2020 15:49:19	METER 1 - M:	190	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/15/2020 07:54:36	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.12	\$14.29	\$0.00	\$0.00	\$14.29

JOB COUNT: 1	WORK ORDER TOTAL:	0.12	14.29	0.00	0.00	14.29
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/14/2020 14:34:15	12/14/2020 14:41:31	0.12	\$14.29
					LABOR	14.29

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 38644

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 190 miles. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-190

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 39328

USING DEPT NO:	507143	OPENED DATE:	03/08/2021 09:23:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2021 07:49:48	METER 1 - M:	1429	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/12/2021 14:00:08	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$5.77	\$35.68	\$0.00	\$41.45

JOB COUNT: 1	WORK ORDER TOTAL:	0.05	5.77	35.68	0.00	41.45
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/08/2021 15:39:54	03/08/2021 15:42:50	0.05	\$5.77
					LABOR	5.77

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	35.68

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 39328

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 1429 Completed PM top side Josh assisted, Scott was bottom side. Completed checklist and vacuumed out vehicle. AMG JW SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 39527

USING DEPT NO:	507143	OPENED DATE:	03/31/2021 08:11:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2021 10:56:29	METER 1 - M:	2111	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2021 09:25:32	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.58	\$68.47	\$0.47	\$0.00	\$68.94

JOB COUNT: 1	WORK ORDER TOTAL:	0.58	68.47	0.47	0.00	68.94
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	03/31/2021 08:31:32	03/31/2021 09:06:21	0.58	\$68.47
					LABOR	68.47

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.47	1	\$0.47
					PARTS	0.47

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 39527

Work Order Notes

(LISAPATE) RF tire hit a curb, hole in sidewall. Spare tire is on

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced rf tire with good used pull off tire. Aired to spec and balanced. Valve stem is still good. Replaced valve core with new non Inv core.

Torqued lugs to 76ft lbs. Put spare back in trunk. JAW

MILEAGE-2111

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40062

USING DEPT NO:	507143	OPENED DATE:	06/01/2021 09:13:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2021 09:08:41	METER 1 - M:	4411	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2021 08:49:45	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.33	\$38.68	\$0.00	\$0.00	\$38.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$96.40	\$46.32	\$0.00	\$142.72

JOB COUNT: 2	WORK ORDER TOTAL:	1.14	135.08	46.32	0.00	181.40
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	06/01/2021 10:13:06	06/01/2021 10:32:46	0.33	\$38.68
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/01/2021 09:51:29	06/01/2021 10:20:20	0.48	\$56.74
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/01/2021 10:03:57	06/01/2021 10:13:01	0.15	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/01/2021 10:01:38	06/01/2021 10:12:44	0.19	\$21.83
					LABOR	135.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.51	1	\$6.51
					PARTS	46.32

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40062

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 4411 Completed PM topside, Josh assisted, Scott was bottomsides. Completed checklist. AMG JW/SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40129

USING DEPT NO:	507143	OPENED DATE:	06/09/2021 07:46:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/09/2021 14:57:55	METER 1 - M:	4706	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2021 11:59:43	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.62	\$73.19	\$4.49	\$0.00	\$77.68

JOB COUNT: 1	WORK ORDER TOTAL:	0.62	73.19	4.49	0.00	77.68
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11901357	06/09/2021 07:49:09	06/09/2021 08:26:22	0.62	\$73.19
					LABOR	73.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	1	\$0.48
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.01	1	\$4.01
					PARTS	4.49

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40129

Work Order Notes

(LISAPATE) LR tire has a screw in it

Job Notes

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 4706 Repaired L/R tire, rebalanced and rechecked for leak, all good. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40917

USING DEPT NO:	507143	OPENED DATE:	09/02/2021 09:26:25	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	09/14/2021 14:41:05	METER 1 - M:	7912	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/15/2021 14:00:16	IN-SERVICE DATE:	09/25/2020						
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry									
			UNIT SERIAL NO:	4T1C11AK4LU370568							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.67	\$17.90	\$0.00	\$21.57
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.08	\$9.24	\$0.00	\$0.00	\$9.24
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.56	\$66.34	\$0.00	\$0.00	\$66.34
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.77	\$91.16	\$484.35	\$0.00	\$575.51
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.71	\$56.92	\$0.00	\$95.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.77	209.12	559.17	2.00	770.29
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11170580	09/08/2021 11:22:22	09/08/2021 11:56:06	0.56	\$66.34
06-15	INSPECT STEERING	11074414	09/14/2021 14:30:00	09/14/2021 14:34:42	0.08	\$9.24
06-15	INSPECT STEERING	11074414	09/14/2021 14:29:04	09/14/2021 14:29:04	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/08/2021 10:05:06	09/08/2021 10:05:48	0.01	\$1.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	09/07/2021 07:14:08	09/07/2021 07:59:47	0.76	\$89.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/02/2021 14:30:00	09/02/2021 14:32:35	0.04	\$5.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/02/2021 14:15:42	09/02/2021 14:15:42	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/02/2021 14:27:25	09/02/2021 14:29:17	0.03	\$3.67
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/02/2021 14:10:06	09/02/2021 14:27:12	0.29	\$33.63
					LABOR	209.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	241.38	2	\$482.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	10	\$0.60

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.50	2	\$0.99
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.27	1	\$9.27
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
					PARTS	559.17

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 40917

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wipers

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues. SH

09-15 - ALIGN STEERING

(ABLACK) AB performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 2 tires put new tires on the front. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 7912. SH/JW Performed PM. Left rear tire is at 2/32 and the DOT is 2519. The other tire dates are 1020. Recommend 2 tires and save the right rear for a spare. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 41824

USING DEPT NO:	507143	OPENED DATE:	12/08/2021 15:01:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2021 13:42:11	METER 1 - M:	10279	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2021 13:25:43	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-004	REPLACE NEW CLEARANCE/MARKER	DON	O	N	GARAGE	0.18	\$20.91	\$0.43	\$0.00	\$21.34
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$2.95	\$17.90	\$0.00	\$20.85
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.38	\$44.68	\$0.00	\$0.00	\$44.68
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.55	\$64.70	\$49.13	\$0.00	\$113.83
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.08	\$9.60	\$18.57	\$0.00	\$28.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.21	142.84	86.03	2.00	230.87
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/09/2021 10:35:25	12/09/2021 10:36:56	0.03	\$2.98
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/09/2021 09:31:59	12/09/2021 09:37:18	0.09	\$10.46
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/09/2021 09:24:58	12/09/2021 09:26:28	0.03	\$2.95
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/09/2021 08:58:37	12/09/2021 09:24:41	0.43	\$51.26
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	12/09/2021 12:28:14	12/09/2021 12:50:57	0.38	\$44.68
03-34-004	REPLACE NEW CLEARANCE/MARKER	11901357	12/09/2021 12:17:19	12/09/2021 12:27:57	0.18	\$20.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	12/09/2021 09:26:45	12/09/2021 09:31:38	0.08	\$9.60
					LABOR	142.84

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-004	REPLACE NEW CLEARANCE/MARKER	194	BULB-TAG/MARKER	0.43	1	\$0.43
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.57	1	\$18.57
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	86.03

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 41824

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-34-004 - REPLACE NEW CLEARANCE/MARKER

(AGUERRA) Replaced R/F side marker light bulb, checked for proper operation, all good. AMG

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 10279 Completed PM topside, Josh was bottomside. Completed checklist. AMG/JW

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 42556

USING DEPT NO:	507143	OPENED DATE:	03/03/2022 10:38:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2022 15:02:26	METER 1 - M:	12202	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/07/2022 07:42:13	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.23	\$17.90	\$0.00	\$22.13
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.10	\$11.51	\$0.00	\$0.00	\$11.51
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.86	\$101.97	\$0.00	\$0.00	\$101.97
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.11	\$131.01	\$643.09	\$0.00	\$774.10
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.61	\$39.78	\$0.00	\$98.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
JOB COUNT: 6		WORK ORDER TOTAL:				2.60	307.33	700.77	2.00	1,010.10

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11310047	03/03/2022 14:10:18	03/03/2022 15:02:09	0.86	\$101.97
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/03/2022 13:06:29	03/03/2022 14:13:06	1.11	\$131.01
06-15	INSPECT STEERING	11074414	03/03/2022 13:00:00	03/03/2022 13:05:51	0.10	\$11.51
06-15	INSPECT STEERING	11074414	03/03/2022 12:59:53	03/03/2022 12:59:53	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/03/2022 11:34:21	03/03/2022 11:36:30	0.04	\$4.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/03/2022 11:04:20	03/03/2022 11:34:08	0.50	\$58.61
LABOR						307.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.65	1	\$0.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.36	1	\$0.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	12	\$1.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	9.63	4	\$38.52

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1549788	TIRE GEN ALTIMAX 215/55R17	150.33	4	\$601.32
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
					PARTS	700.77

Work Order Charge Detail

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 42556

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) SH Mounted EH balanced 4 tires.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Needs 4 tires due to 2/32 tread depth on the front and excessive shoulder wear on the rear.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 43469

USING DEPT NO:	507143	OPENED DATE:	06/02/2022 08:08:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2022 15:18:48	METER 1 - M:	14014	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2022 12:36:56	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.34	\$39.60	\$0.00	\$0.00	\$39.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.73	\$86.04	\$72.23	\$0.00	\$158.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.06	125.64	72.23	2.00	199.87
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	06/02/2022 09:41:41	06/02/2022 10:01:49	0.34	\$39.60
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/02/2022 09:30:00	06/02/2022 09:35:15	0.09	\$10.33
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/02/2022 08:36:30	06/02/2022 09:15:00	0.64	\$75.72
				LABOR		125.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	25.53	1	\$25.53
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.35	1	\$9.35
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
					PARTS	72.23

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 43469

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 14014 Completed PM top and bottom side. Completed checklist. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 44442

USING DEPT NO:	507143	OPENED DATE:	08/24/2022 08:48:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2022 15:04:32	METER 1 - M:	15672	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2022 09:39:56	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.11	\$23.19	\$0.00	\$24.30
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.42	\$49.76	\$0.00	\$0.00	\$49.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$3.02	\$0.00	\$0.00	\$3.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.46	53.89	23.19	5.00	82.08
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/24/2022 09:32:28	08/24/2022 09:57:46	0.42	\$49.76
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/24/2022 09:31:42	08/24/2022 09:32:16	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/24/2022 09:30:00	08/24/2022 09:31:32	0.03	\$3.02
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/24/2022 09:23:33	08/24/2022 09:23:33	0.00	\$0.00
				LABOR		53.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
					PARTS	23.19

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 44442

Work Order Notes

(LISAPATE) PM-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-79-003 - PERFORM SAFETY INSPECTION

(LISAPATE) SI done all good. AG

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1490 miles. Checked fluids and tires. Coolant -34°. JAW,AMG,JM
MILRAGE-15672

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 45143

USING DEPT NO:	507143	OPENED DATE:	11/02/2022 07:05:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2022 15:30:27	METER 1 - M:	17045	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/07/2022 07:31:59	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.39	\$46.54	\$0.00	\$0.00	\$46.54
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.84	\$41.45	\$0.00	\$72.29
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.66	77.38	41.45	5.00	123.83
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/02/2022 10:09:15	11/02/2022 10:32:55	0.39	\$46.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2022 09:34:28	11/02/2022 09:50:09	0.26	\$30.84
					LABOR	77.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
					PARTS	41.45

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 45143

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46026

USING DEPT NO:	507143	OPENED DATE:	02/01/2023 15:40:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/03/2023 09:41:19	METER 1 - M:	18435	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2023 09:06:38	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.35	\$41.33	\$0.00	\$0.00	\$41.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.35	41.33	0.00	5.00	46.33
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/02/2023 07:11:27	02/02/2023 07:32:28	0.35	\$41.33
					LABOR	41.33

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46026

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Vehicle has been driven 1390 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46599

USING DEPT NO:	507143	OPENED DATE:	04/04/2023 07:12:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/07/2023 13:43:54	METER 1 - M:	19540	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/10/2023 08:00:28	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.05	\$5.97	\$193.87	\$0.00	\$199.84
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.06	\$6.59	\$0.00	\$0.00	\$6.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.11	12.56	193.87	5.00	211.43
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	04/04/2023 09:45:28	04/04/2023 09:48:30	0.05	\$5.97
66-79-002	PERFORM SERVICE CALL	11915538	04/04/2023 07:43:09	04/04/2023 07:46:30	0.06	\$6.59
					LABOR	12.56

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557627	TIRE 215/55R17 GEN ALTIMAX	189.63	1	\$189.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.50	1	\$3.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58126	1.75 OZ WHEEL WEIGHT	0.74	1	\$0.74
					PARTS	193.87

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46599

Work Order Notes

(EHANNAH) service call for flat tire - tire patch

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and balanced new right rear tire. Other tire had hole in side wall. -GC
Miles, 19,540

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) could not patch

66-79-002 - PERFORM SERVICE CALL

(CHANNELL) aired tire up brought back to shop\\ RC\CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46991

USING DEPT NO:	507143	OPENED DATE:	05/09/2023 13:36:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2023 14:58:23	METER 1 - M:	20181	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/12/2023 10:38:58	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.26	\$23.96	\$0.00	\$28.22
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.05	\$5.31	\$0.00	\$0.00	\$5.31
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.17	\$19.73	\$0.00	\$0.00	\$19.73
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.49	\$58.34	\$543.47	\$0.00	\$601.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$101.28	\$41.34	\$0.00	\$142.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.60	188.92	608.77	5.00	802.69
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-013	PERFORM ALIGNMENT	11310047	05/11/2023 13:15:36	05/11/2023 13:25:38	0.17	\$19.73
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/10/2023 12:12:31	05/10/2023 12:12:31	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/10/2023 10:20:26	05/10/2023 10:50:06	0.49	\$58.34
06-15	INSPECT STEERING	12201267	05/10/2023 10:17:30	05/10/2023 10:20:12	0.05	\$5.31
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/10/2023 07:19:40	05/10/2023 07:29:13	0.16	\$18.78
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/09/2023 15:02:10	05/09/2023 15:44:07	0.70	\$82.50
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/09/2023 14:59:16	05/09/2023 15:01:26	0.04	\$4.26
					LABOR	188.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.50	3	\$10.49
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.13	23	\$3.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1557627	TIRE 215/55R17 GEN ALTIMAX	176.63	3	\$529.88
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.79	1	\$5.79

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.74	1	\$10.74
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.22	1	\$13.22
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
					PARTS	608.77

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 46991

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

06-15 - INSPECT STEERING

(GRCOOK) Inspected steering and found no issues found at this time-GC

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH/JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and Balanced 3 new tires.-GC

Brake pads are all 7mm on all 4 wheels.

Miles, 20,181

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,JW, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.

Miles, 20,181

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 47523

USING DEPT NO:	507143	OPENED DATE:	07/05/2023 07:31:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/10/2023 13:49:29	METER 1 - M:	21000	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/10/2023 15:29:31	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.39	\$45.56	\$24.08	\$0.00	\$69.64
15-02-029	WARRANTY SEAT TRIM	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.19	\$0.00	\$0.00	\$20.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.06	124.75	24.08	5.00	153.83
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-02-029	WARRANTY SEAT TRIM	11076422	6210662		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	07/10/2023 07:00:00	07/10/2023 07:30:00	0.50	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	07/05/2023 10:02:08	07/05/2023 10:25:18	0.39	\$45.56
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/05/2023 09:51:36	07/05/2023 10:01:52	0.17	\$20.19
				LABOR		124.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	24.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 47523

Work Order Notes

(EHANNAH) pm- replace wipers
(EHANNAH) seat warranty trim- transport

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers. JAW

15-02-029 - WARRANTY SEAT TRIM

(LISAPATE) Tuscaloosa Toyota Installed new trim under front of drivers seat was broken

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 811 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-20992

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 48347

USING DEPT NO:	507143	OPENED DATE:	09/26/2023 15:26:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2023 08:25:40	METER 1 - M:	23523	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2023 11:12:54	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$50.09	\$0.00	\$89.03
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$22.73	\$0.00	\$58.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.63	74.34	72.82	5.00	152.16
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	09/28/2023 07:19:48	09/28/2023 07:37:48	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/28/2023 07:00:00	09/28/2023 07:19:48	0.33	\$38.94
					LABOR	74.34

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.14	1	\$6.14
					PARTS	72.82

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 48347

Work Order Notes

(EHANNAH) pm- wash- estimate for hood damage and transport to vendor for repairs of hood.

Job Notes

16-71 - TRANSPORT BODY

24-71 - REPAIR BODY

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by FC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed FC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 48753

USING DEPT NO:	507143	OPENED DATE:	10/30/2023 08:35:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2023 10:26:26	METER 1 - M:	24276	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2023 13:10:27	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.15	\$17.70	\$221.08	\$0.00	\$238.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.15	17.70	221.08	5.00	243.78
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12395904	11/01/2023 07:00:00	11/01/2023 07:09:00	0.15	\$17.70
06-32-002	INSPECT BATTERY	12395904	10/31/2023 09:15:21	10/31/2023 09:15:21	0.00	\$0.00
06-32-002	INSPECT BATTERY	12395904	10/31/2023 09:15:21	10/31/2023 09:15:21	0.00	\$0.00
				LABOR		17.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	221.08	1	\$221.08
					PARTS	221.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 48753

Work Order Notes

(EHANNAH) inspect the battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replace new battery fc

06-32-002 - INSPECT BATTERY

(LISAPATE)

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49250

USING DEPT NO:	507143	OPENED DATE:	12/13/2023 13:03:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2023 10:12:31	METER 1 - M:	25622	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/18/2023 11:10:11	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.60	\$0.00	\$0.00	\$25.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.22	25.60	0.00	5.00	30.60
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/13/2023 13:50:08	12/13/2023 14:03:09	0.22	\$25.60
					LABOR	25.60

Work Order Charge Detail

UNIT NO:2438532020 TOYOTA CAMRY

WORK ORDER NO:49250

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Driven 1099 miles. Checked fluids tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49503

USING DEPT NO:	507143	OPENED DATE:	01/19/2024 15:32:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/25/2024 10:02:36	METER 1 - M:	26713	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 11:11:44	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-032	REPAIR TRIM, MISCELLANEOUS	DON	O	N	GARAGE	0.10	\$11.80	\$4.79	\$0.00	\$16.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.10	11.80	4.79	5.00	21.59
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-02-032	REPAIR TRIM, MISCELLANEOUS	11074414	01/25/2024 07:00:00	01/25/2024 07:06:00	0.10	\$11.80
					LABOR	11.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-02-032	REPAIR TRIM, MISCELLANEOUS	6221724020	CLIP, FR PILLAR	4.79	1	\$4.79
					PARTS	4.79

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49503

Work Order Notes

(EKIMBREL) repair trim around passenger window

Job Notes

24-02-032 - REPAIR TRIM, MISCELLANEOUS

(EKIMBREL) if replaced clip in trim around passenger window

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49897

USING DEPT NO:	507143	OPENED DATE:	02/22/2024 08:47:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/23/2024 09:32:55	METER 1 - M:	27863	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/26/2024 07:09:18	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.36	\$42.02	\$0.00	\$0.00	\$42.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.36	42.02	0.00	5.00	47.02
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	11074414	02/22/2024 08:53:38	02/22/2024 09:15:00	0.36	\$42.02
					LABOR	42.02

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49897

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240149. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49948

USING DEPT NO:	507143	OPENED DATE:	02/27/2024 07:09:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/29/2024 15:13:14	METER 1 - M:	28023	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2024 07:09:39	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.07	\$8.00	\$5.46	\$0.00	\$13.46
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.56	\$66.41	\$0.00	\$0.00	\$66.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$66.64	\$86.20	\$0.00	\$152.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.20	141.05	91.66	5.00	237.71
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12395904	02/27/2024 09:56:26	02/27/2024 10:00:30	0.07	\$8.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	02/27/2024 09:30:00	02/27/2024 09:53:26	0.39	\$46.09
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	02/27/2024 09:04:40	02/27/2024 09:15:00	0.17	\$20.32
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/27/2024 08:44:13	02/27/2024 08:45:01	0.01	\$1.57
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/27/2024 08:27:58	02/27/2024 08:43:35	0.26	\$30.71
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/27/2024 08:24:37	02/27/2024 08:42:05	0.29	\$34.35
				LABOR		141.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	14	\$2.73
66-PM-PMA	PERFORM OIL CHANGE	23131	TPMS SNAP IN VALVE 21060	3.62	1	\$3.62
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73

Work Order Charge Detail

PARTS	91.66
-------	-------

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 49948

Work Order Notes

(EHANNAH) pm

Job Notes

66-17-030 - PERFORM TIRE PATCH

(FCONTRER) perform tire patch and balanced 14 - 100360 1- 21060 1 14040 fc

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Rotate tires and check Brackets F8 m R 8 m fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes FC sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 50056

USING DEPT NO:	507143	OPENED DATE:	03/04/2024 09:55:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2024 14:08:23	METER 1 - M:	28192	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2024 10:25:37	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-019	REPLACE NEW OXYGEN SENSOR	DON	N	N	GARAGE	1.00	\$118.00	\$275.61	\$0.00	\$393.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	N	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.00	236.00	275.61	5.00	516.61
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-00	SCAN OUT COMPLETE VEHICLE	12052187	03/05/2024 12:20:58	03/05/2024 13:20:58	1.00	\$118.00
03-05-019	REPLACE NEW OXYGEN SENSOR	12052187	03/07/2024 07:00:00	03/07/2024 08:00:00	1.00	\$118.00
SO-00	SCAN OUT COMPLETE VEHICLE	12052187	03/05/2024 12:20:58	03/05/2024 12:20:58	0.00	\$0.00
SO-00	SCAN OUT COMPLETE VEHICLE	12052187	03/05/2024 12:20:58	03/05/2024 12:20:58	0.00	\$0.00
				LABOR		236.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-05-019	REPLACE NEW OXYGEN SENSOR	8946733210	OXYGEN SENSOR	275.61	1	\$275.61
					PARTS	275.61

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 50056

Work Order Notes

(EHANNAH) scan-out

Job Notes

03-05-019 - REPLACE NEW OXYGEN SENSOR

(LISAPATE) Replaced sensor and cleared codes. No other issues found. JAW

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(JWRIGHT) IF scanned unit for code p0037 bad o2 sensor downstream. Replaced sensor and cleared codes. No other issues found. JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 50843

USING DEPT NO:	507143	OPENED DATE:	05/14/2024 11:11:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/17/2024 07:54:52	METER 1 - M:	29551	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/17/2024 09:06:05	IN-SERVICE DATE:	09/25/2020	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK4LU370568	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.02	\$0.00	\$0.00	\$1.02
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.02	\$1.02
PS-00-999	PREP SERVICE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.01	1.02	0.00	1.02	2.04
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$1.02
				COMML	1.02

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/14/2024 13:21:39	05/14/2024 13:22:10	0.01	\$1.02
PS-00-999	PREP SERVICE PREPARE UNIT FOR DISPOSAL	11399745	05/16/2024 14:15:24	05/16/2024 14:15:24	0.00	\$0.00
					LABOR	1.02

Work Order Charge Detail

The University of Alabama

Report Printed: 06/11/2024 12:19:19 By User: GLOBETTI

UNIT NO: 243853 2020 TOYOTA CAMRY

WORK ORDER NO: 50843

Work Order Notes

(LRUSHING) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform fluid check fc

CH-SP - CHARGE Shop Supplies

PS-00-999 - PREP SERVICE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks tags off front and back. Removed strobe light off top of car. CW/GC

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Jun 11 2024 12:19:19 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243853') //Q=