

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 35008

USING DEPT NO: 507143	OPENED DATE: 11/27/2019 10:37:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/02/2019 14:37:31	METER 1 - M: 54 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/02/2019 14:37:33	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	11/27/2019 10:37:36	11/27/2019 11:07:36	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 35008

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 35549

USING DEPT NO: 507143	OPENED DATE: 01/31/2020 14:43:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/05/2020 07:57:37	METER 1 - M: 1438 METER 2 - N: 0
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 02/05/2020 07:57:39	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.50	\$0.00	\$6.70	\$0.00	\$6.70
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.28	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 **WORK ORDER TOTAL: 1.78 0.00 6.70 0.00 6.70**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	01/31/2020 15:25:11	01/31/2020 15:55:10	0.50	\$0.00
66-79-002	PERFORM SERVICE CALL	10208562	01/31/2020 14:52:09	01/31/2020 15:38:11	0.77	\$0.00
66-79-002	PERFORM SERVICE CALL	12052187	01/31/2020 14:54:36	01/31/2020 15:25:11	0.51	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	1.81	1	\$1.81
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.33	1	\$2.33
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.56	1	\$2.56
					PARTS	6.70

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 35549

Work Order Notes

(LISAPATE) Service call to Security Resources flat tire on RR

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) JW found 2 nails in tire. Repaired both sections and balanced out with no weights. Aired and torqued to spec.

66-79-002 - PERFORM SERVICE CALL

(EKIMBREL) JW/EK performed service call. Aired tire up and brought to shop.

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY WORK ORDER NO: 35969

USING DEPT NO:	507143	OPENED DATE:	03/10/2020 10:56:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2020 15:13:58	METER 1 - M:	3099	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/13/2020 10:10:40	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.81	\$0.00	\$5.31	\$0.00	\$5.31

JOB COUNT: 1 WORK ORDER TOTAL: 0.81 0.00 5.31 0.00 5.31

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	03/10/2020 11:04:28	03/10/2020 11:52:57	0.81	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.29	1	\$0.29
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	3	\$0.12
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.56	1	\$2.56
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34

PARTS 5.31

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 35969

Work Order Notes

(EKIMBREL) Right front tire has a nail

Job Notes

66-17-030 - PERFORM TIRE PATCH

(EKIMBREL) AG repaired and balanced RF tire, Rechecked good.

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 36099

USING DEPT NO: 507143	OPENED DATE: 04/06/2020 08:44:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/07/2020 09:06:28	METER 1 - M: 3782 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/08/2020 07:40:50	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.30	\$0.00	\$0.00	\$0.00	\$0.00
66-17-015	PERFORM TIRE ROTATION	DON	O	N	GARAGE	0.21	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.91	\$0.00	\$166.80	\$0.00	\$166.80
66-79-002	PERFORM SERVICE CALL	DON	P	N	GARAGE	0.28	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	O	N	GARAGE	1.32	\$0.00	\$24.03	\$0.00	\$24.03

JOB COUNT: 5	WORK ORDER TOTAL:	3.03	0.00	190.83	0.00	190.83
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/06/2020 11:20:01	04/06/2020 11:45:35	0.43	\$0.00
66-17-015	PERFORM TIRE ROTATION	11901357	04/06/2020 11:45:35	04/06/2020 11:58:26	0.21	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/06/2020 13:00:38	04/06/2020 13:54:21	0.90	\$0.00
09-15	ALIGN STEERING	11310047	04/06/2020 14:15:46	04/06/2020 14:15:46	0.00	\$0.00
09-15	ALIGN STEERING	11310047	04/06/2020 14:30:00	04/06/2020 14:48:07	0.30	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	04/06/2020 10:25:25	04/06/2020 11:20:01	0.91	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	04/06/2020 10:08:29	04/06/2020 10:25:25	0.28	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	3.94	5	\$19.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	1	\$2.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	006189	TIRE 215/55R17 ECOPIA EP422+	163.89	1	\$163.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	(1)	(\$2.21)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.56	1	\$2.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	1	\$0.27
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	2	\$0.08

Work Order Charge Detail

PARTS

190.83

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 36099

Work Order Notes

(IFALLS) Sec Res REQUESTED SERVICE CALL TO MOODY MUSIC FOR FLAT TIRE on left front

Job Notes

09-15 - ALIGN STEERING

(IFALLS) EH performed alignment

66-17-015 - PERFORM TIRE ROTATION

(IFALLS) AG rotated tires

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(IFALLS) AG mounted and balanced left front tire

66-79-002 - PERFORM SERVICE CALL

(IFALLS) AG performed service call and installed spare tire

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG performed pm

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 37123

USING DEPT NO: 507143	OPENED DATE: 07/15/2020 13:41:03	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/15/2020 14:25:51	METER 1 - M: 6089 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/16/2020 12:51:40	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.33** **0.00** **0.00** **0.00** **0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/15/2020 14:25:23	07/15/2020 14:45:11	0.33	\$0.00
					LABOR	0.00

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37123

Work Order Notes

(LISAPATE) Perform safety check

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Safety check was completed. We did not drop oil at this time. We checked fluids, battery and tire pressures. Updated sticker
Coolant -34'
JW

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37133

USING DEPT NO:	507143	OPENED DATE:	07/17/2020 08:12:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/17/2020 10:07:21	METER 1 - M:	6108	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/17/2020 14:50:20	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.48	\$0.00	\$5.33	\$0.00	\$5.33

JOB COUNT: 1	WORK ORDER TOTAL:					0.48	0.00	5.33	0.00	5.33
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	07/17/2020 08:15:08	07/17/2020 08:43:38	0.48	\$0.00

LABOR 0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
66-17-030	PERFORM TIRE PATCH	23131	TPMS SNAP IN VALVE 21060	2.56	1	\$2.56
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.04	4	\$0.16
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	1	\$0.27

PARTS 5.33

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37133

Work Order Notes

(LISAPATE) Nail in RF tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Removed and patched RF tire from the inside. Rechecked ok

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37927

USING DEPT NO: 507143	OPENED DATE: 10/08/2020 10:26:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/08/2020 13:18:55	METER 1 - M: 8133 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/12/2020 12:24:34	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK0LU890671

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
31-17-033	ROTATE TIRE ROTATION AND BRAKE IN	DON	O	N	GARAGE	0.24	\$28.19	\$0.00	\$0.00	\$28.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.11	\$130.52	\$35.75	\$0.00	\$166.27

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.35** **158.71** **35.75** **0.00** **194.46**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/08/2020 10:35:50	10/08/2020 11:06:19	0.51	\$59.95
31-17-033	ROTATE TIRE ROTATION AND BRAKE INSPECTION	11074414	10/08/2020 11:06:40	10/08/2020 11:21:00	0.24	\$28.19
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/08/2020 10:35:44	10/08/2020 10:54:44	0.32	\$37.37
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/08/2020 10:34:56	10/08/2020 10:51:49	0.28	\$33.20
LABOR						158.71

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
PARTS						35.75

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37927

Work Order Notes

(LISAPATE) PM

Job Notes

31-17-033 - ROTATE TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH AMG/JW PERFORMED PM

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 37952

USING DEPT NO: 507143	OPENED DATE: 10/12/2020 07:10:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/13/2020 12:41:30	METER 1 - M: 8225 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/14/2020 08:33:11	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.09	\$10.36	\$0.00	\$0.00	\$10.36
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.47	\$55.00	\$0.00	\$0.00	\$55.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.33	\$156.97	\$647.58	\$0.00	\$804.55

JOB COUNT: 3	WORK ORDER TOTAL:	1.88	222.33	647.58	0.00	869.91
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	10/12/2020 08:10:14	10/12/2020 08:38:19	(0.47)	(\$55.23)
06-15	INSPECT STEERING	11074414	10/12/2020 15:18:27	10/12/2020 15:23:43	0.09	\$10.36
09-15	ALIGN STEERING	11213180	10/13/2020 07:31:47	10/13/2020 07:59:45	0.47	\$55.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/12/2020 13:58:23	10/12/2020 15:18:12	1.33	\$156.97
66-17-030	PERFORM TIRE PATCH	11074414	10/12/2020 08:10:14	10/12/2020 08:38:19	0.47	\$55.23
					LABOR	222.33

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	C111	RED BRAKE CLEANER	3.36	1	\$3.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11711	TIRE 215/55R17 MICH DEFEND T+H	156.57	4	\$626.28
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	4	\$13.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	(4)	(\$13.26)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.84	4	\$15.36
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	3	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.06	22	\$1.32
					PARTS	647.58

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 37952

Work Order Notes

(LISAPATE) Nail in LF tire-Added air
(IFALLS) Nail was to close to side wall to patch.

Job Notes

06-15 - INSPECT STEERING

(SHARBIN) SH Inspected front end found no issues.

09-15 - ALIGN STEERING

(MSIDES) Performed alignment. MS

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Tire can not be patched. The screw is to close to the sidewall of the tire. Tires were rotated at last PM due to shoulder wear on rear tires a full set of tires is recommended . SH

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 38773

USING DEPT NO:	507143	OPENED DATE:	01/13/2021 08:34:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/14/2021 13:42:41	METER 1 - M:	10030	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2021 15:25:18	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU890671	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.33	\$38.61	\$0.00	\$0.00	\$38.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.99	\$116.46	\$35.75	\$0.00	\$152.21
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.05	\$5.34	\$40.41	\$0.00	\$45.75

JOB COUNT: 3	WORK ORDER TOTAL:	1.36	160.41	76.16	0.00	236.57
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/14/2021 09:23:51	01/14/2021 09:23:51	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/14/2021 09:30:00	01/14/2021 09:59:40	0.49	\$58.34
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/14/2021 10:42:33	01/14/2021 10:47:32	0.08	\$9.80
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	01/14/2021 08:55:22	01/14/2021 09:15:00	0.33	\$38.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	01/14/2021 08:48:39	01/14/2021 08:51:22	0.05	\$5.34
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/14/2021 07:49:09	01/14/2021 08:13:43	0.41	\$48.31
					LABOR	160.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	1	\$5.85
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	5	\$32.48
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800208CTYC	CABIN AIR FILTER	40.41	1	\$40.41
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	(1)	(\$5.85)
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.85	5	\$29.25
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	(5)	(\$32.48)
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
					PARTS	76.16

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 38773

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) rotated tires and Checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 10030 Scott completed PM top and bottom side. SH Completed checklist, vacuumed and washed, no fuel needed. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) replaced cabin filter. SH

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 39776

USING DEPT NO: 507143	OPENED DATE: 04/22/2021 08:47:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/26/2021 15:09:05	METER 1 - M: 12197 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/27/2021 08:18:58	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.41	\$48.38	\$0.00	\$0.00	\$48.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$72.80	\$35.68	\$0.00	\$108.48

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.03** **121.18** **35.68** **0.00** **156.86**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/22/2021 11:00:56	04/22/2021 11:25:32	0.41	\$48.38
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/22/2021 10:33:09	04/22/2021 11:00:38	0.46	\$54.05
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/22/2021 10:44:48	04/22/2021 10:54:20	0.16	\$18.75
					LABOR	121.18

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 39776

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 12197. SH Performed PM.

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 40276

USING DEPT NO: 507143	OPENED DATE: 06/28/2021 15:23:18	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/30/2021 08:28:14	METER 1 - M: 13600 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2021 09:36:33	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.45	\$171.36	\$54.29	\$0.00	\$225.65

JOB COUNT: 1 **WORK ORDER TOTAL: 1.45 171.36 54.29 0.00 225.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/29/2021 13:00:00	06/29/2021 13:01:42	0.03	\$3.34
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/29/2021 12:59:49	06/29/2021 12:59:49	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/29/2021 10:30:13	06/29/2021 10:58:39	0.47	\$55.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/29/2021 09:49:36	06/29/2021 10:40:27	0.85	\$100.01
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/29/2021 10:04:21	06/29/2021 10:10:30	0.10	\$12.10
					LABOR	171.37

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.23	1	\$9.23
					PARTS	54.29

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 40276

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 13600 Completed PM topside, Scott was bottomside. Completed checklist. AMG/SH

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 40938

USING DEPT NO: 507143	OPENED DATE: 09/03/2021 13:13:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/08/2021 11:51:00	METER 1 - M: 15798 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/08/2021 15:32:52	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.47	\$17.90	\$0.00	\$27.37
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.24	\$27.93	\$0.00	\$0.00	\$27.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.79	\$50.36	\$0.00	\$96.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.01	\$0.72	\$18.71	\$0.00	\$19.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.71	83.91	86.97	2.00	172.88
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	09/03/2021 13:37:19	09/03/2021 13:51:31	0.24	\$27.93
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/03/2021 13:51:43	09/03/2021 14:15:00	0.39	\$45.79
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/03/2021 14:28:01	09/03/2021 14:28:01	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/03/2021 14:30:00	09/03/2021 14:34:49	0.08	\$9.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	09/03/2021 14:35:00	09/03/2021 14:35:22	0.01	\$0.72
LABOR					83.91	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.08	5	\$30.38
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	10.71	1	\$10.71
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.27	1	\$9.27
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	18.71	1	\$18.71
PARTS					86.97	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 40938

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 15798. SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 41767

USING DEPT NO: 507143	OPENED DATE: 12/02/2021 10:46:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/07/2021 11:23:56	METER 1 - M: 18651 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/07/2021 13:58:24	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.98	\$17.90	\$0.00	\$22.88
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.39	\$46.41	\$0.00	\$0.00	\$46.41
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.64	\$75.55	\$0.00	\$0.00	\$75.55
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.48	\$174.21	\$660.73	\$0.00	\$834.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.71	\$38.42	\$0.00	\$75.13
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 6	WORK ORDER TOTAL:	2.86	337.86	717.05	2.00	1,056.91
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/03/2021 09:30:00	12/03/2021 10:20:16	0.84	\$98.86
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/03/2021 08:36:41	12/03/2021 09:15:00	0.64	\$75.36
06-15	INSPECT STEERING	11074414	12/02/2021 14:37:06	12/02/2021 14:58:49	0.36	\$42.71
06-15	INSPECT STEERING	11074414	12/02/2021 14:10:54	12/02/2021 14:12:47	0.03	\$3.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/02/2021 13:43:00	12/02/2021 14:01:40	0.31	\$36.71
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/02/2021 14:01:55	12/02/2021 14:04:27	0.04	\$4.98
66-17-013	PERFORM ALIGNMENT	11310047	12/03/2021 14:34:25	12/03/2021 15:12:50	0.64	\$75.55
					LABOR	337.87

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	5.84	5	\$29.18
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.24	1	\$9.24

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1549788	TIRE GEN ALTIMAX 215/55R17	157.52	4	\$630.06
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21372	HAMATON VALVE STEM TOYOTA	6.35	4	\$25.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	24	\$3.96
66-17-028	PERFORM MOUNT AND BALANCE TIRES	COATED 15G	COATED 15G WHEEL WEIGHT	0.11	1	\$0.11
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	1	\$0.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58122	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	1	\$0.50
					PARTS	717.05

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 41767

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected brakes and steering found no issues. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed Alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(SHARBIN) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/AMG Performed PM.

(SHARBIN) Vehicle needs 4 tires tread depths are at 2/32. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 41825

USING DEPT NO: 507143	OPENED DATE: 12/08/2021 15:02:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/10/2021 13:33:29	METER 1 - M: 18729 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/13/2021 13:33:04	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.03	\$3.93	\$146.72	\$0.00	\$150.65
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.32	\$37.50	\$0.00	\$0.00	\$37.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.35	41.43	146.72	2.00	190.15
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	12/09/2021 13:52:03	12/09/2021 13:54:03	0.03	\$3.93
35-32	DIAGNOSE CRANKING SYSTEM	12052187	12/09/2021 13:32:47	12/09/2021 13:51:51	0.32	\$37.50
LABOR					41.43	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	146.72	1	\$146.72
PARTS					146.72	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 41825

Work Order Notes

(LISAPATE) Per driver unit is hesitating and slow to crank. Requested we check we check the battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced battery. Charging at 14.1 volts. JAW

35-32 - DIAGNOSE CRANKING SYSTEM

(JWRIGHT) Charged battery and tested low amps need replaced

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 42538

USING DEPT NO: 507143	OPENED DATE: 03/02/2022 14:02:41	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/03/2022 14:52:47	METER 1 - M: 20799 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/07/2022 07:50:23	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.29	\$17.90	\$0.00	\$26.19
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.33	\$38.78	\$0.00	\$0.00	\$38.78
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$37.14	\$39.78	\$0.00	\$76.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.71** **84.21** **57.68** **2.00** **143.89**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/03/2022 07:34:11	03/03/2022 07:53:04	0.31	\$37.14
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/03/2022 07:57:42	03/03/2022 08:01:55	0.07	\$8.29
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	03/03/2022 08:35:51	03/03/2022 08:55:34	0.33	\$38.78
					LABOR 84.21	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	6.72	5	\$33.60
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	(1)	(\$7.59)
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.18	1	\$6.18
					PARTS 57.68	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 42538

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Chad replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 20799 Completed PM topside, Chad assisted, Scott was bottomside. Completed checklist. AMG CW/SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 43486

USING DEPT NO: 507143	OPENED DATE: 06/02/2022 12:00:30	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/02/2022 15:15:18	METER 1 - M: 23604 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/03/2022 12:38:34	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.63	\$46.70	\$0.00	\$98.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.44** **51.63** **46.70** **2.00** **100.33**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/02/2022 13:21:01	06/02/2022 13:47:16	0.44	\$51.63
LABOR						51.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.47	5	\$37.35
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	9.35	1	\$9.35
PARTS						46.70

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 43486

Work Order Notes

(CWIGLEY) PM-Replace Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-23604

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 44037

USING DEPT NO: 507143	OPENED DATE: 07/21/2022 09:22:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/22/2022 15:07:17	METER 1 - M: 25076 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/27/2022 13:31:16	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.18	\$21.50	\$146.72	\$0.00	\$168.22
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.79	\$92.99	\$308.25	\$0.00	\$401.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **1.22** **143.99** **454.97** **2.00** **600.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	07/21/2022 12:46:18	07/21/2022 13:33:35	0.79	\$92.99
03-32-002	REPLACE NEW BATTERY	12052187	07/21/2022 10:44:50	07/21/2022 10:46:56	0.04	\$4.13
03-32-002	REPLACE NEW BATTERY	12052187	07/21/2022 09:30:07	07/21/2022 09:38:57	0.15	\$17.37
06-15	INSPECT STEERING	12052187	07/21/2022 13:33:44	07/21/2022 13:35:00	(0.02)	(\$2.49)
06-15	INSPECT STEERING	12052187	07/21/2022 13:33:44	07/21/2022 13:48:44	0.25	\$29.50
06-15	INSPECT STEERING	12052187	07/21/2022 13:33:44	07/21/2022 13:35:00	0.02	\$2.49
LABOR					143.99	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	47H5	BATTERY	146.72	1	\$146.72
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1549788	TIRE GEN ALTIMAX 215/55R17	150.33	2	\$300.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	10	\$1.65
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	1	\$0.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58121	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.61	2	\$5.22
PARTS					454.97	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44037

Work Order Notes

(LISAPATE) replace battery-needs 2 tires
(EKIMBREL) will come back for alignment, machine down.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Tested battery it has a bad cell. Replaced with new battery. Alternator is charging at 13.2 volts JAW

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(JWRIGHT) Steering good brakes are at 8mm

09-15 - ALIGN STEERING

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(JWRIGHT) Replaced front tires. Aired and balanced to spec. Torqued lug nuts to spec. JAW

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44086

USING DEPT NO:	507143	OPENED DATE:	07/27/2022 09:55:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/02/2022 11:21:29	METER 1 - M:	25284	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/02/2022 15:14:05	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.50	\$59.52	\$0.00	\$0.00	\$59.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL: 0.50 59.52 0.00 2.00 61.52**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	07/27/2022 14:50:02	07/27/2022 15:20:18	0.50	\$59.52
					LABOR	59.52

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44086

Work Order Notes

(LISAPATE) Alignment was not done after replacing tires last week due to machine was down,

Job Notes

09-15 - ALIGN STEERING

(EHOWELL) Adjusted rear toe. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44368

USING DEPT NO: 507143	OPENED DATE: 08/18/2022 07:40:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/19/2022 11:33:25	METER 1 - M: 25861 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/22/2022 08:55:32	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.70	\$82.34	\$17.20	\$0.00	\$99.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.70** **82.34** **17.20** **2.00** **101.54**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	08/18/2022 07:48:25	08/18/2022 08:30:17	0.70	\$82.34
LABOR					0.70	82.34

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	3	\$0.50
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.31	1	\$4.31
66-17-030	PERFORM TIRE PATCH	21372	HAMATON VALVE STEM TOYOTA	11.96	1	\$11.96
66-17-030	PERFORM TIRE PATCH	58121	.50 OZ WHEEL WEIGHT	0.43	1	\$0.43
PARTS					3	17.20

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44368

Work Order Notes

(CWIGLEY) Nail in left rear tire.

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) patched left rear tire. sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44438

USING DEPT NO: 507143	OPENED DATE: 08/24/2022 07:32:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/25/2022 14:25:56	METER 1 - M: 26046 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/26/2022 10:02:08	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.41	\$23.19	\$0.00	\$24.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.32	\$45.59	\$0.00	\$75.91
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$20.52	\$0.00	\$55.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** 0.57 67.13 89.30 5.00 161.43

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12296277	08/24/2022 08:58:30	08/24/2022 08:59:13	0.01	\$1.41
66-PM-PMA	PERFORM OIL CHANGE	12296277	08/24/2022 08:59:35	08/24/2022 09:15:00	0.26	\$30.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12296277	08/25/2022 07:00:00	08/25/2022 07:18:00	0.30	\$35.40
					LABOR	67.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.01	5	\$35.05
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	10.56	1	\$10.56
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	20.52	1	\$20.52
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
					PARTS	89.30

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 44438

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wiper blades jdm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) performed pm with andy

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) replaced cabin filter jdm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 45042

USING DEPT NO: 507143	OPENED DATE: 10/21/2022 07:48:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/24/2022 15:14:25	METER 1 - M: 27735 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/25/2022 07:47:14	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	P	N	GARAGE	0.53	\$62.51	\$156.44	\$0.00	\$218.95
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.75	\$88.99	\$2.73	\$0.00	\$91.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.28	151.50	159.17	5.00	315.67
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	10/21/2022 08:40:53	10/21/2022 08:59:10	0.30	\$35.96
66-17-030	PERFORM TIRE PATCH	11901357	10/21/2022 08:40:53	10/21/2022 08:59:10	(0.30)	(\$35.96)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	10/21/2022 09:07:20	10/21/2022 09:15:00	0.13	\$15.08
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	10/21/2022 09:30:00	10/21/2022 09:54:07	0.40	\$47.43
66-17-030	PERFORM TIRE PATCH	11901357	10/21/2022 12:20:04	10/21/2022 13:05:19	0.75	\$88.99
LABOR					151.50	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	1549788	TIRE GEN ALTIMAX 215/55R17	150.33	1	\$150.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	2.31	2	\$4.62
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	2	\$5.46
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58123	1.00 OZ WHEEL WEIGHT	0.50	2	\$0.99
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.17	3	\$0.50
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	(2)	(\$5.46)
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
PARTS					159.17	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 45042

Work Order Notes

(LISAPATE) Low tire pressure light on again, driver has had air added multiple times. Asked that we check LR tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Replaced and balanced R/R tire. AMG

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) miles: 27735 Repaired and rebalanced L/R tire. Rechecked for leak, all good. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 45138

USING DEPT NO: 507143	OPENED DATE: 11/01/2022 12:46:44	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/02/2022 15:28:06	METER 1 - M: 27987 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/07/2022 07:33:38	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.80	\$74.57	\$0.00	\$98.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.20** **23.80** **74.57** **5.00** **103.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/01/2022 13:18:42	11/01/2022 13:30:48	0.20	\$23.80
					LABOR	23.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	33.12	1	\$33.12
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.35	1	\$6.35
					PARTS	74.57

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 45138

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-27987

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 45663

USING DEPT NO: 507143	OPENED DATE: 01/04/2023 09:55:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/20/2023 14:03:43	METER 1 - M: 29123 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/20/2023 14:03:47	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-42-004	WARRANTY WATER PUMP	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.14	\$16.09	\$0.00	\$0.00	\$16.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.31	\$36.71	\$0.00	\$0.00	\$36.71

JOB COUNT: 5	WORK ORDER TOTAL:	0.95	111.80	0.00	5.00	116.80
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-42-004	WARRANTY WATER PUMP	11076422	6188973		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-42	TRANSPORT COOLING SYSTEM	11915538	01/20/2023 07:00:00	01/20/2023 07:30:00	0.50	\$59.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/09/2023 07:27:02	01/09/2023 07:45:42	0.31	\$36.71
35-42	DIAGNOSE COOLING SYSTEM	11310047	01/09/2023 07:18:51	01/09/2023 07:27:02	0.14	\$16.09
LABOR					111.80	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 45663

Work Order Notes

(EHANNAH) low on coolant

Job Notes

15-42-004 - WARRANTY WATER PUMP

(LISAPATE) Toyota found excessive clearance between water pump seal and shaft, parts were saturated with coolant. Installed new engine computer, engine wiring harness, water pump gasket and water pump. Rechecked all ok

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Taken to Toyota by RC/CW

35-42 - DIAGNOSE COOLING SYSTEM

(EHOWELL) Coolant was topped off. Pressurized the cooling system and inspected for leaks, but no leaks were found. EH/IF

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found the following DTCs: P26CA-31 Engine Coolant Pump-No Signal.

P2681-15 Engine Coolant Bypass Valve-Circuit Short To Battery or Open.

P26CA-14 Engine Coolant Pump-Circuit Short to Ground or Open.

The vehicle may need to have the electrically driven water pump replaced. The vehicle is going back to the dealership. EH

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 46011

USING DEPT NO: 507143	OPENED DATE: 02/01/2023 07:19:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/01/2023 15:05:59	METER 1 - M: 29649 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/03/2023 09:45:29	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.31	\$36.74	\$0.00	\$0.00	\$36.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.32	\$66.96	\$0.00	\$111.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.69	81.06	66.96	5.00	153.02
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	02/01/2023 08:04:08	02/01/2023 08:22:49	0.31	\$36.74
66-PM-PMA	PERFORM OIL CHANGE	12201267	02/01/2023 08:01:42	02/01/2023 08:24:14	0.38	\$44.32
LABOR					81.06	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	11.94	5	\$59.70
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.26	1	\$7.26
PARTS					66.96	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 46011

Work Order Notes

(EHANNAH) pm- replace wipers - preform safety inspection.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. Pads are 7mm. JAW

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- JW-GC, changed oil and oil filter, checked fluids, filters, tires and tire pressure
Miles- 29,649

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 46156

USING DEPT NO: 507143	OPENED DATE: 02/15/2023 07:39:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/21/2023 14:28:02	METER 1 - M: 29867 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/22/2023 09:55:32	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK0LU890671

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	2.75	\$324.80	\$0.00	\$0.00	\$324.80
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.36	\$42.02	\$0.00	\$0.00	\$42.02
CH-32-002	CHARGE BATTERY	DON	O	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** 4.11 484.82 0.00 5.00 489.82

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
CH-32-002	CHARGE BATTERY	11310047	02/21/2023 07:00:00	02/21/2023 08:00:00	1.00	\$118.00
66-79-002	PERFORM SERVICE CALL	11915538	02/21/2023 07:11:32	02/21/2023 07:32:54	0.36	\$42.02
35-32	DIAGNOSE CRANKING SYSTEM	11310047	02/17/2023 07:50:18	02/17/2023 10:35:27	2.75	\$324.80
					LABOR	484.82

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 46156

Work Order Notes

(IFALLS) Service call for dead battery please take a battery to the 600 bldg. back parking lot for pickup.
(EHOWELL)

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(EHOWELL) Performed a parasitic draw test on the vehicle's electrical system. Allowed the vehicle to sit for a while so that the modules could go to sleep. The average draw then became 31 milliamps. This is normal. Verified that the headlights and dome lamp was off. Removed inventory battery and reinstalled vehicle's battery after it finished charging. EH

66-79-002 - PERFORM SERVICE CALL

(IFALLS) performed service call put loaner battery in brought other battery back to charge\RC

CH-32-002 - CHARGE BATTERY

(LISAPATE) Removed inventory battery and reinstalled vehicle's battery after it finished charging. EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 46948

USING DEPT NO: 507143	OPENED DATE: 05/04/2023 08:19:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/08/2023 14:33:50	METER 1 - M: 31070 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/09/2023 07:54:11	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.56	\$23.96	\$0.00	\$28.52
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.37	\$43.56	\$0.00	\$0.00	\$43.56
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.97	\$114.43	\$16.85	\$0.00	\$131.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.67	\$41.36	\$0.00	\$53.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.73	203.72	82.17	5.00	290.89
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML
					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/04/2023 08:52:01	05/04/2023 08:54:20	0.04	\$4.56
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2023 08:54:32	05/04/2023 09:00:28	0.10	\$11.67
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/04/2023 13:34:56	05/04/2023 14:15:00	0.67	\$78.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/04/2023 14:30:00	05/04/2023 14:48:07	0.30	\$35.63
66-17-013	PERFORM ALIGNMENT	11310047	05/05/2023 08:14:49	05/05/2023 08:36:58	0.37	\$43.56
06-15	INSPECT STEERING	11310047	05/05/2023 10:59:54	05/05/2023 11:14:54	0.25	\$29.50
06-15	INSPECT STEERING	11310047	05/05/2023 10:59:54	05/05/2023 10:59:54	0.00	\$0.00
06-15	INSPECT STEERING	11310047	05/05/2023 10:59:54	05/05/2023 10:59:54	0.00	\$0.00
					LABOR	203.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.22	1	\$13.22
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.11	5	\$35.55
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.74	1	\$10.74

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	5.81	1	\$5.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	B110772A	215/55R17 MICH SURVEY TIRES	0.00	4	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.14	17	\$2.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	23131	TPMS SNAP IN VALVE 21060	3.50	4	\$13.98
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58120	.25 OZ WHEEL WEIGHT	0.29	2	\$0.57
					PARTS	82.17

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 46948

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers.

06-15 - INSPECT STEERING

(EHOWELL) Steering good. Brakes 11mm all around. JAW

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GRCOOK) Mounted and balanced all 4 survey tires on 2020 Toyota Camry-GC
LF-25, RF-26, RR-27, LR-28
Miles, 31,070

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-31070

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 47416

USING DEPT NO: 507143	OPENED DATE: 06/23/2023 08:44:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/06/2023 09:16:29	METER 1 - M: 31949 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2023 10:54:35	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK0LU890671

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-42-037	WARRANTY HEATER CONTROL VALVE	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-00	SCAN OUT COMPLETE VEHICLE	DON	O	N	GARAGE	0.61	\$72.34	\$0.00	\$0.00	\$72.34

JOB COUNT: 4	WORK ORDER TOTAL:	1.11	131.34	0.00	5.00	136.34
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-42-037	WARRANTY HEATER CONTROL VALVE	11076422	6211306		\$0.00
15-42-037	WARRANTY HEATER CONTROL VALVE	11076422	6209867		\$0.00
15-42-037	WARRANTY HEATER CONTROL VALVE	11076422	6210541		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-42	TRANSPORT COOLING SYSTEM	11399745	07/06/2023 07:00:00	07/06/2023 07:30:00	0.50	\$59.00
SO-00	SCAN OUT COMPLETE VEHICLE	11310047	06/26/2023 07:23:33	06/26/2023 08:00:20	0.61	\$72.34
LABOR					1.11	131.34

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 47416

Work Order Notes

(EHANNAH) Scan out- check engine light is on.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

15-42-037 - WARRANTY HEATER CONTROL VALVE

(LISAPATE) Tuscaloosa Toyota verified open circuit replaced coolant bypass valve rechecked ok

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) Taken to Toyota by CW

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

SO-00 - SCAN OUT COMPLETE VEHICLE

(LISAPATE) P268115-Engine coolant bypass valve circuit short to battery or open

P26AC15-Engine Coolant bypass valve "B" circuit short to battery or open

JW-Engine heater valve has 11.4 volts at harness. Heater valve tested at 4 ohms and is suppose to have 22-28 ohms. Valve is bad needs replaced. Send to dealer for warranty repair

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 47774

USING DEPT NO: 507143	OPENED DATE: 07/31/2023 07:41:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/01/2023 08:03:27	METER 1 - M: 32490 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/01/2023 11:30:37	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK0LU890671

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.37	\$13.11	\$0.00	\$34.48
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** 0.18 21.37 13.11 5.00 39.48

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/31/2023 07:57:52	07/31/2023 08:08:44	0.18	\$21.37
					LABOR	21.37

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
					PARTS	13.11

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 47774

Work Order Notes

(EHANNAH) pm- replace wipers
(EKIMBREL) just got wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Vehicle has been driven 1420 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 48366

USING DEPT NO:	507143	OPENED DATE:	10/02/2023 08:03:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/05/2023 15:47:12	METER 1 - M:	34311	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2023 07:08:49	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	20TOYOTACAMRY	2020 Toyota Camry		UNIT SERIAL NO:	4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.34	\$24.08	\$0.00	\$35.42
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.66	\$77.29	\$0.00	\$0.00	\$77.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.36	\$50.24	\$0.00	\$60.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
RS-02-061	RESEAL WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$546.25	\$546.25

JOB COUNT: 6	WORK ORDER TOTAL:	1.34	157.99	74.32	551.25	783.56
---------------------	--------------------------	-------------	---------------	--------------	---------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
06-02-061	INSPECT WINDSHIELD	11078716	2112877		\$546.25
RS-02-061	RESEAL WINDSHIELD	11078716	2112877		\$546.25
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
06-02-061	INSPECT WINDSHIELD	11078716	2112877		(\$546.25)
				COMML	551.25

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-02	TRANSPORT CAB & SHEET METAL	11399745	10/05/2023 07:00:00	10/05/2023 07:30:00	0.50	\$59.00
RS-02-061	RESEAL WINDSHIELD	11399745	10/05/2023 07:00:00	10/05/2023 07:30:00	(0.50)	(\$59.00)
RS-02-061	RESEAL WINDSHIELD	11399745	10/05/2023 07:00:00	10/05/2023 07:30:00	0.50	\$59.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	10/04/2023 14:56:47	10/04/2023 15:07:01	0.17	\$20.13
03-51-038	REPLACE NEW WIPER BLADES	12395904	10/04/2023 14:48:20	10/04/2023 14:54:06	0.10	\$11.34
66-PM-PMA	PERFORM OIL CHANGE	12395904	10/04/2023 14:42:36	10/04/2023 14:47:21	0.08	\$9.34
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/04/2023 13:59:40	10/04/2023 14:00:11	0.01	\$1.02
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	10/05/2023 07:00:37	10/05/2023 07:29:41	0.48	\$57.16
					LABOR	157.99

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
-----------------	------------------------	-----------------	--------------------	-------------------	-----------------	-------------------

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.82	5	\$44.10
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.14	1	\$6.14
					PARTS	74.32

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 48366

Work Order Notes

(EHANNAH) Pass side of windshield is leaking very bad
(EHANNAH) pm -wiper

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced new wipers fc

06-02-061 - INSPECT WINDSHIELD

(LRUSHING) Visit Reason Changed On 10/4/2023 3:50 PM By LRUSHING

06-51-002 - INSPECT HUBODOMETER

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass Dr by CW

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Rotate tires fc / sh

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed fluid check FC

CH-SP - CHARGE Shop Supplies

RS-02-061 - RESEAL WINDSHIELD

(LISAPATE) Glass Dr removed and resealed Windshield. PD for recalibration and reseal. Pd by CC

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49275

USING DEPT NO: 507143	OPENED DATE: 12/15/2023 13:06:43	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/18/2023 09:01:26	METER 1 - M: 36467 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/18/2023 11:52:46	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry		UNIT SERIAL NO: 4T1C11AK0LU890671

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.04	\$62.92	\$0.00	\$85.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.20** **23.04** **62.92** **5.00** **90.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/15/2023 14:30:00	12/15/2023 14:41:43	0.20	\$23.04
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/15/2023 14:20:50	12/15/2023 14:20:50	0.00	\$0.00
LABOR					23.04	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.48	5	\$42.38
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
PARTS					62.92	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49275

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 49291

USING DEPT NO: 507143	OPENED DATE: 12/18/2023 09:12:42	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2023 15:34:46	METER 1 - M: 36539 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/21/2023 07:44:20	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-32	INSPECT CRANKING SYSTEM	DON	N	N	GARAGE	0.09	\$10.39	\$0.00	\$0.00	\$10.39
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.08	\$9.05	\$0.00	\$0.00	\$9.05
CH-32-002	CHARGE BATTERY	DON	N	N	GARAGE	0.04	\$4.56	\$0.00	\$0.00	\$4.56
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL:** **0.20** **24.00** **0.00** **5.00** **29.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32	INSPECT CRANKING SYSTEM	11074414	12/18/2023 14:01:07	12/18/2023 14:06:24	0.09	\$10.39
CH-32-002	CHARGE BATTERY	11074414	12/18/2023 14:06:39	12/18/2023 14:08:58	0.04	\$4.56
15-32-002	WARRANTY BATTERY	11074414	12/18/2023 14:09:11	12/18/2023 14:13:47	0.08	\$9.05
					LABOR 24.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
15-32-002	WARRANTY BATTERY	47H5	BATTERY	0.00	1	\$0.00
					PARTS 0.00	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49291

Work Order Notes

(EHANNAH) inspect cranking system- driver reports trouble cranking it.

Job Notes

06-31 - INSPECT CHARGING SYSTEM

06-32 - INSPECT CRANKING SYSTEM

(SHARBIN) Battery tested bad but is 1 1/2 years old going to charge to be sure. SH

15-32-002 - WARRANTY BATTERY

(SHARBIN) Installed a new battery. ALT Charging at 14 volts. SH

(EKIMBREL) ADV AUTO WARRANTIED BATTERY

CH-32-002 - CHARGE BATTERY

(SHARBIN) Charged the battery retested bad. Will be a warranty battery. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 49500

USING DEPT NO: 507143	OPENED DATE: 01/19/2024 10:16:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/29/2024 07:59:56	METER 1 - M: 37252 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/29/2024 11:39:47	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-052	INSPECT WINDOW MOTOR	DON	O	N	GARAGE	1.14	\$134.65	\$0.00	\$0.00	\$134.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.14** **134.65** **0.00** **5.00** **139.65**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-052	INSPECT WINDOW MOTOR	11074414	01/26/2024 10:33:00	01/26/2024 10:39:31	0.11	\$12.82
06-02-052	INSPECT WINDOW MOTOR	11074414	01/19/2024 10:51:31	01/19/2024 11:53:28	1.03	\$121.84
LABOR					1.14	134.66

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49500

Work Order Notes

(EHANNAH) back pass. window is going down on it's on

Job Notes

06-02-052 - INSPECT WINDOW MOTOR

(GARAGE) Drove vehicle did not experience the window going down. Pulled the passenger door panel and inspected the window regulator wiring and the motor. Wiggled wires through the door and could not find a problem. Pulled the drivers window switch and inspected the switch and wiggled the wiring through the door and could not find a problem. LP Drove the vehicle to Ford and Browns could not duplicate the problem at this time. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 49663

USING DEPT NO: 507143	OPENED DATE: 02/01/2024 12:24:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/05/2024 15:42:14	METER 1 - M: 37637 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/06/2024 10:07:42	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-05-019	REPLACE NEW OXYGEN SENSOR	DON	N	N	GARAGE	1.14	\$134.39	\$275.61	\$0.00	\$410.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.34	\$40.12	\$0.00	\$0.00	\$40.12

JOB COUNT: 3	WORK ORDER TOTAL:	1.48	174.51	275.61	5.00	455.12
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-05-019	REPLACE NEW OXYGEN SENSOR	12052187	02/05/2024 07:12:28	02/05/2024 08:20:48	1.14	\$134.39
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/01/2024 13:05:46	02/01/2024 13:06:16	0.01	\$0.98
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	12052187	02/05/2024 08:21:00	02/05/2024 08:40:54	0.33	\$39.14
LABOR					174.51	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-05-019	REPLACE NEW OXYGEN SENSOR	8946733210	OXYGEN SENSOR	275.61	1	\$275.61
PARTS					275.61	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49663

Work Order Notes

(EHANNAH) check engine light is on

Job Notes

03-05-019 - REPLACE NEW OXYGEN SENSOR

(JWRIGHT) Replaced o2 sensor #2 and test drove. Let run for over an hour and found no other issues. JAW

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(JWRIGHT) scanned unit and pulled code p2271-18 o2 sensor bank 1 sensor 2

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 49914

USING DEPT NO: 507143	OPENED DATE: 02/23/2024 08:14:39	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/23/2024 10:11:55	METER 1 - M: 38259 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/26/2024 07:18:36	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.16	\$18.88	\$0.00	\$0.00	\$18.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.16** **18.88** **0.00** **5.00** **23.88**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-021	INSTALL GPS SYSTEM	11074414	02/23/2024 08:29:46	02/23/2024 08:39:22	0.16	\$18.88
LABOR					18.88	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49914

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GARAGE) Installed GPS# 87U030240200. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49942

USING DEPT NO: 507143	OPENED DATE: 02/26/2024 10:55:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/29/2024 15:17:08	METER 1 - M: 38269 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/04/2024 07:07:59	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-053	INSPECT WINDOW REGULATOR	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.81	\$55.64	\$0.00	\$74.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.16	18.81	55.64	5.00	79.45
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/27/2024 07:23:09	02/27/2024 07:32:43	0.16	\$18.81
LABOR					18.81	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.02	5	\$35.10
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
PARTS					55.64	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 49942

Work Order Notes

(EHANNAH) rear pass window is rolling down by itself- if you push another button, it goes too.
(EHANNAH) pm

Job Notes

06-02-053 - INSPECT WINDOW REGULATOR

(EKIMBREL) IF rebooted the power window switch
(IFALLS) performed a reset procedure on the power window switch

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243576 **2020 TOYOTA CAMRY** **WORK ORDER NO:** 50855

USING DEPT NO: 507143	OPENED DATE: 05/15/2024 10:33:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/18/2024 12:30:27	METER 1 - M: 40824 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/20/2024 07:21:53	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 20TOYOTACAMRY 2020 Toyota Camry	UNIT SERIAL NO: 4T1C11AK0LU890671	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.41	\$80.17	\$0.00	\$81.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.10	\$11.73	\$0.00	\$0.00	\$11.73

JOB COUNT: 3 **WORK ORDER TOTAL:** **0.11** **13.14** **80.17** **5.00** **98.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11915538	06/18/2024 09:18:02	06/18/2024 09:24:00	0.10	\$11.73
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/15/2024 13:01:11	05/15/2024 13:01:54	0.01	\$1.41
LABOR					13.14	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.38	5	\$36.90
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
PARTS					80.17	

Work Order Charge Detail

UNIT NO: 243576 2020 TOYOTA CAMRY

WORK ORDER NO: 50855

Work Order Notes

(EHANNAH) pm- prep for sale

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks anf tag and GPS\rc

removed light bar\ GC RC

(IFALLS) gps was removed 87u030240200

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Jul 12 2024 15:12:54 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243576') //Q=