

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 28505

USING DEPT NO:	507201	OPENED DATE:	01/04/2018 09:33:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/25/2018 20:00:00	METER 1 - M:	87	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2018 20:00:00	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	8.00	\$460.00	\$1,331.84	\$0.00	\$1,791.84
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$470.99	\$0.00	\$499.74
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	9.00	517.50	1,802.83	0.00	2,320.33
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	01/25/2018 07:00:00	01/25/2018 07:30:00	0.50	\$28.75
14-78-044	INSTALL TOOLBOX ASSY	11170580	01/25/2018 10:00:00	01/25/2018 10:30:00	0.50	\$28.75
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	01/25/2018 07:00:00	01/25/2018 15:00:00	8.00	\$460.00
					LABOR	517.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5141A	3/8 CONVOLUTED TUBING 50FT	0.38	50	\$18.75
14-78-044	INSTALL TOOLBOX ASSY	TBS63ALP	TOOLBOX	464.99	1	\$464.99
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609C	WHITE STROBE LIGHT KIT	121.50	2	\$243.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONC	ION WIDE ANGLE STROBE CLEAR	162.00	2	\$324.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	MMM06133	ELECTRICAL TAPE	6.71	1	\$6.71
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140PT	WIRE LOOM	4.65	1	\$4.65
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81161S	WIRE	23.10	1	\$23.10
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5141PT	CONVOLUTED TUBING	4.65	1	\$4.65
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	USASD8B100	ZIP TIES	6.29	1	\$6.29
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	12.79	1	\$12.79
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SWITCH	ACCELERATOR SWITCH	7.50	1	\$7.50
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	0.36	50	\$18.00
14-78-044	INSTALL TOOLBOX ASSY	SHIPPING	SHIPPING AND HANDLING	6.00	1	\$6.00

Work Order Charge Detail

PARTS	1802.83
-------	---------

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 28505

Work Order Notes

(LISAPATE) PDI-INSTALL STROBE LIGHTS-INSTALL A TOOLBOX

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) WIRED AND INSTALLED FRONT AND REAR STROBE LIGHTS ON THE INTERIOR AND EXTERIOR OF THE VEHICLE. OPERATION CHECKED OK

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) INSTALLED TOOLBOX

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 29774

USING DEPT NO:	507201	OPENED DATE:	05/11/2018 13:12:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/17/2018 13:20:47	METER 1 - M:	1429	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/17/2018 13:20:49	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.01	\$0.00	\$58.84

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	41.01	0.00	58.84
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/13/2018 07:00:00	07/13/2018 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	7	\$32.13
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	(7)	(\$32.13)
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	(1)	(\$6.45)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.76	6	\$34.56
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
					PARTS	41.01

Work Order Charge Detail

UNIT NO:	242576	2017 TOYOTA TACOMA	WORK ORDER NO:	29774
----------	--------	--------------------	----------------	-------

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 32385

USING DEPT NO:	507201	OPENED DATE:	03/18/2019 15:36:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/20/2019 08:30:10	METER 1 - M:	5398	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/20/2019 08:30:11	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$40.78	\$41.43	\$0.00	\$82.21
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.14	\$9.89	\$13.59	\$0.00	\$23.48

JOB COUNT: 2	WORK ORDER TOTAL:					0.70	50.67	55.02	0.00	105.69
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	03/19/2019 10:50:18	03/19/2019 10:58:29	0.14	\$9.89
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/19/2019 10:16:07	03/19/2019 10:49:52	0.56	\$40.78
					LABOR	50.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
					PARTS	55.02

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 32385

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 32890

USING DEPT NO:	507201	OPENED DATE:	05/13/2019 08:42:16	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2019 10:22:02	METER 1 - M:	5936	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2019 10:22:02	IN-SERVICE DATE:	12/15/2017						
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma			UNIT SERIAL NO:	5TFRX5GN3HX103420					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.89	\$136.74	\$0.00	\$0.00	\$136.74
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$1,622.75	\$1,622.75
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	2.50	\$181.29	\$6.81	\$0.00	\$188.10

JOB COUNT: 3	WORK ORDER TOTAL:	4.39	318.03	6.81	1,622.75	1,947.59
--------------	-------------------	------	--------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	168326	0048095	\$1,622.75
24-71	REPAIR BODY	11150605	168326	0048095	\$1,866.16
24-71	REPAIR BODY	11150605	168326	0048095	(\$1,866.16)
COMML					1622.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	05/17/2019 07:06:47	05/17/2019 09:36:49	2.50	\$181.29
16-71	TRANSPORT BODY	10208562	05/13/2019 09:45:19	05/13/2019 09:51:01	0.10	\$6.89
16-71	TRANSPORT BODY	11915538	05/13/2019 09:47:30	05/13/2019 11:34:58	1.79	\$129.86
LABOR						318.04

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.31	1	\$3.31
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	2	\$0.81
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.69	1	\$2.69
PARTS						6.81

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 32890

Work Order Notes

(LISAPATE) Take to Andrews to repair body damage to Right front door and fender per the estimate. Dept pay, not insurance

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by EK

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage per the estimate. Invoice and estimate attached. Pd by CC

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) SH removed and patched RF tire from the inside. Rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 33703

USING DEPT NO:	507201	OPENED DATE:	08/13/2019 07:33:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/14/2019 10:58:37	METER 1 - M:	7422	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/14/2019 10:58:38	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$38.63	\$41.51	\$0.00	\$80.14

JOB COUNT: 1	WORK ORDER TOTAL:	0.53	38.63	41.51	0.00	80.14
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/13/2019 08:36:14	08/13/2019 09:08:12	0.53	\$38.63
					LABOR	38.63

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
					PARTS	41.51

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 33703

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK/JW

Coolant -20'

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 34489

USING DEPT NO:	507201	OPENED DATE:	10/17/2019 13:56:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/30/2019 08:08:39	METER 1 - M:	8018	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/30/2019 08:08:41	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-40-433	DIAGNOSE OIL LEAK	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
35-40-433	DIAGNOSE OIL LEAK	BT223	OIL FILTER	6.20	(1)	(\$6.20)
35-40-433	DIAGNOSE OIL LEAK	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	(6)	(\$35.01)
35-40-433	DIAGNOSE OIL LEAK	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
35-40-433	DIAGNOSE OIL LEAK	BT223	OIL FILTER	6.20	1	\$6.20
PU-02-032	PURCHASED TRIM, MISCELLANEOUS	753110C030	GRILLE EMBLEM, TOYOTA	62.90	1	\$62.90
PU-02-032	PURCHASED TRIM, MISCELLANEOUS	753110C030	GRILLE EMBLEM, TOYOTA	62.90	(1)	(\$62.90)
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 34489

Work Order Notes

(RTUNAITI) Leaking oil bad

Job Notes

35-40-433 - DIAGNOSE OIL LEAK

(RTUNAITI) Found pinhole in filter. Replaced filter and topped off oil with approx. 1 quart of non-inv oil - JAW

Josh used an oil filter wrench to tighten up oil filter and damaged the oil filter case (puncturing it). - IF

PU-02-032 - PURCHASED TRIM, MISCELLANEOUS

(RTUNAITI) Purchased new grill Toyota logo emblem.
Customer installed.

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 34670

USING DEPT NO:	507201	OPENED DATE:	10/30/2019 08:09:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2019 14:42:11	METER 1 - M:	8317	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	11/01/2019 14:42:13	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-02-032	PURCHASED TRIM, MISCELLANEOUS	DON	O	N	GARAGE	0.00	\$0.00	\$62.90	\$0.00	\$62.90

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	62.90	0.00	62.90
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-02-032	PURCHASED TRIM, MISCELLANEOUS	753110C030	GRILLE EMBLEM, TOYOTA	62.90	1	\$62.90
					PARTS	62.90

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 34670

Work Order Notes

(RTUNAITI) Snap-in Toyota grill emblem is broken - order new emblem

Job Notes

PU-02-032 - PURCHASED TRIM, MISCELLANEOUS

(RTUNAITI) Purchased new grill emblem. Customer installed.

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 35711

USING DEPT NO:	507201	OPENED DATE:	02/20/2020 09:05:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2020 07:47:00	METER 1 - M:	9640	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2020 07:47:01	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.51	\$36.71	\$0.00	\$0.00	\$36.71
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.47	\$34.22	\$826.65	\$0.00	\$860.87
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$65.51	\$41.28	\$0.00	\$106.79

JOB COUNT: 4	WORK ORDER TOTAL:	2.38	172.69	867.93	0.00	1,040.62
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/24/2020 13:07:24	02/24/2020 13:18:26	0.18	\$13.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/24/2020 13:47:58	02/24/2020 13:49:17	0.02	\$1.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/24/2020 14:46:22	02/24/2020 15:02:20	0.27	\$19.29
09-15	ALIGN STEERING	11310047	02/24/2020 15:25:02	02/24/2020 15:55:25	0.51	\$36.71
06-15	INSPECT STEERING	11901357	02/25/2020 07:00:00	02/25/2020 07:30:00	0.50	\$36.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/20/2020 13:55:47	02/20/2020 14:50:00	0.90	\$65.51

LABOR 172.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.36	1	\$6.36
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	4	\$13.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	202.13	4	\$808.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	11	\$4.95

PARTS 867.93

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 35711

Work Order Notes

(EKIMBREL) PM

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) AG/JW Checked front end

09-15 - ALIGN STEERING

(LISAPATE) EH performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mount and balanced 4 new tires

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 36734

USING DEPT NO:	507201	OPENED DATE:	06/08/2020 10:56:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2020 14:38:30	METER 1 - M:	10400	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/08/2020 14:38:35	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$18.13	\$0.00	\$0.00	\$18.13

JOB COUNT: 1	WORK ORDER TOTAL:	0.25	18.13	0.00	0.00	18.13
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10208562	06/08/2020 13:28:24	06/08/2020 13:43:24	0.25	\$18.13
					LABOR	18.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	(1)	(\$6.48)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	(6)	(\$34.92)
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 36734

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) EK checked fluids and tire pressures also checked battery and updated sticker

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 38306

USING DEPT NO:	507201	OPENED DATE:	11/06/2020 10:17:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/09/2020 11:13:15	METER 1 - M:	12752	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/10/2020 07:03:03	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.10	\$11.57	\$114.48	\$0.00	\$126.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.41	\$166.87	\$43.11	\$0.00	\$209.98
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	O	N	GARAGE	0.09	\$10.19	\$15.74	\$0.00	\$25.93

JOB COUNT: 3	WORK ORDER TOTAL:	1.60	188.63	173.33	0.00	361.96
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2020 09:15:11	11/09/2020 10:13:49	0.98	\$115.31
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2020 10:20:13	11/09/2020 10:25:32	0.09	\$10.46
03-32-002	REPLACE NEW BATTERY	11901357	11/09/2020 10:14:05	11/09/2020 10:19:58	0.10	\$11.57
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	11/09/2020 09:09:41	11/09/2020 09:14:52	0.09	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/09/2020 08:48:26	11/09/2020 09:09:20	0.35	\$41.10
					LABOR	188.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.11	6	\$36.63
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	0.93	1	\$0.93
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	15.74	1	\$15.74
					PARTS	173.33

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 38306

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(AGUERRA) Replaced battery and checked charging system all good at 13.8 volts. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 12752 Completed PM top and bottom side. Completed checklist. Washed, vacuumed and fueled vehicle up. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 39726

USING DEPT NO:	507201	OPENED DATE:	04/19/2021 09:20:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/20/2021 14:46:28	METER 1 - M:	14713	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2021 08:15:37	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94

JOB COUNT: 2	WORK ORDER TOTAL:					0.53	62.54	0.00	0.00	62.54
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	04/19/2021 12:51:45	04/19/2021 12:51:45	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	04/19/2021 12:51:45	04/19/2021 12:51:45	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	04/19/2021 12:51:45	04/19/2021 13:03:45	0.20	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/19/2021 12:15:29	04/19/2021 12:35:17	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/19/2021 12:15:29	04/19/2021 12:15:29	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/19/2021 12:15:29	04/19/2021 12:15:29	0.00	\$0.00
					LABOR	62.54

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 39726

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(JWRIGHT) Rotate tires

(JWRIGHT) Rotated tires. Torqued all lug nuts to 83ft lbs. Front pads are 9mm. Rear shoes are 10mm. JAW,AMG

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 313 miles since last service. Updated pm sticker. Checked all fluids and tires. Tires need to be rotated. Coolant -34°. JAW
MILEAGE-14713

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 41429

USING DEPT NO:	507201	OPENED DATE:	10/27/2021 07:12:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/01/2021 07:49:48	METER 1 - M:	17036	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/01/2021 07:49:52	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$15.18	\$0.00	\$38.78
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.90	\$106.07	\$9.23	\$0.00	\$115.30
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.45	\$53.62	\$51.51	\$0.00	\$105.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.20	\$23.60	\$10.10	\$0.00	\$33.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.75	206.89	86.02	2.00	294.91
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/27/2021 09:22:00	10/27/2021 09:34:00	0.20	\$23.60
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/27/2021 09:04:09	10/27/2021 09:22:24	0.30	\$35.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/27/2021 09:22:00	10/27/2021 09:22:00	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/27/2021 09:22:00	10/27/2021 09:22:00	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/27/2021 09:43:48	10/27/2021 09:52:49	0.15	\$17.73
66-17-030	PERFORM TIRE PATCH	11901357	10/27/2021 12:10:04	10/27/2021 13:04:00	0.90	\$106.07
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/01/2021 07:00:00	11/01/2021 07:12:00	0.20	\$23.60
				LABOR		206.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	18.15	1	\$18.15
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	10.10	1	\$10.10
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.31	1	\$4.31
66-17-030	PERFORM TIRE PATCH	58100	.25 OZ WHEEL WEIGHT	0.18	1	\$0.18
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-030	PERFORM TIRE PATCH	58104	1.25 OZ WHEEL WEIGHT	0.47	1	\$0.47
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.86	1	\$3.86
					PARTS	86.02

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 41429

Work Order Notes

(LISAPATE) PM-replace wipers

(LISAPATE) Bolt in RF tire

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-030 - PERFORM TIRE PATCH

(AGUERRA) Repaired and balanced right front tire, rechecked for leak, all good. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 17248 Completed PM topside, Scott assisted, Josh was bottomsides. Completed checklist. AMG SH/JW

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 42970

USING DEPT NO:	507201	OPENED DATE:	04/20/2022 07:05:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2022 13:14:50	METER 1 - M:	19156	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2022 13:36:27	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.83	\$15.18	\$0.00	\$27.01
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.27	\$31.93	\$0.00	\$0.00	\$31.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.70	\$0.00	\$0.00	\$27.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.61	71.46	15.18	2.00	88.64
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	04/20/2022 10:03:46	04/20/2022 10:20:00	0.27	\$31.93
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/20/2022 09:57:31	04/20/2022 10:03:32	0.10	\$11.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2022 09:43:11	04/20/2022 09:57:16	0.23	\$27.70
					LABOR	71.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
					PARTS	15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 42970

Work Order Notes

(CWIGLEY) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Swapped left rear and right front positions due to right front shoulder wear and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 1908 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 44591

USING DEPT NO:	507201	OPENED DATE:	09/07/2022 08:35:55	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/13/2022 11:44:45	METER 1 - M:	20831	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/14/2022 08:20:05	IN-SERVICE DATE:	12/15/2017				
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma							
			UNIT SERIAL NO:	5TFRX5GN3HX103420					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-13-106	ADJUST REAR BRAKE SHOES	DON	O	N	GARAGE	1.20	\$141.31	\$0.00	\$0.00	\$141.31
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	1.00	\$118.00	\$61.34	\$0.00	\$179.34
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.98	\$15.64	\$0.00	\$16.62
66-13-130	PERFORM Burnish Brakes	DON	O	N	GARAGE	0.41	\$48.09	\$0.00	\$0.00	\$48.09
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.92	\$108.53	\$23.52	\$0.00	\$132.05
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.47	\$55.92	\$1,062.97	\$0.00	\$1,118.89
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.49	\$176.31	\$0.00	\$0.00	\$176.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.60	\$71.06	\$40.34	\$0.00	\$111.40
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.03	\$3.74	\$23.76	\$0.00	\$27.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CU-13-001	CUT FRONT BRAKES & ROTORS	DON	O	N	GARAGE	1.51	\$178.31	\$5.93	\$0.00	\$184.24

JOB COUNT: 11	WORK ORDER TOTAL:	7.65	902.25	1,233.50	5.00	2,140.75
---------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-13-106	ADJUST REAR BRAKE SHOES	11310047	09/09/2022 10:19:33	09/09/2022 10:47:53	0.47	\$55.72
01-13-106	ADJUST REAR BRAKE SHOES	11310047	09/12/2022 07:29:20	09/12/2022 08:12:51	0.73	\$85.58
66-13-130	PERFORM Burnish Brakes	11310047	09/12/2022 09:08:02	09/12/2022 09:32:29	0.41	\$48.09
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	09/08/2022 13:53:01	09/08/2022 14:15:00	0.37	\$43.23
CU-13-001	CUT FRONT BRAKES & ROTORS	11310047	09/08/2022 14:30:00	09/08/2022 15:38:41	1.14	\$135.08
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11310047	09/13/2022 07:00:00	09/13/2022 08:00:00	1.00	\$118.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	09/07/2022 10:51:51	09/07/2022 10:53:45	0.03	\$3.74

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12296277	09/07/2022 11:08:42	09/07/2022 11:09:12	0.01	\$0.98
66-79-003	PERFORM SAFETY INSPECTION	11310047	09/07/2022 14:30:00	09/07/2022 14:39:38	0.16	\$18.95
66-79-003	PERFORM SAFETY INSPECTION	11310047	09/07/2022 13:44:16	09/07/2022 14:15:00	0.51	\$60.44
66-PM-PMA	PERFORM OIL CHANGE	11310047	09/07/2022 13:08:08	09/07/2022 13:44:16	0.60	\$71.06
66-79-003	PERFORM SAFETY INSPECTION	12296277	09/07/2022 11:09:22	09/07/2022 11:58:39	0.82	\$96.92
66-17-013	PERFORM ALIGNMENT	11310047	09/12/2022 08:12:51	09/12/2022 09:08:02	0.92	\$108.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	09/12/2022 07:00:54	09/12/2022 07:29:20	0.47	\$55.92
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	09/09/2022 11:14:58	09/09/2022 11:14:58	0.00	\$0.00
					LABOR	902.24

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.69	1	\$5.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	12.30	1	\$12.30
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	12.30	(1)	(\$12.30)
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	23.76	1	\$23.76
CU-13-001	CUT FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	2	\$11.85
CU-13-001	CUT FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	(2)	(\$11.85)
CU-13-001	CUT FRONT BRAKES & ROTORS	C111	RED BRAKE CLEANER	5.93	1	\$5.93
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	RABEH7976H	FRONT BRAKE PADS	61.34	1	\$61.34
66-17-013	PERFORM ALIGNMENT	21030	TPMS SERVICE KIT 6-116	5.88	4	\$23.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	4	\$1.02
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.59	3	\$1.76
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	4	\$2.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	2	\$1.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	05485	TIRE LT245/75R16 BFG COMM T/A	263.60	4	\$1,054.38
					PARTS	1233.50

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 44591

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

01-13-106 - ADJUST REAR BRAKE SHOES

(EHOWELL) Cleaned rear brakes, applied grease to backing plate, and adjusted shoes. EH

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(EKIMBREL) EH REPLACED FRONT BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

(EHOWELL) New wipers were installed.

66-13-130 - PERFORM Burnish Brakes

(EHOWELL) Made hard stops after brake job was performed. EH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Checked alignment. Vehicle was within spec. Reset steering angle sensor using code link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced 4 new tires. Relearned tire positions. EH

66-79-003 - PERFORM SAFETY INSPECTION

(EHOWELL) Inspected vehicle. EH

66-PM-PMA - PERFORM OIL CHANGE

(EHOWELL) Mileage-20831

EH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

CU-13-001 - CUT FRONT BRAKES & ROTORS

(EHOWELL) Cut front rotors using the on-car brake lathe. Installed new pads. EH

(IFALLS) cleaned caliper and pistons

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 46063

USING DEPT NO:	507201	OPENED DATE:	02/06/2023 07:19:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2023 09:42:03	METER 1 - M:	22403	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2023 12:58:45	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.32	\$0.00	\$0.00	\$24.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.21	24.32	0.00	5.00	29.32
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2023 07:46:57	02/06/2023 07:59:19	0.21	\$24.32
					LABOR	24.32

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 46063

Work Order Notes

(EHANNAH) pm-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Vehicle has been driven 1572 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47410

USING DEPT NO:	507201	OPENED DATE:	06/22/2023 12:45:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2023 14:34:48	METER 1 - M:	23698	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 07:51:41	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-040	REPLACE NEW THROTTLE BODY ASSY	DON	O	N	GARAGE	1.96	\$231.12	\$421.31	\$0.00	\$652.43
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.23	\$27.30	\$0.00	\$0.00	\$27.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
CL-44-040	CLEANED THROTTLE BODY ASSY	DON	O	N	GARAGE	1.73	\$204.60	\$0.00	\$0.00	\$204.60
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.11	\$131.50	\$0.00	\$0.00	\$131.50

JOB COUNT: 5	WORK ORDER TOTAL:	5.04	594.52	421.31	5.00	1,020.83
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-32-002	INSPECT BATTERY	11310047	06/23/2023 07:01:46	06/23/2023 07:15:39	0.23	\$27.30
03-44-040	REPLACE NEW THROTTLE BODY ASSY	11310047	06/26/2023 13:38:37	06/26/2023 14:15:00	0.61	\$71.55
03-44-040	REPLACE NEW THROTTLE BODY ASSY	11310047	06/26/2023 14:30:00	06/26/2023 15:51:08	1.35	\$159.56
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	06/27/2023 13:08:08	06/27/2023 14:15:00	1.11	\$131.50
CL-44-040	CLEANED THROTTLE BODY ASSY	11310047	06/23/2023 07:15:39	06/23/2023 08:59:41	1.73	\$204.60
				LABOR		594.51

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-040	REPLACE NEW THROTTLE BODY ASSY	STIS20407	THROTTLE BODY	421.31	1	\$421.31
					PARTS	421.31

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47410

Work Order Notes

(EHANNAH) battery- she said it died on her twice on the way here.

Job Notes

03-44-040 - REPLACE NEW THROTTLE BODY ASSY

(EHOWELL) Replaced throttle body and throttle body gasket. Performed road test after repair and the vehicle did not stall out or go dead. EH

06-32-002 - INSPECT BATTERY

(EHOWELL) Battery tested good. EH

CH-SP - CHARGE Shop Supplies

CL-44-040 - CLEANED THROTTLE BODY ASSY

(EHOWELL) The throttle plate would not open fully while trying to clean it. EH

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(EHOWELL) Found DTC: P1603 Engine Stall and P1604 Startability Fault. Examined data using scan tool while pressing the accelerator pedal and the Throttle Sensor Position readings did not appear to respond properly. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47514

USING DEPT NO:	507201	OPENED DATE:	07/03/2023 10:23:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/05/2023 09:42:13	METER 1 - M:	23765	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/05/2023 10:26:17	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.95	\$21.67	\$0.00	\$28.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$16.36	\$43.82	\$0.00	\$60.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.44	\$51.46	\$0.00	\$0.00	\$51.46

JOB COUNT: 4	WORK ORDER TOTAL:	0.63	74.77	65.49	5.00	145.26
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/03/2023 14:11:28	07/03/2023 14:15:00	0.06	\$6.95
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/03/2023 14:02:55	07/03/2023 14:11:14	0.14	\$16.36
WA-00	WASH COMPLETE VEHICLE	11074414	07/03/2023 14:28:23	07/03/2023 14:28:23	0.00	\$0.00
WA-00	WASH COMPLETE VEHICLE	11074414	07/03/2023 14:30:00	07/03/2023 14:56:10	0.44	\$51.46
				LABOR		74.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.82	1	\$10.82
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
				PARTS		65.49

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47514

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 23,765

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47532

USING DEPT NO:	507201	OPENED DATE:	07/06/2023 08:03:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/06/2023 13:14:20	METER 1 - M:	23765	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2023 14:37:35	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.16	\$18.81	\$115.05	\$0.00	\$133.86
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.62	\$72.77	\$0.00	\$0.00	\$72.77
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.78	91.58	115.05	5.00	211.63
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	12052187	07/06/2023 08:08:52	07/06/2023 08:45:52	0.62	\$72.77
03-32-002	REPLACE NEW BATTERY	12201267	07/06/2023 08:38:06	07/06/2023 08:47:40	0.16	\$18.81
					LABOR	91.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.05	1	\$115.05
					PARTS	115.05

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 47532

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) installed new battery-7-6-23-GC

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped unit off and brought back to shop. JAW,GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 48452

USING DEPT NO:	507201	OPENED DATE:	10/09/2023 10:32:32	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2023 10:18:46	METER 1 - M:	24786	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2023 11:16:55	IN-SERVICE DATE:	12/15/2017						
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma									
				UNIT SERIAL NO:	5TFRX5GN3HX103420						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,677.64	\$1,677.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.50	59.00	0.00	1,682.64	1,741.64
--------------	-------------------	--	--	--	--	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-71	REPAIR BODY	11150605	1697741		\$1,677.64
COMML					1682.64

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	10/18/2023 07:00:00	10/18/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 48452

Work Order Notes

(EHANNAH) repair body- transport body

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Transported by RC/CW

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired body damage to rear bumper area per the estimate. Dept pay. Pd by PO

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 49024

USING DEPT NO:	507201	OPENED DATE:	11/20/2023 13:58:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2023 10:56:48	METER 1 - M:	25336	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2023 13:15:38	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.29	\$33.93	\$0.00	\$0.00	\$33.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.03	\$0.00	\$0.00	\$22.03
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.32	\$37.37	\$0.00	\$0.00	\$37.37

JOB COUNT: 4	WORK ORDER TOTAL:	0.79	93.33	0.00	5.00	98.33
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	11/21/2023 09:36:43	11/21/2023 09:55:43	0.32	\$37.37
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	11/21/2023 09:30:00	11/21/2023 09:36:15	0.10	\$12.29
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	11/21/2023 09:04:00	11/21/2023 09:15:00	0.18	\$21.63
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/21/2023 08:52:11	11/21/2023 09:03:23	0.19	\$22.03
					LABOR	93.32

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 49024

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) DID NOT NEED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Perform tires rotate and check brake F 10 m R 5 m FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Was Fc

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 51659

USING DEPT NO:	507201	OPENED DATE:	07/31/2024 09:26:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/14/2024 07:57:37	METER 1 - M:	27778	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/14/2024 11:22:30	IN-SERVICE DATE:	12/15/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN3HX103420	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.34	\$1.34
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.01	\$1.34	\$0.00	\$0.00	\$1.34

JOB COUNT: 2	WORK ORDER TOTAL:					0.01	1.34	0.00	1.34	2.68
--------------	-------------------	--	--	--	--	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$1.34
COMML					1.34

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/08/2024 15:01:42	08/08/2024 15:02:23	0.01	\$1.34
LABOR						1.34

Work Order Charge Detail

The University of Alabama

Report Printed: 08/15/2024 14:41:24 By User: GLOBETTI

UNIT NO: 242576 2017 TOYOTA TACOMA

WORK ORDER NO: 51659

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks and tag. CW

(GARAGE) Removed gps and strobe lights. JAW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Aug 15 2024 14:41:24 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '5TFRX5GN3HX103420') //Q=