

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 26394

USING DEPT NO: 504302	OPENED DATE: 05/23/2017 07:23:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/24/2017 15:44:48	METER 1 - M: 124 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/24/2017 15:44:49	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:					0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	10208562	05/23/2017 07:23:57	05/23/2017 07:53:57	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 26394

Work Order Notes

(LISAPATE) NEW UNIT INSPECTION

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 26823

USING DEPT NO: 504302	OPENED DATE: 07/12/2017 14:54:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/19/2017 07:16:36	METER 1 - M: 431 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/19/2017 07:16:38	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-024	INSTALL BACK UP CAMERA	DON	O	N	GARAGE	9.00	\$517.50	\$1,274.01	\$0.00	\$1,791.51
14-54-002	INSTALL ALARM - BACK-UP	DON	O	N	GARAGE	1.00	\$57.50	\$39.36	\$0.00	\$96.86

JOB COUNT: 2 **WORK ORDER TOTAL:** **10.00** **575.00** **1,313.37** **0.00** **1,888.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-54-002	INSTALL ALARM - BACK-UP	11213180	07/12/2017 14:56:02	07/12/2017 15:56:02	1.00	\$57.50
14-52-024	INSTALL BACK UP CAMERA	11213180	07/12/2017 14:55:56	07/12/2017 23:55:56	9.00	\$517.50
					LABOR	575.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-52-024	INSTALL BACK UP CAMERA	SHIPPING	SHIPPING AND HANDLING	31.55	1	\$31.55
14-52-024	INSTALL BACK UP CAMERA	PADLOCK	PADLOCK	34.47	1	\$34.47
14-52-024	INSTALL BACK UP CAMERA	PIC1806KT	CONNECTORS	3.49	1	\$3.49
14-52-024	INSTALL BACK UP CAMERA	IATV905A	VLI NIGHT VISION CAMERA 9"MON	720.00	1	\$720.00
14-52-024	INSTALL BACK UP CAMERA	IAPC1107	VLS CAMERA KIT	223.50	2	\$447.00
14-52-024	INSTALL BACK UP CAMERA	IAPX1002	10M AV CABLE	37.50	1	\$37.50
14-54-002	INSTALL ALARM - BACK-UP	ECC520	BACK UP ALARM	39.36	1	\$39.36
					PARTS	1313.37

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 26823

Work Order Notes

(LISAPATE) INSTALL BACK UP ALARM AND BACK UP CAMERA
(RWINTERS) add locks to spare tire carrier.

Job Notes

14-52-024 - INSTALL BACK UP CAMERA

(LISAPATE) INSTALLED 3 CAMERA SYSTEM

14-54-002 - INSTALL ALARM - BACK-UP

(LISAPATE) INSTALLED BACK UP ALARM

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 27374

USING DEPT NO:	504302	OPENED DATE:	09/07/2017 14:18:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2017 09:01:14	METER 1 - M:	803	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/08/2017 09:01:16	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 2 **WORK ORDER TOTAL: 2.50 143.75 0.00 0.00 143.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	09/07/2017 14:21:26	09/07/2017 15:51:26	1.50	\$86.25
66-79-002	PERFORM SERVICE CALL	11213180	09/07/2017 14:18:45	09/07/2017 15:18:45	1.00	\$57.50
					LABOR	143.75

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 27374

Work Order Notes

(LISAPATE) SUPE STORE REQUESTED A SERVICE CALL. TRUCK DIED IN THE MIDDLE OF THE ROAD SPINS OVER WONT START

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) SCAN OUT P0624 FUEL PUMP CIRCUIT OPEN. HIT FUEL TANK AND IT CRANKED UP. FOUND FUEL PUMP CONNECTOR LOOSE. PUT DIEELECTRIC GREASE ON THE CONNECTOR. RECHECKED OK

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 27750

USING DEPT NO:	504302	OPENED DATE:	10/10/2017 10:36:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2017 06:35:43	METER 1 - M:	885	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2017 06:35:45	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.13	\$0.00	\$43.96

JOB COUNT: 1 **WORK ORDER TOTAL: 0.31 17.83 26.13 0.00 43.96**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/10/2017 11:48:01	10/10/2017 12:06:37	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W-20P	PROTECK OIL FULL SYNTHETIC	0.09	224	\$20.16
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
					PARTS	26.13

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 27750

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/CS

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 28187

USING DEPT NO:	504302	OPENED DATE:	11/17/2017 10:42:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/20/2017 07:10:15	METER 1 - M:	978	METER 2 - H: 2
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/20/2017 07:10:17	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	P	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1 WORK ORDER TOTAL: 1.00 57.50 0.00 0.00 57.50

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11213180	11/17/2017 10:43:07	11/17/2017 11:43:07	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 28187

Work Order Notes

(IFALLS) SUPPLY STORE REQUESTED SERVICE CALL ON QUAD FOR LIFT GATE INOP

Job Notes

66-79-002 - PERFORM SERVICE CALL

(IFALLS) MS PERFORMED SERVICE CALL AND FOUND NO ISSUES WITH LIFT GATE

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 29190

USING DEPT NO:	504302	OPENED DATE:	03/26/2018 11:39:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2018 11:14:22	METER 1 - M:	1191	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2018 11:14:28	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$26.97	\$0.00	\$44.80

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	26.97	0.00	44.80
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	03/26/2018 14:24:12	03/26/2018 14:42:48	0.31	\$17.83

					LABOR	17.83
--	--	--	--	--	--------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	1	\$3.00
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	(1)	(\$3.00)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	3.00	7	\$21.00

					PARTS	26.97
--	--	--	--	--	--------------	--------------

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 29190

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS
COOLANT -40'

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 31082

USING DEPT NO: 504302	OPENED DATE: 10/05/2018 10:57:06	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/23/2018 09:35:09	METER 1 - M: 1752 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/23/2018 09:35:11	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-55-027	INSPECT CIRCUIT BREAKER	DON	O	N	GARAGE	2.00	\$145.00	\$0.00	\$0.00	\$145.00
15-55-027	WARRANTY CIRCUIT BREAKER	DON	W	J	GARAGE	0.00	\$0.00	\$31.37	\$0.00	\$31.37
24-35-008	REPAIR TOGGLE SWITCH	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.74	\$126.03	\$41.25	\$0.00	\$167.28

JOB COUNT: 4	WORK ORDER TOTAL:	4.74	343.53	72.62	0.00	416.15
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
15-55-027	WARRANTY CIRCUIT BREAKER	6339191	WS1478908	0045554	\$0.00	
					COMML	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-35-008	REPAIR TOGGLE SWITCH	11758845	10/19/2018 09:00:00	10/19/2018 10:00:00	1.00	\$72.50
06-55-027	INSPECT CIRCUIT BREAKER	11758845	10/19/2018 07:00:00	10/19/2018 09:00:00	(2.00)	(\$145.00)
06-55-027	INSPECT CIRCUIT BREAKER	11758845	10/19/2018 07:00:00	10/19/2018 09:00:00	2.00	\$145.00
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/08/2018 09:20:41	10/08/2018 09:20:41	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/08/2018 09:30:00	10/08/2018 11:14:18	1.74	\$126.03
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/08/2018 09:20:41	10/08/2018 09:20:41	0.00	\$0.00
06-55-027	INSPECT CIRCUIT BREAKER	11268671	10/19/2018 07:00:00	10/19/2018 09:00:00	2.00	\$145.00
					LABOR	343.53

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.04	7	\$35.28
15-55-027	WARRANTY CIRCUIT BREAKER	PIC5547PT	SWITCH TOGGLE 25A ON-OFF	6.36	1	\$6.36
15-55-027	WARRANTY CIRCUIT BREAKER	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	1	\$25.01
24-35-008	REPAIR TOGGLE SWITCH	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	1	\$25.01
24-35-008	REPAIR TOGGLE SWITCH	PIC5574PT	HD BATTERY DISCONNECT SWITCH	6.36	1	\$6.36

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-35-008	REPAIR TOGGLE SWITCH	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	(1)	(\$25.01)
24-35-008	REPAIR TOGGLE SWITCH	PIC5574PT	HD BATTERY DISCONNECT SWITCH	6.36	(1)	(\$6.36)
03-55-027	REPLACE NEW CIRCUIT BREAKER	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	(1)	(\$25.01)
03-55-027	REPLACE NEW CIRCUIT BREAKER	PIC5547PT	SWITCH TOGGLE 25A ON-OFF	6.36	(1)	(\$6.36)
03-55-027	REPLACE NEW CIRCUIT BREAKER	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	1	\$25.01
03-55-027	REPLACE NEW CIRCUIT BREAKER	PIC5547PT	SWITCH TOGGLE 25A ON-OFF	6.36	1	\$6.36
					PARTS	72.62

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 31082

Work Order Notes

(LISAPATE) PM-Liftgate switch inop at times

Job Notes

03-55-027 - REPLACE NEW CIRCUIT BREAKER

06-55-027 - INSPECT CIRCUIT BREAKER

(LISAPATE) Found a faulty toggle switch at the dash and also had a bad connection on signal wire coming from it at the motor

15-55-027 - WARRANTY CIRCUIT BREAKER

(IFALLS) Installed new circuit breaker provided by Lynncoach at no charge

24-35-008 - REPAIR TOGGLE SWITCH

(IFALLS) Repaired wire at motor and replaced toggle switch at the dash. rechecked ok

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by CS,AG,EK/CS

Coolant -47'

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 32237

USING DEPT NO:	504302	OPENED DATE:	02/21/2019 08:58:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2019 18:00:00	METER 1 - M:	2146	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2019 18:00:00	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-046	REPLACE NEW ENGINE WIRING HARNI	DON	A	N	GARAGE	3.27	\$236.87	\$0.00	\$0.00	\$236.87
03-10-001	REPLACE NEW CHASSIS WIRING HARNI	DON	A	N	GARAGE	10.53	\$763.51	\$0.00	\$0.00	\$763.51
03-13-127	REPLACE NEW ABS WIRING HARNESS	DON	A	N	GARAGE	1.12	\$81.28	\$0.00	\$0.00	\$81.28
03-30-007	REPLACE NEW AUX WIRING HARNESS	DON	A	N	GARAGE	5.81	\$421.45	\$0.00	\$0.00	\$421.45
03-30-008	REPLACE NEW BJB WIRING HARNESS	DON	A	N	GARAGE	7.04	\$510.36	\$0.00	\$0.00	\$510.36
25-01-001	REMOVE AIR CONDITIONING ASSEMBL	DON	A	N	GARAGE	17.86	\$1,294.71	\$0.00	\$0.00	\$1,294.71
25-44-001	REMOVE TANK - FUEL, LIQUID	DON	A	N	GARAGE	1.37	\$99.65	\$0.00	\$0.00	\$99.65
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
RF-42-011	REFILLED COOLANT	DON	O	N	GARAGE	0.36	\$25.92	\$0.00	\$0.00	\$25.92
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.55	\$39.55	\$0.00	\$0.00	\$39.55
TD-00	TEST DRIVE COMPLETE VEHICLE	DON	A	N	GARAGE	1.12	\$81.16	\$0.00	\$0.00	\$81.16

JOB COUNT: 11 WORK ORDER TOTAL: 50.03 3,626.96 0.00 0.00 3,626.96

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/21/2019 09:30:23	02/21/2019 09:58:30	(0.47)	(\$33.97)
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/21/2019 09:30:23	02/21/2019 09:58:30	0.47	\$33.97
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2019 09:29:43	02/21/2019 10:52:14	(1.38)	(\$99.71)
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2019 09:29:43	02/21/2019 10:52:14	1.38	\$99.71
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	11170580	03/06/2019 07:57:14	03/06/2019 09:56:34	1.99	\$144.19
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	11170580	03/06/2019 10:16:44	03/06/2019 11:33:26	1.28	\$92.68
03-30-007	REPLACE NEW AUX WIRING HARNESS	11170580	03/06/2019 11:34:15	03/06/2019 11:55:22	0.35	\$25.52
03-30-007	REPLACE NEW AUX WIRING HARNESS	11170580	03/06/2019 13:04:10	03/06/2019 14:03:48	0.99	\$72.06
03-13-127	REPLACE NEW ABS WIRING HARNESS	11170580	03/06/2019 14:04:36	03/06/2019 15:11:45	1.12	\$81.14
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/06/2019 15:12:26	03/06/2019 15:47:36	0.59	\$42.49

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/07/2019 07:13:58	03/07/2019 09:15:15	2.02	\$146.55
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/07/2019 09:16:04	03/07/2019 12:59:46	3.73	\$270.30
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/07/2019 14:44:21	03/07/2019 15:51:12	1.11	\$80.78
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/08/2019 08:57:44	03/08/2019 11:55:49	2.97	\$215.18
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/08/2019 13:29:18	03/08/2019 13:57:13	0.47	\$33.73
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/08/2019 13:57:33	03/08/2019 14:12:20	0.25	\$17.86
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/08/2019 14:12:40	03/08/2019 14:55:35	0.72	\$51.86
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/08/2019 14:56:05	03/08/2019 15:46:32	0.84	\$60.96
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/18/2019 07:15:30	03/18/2019 07:39:37	0.40	\$29.14
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/18/2019 10:53:41	03/18/2019 13:03:40	2.17	\$157.06
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/18/2019 14:00:24	03/18/2019 15:53:01	1.88	\$136.08
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/19/2019 07:01:01	03/19/2019 11:26:15	4.42	\$320.49
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/19/2019 11:26:42	03/19/2019 11:52:46	0.43	\$31.50
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/19/2019 12:59:48	03/19/2019 15:08:57	2.15	\$156.06
03-30-007	REPLACE NEW AUX WIRING HARNESS	11170580	03/19/2019 15:09:25	03/19/2019 15:55:56	0.78	\$56.21
03-30-007	REPLACE NEW AUX WIRING HARNESS	11170580	03/20/2019 08:11:46	03/20/2019 11:53:12	3.69	\$267.57
RF-42-011	REFILLED COOLANT	11170580	03/22/2019 07:47:00	03/22/2019 08:08:27	0.36	\$25.92
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	03/22/2019 08:09:35	03/22/2019 08:42:19	0.55	\$39.55
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	11170580	03/21/2019 07:01:05	03/21/2019 11:55:14	4.90	\$355.43
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	11170580	03/20/2019 12:58:46	03/20/2019 15:54:59	2.94	\$212.93
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	11170580	03/21/2019 13:11:30	03/21/2019 15:52:52	2.69	\$194.98
03-30-007	REPLACE NEW AUX WIRING HARNESS	11170580	03/22/2019 11:29:42	03/22/2019 11:29:47	0.00	\$0.10
25-44-001	REMOVE TANK - FUEL, LIQUID	11170580	03/22/2019 08:45:07	03/22/2019 10:07:35	1.37	\$99.65
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	11170580	03/22/2019 11:30:47	03/22/2019 11:30:51	0.00	\$0.08
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/22/2019 07:00:34	03/22/2019 07:45:58	0.76	\$54.86
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	11170580	03/22/2019 11:30:10	03/22/2019 11:30:14	0.00	\$0.08
TD-00	TEST DRIVE COMPLETE VEHICLE	11170580	03/22/2019 10:21:24	03/22/2019 11:28:34	1.12	\$81.16
03-13-127	REPLACE NEW ABS WIRING HARNESS	11170580	03/22/2019 11:29:01	03/22/2019 11:29:08	0.00	\$0.14
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	11170580	03/22/2019 11:29:23	03/22/2019 11:29:31	0.00	\$0.16
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	03/22/2019 11:31:32	03/25/2019 09:15:00	69.72	\$5,055.02

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	03/25/2019 09:30:00	03/25/2019 10:30:00	1.00	\$72.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	03/25/2019 09:30:00	03/25/2019 11:25:01	1.92	\$138.98
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	03/25/2019 09:30:00	03/25/2019 11:25:01	(1.92)	(\$138.98)
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	03/22/2019 11:31:32	03/25/2019 09:15:00	(69.72)	(\$5,055.02)
					LABOR	3626.95

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	5.97	1	\$5.97
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	5.97	(1)	(\$5.97)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.50	7	\$31.50
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	7651824	DIELECTRIC GREASE	7.37	1	\$7.37
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIGMAT	OIL ABSORBENT MAT	1.02	6	\$6.12
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	VC3B	FORD ORANGE ANTIFREEZE	28.73	5	\$143.63
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	VC3B	FORD ORANGE ANTIFREEZE	28.73	(5)	(\$143.63)
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.73	5	\$143.63
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	USASD11B100	11" ZIP TIE 100 PCS	10.79	1	\$10.79
03-13-127	REPLACE NEW ABS WIRING HARNESS	FWS38073	SOLDER, ROSIN CORE 1/16 IN	17.57	1	\$17.57
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC8231A	1/4 WTPF SHRINK TUBE 4FT	14.03	1	\$14.03
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	11.27	1	\$11.27
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.73	(5)	(\$143.63)
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.74	4	\$114.96
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.74	(4)	(\$114.96)
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.74	3	\$86.22
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	USASD11B100	11" ZIP TIE 100 PCS	10.79	(1)	(\$10.79)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	USASD11B100	11" ZIP TIE 100 PCS	10.79	2	\$21.57
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.50	(7)	(\$31.50)
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	(1)	(\$5.97)
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	7651824	DIELECTRIC GREASE	7.37	(1)	(\$7.37)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	HC3Z14A005P	WIRE ASSY CHASSIS / ABS	404.56	(1)	(\$404.56)
03-30-007	REPLACE NEW AUX WIRING HARNESS	HC3Z14A303G	WIRE ASSY / AUX STUB	19.62	(1)	(\$19.62)
03-13-127	REPLACE NEW ABS WIRING HARNESS	HC3Z14405RQ	WIRE ASSY ABS MAIN / MODULE	393.25	(1)	(\$393.25)
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	HU5Z12A581AC	WIRE ASSY / ENGINE MAIN	216.41	(1)	(\$216.41)
03-30-007	REPLACE NEW AUX WIRING HARNESS	KC3Z14A303BA	WIRE ASSY AUX UNDERHOOD	181.17	(1)	(\$181.17)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
RF-42-011	REFILLED COOLANT	VC3B	FORD ORANGE ANTIFREEZE	28.74	(3)	(\$86.22)
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	HC3Z12A581EJ	WIRE ASSY FUSEBOX/UNDERHOOD	996.53	(1)	(\$996.53)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8221A	SHRINK TUBE 1/4 X 4 FT	4.97	1	\$4.97
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8220A	SHRINK TUBE 3/16 X 4 FT	4.02	1	\$4.02
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC0003ST	WATERPROOF SHRINK TUBE KIT	35.99	1	\$35.99
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	USASD11B100	11" ZIP TIE 100 PCS	10.79	(2)	(\$21.57)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIGMAT	OIL ABSORMENT MAT	1.02	(6)	(\$6.12)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC0003ST	WATERPROOF SHRINK TUBE KIT	35.99	(1)	(\$35.99)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC0003ST	WATERPROOF SHRINK TUBE KIT	35.99	(1)	(\$35.99)
03-13-127	REPLACE NEW ABS WIRING HARNESS	FWS38071	SOLDER, ROSIN CORE 3/32IN	19.45	(1)	(\$19.45)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8220A	SHRINK TUBE 3/16 X 4 FT	4.02	(1)	(\$4.02)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8221A	SHRINK TUBE 1/4 X 4 FT	4.97	(1)	(\$4.97)
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC8231A	1/4 WTPF SHRINK TUBE 4FT	14.03	(1)	(\$14.03)
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	11.27	(1)	(\$11.27)
03-13-127	REPLACE NEW ABS WIRING HARNESS	FWS38071	SOLDER, ROSIN CORE 3/32IN	19.45	1	\$19.45
03-13-127	REPLACE NEW ABS WIRING HARNESS	FWS38073	SOLDER, ROSIN CORE 1/16 IN	17.57	(1)	(\$17.57)
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC0003ST	WATERPROOF SHRINK TUBE KIT	35.99	1	\$35.99
03-30-007	REPLACE NEW AUX WIRING HARNESS	KC3Z14A303BA	WIRE ASSY AUX UNDERHOOD	181.17	1	\$181.17
03-05-046	REPLACE NEW ENGINE WIRING HARNESS	HU5Z12A581AC	WIRE ASSY / ENGINE MAIN	216.41	1	\$216.41
03-13-127	REPLACE NEW ABS WIRING HARNESS	HC3Z14405RQ	WIRE ASSY ABS MAIN / MODULE	393.25	1	\$393.25
03-30-007	REPLACE NEW AUX WIRING HARNESS	HC3Z14A303G	WIRE ASSY / AUX STUB	19.62	1	\$19.62
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	HC3Z14A005P	WIRE ASSY CHASSIS / ABS	404.56	1	\$404.56
03-30-008	REPLACE NEW BJB WIRING HARNESS UNDERHOOD	HC3Z12A581EJ	WIRE ASSY FUSEBOX/UNDERHOOD	996.53	1	\$996.53
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	R134AOZ	R134A FREON-OUNCE	0.30	(5)	(\$1.50)
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	ESTER OIL	A/C ESTER OIL OUNCE	1.55	(1)	(\$1.55)
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	ESTER OIL	A/C ESTER OIL OUNCE	1.55	1	\$1.55
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	R134AOZ	R134A FREON-OUNCE	0.30	5	\$1.50
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC5141A	3/8 CONVOLUTED TUBING 50FT	16.45	1	\$16.45
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8219A	SHRINK TUBING 1/8 IN 4FT	3.23	1	\$3.23
03-10-001	REPLACE NEW CHASSIS WIRING HARNESS	PIC8219A	SHRINK TUBING 1/8 IN 4FT	3.23	(1)	(\$3.23)
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC5141A	3/8 CONVOLUTED TUBING 50FT	16.45	(1)	(\$16.45)
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	6	\$0.81
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	RECYCLED FREON LB	RECLAIMED FREON LB	2.25	1	\$2.25
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC5140A	1/4 CONVOLUTED TUBING 50FT	15.43	1	\$15.43

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	RECYCLED FREON LB	RECLAIMED FREON LB	2.25	(1)	(\$2.25)
25-01-001	REMOVE AIR CONDITIONING ASSEMBLY	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	(6)	(\$0.81)
03-13-127	REPLACE NEW ABS WIRING HARNESS	PIC5140A	1/4 CONVOLUTED TUBING 50FT	15.43	(1)	(\$15.43)
					PARTS	0.00

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 32237

Work Order Notes

(LISAPATE) PM due-Check engine light on-heating and cooling wont work not blowing at all

(IFALLS) found wiring harness chewed up by rodents under the hood, travelers has gotten involved on paying for repairs made by UA garage

(LISAPATE) Supplement was submitted to travelers for Pig Mats, antifreeze, heat shrink, zip ties and evac and recharge fluids. This check will be sent directly to Automotive Services.

(LISAPATE) Payment from Travelers was for \$4042.27 issued to Automotive Services

(LISAPATE) All invoices are attached for auditing purposes.

Job Notes

Work Order Charge Detail

03-05-046 - REPLACE NEW ENGINE WIRING HARNESS

(LISAPATE) Replaced engine harness

03-10-001 - REPLACE NEW CHASSIS WIRING HARNESS

(LISAPATE) Replaced chassis wiring harness

03-13-127 - REPLACE NEW ABS WIRING HARNESS

(LISAPATE) Replaced ABS wiring harness

03-30-007 - REPLACE NEW AUX WIRING HARNESS

(LISAPATE) Replaced auxiliary wiring harness

03-30-008 - REPLACE NEW BJB WIRING HARNESS UNDERHOOD

(LISAPATE) Removed washer fluid reservoir, both front fender liners, lower radiator hose, low side AC line to install BJB harness and aux relay harness. Had to remove all seats, carpet, A and B pillar trim, seat belt pre-tensioner, headliner, parking brake assy, dash and A/C box to install interior wire harness and part of BJB harness.

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

25-01-001 - REMOVE AIR CONDITIONING ASSEMBLY

(LISAPATE) Had to remove A/C to make repairs. Evac and recharged A/C. Rechecked ok

25-44-001 - REMOVE TANK - FUEL, LIQUID

(LISAPATE) Had to remove fuel tank to install chassis harness.

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) Found rodents chewed engine harness and chassis harness, Interior cab harness, auxiliary relay harness and BJB harness

66-PM-PMA - PERFORM OIL CHANGE

RF-42-011 - REFILLED COOLANT

(LISAPATE) Filled coolant up and burped system.

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) Scan out (FORD VCMII) P0036-H02S Heater control circuit B1S2.

P0137- 02 sensor circuit low voltage B1S2.

P0453- Evap system pressure sensor/switch A circuit high U codes presents

U0142:87-0A lost communication with Body Control Module B

U256:87-0A Lost communication with front controls interface Module A

U0557-Invalid data received from front controls Interface module A

TD-00 - TEST DRIVE COMPLETE VEHICLE

(LISAPATE) Test drove put through a drive cycle. Monitors clicked off. Permanent DTC's cleared out of modules. Rechecked ok

Work Order Charge Detail

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 32449

USING DEPT NO:	504302	OPENED DATE:	03/26/2019 13:41:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2019 11:57:29	METER 1 - M:	2160	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/01/2019 11:57:31	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$37.05	\$0.00	\$59.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	22.48	37.05	0.00	59.53
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/26/2019 13:42:02	03/26/2019 14:00:38	0.31	\$22.48
					LABOR	22.48

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
					PARTS	37.05

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 32449

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,EK/AG
Coolant -20'

Cancelled from Work Order# 32237. By User ID LISAPATE on 3/26/2019 9:05 AM.

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 34704

USING DEPT NO: 504302	OPENED DATE: 10/31/2019 11:48:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/05/2019 08:52:53	METER 1 - M: 2928 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/05/2019 08:52:55	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.03	\$2.46	\$25.59	\$0.00	\$28.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.45	\$105.17	\$46.71	\$0.00	\$151.88

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.48** **107.63** **72.30** **0.00** **179.93**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	10/31/2019 14:46:37	10/31/2019 14:48:39	0.03	\$2.46
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/31/2019 13:47:26	10/31/2019 14:46:37	0.99	\$71.51
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/31/2019 14:06:22	10/31/2019 14:34:13	0.46	\$33.65
					LABOR	107.62

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.82	7	\$40.74
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	12.80	2	\$25.59
					PARTS	72.30

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 34704

Work Order Notes

(EKIMBREL) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) Replaced wiper blades.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW,SH/JW. Coolant -34

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 35113

USING DEPT NO: 504302	OPENED DATE: 12/09/2019 15:46:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/19/2019 10:10:57	METER 1 - M: 2998 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/19/2019 10:10:58	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-44-026	REPLACE NEW FILLER PIPE HOSE(S)	DON	O	N	GARAGE	4.50	\$326.25	\$241.52	\$0.00	\$567.77
35-44	DIAGNOSE FUEL SYSTEM	DON	O	N	GARAGE	1.55	\$112.56	\$0.00	\$0.00	\$112.56

JOB COUNT: 2 **WORK ORDER TOTAL:** **6.05** **438.81** **241.52** **0.00** **680.33**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-44	DIAGNOSE FUEL SYSTEM	11213180	12/10/2019 06:45:21	12/10/2019 08:18:30	1.55	\$112.56
03-44-026	REPLACE NEW FILLER PIPE HOSE(S)	11170580	12/18/2019 07:00:00	12/18/2019 08:00:00	1.00	\$72.50
03-44-026	REPLACE NEW FILLER PIPE HOSE(S)	11213180	12/17/2019 07:00:00	12/17/2019 10:30:00	3.50	\$253.75
					LABOR	438.81

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-026	REPLACE NEW FILLER PIPE HOSE(S)	HC3Z9J280E	FUEL DELIVERY PIPE, PRESSURE	213.99	1	\$213.99
03-44-026	REPLACE NEW FILLER PIPE HOSE(S)	SHIPPING	SHIPPING AND HANDLING	27.53	1	\$27.53
					PARTS	241.52

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 35113

Work Order Notes

(LISAPATE) Per Wes truck is leaking fuel

Job Notes

03-44-026 - REPLACE NEW FILLER PIPE HOSE(S)

(EKIMBREL) Installed fuel line on fuel tank and reinstalled fuel tank. Rechecked ok.
(IFALLS) MS REMOVED HOSE AND AB INSTALLED AND RECHECKED

35-44 - DIAGNOSE FUEL SYSTEM

(EKIMBREL) Fuel leaking from plastic feed line where it connects to fuel pump.

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 35469

USING DEPT NO: 504302	OPENED DATE: 01/22/2020 10:13:36	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/02/2020 14:55:42	METER 1 - M: 3089 METER 2 - H: 2
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 03/02/2020 14:55:43	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-05-017	REPLACE NEW MASS AIR FLOW SENS	DON	O	N	GARAGE	0.39	\$28.46	\$158.15	\$0.00	\$186.61
03-41-008	REPLACE NEW INTAKE GASKET(S)	DON	O	N	GARAGE	3.74	\$270.89	\$155.29	\$0.00	\$426.18
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPE	DON	O	N	GARAGE	5.43	\$393.82	\$83.78	\$0.00	\$477.60
19-05-010	WIRE/REWIRE ENGINE KNOCK SENSO	DON	O	N	GARAGE	0.98	\$70.69	\$93.66	\$0.00	\$164.35
19-05-017	WIRE/REWIRE MASS AIR FLOW SENSC	DON	O	N	GARAGE	0.98	\$70.93	\$0.00	\$0.00	\$70.93
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$71.30	\$71.30
24-05-046	REPAIR ENGINE WIRING HARNESS	DON	O	N	GARAGE	0.60	\$43.64	\$0.00	\$0.00	\$43.64
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.38	\$100.21	\$0.00	\$0.00	\$100.21
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	2.69	\$195.29	\$0.00	\$0.00	\$195.29

JOB COUNT: 9 **WORK ORDER TOTAL: 16.19 1,173.93 490.88 71.30 1,736.11**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
20-00	TOWING COMPLETE VEHICLE	11076249	67559		\$71.30
				COMML	71.30

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-05-046	REPAIR ENGINE WIRING HARNESS	11170580	02/25/2020 10:20:47	02/25/2020 10:56:54	0.60	\$43.64
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	11170580	02/25/2020 08:43:32	02/25/2020 09:07:05	0.39	\$28.46
19-05-010	WIRE/REWIRE ENGINE KNOCK SENSOR	11170580	02/24/2020 14:54:07	02/24/2020 15:52:37	0.98	\$70.69
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	11170580	01/28/2020 09:44:18	01/28/2020 11:56:44	2.21	\$160.02
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11170580	01/23/2020 09:22:44	01/23/2020 12:04:21	2.69	\$195.29
66-79-002	PERFORM SERVICE CALL	10208562	01/22/2020 10:48:24	01/22/2020 11:35:00	0.78	\$56.31
66-79-002	PERFORM SERVICE CALL	11074414	01/22/2020 10:48:08	01/22/2020 11:24:28	0.61	\$43.90
03-41-008	REPLACE NEW INTAKE GASKET(S)	11170580	01/28/2020 13:11:32	01/28/2020 14:15:00	1.06	\$76.69
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	11170580	01/31/2020 08:28:37	01/31/2020 09:15:00	0.77	\$56.05

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	11170580	01/31/2020 09:30:00	01/31/2020 11:57:06	2.45	\$177.75
03-41-008	REPLACE NEW INTAKE GASKET(S)	11170580	01/31/2020 13:02:29	01/31/2020 14:15:00	1.21	\$87.62
03-41-008	REPLACE NEW INTAKE GASKET(S)	11170580	01/31/2020 14:30:00	01/31/2020 15:58:12	1.47	\$106.58
19-05-017	WIRE/REWIRE MASS AIR FLOW SENSOR	11170580	02/25/2020 09:07:05	02/25/2020 09:15:00	0.13	\$9.57
19-05-017	WIRE/REWIRE MASS AIR FLOW SENSOR	11170580	02/25/2020 09:30:00	02/25/2020 10:20:47	0.85	\$61.36
					LABOR	1173.93

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-41-008	REPLACE NEW INTAKE GASKET(S)	3L3Z8C387AC	GASKET, WATER CROSSOVER	11.81	1	\$11.81
03-41-008	REPLACE NEW INTAKE GASKET(S)	F1VY8255A	THERMOSTAT SEAL	7.85	1	\$7.85
03-41-008	REPLACE NEW INTAKE GASKET(S)	3L3Z8C388AC	GASKET, WATER CROSSOVER	12.51	1	\$12.51
03-41-008	REPLACE NEW INTAKE GASKET(S)	7R3Z9439AA	INTAKE MANIFOLD GASKET / ORING	5.48	10	\$54.75
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	3U2Z14S411BXAB	CHT WIRING REPAIR HARNESS	42.23	1	\$42.23
03-41-008	REPLACE NEW INTAKE GASKET(S)	3U2Z14S411FJAC	MAF WIRING REPAIR HARNESS	50.10	1	\$50.10
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	3U2Z14S411ARB	CHT REPAIR HARNESS	83.78	1	\$83.78
03-41-008	REPLACE NEW INTAKE GASKET(S)	7L1Z18801A	RF INTERFERENCE CAPACITOR	16.44	1	\$16.44
19-05-010	WIRE/REWIRE ENGINE KNOCK SENSOR	AU2Z14S411BJA	KNOCK SENSOR REPAIR HARNESS	46.83	2	\$93.66
03-41-008	REPLACE NEW INTAKE GASKET(S)	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.83	1	\$1.83
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	STIMAS0319	MASS AIR FLOW SENSOR	149.33	1	\$149.33
19-05-007	WIRE/REWIRE CYLINDER HEAD TEMPERATURE SEN	3U2Z14S411BXAB	CHT WIRING REPAIR HARNESS	42.23	(1)	(\$42.23)
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	STIMAS0319	MASS AIR FLOW SENSOR	149.33	(1)	(\$149.33)
03-05-017	REPLACE NEW MASS AIR FLOW SENSOR	8V2Z12B579A	MASS AIR FLOW SENSOR	158.15	1	\$158.15
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	146.72	(1)	(\$146.72)
66-79-002	PERFORM SERVICE CALL	652	BATTERY BCI 65 850 CCA	146.72	1	\$146.72
					PARTS	490.88

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 35469

Work Order Notes

(LISAPATE) Wes requested a service call to the Ferguson loading dock truck will turn over just spits and sputters wont crank. He said it has 3/4 tank full of gas

Job Notes

03-05-017 - REPLACE NEW MASS AIR FLOW SENSOR

(LISAPATE) Found MAF sensor was bad. Installed new MAF sensor test drove rechecked ok

03-41-008 - REPLACE NEW INTAKE GASKET(S)

(LISAPATE) Removed intake manifold to install new pigtails for CHT and knock sensors. Installed new manifold gaskets and coolant gaskets. Topped off coolant

19-05-007 - WIRE/REWIRE CYLINDER HEAD TEMPERATURE SENS

(LISAPATE) Installed new pigtail for cylinder head temp sensor

19-05-010 - WIRE/REWIRE ENGINE KNOCK SENSOR

(LISAPATE) Installed 2 pigtails for the knock sensors

19-05-017 - WIRE/REWIRE MASS AIR FLOW SENSOR

(LISAPATE) Installed a new pigtail in the MAF

20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Bambarger towed from the Ferguson Center to the shop.

24-05-046 - REPAIR ENGINE WIRING HARNESS

(GARAGE) Job 24-05-046 was added on-the-fly by 11170580 on 02/25/2020 10:21:46.

(LISAPATE) Repaired additional misc wiring on the engine harness

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed. Found wires under the hood chewed by a rodent. Called for a tow truck

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(GARAGE) Job SO-05 was added on-the-fly by 11170580 on 01/23/2020 09:24:10.

(LISAPATE) Scan out P0103 MAF circuit high-P011 IAT circuit high-P1289 CHT circuit high

Found MAF wires chewed, CHT sensor and knock sensors also chewd.

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 36500

USING DEPT NO:	504302	OPENED DATE:	05/19/2020 13:55:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2020 11:32:21	METER 1 - M:	3180	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2020 15:34:22	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.04	\$75.66	\$36.95	\$0.00	\$112.61

JOB COUNT: 1 **WORK ORDER TOTAL: 1.04 75.66 36.95 0.00 112.61**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2020 14:51:13	05/19/2020 15:53:50	1.04	\$75.66
					LABOR	75.66

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
					PARTS	36.95

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 36500

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW/JW performed PM. Coolant -34

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 37478

USING DEPT NO: 504302	OPENED DATE: 09/01/2020 09:53:05	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/02/2020 11:29:29	METER 1 - M: 3248 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/02/2020 13:41:15	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$9.83	\$0.00	\$0.00	\$9.83

JOB COUNT: 1	WORK ORDER TOTAL:	0.14	9.83	0.00	0.00	9.83
---------------------	--------------------------	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/01/2020 10:32:16	09/01/2020 10:40:24	0.14	\$9.83
					LABOR	9.83

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 37478

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 68 miles since last pm. Updated sticker, checked fluids and tires. Coolant -34 JAW,SH

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38115

USING DEPT NO:	504302	OPENED DATE:	10/22/2020 10:07:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/27/2020 10:26:49	METER 1 - M:	3282	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/27/2020 12:38:20	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	DON	O	N	GARAGE	0.34	\$40.09	\$0.00	\$0.00	\$40.09

JOB COUNT: 1 WORK ORDER TOTAL: 0.34 40.09 0.00 0.00 40.09

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
25-53-006	REMOVE WORDMARKS/IDENTIFIERS	11310047	10/22/2020 10:15:53	10/22/2020 10:36:16	0.34	\$40.09
					LABOR	40.09

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38115

Work Order Notes

(LISAPATE) Remove wordmarks

Job Notes

25-53-006 - REMOVE WORDMARKS/IDENTIFIERS

(EHOWELL) Removed word marks and Alabama sticker from the exterior of the vehicle. EH

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38424

USING DEPT NO: 504302	OPENED DATE: 11/18/2020 13:48:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/19/2020 12:05:38	METER 1 - M: 3283 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/20/2020 10:05:30	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.38	\$44.97	\$47.51	\$0.00	\$92.48

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.38** **44.97** **47.51** **0.00** **92.48**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/18/2020 14:30:00	11/18/2020 14:35:31	0.09	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/18/2020 13:57:39	11/18/2020 14:15:00	0.29	\$34.12
					LABOR	44.97

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	6.77	1	\$6.77
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.82	7	\$40.74
					PARTS	47.51

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38424

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC/JAW
MILEAGE- 3283

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38840

USING DEPT NO:	504302	OPENED DATE:	01/20/2021 09:06:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2021 14:23:58	METER 1 - M:	3616	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2021 15:53:54	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-52-024	ADJUST BACK UP CAMERA	DON	O	N	GARAGE	0.13	\$15.27	\$0.00	\$0.00	\$15.27
01-55-009	ADJUST LIFT ASSEMBLY - LIFT TRUCKS	DON	O	N	GARAGE	0.34	\$40.12	\$0.00	\$0.00	\$40.12
14-02-062	INSTALL STEP/RUNNING BOARDS	DON	O	N	GARAGE	0.76	\$89.98	\$296.74	\$0.00	\$386.72

JOB COUNT: 3	WORK ORDER TOTAL:	1.23	145.37	296.74	0.00	442.11
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-52-024	ADJUST BACK UP CAMERA	11901357	01/20/2021 13:05:28	01/20/2021 13:13:14	0.13	\$15.27
01-55-009	ADJUST LIFT ASSEMBLY - LIFT TRUCKS	11901357	01/20/2021 13:13:53	01/20/2021 13:34:17	0.34	\$40.12
14-02-062	INSTALL STEP/RUNNING BOARDS	11901357	01/20/2021 12:19:08	01/20/2021 13:04:53	0.76	\$89.98
					LABOR	145.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-02-062	INSTALL STEP/RUNNING BOARDS	DORBOLT	BOLT	13.80	1	\$13.80
14-02-062	INSTALL STEP/RUNNING BOARDS	SHIPPING	SHIPPING AND HANDLING	75.00	1	\$75.00
14-02-062	INSTALL STEP/RUNNING BOARDS	22796090	STIRRUP STEP KIT - WALTCO LIFT	218.30	1	\$218.30
14-02-062	INSTALL STEP/RUNNING BOARDS	SHIPPING	SHIPPING AND HANDLING	75.00	(1)	(\$75.00)
14-02-062	INSTALL STEP/RUNNING BOARDS	22796090	STIRRUP STEP KIT - WALTCO LIFT	218.30	1	\$218.30
14-02-062	INSTALL STEP/RUNNING BOARDS	22796090	STIRRUP STEP KIT - WALTCO LIFT	218.30	(1)	(\$218.30)
14-02-062	INSTALL STEP/RUNNING BOARDS	22796090	STIRRUP STEP KIT - WALTCO LIFT	218.30	(1)	(\$218.30)
14-02-062	INSTALL STEP/RUNNING BOARDS	22796090	STIRRUP STEP KIT - WALTCO LIFT	218.30	1	\$218.30
14-02-062	INSTALL STEP/RUNNING BOARDS	SHIPPING	SHIPPING AND HANDLING	64.64	1	\$64.64
					PARTS	296.74

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 38840

Work Order Notes

(LISAPATE) Add steps on both sides-truck is too low in the rear cant close lift gate on a level surface.-tilt the back up camera down to see the rear bumper.

Job Notes

01-52-024 - ADJUST BACK UP CAMERA

(AGUERRA) adjusted rear camera to see rear bumper. 15 min. AMG IF

01-55-009 - ADJUST LIFT ASSEMBLY - LIFT TRUCKS

(AGUERRA) Isaac checked lift gate for proper operation, unable to find any issues with lift. IF AMG

14-02-062 - INSTALL STEP/RUNNING BOARDS

(AGUERRA) Miles: 3616 Added rear step on both sides. 30 min. AMG

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 39534

USING DEPT NO:	504302	OPENED DATE:	03/31/2021 09:46:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/01/2021 11:19:05	METER 1 - M:	4321	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2021 07:39:11	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$73.23	\$5.84	\$0.00	\$79.07

JOB COUNT: 1 WORK ORDER TOTAL: 0.62 73.23 5.84 0.00 79.07

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/31/2021 14:35:41	03/31/2021 15:09:10	0.56	\$65.85
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/31/2021 14:03:19	03/31/2021 14:07:04	0.06	\$7.38
					LABOR	73.23

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	5.84	1	\$5.84
					PARTS	5.84

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 39534

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 4321 Vehicle has been 1038 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 40190

USING DEPT NO:	504302	OPENED DATE:	06/16/2021 11:13:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/18/2021 13:43:24	METER 1 - M:	5084	METER 2 - H: 2
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	06/18/2021 13:43:28	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	0.23	\$27.50	\$0.00	\$0.00	\$27.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$17.08	\$41.99	\$0.00	\$59.07

JOB COUNT: 2 **WORK ORDER TOTAL: 0.38 44.58 41.99 0.00 86.57**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/16/2021 14:31:45	06/16/2021 14:40:26	0.14	\$17.08
14-52-021	INSTALL GPS SYSTEM	12052187	06/16/2021 14:01:01	06/16/2021 14:15:00	0.23	\$27.50
					LABOR	44.58

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.43	7	\$30.98
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.50	1	\$4.50
					PARTS	41.99

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 40190

Work Order Notes

(CHANNELL) pm

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(JWRIGHT) installed GPS serial #5041372079. JAW

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 5135 Completed PM topside, Scott was bottomsides. Completed checklist and vacuumed out vehicle. AMG/SH

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 40670

USING DEPT NO: 504302	OPENED DATE: 08/09/2021 10:10:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2021 11:26:17	METER 1 - M: 5802 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/11/2021 09:33:21	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$113.55	\$0.00	\$125.35
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.57	\$67.39	\$0.00	\$0.00	\$67.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.67	79.19	113.55	2.00	194.74
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11074414	08/09/2021 10:51:59	08/09/2021 10:52:14	0.00	(\$0.49)
03-32-002	REPLACE NEW BATTERY	11074414	08/09/2021 10:51:59	08/09/2021 10:52:14	0.00	\$0.49
03-32-002	REPLACE NEW BATTERY	11074414	08/09/2021 10:51:59	08/09/2021 10:57:59	0.10	\$11.80
66-79-002	PERFORM SERVICE CALL	11074414	08/09/2021 10:17:25	08/09/2021 10:51:41	0.57	\$67.39
LABOR					79.19	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	113.55	1	\$113.55
PARTS					113.55	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 40670

Work Order Notes

(LISAPATE) Dept requested a service call for a dead battery to Gordon Palmer

Job Notes

03-32-002 - REPLACE NEW BATTERY

(SHARBIN) Replaced battery. SH

66-79-002 - PERFORM SERVICE CALL

(SHARBIN) Mileage 5802. Battery in the vehicle was 4 years old. Replaced the battery ALT is charging at 14.5 SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 41033

USING DEPT NO:	504302	OPENED DATE:	09/15/2021 14:33:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/16/2021 14:13:17	METER 1 - M:	6217	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2021 14:53:46	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,G	DON	O	N	GARAGE	0.29	\$34.06	\$8.88	\$0.00	\$42.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.29 34.06 8.88 0.00 42.94

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	11901357	09/15/2021 14:46:02	09/15/2021 15:03:21	0.29	\$34.06
LABOR						34.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-53-999	ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	2	\$8.88
PARTS						8.88

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 41033

Work Order Notes

(LISAPATE) Truck is low on oil. Will be back for service

Job Notes

AD-53-999 - ADDED VEHICLE FLUIDS,LUBRCNTS,GASES&

(AGUERRA) miles: 6217 Topped off engine oil, used 1.5 quarts 5W20.AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 41826

USING DEPT NO:	504302	OPENED DATE:	12/08/2021 15:04:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2021 13:40:02	METER 1 - M:	6860	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/13/2021 13:27:47	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-13	ADJUST BRAKES	DON	P	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.93	\$15.18	\$0.00	\$21.11
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	0.06	\$7.34	\$0.00	\$0.00	\$7.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.25	\$35.81	\$0.00	\$98.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.14	134.52	50.99	2.00	187.51
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
01-13	ADJUST BRAKES	11213180	12/10/2021 07:00:00	12/10/2021 07:30:00	0.50	\$59.00
35-32	DIAGNOSE CRANKING SYSTEM	12052187	12/09/2021 14:44:25	12/09/2021 14:48:09	0.06	\$7.34
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/09/2021 14:12:36	12/09/2021 14:44:15	0.53	\$62.25
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/09/2021 14:40:55	12/09/2021 14:43:56	0.05	\$5.93
					LABOR	134.52

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	4.44	7	\$31.08
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	4.73	1	\$4.73
					PARTS	50.99

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 41826

Work Order Notes

(LISAPATE) PM-Adjust brakes-replace wipers-Per driver check battery keeps resetting the clock and seems sluggish when using the lift

Job Notes

01-13 - ADJUST BRAKES

(LISAPATE) Adjusted brakes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

35-32 - DIAGNOSE CRANKING SYSTEM

(JWRIGHT) Tested battery, charging and cranking system and found no issues. Battery is rated at 650cca and tested at 702cca. Alternator is charging at 14.1 unloaded and 14.6 loaded. Took 2.3 seconds to start during cranking test. No issues found and all wires are tight

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/JAW

MILEAGE-6860

Greased lift and operated with no issues

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 42477

USING DEPT NO:	504302	OPENED DATE:	02/25/2022 08:26:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2022 15:08:05	METER 1 - M:	7584	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/01/2022 07:21:45	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.18	\$0.00	\$32.88
06-55-039	INSPECT LIFTGATE ASSY	DON	O	N	GARAGE	0.03	\$3.44	\$0.00	\$0.00	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.21	\$24.85	\$41.16	\$0.00	\$66.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.39	45.99	56.34	2.00	104.33
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/28/2022 07:00:00	02/28/2022 07:09:00	0.15	\$17.70
06-55-039	INSPECT LIFTGATE ASSY	12052187	02/25/2022 15:10:59	02/25/2022 15:12:44	0.03	\$3.44
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2022 14:33:22	02/25/2022 14:46:00	0.21	\$24.85
					LABOR	45.99

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	36.02	1	\$36.02
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	36.02	(1)	(\$36.02)
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	36.02	1	\$36.02
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	2	\$15.18
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	36.02	(1)	(\$36.02)
66-PM-PMA	PERFORM OIL CHANGE	PA10068	AIR FILTER	41.16	1	\$41.16
					PARTS	56.34

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 42477

Work Order Notes

(LISAPATE) PM-replace wipers-liftgate inop, will work if you hit on the switch

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

06-55-039 - INSPECT LIFTGATE ASSY

(JWRIGHT) Inspected lift gate. Removed switches and checked all wiring and connections. Found no issues and lift gate operated with no problems. Driver needed it back and will let us know if it has any other issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 724 miles since last pm. Updated sticker. Checked fluids and tires. Coolant -34°. JAW
MILEAGE-7584

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 43562

USING DEPT NO:	504302	OPENED DATE:	06/08/2022 08:33:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/10/2022 14:22:19	METER 1 - M:	8770	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2022 09:02:50	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.56	\$15.57	\$0.00	\$20.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$44.12	\$48.74	\$0.00	\$92.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.41	48.68	64.31	2.00	114.99
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/09/2022 08:09:30	06/09/2022 08:11:49	0.04	\$4.56
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/09/2022 07:46:33	06/09/2022 08:08:59	0.37	\$44.12
LABOR					48.68	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	9.36	1	\$9.36
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.79	2	\$15.57
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.63	7	\$39.38
PARTS					64.31	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 43562

Work Order Notes

(LISAPATE) PM-replace wipers-adjust brakes

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM and greased the lift gate.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 44691

USING DEPT NO:	504302	OPENED DATE:	09/14/2022 11:05:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/15/2022 14:19:43	METER 1 - M:	9878	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/16/2022 07:39:40	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.25	\$29.50	\$15.60	\$0.00	\$45.10
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.19	\$22.35	\$0.00	\$0.00	\$22.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.59	\$6.09	\$0.00	\$24.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.60	70.44	21.69	5.00	97.13
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	09/15/2022 07:00:00	09/15/2022 07:15:00	0.25	\$29.50
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	09/14/2022 15:28:37	09/14/2022 15:39:59	0.19	\$22.35
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2022 15:18:55	09/14/2022 15:28:22	0.16	\$18.59
					LABOR	70.44

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.09	1	\$6.09
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.80	2	\$15.60
					PARTS	21.69

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 44691

Work Order Notes

(CHANNELL) pm\replace wipers
left side control screw srripped.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) replaced wipers. SH

07-55-039 - LUBRICATE LIFTGATE ASSY

(SHARBIN) Greased the lift gate. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 108 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. Installed a bigger screw in the left side lift gate control. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 45676

USING DEPT NO: 504302	OPENED DATE: 01/04/2023 15:36:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/09/2023 15:04:26	METER 1 - M: 11093 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/10/2023 08:02:28	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.06	\$15.63	\$0.00	\$21.69
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	O	N	GARAGE	0.23	\$27.34	\$0.00	\$0.00	\$27.34
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$66.57	\$49.53	\$0.00	\$116.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.85	99.97	65.16	5.00	170.13
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11901357	01/09/2023 07:38:51	01/09/2023 07:52:45	0.23	\$27.34
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/05/2023 13:56:07	01/05/2023 13:59:12	0.05	\$6.06
66-PM-PMA	PERFORM OIL CHANGE	11901357	01/05/2023 13:21:53	01/05/2023 13:55:44	0.56	\$66.57
					LABOR	99.97

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	7	\$43.68
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.85	1	\$5.85
					PARTS	65.16

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 45676

Work Order Notes

(EHANNAH) pm- replace wipers, check all the tires for nails and tread

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(AGUERRA) Inspected both front tires, unable to find any nails or leaks. Vehicle sat inside the shop for 3 days and did not lose any air pressure in the front tires. AMG

66-17-030 - PERFORM TIRE PATCH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 11093 Completed PM topside, Ethan was bottomsides. AMG/EH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 46626

USING DEPT NO: 504302	OPENED DATE: 04/05/2023 12:32:01	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/07/2023 07:52:34	METER 1 - M: 12992 METER 2 - H: 2
WO VISIT REASON: UNSCHEDULED	CLOSED DATE: 04/07/2023 14:35:49	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **5.00** **64.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	12052187	04/05/2023 12:33:36	04/05/2023 13:03:36	0.50	\$59.00
66-79-002	PERFORM SERVICE CALL	12052187	04/05/2023 12:33:36	04/05/2023 12:33:36	0.00	\$0.00
66-79-002	PERFORM SERVICE CALL	12052187	04/05/2023 12:33:36	04/05/2023 12:33:36	0.00	\$0.00
LABOR					59.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	(1)	(\$5.94)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	(7)	(\$43.68)
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	7	\$43.68
PARTS					0.00	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 46626

Work Order Notes

(EKIMBREL) SERVICE CALL, LIFTGATE ISSUE

Job Notes

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Went on service call and found lift gate not coming up. Removed fuse at the solenoid and it was good. Reinstalled fuse and lift gate started working. Raised and lowered multiple times while moving wires to check for a short and found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 46705

USING DEPT NO:	504302	OPENED DATE:	04/13/2023 08:04:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/19/2023 07:37:17	METER 1 - M:	12194	METER 2 - H: 2
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/19/2023 10:00:57	IN-SERVICE DATE:	05/17/2017	
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.62	\$49.62	\$0.00	\$68.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.21	\$24.78	\$0.00	\$0.00	\$24.78

JOB COUNT: 3	WORK ORDER TOTAL:	0.37	43.40	49.62	5.00	98.02
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	04/14/2023 14:30:00	04/14/2023 14:42:36	0.21	\$24.78
WA-00	WASH COMPLETE VEHICLE	12201267	04/14/2023 14:21:01	04/14/2023 14:21:01	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/14/2023 14:05:32	04/14/2023 14:15:00	0.16	\$18.62
LABOR					43.40	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	7	\$43.68
PARTS					49.62	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 46705

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,SH- Changed oil and oil filter, checked fluids, filter good, tires and tire pressure.
Miles, 12,194

(LISAPATE) JW inspected the liftgate

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47064

USING DEPT NO: 504302	OPENED DATE: 05/16/2023 07:47:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/16/2023 10:59:02	METER 1 - M: 12687 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/16/2023 13:08:58	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.04	\$5.08	\$0.00	\$0.00	\$5.08
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.04** **5.08** **0.00** **5.00** **10.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11915538	05/16/2023 08:36:54	05/16/2023 08:39:29	0.04	\$5.08
66-79-002	PERFORM SERVICE CALL	11915538	05/16/2023 08:36:54	05/16/2023 08:39:29	(0.04)	(\$5.08)
66-79-002	PERFORM SERVICE CALL	11915538	05/16/2023 08:36:54	05/16/2023 08:39:29	0.04	\$5.08
LABOR						5.08

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47064

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped off drvier said they needed truck\ they would leave it running for awhile\ RC
(AJONES) Visit Reason Changed On 5/30/2023 2:05 PM By AJONES

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 5/30/2023 2:05 PM By AJONES

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47353

USING DEPT NO: 504302	OPENED DATE: 06/14/2023 07:57:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/14/2023 15:24:11	METER 1 - M: 13094 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/15/2023 07:09:29	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.50** **59.00** **0.00** **5.00** **64.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	11915538	06/14/2023 13:00:00	06/14/2023 14:15:00	1.25	\$147.50
06-32-002	INSPECT BATTERY	11915538	06/14/2023 14:30:00	06/14/2023 14:59:56	(0.50)	(\$58.87)
06-32-002	INSPECT BATTERY	11915538	06/14/2023 14:30:00	06/14/2023 14:59:56	0.50	\$58.87
66-79-002	PERFORM SERVICE CALL	11915538	06/15/2023 07:09:19	06/15/2023 07:39:19	0.50	\$59.00
06-32-002	INSPECT BATTERY	11915538	06/14/2023 10:51:48	06/14/2023 12:00:00	1.14	\$134.13
06-32-002	INSPECT BATTERY	11915538	06/14/2023 13:00:00	06/14/2023 14:15:00	(1.25)	(\$147.50)
06-32-002	INSPECT BATTERY	11915538	06/14/2023 10:51:48	06/14/2023 12:00:00	(1.14)	(\$134.13)
LABOR					59.00	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47353

Work Order Notes

(EHANNAH) service call for dead battery

Job Notes

06-32-002 - INSPECT BATTERY

66-79-002 - PERFORM SERVICE CALL

(GARAGE) jumped off left running\RC CW

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 6/26/2023 10:17 AM By AJONES

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47560

USING DEPT NO: 504302	OPENED DATE: 07/10/2023 14:09:22	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/12/2023 11:59:03	METER 1 - M: 13332 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/12/2023 13:58:47	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	B	N	GARAGE	0.61	\$71.46	\$155.33	\$0.00	\$226.79
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.55	\$64.77	\$0.00	\$0.00	\$64.77
CH-SP	CHARGE Shop Supplies	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	1.15	136.23	155.33	5.00	296.56
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	12052187	07/10/2023 15:02:56	07/10/2023 15:39:16	(0.61)	(\$71.46)
03-32-002	REPLACE NEW BATTERY	12052187	07/10/2023 15:02:56	07/10/2023 15:39:16	0.61	\$71.46
03-32-002	REPLACE NEW BATTERY	12052187	07/10/2023 15:02:56	07/10/2023 15:39:16	0.61	\$71.46
66-79-002	PERFORM SERVICE CALL	12052187	07/10/2023 14:30:00	07/10/2023 15:02:56	0.55	\$64.77
66-79-002	PERFORM SERVICE CALL	12052187	07/10/2023 14:17:19	07/10/2023 14:17:19	0.00	\$0.00
LABOR					136.23	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	155.33	1	\$155.33
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	155.33	(1)	(\$155.33)
03-32-002	REPLACE NEW BATTERY	650	BATTERY BCI 65 650 CCA	155.33	1	\$155.33
PARTS					155.33	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47560

Work Order Notes

(LISAPATE) Service call battery is dead again

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Replaced battery on service call. Alternator charging at 14.3 volts under load. JAW

(AJONES) Visit Reason Changed On 8/1/2023 8:02 AM By AJONES

66-79-002 - PERFORM SERVICE CALL

(GARAGE) went on service call and checked unit. Battery is dead and had corrosion built up. Battery is 3 years old. Replaced battery. JAW

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 8/1/2023 8:02 AM By AJONES

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47780

USING DEPT NO: 504302	OPENED DATE: 07/31/2023 09:55:58	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/07/2023 07:57:19	METER 1 - M: 13616 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/07/2023 09:44:42	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.51	\$16.62	\$0.00	\$26.13
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.29	\$33.96	\$0.00	\$0.00	\$33.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$74.83	\$0.00	\$0.00	\$74.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.25	147.80	16.62	5.00	169.42
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/31/2023 13:26:50	07/31/2023 14:04:53	0.63	\$74.83
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/31/2023 13:26:50	07/31/2023 14:04:53	(0.63)	(\$74.83)
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/31/2023 13:26:50	07/31/2023 14:04:53	0.63	\$74.83
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/31/2023 13:26:50	07/31/2023 14:04:53	(0.63)	(\$74.83)
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/31/2023 13:26:50	07/31/2023 14:04:53	0.63	\$74.83
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/31/2023 14:04:53	07/31/2023 14:09:43	0.08	\$9.51
66-79-003	PERFORM SAFETY INSPECTION	12201267	07/31/2023 14:09:43	07/31/2023 14:15:00	0.09	\$10.39
66-79-003	PERFORM SAFETY INSPECTION	12201267	07/31/2023 14:30:00	07/31/2023 14:41:59	0.20	\$23.57
06-15	INSPECT STEERING	12201267	08/07/2023 07:00:00	08/07/2023 07:15:00	0.25	\$29.50
06-15	INSPECT STEERING	12201267	08/07/2023 07:00:00	08/07/2023 07:15:00	(0.25)	(\$29.50)
06-15	INSPECT STEERING	12201267	08/07/2023 07:00:00	08/07/2023 07:15:00	0.25	\$29.50
					LABOR	147.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
-----------------	------------------------	-----------------	--------------------	-------------------	-----------------	-------------------

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.31	2	\$16.62
					PARTS	16.62

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 47780

Work Order Notes

(EHANNAH) pm- replace wipers- do SI - adjust brakes- inspect steering
(EKIMBREL) truck doesn't get brakes adjusted
(EKIMBREL) inspect steering is covered under safety inspection

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

06-15 - INSPECT STEERING

(LRUSHING) Visit Reason Changed On 8/25/2023 2:54 PM By LRUSHING

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC
Brake pads are Front 8mm and Rear 8mm

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Fluid check only, checked fluids, filter good, tires and tire pressure, updated oil change sticker.
Miles, 13,616

(LRUSHING) Visit Reason Changed On 8/25/2023 2:54 PM By LRUSHING

(LRUSHING) Visit Reason Changed On 8/25/2023 2:54 PM By LRUSHING

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 48331

USING DEPT NO: 504302	OPENED DATE: 09/26/2023 08:16:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/28/2023 08:29:53	METER 1 - M: 14306 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/28/2023 11:11:11	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-02-016	INSPECT TAIL&LIFT GATE	DON	U	N	GARAGE	1.30	\$153.79	\$0.00	\$0.00	\$153.79
CH-SP	CHARGE Shop Supplies	DON	U	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.30** **153.79** **0.00** **5.00** **158.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-02-016	INSPECT TAIL&LIFT GATE	12052187	09/27/2023 07:25:22	09/27/2023 08:43:34	(1.30)	(\$153.79)
06-02-016	INSPECT TAIL&LIFT GATE	12052187	09/27/2023 07:25:22	09/27/2023 08:43:34	1.30	\$153.79
06-02-016	INSPECT TAIL&LIFT GATE	12052187	09/27/2023 07:25:22	09/27/2023 08:43:34	1.30	\$153.79
LABOR						153.79

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 48331

Work Order Notes

(EHANNAH) inspect lift gate

Job Notes

06-02-016 - INSPECT TAIL&LIFT GATE

(GARAGE) FC cleaned off both magnetic probes and reinstalled. Operated and then stopped working. I tested and found loose connection going up to the switch. Reconnected good and operated multiple times with no issues. FC greased and topped off fluid. JAW

(AJONES) Visit Reason Changed On 9/28/2023 9:52 PM By AJONES

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 9/28/2023 9:53 PM By AJONES

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 48907

USING DEPT NO: 504302	OPENED DATE: 11/09/2023 08:10:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/04/2024 08:55:26	METER 1 - M: 14837 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/04/2024 12:02:16	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-64-004	REPLACE NEW LIFT CYLINDERS	DON	N	N	GARAGE	0.23	\$27.53	\$3,305.88	\$138.00	\$3,471.41
06-02-016	INSPECT TAIL&LIFT GATE	DON	N	N	GARAGE	1.91	\$225.18	\$0.00	\$0.00	\$225.18
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.63	\$74.41	\$0.00	\$0.00	\$74.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$26.06	\$56.98	\$0.00	\$83.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	3.24	382.68	3,362.86	143.00	3,888.54
---------------------	--------------------------	-------------	---------------	-----------------	---------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-64-004	REPLACE NEW LIFT CYLINDERS	8802628	30127		\$138.00
				COMML	143.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-015	PERFORM TIRE ROTATION	12395904	11/14/2023 09:57:13	11/14/2023 10:35:03	0.63	\$74.41
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/14/2023 09:43:17	11/14/2023 09:56:32	0.22	\$26.06
03-64-004	REPLACE NEW LIFT CYLINDERS	12052187	12/13/2023 14:01:00	12/13/2023 14:15:00	0.23	\$27.53
06-02-016	INSPECT TAIL&LIFT GATE	12052187	11/21/2023 08:01:41	11/21/2023 08:21:48	0.34	\$39.56
06-02-016	INSPECT TAIL&LIFT GATE	12052187	11/22/2023 08:26:13	11/22/2023 09:54:07	1.47	\$172.87
06-02-016	INSPECT TAIL&LIFT GATE	12052187	12/13/2023 13:54:18	12/13/2023 14:00:47	0.11	\$12.75
06-15	INSPECT STEERING	12052187	01/04/2024 07:30:00	01/04/2024 07:45:00	(0.25)	(\$29.50)
06-15	INSPECT STEERING	12052187	01/04/2024 07:30:00	01/04/2024 07:45:00	0.25	\$29.50
01-13	ADJUST BRAKES	12052187	01/04/2024 07:00:00	01/04/2024 07:30:00	(0.50)	(\$59.00)
01-13	ADJUST BRAKES	12052187	01/04/2024 07:00:00	01/04/2024 07:30:00	0.50	\$59.00
06-15	INSPECT STEERING	12052187	01/04/2024 07:30:00	01/04/2024 07:45:00	0.25	\$29.50

Work Order Charge Detail

					LABOR	382.68
<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.26	7	\$43.79
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	7.25	1	\$7.25
03-64-004	REPLACE NEW LIFT CYLINDERS	22780060	HYD CYLINDER SET OF 2	3298.77	1	\$3,298.77
03-64-004	REPLACE NEW LIFT CYLINDERS	PIGMAT	OIL ABSORMENT MAT	1.19	6	\$7.11
					PARTS	3362.86

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 48907

Work Order Notes

(EHANNAH) pm- adjust brakes- inspect steering- inspect lift gate it is still dropping overnight

Job Notes

01-13 - ADJUST BRAKES

03-64-004 - REPLACE NEW LIFT CYLINDERS

(JWRIGHT) Replaced both lift cylinders. Left it raised up for 4 hours and did not drop any. Topped off fluid with non inv oil. JAW
1.5 hr

06-02-016 - INSPECT TAIL&LIFT GATE

(JWRIGHT) inspected and found lift gate keeps dropping. Believe the cylinders are loosing pressure allowing them to drop. We have already done everything else. Need to quote new cylinders. JAW

06-15 - INSPECT STEERING

(LISAPATE) Checked steering JW
(LRUSHING) Visit Reason Changed On 1/22/2024 3:44 PM By LRUSHING

66-17-015 - PERFORM TIRE ROTATION

(FCONTRER) Rotate tires fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed and fluid check fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 49955

USING DEPT NO: 504302	OPENED DATE: 02/27/2024 08:27:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/07/2024 14:13:09	METER 1 - M: 15455 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/08/2024 10:05:35	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.24	\$28.78	\$0.00	\$0.00	\$28.78
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.05	\$5.83	\$0.00	\$0.00	\$5.83
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	3.22	\$379.57	\$2,308.87	\$0.00	\$2,688.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.30	\$0.00	\$0.00	\$39.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	3.84	453.48	2,308.87	5.00	2,767.35
---------------------	--------------------------	-------------	---------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11074414	02/27/2024 10:29:17	02/27/2024 10:43:55	(0.24)	(\$28.78)
06-15	INSPECT STEERING	11074414	02/27/2024 10:29:17	02/27/2024 10:43:55	0.24	\$28.78
66-17-013	PERFORM ALIGNMENT	12052187	03/01/2024 15:21:31	03/01/2024 15:24:29	0.05	\$5.83
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/01/2024 09:30:00	03/01/2024 11:48:45	2.31	\$272.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/01/2024 08:29:47	03/01/2024 09:15:00	0.75	\$88.93
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/01/2024 08:08:45	03/01/2024 08:17:47	0.15	\$17.77
06-15	INSPECT STEERING	11074414	02/27/2024 10:29:17	02/27/2024 10:43:55	0.24	\$28.78
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/27/2024 09:56:07	02/27/2024 10:16:06	0.33	\$39.30
					LABOR	453.49

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	562050	TIRE 225/70R19.5 TOYO M143	375.48	6	\$2,252.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	61131	LT1 1.00 OZ WHEEL WEIGHT	1.07	3	\$3.20
66-17-028	PERFORM MOUNT AND BALANCE TIRES	61133	LT1 2.00 OZ WHEEL WEIGHT	1.77	6	\$10.62

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	61137	LT1 4.00 OZ WHEEL WEIGHT	3.26	3	\$9.77
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22000	VALVE STEM CHROME LOW BOLT IN	5.40	6	\$32.40
					PARTS	2308.87

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 49955

Work Order Notes

(EHANNAH) pm- wash

Job Notes

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found slight movement in the pitman arm knuckle. Josh will recheck during alignment. SH
(LRUSHING) Visit Reason Changed On 3/27/2024 1:45 PM By LRUSHING

66-17-013 - PERFORM ALIGNMENT

(GARAGE) Performed alignment. Adjusted front toe. Test drove and found no issues. JAW

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 6 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 618 miles. Checked fluids tire pressure updated the oil change sticker and greased the lift gate. Needs 6 tires due to 2017 build dates. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 50924

USING DEPT NO: 504302	OPENED DATE: 05/23/2024 08:40:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/23/2024 13:48:06	METER 1 - M: 16168 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/24/2024 07:59:38	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550	2017 Ford F550	UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$109.37	\$0.00	\$109.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.00** **0.00** **109.37** **5.00** **114.37**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/23/2024 09:17:29	05/23/2024 09:17:29	0.00	\$0.00
LABOR					0.00	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	(1)	(\$25.26)
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	1	\$25.26
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	(1)	(\$25.26)
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE AP	ANTIFREEZE-ALL PURPOSE	25.26	1	\$25.26
66-PM-PMA	PERFORM OIL CHANGE	BALB329	OIL FILTER	5.94	1	\$5.94
66-PM-PMA	PERFORM OIL CHANGE	5W20TQT	QUART CAM2 SYN 5W20 32OZ	14.78	7	\$103.43
PARTS					109.37	

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 50924

Work Order Notes

(EHANNAH) pm- check coolant level

Job Notes

06-05-005 - INSPECT COOLANT TEMPERATURE SENSOR

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) SH/FC Performed PM. Added about 1/2 quart of non-inv coolant. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 51041

USING DEPT NO:	504302	OPENED DATE:	06/05/2024 13:29:26	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 10:37:59	METER 1 - M:	16258	METER 2 - H:	2		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 11:17:22	IN-SERVICE DATE:	05/17/2017				
TECH SPEC NO:	17FORDF550	2017 Ford F550		UNIT SERIAL NO:	1FDUF5GYXHED53414				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-15-004	RECALL STEERING LINKAGE	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
17-GA-005	RECALL Scheduling and Preparation	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 51041

Work Order Notes

(EHANNAH) prep and schedule- RECALL for steering linkage

Job Notes

17-15-004 - RECALL STEERING LINKAGE

(EHANNAH) LL Ford came to our shop for Recall for steering linkage

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise

(LRUSHING) Visit Reason Changed On 6/26/2024 3:36 PM By LRUSHING

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 51534

USING DEPT NO: 504302	OPENED DATE: 07/18/2024 15:43:53	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/07/2024 08:31:59	METER 1 - M: 16757 METER 2 - H: 2
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/08/2024 07:49:07	IN-SERVICE DATE: 05/17/2017
TECH SPEC NO: 17FORDF550 2017 Ford F550		UNIT SERIAL NO: 1FDUF5GYXHED53414

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

UNIT NO: 242304 2017 FORD F550

WORK ORDER NO: 51534

Work Order Notes

(EHANNAH) prep for sale

Job Notes

01-13 - ADJUST BRAKES

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) removed GPS 87u030640104 RC

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) removed wordmarks and tag/ RC

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Aug 13 2024 11:15:17 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '1FDUF5GYXHED53414') //Q=