

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35086

USING DEPT NO:	507301	OPENED DATE:	12/06/2019 14:35:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/10/2019 07:26:13	METER 1 - M:	53	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2019 07:26:14	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	36.25	0.00	0.00	36.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	12/06/2019 14:36:23	12/06/2019 15:06:23	0.50	\$36.25
					LABOR	36.25

# Work Order Charge Detail

UNIT NO: 243601 2019 TOYOTA HIGHLANDER WORK ORDER NO: 35086

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35855

USING DEPT NO:	507301	OPENED DATE:	03/03/2020 08:36:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2020 07:25:07	METER 1 - M:	3732	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2020 07:25:08	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$23.28	\$35.68	\$0.00	\$58.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.32	23.28	35.68	0.00	58.96
--------------	-------------------	------	-------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/03/2020 10:06:45	03/03/2020 10:26:01	0.32	\$23.28
					<b>LABOR</b>	<b>23.28</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					<b>PARTS</b>	<b>35.68</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35855

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by EK,JW/SH

Coolant -35'

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 37005

USING DEPT NO:	507301	OPENED DATE:	07/02/2020 09:56:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2020 10:42:14	METER 1 - M:	4813	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/02/2020 13:24:07	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$18.13	\$0.00	\$0.00	\$18.13

JOB COUNT: 1	WORK ORDER TOTAL:	0.25	18.13	0.00	0.00	18.13
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/02/2020 10:42:39	07/02/2020 10:57:39	0.25	\$18.13
					LABOR	18.13

# Work Order Charge Detail

UNIT NO: 243601 2019 TOYOTA HIGHLANDER WORK ORDER NO: 37005

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW checked fluids, battery, tire pressures, and updated sticker. Coolant -34

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38482

USING DEPT NO:	507301	OPENED DATE:	11/30/2020 07:21:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2020 14:52:19	METER 1 - M:	5547	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2020 07:38:49	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.59	\$43.89	\$0.00	\$89.48

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.39</b>	<b>45.59</b>	<b>43.89</b>	<b>0.00</b>	<b>89.48</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/30/2020 07:42:41	11/30/2020 08:05:52	0.39	\$45.59
					<b>LABOR</b>	<b>45.59</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.11	5	\$30.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.86	1	\$6.86
					<b>PARTS</b>	<b>43.89</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38482

## Work Order Notes

(EKIMBREL) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Found no issues. Coolant -34°. AB/JAW  
MILEAGE-5547



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39755

USING DEPT NO:	507301	OPENED DATE:	04/21/2021 07:06:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2021 15:06:01	METER 1 - M:	7338	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/23/2021 10:29:58	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$45.63	\$0.00	\$0.00	\$45.63

JOB COUNT: 1	WORK ORDER TOTAL:	0.39	45.63	0.00	0.00	45.63
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/21/2021 07:22:01	04/21/2021 07:45:13	0.39	\$45.63
					LABOR	45.63

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39755

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 7338. Vehicle has been driven 7338 miles since last oil change. Checked fluids battery tire pressure and updated oil change sticker. SH

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40269

USING DEPT NO:	507301	OPENED DATE:	06/28/2021 09:04:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2021 15:10:44	METER 1 - M:	9355	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/29/2021 08:55:30	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.40	\$35.93	\$0.00	\$71.33

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	35.40	35.93	0.00	71.33
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11170580	06/28/2021 15:10:04	06/28/2021 15:28:04	0.30	\$35.40
					LABOR	35.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
					PARTS	35.93

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40269

---

## Work Order Notes

(LISAPATE) PM

---

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AB

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40480

USING DEPT NO:	507301	OPENED DATE:	07/20/2021 09:10:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2021 10:12:46	METER 1 - M:	11726	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2021 14:15:55	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.82	\$26.02	\$0.00	\$30.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.86	\$101.38	\$35.93	\$0.00	\$137.31

JOB COUNT: 2	WORK ORDER TOTAL:	0.90	106.20	61.95	0.00	168.15
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/20/2021 13:00:00	07/20/2021 13:21:34	0.36	\$42.41
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/20/2021 12:58:36	07/20/2021 12:58:36	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/20/2021 12:51:24	07/20/2021 13:21:23	0.50	\$58.97
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/20/2021 12:48:44	07/20/2021 12:51:11	0.04	\$4.82
					LABOR	106.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	9.84	1	\$9.84
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	8.85	1	\$8.85
					PARTS	61.95

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40480

## Work Order Notes

(LISAPATE) PM

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 11726. SH/AMG Performed PM.

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41122

USING DEPT NO:	507301	OPENED DATE:	09/27/2021 08:20:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2021 13:31:45	METER 1 - M:	15918	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2021 11:04:28	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.17	\$20.45	\$27.08	\$0.00	\$47.53
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.64	\$75.55	\$0.00	\$0.00	\$75.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$91.25	\$34.67	\$0.00	\$125.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.59	187.25	61.75	2.00	251.00
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	09/27/2021 12:00:38	09/27/2021 12:10:11	0.16	\$18.78
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	09/27/2021 10:26:09	09/27/2021 10:55:01	0.48	\$56.77
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/27/2021 09:38:10	09/27/2021 10:24:34	0.77	\$91.25
03-51-038	REPLACE NEW WIPER BLADES	12052187	09/27/2021 09:27:34	09/27/2021 09:37:58	0.17	\$20.45
				LABOR		187.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.61	1	\$5.61
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.18	1	\$9.18
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
				PARTS		61.75

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41122

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Installed new wiper blades

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(JWRIGHT) Rotated tires. Torqued to spec. All brake pads are 10mm. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW

MILEAGE-15918

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41712

USING DEPT NO:	507301	OPENED DATE:	11/29/2021 07:31:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2021 11:18:05	METER 1 - M:	20086	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	12/02/2021 12:19:22	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$17.90	\$0.00	\$35.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.57	\$67.06	\$34.39	\$0.00	\$101.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:		0.72	84.76	52.29	2.00	139.05
--------------	-------------------	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/29/2021 12:28:53	11/29/2021 12:28:53	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/29/2021 12:26:01	11/29/2021 12:35:01	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/29/2021 12:26:01	11/29/2021 12:26:01	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	11/29/2021 12:26:01	11/29/2021 12:26:01	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/29/2021 11:07:51	11/29/2021 11:41:57	0.57	\$67.06
LABOR						84.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
PARTS						52.29

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41712

## Work Order Notes

(IFALLS) pm

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 20086 Completed PM topside, Josh was bottomside. AMG/JW

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42296

USING DEPT NO:	507301	OPENED DATE:	02/08/2022 11:49:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/08/2022 14:08:10	METER 1 - M:	25068	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/09/2022 07:45:45	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.93	\$109.54	\$62.82	\$0.00	\$172.36
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.07	\$12.23	\$0.00	\$14.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.95	111.61	75.05	2.00	188.66
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/08/2022 13:05:22	02/08/2022 13:34:41	0.49	\$57.66
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/08/2022 13:33:10	02/08/2022 13:34:13	0.02	\$2.07
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/08/2022 13:06:35	02/08/2022 13:32:58	0.44	\$51.89
				LABOR		111.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	12.23	1	\$12.23
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	27.78	1	\$27.78
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
				PARTS		75.05

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42296

## Work Order Notes

(LISAPATE) PM

## Job Notes

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/JW Performed PM.

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced cabin air filter. SH

**CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42668

USING DEPT NO:	507301	OPENED DATE:	03/21/2022 10:54:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/22/2022 11:05:59	METER 1 - M:	29762	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2022 07:24:10	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$28.48	\$0.00	\$67.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.94	28.48	2.00	69.42
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/21/2022 12:12:27	03/21/2022 12:32:15	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/21/2022 12:12:27	03/21/2022 12:12:27	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/21/2022 12:12:27	03/21/2022 12:12:27	0.00	\$0.00
				LABOR		38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
					PARTS	28.48

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42668

## Work Order Notes

(LISAPATE) PM

## Job Notes

### 66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. SH drained oil and removed filter. JAW installed oil filter and refilled oil. Coolant -34°. JAW,SH/SH,JAW  
MILEAGE-29762

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43080

USING DEPT NO:	507301	OPENED DATE:	04/28/2022 08:48:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2022 11:47:27	METER 1 - M:	33246	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2022 15:00:05	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.95	\$22.62	\$0.00	\$27.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.45	\$35.46	\$0.00	\$65.91
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	35.40	58.08	2.00	95.48
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/28/2022 09:45:44	04/28/2022 09:48:15	0.04	\$4.95
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2022 09:30:00	04/28/2022 09:45:29	0.26	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/28/2022 09:20:35	04/28/2022 09:20:35	0.00	\$0.00
				LABOR		35.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.43	1	\$12.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	58.08

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43080

## Work Order Notes

(LISAPATE) PM-replace wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH Performed PM.

**CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43470

USING DEPT NO:	507301	OPENED DATE:	06/02/2022 08:09:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/02/2022 15:28:29	METER 1 - M:	37759	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2022 12:36:24	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.08	\$9.83	\$35.59	\$0.00	\$45.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.08	9.83	35.59	2.00	47.42
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/02/2022 09:30:00	06/02/2022 09:35:00	0.08	\$9.83
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/02/2022 09:19:16	06/02/2022 09:19:16	0.00	\$0.00
				LABOR		9.83

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.27	1	\$5.27
					PARTS	35.59

# Work Order Charge Detail

UNIT NO:2436012019 TOYOTA HIGHLANDER

WORK ORDER NO:43470

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE  
(HHARBIN) SH/AMG Performed PM.  
CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44249

USING DEPT NO:	507301	OPENED DATE:	08/10/2022 09:29:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/16/2022 08:18:12	METER 1 - M:	41205	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	08/16/2022 13:58:20	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.05	\$5.41	\$0.00	\$0.00	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.45	\$41.35	\$0.00	\$89.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.46	53.86	41.35	2.00	97.21
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/10/2022 13:24:47	08/10/2022 13:27:32	0.05	\$5.41
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/10/2022 13:00:00	08/10/2022 13:24:38	0.41	\$48.45
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/10/2022 12:40:28	08/10/2022 12:40:28	0.00	\$0.00
				LABOR		53.86

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
					PARTS	41.35

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44249

## Work Order Notes

(LRUSHING) PM

## Job Notes

### **66-79-003 - PERFORM SAFETY INSPECTION**

(JWRIGHT) Performed safety inspection. All pads are 10mm. No issues found. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW  
MILEAGE-41205

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44460

USING DEPT NO:	507301	OPENED DATE:	08/25/2022 08:35:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/26/2022 09:50:43	METER 1 - M:	42616	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2022 13:42:31	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.10	\$11.60	\$0.00	\$0.00	\$11.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.10	11.60	0.00	5.00	16.60
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	12052187	08/25/2022 09:06:13	08/25/2022 09:12:07	0.10	\$11.60
LABOR						11.60

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44460

## Work Order Notes

(CWIGLEY) they had to swap the RF tire out. It needs to be inspected to see if its ok, or needs to be replaced.

## Job Notes

### 06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(JWRIGHT) Inspected rf tire and lug nuts all is good. Tire was replaced somewhere on the road. Donut is still under the car. JAW

(IFALLS) Tire was replaced out of town by renter.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45034

USING DEPT NO:	507301	OPENED DATE:	10/20/2022 07:24:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2022 10:58:51	METER 1 - M:	46437	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2022 13:59:26	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.58	\$48.32	\$0.00	\$78.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.26	30.58	48.32	5.00	83.90
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/20/2022 08:01:30	10/20/2022 08:17:03	0.26	\$30.58
					LABOR	30.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
					PARTS	48.32

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45034

## Work Order Notes

(LISAPATE) PM

## Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) RC/SH Performed PM.

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46211

USING DEPT NO:	507301	OPENED DATE:	02/21/2023 09:27:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2023 10:38:55	METER 1 - M:	50985	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2023 11:16:42	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.31	\$23.26	\$0.00	\$30.57
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$36.94	\$46.32	\$0.00	\$83.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.38	44.25	69.58	5.00	118.83
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/22/2023 07:08:10	02/22/2023 07:18:06	0.17	\$19.54
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/22/2023 07:04:14	02/22/2023 07:07:57	0.06	\$7.31
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/21/2023 15:32:00	02/21/2023 15:40:51	0.15	\$17.41
				LABOR		44.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	8.01	1	\$8.01
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
				PARTS		69.58

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46211

## Work Order Notes

(EHANNAH) pm- replace wipers.

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

### 66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46960

USING DEPT NO:	507301	OPENED DATE:	05/05/2023 08:23:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2023 15:07:57	METER 1 - M:	54760	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/12/2023 10:37:46	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-40-440	REPLACE NEW OIL CRANKCASE FILTE	DON	O	N	GARAGE	0.10	\$11.80	\$64.88	\$0.00	\$76.68
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.06	\$7.15	\$0.00	\$0.00	\$7.15
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	2.95	\$347.58	\$0.00	\$0.00	\$347.58
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.24	\$146.29	\$938.66	\$0.00	\$1,084.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.34	\$48.36	\$0.00	\$69.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.04	\$4.13	\$20.27	\$0.00	\$24.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7	WORK ORDER TOTAL:	4.56	538.29	1,072.17	5.00	1,615.46
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-40-440	REPLACE NEW OIL CRANKCASE FILTER HOUSING	12201267	05/11/2023 07:00:00	05/11/2023 07:06:00	0.10	\$11.80
06-15	INSPECT STEERING	12201267	05/11/2023 10:40:03	05/11/2023 10:43:41	0.06	\$7.15
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/09/2023 14:30:00	05/09/2023 15:44:23	1.24	\$146.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12201267	05/09/2023 14:21:51	05/09/2023 14:21:51	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	05/08/2023 07:30:15	05/08/2023 07:32:21	0.04	\$4.13
66-PM-PMA	PERFORM OIL CHANGE	12201267	05/08/2023 07:25:49	05/08/2023 07:30:01	0.07	\$8.26
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/05/2023 10:46:19	05/05/2023 10:52:58	0.11	\$13.08
66-17-013	PERFORM ALIGNMENT	11310047	05/11/2023 09:54:17	05/11/2023 12:51:01	2.95	\$347.58
				LABOR		538.29

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	5	\$31.28
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	26744	P245/60R18 TIRES	228.38	4	\$913.50
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	20.27	1	\$20.27
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	26744	P245/60R18 TIRES	228.38	(4)	(\$913.50)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	26744	P245/60R18 TIRES	228.38	4	\$913.50
03-40-440	REPLACE NEW OIL CRANKCASE FILTER HOUSING	1562036020	OIL FILTER HOUSING	64.88	1	\$64.88
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.31	4	\$21.24
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.14	29	\$3.92
					<b>PARTS</b>	<b>1072.17</b>

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46960

## Work Order Notes

(CWIGLEY) PM and wash.

## Job Notes

### **03-40-440 - REPLACE NEW OIL CRANKCASE FILTER HOUSING**

(GARAGE) Plastic filter housing on the Toyota broke the tabs while removing, installed new housing.-GC

### **06-15 - INSPECT STEERING**

(GRCOOK) Inspected steering, found no issues at this time-GC

### **66-17-013 - PERFORM ALIGNMENT**

(EHOWELL) Performed alignment. EH/JAW

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GRCOOK) Mounted and Balanced all 4 new tires-GC  
Miles, 54,760

### **66-PM-PMA - PERFORM OIL CHANGE**

(GRCOOK) Performed PM-JW,GC, Changed oil and oil filter, checked fluids, filter good, tires and tire pressure.  
Miles, 54,760

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(GRCOOK) Replaced cabin filter-JW

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47137

USING DEPT NO:	507301	OPENED DATE:	05/22/2023 12:07:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/31/2023 11:48:24	METER 1 - M:	56804	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/31/2023 11:48:26	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
05-02-061	REPLACE USED WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$730.25	\$730.25
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	735.25	794.25
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
05-02-061	REPLACE USED WINDSHIELD	11078716	2-108881		\$730.25
COMML					735.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	05/31/2023 07:00:00	05/31/2023 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47137

## Work Order Notes

(EHANNAH) replace new windshield

## Job Notes

### 05-02-061 - REPLACE USED WINDSHIELD

(LISAPATE) Glass Dr installed a new windshield. PD by CC

### 16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Took to Glass Dr for new windshield to be installed

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47398

USING DEPT NO:	507301	OPENED DATE:	06/21/2023 10:34:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/21/2023 14:46:45	METER 1 - M:	57079	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/21/2023 14:46:46	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.34	\$24.08	\$0.00	\$27.42
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.40	\$47.53	\$48.43	\$0.00	\$95.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.43	50.87	72.51	5.00	128.38
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/21/2023 11:11:02	06/21/2023 11:12:44	0.03	\$3.34
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/21/2023 10:46:40	06/21/2023 11:10:50	0.40	\$47.53
LABOR						50.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
PARTS						72.51



# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47398

## Work Order Notes

(EHANNAH) pm- replace wipers - wash

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 47889

USING DEPT NO:	507301	OPENED DATE:	08/11/2023 13:42:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2023 13:13:54	METER 1 - M:	61672	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/22/2023 09:32:04	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.71	\$48.11	\$0.00	\$76.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.24	28.71	48.11	5.00	81.82
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/11/2023 14:00:24	08/11/2023 14:15:00	0.24	\$28.71
					LABOR	28.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.00	1	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
					PARTS	48.11

# Work Order Charge Detail

UNIT NO:	243601	2019 TOYOTA HIGHLANDER	WORK ORDER NO:	47889
----------	--------	------------------------	----------------	-------

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 48218

USING DEPT NO:	507301	OPENED DATE:	09/15/2023 07:12:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2023 15:31:15	METER 1 - M:	62173	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2023 08:27:02	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$759.00	\$759.00
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	764.00	823.00
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2112394		\$759.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					764.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	09/19/2023 07:00:00	09/19/2023 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 48218

---

## Work Order Notes

(EHANNAH) glass dr replace windshield

---

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(LISAPATE) Glass Dr installed a new windshield and recalibrated. Pd by CC

### **16-71 - TRANSPORT BODY**

(LISAPATE) Taken to Glass Dr by RC/CW

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 48965

USING DEPT NO:	507301	OPENED DATE:	11/15/2023 09:17:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/16/2023 14:09:27	METER 1 - M:	65947	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/16/2023 15:47:35	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$86.15	\$0.00	\$125.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.33	38.94	86.15	5.00	130.09
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	11/16/2023 07:00:00	11/16/2023 07:19:48	0.33	\$38.94
					LABOR	38.94

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	DODGE DURANGO AIR FILTER	30.92	1	\$30.92
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	12.96	1	\$12.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	5	\$31.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.77	1	\$10.77
					PARTS	86.15

# Work Order Charge Detail

UNIT NO:2436012019 TOYOTA HIGHLANDER

WORK ORDER NO:48965

Work Order Notes

(LRUSHING) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 50536

USING DEPT NO:	507301	OPENED DATE:	04/11/2024 09:00:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2024 09:44:47	METER 1 - M:	70120	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2024 12:28:03	IN-SERVICE DATE:	12/06/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH0KS060303	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.18	\$46.13	\$0.00	\$92.31
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.39	46.18	46.13	5.00	97.31
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/11/2024 11:36:31	04/11/2024 12:00:00	0.39	\$46.18
LABOR						46.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
PARTS						46.13



# Work Order Charge Detail

UNIT NO:2436012019 TOYOTA HIGHLANDER

WORK ORDER NO:50536

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		243601		2019 TOYOTA HIGHLANDER				WORK ORDER NO:		51567		
USING DEPT NO:		507301		OPENED DATE:		07/23/2024 08:57:43		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		08/07/2024 10:21:48		METER 1 - M: 72907		METER 2 - N: 0		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		08/07/2024 10:21:49		IN-SERVICE DATE:		12/06/2019		
TECH SPEC NO:		19TOYHIGHLNDR		2019 Toyota Highlander				UNIT SERIAL NO:		5TDZARFH0KS060303		
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999		PREP DISPOSE PREPARE UNIT FOR DI		DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:				0.00		0.00	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 08/09/2024 08:55:34 By User: GLOBETTI

UNIT NO: 243601 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51567

## Work Order Notes

(EHANNAH) prep for sale

## Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Aug 09 2024 08:55:34 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '243601') //Q=