

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 35343

USING DEPT NO: 507201	OPENED DATE: 01/08/2020 10:47:27	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/10/2020 14:00:12	METER 1 - M: 83 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/10/2020 14:00:15	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	12052187	01/08/2020 10:48:11	01/08/2020 11:18:11	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 35343

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) JW performed PDI

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 35590

USING DEPT NO: 507201	OPENED DATE: 02/06/2020 09:56:07	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/14/2020 09:27:31	METER 1 - M: 540 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/14/2020 09:27:33	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.48	\$34.74	\$0.00	\$0.00	\$34.74

JOB COUNT: 1	WORK ORDER TOTAL:	0.48	34.74	0.00	0.00	34.74
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-044	INSTALL TOOLBOX ASSY	11074414	02/06/2020 10:02:53	02/06/2020 10:31:38	0.48	\$34.74
					LABOR	34.74

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 35590

Work Order Notes

(LISAPATE) Removed toolbox from T13 install on T6

Job Notes

14-78-044 - INSTALL TOOLBOX ASSY

(LISAPATE) Removed toolbox from 0573C and installed into 2905C

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 36263

USING DEPT NO:	507201	OPENED DATE:	04/29/2020 13:33:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2020 15:58:33	METER 1 - M:	1218	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2020 07:32:55	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
05-17-028	REPLACE USED MOUNT AND BALANCE	DON	O	N	GARAGE	0.20	\$14.50	\$4.13	\$0.00	\$18.63
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	O	N	GARAGE	0.00	\$0.00	\$2.73	\$0.00	\$2.73

JOB COUNT: 2 WORK ORDER TOTAL: 0.20 14.50 6.86 0.00 21.36

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
05-17-028	REPLACE USED MOUNT AND BALANCE TIRES	11310047	04/29/2020 15:56:13	04/29/2020 16:08:13	0.20	\$14.50
					LABOR	14.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
05-17-028	REPLACE USED MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
05-17-028	REPLACE USED MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.41	2	\$0.81
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
					PARTS	6.86

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 36263

Work Order Notes

(IFALLS) Nail in left front tire

Job Notes

05-17-028 - REPLACE USED MOUNT AND BALANCE TIRES

(IFALLS) EH installed a used non inventory tire, mounted and balanced

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(IFALLS) EH found nail in left front tire, tried to patch and patch still leaked. To close to side wall

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 36509

USING DEPT NO: 507201	OPENED DATE: 05/20/2020 07:50:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2020 11:27:00	METER 1 - M: 1303 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/20/2020 15:36:41	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.91	\$65.77	\$41.40	\$0.00	\$107.17

JOB COUNT: 1	WORK ORDER TOTAL:	0.91	65.77	41.40	0.00	107.17
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/20/2020 09:15:00	05/20/2020 09:26:15	0.19	\$13.59
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/20/2020 09:03:18	05/20/2020 09:15:00	0.20	\$14.14
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/20/2020 09:30:00	05/20/2020 10:01:29	0.52	\$38.04
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/20/2020 09:02:54	05/20/2020 09:02:54	0.00	\$0.00
					LABOR	65.77

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
					PARTS	41.40

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 36509

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JW,SH/JW performed pm. Coolant -20

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 37006

USING DEPT NO: 507201	OPENED DATE: 07/02/2020 10:53:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/07/2020 14:09:53	METER 1 - M: 1802 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/08/2020 07:41:57	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	6.76	\$489.82	\$550.34	\$0.00	\$1,040.16

JOB COUNT: 1	WORK ORDER TOTAL:	6.76	489.82	550.34	0.00	1,040.16
---------------------	--------------------------	-------------	---------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11310047	07/06/2020 07:11:18	07/06/2020 11:21:40	4.17	\$302.53
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11310047	07/02/2020 14:30:00	07/02/2020 15:54:17	1.40	\$101.84
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11310047	07/02/2020 13:04:17	07/02/2020 14:15:00	1.18	\$85.45
					LABOR	489.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	2.24	1	\$2.24
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	122.55	2	\$245.10
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	147.90	2	\$295.80
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	6.81	1	\$6.81
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.39	1	\$0.39
					PARTS	550.34

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 37006

Work Order Notes

(EKIMBREL) Install strobes

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(IFALLS) Ran wires from the rear of the vehicle to switch in the cab. Mounted strobes in the grill and ran wires under the cab to join other wires going inside the cab. Soldered wires and installed loom to protect wires.

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 37515

USING DEPT NO:	507201	OPENED DATE:	09/04/2020 13:10:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/29/2020 15:50:10	METER 1 - M:	2906	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/29/2020 15:50:11	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25
09-15	ALIGN STEERING	DON	O	N	GARAGE	2.78	\$201.49	\$0.00	\$2,300.00	\$2,501.49
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	4.28	310.24	0.00	2,300.00	2,610.24
---------------------	--------------------------	-------------	---------------	-------------	-----------------	-----------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
09-15	ALIGN STEERING	11150605	1690234		\$2,300.00
				COMML	2300.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	09/29/2020 07:00:00	09/29/2020 08:00:00	1.00	\$72.50
06-15	INSPECT STEERING	11170580	09/29/2020 07:00:00	09/29/2020 07:30:00	0.50	\$36.25
09-15	ALIGN STEERING	11170580	09/04/2020 13:16:03	09/04/2020 16:02:48	2.78	\$201.49
					LABOR	310.24

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 37515

Work Order Notes

(LISAPATE) Front end RF side was damaged. Check steering and alignment dept will still use truck until repairs are made.

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) Checked steering components prior to going to the Body Shop

09-15 - ALIGN STEERING

(LISAPATE) Performed alignment

16-71 - TRANSPORT BODY

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired RF bumper and fender damage per estimate.

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 38032

USING DEPT NO: 507201	OPENED DATE: 10/16/2020 08:31:14	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/16/2020 13:07:41	METER 1 - M: 3502 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/19/2020 13:01:18	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.41	\$48.25	\$0.00	\$0.00	\$48.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$79.88	\$54.17	\$0.00	\$134.05

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.09** **128.13** **54.17** **0.00** **182.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	10/16/2020 09:52:26	10/16/2020 10:16:58	0.41	\$48.25
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/16/2020 09:43:37	10/16/2020 09:47:32	0.07	\$7.70
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/16/2020 09:00:59	10/16/2020 09:37:41	0.61	\$72.18
					LABOR	128.13

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.84	1	\$6.84
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	7	\$40.85
					PARTS	54.17

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 38032

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) AMG SH/AMG PERFORMED PM.

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 39456

USING DEPT NO:	507201	OPENED DATE:	03/22/2021 10:14:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/23/2021 15:19:12	METER 1 - M:	5937	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2021 08:45:58	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.50	\$58.57	\$33.41	\$0.00	\$91.98

JOB COUNT: 1 WORK ORDER TOTAL: 0.50 58.57 33.41 0.00 91.98

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/22/2021 15:08:39	03/22/2021 15:38:26	0.50	\$58.57
					LABOR	58.57

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
					PARTS	33.41

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 39456

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 5937. SH Performed PM washed and vacuumed was full of gas.

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA WORK ORDER NO: 39810

USING DEPT NO:	507201	OPENED DATE:	04/27/2021 08:40:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/29/2021 10:09:16	METER 1 - M:	6501	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2021 11:00:23	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	1.57	\$185.82	\$8.48	\$0.00	\$194.30

JOB COUNT: 1 WORK ORDER TOTAL: 1.57 185.82 8.48 0.00 194.30

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	04/27/2021 12:14:56	04/27/2021 13:49:25	1.57	\$185.82
					LABOR	185.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.47	1	\$0.47
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.01	2	\$8.01
					PARTS	8.48

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 39810

Work Order Notes

(LISAPATE) Nail in RF tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(JWRIGHT) Repaired the RF tire and the LR tire. Reused old wheel weights except 1. Also reused valve stem seals since they were still good. Aired to spec and found no other leaks. Torqued lugs to 83ft lbs. JAW

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 40829

USING DEPT NO: 507201	OPENED DATE: 08/24/2021 13:13:57	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/27/2021 08:11:57	METER 1 - M: 7784 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/27/2021 14:32:18	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.07	\$8.62	\$15.18	\$0.00	\$23.80
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.21	\$25.11	\$0.00	\$0.00	\$25.11
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.62	72.67	15.18	2.00	89.85
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	08/25/2021 07:40:18	08/25/2021 07:53:04	0.21	\$25.11
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/25/2021 07:35:42	08/25/2021 07:40:05	0.07	\$8.62
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/25/2021 07:53:13	08/25/2021 08:13:01	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/25/2021 07:53:13	08/25/2021 07:56:46	0.06	\$6.98
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/25/2021 07:53:13	08/25/2021 07:56:46	(0.06)	(\$6.98)
					LABOR	72.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
					PARTS	15.18

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 40829

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades. JAW

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed SI found no issues. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1847 miles since last pm. Updated sticker. Checked all tires and fluids. Found no issues. Coolant -34°. JAW
MILEAGE-7784

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 42209

USING DEPT NO: 507201	OPENED DATE: 01/28/2022 07:26:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/31/2022 11:11:14	METER 1 - M: 10009 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/31/2022 12:56:17	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.02	\$2.88	\$1.71	\$0.00	\$4.59
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.88	\$20.38	\$0.00	\$27.26
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.14	\$17.04	\$0.00	\$0.00	\$17.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.09	\$129.01	\$31.97	\$0.00	\$160.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.32	155.81	54.06	2.00	211.87
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/28/2022 09:30:00	01/28/2022 09:38:40	0.14	\$17.04
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	01/28/2022 09:24:27	01/28/2022 09:24:27	0.00	\$0.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11074414	01/28/2022 09:02:47	01/28/2022 09:04:15	0.02	\$2.88
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/28/2022 08:47:14	01/28/2022 08:50:44	0.06	\$6.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/28/2022 08:15:48	01/28/2022 08:46:59	0.52	\$61.33
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/28/2022 08:07:36	01/28/2022 08:42:01	0.57	\$67.69
					LABOR	155.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	7443	BULB- TAILLIGHT	1.71	1	\$1.71
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
					PARTS	54.06

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 42209

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(SHARBIN) Replaced right rear bottom brake light bulb. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 43305

USING DEPT NO: 507201	OPENED DATE: 05/19/2022 07:44:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2022 14:57:13	METER 1 - M: 12275 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2022 08:08:31	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.18	\$0.00	\$32.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$39.86	\$0.00	\$78.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.48	56.64	55.04	2.00	113.68
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/19/2022 09:27:41	05/19/2022 09:36:41	0.15	\$17.70
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/19/2022 09:27:41	05/19/2022 09:27:41	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/19/2022 09:27:41	05/19/2022 09:27:41	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2022 09:15:34	05/19/2022 09:35:22	0.33	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2022 09:15:34	05/19/2022 09:15:34	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2022 09:15:34	05/19/2022 09:15:34	0.00	\$0.00
LABOR					56.64	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
PARTS					55.04	

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 43305

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW
MILEAGE-12275

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 45092

USING DEPT NO:	507201	OPENED DATE:	10/27/2022 09:56:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/08/2022 07:19:00	METER 1 - M:	14615	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2022 09:22:16	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.79	\$10.47	\$0.00	\$11.26
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.17	\$20.39	\$0.00	\$0.00	\$20.39
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.68	\$198.57	\$0.00	\$0.00	\$198.57
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.84	\$217.12	\$663.11	\$0.00	\$880.23
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.42	\$68.65	\$0.00	\$103.07
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.06	\$6.85	\$14.58	\$0.00	\$21.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 7 WORK ORDER TOTAL: 4.05 478.14 756.81 5.00 1,239.95

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	10/31/2022 14:30:00	10/31/2022 14:55:58	0.43	\$51.07
09-15	ALIGN STEERING	11310047	10/31/2022 13:00:00	10/31/2022 14:15:00	1.25	\$147.50
09-15	ALIGN STEERING	11310047	10/31/2022 12:24:40	10/31/2022 12:24:40	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	10/31/2022 07:17:16	10/31/2022 09:07:40	1.84	\$217.12
06-15	INSPECT STEERING	11074414	10/27/2022 11:39:28	10/27/2022 11:49:50	0.17	\$20.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	10/27/2022 11:34:58	10/27/2022 11:38:27	0.06	\$6.85
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/27/2022 11:34:23	10/27/2022 11:34:47	0.01	\$0.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/27/2022 11:16:39	10/27/2022 11:34:09	0.29	\$34.42
					LABOR	478.14

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	154.91	(4)	(\$619.62)

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	154.91	4	\$619.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.98	4	\$27.90
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	1	\$10.47
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	14.58	1	\$14.58
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.72	1	\$5.72
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	154.91	4	\$619.62
66-17-028	PERFORM MOUNT AND BALANCE TIRES	19190	19" WIPERS	10.47	1	\$10.47
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	2	\$1.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	2	\$1.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
					PARTS	756.81

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 45092

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) JM replaced wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected steering found no issues at this time. SH

09-15 - ALIGN STEERING

(EHOWELL) Set front toe. Performed road test and the steering wheel was way off to one side. Set front toe again and performed another road test. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced four new tires. Brakes look good at all four corners of the vehicle. EH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/SH AMG Performed PM.

(SHARBIN) Vehicle needs 4 tires due to excessive shoulder wear. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 46612

USING DEPT NO: 507201	OPENED DATE: 04/04/2023 12:15:19	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 04/07/2023 07:48:52	METER 1 - M: 16210 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 04/07/2023 14:37:19	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$18.32	\$0.00	\$0.00	\$18.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.90	\$0.00	\$0.00	\$3.90

JOB COUNT: 3	WORK ORDER TOTAL:	0.19	22.22	0.00	5.00	27.22
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	04/05/2023 09:13:01	04/05/2023 09:15:00	0.03	\$3.90
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/05/2023 09:03:21	04/05/2023 09:12:40	0.16	\$18.32
LABOR					22.22	

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 46612

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Fluid check only, tires and tire pressure, filters good, Miles, 16,210

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 46730

USING DEPT NO: 507201	OPENED DATE: 04/17/2023 08:28:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/01/2023 08:10:35	METER 1 - M: 16292 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/02/2023 09:25:02	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
24-71	REPAIR BODY	11150605	1697385		\$480.01
24-71	REPAIR BODY	11150605	1697385		(\$480.01)
24-71	REPAIR BODY	11150605	1697385		\$0.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-71	TRANSPORT BODY	11915538	05/01/2023 07:00:00	05/01/2023 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 46730

Work Order Notes

(LISAPATE) transport for body work to be paid by other party involved

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews repaired per estimate. Other party Brad Bullock paid invoice directly to Andrews. See attached

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47754

USING DEPT NO:	507201	OPENED DATE:	07/27/2023 07:11:33	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	08/01/2023 08:13:19	METER 1 - M:	17663	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:21:28	IN-SERVICE DATE:	01/08/2020		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.28	\$33.04	\$115.32	\$0.00	\$148.36
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.02	\$2.20	\$0.00	\$0.00	\$2.20
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.30	35.24	115.32	5.00	155.56
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-32-002	INSPECT BATTERY	12052187	07/28/2023 07:40:27	07/28/2023 07:41:34	0.02	\$2.20
03-32-002	REPLACE NEW BATTERY	12052187	07/28/2023 07:23:39	07/28/2023 07:40:27	0.28	\$33.04
LABOR					35.24	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	115.32	1	\$115.32
PARTS					115.32	

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47754

Work Order Notes

(EHANNAH) driver reports trouble with the battery, he thinks it might be the battery post.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(GARAGE) Replaced battery. Alternator charging at 13.8 volts. JAW

06-32-002 - INSPECT BATTERY

(GARAGE) inspected battery and it is 3 years old will not hold a charge. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47873

USING DEPT NO: 507201	OPENED DATE: 08/10/2023 07:53:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/10/2023 15:31:47	METER 1 - M: 17815 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/21/2023 08:55:31	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$16.10	\$0.00	\$33.80
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$46.98	\$0.00	\$85.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	P	N	GARAGE	0.30	\$35.40	\$11.79	\$0.00	\$47.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.10	\$11.37	\$0.00	\$0.00	\$11.37

JOB COUNT: 6	WORK ORDER TOTAL:	1.13	132.91	74.87	5.00	212.78
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	08/10/2023 12:18:53	08/10/2023 12:36:53	0.30	\$35.40
WA-00	WASH COMPLETE VEHICLE	11074414	08/10/2023 13:00:00	08/10/2023 13:05:47	0.10	\$11.37
WA-00	WASH COMPLETE VEHICLE	11074414	08/10/2023 12:39:00	08/10/2023 12:39:00	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/10/2023 12:22:55	08/10/2023 12:37:55	0.25	\$29.50
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/10/2023 12:22:55	08/10/2023 12:22:55	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/10/2023 12:22:55	08/10/2023 12:22:55	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/10/2023 12:15:51	08/10/2023 12:15:51	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/10/2023 12:15:51	08/10/2023 12:15:51	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/10/2023 12:15:51	08/10/2023 12:24:51	0.15	\$17.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2023 11:59:05	08/10/2023 11:59:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2023 11:59:05	08/10/2023 11:59:05	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/10/2023 11:59:05	08/10/2023 12:18:53	0.33	\$38.94

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB19-1	WIPER BLADE 19"	7.77	1	\$7.77
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.80	6	\$40.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
					PARTS	74.87

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47873

Work Order Notes

(EHANNAH) pm-replace wipers-wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GARAGE) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC/SH Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(EKIMBREL) SH REPLACED CABIN FILTER

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47952

USING DEPT NO:	507201	OPENED DATE:	08/22/2023 14:44:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2023 11:29:28	METER 1 - M:	17815	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2023 13:46:28	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN7LX171826	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	5	N	GARAGE	0.10	\$11.80	\$656.72	\$0.00	\$668.52
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.10 11.80 656.72 5.00 673.52

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	10208562	08/23/2023 07:00:00	08/23/2023 07:06:00	0.10	\$11.80
					LABOR	11.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ECC5585AVM	LED MINI AMBER STROBE LIGHT	656.72	1	\$656.72
					PARTS	656.72

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 47952

Work Order Notes

(LISAPATE) Purchase strobe light

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) IF installed amber magnetic strobe light

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 49375

USING DEPT NO: 507201	OPENED DATE: 01/08/2024 11:50:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/10/2024 10:09:57	METER 1 - M: 19659 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/11/2024 09:09:01	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	P	N	GARAGE	0.10	\$11.80	\$1.86	\$0.00	\$13.66
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.64	\$70.86	\$0.00	\$113.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$45.30	\$0.00	\$0.00	\$45.30

JOB COUNT: 4	WORK ORDER TOTAL:	0.85	99.74	72.72	5.00	177.46
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	12395904	01/10/2024 07:00:00	01/10/2024 07:06:00	0.10	\$11.80
WA-00	WASH COMPLETE VEHICLE	12395904	01/09/2024 06:51:15	01/09/2024 07:14:17	0.38	\$45.30
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/08/2024 15:12:32	01/08/2024 15:34:13	0.36	\$42.64
					LABOR	99.74

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	7440N	BULB	1.86	1	\$1.86
					PARTS	72.72

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 49375

Work Order Notes

(LRUSHING) pm -wash

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LISAPATE) Replaced RR brake light

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Was fc

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 51810

USING DEPT NO: 507201	OPENED DATE: 08/14/2024 12:15:29	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/17/2024 09:19:03	METER 1 - M: 22594 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/17/2024 09:27:29	IN-SERVICE DATE: 01/08/2020
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN7LX171826

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$4.06	\$4.06
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.03	\$4.06	\$0.00	\$0.00	\$4.06

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.03** **4.06** **0.00** **4.06** **8.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$4.06
				COMML	4.06

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/16/2024 12:56:11	08/16/2024 12:58:15	0.03	\$4.06
					LABOR	4.06

Work Order Charge Detail

UNIT NO: 243619 2020 TOYOTA TACOMA

WORK ORDER NO: 51810

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks. Removed pancake strobe. Removed tag 2905C. Checked inside of vehicle. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Aug 21 2024 10:47:08 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243619') //Q=