

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 26608

USING DEPT NO:	507201	OPENED DATE:	06/14/2017 15:08:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/19/2017 06:41:31	METER 1 - M:	282	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/19/2017 06:41:32	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$449.99	\$0.00	\$478.74
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 2** **WORK ORDER TOTAL: 1.00 57.50 449.99 0.00 507.49**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11213180	06/14/2017 15:09:38	06/14/2017 15:39:38	0.50	\$28.75
14-78-044	INSTALL TOOLBOX ASSY	11758845	06/14/2017 15:09:44	06/14/2017 15:39:44	0.50	\$28.75
					<b>LABOR</b>	<b>57.50</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-044	INSTALL TOOLBOX ASSY	TBS63ALP	TOOLBOX	449.99	1	\$449.99
					<b>PARTS</b>	<b>449.99</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 26608

---

**Work Order Notes**

(LISAPATE) DO PDI-INSTALL TOOLBOX

---

**Job Notes**

**14-78-044 - INSTALL TOOLBOX ASSY**

(LISAPATE) INSTALLED TOOLBOX

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI-COMPLETED

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 26998

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 08/07/2017 07:37:18	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/15/2017 06:38:17	<b>METER 1 - M:</b> 548 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/15/2017 06:38:19	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	15.29	\$879.06	\$1,345.83	\$0.00	\$2,224.89

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>15.29</b>	<b>879.06</b>	<b>1,345.83</b>	<b>0.00</b>	<b>2,224.89</b>
---------------------	--------------------------	--------------	---------------	-----------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	08/08/2017 07:17:10	08/08/2017 17:58:13	10.68	\$614.34
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	08/09/2017 06:07:31	08/09/2017 10:43:45	4.60	\$264.72
					<b>LABOR</b>	<b>879.06</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	03MFP3011	HEAT SHRINK	7.49	1	\$7.49
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC1808KT	CONNECTOR	3.49	1	\$3.49
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SHIPPING	SHIPPING AND HANDLING	6.00	1	\$6.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8230A	3/16 WTPF HEAT SHRINK 4FT	12.79	1	\$12.79
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	USASD11B100	11" ZIP TIE 100 PCS	10.79	1	\$10.79
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SFIONA	STROBE LIGHT KIT	165.60	2	\$331.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0950PT	FUSE HOLDER	3.24	1	\$3.24
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	MMM06133	ELECTRICAL TAPE	6.57	1	\$6.57
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.59	1	\$0.59
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	0.36	50	\$18.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8231A	1/4 WTPF SHRINK TUBE 4FT	15.97	1	\$15.97
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81167S	WIRE	24.00	1	\$24.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONC	ION WIDE ANGLE STROBE CLEAR	162.00	2	\$324.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609C	WHITE STROBE LIGHT KIT	121.50	2	\$243.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	SWITCH	ACCELERATOR SWITCH	7.50	1	\$7.50
					<b>PARTS</b>	<b>1345.83</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 26998

---

**Work Order Notes**

(LISAPATE) INSTALL FRONT AND REAR STROBE LIGHTS

---

**Job Notes**

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(RWINTERS) INSTALLED AMBER STROBES INSIDE VEHICLE AND INSTALLED WITH STROBES IN GRILLE AND TAILLIGHTS

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 28207

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 11/20/2017 15:16:12	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/22/2017 13:08:00	<b>METER 1 - M:</b> 2004 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> PREVENTIVE MAINT	<b>CLOSED DATE:</b> 11/22/2017 13:08:02	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$41.22	\$0.00	\$59.05

**JOB COUNT: 1** **WORK ORDER TOTAL:** **0.31** **17.83** **41.22** **0.00** **59.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 07:24:21	11/21/2017 07:24:30	0.00	(\$0.14)
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 07:24:21	11/21/2017 07:24:30	0.00	\$0.14
66-PM-PMA	PERFORM OIL CHANGE	11901357	11/21/2017 07:24:21	11/21/2017 07:42:57	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	SYN0W20	NAPA 0W20	5.75	6	\$34.47
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.75	1	\$6.75
					<b>PARTS</b>	<b>41.22</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 28207

---

**Work Order Notes**

(IFALLS) PM

---

**Job Notes**

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG PERFORMED PM AND USED OIL PURCHASED FROM NAPA

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 29038

USING DEPT NO:	507201	OPENED DATE:	03/01/2018 14:25:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/05/2018 08:42:21	METER 1 - M:	3327	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	03/05/2018 08:42:23	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	P	N	GARAGE	0.40	\$23.00	\$6.64	\$0.00	\$29.64

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.40 23.00 6.64 0.00 29.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11758845	03/02/2018 07:00:00	03/02/2018 07:24:00	0.40	\$23.00

**LABOR 23.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.49	1	\$3.49
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	2.40	1	\$2.40
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.38	2	\$0.75

**PARTS 6.64**

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 29038

---

**Work Order Notes**

(IFALLS) NAIL IN LEFT REAR TIRE

---

**Job Notes**

66-17-030 - PERFORM TIRE PATCH

(IFALLS) CS PATCHED LEFT REAR TIRE

---



# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 29753

USING DEPT NO:	507201	OPENED DATE:	05/10/2018 07:33:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/18/2018 07:44:52	METER 1 - M:	4569	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/18/2018 07:44:53	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$33.99	\$0.00	\$51.82

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.31 17.83 33.99 0.00 51.82**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/14/2018 06:00:00	05/14/2018 06:18:36	0.31	\$17.83
					<b>LABOR</b>	<b>17.83</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	4.59	6	\$27.54
					<b>PARTS</b>	<b>33.99</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 29753

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM BY EK/SH  
COOLANT -35'

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 31297

USING DEPT NO:	507201	OPENED DATE:	10/25/2018 15:07:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/05/2018 06:48:52	METER 1 - M:	7309	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/05/2018 06:48:56	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	4.64	\$336.40	\$0.00	\$0.00	\$336.40
17-01-004	RECALL BLOWER MOTOR	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$47.49	\$41.59	\$0.00	\$89.08

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>5.30</b>	<b>383.89</b>	<b>41.59</b>	<b>0.00</b>	<b>425.48</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-01-004	RECALL BLOWER MOTOR	11076422	6013637	0045707	\$0.00
<b>COMML</b>					<b>0.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	11915538	10/31/2018 11:15:51	10/31/2018 15:54:15	4.64	\$336.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2018 09:15:00	10/26/2018 09:44:09	0.49	\$35.22
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2018 09:05:45	10/26/2018 09:05:45	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/26/2018 09:04:51	10/26/2018 09:15:00	0.17	\$12.26
<b>LABOR</b>					<b>383.88</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.58	1	\$6.58
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
<b>PARTS</b>					<b>41.59</b>	

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 31297

---

**Work Order Notes**

(EKIMBREL) PM  
(LISAPATE) Toyota Recall possible bad blower motor fan hub

---

**Job Notes**

**16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT**

(LISAPATE) Taken to Toyota by RC

**17-01-004 - RECALL BLOWER MOTOR**

(LISAPATE) Toyota completed recall installed a new blower motor

**66-PM-PMA - PERFORM OIL CHANGE**

(RTUNAITI) PM by AG/SH  
Coolant -50'

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 33555

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 07/29/2019 09:01:35	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/31/2019 07:17:29	<b>METER 1 - M:</b> 10513 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/31/2019 07:17:30	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.79	\$56.99	\$47.75	\$0.00	\$104.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.12	\$8.46	\$13.59	\$0.00	\$22.05

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.90** **65.45** **61.34** **0.00** **126.79**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/29/2019 14:46:28	07/29/2019 15:09:32	0.38	\$27.87
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/29/2019 14:47:04	07/29/2019 15:11:10	0.40	\$29.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	07/29/2019 15:09:32	07/29/2019 15:16:32	0.12	\$8.46
					<b>LABOR</b>	<b>65.45</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.51	1	\$6.51
					<b>PARTS</b>	<b>61.34</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 33555

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by SH/AG  
Coolant -50'

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LISAPATE) Replaced cabin filter

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 35694

USING DEPT NO:	507201	OPENED DATE:	02/19/2020 09:10:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2020 13:48:08	METER 1 - M:	12701	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2020 14:45:18	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.12	\$8.56	\$0.00	\$0.00	\$8.56
09-15	ALIGN STEERING	DON	O	N	GARAGE	2.07	\$150.42	\$0.00	\$0.00	\$150.42
15-03-010	WARRANTY CLUSTER ASSY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-03	TRANSPORT INSTRUMENTS, GAUGES,	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.26	\$91.51	\$8.40	\$0.00	\$99.91
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.85	\$61.38	\$41.28	\$0.00	\$102.66
66-PM-PMC	PERFORM CABIN FILTER REPLACEMEI	DON	O	N	GARAGE	0.36	\$25.84	\$13.59	\$0.00	\$39.43

<b>JOB COUNT: 7</b>	<b>WORK ORDER TOTAL:</b>	<b>5.66</b>	<b>410.21</b>	<b>63.27</b>	<b>0.00</b>	<b>473.48</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-03-010	WARRANTY CLUSTER ASSY	11076422	6071738		\$0.00
				<b>COMML</b>	<b>0.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-03	TRANSPORT INSTRUMENTS, GAUGES, METERS	10208562	03/05/2020 07:00:00	03/05/2020 08:00:00	1.00	\$72.50
09-15	ALIGN STEERING	11310047	02/20/2020 08:42:10	02/20/2020 10:07:03	1.41	\$102.57
09-15	ALIGN STEERING	11310047	02/20/2020 07:44:11	02/20/2020 08:23:47	0.66	\$47.85
06-15	INSPECT STEERING	11901357	02/19/2020 13:48:19	02/19/2020 13:55:24	0.12	\$8.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	02/19/2020 10:38:02	02/19/2020 11:53:46	1.26	\$91.51
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/19/2020 09:42:22	02/19/2020 10:03:45	0.36	\$25.84
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/19/2020 09:27:09	02/19/2020 10:03:49	0.61	\$44.31
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2020 09:28:14	02/19/2020 09:42:22	0.24	\$17.08
					<b>LABOR</b>	<b>410.22</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.36	1	\$6.36

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	6	\$34.92
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	13.59	1	\$13.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	3.30	2	\$6.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.45	4	\$1.80
					<b>PARTS</b>	<b>63.27</b>



# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 35694

---

## Work Order Notes

(EKIMBREL) PM

### Job Notes

#### **06-15 - INSPECT STEERING**

(LISAPATE) SH/JW Checked front end no issues found

#### **09-15 - ALIGN STEERING**

(LISAPATE) EH Performed alignment

#### **15-03-010 - WARRANTY CLUSTER ASSY**

(LISAPATE) Tuscaloosa Toyota found an open circuit in cluster causing decelerating and speedometer to stop momentarily. Removed and installed new cluster under warranty

#### **16-03 - TRANSPORT INSTRUMENTS, GAUGES, METERS**

(LISAPATE) Truck taken to Toyota by EK

#### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Mount and balanced 2 Hankook pull offs (non inventory) installed on the front

#### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by SH/AG

#### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LISAPATE) Replaced cabin filter

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 36709

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 06/04/2020 15:17:35	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/05/2020 14:56:40	<b>METER 1 - M:</b> 12974 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/08/2020 08:20:01	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$30.31	\$0.00	\$0.00	\$30.31

**JOB COUNT: 1** **WORK ORDER TOTAL:** 0.42 30.31 0.00 0.00 30.31

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/05/2020 14:30:29	06/05/2020 14:55:34	0.42	\$30.31
					<b>LABOR</b>	<b>30.31</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	(7)	(\$40.74)
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	(1)	(\$6.48)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	7	\$40.74
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
					<b>PARTS</b>	<b>0.00</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 36709

---

**Work Order Notes**

(EKIMBREL) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(EKIMBREL) Did not change oil at this time. AG checked fluids, tire pressures, battery, and updated sticker. Coolant -35

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 37512

USING DEPT NO:	507201	OPENED DATE:	09/04/2020 07:12:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2020 11:09:54	METER 1 - M:	13534	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2020 12:41:46	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-78-044	REPAIR TOOLBOX ASSY	DON	O	N	GARAGE	0.25	\$18.41	\$0.00	\$0.00	\$18.41
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$41.69	\$0.00	\$0.00	\$41.69

**JOB COUNT: 2** **WORK ORDER TOTAL: 0.83 60.10 0.00 0.00 60.10**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-78-044	REPAIR TOOLBOX ASSY	11901357	09/04/2020 08:33:42	09/04/2020 08:48:56	0.25	\$18.41
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/04/2020 07:58:49	09/04/2020 08:33:19	0.58	\$41.69
					<b>LABOR</b>	<b>60.10</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 37512

---

**Work Order Notes**

(LISAPATE) PM/Check fluids-Tool box latch is inop

---

**Job Notes**

**24-78-044 - REPAIR TOOLBOX ASSY**

(LISAPATE) Adjusted linkage on toolbox latches, checked for proper operation all good. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) Vehicle has been driven 833 miles. Checked fluids and tire pressures, updated oil change sticker. AMG

---

# Work Order Charge Detail

**UNIT NO:** 242325      **2017 TOYOTA TACOMA**      **WORK ORDER NO:** 38681

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 12/16/2020 11:21:21	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/18/2020 11:34:52	<b>METER 1 - M:</b> 14326 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/08/2021 10:02:56	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA      2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.04	\$4.85	\$0.00	\$0.00	\$4.85

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.04**      **4.85**      **0.00**      **0.00**      **4.85**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-31	DIAGNOSE CHARGING SYSTEM	11170580	12/18/2020 10:49:27	12/18/2020 10:51:55	0.04	\$4.85
					<b>LABOR</b>	<b>4.85</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 38681

---

**Work Order Notes**

(LISAPATE) Check charging system for battery going dead due to LRV camera system

---

**Job Notes**

**35-31 - DIAGNOSE CHARGING SYSTEM**

(ABLACK) AB found fuse that powers the cameras was tapped into the fuel injector fuse. Removed fuse for the cameras and the dept is planning on us installing a toggle switch to cut the camera system on and off after first of the year.

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 38733

USING DEPT NO:	507201	OPENED DATE:	01/08/2021 15:17:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/13/2021 07:46:10	METER 1 - M:	14326	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/14/2021 11:08:29	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
19-52-007	WIRE/REWIRE CAMERA	DON	O	N	GARAGE	0.66	\$77.52	\$29.34	\$0.00	\$106.86

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.66</b>	<b>77.52</b>	<b>29.34</b>	<b>0.00</b>	<b>106.86</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
19-52-007	WIRE/REWIRE CAMERA	11170580	01/12/2021 11:50:24	01/12/2021 11:51:30	0.02	\$2.16
19-52-007	WIRE/REWIRE CAMERA	11170580	01/12/2021 08:08:13	01/12/2021 08:46:32	0.64	\$75.36
					<b>LABOR</b>	<b>77.52</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
19-52-007	WIRE/REWIRE CAMERA	WPS67702	HD SOLENOID CONTINUOUS DUTY	29.34	1	\$29.34
19-52-007	WIRE/REWIRE CAMERA	WPS67702	HD SOLENOID CONTINUOUS DUTY	29.34	(2)	(\$58.68)
19-52-007	WIRE/REWIRE CAMERA	WPS67702	HD SOLENOID CONTINUOUS DUTY	29.34	2	\$58.68
					<b>PARTS</b>	<b>29.34</b>



# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 38733

---

**Work Order Notes**

(RTUNAITI) Battery dead - Check for electrical draw

---

**Job Notes**

**19-52-007 - WIRE/REWIRE CAMERA**

(ABLACK) AB found camera system draining the truck battery. Installed a continuous duty solenoid in line with the camera systems power source.

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 38974

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 02/01/2021 09:08:38	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/19/2021 08:54:58	<b>METER 1 - M:</b> 14460 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/19/2021 14:20:43	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.60	\$188.54	\$115.49	\$0.00	\$304.03
03-53-003	REPLACE NEW CABIN FILTER	DON	O	N	GARAGE	0.02	\$2.62	\$15.74	\$0.00	\$18.36
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	2.56	\$301.59	\$0.00	\$0.00	\$301.59
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.20	\$23.60	\$0.00	\$0.00	\$23.60
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.28	\$32.88	\$0.00	\$0.00	\$32.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.91	\$106.86	\$44.37	\$0.00	\$151.23

<b>JOB COUNT: 6</b>	<b>WORK ORDER TOTAL:</b>	<b>5.56</b>	<b>656.09</b>	<b>175.60</b>	<b>0.00</b>	<b>831.69</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-53-003	REPLACE NEW CABIN FILTER	12052187	02/01/2021 15:01:44	02/01/2021 15:03:04	0.02	\$2.62
66-79-003	PERFORM SAFETY INSPECTION	12052187	02/01/2021 15:03:18	02/01/2021 15:20:01	0.28	\$32.88
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	02/01/2021 15:20:16	02/01/2021 15:21:46	0.03	\$2.95
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	12052187	02/01/2021 15:20:16	02/01/2021 15:21:46	(0.03)	(\$2.95)
35-31	DIAGNOSE CHARGING SYSTEM	11170580	02/04/2021 09:00:12	02/04/2021 10:39:32	1.66	\$195.36
35-31	DIAGNOSE CHARGING SYSTEM	11170580	02/17/2021 08:04:21	02/17/2021 08:58:22	0.90	\$106.23
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12052187	02/18/2021 07:00:00	02/18/2021 07:12:00	0.20	\$23.60
03-32-002	REPLACE NEW BATTERY	11170580	02/12/2021 14:30:00	02/12/2021 15:54:23	1.41	\$165.95
03-32-002	REPLACE NEW BATTERY	11170580	02/12/2021 14:03:31	02/12/2021 14:15:00	0.19	\$22.58
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/01/2021 14:07:10	02/01/2021 15:01:30	0.91	\$106.86
					<b>LABOR</b>	<b>656.08</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	6	\$37.89
03-53-003	REPLACE NEW CABIN FILTER	800038C	CABIN AIR FILTER REP 4871	15.74	1	\$15.74
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	01253	BATT TERM PROTECTOR, PAIR PK	1.94	1	\$1.94
					<b>PARTS</b>	<b>175.60</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 38974

---

## Work Order Notes

(LISAPATE) PM-Do annual safety inspection-Check for a draw battery is dead again from camera system

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(ABLACK) AB old battery tested bad. Installed a new battery. Rechecked ok.

### **03-53-003 - REPLACE NEW CABIN FILTER**

(JWRIGHT) Replaced cabin filter with new

### **31-17 - ROTATE TIRES, TUBES, LINERS & VALVES**

(LISAPATE)

### **35-31 - DIAGNOSE CHARGING SYSTEM**

(ABLACK) AB tested vehicle for a draw. Found no draw on vehicle. Let vehicle sit for several days and never had an issue cranking. Tested battery after it had sat for days and found the cold cranking amps were low. Installed a new battery . Rechecked ok.

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(LISAPATE) Rotated tires and adjusted air pressures. Brakes are 6mm thickness. JAW

### **66-79-003 - PERFORM SAFETY INSPECTION**

(JWRIGHT) Performed safety inspection. Found no issues. Brakes are 6mm thick. JAW

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 40086

USING DEPT NO:	507201	OPENED DATE:	06/02/2021 13:53:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/04/2021 07:48:38	METER 1 - M:	15317	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/04/2021 14:19:41	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.09	\$10.10	\$7.79	\$0.00	\$17.89

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>0.09</b>	<b>10.10</b>	<b>7.79</b>	<b>0.00</b>	<b>17.89</b>
---------------------	--------------------------	--	--	--	--	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11074414	06/02/2021 14:30:00	06/02/2021 14:35:08	0.09	\$10.10
66-17-030	PERFORM TIRE PATCH	11074414	06/02/2021 14:25:27	06/02/2021 14:25:27	0.00	\$0.00
					<b>LABOR</b>	<b>10.10</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.48	1	\$0.48
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	4.01	1	\$4.01
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.30	1	\$3.30
					<b>PARTS</b>	<b>7.79</b>

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 40086

---

**Work Order Notes**

(LISAPATE) Screw in LF tire

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(SHARBIN) Patched left front tire. SH

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 40359

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 07/06/2021 12:05:38	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/08/2021 10:43:30	<b>METER 1 - M:</b> 15574 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/09/2021 08:23:42	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA 2017 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.31	\$14.46	\$0.00	\$19.77
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.27	\$0.00	\$0.00	\$49.27
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$6.23	\$7.53	\$0.00	\$13.76

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.52</b>	<b>60.81</b>	<b>21.99</b>	<b>0.00</b>	<b>82.80</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/07/2021 07:59:03	07/07/2021 08:01:45	0.05	\$5.31
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	07/07/2021 07:55:41	07/07/2021 07:58:51	0.05	\$6.23
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/07/2021 07:30:21	07/07/2021 07:55:24	0.42	\$49.27
					<b>LABOR</b>	<b>60.81</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.13	1	\$7.13
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	7.53	1	\$7.53
					<b>PARTS</b>	<b>21.99</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 40359

---

## Work Order Notes

(CHANNELL) pm

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 15574 Vehicle has been 1114 miles oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

---



# Work Order Charge Detail

**UNIT NO:** 242325      **2017 TOYOTA TACOMA**      **WORK ORDER NO:** 41770

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 12/02/2021 11:14:45	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/09/2021 11:26:20	<b>METER 1 - M:</b> 16806 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/09/2021 13:18:57	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.75	\$15.18	\$0.00	\$19.93
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.08	\$9.11	\$0.00	\$0.00	\$9.11
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.43	\$50.45	\$0.00	\$0.00	\$50.45
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.76	\$90.20	\$328.45	\$0.00	\$418.65
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.90	\$105.71	\$62.56	\$0.00	\$168.27
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.07	\$10.10	\$0.00	\$12.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

**JOB COUNT: 7**      **WORK ORDER TOTAL:**      **2.22**      **262.29**      **416.29**      **2.00**      **680.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					<b>COMML</b> <b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	12/07/2021 10:49:35	12/07/2021 11:35:27	0.76	\$90.20
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	12/03/2021 13:36:41	12/03/2021 13:37:44	0.02	\$2.07
06-15	INSPECT STEERING	11074414	12/03/2021 13:31:54	12/03/2021 13:36:32	0.08	\$9.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/03/2021 10:25:41	12/03/2021 11:02:27	0.61	\$72.31
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/02/2021 15:14:50	12/02/2021 15:31:49	0.28	\$33.40
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/02/2021 15:12:10	12/02/2021 15:14:35	0.04	\$4.75
09-15	ALIGN STEERING	11310047	12/07/2021 13:20:38	12/07/2021 13:46:17	0.43	\$50.45
					<b>LABOR</b> <b>262.29</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.45	1	\$8.45
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	10.10	1	\$10.10
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	20.82	1	\$20.82
66-PM-PMA	PERFORM OIL CHANGE	VV324	TRANS FLUID QT	6.38	1	\$6.38
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.41	1	\$0.41
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.56	1	\$0.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.66	1	\$0.66
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.31	2	\$8.61
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	159.11	2	\$318.21
					<b>PARTS</b>	<b>416.29</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 41770

---

## Work Order Notes

(LISAPATE) PM-replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(AGUERRA) Replaced wipers. AMG

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected steering and brakes found no issues. SH

### **09-15 - ALIGN STEERING**

(EHOWELL) Checked alignment. No adjustments were necessary. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 2 tires. Put new tires on the front. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH Performed PM. Needs 2 front tires due to tread depth of 1/32 and 2/32.

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced cabin air filter. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 43128

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 05/04/2022 08:10:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/05/2022 11:09:51	<b>METER 1 - M:</b> 17791 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/05/2022 12:43:39	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$8.98	\$15.18	\$0.00	\$24.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.05	\$6.46	\$0.00	\$0.00	\$6.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.13</b>	<b>15.44</b>	<b>15.18</b>	<b>2.00</b>	<b>32.62</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 10:12:47	05/04/2022 10:13:32	0.01	\$1.48
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/04/2022 10:08:01	05/04/2022 10:12:35	0.08	\$8.98
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 09:30:00	05/04/2022 09:32:32	0.04	\$4.98
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 09:25:20	05/04/2022 09:25:20	0.00	\$0.00
<b>LABOR</b>					<b>15.44</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
<b>PARTS</b>					<b>15.18</b>	

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 43128

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Unit has been 985 miles. Checked fluids and tires. Coolant -34°. JAW  
MILEAGE-17791

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 45336

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 11/21/2022 12:12:13	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/23/2022 13:55:22	<b>METER 1 - M:</b> 19280 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/28/2022 11:02:05	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$113.55	\$0.00	\$131.25
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.51	\$60.51	\$0.00	\$0.00	\$60.51
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.52	\$42.27	\$0.00	\$50.79
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.69	\$14.58	\$0.00	\$17.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT:</b> 5	<b>WORK ORDER TOTAL:</b>	<b>0.76</b>	<b>89.42</b>	<b>170.40</b>	<b>5.00</b>	<b>264.82</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11901357	11/28/2022 07:00:00	11/28/2022 07:09:00	0.15	\$17.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	11/23/2022 13:37:47	11/23/2022 13:39:09	0.02	\$2.69
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/23/2022 13:33:17	11/23/2022 13:37:37	0.07	\$8.52
06-32-002	INSPECT BATTERY	11901357	11/23/2022 09:32:39	11/23/2022 10:03:25	0.51	\$60.51
					<b>LABOR</b>	<b>89.42</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	14.58	1	\$14.58
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.73	1	\$5.73
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
					<b>PARTS</b>	<b>170.40</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 45336

---

## Work Order Notes

(CWIGLEY) Check battery, driver said they've had to jump it off a few times.

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(LISAPATE) Replaced battery AG

### **06-32-002 - INSPECT BATTERY**

(AGUERRA) Tested battery, needs replacing. AMG

### **66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/AMG  
MILEAGE-19280

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(JWRIGHT) Replaced cabin filter. JAW

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 46678

USING DEPT NO:	507201	OPENED DATE:	04/11/2023 11:00:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/12/2023 09:11:47	METER 1 - M:	20037	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2023 10:30:53	IN-SERVICE DATE:	06/13/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN2HX089963	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.08	\$16.55	\$0.00	\$19.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$26.09	\$0.00	\$0.00	\$26.09
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.02	\$2.03	\$0.00	\$0.00	\$2.03

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.26</b>	<b>31.20</b>	<b>16.55</b>	<b>5.00</b>	<b>52.75</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	04/11/2023 15:37:58	04/11/2023 15:39:00	0.02	\$2.03
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/11/2023 15:24:13	04/11/2023 15:37:29	0.22	\$26.09
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/11/2023 15:22:26	04/11/2023 15:24:00	0.03	\$3.08
					<b>LABOR 31.20</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.22	1	\$8.22
					<b>PARTS 16.55</b>	



# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 46678

---

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) CW Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 757 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Wash bay is down. SH

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 50212

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 03/22/2024 11:38:05	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/29/2024 09:27:03	<b>METER 1 - M:</b> 22555 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/29/2024 09:53:23	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	5	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.32	\$37.69	\$0.00	\$0.00	\$37.69
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	1.39	\$164.32	\$360.90	\$0.00	\$525.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.63	\$52.07	\$0.00	\$103.70
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.28	\$11.79	\$0.00	\$13.07
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.23	\$27.14	\$0.00	\$0.00	\$27.14

**JOB COUNT: 7** **WORK ORDER TOTAL:** **2.64** **311.56** **424.76** **5.00** **741.32**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	12395904	03/29/2024 07:00:00	03/29/2024 07:15:00	0.25	\$29.50
06-15	INSPECT STEERING	12395904	03/29/2024 07:00:00	03/29/2024 07:15:00	(0.25)	(\$29.50)
06-15	INSPECT STEERING	12395904	03/29/2024 07:00:00	03/29/2024 07:15:00	0.25	\$29.50
66-17-013	PERFORM ALIGNMENT	12052187	03/26/2024 07:25:00	03/26/2024 07:44:10	0.32	\$37.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	03/22/2024 14:56:52	03/22/2024 14:57:31	0.01	\$1.28
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/22/2024 14:30:00	03/22/2024 14:56:15	0.44	\$51.63
66-PM-PMA	PERFORM OIL CHANGE	12395904	03/22/2024 14:27:02	03/22/2024 14:27:02	0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	03/25/2024 07:17:44	03/25/2024 08:41:17	1.39	\$164.32
WA-00	WASH COMPLETE VEHICLE	12395904	03/25/2024 08:42:42	03/25/2024 08:56:30	0.23	\$27.14
					<b>LABOR</b>	<b>311.56</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
-----------------	------------------------	-----------------	--------------------	-------------------	-----------------	-------------------

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.33	1	\$6.33
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.52	1	\$4.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.80	2	\$9.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	1.22	1	\$1.22
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	2	\$0.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	173.63	2	\$347.25
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	1.34	1	\$1.34
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
					<b>PARTS</b>	<b>424.76</b>

# Work Order Charge Detail

UNIT NO: 242325 2017 TOYOTA TACOMA

WORK ORDER NO: 50212

---

## Work Order Notes

(LRUSHING) PM AND WASH

---

## Job Notes

### **06-15 - INSPECT STEERING**

(LISAPATE) FC checked front end  
(IFALLS) Visit Reason Changed On 3/29/2024 9:53 AM By IFALLS

### **66-17-013 - PERFORM ALIGNMENT**

(GARAGE) Checked alignment and all is within spec. Test drove and found no issues. No adjustments made. JAW

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(FCONTRER) Replaced 2 new tires moonted and balanced 58107 - 1 - 58103 - 1 - 58100 - 1 - 58106 - 1 - 21103 - 2 fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) perform oil changes fc

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced cabin filter FC

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(FCONTRER) Wash fc

---

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 51662

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 07/31/2024 14:22:58	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/14/2024 08:07:15	<b>METER 1 - M:</b> 22714 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/14/2024 11:21:07	<b>IN-SERVICE DATE:</b> 06/13/2017
<b>TECH SPEC NO:</b> 17TOYTACOMA	2017 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN2HX089963

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.40	\$2.40
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.10	\$0.30	\$0.00	\$2.40

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.02** **2.10** **0.30** **2.40** **4.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.40
<b>COMML</b>					<b>2.40</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/08/2024 08:34:27	08/08/2024 08:35:31	0.02	\$2.10
<b>LABOR</b>					<b>2.10</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	2	\$0.30
<b>PARTS</b>					<b>0.30</b>	

# Work Order Charge Detail

**UNIT NO:** 242325 2017 TOYOTA TACOMA

**WORK ORDER NO:** 51662

---

**Work Order Notes**

(LRUSHING) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) Removed wordmarks and tag. CW/RC

(GARAGE) Removed cameras and strobe lights. JAW

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Thu Aug 15 2024 14:31:24 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '5TFRX5GN2HX089963') //Q=