

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35012

USING DEPT NO: 750101	OPENED DATE: 11/27/2019 10:52:50	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/02/2019 14:43:29	METER 1 - M: 53 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/02/2019 14:43:30	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	11/27/2019 10:53:28	11/27/2019 11:23:28	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35012

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35660

USING DEPT NO:	750101	OPENED DATE:	02/14/2020 08:33:26	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2020 14:57:31	METER 1 - M:	3948	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2020 14:57:33	IN-SERVICE DATE:	11/27/2019		
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH3KS060456		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$23.14	\$42.04	\$0.00	\$65.18

JOB COUNT: 1 WORK ORDER TOTAL: 0.32 23.14 42.04 0.00 65.18

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/14/2020 09:42:55	02/14/2020 10:02:04	0.32	\$23.14
					LABOR	23.14

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.82	5	\$29.10
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
					PARTS	42.04

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 35660

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) RC/SH. Coolant -10

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36903

USING DEPT NO:	750101	OPENED DATE:	06/22/2020 09:56:12	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	06/22/2020 13:41:42	METER 1 - M:	5883	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/22/2020 15:21:25	IN-SERVICE DATE:	11/27/2019		
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH3KS060456		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$24.85	\$35.68	\$0.00	\$60.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.34	24.85	35.68	0.00	60.53
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/22/2020 10:38:07	06/22/2020 10:58:41	0.34	\$24.85
					LABOR	24.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	5	\$29.18
					PARTS	35.68

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 36903

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) performed pm service. (JAW/SH) coolant -34°

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38291

USING DEPT NO: 750101	OPENED DATE: 11/05/2020 09:21:34	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/05/2020 10:49:20	METER 1 - M: 5952 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/06/2020 08:32:59	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$2.51	\$0.00	\$14.31

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.10** **11.80** **2.51** **0.00** **14.31**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	10321076	11/06/2020 07:00:00	11/06/2020 07:06:00	0.10	\$11.80
					LABOR	11.80

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.51	1	\$2.51
					PARTS	2.51

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38291

Work Order Notes

(LISAPATE) Per Donald key fob battery is inop

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(LISAPATE) Installed new key fob battery

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38600

USING DEPT NO: 750101	OPENED DATE: 12/09/2020 08:59:54	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/10/2020 09:51:24	METER 1 - M: 8387 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/11/2020 09:08:12	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.11	\$13.08	\$2.51	\$0.00	\$15.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.96	\$113.31	\$37.78	\$0.00	\$151.09

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.07** **126.39** **40.29** **0.00** **166.68**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	11074414	12/09/2020 09:58:22	12/09/2020 10:05:01	0.11	\$13.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/09/2020 09:30:00	12/09/2020 09:58:08	0.47	\$55.33
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/09/2020 09:07:31	12/09/2020 09:15:00	0.12	\$14.72
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/09/2020 09:07:32	12/09/2020 09:29:32	0.37	\$43.27
					LABOR	126.40

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.51	1	\$2.51
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.50	1	\$6.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.26	5	\$31.28
					PARTS	40.29

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 38600

Work Order Notes

(LISAPATE) PM-Key fob barely working

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

(SHARBIN) Replaced key fob battery. Fob is working properly. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 8387. AMG/SH Performed PM. JW Vacuumed SH Washed and filled with gas.

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39203

USING DEPT NO: 750101	OPENED DATE: 02/25/2021 08:23:10	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/25/2021 13:38:17	METER 1 - M: 13522 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/01/2021 15:34:49	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.42	\$167.17	\$28.64	\$0.00	\$195.81	
JOB COUNT: 1						WORK ORDER TOTAL:	1.42	167.17	28.64	0.00	195.81

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/25/2021 08:29:50	02/25/2021 09:15:00	0.75	\$88.83
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/25/2021 08:30:00	02/25/2021 08:51:03	0.35	\$41.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/25/2021 08:28:55	02/25/2021 08:47:42	0.31	\$36.94
					LABOR	167.17

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	28.64

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39203

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 13522 Completed PM topside, Josh assisted. Scott was bottom side. Completed checklist, vacuumed, washed and fueled up vehicle. AMG JW SH

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39844

USING DEPT NO: 750101	OPENED DATE: 04/30/2021 09:07:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/04/2021 13:37:27	METER 1 - M: 17508 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/06/2021 10:10:17	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.51	\$177.89	\$30.07	\$0.00	\$207.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.05	\$5.70	\$12.39	\$0.00	\$18.09

JOB COUNT: 2 **WORK ORDER TOTAL:** **1.56** **183.59** **42.46** **0.00** **226.05**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/30/2021 10:28:18	04/30/2021 10:31:12	0.05	\$5.70
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/30/2021 10:05:33	04/30/2021 10:26:39	0.35	\$41.50
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/30/2021 09:15:13	04/30/2021 10:08:31	0.89	\$104.82
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/30/2021 09:30:00	04/30/2021 09:41:34	0.19	\$22.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/30/2021 09:10:31	04/30/2021 09:15:00	0.07	\$8.82
					LABOR	183.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	7.64	1	\$7.64
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	12.39	1	\$12.39
					PARTS	42.46

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 39844

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 17508. SH/AMG Performed PM. SH Washed and vacuumed was full of gas.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced cabin air filter. SH

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40311

USING DEPT NO: 750101	OPENED DATE: 07/01/2021 08:13:08	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 07/02/2021 11:01:17	METER 1 - M: 21960 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 07/06/2021 08:34:34	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.21	\$142.65	\$35.93	\$0.00	\$178.58

JOB COUNT: 1 **WORK ORDER TOTAL:** **1.21** **142.65** **35.93** **0.00** **178.58**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/01/2021 08:20:17	07/01/2021 09:15:00	0.91	\$107.61
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/01/2021 08:23:05	07/01/2021 08:40:54	0.30	\$35.04
					LABOR	142.65

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.96	1	\$6.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
					PARTS	35.93

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40311

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE21960

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40847

USING DEPT NO: 750101	OPENED DATE: 08/25/2021 14:58:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/27/2021 07:40:56	METER 1 - M: 25406 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/27/2021 14:36:14	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.14	\$17.04	\$27.04	\$0.00	\$44.08
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.55	\$64.74	\$0.00	\$0.00	\$64.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$39.50	\$34.76	\$0.00	\$74.26
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.03	121.28	61.80	2.00	185.08
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	08/25/2021 15:18:46	08/25/2021 15:51:41	0.55	\$64.74
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/25/2021 15:06:10	08/25/2021 15:23:22	0.29	\$33.83
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/25/2021 15:19:14	08/25/2021 15:22:07	0.05	\$5.67
03-51-038	REPLACE NEW WIPER BLADES	12052187	08/25/2021 15:10:21	08/25/2021 15:19:01	0.14	\$17.04
					LABOR	121.28

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.14	1	\$9.14
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.70	1	\$5.70
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
					PARTS	61.80

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 40847

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Installed new wiper blades. JAW,SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires inspected brakes washed and filled with gas. SH

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Tires need rotating. Coolant -34°. JAW,SH/AMG
MILEAGE-25406

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41364

USING DEPT NO: 750101	OPENED DATE: 10/19/2021 08:36:49	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/20/2021 11:36:26	METER 1 - M: 29426 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/20/2021 12:54:57	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.04	\$4.43	\$27.10	\$0.00	\$31.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.72	\$84.40	\$42.21	\$0.00	\$126.61
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.75	88.83	69.31	2.00	160.14
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/19/2021 09:42:58	10/19/2021 09:45:13	0.04	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2021 09:30:00	10/19/2021 09:41:19	0.19	\$22.26
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2021 08:43:24	10/19/2021 09:15:00	0.53	\$62.15
LABOR					88.84	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5066517	WSWF RAIN-X -20DEG DEICER GAL	7.89	1	\$7.89
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
PARTS					69.31	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 41364

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 29426. SH Performed PM washed and vacuumed.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42056

USING DEPT NO: 750101	OPENED DATE: 01/12/2022 08:28:32	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/13/2022 10:25:55	METER 1 - M: 34051 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/14/2022 08:11:03	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.65	\$27.75	\$0.00	\$91.40
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.54** **63.65** **27.75** **2.00** **93.40**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/12/2022 09:20:49	01/12/2022 09:20:49	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/12/2022 08:35:22	01/12/2022 09:07:44	0.54	\$63.65
LABOR					63.65	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
PARTS					27.75	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42056

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42149

USING DEPT NO: 750101	OPENED DATE: 01/24/2022 08:54:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/25/2022 11:43:46	METER 1 - M: 34051 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/25/2022 14:21:51	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	O	N	GARAGE	0.10	\$11.80	\$2.73	\$0.00	\$14.53
16-51	TRANSPORT GENERAL ACCESSORIES	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PR-51-044	PROGRAM KEY FOB/REMOTE	DON	O	N	GARAGE	0.00	\$0.00	\$240.69	\$92.00	\$332.69

JOB COUNT: 4	WORK ORDER TOTAL:	0.60	70.80	243.42	94.00	408.22
---------------------	--------------------------	-------------	--------------	---------------	--------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
PR-51-044	PROGRAM KEY FOB/REMOTE	11076422	6146502		\$92.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					94.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-042	REPLACE NEW KEY FOB BATTERY	11237753	01/25/2022 07:00:00	01/25/2022 07:06:00	0.10	\$11.80
16-51	TRANSPORT GENERAL ACCESSORIES	11915538	01/25/2022 07:00:00	01/25/2022 07:30:00	0.50	\$59.00
LABOR					70.80	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PR-51-044	PROGRAM KEY FOB/REMOTE	890700R121	TOYOTA KEY AND TRANSMITTER	240.69	1	\$240.69
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	2.73	1	\$2.73
PARTS					243.42	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42149

Work Order Notes

(LISAPATE) Take to Toyota to program new key driver requested

Job Notes

03-51-042 - REPLACE NEW KEY FOB BATTERY

16-51 - TRANSPORT GENERAL ACCESSORIES

CH-SP - CHARGE Shop Supplies

PR-51-044 - PROGRAM KEY FOB/REMOTE

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42687

USING DEPT NO: 750101	OPENED DATE: 03/24/2022 08:24:35	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 03/25/2022 15:42:51	METER 1 - M: 36465 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 03/29/2022 15:11:38	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$27.10	\$0.00	\$31.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$35.04	\$0.00	\$73.98
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.36	42.97	62.14	2.00	107.11
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2022 08:51:47	03/24/2022 08:52:16	(0.01)	(\$0.95)
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2022 08:51:47	03/24/2022 08:52:16	0.01	\$0.95
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/24/2022 08:51:47	03/24/2022 09:11:35	0.33	\$38.94
03-51-038	REPLACE NEW WIPER BLADES	12052187	03/24/2022 08:49:36	03/24/2022 08:51:39	0.03	\$4.03
LABOR					42.97	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.05	1	\$6.05
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
PARTS					62.14	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 42687

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. RC,JAW/AMB
MILEAGE-36465

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43309

USING DEPT NO: 750101	OPENED DATE: 05/19/2022 09:18:24	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/20/2022 14:50:43	METER 1 - M: 43939 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/23/2022 08:09:40	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$0.59	\$27.10	\$0.00	\$27.69
03-PM-001	REPLACE NEW AIR FILTER	DON	P	N	GARAGE	0.30	\$35.40	\$0.00	\$0.00	\$35.40
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	P	N	GARAGE	0.30	\$35.40	\$29.30	\$0.00	\$64.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$93.88	\$63.01	\$0.00	\$156.89
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.40	165.27	119.41	2.00	286.68
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11074414	05/20/2022 07:00:00	05/20/2022 07:18:00	0.30	\$35.40
03-PM-001	REPLACE NEW AIR FILTER	11074414	05/20/2022 07:18:00	05/20/2022 07:36:00	0.30	\$35.40
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/19/2022 10:02:33	05/19/2022 10:02:51	0.01	\$0.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/19/2022 09:30:00	05/19/2022 10:01:47	0.53	\$62.51
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/19/2022 09:26:03	05/19/2022 09:26:03	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2022 09:30:00	05/19/2022 09:45:57	0.27	\$31.37
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/19/2022 09:28:51	05/19/2022 09:28:51	0.00	\$0.00
					LABOR	165.27

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49430	AIR FILTER	35.19	1	\$35.19
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.20	1	\$9.20
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	29.30	1	\$29.30

Work Order Charge Detail

The University of Alabama

Report Printed: 09/25/2024 10:14:14 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.39	1	\$5.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	119.41

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 43309

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

03-PM-001 - REPLACE NEW AIR FILTER

(LISAPATE) Replaced air filter

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/SH
MILEAGE-43939

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44391

USING DEPT NO:	750101	OPENED DATE:	08/19/2022 08:24:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2022 14:30:35	METER 1 - M:	49110	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2022 09:59:36	IN-SERVICE DATE:	11/27/2019	
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH3KS060456	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-78-043	INSPECT REAR BUMPER GUARDS	DON	N	N	GARAGE	0.23	\$27.53	\$0.00	\$0.00	\$27.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.71	\$41.35	\$0.00	\$70.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.48	56.24	41.35	5.00	102.59
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-78-043	INSPECT REAR BUMPER GUARDS	11901357	08/19/2022 13:58:50	08/19/2022 14:12:50	0.23	\$27.53
06-78-043	INSPECT REAR BUMPER GUARDS	11901357	08/19/2022 13:58:50	08/19/2022 14:12:50	(0.23)	(\$27.53)
06-78-043	INSPECT REAR BUMPER GUARDS	11901357	08/19/2022 13:58:50	08/19/2022 14:12:50	0.23	\$27.53
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/19/2022 13:21:49	08/19/2022 13:36:25	0.24	\$28.71
LABOR					56.24	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.26	1	\$7.26
PARTS					41.35	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44391

Work Order Notes

(CWIGLEY) PM/ Inspect rear bumper panel.

Job Notes

06-78-043 - INSPECT REAR BUMPER GUARDS

(AGUERRA) Inspected rear lower bumper panel. Found right mounting bracket bent. Straightened bracket and installed a new non inventory clip. AMG
(AJONES) Visit Reason Changed On 8/31/2022 8:20 AM By AJONES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 49110 Completed PM top and bottom side. AMG/AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44998

USING DEPT NO: 750101	OPENED DATE: 10/17/2022 09:48:04	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/18/2022 14:29:37	METER 1 - M: 54383 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/18/2022 15:39:40	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.31	\$36.97	\$0.00	\$0.00	\$36.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.61	\$71.52	\$42.18	\$0.00	\$113.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.92	108.49	42.18	5.00	155.67
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	10/17/2022 11:28:14	10/17/2022 11:47:02	0.31	\$36.97
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/17/2022 10:51:13	10/17/2022 10:52:32	0.02	\$2.59
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/17/2022 10:34:56	10/17/2022 10:50:59	0.27	\$31.57
66-PM-PMA	PERFORM OIL CHANGE	12052187	10/17/2022 10:31:44	10/17/2022 10:50:44	0.32	\$37.37
LABOR					108.50	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.45	1	\$5.45
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
PARTS					42.18	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 44998

Work Order Notes

(LISAPATE) PM-Rotate tires and inspect brakes

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 54383 Completed PM topside, Josh was bottomsides. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45364

USING DEPT NO: 750101	OPENED DATE: 11/28/2022 08:29:26	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/29/2022 13:55:31	METER 1 - M: 58476 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 11/30/2022 08:14:33	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.78	\$32.73	\$0.00	\$43.51
24-40-440	REPAIR OIL CRANKCASE FILTER HOUS	DON	O	N	GARAGE	0.11	\$13.34	\$43.68	\$0.00	\$57.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$34.84	\$42.03	\$0.00	\$76.87
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.50	58.96	118.44	5.00	182.40
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-40-440	REPAIR OIL CRANKCASE FILTER HOUSING	11074414	11/28/2022 11:25:17	11/28/2022 11:32:04	0.11	\$13.34
66-PM-PMA	PERFORM OIL CHANGE	12201267	11/28/2022 10:04:12	11/28/2022 10:21:55	0.30	\$34.84
03-51-038	REPLACE NEW WIPER BLADES	12201267	11/28/2022 09:58:28	11/28/2022 10:03:57	0.09	\$10.78
					LABOR	58.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
03-51-038	REPLACE NEW WIPER BLADES	12A	12" WIPER BLADE	9.47	1	\$9.47
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
03-51-038	REPLACE NEW WIPER BLADES	19190	19" WIPERS	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
24-40-440	REPAIR OIL CRANKCASE FILTER HOUSING	CAP5608P	OIL HOUSING CAP	43.68	1	\$43.68
					PARTS	118.44

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 45364

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) replaced wipers-GRC

24-40-440 - REPAIR OIL CRANKCASE FILTER HOUSING

(SHARBIN) Oil filter housing cap broke when JW was removing it. Installed a new oil filter housing cap and rechecked for leaks. All good. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) done pm- changed oil and oil filter-GRC/JW, checked fluids, tires and tire pressure.

Miles- 58,476

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46031

USING DEPT NO: 750101	OPENED DATE: 02/02/2023 08:50:59	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/03/2023 11:38:36	METER 1 - M: 58476 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/06/2023 10:24:47	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR 2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.51	\$60.25	\$0.00	\$0.00	\$60.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.09	\$10.42	\$49.35	\$0.00	\$59.77
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.39	\$45.95	\$13.17	\$0.00	\$59.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.99	116.62	62.52	5.00	184.14
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	02/02/2023 13:37:58	02/02/2023 14:01:20	0.39	\$45.95
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/02/2023 13:05:08	02/02/2023 13:35:46	0.51	\$60.25
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/02/2023 12:30:55	02/02/2023 12:36:13	0.09	\$10.42
					LABOR	116.62

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	13.17	1	\$13.17
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.04	1	\$11.04
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
					PARTS	62.52

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46031

Work Order Notes

(EHANNAH) pm- replace wipers - perform safety inspections.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) cancel

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed a safety inspection. Found no issues at this time. SH
Front pads are at 6MM thickness
Rear pads are at 8 MM thickness

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/JAW
MILEAGE-60730

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46711

USING DEPT NO:	750101	OPENED DATE:	04/13/2023 09:36:12	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/19/2023 15:28:40	METER 1 - M:	65901	METER 2 - N:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/20/2023 07:46:43	IN-SERVICE DATE:	11/27/2019		
TECH SPEC NO:	19TOYHIGHLNDR	2019 Toyota Highlander		UNIT SERIAL NO:	5TDZARFH3KS060456		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	V	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$27.80	\$48.30	\$0.00	\$76.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.18	\$21.57	\$0.00	\$0.00	\$21.57

JOB COUNT: 4	WORK ORDER TOTAL:	0.42	49.37	48.30	62.50	160.17
---------------------	--------------------------	-------------	--------------	--------------	--------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	2107764		\$57.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					62.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	04/13/2023 13:26:47	04/13/2023 13:37:45	0.18	\$21.57
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/13/2023 13:05:19	04/13/2023 13:19:27	0.24	\$27.80
LABOR					49.37	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	5	\$31.28
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.70	1	\$10.70
PARTS					48.30	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 46711

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) can

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr repaired ding in the windshield. PD by CC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 65,901

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 48008

USING DEPT NO: 750101	OPENED DATE: 08/28/2023 11:32:15	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/31/2023 10:15:15	METER 1 - M: 68769 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/11/2023 15:19:06	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-51-044	REPAIR KEY FOB/REMOTE	DON	5	N	GARAGE	0.39	\$45.76	\$0.00	\$0.00	\$45.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.96	\$79.03	\$0.00	\$90.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.49	\$57.79	\$0.00	\$0.00	\$57.79

JOB COUNT: 4	WORK ORDER TOTAL:	0.98	115.51	79.03	5.00	199.54
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	12201267	08/28/2023 13:19:19	08/28/2023 13:48:42	0.49	\$57.79
24-51-044	REPAIR KEY FOB/REMOTE	11074414	08/28/2023 13:01:57	08/28/2023 13:25:13	0.39	\$45.76
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/28/2023 13:00:00	08/28/2023 13:06:05	0.10	\$11.96
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/28/2023 12:51:07	08/28/2023 12:51:07	0.00	\$0.00
					LABOR	115.51

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.00	1	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	PA6116F	DODGE DURANGO AIR FILTER	30.92	1	\$30.92
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
					PARTS	79.03

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 48008

Work Order Notes

(LRUSHING) pm-wash

Job Notes

24-51-044 - REPAIR KEY FOB/REMOTE

(LRUSHING) repair key fob

(SHARBIN) Installed a new key fob battery this did not fix the problem key fob is bad. Per LP we gave them our extra key fob and kept the bad one as our spare key. SH

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Changed oil and oil filter, checked fluids, changed air filter, cabin filter good, tires and tire pressure.

Miles, 68,769

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-FC

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49448

USING DEPT NO: 750101	OPENED DATE: 01/11/2024 09:13:09	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/17/2024 10:11:29	METER 1 - M: 69284 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/18/2024 08:04:05	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.70	\$0.00	\$0.00	\$11.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.10	11.70	0.00	5.00	16.70
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/11/2024 14:30:00	01/11/2024 14:35:57	0.10	\$11.70
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/11/2024 14:20:02	01/11/2024 14:20:02	0.00	\$0.00
LABOR					11.70	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 49448

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51204

USING DEPT NO: 750101	OPENED DATE: 06/14/2024 10:45:33	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/14/2024 13:35:03	METER 1 - M: 71439 METER 2 - N: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/14/2024 14:39:25	IN-SERVICE DATE: 11/27/2019
TECH SPEC NO: 19TOYHIGHLNDR	2019 Toyota Highlander	UNIT SERIAL NO: 5TDZARFH3KS060456

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.51	\$46.46	\$0.00	\$47.97
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.31	\$0.00	\$0.00	\$1.31

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.82	46.46	5.00	54.28
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/14/2024 13:21:26	06/14/2024 13:22:06	0.01	\$1.31
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/14/2024 13:20:40	06/14/2024 13:21:26	0.01	\$1.51
LABOR					2.82	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	5	\$34.88
PARTS					46.46	

Work Order Charge Detail

UNIT NO: 243575 2019 TOYOTA HIGHLANDER

WORK ORDER NO: 51204

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Wash bay occupied filled with gas. SH

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Sep 25 2024 10:14:14 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243575') //Q=