

Work Order Charge Detail

UNIT NO: 243616 **2020 TOYOTA TACOMA** **WORK ORDER NO:** 35205

USING DEPT NO:	507203	OPENED DATE:	12/16/2019 13:59:53	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2019 06:51:49	METER 1 - M:	63	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2019 06:51:50	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.50** **36.25** **0.00** **0.00** **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	12052187	12/16/2019 14:00:47	12/16/2019 14:30:47	0.50	\$36.25
					LABOR	36.25

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 35205

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) JW performed PDI

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 35408

USING DEPT NO: 507203	OPENED DATE: 01/15/2020 09:55:23	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 01/31/2020 09:05:08	METER 1 - M: 196 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 01/31/2020 09:05:10	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>	
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	11.85	\$858.96	\$649.55	\$0.00	\$1,508.51	
JOB COUNT: 1						WORK ORDER TOTAL:	11.85	858.96	649.55	0.00	1,508.51

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/24/2020 13:09:02	01/24/2020 13:53:00	0.73	\$53.13
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/27/2020 06:06:58	01/27/2020 09:15:00	3.13	\$227.21
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/27/2020 09:30:00	01/27/2020 11:56:42	2.45	\$177.26
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/27/2020 13:01:21	01/27/2020 14:15:00	1.23	\$88.99
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/27/2020 14:30:00	01/27/2020 15:01:13	0.52	\$37.72
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11213180	01/24/2020 08:09:09	01/24/2020 11:56:27	3.79	\$274.65
					LABOR	858.96

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	HSD524	1/4 DRILL BIT	4.02	(1)	(\$4.02)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	7709228	CABLE TIE 8 IN 100 PC BLK	7.98	2	\$15.96
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	HSD524	1/4 DRILL BIT	4.02	1	\$4.02
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	6.71	1	\$6.71
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.57	1	\$0.57
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	2.24	1	\$2.24
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC5140A	1/4 CONVOLUTED TUBING 50FT	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81184S	PRIMARY WIRE 18 GA GREEN 100'	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81183S	PRIMARY WIRE 18 GA BLK 100'	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC81181S	PRIMARY WIRE 18 GA RED 100'	15.44	1	\$15.44
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC2260GT	16-14 GA BUTT CONNECTOR	25.01	1	\$25.01
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	121.65	2	\$243.30
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	147.00	2	\$294.00
					PARTS	649.55

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 35408

Work Order Notes

(LISAPATE) Install strobe lights front and rear per Charley

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(LISAPATE) Wired and installed front and rear strobe light package. Rechecked all ok

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 35663

USING DEPT NO:	507203	OPENED DATE:	02/14/2020 08:59:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2020 14:52:09	METER 1 - M:	255	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2020 14:52:12	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-51-062	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	1.00	\$72.50	\$943.95	\$0.00	\$1,016.45

JOB COUNT: 1	WORK ORDER TOTAL:					1.00	72.50	943.95	0.00	1,016.45
---------------------	--------------------------	--	--	--	--	-------------	--------------	---------------	-------------	-----------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-062	INSTALL TOOLBOX ASSY	10321076	02/14/2020 15:26:00	02/14/2020 15:56:00	0.50	\$36.25
14-51-062	INSTALL TOOLBOX ASSY	11915538	02/14/2020 10:26:24	02/14/2020 10:56:24	0.50	\$36.25
					LABOR	72.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-51-062	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	1348.50	1	\$1,348.50
14-51-062	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	1348.50	(1)	(\$1,348.50)
14-51-062	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	943.95	1	\$943.95
					PARTS	943.95

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 35663

Work Order Notes

(EKIMBREL) Install toolbox

Job Notes

14-51-062 - INSTALL TOOLBOX ASSY

(EKIMBREL) RC/MT installed toolbox

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 36166

USING DEPT NO:	507203	OPENED DATE:	04/17/2020 10:54:18	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	04/20/2020 13:16:26	METER 1 - M:	267	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/20/2020 14:15:59	IN-SERVICE DATE:	12/16/2019		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$43.02	\$53.77	\$0.00	\$96.79

JOB COUNT: 1 WORK ORDER TOTAL: 0.59 43.02 53.77 0.00 96.79

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2020 09:30:00	04/20/2020 09:37:36	0.13	\$9.18
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2020 08:47:00	04/20/2020 09:15:00	0.47	\$33.83
					LABOR	43.01

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.44	1	\$6.44
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	7	\$40.85
					PARTS	53.77

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 36166

Work Order Notes

(IFALLS) First pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) AG performed pm

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 37743

USING DEPT NO: 507203	OPENED DATE: 09/24/2020 13:23:02	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 09/24/2020 14:45:12	METER 1 - M: 2923 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 09/25/2020 09:07:02	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$23.02	\$47.33	\$0.00	\$70.35

JOB COUNT: 1 **WORK ORDER TOTAL:** **0.32** **23.02** **47.33** **0.00** **70.35**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/24/2020 14:15:32	09/24/2020 14:15:32	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/24/2020 14:15:00	09/24/2020 14:27:48	0.21	\$15.47
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/24/2020 13:58:06	09/24/2020 14:00:00	0.03	\$2.30
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/24/2020 13:40:04	09/24/2020 13:44:25	0.07	\$5.26
					LABOR	23.03

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	7	\$40.85
					PARTS	47.33

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 37743

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 39117

USING DEPT NO: 507203	OPENED DATE: 02/17/2021 13:20:17	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 02/19/2021 15:42:25	METER 1 - M: 3711 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 02/22/2021 11:26:28	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma		UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.10	\$11.80	\$12.71	\$0.00	\$24.51
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.70	\$82.60	\$0.00	\$0.00	\$82.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.68	\$0.00	\$0.00	\$38.68

JOB COUNT: 3	WORK ORDER TOTAL:	1.13	133.08	12.71	0.00	145.79
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11074414	02/19/2021 07:00:00	02/19/2021 07:06:00	(0.10)	(\$11.80)
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11074414	02/19/2021 07:00:00	02/19/2021 07:06:00	0.10	\$11.80
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11213180	02/19/2021 07:00:00	02/19/2021 07:06:00	0.10	\$11.80
66-79-003	PERFORM SAFETY INSPECTION	11213180	02/18/2021 10:15:31	02/18/2021 10:57:31	0.70	\$82.60
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/18/2021 08:34:37	02/18/2021 08:54:17	0.33	\$38.68
					LABOR	133.08

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	12.71	1	\$12.71
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	(1)	(\$6.48)
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
					PARTS	12.71

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 39117

Work Order Notes

(LISAPATE) PM-Do annual safety inspection

Job Notes

03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT

(ABLACK) Installed new cabin filter.

66-79-003 - PERFORM SAFETY INSPECTION

(ABLACK) Performed SI. MS

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 3711. Vehicle has been driven 788 miles since last oil change. Checked fluids battery tire pressure and updated oil change sticker and vacuumed. SH

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 40254

USING DEPT NO: 507203	OPENED DATE: 06/25/2021 14:01:20	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 06/28/2021 15:45:22	METER 1 - M: 4680 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 06/29/2021 08:47:23	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.28	\$32.94	\$0.00	\$0.00	\$32.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.84	\$31.31	\$0.00	\$60.15

JOB COUNT: 2 **WORK ORDER TOTAL: 0.52 61.78 31.31 0.00 93.09**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/25/2021 14:46:34	06/25/2021 15:03:19	0.28	\$32.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/25/2021 14:30:00	06/25/2021 14:44:40	0.24	\$28.84
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/25/2021 14:15:53	06/25/2021 14:15:53	0.00	\$0.00
					LABOR	61.78

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	7	\$31.40
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.40	1	\$4.40
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	(7)	(\$31.40)
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	31.31

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 40254

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) SH AMG Rotated tires and inspected brakes.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 4680. SH Performed PM.

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 41693

USING DEPT NO: 507203	OPENED DATE: 11/23/2021 12:27:56	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 11/29/2021 13:30:13	METER 1 - M: 5755 METER 2 - H: 0
WO VISIT REASON: PREVENTIVE MAINT	CLOSED DATE: 11/29/2021 13:30:19	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.16	\$18.78	\$20.38	\$0.00	\$39.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.67	\$0.00	\$0.00	\$21.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.34	40.45	20.38	2.00	62.83
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	11/23/2021 14:57:08	11/23/2021 15:08:09	0.18	\$21.67
03-51-038	REPLACE NEW WIPER BLADES	12052187	11/23/2021 14:47:25	11/23/2021 14:56:58	0.16	\$18.78
LABOR					40.45	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
PARTS					20.38	

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 41693

Work Order Notes

(IFALLS) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has been 1114 miles since last pm. Updated sticker. Checked tires and fluids. Coolant -34°. JAW
MILEAGE-5794

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 43124

USING DEPT NO:	507203	OPENED DATE:	05/03/2022 14:21:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/05/2022 11:07:20	METER 1 - M:	6535	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/05/2022 12:46:36	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.70	\$20.38	\$0.00	\$22.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.17	\$31.97	\$0.00	\$81.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.43	50.87	52.35	2.00	105.22
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/04/2022 07:24:39	05/04/2022 07:48:54	0.40	\$47.69
03-51-038	REPLACE NEW WIPER BLADES	12052187	05/04/2022 07:46:53	05/04/2022 07:47:45	0.01	\$1.70
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/04/2022 07:45:59	05/04/2022 07:46:44	0.01	\$1.48
LABOR					50.87	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.19	1	\$10.19
PARTS					52.35	

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 43124

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. SH,JAW/SH
MILEAGE-6535

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 44882

USING DEPT NO: 507203	OPENED DATE: 10/05/2022 15:35:00	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 10/06/2022 11:02:31	METER 1 - M: 7801 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 10/06/2022 12:13:31	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$22.42	\$0.00	\$0.00	\$22.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.19** **22.42** **0.00** **5.00** **27.42**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/06/2022 09:03:36	10/06/2022 09:15:00	0.19	\$22.42
LABOR						22.42

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 44882

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 7801 Vehicle has been 1266 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 46254

USING DEPT NO:	507203	OPENED DATE:	02/23/2023 12:10:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/24/2023 11:06:30	METER 1 - M:	8799	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/24/2023 12:57:39	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.64	\$20.94	\$0.00	\$24.58
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.06	\$7.28	\$0.00	\$0.00	\$7.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.60	\$42.72	\$0.00	\$82.32
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4 **WORK ORDER TOTAL: 0.43 50.52 63.66 5.00 119.18**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-003	PERFORM SAFETY INSPECTION	12052187	02/23/2023 13:34:31	02/23/2023 13:38:13	0.06	\$7.28
03-51-038	REPLACE NEW WIPER BLADES	12052187	02/23/2023 13:32:29	02/23/2023 13:34:20	0.03	\$3.64
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/23/2023 13:12:11	02/23/2023 13:32:19	0.34	\$39.60
					LABOR	50.52

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.11	6	\$36.63
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.09	1	\$6.09
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	1	\$10.47
					PARTS	63.66

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 46254

Work Order Notes

(EHANNAH) pm- replace wipers - preform safety inspection

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers.

66-79-003 - PERFORM SAFETY INSPECTION

(JWRIGHT) Performed safety inspection. All good. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/JAW
MILEAGE-8799

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 47742

USING DEPT NO:	507203	OPENED DATE:	07/26/2023 09:43:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/26/2023 14:19:10	METER 1 - M:	9283	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2023 11:09:18	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.13	\$15.47	\$0.00	\$0.00	\$15.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.32	\$38.15	\$0.00	\$0.00	\$38.15

JOB COUNT: 3	WORK ORDER TOTAL:	0.45	53.62	0.00	5.00	58.62
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	07/26/2023 13:00:00	07/26/2023 13:19:24	0.32	\$38.15
WA-00	WASH COMPLETE VEHICLE	11074414	07/26/2023 12:58:26	07/26/2023 12:58:26	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/26/2023 11:41:53	07/26/2023 11:49:45	0.13	\$15.47
					LABOR	53.62

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 47742

Work Order Notes

(EHANNAH) pm- replace wipers- wash
(EKIMBREL) DID NOT NEED WIPERS YET

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Vehicle has been driven 484 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed the vehicle. SH

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 49301

USING DEPT NO: 507203	OPENED DATE: 12/19/2023 09:20:40	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 12/20/2023 15:17:26	METER 1 - M: 9682 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 12/21/2023 07:40:09	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.58	\$43.92	\$0.00	\$86.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.36** **42.58** **43.92** **5.00** **91.50**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/19/2023 09:30:00	12/19/2023 09:51:39	0.36	\$42.58
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/19/2023 09:26:37	12/19/2023 09:26:37	0.00	\$0.00
LABOR					42.58	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	6	\$37.71
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
PARTS					43.92	

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 49301

Work Order Notes

(EKIMBREL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 50822

USING DEPT NO: 507203	OPENED DATE: 05/13/2024 09:18:47	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 05/17/2024 08:31:30	METER 1 - M: 10546 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 05/17/2024 09:33:20	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA 2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.01	\$1.48	\$0.00	\$0.00	\$1.48
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	1.44	\$169.66	\$0.00	\$0.00	\$169.66
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.01	\$1.02	\$773.22	\$0.00	\$774.24
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$3.51	\$0.00	\$0.00	\$3.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.49	175.67	773.22	5.00	953.89
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					COMML 5.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-15	INSPECT STEERING	11074414	05/13/2024 11:11:54	05/13/2024 11:12:39	0.01	\$1.48
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/13/2024 10:45:21	05/13/2024 10:47:08	0.03	\$3.51
66-17-013	PERFORM ALIGNMENT	11310047	05/16/2024 09:30:00	05/16/2024 09:44:41	0.24	\$28.88
66-17-013	PERFORM ALIGNMENT	11310047	05/16/2024 08:03:25	05/16/2024 09:15:00	1.19	\$140.78
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	05/15/2024 14:49:33	05/15/2024 14:50:04	0.01	\$1.02
					LABOR	175.67

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.58	4	\$18.30
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	1.01	2	\$2.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.51	3	\$1.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	1.17	1	\$1.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	187.40	4	\$749.58

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	187.40	(4)	(\$749.58)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	000223	TIRE 245/75R16 FSTONE DEST LE2	187.40	4	\$749.58
					PARTS	773.22

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 50822

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) DID NOT NEED WIPERS

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(GARAGE) Inspected the steering. Found no issues at this time. SH

66-17-013 - PERFORM ALIGNMENT

(EHOWELL) Performed alignment and reset steering using Code Link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 4 tires. SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Driven 739 miles. Checked fluids tires and updated the oil change sticker. Tires are wearing on the shoulders suggest 4 tires. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(EHOWELL) EH ran vehicle through the automatic car wash.

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 51871

USING DEPT NO: 507203	OPENED DATE: 08/19/2024 13:46:21	LOCATION: GARAGE - University Automotive Services
WO STATUS: CLOSED	COMPLETED DATE: 08/23/2024 12:58:05	METER 1 - M: 11195 METER 2 - H: 0
WO VISIT REASON: SCHEDULED	CLOSED DATE: 08/26/2024 15:29:47	IN-SERVICE DATE: 12/16/2019
TECH SPEC NO: 20TOYTACOMA	2020 Toyota Tacoma	UNIT SERIAL NO: 5TFRX5GN4LX169340

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.33	\$2.33
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.33	\$0.00	\$0.00	\$2.33

JOB COUNT: 2 **WORK ORDER TOTAL:** **0.02** **2.33** **0.00** **2.33** **4.66**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.33
					COMML 2.33

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/22/2024 14:09:40	08/22/2024 14:10:51	0.02	\$2.33
					LABOR	2.33

Work Order Charge Detail

UNIT NO: 243616 2020 TOYOTA TACOMA

WORK ORDER NO: 51871

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) Removed wordmarks, and tag 2915C. Checked inside of vehicle. CW

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Fri Sep 06 2024 14:53:25 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.serial_no} = '5TFRX5GN4LX169340') //Q=