

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 35342

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 01/08/2020 10:42:23	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/10/2020 14:00:54	<b>METER 1 - M:</b> 84 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/10/2020 14:00:56	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA      2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$36.25	\$0.00	\$0.00	\$36.25

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **36.25**      **0.00**      **0.00**      **36.25**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11901357	01/08/2020 10:43:22	01/08/2020 11:13:22	0.50	\$36.25
					<b>LABOR</b>	<b>36.25</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 35342

---

**Work Order Notes**

(EKIMBREL) PDI

---

**Job Notes**

**66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION**

(EKIMBREL) AG performed PDI

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 36104

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 04/06/2020 13:12:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/08/2020 11:00:00	<b>METER 1 - M:</b> 808 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/08/2020 11:54:31	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	P	N	GARAGE	5.32	\$385.56	\$584.10	\$0.00	\$969.66

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>5.32</b>	<b>385.56</b>	<b>584.10</b>	<b>0.00</b>	<b>969.66</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/07/2020 07:42:15	04/07/2020 09:01:20	1.32	\$95.56
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 14:30:00	04/06/2020 16:30:00	2.00	\$145.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 14:30:00	04/06/2020 15:55:49	(1.43)	(\$103.70)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 14:30:00	04/06/2020 15:55:49	1.43	\$103.70
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 13:39:32	04/06/2020 15:39:32	2.00	\$145.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 13:39:32	04/06/2020 14:15:00	(0.59)	(\$42.86)
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	04/06/2020 13:39:32	04/06/2020 14:15:00	0.59	\$42.86
					<b>LABOR</b>	<b>385.56</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	147.90	2	\$295.80
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	122.55	2	\$245.10
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	13460	SOLDER ELEC 60/40 FINE .050	10.28	2	\$20.55
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WLD13461	SOLDER ELEC 60/40 .032 XFINE	7.41	1	\$7.41
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.39	1	\$0.39
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	6.81	1	\$6.81
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8220A	SHRINK TUBE 3/16 X 4 FT	4.02	2	\$8.04
					<b>PARTS</b>	<b>584.10</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 36104

---

**Work Order Notes**

(IFALLS) INSTALL STROBES

---

**Job Notes**

**14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY**

(IFALLS) AB installed front and rear strobe lights

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 36364

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 05/11/2020 06:57:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/11/2020 08:26:17	<b>METER 1 - M:</b> 1058 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/13/2020 08:12:13	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$34.20	\$41.49	\$0.00	\$75.69

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>	<b>0.47</b>	<b>34.20</b>	<b>41.49</b>	<b>0.00</b>	<b>75.69</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/11/2020 07:25:14	05/11/2020 07:48:01	0.38	\$27.53
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/11/2020 07:33:56	05/11/2020 07:39:27	0.09	\$6.67
					<b>LABOR</b>	<b>34.20</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
					<b>PARTS</b>	<b>41.49</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 36364

---

**Work Order Notes**

(EKIMBREL) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(IFALLS) AG/JW Performed pm

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 37971

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 10/13/2020 09:35:52	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/14/2020 09:53:28	<b>METER 1 - M:</b> 3993 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/14/2020 15:13:14	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA	2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.72	\$85.06	\$0.00	\$0.00	\$85.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.37	\$41.49	\$0.00	\$76.86

**JOB COUNT: 2** **WORK ORDER TOTAL:** **1.02** **120.43** **41.49** **0.00** **161.92**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	10/13/2020 12:04:33	10/13/2020 12:47:48	0.72	\$85.06
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/13/2020 11:42:05	10/13/2020 12:00:04	0.30	\$35.37
					<b>LABOR</b>	<b>120.43</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	5.84	6	\$35.01
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
					<b>PARTS</b>	<b>41.49</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 37971

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/AB PERFORMED PM.

---



# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 38722

USING DEPT NO:	507201	OPENED DATE:	01/07/2021 14:48:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2021 09:36:24	METER 1 - M:	5375	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/12/2021 12:42:08	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.47	\$55.30	\$7.67	\$0.00	\$62.97

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.47 55.30 7.67 0.00 62.97**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	12052187	01/08/2021 08:31:59	01/08/2021 09:00:06	0.47	\$55.30
					<b>LABOR</b>	<b>55.30</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	3.32	1	\$3.32
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	3.51	1	\$3.51
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.42	2	\$0.84
					<b>PARTS</b>	<b>7.67</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 38722

---

**Work Order Notes**

(EKIMBREL) LR tire has a screw in it.

---

**Job Notes**

**66-17-030 - PERFORM TIRE PATCH**

(JWRIGHT) Repaired or tire and balanced. Aired and torqued to spec. Test drove and tpms light went off. JAW

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 39515

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 03/30/2021 07:53:36	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/01/2021 10:53:36	<b>METER 1 - M:</b> 6998 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/06/2021 07:53:13	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLAC	DON	O	N	GARAGE	0.13	\$15.01	\$22.43	\$0.00	\$37.44
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.49	\$58.21	\$33.41	\$0.00	\$91.62

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.62** **73.22** **55.84** **0.00** **129.06**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	11901357	03/31/2021 09:14:04	03/31/2021 09:21:42	0.13	\$15.01
66-PM-PMA	PERFORM OIL CHANGE	11901357	03/30/2021 09:32:41	03/30/2021 10:02:17	0.49	\$58.21
					<b>LABOR</b>	<b>73.22</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	22.43	1	\$22.43
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	22.43	(1)	(\$22.43)
03-PM-PMC	REPLACE NEW CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	22.43	1	\$22.43
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.50	1	\$6.50
					<b>PARTS</b>	<b>55.84</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 39515

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**03-PM-PMC - REPLACE NEW CABIN FILTER REPLACEMENT**

(AGUERRA) replaced cabin filter. AMG

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 6998 Completed PM top side, Josh was bottom side. Completed checklist and vacuumed out vehicle. AMG/JW

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 41359

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 10/18/2021 15:11:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/22/2021 10:55:22	<b>METER 1 - M:</b> 10895 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/26/2021 07:28:55	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>		
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.21	\$15.18	\$0.00	\$20.39		
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.60	\$71.23	\$0.00	\$0.00	\$71.23		
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.37	\$44.02	\$0.00	\$0.00	\$44.02		
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.82	\$97.25	\$282.73	\$0.00	\$379.98		
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.07	\$71.45	\$0.00	\$132.52		
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00		
<b>JOB COUNT: 6</b>						<b>WORK ORDER TOTAL:</b>		<b>2.36</b>	<b>278.78</b>	<b>369.36</b>	<b>2.00</b>	<b>650.14</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00	
					<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
09-15	ALIGN STEERING	11310047	10/21/2021 13:43:29	10/21/2021 14:05:52	0.37	\$44.02
06-15	INSPECT STEERING	11074414	10/19/2021 07:53:22	10/19/2021 08:29:35	0.60	\$71.23
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/20/2021 07:10:35	10/20/2021 07:42:12	0.53	\$62.18
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	10/19/2021 15:24:41	10/19/2021 15:42:31	0.30	\$35.07
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/19/2021 07:49:11	10/19/2021 07:51:50	0.04	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/19/2021 07:17:58	10/19/2021 07:49:01	0.52	\$61.07
					<b>LABOR</b>	<b>278.78</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	29.10	1	\$29.10
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	6	\$37.89
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.46	1	\$4.46

# Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	3.00	2	\$6.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.35	2	\$0.69
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.56	1	\$0.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04504620000	GEN GRABBER 245/75R16	137.61	2	\$275.22
<b>PARTS</b>						<b>369.36</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 41359

---

## Work Order Notes

(LISAPATE) PM-replace wipers  
(LISAPATE)

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected steering found no issues. SH

### **09-15 - ALIGN STEERING**

(EHOWELL) Performed Alignment. EH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 2 tires put new tires on the front. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 10895. SH Performed PM.

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 42967

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 04/19/2022 13:28:03	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 04/21/2022 09:01:16	<b>METER 1 - M:</b> 14833 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 04/21/2022 10:30:47	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.20	\$15.18	\$0.00	\$17.38
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.37	\$43.96	\$52.48	\$0.00	\$96.44
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.11	\$13.24	\$23.15	\$0.00	\$36.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>0.50</b>	<b>59.40</b>	<b>90.81</b>	<b>2.00</b>	<b>152.21</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/20/2022 09:30:00	04/20/2022 09:31:07	0.02	\$2.20
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/20/2022 09:28:24	04/20/2022 09:28:24	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/20/2022 08:58:15	04/20/2022 09:15:00	0.28	\$32.94
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/20/2022 09:09:24	04/20/2022 09:15:00	0.09	\$11.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/20/2022 09:29:54	04/20/2022 09:29:54	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/20/2022 09:30:00	04/20/2022 09:36:44	0.11	\$13.24
					<b>LABOR</b>	<b>59.39</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	23.15	1	\$23.15
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.06	1	\$5.06
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.81	6	\$40.86
					<b>PARTS</b>	<b>90.81</b>



# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 42967

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/AMG Performed PM

**66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(AGUERRA) Replaced cabin filter. AMG

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 44046

USING DEPT NO:	507201	OPENED DATE:	07/22/2022 09:41:07	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2022 10:15:20	METER 1 - M:	16349	METER 2 - H:	0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2022 13:21:48	IN-SERVICE DATE:	01/08/2020		
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-52-024	WARRANTY BACK UP CAMERA	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-52	TRANSPORT ELECTRICAL ACCESSORI	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
35-52-024	DIAGNOSE BACK UP CAMERA	DON	O	N	GARAGE	0.38	\$44.35	\$0.00	\$0.00	\$44.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.88</b>	<b>103.35</b>	<b>0.00</b>	<b>2.00</b>	<b>105.35</b>
---------------------	--------------------------	-------------	---------------	-------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
15-52-024	WARRANTY BACK UP CAMERA	11076422	6169098		\$0.00
				<b>COMML</b>	<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11915538	07/28/2022 07:00:00	07/28/2022 07:30:00	0.50	\$59.00
35-52-024	DIAGNOSE BACK UP CAMERA	11310047	07/22/2022 10:37:40	07/22/2022 11:00:13	0.38	\$44.35
					<b>LABOR</b>	<b>103.35</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 44046

---

## Work Order Notes

(LISAPATE) Per BJ back up camera is not working

---

## Job Notes

### **15-52-024 - WARRANTY BACK UP CAMERA**

(LISAPATE) Tuscaloosa Toyota installed a new camera and bracket under warranty

### **16-52 - TRANSPORT ELECTRICAL ACCESSORIES**

(LISAPATE) Taken to Toyota by RC

### **35-52-024 - DIAGNOSE BACK UP CAMERA**

(EHOWELL) The plastic bracket that holds the backup camera was broken and the camera fell down inside the tailgate. The vehicle is going to the dealership for repairs. EH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 44632

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 09/09/2022 08:26:26	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/12/2022 10:26:33	<b>METER 1 - M:</b> 17140 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/12/2022 13:08:52	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA	2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.74	\$40.34	\$0.00	\$83.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.36** **42.74** **40.34** **5.00** **88.08**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/09/2022 14:30:00	09/09/2022 14:51:44	0.36	\$42.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/09/2022 14:15:58	09/09/2022 14:15:58	0.00	\$0.00
<b>LABOR</b>					<b>42.74</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	(1)	(\$26.39)
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.69	1	\$5.69
<b>PARTS</b>					<b>40.34</b>	

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 44632

---

**Work Order Notes**

(CWIGLEY) PM. Dale Cole ask to check the tires to see if it needed new ones.

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. Inspected tires they do not need to be replaced at this time. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 45659

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 01/04/2023 08:19:30	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/04/2023 15:55:13	<b>METER 1 - M:</b> 18528 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/09/2023 08:34:21	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-32-002	INSPECT BATTERY	DON	O	N	GARAGE	0.04	\$5.15	\$0.00	\$0.00	\$5.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.04** **5.15** **0.00** **5.00** **10.15**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-32-002	INSPECT BATTERY	12052187	01/04/2023 08:30:38	01/04/2023 08:33:15	0.04	\$5.15
<b>LABOR</b>						<b>5.15</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 45659

---

**Work Order Notes**

(EHANNAH) inspect battery

---

**Job Notes**

**06-32-002 - INSPECT BATTERY**

(JWRIGHT) Inspected battery. Battery tested good. Alternator charging at 13.6 unloaded and 13.3 loaded. Found no issues with battery or charging system. JAW

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 46102

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 02/09/2023 08:24:26	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/09/2023 08:57:45	<b>METER 1 - M:</b> 18974 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/10/2023 11:03:30	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA 2020 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.49	\$20.94	\$0.00	\$23.43
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.15	\$0.00	\$0.00	\$40.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.36</b>	<b>42.64</b>	<b>20.94</b>	<b>5.00</b>	<b>68.58</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/09/2023 08:54:18	02/09/2023 08:55:34	0.02	\$2.49
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/09/2023 08:33:42	02/09/2023 08:54:07	0.34	\$40.15
<b>LABOR</b>					<b>42.64</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.47	1	\$10.47
<b>PARTS</b>					<b>20.94</b>	



# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 46102

---

## Work Order Notes

(EHANNAH) pm- replace wipers

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 1834 miles since the last PM. Checked fluids battery and updated the oil change sticker. Vehicle needs 4 tires due to excessive shoulder wear. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 46104

USING DEPT NO:	507201	OPENED DATE:	02/09/2023 08:57:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2023 10:54:59	METER 1 - M:	18974	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/13/2023 12:24:44	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.17	\$19.70	\$0.00	\$0.00	\$19.70
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.85	\$100.30	\$815.76	\$0.00	\$916.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.02</b>	<b>120.00</b>	<b>815.76</b>	<b>5.00</b>	<b>940.76</b>
---------------------	--------------------------	-------------	---------------	---------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-15	INSPECT STEERING	11074414	02/09/2023 09:01:07	02/09/2023 09:11:08	0.17	\$19.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/10/2023 08:52:56	02/10/2023 09:15:00	0.37	\$43.40
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	02/10/2023 09:30:00	02/10/2023 09:58:56	0.48	\$56.90
<b>LABOR</b>					<b>120.00</b>	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	6.96	4	\$27.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.45	2	\$0.90
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.65	2	\$1.29
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	2	\$1.59
66-17-028	PERFORM MOUNT AND BALANCE TIRES	04504620000	GEN GRABBER 245/75R16	195.75	4	\$783.00
<b>PARTS</b>					<b>815.76</b>	

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 46104

---

## Work Order Notes

(LISAPATE) Needs 4 tires

(LISAPATE) Unit will be back for alignment no tech available at this time

---

## Job Notes

### **06-15 - INSPECT STEERING**

(SHARBIN) Inspected steering found no issues at this time. SH

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(SHARBIN) Mounted and balanced 4 tires. SH

### **CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 46280

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 02/27/2023 07:19:31	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/28/2023 08:34:23	<b>METER 1 - M:</b> 19175 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/28/2023 09:09:01	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA	2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.84	\$99.12	\$0.00	\$0.00	\$99.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 2**      **WORK ORDER TOTAL:**      **0.84**      **99.12**      **0.00**      **5.00**      **104.12**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-013	PERFORM ALIGNMENT	11310047	02/28/2023 07:00:00	02/28/2023 07:50:24	0.84	\$99.12
09-00	ALIGN COMPLETE VEHICLE	11310047	02/27/2023 13:57:17	02/27/2023 14:47:57	(0.84)	(\$99.64)
09-00	ALIGN COMPLETE VEHICLE	11310047	02/27/2023 13:57:17	02/27/2023 14:47:57	0.84	\$99.64
<b>LABOR</b>					<b>99.12</b>	

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 46280

---

**Work Order Notes**

(EHANNAH) alignment needed

---

**Job Notes**

**09-00 - ALIGN COMPLETE VEHICLE**

(EHOWELL) Set front toe and reset steering using code link. EH

**66-17-013 - PERFORM ALIGNMENT**

(EKIMBREL) Set front toe and reset steering using code link. EH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 243618      **2020 TOYOTA TACOMA**      **WORK ORDER NO:** 47498

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 06/30/2023 13:03:11	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 07/03/2023 10:01:12	<b>METER 1 - M:</b> 20796 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 07/05/2023 08:33:27	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA      2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.41	\$16.66	\$0.00	\$20.07
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$21.93	\$74.15	\$0.00	\$96.08
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.67	\$11.79	\$0.00	\$17.46
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.03	\$3.28	\$0.00	\$0.00	\$3.28

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>0.29</b>	<b>34.29</b>	<b>102.60</b>	<b>5.00</b>	<b>141.89</b>
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/30/2023 13:48:47	06/30/2023 13:50:27	0.03	\$3.28
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/30/2023 13:45:42	06/30/2023 13:48:35	0.05	\$5.67
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/30/2023 13:43:46	06/30/2023 13:45:30	0.03	\$3.41
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/30/2023 13:32:25	06/30/2023 13:43:34	0.19	\$21.93
					<b>LABOR</b>	<b>34.29</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	27.18	1	\$27.18
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.80	6	\$40.77
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
					<b>PARTS</b>	<b>102.60</b>

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 47498

---

## Work Order Notes

(EHANNAH) pm- replace wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) JW Replaced the wipers. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/JW Performed PM.

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(SHARBIN) Replaced the cabin air filter. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Vehicle is clean. SH

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 49107

USING DEPT NO:	507201	OPENED DATE:	11/30/2023 13:45:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/01/2023 10:33:20	METER 1 - M:	23436	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 10:33:24	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$21.70	\$0.00	\$45.30
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.59	\$69.29	\$0.00	\$0.00	\$69.29
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$44.01	\$0.00	\$82.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.30	\$35.24	\$0.00	\$0.00	\$35.24

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>1.42</b>	<b>167.07</b>	<b>65.71</b>	<b>5.00</b>	<b>237.78</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	11/30/2023 15:09:19	11/30/2023 15:27:14	0.30	\$35.24
66-79-003	PERFORM SAFETY INSPECTION	11074414	11/30/2023 14:33:53	11/30/2023 15:09:07	0.59	\$69.29
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/30/2023 14:26:32	11/30/2023 14:38:32	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/30/2023 14:26:32	11/30/2023 14:26:32	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/30/2023 14:26:32	11/30/2023 14:26:32	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/30/2023 14:17:17	11/30/2023 14:17:17	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/30/2023 14:17:17	11/30/2023 14:17:17	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/30/2023 14:17:17	11/30/2023 14:37:05	0.33	\$38.94
					<b>LABOR</b>	<b>167.07</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	1	\$10.85



# Work Order Charge Detail

---

**PARTS**

**65.71**

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 49107

---

## Work Order Notes

(EHANNAH) pm- wipers- do SI- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. Front brake pads and rear brake shoes measure 5MM. Rotated the tires. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) SH/FC Performed PM. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed and filled with gas. SH

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 49536

USING DEPT NO:	507201	OPENED DATE:	01/23/2024 09:40:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/23/2024 15:43:21	METER 1 - M:	23965	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2024 07:23:39	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.25	\$29.14	\$199.98	\$0.00	\$229.12
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2 WORK ORDER TOTAL: 0.25 29.14 199.98 5.00 234.12

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11074414	01/23/2024 09:47:38	01/23/2024 10:02:27	0.25	\$29.14
					<b>LABOR</b>	<b>29.14</b>

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	24F-3	BATTERY	199.98	1	\$199.98
					<b>PARTS</b>	<b>199.98</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 49536

---

**Work Order Notes**

(LISAPATE) Battery is dead keeps jumping off

---

**Job Notes**

**03-32-002 - REPLACE NEW BATTERY**

(GARAGE) Battery tested bad. Installed a new battery ALT charging at 13.8 volts. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

UNIT NO: 243618 2020 TOYOTA TACOMA

WORK ORDER NO: 51234

USING DEPT NO:	507201	OPENED DATE:	06/18/2024 10:32:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/18/2024 12:19:58	METER 1 - M:	26499	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2024 07:37:08	IN-SERVICE DATE:	01/08/2020	
TECH SPEC NO:	20TOYTACOMA	2020 Toyota Tacoma		UNIT SERIAL NO:	5TFRX5GN4LX171783	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.02	\$22.13	\$0.00	\$23.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.34	\$48.30	\$0.00	\$49.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.38	\$0.00	\$0.00	\$1.38

**JOB COUNT: 4** **WORK ORDER TOTAL: 0.03 3.74 70.43 5.00 79.17**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML 5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	06/18/2024 11:31:28	06/18/2024 11:32:10	0.01	\$1.38
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/18/2024 11:03:38	06/18/2024 11:04:09	0.01	\$1.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/18/2024 11:02:57	06/18/2024 11:03:38	0.01	\$1.34
					<b>LABOR 3.74</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	1	\$11.25
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
					<b>PARTS 70.43</b>	

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 51234

---

**Work Order Notes**

(EHANNAH) pm- wipers- wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) SH/FC Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Wash bay occupied filled with gas. SH

---

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 51904

<b>USING DEPT NO:</b> 507201	<b>OPENED DATE:</b> 08/22/2024 07:32:00	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/27/2024 10:31:11	<b>METER 1 - M:</b> 27690 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/27/2024 11:05:01	<b>IN-SERVICE DATE:</b> 01/08/2020
<b>TECH SPEC NO:</b> 20TOYTACOMA	2020 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFRX5GN4LX171783

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.20	\$2.20
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.02	\$2.20	\$0.00	\$0.00	\$2.20

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.02** **2.20** **0.00** **2.20** **4.40**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.20
				<b>COMML</b>	<b>2.20</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	08/26/2024 07:30:12	08/26/2024 07:31:19	0.02	\$2.20
					<b>LABOR</b>	<b>2.20</b>

# Work Order Charge Detail

**UNIT NO:** 243618 2020 TOYOTA TACOMA

**WORK ORDER NO:** 51904

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) No wordmarks. Removed Tag 2909C. No GPS. Checked inside of vehicle. CW/RC

---



# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Fri Sep 06 2024 15:01:59 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.serial\_no} = '5TFRX5GN4LX171783') //Q=