

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 41491

USING DEPT NO:	507121	OPENED DATE:	11/02/2021 14:25:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/02/2021 14:28:10	METER 1 - M:	128	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/02/2021 14:28:13	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	2.00	120.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	12052187	11/02/2021 14:27:33	11/02/2021 15:27:33	1.00	\$118.00
					LABOR	118.00

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 41491

Work Order Notes

(IFALLS) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(IFALLS) JW performed pdi

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42291

USING DEPT NO:	507121	OPENED DATE:	02/08/2022 07:52:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/14/2022 14:19:03	METER 1 - M:	385	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2022 08:17:53	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-35-019	INSTALL POWER INVERTER	DON	O	N	GARAGE	9.32	\$1,099.53	\$686.57	\$0.00	\$1,786.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	9.32	1,099.53	686.57	2.00	1,788.10
--------------	-------------------	------	----------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 14:30:00	02/09/2022 15:00:53	0.51	\$60.74
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 14:22:23	02/09/2022 14:22:23	0.00	\$0.00
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 13:27:58	02/09/2022 13:55:46	0.46	\$54.67
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 09:31:43	02/09/2022 11:50:01	2.31	\$271.99
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 08:07:09	02/09/2022 09:15:00	1.13	\$133.44
14-35-019	INSTALL POWER INVERTER	11310047	02/09/2022 07:13:42	02/09/2022 07:54:25	0.68	\$80.08
14-35-019	INSTALL POWER INVERTER	11310047	02/08/2022 14:30:00	02/08/2022 15:52:25	1.37	\$162.09
14-35-019	INSTALL POWER INVERTER	11310047	02/08/2022 13:09:35	02/08/2022 14:15:00	1.09	\$128.65
14-35-019	INSTALL POWER INVERTER	11310047	02/08/2022 11:01:43	02/08/2022 11:37:14	0.59	\$69.85
14-35-019	INSTALL POWER INVERTER	11310047	02/08/2022 08:01:39	02/08/2022 09:11:50	1.17	\$138.03
					LABOR	1099.54

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-35-019	INSTALL POWER INVERTER	06133	ELECTRICAL TAPE 3M SUPER 33+	9.32	1	\$9.32
14-35-019	INSTALL POWER INVERTER	WILW747	RAZOR BLADES	0.11	1	\$0.11
14-35-019	INSTALL POWER INVERTER	WILW16653	2000 WATT POWER INVENTOR	340.37	1	\$340.37
14-35-019	INSTALL POWER INVERTER	BOLTS	INTAKE BOLTS	0.38	10	\$3.75
14-35-019	INSTALL POWER INVERTER	PIC0954PT	ATM FUSED ADD-A-CIRCUIT	5.13	1	\$5.13

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-35-019	INSTALL POWER INVERTER	BOLT	BOLT	0.75	4	\$3.00
14-35-019	INSTALL POWER INVERTER	GAHG818010016	SLEEVE-HOSE COVERING	4.07	25	\$101.63
14-35-019	INSTALL POWER INVERTER	DKB05462	LUG, COPPER 2 GA 5/16IN	1.38	6	\$8.28
14-35-019	INSTALL POWER INVERTER	FWS38073	SOLDER, ROSIN CORE 1/16 IN	21.17	1	\$21.17
14-35-019	INSTALL POWER INVERTER	DKB05461	LUG, COPPER 2GA 1/4IN	1.38	3	\$4.14
14-35-019	INSTALL POWER INVERTER	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	2.66	1	\$2.66
14-35-019	INSTALL POWER INVERTER	FWS52025	2 GA CABLE BULK 1 FOOT	6.00	24	\$144.00
14-35-019	INSTALL POWER INVERTER	WPS67702	HD SOLENOID CONTINUOUS DUTY	43.01	1	\$43.01
					PARTS	686.57

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42291

Work Order Notes

(EKIMBREL) INSTALL POWER INVERTER

Job Notes

14-35-019 - INSTALL POWER INVERTER

(EHOWELL) Installed a power inverter, continuous duty solenoid, and a micro piggy back fuse holder in the under hood fuse block. Ran welding cable from the battery to the rear of the vehicle. Installed new lugs onto the cables using solder and heat shrink. Installed a protective sheathing around the welding cable. Verified operation of power inverter after installation. EH 9.0 HRS

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42708

USING DEPT NO:	507121	OPENED DATE:	03/25/2022 11:55:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2022 11:57:16	METER 1 - M:	2777	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2022 14:26:44	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$57.50	\$57.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	57.50	57.50
--------------	-------------------	------	------	------	-------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
24-02-061	REPAIR WINDSHIELD	11078716	297506		\$57.50
COMML					57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42708

Work Order Notes

(LISAPATE) Rock chip in windshield

Job Notes

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr repaired windshield. PD by CC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42957

USING DEPT NO:	507121	OPENED DATE:	04/19/2022 09:28:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2022 09:02:05	METER 1 - M:	4673	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2022 10:29:26	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.78	\$92.24	\$53.21	\$0.00	\$145.45
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.78	92.24	53.21	2.00	147.45
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/19/2022 09:56:17	04/19/2022 10:37:10	0.68	\$80.40
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/19/2022 09:50:26	04/19/2022 09:56:27	0.10	\$11.83
				LABOR		92.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.46	6	\$44.73
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.48	1	\$8.48
					PARTS	53.21

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 42957

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) AMG/SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 43786

USING DEPT NO:	507121	OPENED DATE:	06/29/2022 11:58:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2022 14:48:32	METER 1 - M:	8817	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/01/2022 14:26:36	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$59.66	\$53.39	\$0.00	\$113.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.51	59.66	53.39	2.00	115.05
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2022 13:30:11	06/29/2022 13:30:34	0.01	\$0.75
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2022 13:00:00	06/29/2022 13:29:57	0.50	\$58.90
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/29/2022 12:39:29	06/29/2022 12:39:29	0.00	\$0.00
				LABOR		59.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.48	1	\$8.48
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.49	6	\$44.91
				PARTS		53.39

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 43786

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. EH/JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 44678

USING DEPT NO:	507121	OPENED DATE:	09/13/2022 14:55:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2022 13:29:28	METER 1 - M:	13608	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2022 07:00:31	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-27	WARRANTY TRANSMISSION - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-27	TRANSPORT TRANSMISSION - MAIN, A	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.15	\$62.48	\$0.00	\$124.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.03	121.15	62.48	5.00	188.63
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
15-27	WARRANTY TRANSMISSION - MAIN, AUTOMATIC	11078175	104260		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	09/23/2022 07:00:00	09/23/2022 07:30:00	0.50	\$59.00
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	09/23/2022 07:00:00	09/23/2022 12:00:00	(5.00)	(\$590.00)
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11915538	09/23/2022 07:00:00	09/23/2022 12:00:00	5.00	\$590.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/14/2022 07:35:31	09/14/2022 08:07:07	0.53	\$62.15
LABOR						121.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	9.47	6	\$56.79
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.69	1	\$5.69
PARTS						62.48

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 44678

Work Order Notes

(CWIGLEY) PM. Driver says the transmission is shifting rough.

Job Notes

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Tuscaloosa Ford verified concern, no DTC's, fluid level and condition ok. performed accelerated main control break in procedure. Cleared KAM and performed transmission strategy down load. Performed adaptive learning drive cycle. Road tested and verified repair.

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) Taken to Ford by RC

35-27 - DIAGNOSE TRANSMISSION - MAIN, AUTOMATIC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 45405

USING DEPT NO:	507121	OPENED DATE:	12/01/2022 11:07:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2022 07:48:04	METER 1 - M:	17996	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/02/2022 09:50:33	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.31	\$32.69	\$0.00	\$34.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.46	\$69.81	\$0.00	\$139.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.60	70.77	102.50	5.00	178.27
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/01/2022 14:02:13	12/01/2022 14:02:53	0.01	\$1.31
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/01/2022 13:26:42	12/01/2022 14:02:01	0.59	\$69.46
					LABOR	70.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.73	1	\$5.73
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	10.68	6	\$64.08
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.43	1	\$10.43
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	9.47	1	\$9.47
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.79	1	\$12.79
					PARTS	102.50

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 45405

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH JW/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 46246

USING DEPT NO:	507121	OPENED DATE:	02/22/2023 09:36:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/24/2023 11:00:13	METER 1 - M:	22100	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/24/2023 13:08:38	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.56	\$66.18	\$56.64	\$0.00	\$122.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.56	66.18	56.64	5.00	127.82
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/23/2023 10:22:10	02/23/2023 10:55:49	0.56	\$66.18
					LABOR	66.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.09	1	\$6.09
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	(1)	(\$5.76)
66-PM-PMA	PERFORM OIL CHANGE	BALB7449	OIL FILTER	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.24	6	\$37.44
					PARTS	56.64

Work Order Charge Detail

UNIT NO:2440802021 FORD EXPLORER

WORK ORDER NO:46246

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 47293

USING DEPT NO:	507121	OPENED DATE:	06/08/2023 09:25:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2023 14:29:27	METER 1 - M:	26311	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/12/2023 15:58:47	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.88	\$34.13	\$0.00	\$39.01
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.36	\$42.58	\$0.00	\$0.00	\$42.58
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.01	\$71.15	\$0.00	\$106.16
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.08	\$9.74	\$33.45	\$0.00	\$43.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.78	92.21	138.73	5.00	235.94
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/08/2023 10:13:23	06/08/2023 10:35:02	0.36	\$42.58
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/08/2023 10:07:55	06/08/2023 10:10:24	0.04	\$4.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/08/2023 09:49:57	06/08/2023 10:07:45	0.30	\$35.01
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/08/2023 09:44:48	06/08/2023 09:49:45	0.08	\$9.74
					LABOR	92.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	7.56	6	\$45.36
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.20	1	\$6.20
66-PM-PMA	PERFORM OIL CHANGE	46935	AIR FILTER-SECURITY INTERCEP.	19.59	1	\$19.59
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.83	1	\$10.83
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99542P	CABIN FILTER 2021 EXP INT	33.45	1	\$33.45
					PARTS	138.73

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 47293

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH Rear GC Front

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires relearned the tire positions and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 47928

USING DEPT NO:	507121	OPENED DATE:	08/18/2023 09:12:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/22/2023 10:35:25	METER 1 - M:	30325	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/22/2023 13:38:43	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$2.98	\$34.15	\$0.00	\$37.13
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.58	\$68.64	\$13.61	\$0.00	\$82.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.73	\$72.15	\$0.00	\$83.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.71	83.35	119.91	5.00	208.26
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	11074414	08/18/2023 10:03:50	08/18/2023 10:38:44	0.58	\$68.64
66-17-030	PERFORM TIRE PATCH	11074414	08/18/2023 10:03:50	08/18/2023 10:38:44	0.58	\$68.64
66-17-030	PERFORM TIRE PATCH	11074414	08/18/2023 10:03:50	08/18/2023 10:38:44	(0.58)	(\$68.64)
66-PM-PMA	PERFORM OIL CHANGE	12201267	08/18/2023 09:58:43	08/18/2023 10:04:41	0.10	\$11.73
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/18/2023 10:02:19	08/18/2023 10:03:50	0.03	\$2.98
					LABOR	83.35

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	6	\$1.53
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.24	1	\$5.24
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	1	\$6.84
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	(6)	(\$1.53)
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.24	(1)	(\$5.24)
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	(1)	(\$6.84)
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.26	6	\$1.53
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.24	1	\$5.24
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.84	1	\$6.84

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.81	6	\$52.83
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	(6)	(\$37.71)
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	6.29	6	\$37.71
03-51-038	REPLACE NEW WIPER BLADES	19210	WIPER BLADE 21IN BEAM STYLE	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	60-011-G	WIPER-REAR FORD EXPLORER	10.07	1	\$10.07
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	119.91

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 47928

Work Order Notes

(EHANNAH) pm- wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH

66-17-030 - PERFORM TIRE PATCH

(GARAGE) Customer stated the left rear tire was low. Found a nail in the tire. Patched the tire rechecked good. SH

(LRUSHING) Visit Reason Changed On 8/30/2023 8:25 AM By LRUSHING

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM- CW,GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure. Had to remove small back skid pan.
Miles, 30,325

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 49493

USING DEPT NO:	507121	OPENED DATE:	01/18/2024 13:34:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/22/2024 15:05:02	METER 1 - M:	34227	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/23/2024 07:53:30	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.82	\$72.96	\$0.00	\$124.78
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.44	51.82	72.96	5.00	129.78
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
	COMML				5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/18/2024 13:44:27	01/18/2024 14:10:48	0.44	\$51.82
	LABOR					51.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30T	5W30 SYNTHETIC OIL THOMAS CAM2	8.94	6	\$53.64
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	(1)	(\$13.52)
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	(6)	(\$33.93)
66-PM-PMA	PERFORM OIL CHANGE	FL500S	FILTER-OIL FORD	13.52	1	\$13.52
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W20BT	BULK OIL 5W20 SYNTHETIC THOMAS	5.66	6	\$33.93
	PARTS					72.96

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 49493

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes FC -sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50061

USING DEPT NO:	507121	OPENED DATE:	03/04/2024 10:51:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2024 14:25:11	METER 1 - M:	35132	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/05/2024 09:46:07	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	59.00	0.00	5.00	64.00
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 12:27:33	03/04/2024 12:27:33	0.00	\$0.00
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 12:27:33	03/04/2024 12:27:33	0.00	\$0.00
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 12:27:33	03/04/2024 12:57:33	0.50	\$59.00
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 12:27:33	03/04/2024 12:57:33	0.50	\$59.00
14-52-021	INSTALL GPS SYSTEM	12201267	03/04/2024 12:27:33	03/04/2024 12:57:33	(0.50)	(\$59.00)
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50061

Work Order Notes

(EHANNAH) install GPS

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(GRCOOK) Installed GPS SN: 87U030240167 in unit 3872C-GC

(LRUSHING) Visit Reason Changed On 3/27/2024 8:41 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 3/27/2024 8:41 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50434

USING DEPT NO:	507121	OPENED DATE:	04/04/2024 15:47:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2024 08:40:01	METER 1 - M:	35517	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2024 10:34:05	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-028	INSTALL WINDOW TINT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$189.75	\$189.75
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	N	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	194.75	253.75
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
14-78-028	INSTALL WINDOW TINT	8616313	2368		\$189.75
				COMML	194.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	11399745	04/22/2024 07:00:00	04/22/2024 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50434

Work Order Notes

(LRUSHING) full tint and strip across the top

Job Notes

14-78-028 - INSTALL WINDOW TINT

(LISAPATE) Custom films added tint to both front windows and windshield strip. PD by PO

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 4/30/2024 7:42 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50925

USING DEPT NO:	507121	OPENED DATE:	05/23/2024 08:53:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/24/2024 08:00:16	METER 1 - M:	37987	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2024 08:00:20	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.02	\$2.88	\$0.00	\$0.00	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.38	\$69.24	\$0.00	\$70.62
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.04	4.26	69.24	5.00	78.50
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	05/23/2024 11:01:15	05/23/2024 11:02:43	0.02	\$2.88
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/23/2024 11:00:07	05/23/2024 11:00:49	0.01	\$1.38
				LABOR	4.26	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
					PARTS	69.24

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 50925

Work Order Notes

(EHANNAH) pm

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Perform rotate tires and check brakes F 8-m R -8m fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc -sh

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51036

USING DEPT NO:	507121	OPENED DATE:	06/05/2024 12:36:40	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2024 10:46:51	METER 1 - M:	38231	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/06/2024 11:15:07	IN-SERVICE DATE:	10/29/2021						
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer			UNIT SERIAL NO:	1FMSK7BH7MGB98292					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
17-GA-005	RECALL Scheduling and Preparation	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-22-014	REPAIR REAR AXLE BEARING	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2		WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51036

Work Order Notes

(EHANNAH) prep and scheduling- RECALL rear axle bolt

Job Notes

17-GA-005 - RECALL Scheduling and Preparation

(EHANNAH) prep and scheduling by Denise.

(LRUSHING) Visit Reason Changed On 6/26/2024 1:19 PM By LRUSHING

24-22-014 - REPAIR REAR AXLE BEARING

(EHANNAH) LL Ford came to out shop for Recall for rea ale bolt.

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51626

USING DEPT NO:	507121	OPENED DATE:	07/29/2024 09:08:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/31/2024 16:50:28	METER 1 - M:	41058	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2024 08:46:26	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-061	REPAIR WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$91.94	\$91.94
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	96.94	96.94
--------------	-------------------	------	------	------	-------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-02-061	REPAIR WINDSHIELD	11078716	120268		\$91.94
24-02-061	REPAIR WINDSHIELD	11078716	120268		\$91.94
24-02-061	REPAIR WINDSHIELD	11078716	120268		(\$91.94)
				COMML	96.94

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51626

Work Order Notes

(EKIMBREL) repair windshield

Job Notes

24-02-061 - REPAIR WINDSHIELD

(EKIMBREL) glass dr repaired windshield

(LRUSHING) Visit Reason Changed On 8/21/2024 8:57 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/21/2024 8:57 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51781

USING DEPT NO:	507121	OPENED DATE:	08/13/2024 08:12:45	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/17/2024 07:57:42	METER 1 - M:	42526	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/17/2024 08:14:29	IN-SERVICE DATE:	10/29/2021						
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer									
				UNIT SERIAL NO:	1FMSK7BH7MGB98292						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$91.74	\$0.00	\$91.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	91.74	5.00	96.74
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FA1884	AIR FILTER	22.50	1	\$22.50
66-PM-PMA	PERFORM OIL CHANGE	SF16	SEA FOAM 16OZ	13.11	1	\$13.11
66-PM-PMA	PERFORM OIL CHANGE	5W30BT	5W30 BULK	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
PARTS						91.74

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 51781

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure
Miles, 42,526

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 52000

USING DEPT NO:	507121	OPENED DATE:	09/03/2024 10:59:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2024 08:46:00	METER 1 - M:	43584	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2024 12:58:44	IN-SERVICE DATE:	10/29/2021	
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer		UNIT SERIAL NO:	1FMSK7BH7MGB98292	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	N	N	GARAGE	0.00	\$0.00	\$11.60	\$0.00	\$11.60
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	11.60	5.00	16.60
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	20046	SNAP-IN VALVE FORD INTERCEPTOR	6.06	1	\$6.06
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.81	1	\$2.81
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	14	\$2.73
PARTS						11.60

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 52000

Work Order Notes

(EHANNAH) tire patch in DR- nail in it
(GARAGE) P

Job Notes

66-17-030 - PERFORM TIRE PATCH

(GARAGE) Performed tire patch, vehicle had screw in driver rear tire and could be patched, broke down tire and patched and mounted tire and inspected patch and found np issues, balanced tire and reinstall tire on vehicle-GC
Miles, 43,584

CH-SP - CHARGE Shop Supplies

(AJONES) Visit Reason Changed On 9/9/2024 11:27 AM By AJONES

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 52786

USING DEPT NO:	507121	OPENED DATE:	11/12/2024 09:01:41	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2024 13:23:44	METER 1 - M:	47052	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2024 15:31:50	IN-SERVICE DATE:	10/29/2021						
TECH SPEC NO:	21FORDEXPLOR	2021 Ford Explorer									
		UNIT SERIAL NO:	1FMSK7BH7MGB98292								

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-35-019	REMOVE POWER INVERTER	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 3						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 12/18/2024 11:36:36 By User: GLOBETTI

UNIT NO: 244080 2021 FORD EXPLORER

WORK ORDER NO: 52786

Work Order Notes

(EHANNAH) remover power inverter to install in new vehicle. new vehicle comes next week.

Job Notes

25-35-019 - REMOVE POWER INVERTER

(GARAGE) removed power inverter prep for sale checked ok, cm
(EHOWELL) Visit Reason Changed On 11/21/2024 1:23 PM By EHOWELL

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) CM removed GPS# 87U030240167.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EHOWELL) CM performed prep for sale.
(IFALLS) cm removed police lights to sell a civilian unit

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed Dec 18 2024 11:36:36 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244080') //Q=