

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10164

USING DEPT NO:	504302	OPENED DATE:	01/26/2012 07:32:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2012 07:16:50	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2012 07:16:52	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.39	\$80.01	\$182.44	\$0.00	\$262.45

JOB COUNT: 2	WORK ORDER TOTAL:	2.89	166.26	182.44	0.00	348.70
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	10260422	01/26/2012 10:25:08	01/26/2012 11:48:37	1.39	\$80.01
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	11397026	01/26/2012 17:00:00	01/26/2012 18:30:00	1.50	\$86.25
					LABOR	166.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.65	1	\$17.65
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.07	5	\$90.37
66-PM-PMA	PERFORM OIL CHANGE	2813	AIR FILTER	69.51	1	\$69.51
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
					PARTS	182.44

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10164

Work Order Notes

(LPATE) PM

Job Notes

35-40 - DIAGNOSE ENGINE / MOTOR SYSTEMS

(LPATE) CHECKED FOR OIL LEAK HAD TO PRESSURE WASH UNDERNEATH TRUCK, TIGHTENED UP OIL PAN BOLTS HAD SLIGHT SEEPAGE LET RUN FOR AWHILE DID NOT SEE ANY OTHER LEAKS.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 12.05

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY RT/GM-REPLACED AIR FILTER-LUBED FRONT DRIVE SHAFT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10424

USING DEPT NO:	504302	OPENED DATE:	02/23/2012 07:41:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/24/2012 14:33:20	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/24/2012 14:33:22	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-13-003	ADJUST PARKING BRAKES	DON	O	N	GARAGE	1.00	\$57.50	\$5.59	\$0.00	\$63.09
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
PU-51-058	PURCHASED GREASE GUN	DON	O	N	GARAGE	0.30	\$17.25	\$51.36	\$0.00	\$68.61

JOB COUNT: 3	WORK ORDER TOTAL:	1.80	103.50	56.95	0.00	160.45
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PU-51-058	PURCHASED GREASE GUN	11397026	02/24/2012 17:30:00	02/24/2012 17:48:00	0.30	\$17.25
06-13	INSPECT BRAKES	11397026	02/24/2012 17:00:00	02/24/2012 17:30:00	0.50	\$28.75
01-13-003	ADJUST PARKING BRAKES	11397026	02/24/2012 17:30:00	02/24/2012 18:30:00	1.00	\$57.50
					LABOR	103.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
01-13-003	ADJUST PARKING BRAKES	DOR20753	BRAKE PEDAL COVER	5.59	1	\$5.59
PU-51-058	PURCHASED GREASE GUN	TUBE GREASE	TUBE GREASE	3.45	1	\$3.45
PU-51-058	PURCHASED GREASE GUN	ALEF103	GREASE GUN	36.72	1	\$36.72
PU-51-058	PURCHASED GREASE GUN	AFF8018	18" GREASE GUN HOSE	11.19	1	\$11.19
					PARTS	56.95

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10424

Work Order Notes

(LPATE) CHECK BRAKES PER TIM EMERGENCY BRAKE IS NOT HOLDING.

Job Notes

01-13-003 - ADJUST PARKING BRAKES

(LPATE) SHOES LOOK GOOD, ADJUSTED EMERGENCY BRAKES, RETESTED OK. REPLACED BRAKE PEDAL COVER IN TRUCK.

06-13 - INSPECT BRAKES

(LPATE) REMOVED DRIVESHAFT FOR ACCESS TO REMOVE EMERGENCY BRAKE DRUM. CHECKED EMERGENCY BRAKE SHOES.

PU-51-058 - PURCHASED GREASE GUN

(RWINTERS) GREASED LIFT ASSY. GAVE TIM A MANUAL GREASE GUN WITH EXTENSION HOSE AND A TUBE OF GREASE TO LUBE LIFTGATE AS NEEDED.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10732

USING DEPT NO:	504302	OPENED DATE:	04/09/2012 13:13:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/10/2012 14:17:25	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/10/2012 14:17:27	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCI	DON	O	N	GARAGE	0.00	\$0.00	\$41.94	\$0.00	\$41.94

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	41.94	0.00	41.94
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	1366	OPEN GEAR GREASE SPRAY	10.49	4	\$41.94
					PARTS	41.94

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 10732

Work Order Notes

(LPATE) TIM REQUESTED BLACK OPEN GEAR GREASE SPRAY FOR LIFTGATE ON TRUCK

Job Notes

PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LPATE) GAVE TIM 4 CANS OF GREASE FOR LIFTGATE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 11300

USING DEPT NO:	504302	OPENED DATE:	06/26/2012 08:57:35	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	08/08/2012 13:26:30	METER 1 - M:	25155	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/08/2012 13:26:32	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650			UNIT SERIAL NO:	3FRNF65Y56V356324			

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-047	REPLACE NEW SEAT BELTS	DON	O	N	GARAGE	2.54	\$145.97	\$193.36	\$0.00	\$339.33
03-05-024	REPLACE NEW EGR VALVE	DON	O	N	GARAGE	1.89	\$108.51	\$257.53	\$0.00	\$366.04
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$869.53	\$869.53
03-41-008	REPLACE NEW INTAKE GASKET(S)	DON	O	N	GARAGE	2.72	\$156.32	\$748.05	\$0.00	\$904.37
03-42-028	REPLACE NEW COOLANT RESERVOIR	DON	O	N	GARAGE	0.51	\$29.34	\$249.96	\$0.00	\$279.30
03-43-004	REPLACE NEW TURBOCHARGER	DON	O	N	GARAGE	3.50	\$201.46	\$2,850.45	\$0.00	\$3,051.91
03-53-006	REPLACE NEW WORDMARKS/IDENTIFI	DON	O	N	GARAGE	0.25	\$14.38	\$22.50	\$0.00	\$36.88
06-43-004	INSPECT TURBOCHARGER	DON	O	N	GARAGE	8.28	\$476.05	\$0.00	\$0.00	\$476.05
16-05	TRANSPORT ELECTRONIC ENGINE EE	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
16-41	TRANSPORT AIR INTAKE SYSTEM	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
36-42-016	FLUSH FLUSH COOLING SYSTEM	DON	O	N	GARAGE	0.84	\$48.40	\$69.36	\$0.00	\$117.76
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.07	\$119.11	\$109.30	\$0.00	\$228.41
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	1.09	\$62.93	\$23.67	\$0.00	\$86.60
AD-42-007	ADDED COOLANT FILTER	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
CL-41-002	CLEANED INTAKE MANIFOLD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$207.00	\$207.00
PR-05-020	PROGRAM PCM/PROCESSOR ASSEMB	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$241.50	\$241.50

JOB COUNT: 17	WORK ORDER TOTAL:	29.70	1,707.47	4,524.18	1,318.03	7,549.68
---------------	-------------------	-------	----------	----------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11075943	D226253	0016786	\$869.53
PR-05-020	PROGRAM PCM/PROCESSOR ASSEMBLY	11099772	FDCS530826	0016799	\$241.50
CL-41-002	CLEANED INTAKE MANIFOLD	6166005	149	0016861	\$207.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

					COMML	1318.03
<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-41	TRANSPORT AIR INTAKE SYSTEM	10260422	08/06/2012 07:00:00	08/06/2012 09:00:00	2.00	\$115.00
03-05-024	REPLACE NEW EGR VALVE	11397026	07/24/2012 14:30:00	07/24/2012 15:10:39	0.68	\$38.96
03-05-024	REPLACE NEW EGR VALVE	11397026	07/24/2012 13:02:25	07/24/2012 14:15:00	1.21	\$69.56
03-43-004	REPLACE NEW TURBOCHARGER	11397026	07/20/2012 14:30:00	07/20/2012 15:00:46	0.51	\$29.49
03-43-004	REPLACE NEW TURBOCHARGER	11397026	07/20/2012 11:15:33	07/20/2012 14:15:00	2.99	\$171.97
03-41-008	REPLACE NEW INTAKE GASKET(S)	11397026	07/19/2012 14:30:00	07/19/2012 15:58:11	1.47	\$84.51
03-41-008	REPLACE NEW INTAKE GASKET(S)	11397026	07/19/2012 13:00:04	07/19/2012 14:15:00	1.25	\$71.81
16-05	TRANSPORT ELECTRONIC ENGINE EEC SYSTEM	11074414	08/06/2012 07:00:00	08/06/2012 09:00:00	2.00	\$115.00
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	11074414	08/06/2012 07:00:00	08/06/2012 07:15:00	0.25	\$14.38
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10260422	08/06/2012 07:00:00	08/06/2012 08:00:00	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11397026	08/02/2012 14:30:25	08/02/2012 15:36:05	1.09	\$62.93
36-42-016	FLUSH FLUSH COOLING SYSTEM	11397026	08/02/2012 11:07:49	08/02/2012 11:58:19	0.84	\$48.40
03-02-047	REPLACE NEW SEAT BELTS	11397026	08/02/2012 09:30:00	08/02/2012 10:19:43	0.83	\$47.64
03-02-047	REPLACE NEW SEAT BELTS	11397026	08/02/2012 07:32:24	08/02/2012 09:15:00	1.71	\$98.33
03-42-028	REPLACE NEW COOLANT RESERVOIR	11397026	08/02/2012 07:01:29	08/02/2012 07:32:06	0.51	\$29.34
06-43-004	INSPECT TURBOCHARGER	11397026	07/23/2012 14:30:00	07/24/2012 09:15:00	(18.75)	(\$1,078.13)
06-43-004	INSPECT TURBOCHARGER	11397026	07/24/2012 09:30:00	07/24/2012 13:01:45	3.53	\$202.93
06-43-004	INSPECT TURBOCHARGER	11397026	07/23/2012 14:30:00	07/24/2012 09:15:00	18.75	\$1,078.13
06-43-004	INSPECT TURBOCHARGER	11397026	07/23/2012 09:30:00	07/23/2012 14:15:00	4.75	\$273.13
06-43-004	INSPECT TURBOCHARGER	11397026	07/20/2012 15:01:21	07/23/2012 09:15:00	(66.23)	(\$3,808.08)
06-43-004	INSPECT TURBOCHARGER	11397026	07/20/2012 15:01:21	07/23/2012 09:15:00	66.23	\$3,808.08
66-PM-PMA	PERFORM OIL CHANGE	10260422	06/26/2012 09:54:42	06/26/2012 11:58:59	2.07	\$119.11
AD-42-007	ADDED COOLANT FILTER	11397026	08/06/2012 07:00:00	08/06/2012 08:00:00	1.00	\$57.50

LABOR 1707.49

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.65	1	\$17.65
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.33	5	\$91.65
03-43-004	REPLACE NEW TURBOCHARGER	EGR COOLER	EGR COOLER	478.50	1	\$478.50
03-43-004	REPLACE NEW TURBOCHARGER	ADP4C3Z9B246F	STC FITTING UPGRADE	88.50	1	\$88.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-43-004	REPLACE NEW TURBOCHARGER	SMCCOOLFIL	COOLANT BYPASS SYSTEM	222.00	1	\$222.00
03-53-006	REPLACE NEW WORDMARKS/IDENTIFIERS	WORDMARK	WORDMARK-CRIMSON/ GRAY	22.50	1	\$22.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	23.67	1	\$23.67
03-43-004	REPLACE NEW TURBOCHARGER	EAT62414	FIREPROOF SLEEVE	22.43	6	\$134.55
03-41-008	REPLACE NEW INTAKE GASKET(S)	15W40	OIL GAL BOTTLE (DIESEL)	18.33	5	\$91.65
03-41-008	REPLACE NEW INTAKE GASKET(S)	C111	RED BRAKE CLEANER	4.91	4	\$19.62
36-42-016	FLUSH FLUSH COOLING SYSTEM	COOLANT FLUSH	COOLANT FLUSH	4.03	1	\$4.03
03-41-008	REPLACE NEW INTAKE GASKET(S)	20 CLAMP	CLAMP 3/4-1 3/4	0.83	1	\$0.83
03-41-008	REPLACE NEW INTAKE GASKET(S)	P7235	FILTER-OIL	17.65	1	\$17.65
03-41-008	REPLACE NEW INTAKE GASKET(S)	15W40QT	DIESEL OIL QT DELO CK-4	4.62	2	\$9.24
36-42-016	FLUSH FLUSH COOLING SYSTEM	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	13.07	5	\$65.33
03-41-008	REPLACE NEW INTAKE GASKET(S)	PM22A	CETANE BOOSTER FOR DIESEL FUEL	10.11	12	\$121.32
03-42-028	REPLACE NEW COOLANT RESERVOIR	4C4Z8B379A	RADIATOR RESERVOIR	249.96	1	\$249.96
03-02-047	REPLACE NEW SEAT BELTS	8C4Z70611B09AA	SEAT BELT ASSY	57.17	1	\$57.17
03-02-047	REPLACE NEW SEAT BELTS	8C4Z70611B08AA	SEAT BELT ASSY	56.64	1	\$56.64
03-02-047	REPLACE NEW SEAT BELTS	6C4Z7061203AA	SEAT BELT ASSY	25.55	1	\$25.55
03-43-004	REPLACE NEW TURBOCHARGER	3C3Z6N640AA	EXHAUST GASKET	4.65	1	\$4.65
03-41-008	REPLACE NEW INTAKE GASKET(S)	3C3Z6A642CA	OIL COOLER KIT	440.89	1	\$440.89
03-41-008	REPLACE NEW INTAKE GASKET(S)	3C3Z9439AA	INTAKE GASKETS	14.70	2	\$29.40
03-02-047	REPLACE NEW SEAT BELTS	6C4Z70611B60BA	SEAT BELT ASSY	47.11	1	\$47.11
03-43-004	REPLACE NEW TURBOCHARGER	5C4Z6K682BRM	TURBOCHARGER	1864.80	1	\$1,864.80
03-43-004	REPLACE NEW TURBOCHARGER	3C3Z9H529A	IPR SCREEN AND SEAL KIT	57.45	1	\$57.45
03-05-024	REPLACE NEW EGR VALVE	5C4Z9F452AA	EGR VALVE	257.53	1	\$257.53
03-41-008	REPLACE NEW INTAKE GASKET(S)	6C3Z9T515A	TUBE ASSY	35.10	1	\$35.10
03-02-047	REPLACE NEW SEAT BELTS	6C4Z70611B60BA	SEAT BELT ASSY	47.11	(1)	(\$47.11)
03-41-008	REPLACE NEW INTAKE GASKET(S)	P7235	FILTER-OIL	17.65	(1)	(\$17.65)
03-02-047	REPLACE NEW SEAT BELTS	FREIGHT	SHIPPING CHARGES	52.50	1	\$52.50
03-02-047	REPLACE NEW SEAT BELTS	FREIGHT	SHIPPING CHARGES	52.50	(1)	(\$52.50)
03-02-047	REPLACE NEW SEAT BELTS	FREIGHT	SHIPPING CHARGES	54.00	1	\$54.00
					PARTS	4524.18

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **11300**

Work Order Notes

(LPATE) PM-REPLACE FRONT STEERING TIRES-INSPECT TURBO-REPLACED WORDMARK ON 1 DOOR.

Job Notes

Work Order Charge Detail

03-02-047 - REPLACE NEW SEAT BELTS

(LPATE) INSTALLED NEW DRIVER AND PASSENGER SEAT BELT HARNESS. ALSO REPLACED DRIVER SEAT BELT BUCKLE.

03-05-024 - REPLACE NEW EGR VALVE

(RWINTERS) REPLACED EGR COOLER, OIL COOLER PIPE, OIL COOLER, HIGH PRESSURE OIL PUMP FITTING AND EGR VALVE. CHANGED OIL AGAIN.

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) GOODYEAR REPLACED 2 TIRES M&B. P0040478.

03-41-008 - REPLACE NEW INTAKE GASKET(S)

(LPATE) REMOVED IPR SENSOR, REMOVED COVER INSTALLED HIGH PRESSURE OIL PUMP KIT. REPLACED ORINGS ON IPR SENSOR. TEST DROVE AFTER ALL WORK COMPLETED. EVERYTHING OK.

03-42-028 - REPLACE NEW COOLANT RESERVOIR

(LPATE) REPLACED COOLANT RESERVOIR WAS CRACKED.

03-43-004 - REPLACE NEW TURBOCHARGER

(LPATE) R&R NEW TURBO ASSY.

03-53-006 - REPLACE NEW WORDMARKS/IDENTIFIERS

(LPATE) INSTALLED NEW PASSENGER DOOR WORDMARK WAS PEELING

(LPATE) REPLACED WORDMARK ON PASSENGER DOOR

06-43-004 - INSPECT TURBOCHARGER

(RWINTERS) CHECKED OUT, EGR VALVE HAD SEVERE COKING. DISASSEMBLED TURBO FOUND TURBO STUTTED AND ACTUATOR VANE SHAFT GUMMED UP, ONLY WORKING @ 50% STROKE.

16-05 - TRANSPORT ELECTRONIC ENGINE EEC SYSTEM

(LPATE) SH DROVE TO LONG LEWIS FORD AND BACK.

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO GOODYEAR BY GM

16-41 - TRANSPORT AIR INTAKE SYSTEM

(LPATE) TAKEN TO RON SPORL BY GM

36-42-016 - FLUSH FLUSH COOLING SYSTEM

(LPATE) FLUSHED COOLING SYSTEM. WITH FLUSH REPLACED COOLANT WITH NEW DIESEL 50/50 ANTIFREEZE.

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

(LPATE)

The following parts are included with the standard job:

Part No : 15W40
Qty : 5
Description : OIL BOTTLE (DIESEL)
Manufacturer :

Part No : P7235
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : TUBE GREASE
Qty : 1
Description : TUBE GREASE
Manufacturer :

(LPATE) PM BY GM

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA
Qty : 1
Description : FUEL FILTER
Manufacturer :

(LPATE) REPLACED FUEL FILTER

AD-42-007 - ADDED COOLANT FILTER

(RWINTERS) INSTALLED COOLING SYSTEM FILTER KIT.

CL-41-002 - CLEANED INTAKE MANIFOLD

(LPATE) RON SPORL IN BESSEMER CLEANED INTAKE MANIFOLD 3 TIMES. PD BY CC ON PAYPAL.

PR-05-020 - PROGRAM PCM/PROCESSOR ASSEMBLY

(LPATE) PER LONG LEWIS INVOICE-ENGINE LOOSES POWER AT TIMES.DERATING OR GOING TO IDLE SPEED WHEN ACCEL. CHECK AND ADVISE \$105.00. EGR VALVE GUMMED W/WET CARBON FROM EGR COOLER LEAKAGE VERIFIED CONCERN. RUN ECM TEST, NO DTC'S FOUND. KOER PASS, EGR SYSTEM TEST DTC 346. FOLLO' EGRM TEST TO FIND EGR VALVE STICKING. REMOVED EGR VALVE FOR INPS TO FIND PLUGGED W/WET CARBON. QUOTED \$3124.00. CUSTOMER DECLINED. CUSTOMER REQUESTED LATEST PROGRAMMING UPDATE IF DOES NOT HAVE DOWNLOAD AND UPLIKNK ECM DATA. REPROGRAM PCMW/DLC04500679 AND IDM W/DLC4504178 \$105.00.

Work Order Charge Detail

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 11891

USING DEPT NO:	504302	OPENED DATE:	09/12/2012 15:29:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2012 07:54:26	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2012 07:54:28	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	P	N	GARAGE	0.20	\$11.50	\$21.48	\$0.00	\$32.98
03-55-044	REPLACE NEW LIFTGATE DUAL CONTF	DON	O	N	GARAGE	1.00	\$57.50	\$827.53	\$0.00	\$885.03

JOB COUNT: 2	WORK ORDER TOTAL:	1.20	69.00	849.01	0.00	918.01
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	11268671	09/27/2012 06:00:00	09/27/2012 07:00:00	1.00	\$57.50
03-42-007	REPLACE NEW COOLANT FILTER	11397026	09/18/2012 14:30:00	09/19/2012 08:04:17	(17.57)	(\$1,010.36)
03-42-007	REPLACE NEW COOLANT FILTER	11397026	09/18/2012 14:30:00	09/19/2012 08:04:17	17.57	\$1,010.36
03-42-007	REPLACE NEW COOLANT FILTER	11397026	09/18/2012 11:46:17	09/18/2012 14:15:00	(2.48)	(\$142.52)
03-42-007	REPLACE NEW COOLANT FILTER	11397026	09/18/2012 11:46:17	09/18/2012 14:15:00	2.48	\$142.52
03-42-007	REPLACE NEW COOLANT FILTER	11397026	09/17/2012 07:00:00	09/17/2012 07:12:00	0.20	\$11.50
					LABOR	69.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	80000437	DUAL CONTROL SWITCH KIT	201.60	4	\$806.40
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	SHIPPING	SHIPPING AND HANDLING	15.84	1	\$15.84
03-42-007	REPLACE NEW COOLANT FILTER	4070	FILTER	8.41	1	\$8.41
03-42-007	REPLACE NEW COOLANT FILTER	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	13.07	1	\$13.07
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	PTX81158	SILICONE-BLACK	5.29	1	\$5.29
					PARTS	849.01

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 11891

Work Order Notes

(LPATE) REPLACE COOLANT FILTER-TIM REQUESTED NEW DUAL SWITCH FOR LIFTGATE ON TRUCK.

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(GMANNING) BG REPLACED COOLANT FILTER, TOPPED OFF COOLANT RESEVOIR, RECHECKED OK.

03-55-044 - REPLACE NEW LIFTGATE DUAL CONTROL SWITCH

(LPATE) REPLACED SWITCH ON LIFTGATE AND RELOCATED IT HIGHER UP AND REROUTED THE WIRING. PUT SILICONE IN THE OLD HOLE SO WATER WOULD NOT GET IN. PUT EXTRA SWITCHS ORDERED IN TRUCK TO BE AVAILABE WHEN NEEDED.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 12402

USING DEPT NO:	504302	OPENED DATE:	11/16/2012 10:14:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2012 14:27:24	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/19/2012 14:27:25	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	P	N	GARAGE	0.25	\$14.38	\$8.41	\$0.00	\$22.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$16.77	\$185.68	\$0.00	\$202.45
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.31	\$17.83	\$25.71	\$0.00	\$43.54

JOB COUNT: 3	WORK ORDER TOTAL:	0.85	48.98	219.80	0.00	268.78
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-007	REPLACE NEW COOLANT FILTER	11338644	11/19/2012 07:00:00	11/19/2012 07:15:00	0.25	\$14.38
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	11/19/2012 07:00:00	11/19/2012 07:18:36	0.31	\$17.83
66-PM-PMA	PERFORM OIL CHANGE	11338644	11/16/2012 15:34:42	11/16/2012 15:52:12	0.29	\$16.77
					LABOR	48.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	66.72	1	\$66.72
03-42-007	REPLACE NEW COOLANT FILTER	4070	FILTER	8.41	1	\$8.41
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	25.71	1	\$25.71
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	2	\$9.81
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.30	5	\$91.50
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.65	1	\$17.65
					PARTS	219.80

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 12402

Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER AND COOLANT FILTER-LUBE LIFT GATE.
(RWINTERS)

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(RWINTERS) REPLACED THE COOLANT FUEL FILTER.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)
The following parts are included with the standard job:

Part No : 15W40
Qty : 5
Description : OIL BOTTLE (DIESEL)
Manufacturer :

Part No : P7235
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : TUBE GREASE
Qty : 1
Description : TUBE GREASE
Manufacturer :

(RWINTERS) PM AND LUBE LIFTGATE-RS

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)
The following parts are included with the standard job:

Part No : F81Z9N184AA
Qty : 1
Description : FUEL FILTER
Manufacturer :

(RWINTERS) REPLACED THE FUEL FILTER.

Work Order Charge Detail

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 12756

USING DEPT NO:	504302	OPENED DATE:	01/11/2013 08:04:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/11/2013 14:51:01	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/11/2013 14:51:03	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$210.22	\$0.00	\$210.22

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	210.22	0.00	210.22
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	25.72	1	\$25.72
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	12.75	(1)	(\$12.75)
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	12.75	1	\$12.75
PU-55-012	PURCHASED CARGO RESTRAINTS	USCCBEF	2" CUSTOM CAMBUCKLE STRAP	18.00	6	\$108.00
PU-55-012	PURCHASED CARGO RESTRAINTS	USCCBEF	2" CUSTOM CAMBUCKLE STRAP	25.50	3	\$76.50
					PARTS	210.22

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **12756**

Work Order Notes

(LPATE) TIM AND ARTHUR REQUESTED EXTRA HEAVY DUTY STRAPS FOR MOVERS TRUCKS TO SECURE CARGO.

Job Notes

PU-55-012 - PURCHASED CARGO RESTRAINTS

(LPATE) PURCHASED STRAPS AND GAVE TO TIM.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13218

USING DEPT NO:	504302	OPENED DATE:	03/05/2013 15:19:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2013 06:45:02	METER 1 - M:	25155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/06/2013 06:45:03	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCI	DON	O	N	GARAGE	0.00	\$0.00	\$37.89	\$0.00	\$37.89

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	37.89	0.00	37.89
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	16TDL	PB DRY LUBE PTFE AERO 9.3OZ	9.35	3	\$28.04
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	TUBE GREASE	TUBE GREASE	3.28	3	\$9.85
					PARTS	37.89

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13218

Work Order Notes

(RWINTERS) TIM REQUESTED LUBE AND GREASE FOR HIS DOOR AND LIFTGATE ON TRUCK

Job Notes

PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LPATE) GAVE TIM 3 CANS OF LUBE AND 3 TUBES OF GREASE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13631

USING DEPT NO:	504302	OPENED DATE:	04/25/2013 07:25:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/09/2013 06:59:17	METER 1 - M:	31379	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/09/2013 06:59:19	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	O	N	GARAGE	0.50	\$28.75	\$17.23	\$0.00	\$45.98
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-02-017	REPAIR DOOR PANELS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$227.47	\$0.00	\$284.97
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.60	\$34.50	\$0.00	\$0.00	\$34.50

JOB COUNT: 5	WORK ORDER TOTAL:	3.10	178.25	244.70	0.00	422.95
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11413680	05/08/2013 07:00:00	05/08/2013 08:00:00	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11413680	05/03/2013 08:00:00	05/03/2013 08:36:00	0.60	\$34.50
66-PM-PMA	PERFORM OIL CHANGE	11413680	05/03/2013 07:00:00	05/03/2013 08:00:00	1.00	\$57.50
03-42-007	REPLACE NEW COOLANT FILTER	11413680	05/03/2013 08:36:00	05/03/2013 09:06:00	0.50	\$28.75
					LABOR	178.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.30	5	\$91.50
66-PM-PMA	PERFORM OIL CHANGE	PM22A	CETANE BOOSTER FOR DIESEL FUEL	10.57	1	\$10.57
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	66.72	1	\$66.72
66-PM-PMA	PERFORM OIL CHANGE	WIX33818	FUEL FILTER	45.85	1	\$45.85
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	7.97	1	\$7.97
03-42-007	REPLACE NEW COOLANT FILTER	BALP7235	OIL FILTER	17.23	1	\$17.23
					PARTS	244.70

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13631

Work Order Notes

(LPATE) PM, REPAIR REAR DOOR, REPLACE FUEL FILTER AND COOLANT FILTER

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(LPATE) REPLACED COOLANT FILTER

16-02 - TRANSPORT CAB & SHEET METAL

(LPATE) TAKEN TO OVERHEAD DOOR BY RT

24-02-017 - REPAIR DOOR PANELS

(RWINTERS) WASTE MGMT RECYCLING DAMAGED REAR DOOR ON TRUCK (CONTACT PERSON JEFF JONES 758-1838). WASTE MGMT WILL PAY THEM DIRECT NO INVOICE AND NO CHARGE TO UA.

(RWINTERS) LOWER PANEL AND ROLLERS REPLACED...STILL HAS ISSUE WITH DOOR OPENING AND CLOSING (STIFF) UPPER SPRINGS ON ORDER. WILL BE INSTALLED AT A LATER DATE WHEN PARTS ARRIVE BY GAVIN @ OVERHEAD DOOR.

66-PM-PMA - PERFORM OIL CHANGE

(GMANNING)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.05

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY RT/RS

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13953

USING DEPT NO:	504302	OPENED DATE:	05/28/2013 09:35:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2013 14:50:46	METER 1 - M:	31738	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/28/2013 14:50:48	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
01-13-109	ADJUST EMERGENCY BRAKE RELEASE	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
01-13-109	ADJUST EMERGENCY BRAKE RELEASE HANDLE	11338644	05/28/2013 09:36:45	05/28/2013 10:06:45	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 13953

Work Order Notes

(LPATE) PER TIM EMERGENCY BRAKE HANDLE WILL NOT HOLD

Job Notes

01-13-109 - ADJUST EMERGENCY BRAKE RELEASE HANDLE

(LPATE) ADJUSTED THE BACK OFF WAS NOT HOLDING. RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 1409

USING DEPT NO:	504302	OPENED DATE:	05/28/2008 15:21:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/28/2008 15:31:46	METER 1 - M:	9523	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	05/28/2008 15:31:47	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$45.00	\$113.66	\$0.00	\$158.66
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.60	\$27.00	\$48.59	\$0.00	\$75.59

JOB COUNT: 2	WORK ORDER TOTAL:	1.60	72.00	162.25	0.00	234.25
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11088474	05/28/2008 16:22:00	05/28/2008 16:58:00	0.60	\$27.00
66-PM-PMA	PERFORM OIL CHANGE	11088474	05/28/2008 15:22:00	05/28/2008 16:22:00	1.00	\$45.00
					LABOR	72.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	VC7B	GOLD ANTIFREEZE	19.05	1	\$19.05
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	F81Z9N184AA	FUEL FILTER	48.59	1	\$48.59
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.43	1	\$2.43
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	20.85	1	\$20.85
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	14.27	5	\$71.33
					PARTS	162.25

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 1409

Work Order Notes

(LOBRIEN) PM AND FUEL FILTER.

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LOBRIEN) PM BY JASON ELMORE.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LOBRIEN) R&R FUEL FILTER.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14214

USING DEPT NO:	504302	OPENED DATE:	06/26/2013 13:41:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/08/2013 14:09:41	METER 1 - M:	32201	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/08/2013 14:09:44	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.50	\$28.75	\$79.41	\$0.00	\$108.16
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '1	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	79.41	0.00	136.91
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11268671	07/05/2013 07:00:00	07/05/2013 07:30:00	0.50	\$28.75
03-01-004	REPLACE NEW BLOWER MOTOR	11397026	07/05/2013 07:00:00	07/05/2013 07:30:00	0.50	\$28.75
					LABOR	57.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-01-004	REPLACE NEW BLOWER MOTOR	TYC700099	BLOWER MOTOR	79.41	1	\$79.41
					PARTS	79.41

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14214

Work Order Notes

(GMANNING) A/C NOT WORKING

Job Notes

03-01-004 - REPLACE NEW BLOWER MOTOR

(GMANNING) BG REPLACED BLOWER MOTOR. RECHECKED OK.

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(GMANNING) BLOWER MOTOR INOP

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14741

USING DEPT NO:	504302	OPENED DATE:	08/27/2013 15:05:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/28/2013 08:40:03	METER 1 - M:	32830	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/28/2013 08:40:05	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-35-006	REPLACE NEW FUSE(S)	DON	O	N	GARAGE	0.50	\$28.75	\$1.86	\$0.00	\$30.61
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:	1.50	86.25	1.86	0.00	88.11
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11397026	08/27/2013 15:07:25	08/27/2013 16:07:25	1.00	\$57.50
03-35-006	REPLACE NEW FUSE(S)	11397026	08/27/2013 15:07:32	08/27/2013 15:37:32	0.50	\$28.75
					LABOR	86.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-35-006	REPLACE NEW FUSE(S)	PIC0963C	FUSE HOLDER	1.86	1	\$1.86
					PARTS	1.86

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14741

Work Order Notes

(LPATE) TIM REQUESTED SERVICE CALL TO CAPSTONE VILLAGE TRUCK WILL NOT CRANK

Job Notes

03-35-006 - REPLACE NEW FUSE(S)

(LPATE) FOUND BLOWN 40 AMP FUSE IN THE BATTERY BOX SOLDERED IN A NEW FUSE HOLDER AND INSTALLED ANOTHER 40 AMP FUSE. NO CHARGE FOR FUSES

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL TO CAPSTONE VILLAGE GOT TRUCK CRANKED DRIVER WILL BRING TO GARAGE TO REPAIR

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14831

USING DEPT NO:	504302	OPENED DATE:	09/09/2013 07:54:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/10/2013 13:58:24	METER 1 - M:	32958	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/10/2013 13:58:25	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-035	REPLACE NEW WATER/DCA FILTER	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.05	\$60.10	\$117.29	\$0.00	\$177.39
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.02	\$1.26	\$53.82	\$0.00	\$55.08

JOB COUNT: 3	WORK ORDER TOTAL:	1.57	90.11	171.11	0.00	261.22
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-035	REPLACE NEW WATER/DCA FILTER	11338644	09/09/2013 14:36:17	09/09/2013 15:06:17	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/09/2013 10:36:32	09/09/2013 11:39:15	1.05	\$60.10
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	09/09/2013 10:34:57	09/09/2013 10:36:16	0.02	\$1.26
					LABOR	90.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	3.25	1	\$3.25
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.39	5	\$91.95
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	1	\$45.85
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALB5134	COOLANT FILTER SPIN-ON	7.97	1	\$7.97
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	(1)	(\$45.85)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	1	\$45.85
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALB5134	COOLANT FILTER SPIN-ON	7.97	1	\$7.97
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALB5134	COOLANT FILTER SPIN-ON	7.97	(1)	(\$7.97)
					PARTS	171.11

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 14831

Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER-REPLACE WATER FILTER

Job Notes

03-42-035 - REPLACE NEW WATER/DCA FILTER

(LPATE) REPLACED WATER FILTER

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.05

(LPATE) PM BY BG/RS-GREASED THE LIFT GATE AND CHECKED FLUID WAS GOOD

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15174

USING DEPT NO:	504302	OPENED DATE:	10/21/2013 08:05:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/21/2013 14:18:01	METER 1 - M:	33416	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/21/2013 14:18:02	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-058	REPLACE NEW DOOR LOCK	DON	O	N	GARAGE	0.40	\$23.00	\$112.86	\$0.00	\$135.86
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
36-01-010	FLUSH EVAPORATOR	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.90	109.25	112.86	0.00	222.11
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
36-01-010	FLUSH EVAPORATOR	11268671	10/21/2013 10:51:47	10/21/2013 11:51:47	1.00	\$57.50
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11268671	10/21/2013 10:51:41	10/21/2013 11:21:41	0.50	\$28.75
03-02-058	REPLACE NEW DOOR LOCK	11268671	10/21/2013 10:51:35	10/21/2013 11:15:35	0.40	\$23.00
					LABOR	109.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-02-058	REPLACE NEW DOOR LOCK	XL1Z14028AB	DOOR LOCK SWITCH	62.57	1	\$62.57
03-02-058	REPLACE NEW DOOR LOCK	XL1Z14028AA	DOOR LOCK SWITCH	50.29	1	\$50.29
					PARTS	112.86

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15174

Work Order Notes

(LPATE) BOTH DOORS LOCKS WILL NOT WORK AT TIMES-A/C WILL BARELY BLOW OUT OF VENTS WHEN ON HIGH

Job Notes

03-02-058 - REPLACE NEW DOOR LOCK

(LPATE) REPLACED BOTH DOOR LOCK SWITCHES

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LPATE) CHECKED A/C EVAPORATOR IS CLOGGED UP

36-01-010 - FLUSH EVAPORATOR

(LPATE) FLUSHED OUT EVAP WITH WATER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15497

USING DEPT NO:	504302	OPENED DATE:	11/25/2013 14:36:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/25/2013 16:00:00	METER 1 - M:	33776	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2013 16:00:00	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$26.97	\$0.00	\$41.35

JOB COUNT: 1	WORK ORDER TOTAL:	0.25	14.38	26.97	0.00	41.35
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	11/25/2013 14:37:43	11/25/2013 14:52:43	0.25	\$14.38
					LABOR	14.38

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	13.49	2	\$26.97
					PARTS	26.97

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15497

Work Order Notes

(GMANNING) NEEDS WIPER BLADES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GMANNING) REPLACED BOTH WIPER BLADES.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15534

USING DEPT NO:	504302	OPENED DATE:	12/03/2013 09:37:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/04/2013 07:18:08	METER 1 - M:	33811	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/04/2013 07:18:09	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-50-100	REPLACE NEW BELT, SERPENTINE OR	DON	O	N	GARAGE	0.00	\$0.00	\$57.15	\$0.00	\$57.15
03-50-103	REPLACE NEW BELT TENSIONER	DON	O	N	GARAGE	1.50	\$86.25	\$217.55	\$0.00	\$303.80
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 3	WORK ORDER TOTAL:	2.00	115.00	274.70	0.00	389.70
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-50-103	REPLACE NEW BELT TENSIONER	11338644	12/03/2013 10:03:00	12/03/2013 12:39:00	(2.60)	(\$149.50)
03-50-103	REPLACE NEW BELT TENSIONER	11338644	12/03/2013 10:03:00	12/03/2013 12:39:00	2.60	\$149.50
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	11338644	12/03/2013 10:02:52	12/03/2013 10:32:52	0.50	\$28.75
03-50-103	REPLACE NEW BELT TENSIONER	11338644	12/03/2013 10:03:00	12/03/2013 11:33:00	1.50	\$86.25
					LABOR	115.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-50-103	REPLACE NEW BELT TENSIONER	49567	BELT TENSIONER	217.55	1	\$217.55
03-50-100	REPLACE NEW BELT, SERPENTINE OR MISC.	GATK080830HD	BELT	57.15	1	\$57.15
					PARTS	274.70

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15534

Work Order Notes

(LPATE) PER TIM HEARING A LOUD NOISE FROM ENGINE AREA

Job Notes

03-50-100 - REPLACE NEW BELT, SERPENTINE OR MISC.

(LPATE) REPLACED BELT

03-50-103 - REPLACE NEW BELT TENSIONER

(LPATE) REPLACED TENSIONER. RECHECKED OK

35-40 - DIAGNOSE ENGINE / MOTOR SYSTEMS

(LPATE) CHECKED BEARINGS ARE BAD IN TENSIONER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15554

USING DEPT NO:	504302	OPENED DATE:	12/04/2013 13:10:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2013 13:15:51	METER 1 - M:	33834	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2013 13:15:52	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$0.73	\$0.00	\$17.98

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	0.73	0.00	17.98
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11568366	12/04/2013 13:10:46	12/04/2013 13:28:46	0.30	\$17.25
					LABOR	17.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.73	1	\$0.73
					PARTS	0.73

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15554

Work Order Notes

(LPATE) FRONT LEFT BLINKER OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT FRONT BLINKER BULB

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15627

USING DEPT NO:	504302	OPENED DATE:	12/10/2013 14:17:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/17/2013 08:55:05	METER 1 - M:	33910	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/17/2013 08:55:06	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-044	REPLACE NEW FUEL LINES	DON	O	N	GARAGE	2.00	\$115.00	\$244.92	\$0.00	\$359.92
35-44	DIAGNOSE FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$12.97	\$0.00	\$41.72

JOB COUNT: 2	WORK ORDER TOTAL:	2.50	143.75	257.89	0.00	401.64
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-44-044	REPLACE NEW FUEL LINES	11397026	12/16/2013 07:00:00	12/16/2013 09:00:00	2.00	\$115.00
35-44	DIAGNOSE FUEL SYSTEM	11397026	12/12/2013 07:40:14	12/12/2013 07:45:03	(0.08)	(\$4.62)
35-44	DIAGNOSE FUEL SYSTEM	11397026	12/12/2013 07:40:14	12/12/2013 07:45:03	0.08	\$4.62
35-44	DIAGNOSE FUEL SYSTEM	11397026	12/12/2013 07:40:14	12/12/2013 08:10:14	0.50	\$28.75
					LABOR	143.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-044	REPLACE NEW FUEL LINES	FREIGHT	SHIPPING CHARGES	3.00	1	\$3.00
03-44-044	REPLACE NEW FUEL LINES	FREIGHT	SHIPPING CHARGES	6.00	(1)	(\$6.00)
03-44-044	REPLACE NEW FUEL LINES	FREIGHT	SHIPPING CHARGES	6.00	1	\$6.00
03-44-044	REPLACE NEW FUEL LINES	FREIGHT	SHIPPING CHARGES	9.00	1	\$9.00
03-44-044	REPLACE NEW FUEL LINES	4C4Z9324C	HOSE ASSEMBLY	65.70	1	\$65.70
03-44-044	REPLACE NEW FUEL LINES	4C4Z9324B	HOSE ASSEMBLY	51.75	1	\$51.75
03-44-044	REPLACE NEW FUEL LINES	4C4Z9J338BA	FUEL TUBE LINES	115.47	1	\$115.47
35-44	DIAGNOSE FUEL SYSTEM	4C4Z9J338BA	FUEL TUBE LINES	115.47	(1)	(\$115.47)
35-44	DIAGNOSE FUEL SYSTEM	4C4Z9J338BA	FUEL TUBE LINES	115.47	1	\$115.47
35-44	DIAGNOSE FUEL SYSTEM	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	12.97	1	\$12.97
					PARTS	257.89

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15627

Work Order Notes

(LPATE) PER DRIVER LEAKING DIESEL FUEL

Job Notes

03-44-044 - REPLACE NEW FUEL LINES

(GMANNING) REPLACED FUEL LINES GOING TO FUEL FILTER ADAPTER, ALSO REPLACED SHORT FUEL LINE QUICK CONNECTORS. RECHECKED, EVERYTHING OK.

35-44 - DIAGNOSE FUEL SYSTEM

(GMANNING) LEAKING FROM FUEL LINES GOING TO FUEL FILTER ADAPTER.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 15836

USING DEPT NO:	504302	OPENED DATE:	01/13/2014 08:03:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/06/2014 15:00:35	METER 1 - M:	34064	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/06/2014 15:00:39	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-40-404	REPLACE NEW TIMING CHAIN COVER/	DON	O	N	GARAGE	10.00	\$575.00	\$331.35	\$0.00	\$906.35
03-42-004	REPLACE NEW WATER PUMP	DON	O	N	GARAGE	0.00	\$0.00	\$290.64	\$0.00	\$290.64
03-42-006	REPLACE NEW THERMOSTATS	DON	O	N	GARAGE	0.00	\$0.00	\$43.80	\$0.00	\$43.80
03-42-007	REPLACE NEW COOLANT FILTER	DON	O	N	GARAGE	1.00	\$57.50	\$7.97	\$0.00	\$65.47
03-42-013	REPLACE NEW HOSES, COOLING SYS	DON	O	N	GARAGE	0.00	\$0.00	\$49.49	\$0.00	\$49.49
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	1.26	\$72.20	\$97.29	\$0.00	\$169.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$112.43	\$0.00	\$169.93
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	1.00	\$57.50	\$45.85	\$0.00	\$103.35
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	O	N	GARAGE	1.00	\$57.50	\$355.64	\$0.00	\$413.14

JOB COUNT: 9	WORK ORDER TOTAL:	15.26	877.20	1,334.46	0.00	2,211.66
--------------	-------------------	-------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	11397026	02/06/2014 07:00:00	02/06/2014 17:00:00	10.00	\$575.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/06/2014 06:00:00	02/06/2014 07:00:00	1.00	\$57.50
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11397026	02/06/2014 08:00:00	02/06/2014 09:00:00	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	02/06/2014 07:00:00	02/06/2014 08:00:00	1.00	\$57.50
03-42-007	REPLACE NEW COOLANT FILTER	11074414	02/06/2014 06:00:00	02/06/2014 07:00:00	1.00	\$57.50
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	11397026	01/14/2014 14:19:50	01/14/2014 15:35:10	1.26	\$72.20
					LABOR	877.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	C111	RED BRAKE CLEANER	4.86	4	\$19.44
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	12.98	6	\$77.85
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.39	5	\$91.95
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	3.25	1	\$3.25

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM TRANSMISSION SERVICE	SHIPPING	SHIPPING AND HANDLING	21.66	1	\$21.66
66-PM-PMT	PERFORM TRANSMISSION SERVICE	CIT632493001004	QUATRASYND TRANS FLUID	254.49	1	\$254.49
66-PM-PMT	PERFORM TRANSMISSION SERVICE	M329542824	TRANSMISSION FILTER	53.10	1	\$53.10
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	4C4Z8260AA	LOWER RADIATOR HOSE	44.77	1	\$44.77
66-PM-PMT	PERFORM TRANSMISSION SERVICE	WIX57701	TRANSMISSION FILTER	26.39	1	\$26.39
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	3C3Z6N640AA	EXHAUST GASKET	5.57	1	\$5.57
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	3C3Z9439AA	INTAKE GASKETS	18.39	2	\$36.78
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	1	\$45.85
03-42-004	REPLACE NEW WATER PUMP	5C4Z8501AA	WATER PUMP	290.64	1	\$290.64
03-42-006	REPLACE NEW THERMOSTATS	4C4Z8575AA	THERMOSTAT	43.80	1	\$43.80
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	4C4Z6020AA	GASKET	125.41	1	\$125.41
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	3C3Z9T514AG	TURBO MOUNTING KIT	13.95	1	\$13.95
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	4C4Z8507AA	GASKET	45.12	1	\$45.12
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	3C3Z8255AA	GASKET	6.96	1	\$6.96
03-40-404	REPLACE NEW TIMING CHAIN COVER/GASKET	3C3Z9433AB	OIL COOLER GASKET KIT	97.56	1	\$97.56
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	FHCCC48	RADIATOR HOSE CLAMPS	1.37	2	\$2.73
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	QBC5072	HOSE CLAMP	1.99	1	\$1.99
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	7.97	1	\$7.97
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
					PARTS	1334.46

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **15836**

Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER-CHECK FOR OIL LEAKING-SERVICE TRANSMISSION

Job Notes

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

03-40-404 - REPLACE NEW TIMING CHAIN COVER/GASKET

(LPATE) REMOVED THE INTAKE AND TURBO FOR ACCESS, REMOVED THE FRONT COVER. REPLACED THE TIMING COVER GASKET, FRONT SEAL INTAKE GASKETS. TEST DROVE OK

03-42-004 - REPLACE NEW WATER PUMP

(LPATE) REPLACED THE WATERPUMP

03-42-006 - REPLACE NEW THERMOSTATS

(LPATE) REPLACED THE THERMOSTAT AND GASKET

03-42-007 - REPLACE NEW COOLANT FILTER

(LPATE) REPLACED THE COOLANT FILTER

03-42-013 - REPLACE NEW HOSES, COOLING SYSTEM

(RWINTERS) REPLACED THE LOWER RADIATOR HOSE AND REPLACED THE O-RING FOR THE PIPE GOING TO THE TURBO

35-40 - DIAGNOSE ENGINE / MOTOR SYSTEMS

(LPATE) CHECKED OUT FOUND FRONT TIMING COVER GASKET LEAKING

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.05

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY SH

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LPATE) CHANGED TRANSMISSION FILTER INSIDE THE PAN ALSO CHANGED EXTERNAL FILTER AND FLUID. REFILLED RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 16660

USING DEPT NO:	504302	OPENED DATE:	04/17/2014 11:51:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/21/2014 14:43:12	METER 1 - M:	34861	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/21/2014 14:43:14	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-02-027	TRANSPORT SEAT FRAMES & SPRINGS	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25
25-02-027	REMOVE SEAT FRAMES & SPRINGS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$119.25	\$0.00	\$176.75
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$45.85	\$0.00	\$74.60
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$479.76	\$0.00	\$479.76

JOB COUNT: 5	WORK ORDER TOTAL:	2.80	161.00	644.86	0.00	805.86
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	04/21/2014 06:00:00	04/21/2014 07:00:00	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10260422	04/21/2014 07:00:00	04/21/2014 07:30:00	0.50	\$28.75
16-02-027	TRANSPORT SEAT FRAMES & SPRINGS	10260422	04/21/2014 07:30:00	04/21/2014 08:00:00	(0.50)	(\$28.75)
16-02-027	TRANSPORT SEAT FRAMES & SPRINGS	10260422	04/21/2014 07:30:00	04/21/2014 08:00:00	0.50	\$28.75
16-02-027	TRANSPORT SEAT FRAMES & SPRINGS	10260422	04/21/2014 07:30:00	04/21/2014 07:48:00	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	10260422	04/21/2014 06:00:00	04/21/2014 07:00:00	1.00	\$57.50
					LABOR	161.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-55-012	PURCHASED CARGO RESTRAINTS	LB200-4PK	STEEL ROUND TUBE LOAD BAR 4-PK	119.94	4	\$479.76
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.77	5	\$93.83
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	7.97	1	\$7.97
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	1	\$45.85
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	7.97	(1)	(\$7.97)
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	8.19	1	\$8.19
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	(1)	(\$45.85)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	45.85	1	\$45.85

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	8.19	(1)	(\$8.19)
66-PM-PMA	PERFORM OIL CHANGE	BALB5134	COOLANT FILTER SPIN-ON	8.19	1	\$8.19
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	(1)	(\$17.23)
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
					PARTS	644.86

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **16660**

Work Order Notes

(LPATE) PURCHASED A 4PACK OF CARGO RESTRAINT BARS FOR MOIVING TRUCKS.

Job Notes

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

16-02-027 - TRANSPORT SEAT FRAMES & SPRINGS

(GMANNING) GM TRANSPORTED SEAT TO UPHOLSTERY SHOP FOR RECOVERING.

25-02-027 - REMOVE SEAT FRAMES & SPRINGS

(GMANNING) SH REMOVED PASSENGER SEAT. SENT TO UA UPHOLSTERY SHOP TO BE RECOVERED, AND REINSTALLED IN TRUCK.

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 15W40
Qty : 5
Description : OIL GAL BOTTLE (DIESEL)
Manufacturer :

Part No : P7235
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : TUBE GREASE
Qty : 1
Description : TUBE GREASE
Manufacturer :

(GMANNING) PM BY GM/SH. ALSO REPLACED COOLANT FILTER.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA
Qty : 1
Description : FUEL FILTER
Manufacturer :

(GMANNING) GM REPLACED FUEL FILTER

PU-55-012 - PURCHASED CARGO RESTRAINTS

(RWINTERS) GAVE ALL 4 BARS TO TIM TAYLOR FOR TRUCKS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17813

USING DEPT NO:	504302	OPENED DATE:	08/15/2014 09:22:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/18/2014 09:16:13	METER 1 - M:	36341	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/18/2014 09:16:15	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	O	N	GARAGE	0.50	\$28.75	\$8.19	\$0.00	\$36.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.84	\$48.09	\$119.16	\$0.00	\$167.25
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.89	\$47.35	\$0.00	\$76.24

JOB COUNT: 3	WORK ORDER TOTAL:	1.84	105.73	174.70	0.00	280.43
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	08/18/2014 07:50:40	08/18/2014 07:50:49	0.00	\$0.14
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	08/18/2014 07:00:00	08/18/2014 07:30:00	0.50	\$28.75
03-42-007	REPLACE NEW COOLANT FILTER	11338644	08/18/2014 07:30:00	08/18/2014 08:00:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11338644	08/16/2014 10:06:28	08/16/2014 10:56:39	0.84	\$48.09
					LABOR	105.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	8.19	1	\$8.19
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	47.35	1	\$47.35
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.77	5	\$93.83
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	3.24	1	\$3.24
					PARTS	174.70

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17813

Work Order Notes

(LPATE) PM-FUEL FILTER-REPLACE COOANT FILTER-TRUCK IS COMING BACK FOR REAR TIRES FRIDAY

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(LPATE) REPLACED COOLANT FILTER

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.05

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY BG/RS

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17868

USING DEPT NO:	504302	OPENED DATE:	08/22/2014 07:45:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2014 18:00:00	METER 1 - M:	36411	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/25/2014 18:00:00	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,789.22	\$1,789.22
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 3	WORK ORDER TOTAL:	2.00	115.00	0.00	1,789.22	1,904.22
--------------	-------------------	------	--------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	7588361	4800139800	0025102	\$1,789.22
COMML					1789.22

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11338644	08/25/2014 07:00:00	08/25/2014 08:00:00	1.00	\$57.50
66-79-002	PERFORM SERVICE CALL	11338644	08/22/2014 07:48:48	08/22/2014 09:18:48	(1.50)	(\$86.25)
66-79-002	PERFORM SERVICE CALL	11338644	08/22/2014 07:48:48	08/22/2014 09:18:48	1.50	\$86.25
66-79-002	PERFORM SERVICE CALL	11338644	08/22/2014 07:48:48	08/22/2014 08:48:48	1.00	\$57.50
LABOR						115.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17868

Work Order Notes

(LPATE) TIM REQUESTED A SERVICE CALL TO STADIUM DRIVE. FLASHERS LEFT ON BATTERY WENT DEAD-TRUCK NEEDS 4 REAR TIRES.

Job Notes

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LPATE) TCI REMOVED AND INSTALLED 4 NEW REAR TIRES. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LPATE) TAKEN TO TCI BY RS

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL COMPLETED. JUMPED TRUCK OFF BUT HAD TO REMOVE THE STEP ON DRIVER SIDE TO ACCESS THE BATTERIES.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17995

USING DEPT NO:	504302	OPENED DATE:	09/08/2014 07:27:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2014 11:47:58	METER 1 - M:	36411	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2014 11:47:59	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
04-31-001	REPLACE RBLT ALTERNATOR	DON	O	N	GARAGE	2.40	\$138.00	\$347.22	\$0.00	\$485.22
15-50-103	WARRANTY BELT TENSIONER	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-31	TRANSPORT CHARGING SYSTEM	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$97.75	\$97.75
35-31	DIAGNOSE CHARGING SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 5	WORK ORDER TOTAL:	4.90	281.75	347.22	97.75	726.72
--------------	-------------------	------	--------	--------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
20-00	TOWING COMPLETE VEHICLE	11076249	42776	0025559	\$172.50
20-00	TOWING COMPLETE VEHICLE	11076249	42776	0025559	(\$172.50)
20-00	TOWING COMPLETE VEHICLE	11076249	42776	0025559	\$97.75
COMML					97.75

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
04-31-001	REPLACE RBLT ALTERNATOR	11088858	09/25/2014 06:00:00	09/25/2014 08:24:00	2.40	\$138.00
35-31	DIAGNOSE CHARGING SYSTEM	11088858	09/25/2014 06:00:00	09/25/2014 07:48:00	(1.80)	(\$103.50)
35-31	DIAGNOSE CHARGING SYSTEM	11088858	09/25/2014 06:00:00	09/25/2014 07:48:00	1.80	\$103.50
35-31	DIAGNOSE CHARGING SYSTEM	11088858	09/25/2014 06:00:00	09/25/2014 06:30:00	0.50	\$28.75
16-31	TRANSPORT CHARGING SYSTEM	11255091	09/09/2014 09:08:58	09/09/2014 10:08:58	(1.00)	(\$57.50)
16-31	TRANSPORT CHARGING SYSTEM	11255091	09/09/2014 09:08:58	09/09/2014 10:08:58	1.00	\$57.50
16-31	TRANSPORT CHARGING SYSTEM	11255091	09/09/2014 09:08:58	09/10/2014 13:02:18	(27.89)	(\$1,603.61)
16-31	TRANSPORT CHARGING SYSTEM	11255091	09/09/2014 09:08:58	09/10/2014 13:02:18	27.89	\$1,603.61
16-31	TRANSPORT CHARGING SYSTEM	11255091	09/09/2014 09:08:58	09/09/2014 11:08:58	2.00	\$115.00
LABOR						281.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
04-31-001	REPLACE RBLT ALTERNATOR	ALTERNATOR	ALTERNATOR	337.50	1	\$337.50

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
04-31-001	REPLACE RBLT ALTERNATOR	C111	RED BRAKE CLEANER	4.86	2	\$9.72
PARTS						347.22

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 17995

Work Order Notes

(LPATE) ALT NOT CHARGING

Job Notes

04-31-001 - REPLACE RBLT ALTERNATOR

(LPATE) REMOVED AND INSTALLED ALT. WITH REMAN UNIT FROM NABORS. PD BY CC

15-50-103 - WARRANTY BELT TENSIONER

(LPATE) REMOVED AND INSTALLED BELT TENSIONER AS WARRANTY FROM NAS WAS CRACKED.

16-31 - TRANSPORT CHARGING SYSTEM

(LPATE) ALTERNATOR TAKEN TO NABORS IN BIRMINGHAM AND SWAPPED OUT BY NT (NEEDED TRUCK BACK IN SERVICE ASAP FOR FOOTBALL GAME)

20-00 - TOWING COMPLETE VEHICLE

(LPATE) BAMBARGER TOWED TRUCK FROM PRESIDENTS MANSION TO GARAGE. PD BY CC

35-31 - DIAGNOSE CHARGING SYSTEM

(LPATE) CHECKED SYSTEM ALT IS NOT CHARGING

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 18323

USING DEPT NO:	504302	OPENED DATE:	10/06/2014 09:06:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2014 18:00:00	METER 1 - M:	36960	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/24/2014 18:00:00	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$29.09	\$0.00	\$46.34
03-40-436	REPLACE NEW FRONT CRANK SEAL	DON	O	N	GARAGE	0.00	\$0.00	\$1,169.09	\$0.00	\$1,169.09
14-52-007	INSTALL CAMERA	DON	O	N	GARAGE	4.00	\$230.00	\$635.73	\$0.00	\$865.73
PU-55-012	PURCHASED CARGO RESTRAINTS	DON	O	N	GARAGE	0.00	\$0.00	\$388.11	\$0.00	\$388.11
PU-78-036	PURCHASED TOUCH UP PAINT	DON	O	N	GARAGE	0.00	\$0.00	\$9.37	\$0.00	\$9.37

JOB COUNT: 5	WORK ORDER TOTAL:	4.30	247.25	2,231.39	0.00	2,478.64
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-007	INSTALL CAMERA	11268671	10/06/2014 09:13:59	10/06/2014 13:13:59	4.00	\$230.00
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11268671	10/06/2014 09:14:04	10/06/2014 09:32:04	0.30	\$17.25
					LABOR	247.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-78-036	PURCHASED TOUCH UP PAINT	PMP195005920A	WHITE TOUCH-UP PAINT	9.37	1	\$9.37
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	23.10	1	\$23.10
PU-55-012	PURCHASED CARGO RESTRAINTS	5320SEFBLU	2"X20" RATCHET STRAP((BLUE)	14.24	3	\$42.71
PU-55-012	PURCHASED CARGO RESTRAINTS	5316SEFGRY	2"X16" RATCHET STRAP	13.48	3	\$40.45
PU-55-012	PURCHASED CARGO RESTRAINTS	5312SEFY	2"X12" RATCHET STRAP (YELLOW)	12.43	3	\$37.30
PU-55-012	PURCHASED CARGO RESTRAINTS	RTO6	2"X6" TIE OFF (YELLOW)	5.99	6	\$35.91
PU-55-012	PURCHASED CARGO RESTRAINTS	C320SEF	2"X20" STRAP W CAM BUC (BLUE)	13.48	3	\$40.45
PU-55-012	PURCHASED CARGO RESTRAINTS	C316SEF	2"X16" STRAP W CAM BUC (GREY)	11.99	6	\$71.91
03-40-436	REPLACE NEW FRONT CRANK SEAL	F6TZ6730AA	OIL DRAIN PLUG	12.13	1	\$12.13
03-40-436	REPLACE NEW FRONT CRANK SEAL	3C3Z6616BA	OIL COVER	51.75	1	\$51.75
03-40-436	REPLACE NEW FRONT CRANK SEAL	3C3Z6700BA	CRANK SEAL	27.45	1	\$27.45
03-40-436	REPLACE NEW FRONT CRANK SEAL	4C4Z8A616EA	CLUTCH ASSY	351.13	1	\$351.13
03-40-436	REPLACE NEW FRONT CRANK SEAL	303761	FRONT SEAL TOOL INSTALLER	682.59	1	\$682.59
PU-55-012	PURCHASED CARGO RESTRAINTS	C312SEF	2X12 CAM BUCKLE STRAP	11.24	6	\$67.41

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-40-436	REPLACE NEW FRONT CRANK SEAL	FJC4923	ENGINE OIL DYE	6.15	4	\$24.60
03-40-436	REPLACE NEW FRONT CRANK SEAL	C111	RED BRAKE CLEANER	4.86	4	\$19.44
PU-55-012	PURCHASED CARGO RESTRAINTS	SHIPPING	SHIPPING AND HANDLING	28.87	1	\$28.87
14-52-007	INSTALL CAMERA	CONNECTOR	CONNECTOR-NYLON	0.84	2	\$1.68
14-52-007	INSTALL CAMERA	PCP WIRE	WIRE-PLASTIC COATED PRIMARY	0.33	10	\$3.30
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	OPTA700GBP	6" TAIL LIGHT GROMMET	2.40	1	\$2.40
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	OPTSTL72RBP	6" LED TAILLIGHT	26.69	1	\$26.69
14-52-007	INSTALL CAMERA	PIC5141A	3/8 CONVOLUTED TUBING 50FT	0.62	50	\$30.75
14-52-007	INSTALL CAMERA	CAM3221	BACK UP CAMERA SYSTEM	600.00	1	\$600.00
					PARTS	2231.39

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 18323

Work Order Notes

(LPATE) CHECK FOR OIL LEAK-INSTALL BACK UP CAMERA-SHANE REQUESTED PURCHASE CARGO STRAPS FOR USE IN ALL MOVING TRUCKS

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED RIGHT REAR TAILLIGHT AND GROMMET

03-40-436 - REPLACE NEW FRONT CRANK SEAL

(IFALLS) REPLACED FRONT CRANKSHAFT SEAL AND SEAL COVER(OIL PUMP COVER) TEST DROVE RECHECKED EVERYTHING OK PRESSURE WASHED ALL OIL FRO UNDER THE TRUCK

14-52-007 - INSTALL CAMERA

(LPATE) INSTALLED BACK UP CAMERA

PU-55-012 - PURCHASED CARGO RESTRAINTS

(LPATE) PURCHASED CARGO STRAPS AND GAVE TO SHANE TO BE USED ON ALL 3 MOVING TRUCKS

PU-78-036 - PURCHASED TOUCH UP PAINT

(LPATE) SHANE REQUESTED TOUCH UP PAINT FOR TRUCK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 18835

USING DEPT NO:	504302	OPENED DATE:	11/20/2014 07:31:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2014 09:15:32	METER 1 - M:	37467	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2014 09:15:34	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$298.50	\$0.00	\$298.50
66-00-CO1	PERFORM Call Out-Charge Service Call	DON	B	N	GARAGE	1.67	\$96.03	\$0.00	\$0.00	\$96.03

JOB COUNT: 2	WORK ORDER TOTAL:	1.67	96.03	298.50	0.00	394.53
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-00-CO1	PERFORM Call Out-Charge Service Call	11338644	11/20/2014 10:35:35	11/20/2014 12:15:47	1.67	\$96.03
03-32-002	REPLACE NEW BATTERY	11074414	11/20/2014 10:35:28	11/20/2014 11:35:28	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11074414	11/20/2014 10:35:28	11/20/2014 11:35:28	(1.00)	(\$57.50)
					LABOR	96.03

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	SLI31SA	12V 31 PROCELL 18	149.25	2	\$298.50
					PARTS	298.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **18835**

Work Order Notes

(LPATE) RYAN CALLED OUT AFTER HOURS DRIVER RAN THE LIFTGATE WITH THE TRUCK NOT RUNNING. BATTERY IS DEAD. DUE TO FOOTBALL GAME NEED TRUCK BACK UP AND GOING ASAP

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BOTH BATTERIES IN TRUCK. RECHECKED OK

66-00-CO1 - PERFORM Call Out-Charge Service Call

(LPATE) RS PERFORMED CALL OUT

66-79-002 - PERFORM SERVICE CALL

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 18948

USING DEPT NO:	504302	OPENED DATE:	12/03/2014 11:14:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/03/2014 15:40:17	METER 1 - M:	37525	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/03/2014 15:40:19	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-78-040	REPAIR TENT STAKE DRIVER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$115.00	\$115.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	0.00	115.00	172.50
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-78-040	REPAIR TENT STAKE DRIVER	3439100	15893	0026409	\$115.00
				COMML	115.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	10337093	12/03/2014 11:18:53	12/03/2014 12:18:53	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 18948

Work Order Notes

(LPATE) STAKE FOR INSTALLING TENTS ON QUAD BROKE NEED REPAIRED ASAP FOR FOOTBALL GAME

Job Notes

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LPATE) TAKEN TO HARDSTEEL BY AY

24-78-040 - REPAIR TENT STAKE DRIVER

(LPATE) HARDSTEEL REPAIRED STAKE DRIVER. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 19155

USING DEPT NO:	504302	OPENED DATE:	01/07/2015 08:42:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/07/2015 11:39:13	METER 1 - M:	37887	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/07/2015 11:39:14	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-53-027	PURCHASED ROAD ICE MELT	DON	O	N	GARAGE	0.00	\$0.00	\$94.35	\$0.00	\$94.35

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	94.35	0.00	94.35
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-53-027	PURCHASED ROAD ICE MELT	20BRR	ROAD ICE MELT	9.44	10	\$94.35
					PARTS	94.35

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **19155**

Work Order Notes

(LPATE) TONY JOHNSON REQUESTED ICE MELT FOR HIS DEPTS DUE TO UPCOMING WEATHER

Job Notes

PU-53-027 - PURCHASED ROAD ICE MELT

(LPATE) DELIVERED ICE MELT TO ASB

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 19178

USING DEPT NO:	504302	OPENED DATE:	01/09/2015 07:36:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/14/2015 14:51:40	METER 1 - M:	38093	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/14/2015 14:51:41	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-070	REPLACE NEW DOOR LATCH SWITCH	DON	O	N	GARAGE	1.00	\$57.50	\$121.57	\$0.00	\$179.07

JOB COUNT: 1	WORK ORDER TOTAL:					1.00	57.50	121.57	0.00	179.07
---------------------	--------------------------	--	--	--	--	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-070	REPLACE NEW DOOR LATCH SWITCH	11074414	01/14/2015 06:00:00	01/14/2015 07:00:00	1.00	\$57.50
					LABOR	57.50

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-070	REPLACE NEW DOOR LATCH SWITCH	XL1Z14028AB	DOOR LOCK SWITCH	65.25	1	\$65.25
03-02-070	REPLACE NEW DOOR LATCH SWITCH	XL1Z14028AA	DOOR LOCK SWITCH	56.32	1	\$56.32
					PARTS	121.57

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **19178**

Work Order Notes

(LPATE) DOOR LOCKS INOP

Job Notes

03-02-070 - REPLACE NEW DOOR LATCH SWITCH

(LPATE) REPLACED BOTH DOOR LOCK AND UNLOCK SWITCHES

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 19537

USING DEPT NO:	504302	OPENED DATE:	02/13/2015 08:04:21	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2015 09:54:35	METER 1 - M:	38314	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/13/2015 09:54:37	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.30	\$17.25	\$17.37	\$0.00	\$34.62

JOB COUNT: 1	WORK ORDER TOTAL:					0.30	17.25	17.37	0.00	34.62
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11397026	02/13/2015 09:20:23	02/13/2015 09:38:23	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	C111	RED BRAKE CLEANER	4.86	1	\$4.86
66-79-002	PERFORM SERVICE CALL	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	12.51	1	\$12.51
					PARTS	17.37

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **19537**

Work Order Notes

(LPATE) SHANE REQUESTED SERVICE CALL TO ASB FOR FLUID LEAKING FROM TRUCK

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LPATE) SERVICE CALL COMPLETE CHECKED FOUND BOTTOM RADIATOR HOSE LEAKING, TIGHTENED LOOSE CLAMP. RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 19648

USING DEPT NO:	504302	OPENED DATE:	03/02/2015 07:39:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2015 07:33:21	METER 1 - M:	38602	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2015 07:33:23	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-040	REPLACE NEW POWER STEERING RE	DON	O	N	GARAGE	0.50	\$28.75	\$138.68	\$0.00	\$167.43
03-40-419	REPLACE NEW OIL PAN/GASKET	DON	O	N	GARAGE	10.70	\$615.12	\$155.56	\$0.00	\$770.68
03-42-007	REPLACE NEW COOLANT FILTER	DON	P	N	GARAGE	1.71	\$98.36	\$8.19	\$0.00	\$106.55
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$35.94	\$0.00	\$50.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$111.06	\$0.00	\$128.89
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.36	\$20.95	\$47.35	\$0.00	\$68.30

JOB COUNT: 6	WORK ORDER TOTAL:	13.83	795.39	496.78	0.00	1,292.17
--------------	-------------------	-------	--------	--------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11213180	03/03/2015 07:00:00	03/03/2015 07:15:00	0.25	\$14.38
03-40-419	REPLACE NEW OIL PAN/GASKET	11397026	03/02/2015 09:30:00	03/02/2015 11:04:36	1.58	\$90.66
03-40-419	REPLACE NEW OIL PAN/GASKET	11397026	03/02/2015 08:07:44	03/02/2015 09:15:00	1.12	\$64.46
03-40-419	REPLACE NEW OIL PAN/GASKET	11397026	03/02/2015 11:04:16	03/02/2015 19:04:16	8.00	\$460.00
03-15-040	REPLACE NEW POWER STEERING RESERVOIR	11397026	03/02/2015 11:04:10	03/02/2015 11:34:10	0.50	\$28.75
03-42-007	REPLACE NEW COOLANT FILTER	10260422	03/02/2015 09:41:48	03/02/2015 10:54:26	1.21	\$69.61
66-PM-PMA	PERFORM OIL CHANGE	11397026	03/02/2015 10:50:41	03/02/2015 11:09:17	0.31	\$17.83
03-42-007	REPLACE NEW COOLANT FILTER	10260422	03/02/2015 10:50:31	03/02/2015 11:20:31	0.50	\$28.75
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10260422	03/02/2015 09:19:56	03/02/2015 09:41:48	0.36	\$20.95
					LABOR	795.39

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-40-419	REPLACE NEW OIL PAN/GASKET	4C4Z6710BA	OIL PAN GASKET	19.92	1	\$19.92
03-40-419	REPLACE NEW OIL PAN/GASKET	4C4Z6710AA	OIL PAN GASKET	18.31	1	\$18.31
03-15-040	REPLACE NEW POWER STEERING RESERVOIR	4C4Z3A697BB	POWER STEERING RESERVOIR	117.67	1	\$117.67
03-15-040	REPLACE NEW POWER STEERING RESERVOIR	VV324	TRANS FLUID QT	7.00	3	\$21.01
03-40-419	REPLACE NEW OIL PAN/GASKET	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	12.51	5	\$62.55

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-40-419	REPLACE NEW OIL PAN/GASKET	C111	RED BRAKE CLEANER	4.86	3	\$14.58
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.77	5	\$93.83
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	47.35	1	\$47.35
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	8.19	1	\$8.19
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	17.23	1	\$17.23
03-40-419	REPLACE NEW OIL PAN/GASKET	FJC4923	ENGINE OIL DYE	6.21	4	\$24.84
03-40-419	REPLACE NEW OIL PAN/GASKET	C111	RED BRAKE CLEANER	4.86	1	\$4.86
03-51-038	REPLACE NEW WIPER BLADES	40720A	WIPER BLADE 20"	17.97	2	\$35.94
03-40-419	REPLACE NEW OIL PAN/GASKET	SHIPPING	SHIPPING AND HANDLING	10.50	1	\$10.50
					PARTS	496.78

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 19648

Work Order Notes

(LPATE) TRUCK IS LEAKING OIL-DUE FOR SERVICE

Job Notes

03-15-040 - REPLACE NEW POWER STEERING RESERVOIR

(LPATE) REPLACED POWER STEERING RESERVOIR

03-40-419 - REPLACE NEW OIL PAN/GASKET

(LPATE) REPLACED UPPER AND LOWER OIL PAN GASKETS

03-42-007 - REPLACE NEW COOLANT FILTER

(LPATE) REPLACED COOLANT FILTER

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.05

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY GM/BG

(RWINTERS) ADDED DYE

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 20258

USING DEPT NO:	504302	OPENED DATE:	05/14/2015 15:23:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/20/2015 14:05:10	METER 1 - M:	39246	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2015 14:05:11	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-073	REPLACE NEW A/C CLUTCH ASSY	DON	O	N	GARAGE	1.50	\$86.25	\$187.37	\$0.00	\$273.62
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	2.00	115.00	187.37	0.00	302.37
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11268671	05/19/2015 07:00:00	05/19/2015 07:30:00	0.50	\$28.75
03-01-073	REPLACE NEW A/C CLUTCH ASSY	11213180	05/19/2015 07:00:00	05/19/2015 08:30:00	1.50	\$86.25
					LABOR	115.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-01-073	REPLACE NEW A/C CLUTCH ASSY	MEI5176	A/C CLUTCH ASSY	187.37	1	\$187.37
					PARTS	187.37

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **20258**

Work Order Notes

(LPATE) A/C MAKING NOISE

Job Notes

03-01-073 - REPLACE NEW A/C CLUTCH ASSY

(LPATE) REPLACED A/C CLUTCH ASSY. RECHECKED OK

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LPATE) NEEDS A/C CLUTCH

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 20599

USING DEPT NO:	504302	OPENED DATE:	06/22/2015 14:56:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/26/2015 10:35:38	METER 1 - M:	39830	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/26/2015 10:35:39	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-035	REPLACE NEW WATER/DCA FILTER	DON	O	N	GARAGE	0.16	\$8.99	\$6.41	\$0.00	\$15.40
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.34	\$77.08	\$83.09	\$0.00	\$160.17
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.06	\$3.23	\$19.47	\$0.00	\$22.70

JOB COUNT: 3	WORK ORDER TOTAL:	1.55	89.30	108.97	0.00	198.27
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-035	REPLACE NEW WATER/DCA FILTER	11074414	06/23/2015 09:38:02	06/23/2015 09:47:25	0.16	\$8.99
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	06/23/2015 09:34:31	06/23/2015 09:37:53	0.06	\$3.23
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/23/2015 09:15:00	06/23/2015 09:34:24	0.32	\$18.59
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/23/2015 07:58:58	06/23/2015 09:00:00	1.02	\$58.49
					LABOR	89.30

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	12.20	5	\$61.00
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.12	1	\$2.12
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	8.21	1	\$8.21
03-42-035	REPLACE NEW WATER/DCA FILTER	4070	FILTER	6.64	1	\$6.64
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.76	1	\$11.76
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	19.47	1	\$19.47
03-42-035	REPLACE NEW WATER/DCA FILTER	4070	FILTER	6.64	(1)	(\$6.64)
03-42-035	REPLACE NEW WATER/DCA FILTER	4070	FILTER	6.41	1	\$6.41
					PARTS	108.97

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 20599

Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER AND COOLANT FILTER

Job Notes

03-42-035 - REPLACE NEW WATER/DCA FILTER

(LPATE) REPLACED COOLANT FILTER

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

The following parts are included with the standard job:

Part No : 15W40
Qty : 5
Description : OIL GAL BOTTLE (DIESEL)
Manufacturer :

Part No : P7235
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : TUBE GREASE
Qty : 1
Description : TUBE GREASE
Manufacturer :

(LPATE) PM BY SH,RS/SH-GREASED THE LIFTGATE FOUND A BOLT MISSING IN A PIN. REPALCED THE BOLT AND CHECKED ALL OTHER BOLTS. OK

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA
Qty : 1
Description : FUEL FILTER
Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 20982

USING DEPT NO:	504302	OPENED DATE:	08/04/2015 08:38:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/04/2015 09:14:48	METER 1 - M:	40365	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/04/2015 09:14:50	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-40-425	PURCHASED ENGINE OIL DIPSTICK/TU	DON	O	N	GARAGE	0.00	\$0.00	\$10.78	\$0.00	\$10.78

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	10.78	0.00	10.78
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-40-425	PURCHASED ENGINE OIL DIPSTICK/TUBE	4C4Z6750AA	DIPSTICK	10.78	1	\$10.78
					PARTS	10.78

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **20982**

Work Order Notes

(LPATE) DRIVER REQUESTED NEW OIL DIPSTICK

Job Notes

PU-40-425 - PURCHASED ENGINE OIL DIPSTICK/TUBE

(LPATE) INSTALLED NEW OIL DIPSTICK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 2115

USING DEPT NO:	504302	OPENED DATE:	10/07/2008 14:52:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/08/2008 09:14:55	METER 1 - M:	11076	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/08/2008 09:14:57	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-051	REPLACE NEW SEAT COVER	DON	N	N	GARAGE	0.00	\$0.00	\$27.00	\$0.00	\$27.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	27.00	0.00	27.00
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-051	REPLACE NEW SEAT COVER	5040620	SEAT COVER-DRIVER	27.00	1	\$27.00
					PARTS	27.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **2115**

Work Order Notes

(LPATE) DRIVER REQUESTED SEAT COVER

Job Notes

03-02-051 - REPLACE NEW SEAT COVER

(LPATE) SPECIAL ORDERED SEAT COVER DRIVER INSTALLED

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 21313

USING DEPT NO:	504302	OPENED DATE:	09/03/2015 15:13:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/04/2015 10:03:20	METER 1 - M:	40633	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2015 10:03:22	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	1.33	\$76.32	\$0.49	\$0.00	\$76.81

JOB COUNT: 1	WORK ORDER TOTAL:	1.33	76.32	0.49	0.00	76.81
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11338644	09/04/2015 07:48:56	09/04/2015 08:50:34	1.03	\$59.07
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11338644	09/03/2015 15:13:48	09/03/2015 15:31:48	0.30	\$17.25
					LABOR	76.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	0.49	1	\$0.49
					PARTS	0.49

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **21313**

Work Order Notes

(LPATE) LEFT FRONT TURN SIGNAL OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR,TAIL,STOP,TURN,ETC

(LPATE) REPLACED LT TURN SIGNAL BULB

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 21495

USING DEPT NO:	504302	OPENED DATE:	09/21/2015 10:40:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2015 06:42:13	METER 1 - M:	40956	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2015 06:42:14	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-78	TRANSPORT TRIM & MISCELLANEOUS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
24-78-040	REPAIR TENT STAKE DRIVER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$172.50	\$172.50

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	57.50	0.00	172.50	230.00
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-78-040	REPAIR TENT STAKE DRIVER	3439100	16479	0030281	\$172.50
				COMML	172.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-78	TRANSPORT TRIM & MISCELLANEOUS HARDWARE	10337093	09/21/2015 10:40:49	09/21/2015 11:40:49	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 21495

Work Order Notes

(LISAPATE) TENT STAKE DRIVER BROKEN

Job Notes

16-78 - TRANSPORT TRIM & MISCELLANEOUS HARDWARE

(LISAPATE) STAKE TAKEN TO HARDSTEEL BY AY

24-78-040 - REPAIR TENT STAKE DRIVER

(LISAPATE) HARDSTEEL REPAIRED STAKE DRIVER HAMMER SHAFT. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22185

USING DEPT NO:	504302	OPENED DATE:	12/10/2015 11:42:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/11/2015 14:51:50	METER 1 - M:	42144	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/11/2015 14:51:51	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
25-44-012	REMOVE TANK - FUEL, GASEOUS	DON	O	N	GARAGE	1.00	\$57.50	\$31.36	\$0.00	\$88.86

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	31.36	0.00	88.86
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
25-44-012	REMOVE TANK - FUEL, GASEOUS	11338644	12/10/2015 11:43:14	12/10/2015 12:43:14	1.00	\$57.50
					LABOR	57.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
25-44-012	REMOVE TANK - FUEL, GASEOUS	4C4Z9030A	FUEL CAP	27.21	1	\$27.21
25-44-012	REMOVE TANK - FUEL, GASEOUS	3/4	HOSE-HEATER	0.83	5	\$4.15
					PARTS	31.36

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22185

Work Order Notes

(LISAPATE) FUEL TANK CHAIN BROKE AND FELL INTO TANK

Job Notes

25-44-012 - REMOVE TANK - FUEL, GASEOUS

(LISAPATE) REMOVED TANK AND SENDING UNIT TO RETRIEVE FUEL CAP CHAIN. INSTALLED NEW FUEL CAP WITH CHAIN.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22247

USING DEPT NO:	504302	OPENED DATE:	12/21/2015 07:46:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/21/2015 08:45:01	METER 1 - M:	42391	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/21/2015 08:45:03	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	10337093	12/21/2015 07:47:23	12/21/2015 08:47:23	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **22247**

Work Order Notes

(RWINTERS) ERIC REQUESTED A SERVICE CALL TO SOCCER FIELD TRUCK IS OUT OF FUEL

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) ADDED 5 GAL DIESEL FUEL TO TRUCK CRANKED FOLLOWED DRIVER TO PUMPS. REFILLED OUR GAS CAN

(RWINTERS) WILL NEED TO BRING BACK IN TO CHECK GAUGE/SENDING UNIT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22259

USING DEPT NO:	504302	OPENED DATE:	01/04/2016 09:12:32	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/08/2016 07:40:06	METER 1 - M:	42427	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2016 07:40:07	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-44-003	REPLACE NEW FUEL PUMP	DON	O	N	GARAGE	1.90	\$109.25	\$52.04	\$0.00	\$161.29
35-44	DIAGNOSE FUEL SYSTEM	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 2	WORK ORDER TOTAL:	2.40	138.00	52.04	0.00	190.04
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-44	DIAGNOSE FUEL SYSTEM	10260422	01/07/2016 06:00:00	01/07/2016 06:30:00	0.50	\$28.75
03-44-003	REPLACE NEW FUEL PUMP	10260422	01/07/2016 06:30:00	01/07/2016 08:24:00	1.90	\$109.25
					LABOR	138.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-44-003	REPLACE NEW FUEL PUMP	4C4Z9275FB	FUEL SENDING UNIT	52.04	1	\$52.04
					PARTS	52.04

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22259

Work Order Notes

(LISAPATE) FUEL GAGE INOP

Job Notes

03-44-003 - REPLACE NEW FUEL PUMP

(LISAPATE) REMOVED AND REPLACED FUEL SENDING UNIT. RECHECKED OK

35-44 - DIAGNOSE FUEL SYSTEM

(LISAPATE) FOUND FUEL SENDING UNIT FAULTY

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22585

USING DEPT NO:	504302	OPENED DATE:	02/18/2016 15:38:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/04/2016 08:20:26	METER 1 - M:	43041	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/04/2016 08:20:27	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	P	N	GARAGE	0.13	\$7.20	\$5.76	\$0.00	\$12.96
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$3.51	\$17.06	\$0.00	\$20.57
16-71	TRANSPORT BODY	DON	O	N	GARAGE	1.22	\$69.88	\$0.00	\$0.00	\$69.88
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$3,100.98	\$3,100.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.37	\$78.68	\$141.02	\$0.00	\$219.70
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.08	\$4.68	\$31.85	\$0.00	\$36.53

JOB COUNT: 6	WORK ORDER TOTAL:	2.85	163.95	195.69	3,100.98	3,460.62
--------------	-------------------	------	--------	--------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	164929	0032393	\$3,100.98
				COMML	3100.98

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/29/2016 14:15:00	02/29/2016 15:01:50	0.78	\$44.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/29/2016 13:24:44	02/29/2016 14:00:00	0.59	\$33.80
03-42-007	REPLACE NEW COOLANT FILTER	11074414	02/29/2016 13:16:38	02/29/2016 13:24:09	0.13	\$7.20
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	02/29/2016 13:11:18	02/29/2016 13:16:11	0.08	\$4.68
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/29/2016 13:06:04	02/29/2016 13:09:44	0.06	\$3.51
16-71	TRANSPORT BODY	10337093	02/26/2016 14:12:29	02/26/2016 15:25:24	1.22	\$69.88
				LABOR		163.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	WIX33818	FUEL FILTER	31.85	1	\$31.85
66-PM-PMA	PERFORM OIL CHANGE	2813	AIR FILTER	50.81	1	\$50.81
66-PM-PMA	PERFORM OIL CHANGE	VV831	HP 80W90 GEAR OIL GL5 QT	4.35	1	\$4.35

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	8.03	1	\$8.03
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.60	1	\$2.60
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.78	1	\$2.78
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	12.12	5	\$60.60
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
					PARTS	195.69

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 22585

Work Order Notes

(LISAPATE) PM-REPLACE FUEL FILTER-REPLACE COOLANT FILTER-REPLACE WIPERS-REPAIR ROOF DAMAGE

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(LISAPATE) REPLACED COOLANT FILTER

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

16-71 - TRANSPORT BODY

(LISAPATE) TAKEN TO ANDREWS BY AY

24-71 - REPAIR BODY

(LISAPATE) ANDREW'S REPAIRED DAMAGE TO ROOF PER ESTIMATE. SEE ATTACHED. PD BY CC

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY SH-REPLACED AIR FILTER

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23311

USING DEPT NO:	504302	OPENED DATE:	05/06/2016 09:38:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/06/2016 14:30:11	METER 1 - M:	44074	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/06/2016 14:30:12	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-052	REPLACE NEW LIFT ASSIST ROD	DON	O	N	GARAGE	2.00	\$115.00	\$0.00	\$0.00	\$115.00
03-65-002	REPLACE NEW HYDRAULIC TANK/RESI	DON	O	N	GARAGE	1.50	\$86.25	\$204.91	\$0.00	\$291.16
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT A	DON	O	N	GARAGE	6.00	\$345.00	\$1,992.34	\$0.00	\$2,337.34

JOB COUNT: 3	WORK ORDER TOTAL:	9.50	546.25	2,197.25	0.00	2,743.50
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	11213180	05/06/2016 11:08:53	05/06/2016 17:08:53	6.00	\$345.00
03-65-002	REPLACE NEW HYDRAULIC TANK/RESERVOIR	11213180	05/06/2016 11:08:58	05/06/2016 12:38:58	1.50	\$86.25
03-55-052	REPLACE NEW LIFT ASSIST ROD	11213180	05/06/2016 11:09:10	05/06/2016 13:09:10	2.00	\$115.00
					LABOR	546.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	80000201	LOCK VALVE RETRO KIT	165.83	1	\$165.83
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	7500019-3	SOCKET HEAD SHOULDER SCREW	14.28	1	\$14.28
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	26417301	TORSION BAR ANCHOR ASSY	16.22	1	\$16.22
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	22517100	TORSION BAR 1/2" DIA	130.59	1	\$130.59
03-65-200	REPLACE NEW HYD-CYLINDER (LIFT ARM)	22780050	CYLINDER ROD	832.71	2	\$1,665.42
03-65-002	REPLACE NEW HYDRAULIC TANK/RESERVOIR	70401513	HYD RESERVOIR TANK	144.28	1	\$144.28
03-65-002	REPLACE NEW HYDRAULIC TANK/RESERVOIR	C111	RED BRAKE CLEANER	2.86	2	\$5.72
03-65-002	REPLACE NEW HYDRAULIC TANK/RESERVOIR	ISO32	RANDO HD ISO 32 HYD OIL	40.91	1	\$40.91
03-65-002	REPLACE NEW HYDRAULIC TANK/RESERVOIR	SHIPPING	SHIPPING AND HANDLING	14.00	1	\$14.00
					PARTS	2197.25

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23311

Work Order Notes

(LISAPATE) REPLACE ASSIST ROD AND HYD CYLINDERS

Job Notes

03-55-052 - REPLACE NEW LIFT ASSIST ROD

(LISAPATE) REPLACED THE ASSIST ROD.

03-65-002 - REPLACE NEW HYDRAULIC TANK/RESERVOIR

(LISAPATE) REPLACED THE FLUID RESERVOIR FOR THE PUMP

(RWINTERS) billed fluid on this line-return job

03-65-200 - REPLACE NEW HYD-CYLINDER (LIFT ARM)

(LISAPATE) REPLACED BOTH HYD CYLINDERS, FLUSHED SYSTEM WITH CLEAN FLUID AND FILLED WITH ALREADY CHARGED OUT FLUID. THOROUGHLY CLEANED LIF AND REGREASED ALL FITTINGS.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23366

USING DEPT NO:	504302	OPENED DATE:	05/13/2016 13:49:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/16/2016 14:14:46	METER 1 - M:	44407	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/16/2016 14:14:47	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	10337093	05/13/2016 13:51:20	05/13/2016 14:51:20	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23366

Work Order Notes

(LISAPATE) GERALD REQUESTED A SERVICE CALL TO THE FRONT OF THE FERGUSON CENTER DRVIER LEFT FLASHERS ON BATTERY IS DEAD

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED. JUMPED OFF CHARGING AT 13.7 VOLTS.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23592

USING DEPT NO:	504302	OPENED DATE:	06/03/2016 13:14:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2016 13:45:52	METER 1 - M:	44726	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/07/2016 13:45:54	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	DON	O	N	GARAGE	0.00	\$0.00	\$25.96	\$0.00	\$25.96

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	25.96	0.00	25.96
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	LLH13447	NYLON ROPE	0.20	3	\$0.60
PU-79-022	PURCHASED WHEEL CHOCKS/BLOCKS	SIRWC1000	WHEEL CHOCKS	12.68	2	\$25.36
					PARTS	25.96

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23592

Work Order Notes

(LISAPATE) PURCHASE WHEEL CHOCKS FOR THE TRUCK

Job Notes

PU-79-022 - PURCHASED WHEEL CHOCKS/BLOCKS

(LISAPATE) GAVE DRIVER WHEEL CHOCKS AND ROPE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23868

USING DEPT NO:	504302	OPENED DATE:	07/12/2016 09:28:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/14/2016 06:30:11	METER 1 - M:	45509	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/14/2016 06:30:15	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	DON	O	N	GARAGE	1.50	\$86.25	\$7.62	\$0.00	\$93.87
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 3	WORK ORDER TOTAL:	3.00	172.50	7.62	0.00	180.12
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11213180	07/13/2016 07:00:00	07/13/2016 08:30:00	1.50	\$86.25
06-15	INSPECT STEERING	11213180	07/12/2016 09:29:31	07/12/2016 09:59:31	(0.50)	(\$28.75)
06-15	INSPECT STEERING	11213180	07/12/2016 09:29:31	07/12/2016 09:59:31	0.50	\$28.75
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	11213180	07/12/2016 09:29:37	07/12/2016 10:59:37	1.50	\$86.25
					LABOR	172.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	F3TZ7L278A	BUSHING	3.81	2	\$7.62
					PARTS	7.62

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 23868

Work Order Notes

(LISAPATE) SHIFT INHIBIT LIGHT COMING ON

Job Notes

03-15-025 - REPLACE NEW SHIFT TUBE/BUSHINGS

(LISAPATE) REPLACED BUSHINGS. IF PROBLEM REOCCURS DRIVER WILL BRING BACK

06-15 - INSPECT STEERING

(LISAPATE) FOUND SHIFT TUBE BUSHINGS WORN

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) NO CODES STORE FOUND SHIFT LEVER BUSHINGS TO BE SEVERLY WORN

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24002

USING DEPT NO:	504302	OPENED DATE:	07/27/2016 09:36:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/28/2016 09:55:05	METER 1 - M:	45969	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/28/2016 09:55:07	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 1	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11074414	07/27/2016 09:37:26	07/27/2016 10:37:26	1.00	\$57.50
					LABOR	57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24002

Work Order Notes

(LISAPATE) ERIC REQUESTED A SERVICE CALL TO TUTWILER BATTERY IS DEAD ON THE TRUCK

Job Notes

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED DRIVER WAS OPERATING LIFT WITHOUT THE TRUCK RUNNING. JUMPED THE TRUCK OFF AND TOLD THEM TO BRING TO TH GARAGE FOR BATTERIES TO BE RECHECKED. DRIVER DID NOT BRING HE STATED TRUCK WAS CRANKING OK THIS MORNING

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24014

USING DEPT NO:	504302	OPENED DATE:	07/28/2016 14:34:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/03/2016 06:26:34	METER 1 - M:	45969	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/03/2016 06:26:35	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.00	\$57.50	\$148.00	\$0.00	\$205.50
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.67	\$96.17	\$0.00	\$0.00	\$96.17

JOB COUNT: 2	WORK ORDER TOTAL:	2.67	153.67	148.00	0.00	301.67
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11074414	07/28/2016 14:48:00	07/28/2016 15:28:21	0.67	\$38.67
66-79-002	PERFORM SERVICE CALL	11074414	07/28/2016 14:35:37	07/28/2016 15:35:37	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11213180	07/28/2016 14:35:43	07/28/2016 15:35:43	1.00	\$57.50
					LABOR	153.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	31S30	BATTERY BCI 31 HD STUD 950 CCA	74.00	2	\$148.00
					PARTS	148.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24014

Work Order Notes

(LISAPATE) ERIC REQUESTED A SERVICE CALL TO BRYCE FOR DEAD BATTERY

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) FOUND ONE BATTERY TO HAVE A BAD CELL. OTHER BATTERY CANNOT OPERATE LIFT WITHOUT ENGINE RUNNING ALONE.
REPLACED BOTH BATTERIES, CHECKED CHARGING SYSTEM. ALL CHECKED OUT.

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED. JUMPED OFF DRIVER BROUGHT TO THE GARAGE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24252

USING DEPT NO:	504302	OPENED DATE:	08/30/2016 07:38:08	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	09/21/2016 09:56:13	METER 1 - M:	46729	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/21/2016 09:56:15	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-035	REPLACE NEW WATER/DCA FILTER	DON	O	N	GARAGE	0.50	\$28.75	\$5.76	\$0.00	\$34.51
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.60	\$91.95	\$127.12	\$0.00	\$219.07
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$16.99	\$0.00	\$45.74

JOB COUNT: 3	WORK ORDER TOTAL:					2.60	149.45	149.87	0.00	299.32
--------------	-------------------	--	--	--	--	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	09/19/2016 13:14:11	09/19/2016 13:44:11	0.50	\$28.75
03-42-035	REPLACE NEW WATER/DCA FILTER	11074414	09/19/2016 12:44:11	09/19/2016 13:14:11	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/19/2016 11:38:14	09/19/2016 13:14:11	1.60	\$91.95
					LABOR	149.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	11.96	5	\$59.80
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.14	1	\$2.14
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	7.97	1	\$7.97
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	45.36	1	\$45.36
03-42-035	REPLACE NEW WATER/DCA FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
					PARTS	149.87

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24252

Work Order Notes

(LISAPATE) PM-REPLACE FUEL FILTER-REPLACE COOLANT FILTER

Job Notes

03-42-035 - REPLACE NEW WATER/DCA FILTER

(LISAPATE) REPLACED COOLANT FILTER

66-40-438 - PERFORM OIL SAMPLE ANALYSIS

66-PM-OLS - PERFORM OIL SAMPLES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY SH-REPALCED AIR FILTER-JACKED UP FRONT END GREASED KING PINS AND ALSO GREASED LIFGATE.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 2430

USING DEPT NO:	504302	OPENED DATE:	11/18/2008 09:22:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/19/2008 07:31:39	METER 1 - M:	11497	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/19/2008 07:31:40	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$30.90	\$0.00	\$45.28
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$120.72	\$0.00	\$178.22
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.50	\$28.75	\$48.59	\$0.00	\$77.34

JOB COUNT: 3	WORK ORDER TOTAL:	1.75	100.63	200.21	0.00	300.84
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11088474	11/18/2008 12:15:00	11/18/2008 12:45:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11088474	11/18/2008 11:00:00	11/18/2008 12:00:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11088474	11/18/2008 12:00:00	11/18/2008 12:15:00	0.25	\$14.38
					LABOR	100.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.45	2	\$30.90
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	16.41	5	\$82.05
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	F81Z9N184AA	FUEL FILTER	48.59	1	\$48.59
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.63	1	\$2.63
66-PM-PMA	PERFORM OIL CHANGE	3C3Z6734AA	GASKET	4.99	1	\$4.99
66-PM-PMA	PERFORM OIL CHANGE	FL2016	OIL FILTER KIT	31.05	1	\$31.05
					PARTS	200.21

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 2430

Work Order Notes

(LPATE) PM-REPLACED WIPERS-REPLACE FUEL FILTER

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 0

(LPATE) PM BY JE-REPLACED COPPER OIL PLUG GASKET

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE) The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24459

USING DEPT NO:	504302	OPENED DATE:	09/27/2016 14:39:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/27/2016 15:50:00	METER 1 - M:	46805	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2016 15:50:01	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-53-996	PURCHASED MISC TOOLS	DON	O	N	GARAGE	0.00	\$0.00	\$133.44	\$0.00	\$133.44

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	133.44	0.00	133.44
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-53-996	PURCHASED MISC TOOLS	GRE2036R	1/2" DRIVE	8.75	2	\$17.50
PU-53-996	PURCHASED MISC TOOLS	44809	1/2" RATCHET	24.99	1	\$24.99
PU-53-996	PURCHASED MISC TOOLS	44809	1/2" RATCHET	24.99	1	\$24.99
PU-53-996	PURCHASED MISC TOOLS	44809	1/2" RATCHET	24.99	1	\$24.99
PU-53-996	PURCHASED MISC TOOLS	44809	1/2" RATCHET	24.99	1	\$24.99
PU-53-996	PURCHASED MISC TOOLS	50733	1" SOCKET	7.99	1	\$7.99
PU-53-996	PURCHASED MISC TOOLS	50733	1" SOCKET	7.99	1	\$7.99
					PARTS	133.44

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24459

Work Order Notes

(LISAPATE) PURCHASED TOOLS FOR MOVERS TO USE WHEN INSTALLING TENTS

Job Notes

PU-53-996 - PURCHASED MISC TOOLS

(LISAPATE) GAVE TOOLS TO MANNING

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24595

USING DEPT NO:	504302	OPENED DATE:	10/12/2016 07:22:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2016 13:23:32	METER 1 - M:	50021	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2016 13:23:34	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	1.50	\$86.25	\$0.00	\$0.00	\$86.25

JOB COUNT: 1	WORK ORDER TOTAL:	1.50	86.25	0.00	0.00	86.25
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11397026	10/12/2016 09:45:26	10/12/2016 11:15:26	1.50	\$86.25
					LABOR	86.25

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24595

Work Order Notes

(LISAPATE) CHECK ENGINE LIGHT IS ON

Job Notes

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(LISAPATE) SCAN OUT P0443-EVAP PURGE CIRCUIT PERFORMANCE
CLEARED CODE, CUSTOMER HAD TO PICK UP WILL BRING BACK AT A LATER DATE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24732

USING DEPT NO:	504302	OPENED DATE:	10/24/2016 10:47:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2016 09:46:13	METER 1 - M:	47237	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2016 09:46:14	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-027	REPLACE NEW RELAY	DON	O	N	GARAGE	0.30	\$17.25	\$16.73	\$0.00	\$33.98
PU-53-996	PURCHASED MISC TOOLS	DON	O	N	GARAGE	0.00	\$0.00	\$21.00	\$0.00	\$21.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.30	17.25	37.73	0.00	54.98
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-027	REPLACE NEW RELAY	11170580	10/24/2016 10:50:04	10/24/2016 11:08:04	0.30	\$17.25
					LABOR	17.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-027	REPLACE NEW RELAY	STIEFL4	FLASHER	16.73	1	\$16.73
PU-53-996	PURCHASED MISC TOOLS	STRUCTURAL PIPE	STEEL PIPE	7.00	3	\$21.00
					PARTS	37.73

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 24732

Work Order Notes

(LISAPATE) FLASHERS INOP-DRIVER REQUESTED STEEL PIPES FOR INSTALLING TENTS ON QUAD

Job Notes

03-34-027 - REPLACE NEW RELAY

(LISAPATE) REPLACED HAZARDS HIGH RESISTANCE RELAY. RECHECKED OK

PU-53-996 - PURCHASED MISC TOOLS

(LISAPATE) PURCHASED 3 STEEL TUBES FOR INSTALLING TENTS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 25381

USING DEPT NO:	504302	OPENED DATE:	01/09/2017 09:12:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/20/2017 09:02:44	METER 1 - M:	48317	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/20/2017 09:02:51	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-42-035	ADJUST WATER/DCA FILTER	DON	O	N	GARAGE	0.30	\$17.25	\$5.76	\$0.00	\$23.01
03-55-044	REPLACE NEW LIFTGATE DUAL CONTF	DON	O	N	GARAGE	2.50	\$143.75	\$125.25	\$0.00	\$269.00
03-65-065	REPLACE NEW HYDRAULIC PUMP	DON	O	N	GARAGE	2.00	\$115.00	\$1,113.84	\$0.00	\$1,228.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$46.88	\$121.82	\$0.00	\$168.70
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	1.00	\$57.50	\$16.99	\$0.00	\$74.49
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	0.79	\$45.14	\$220.05	\$0.00	\$265.19

JOB COUNT: 6	WORK ORDER TOTAL:	7.40	425.52	1,603.71	0.00	2,029.23
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-65-065	REPLACE NEW HYDRAULIC PUMP	11213180	01/18/2017 09:30:00	01/18/2017 11:30:00	2.00	\$115.00
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	11213180	01/18/2017 07:00:00	01/18/2017 09:30:00	2.50	\$143.75
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11170580	01/11/2017 10:29:39	01/11/2017 11:16:45	0.79	\$45.14
66-PM-PMA	PERFORM OIL CHANGE	11758845	01/09/2017 13:46:24	01/09/2017 14:35:19	0.82	\$46.88
01-42-035	ADJUST WATER/DCA FILTER	11758845	01/09/2017 13:16:43	01/09/2017 13:16:55	0.00	(\$0.19)
01-42-035	ADJUST WATER/DCA FILTER	11758845	01/09/2017 13:16:43	01/09/2017 13:16:55	0.00	\$0.19
01-42-035	ADJUST WATER/DCA FILTER	11758845	01/09/2017 13:16:43	01/09/2017 13:34:43	0.30	\$17.25
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	01/09/2017 13:16:33	01/09/2017 13:16:43	0.00	(\$0.16)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	01/09/2017 13:16:33	01/09/2017 13:16:43	0.00	\$0.16
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	01/09/2017 13:16:33	01/09/2017 14:16:33	1.00	\$57.50
					LABOR	425.52

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.69	1	\$2.69
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	11.96	5	\$59.80
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	80001429	SWITCH KIT	114.48	1	\$114.48

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	93604	ELECTRICAL TAPE	0.95	1	\$0.95
03-65-065	REPLACE NEW HYDRAULIC PUMP	70430620	HYDRAULIC PUMP	1113.84	1	\$1,113.84
66-PM-PMT	PERFORM TRANSMISSION SERVICE	MK29542824	TRANSMISSION FILTER	32.61	1	\$32.61
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99
66-PM-PMT	PERFORM TRANSMISSION SERVICE	CIT632493001004	QUATRASYND TRANS FLUID	169.68	1	\$169.68
66-PM-PMT	PERFORM TRANSMISSION SERVICE	WIX57701	TRANSMISSION FILTER	17.76	1	\$17.76
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	LITMEG175	LITTELFUSE	4.91	1	\$4.91
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	LITMEG175	LITTELFUSE	4.94	1	\$4.94
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	45.36	1	\$45.36
01-42-035	ADJUST WATER/DCA FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	LITMEG175	LITTELFUSE	4.94	(1)	(\$4.94)
03-55-044	REPLACE NEW LIFTGATE DUAL CONTROL SWITCH	LITMEG175	LITTELFUSE	4.91	1	\$4.91
					PARTS	1603.71

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 25381

Work Order Notes

(LISAPATE) PM-PMF-PMT-LIFTGATE IS INOP

Job Notes

01-42-035 - ADJUST WATER/DCA FILTER

(LISAPATE) REPLACED COOLANT FILTER

03-55-044 - REPLACE NEW LIFTGATE DUAL CONTROL SWITCH

(LISAPATE) REPLACED 175 AMP MEGA FUSE. ALSO REPLACED CONTROL SWITCH

03-65-065 - REPLACE NEW HYDRAULIC PUMP

(RWINTERS) FOUND PUMP WAS GETTING HOT DUE TO STICKING CONTROL SWITCH RUNNING PUMP NONSTOP. REPLACED LIFTGATE HYD PUMP AND FILLED WITH CHARGED OUT FLUID. RECHECKED OK

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY CS-REPLACED AIR FILTER

COOLANT -29'

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(RWINTERS) SERVICED TRANSMISSION REPLACED BOTH INTERNAL AND EXTERNAL FILTERS AND FLUID. TEST DROVE RECHECKED OK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 26454

USING DEPT NO:	504302	OPENED DATE:	05/26/2017 08:26:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/16/2017 09:39:09	METER 1 - M:	50430	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/16/2017 09:39:10	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-035	REPLACE NEW WATER/DCA FILTER	DON	O	N	GARAGE	0.50	\$28.75	\$5.76	\$0.00	\$34.51
24-32-001	REPAIR CABLES/WIRING	DON	O	N	GARAGE	1.50	\$86.25	\$9.77	\$0.00	\$96.02
31-17	ROTATE TIRES, TUBES, LINERS & VALV	DON	P	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
66-79-002	PERFORM SERVICE CALL	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-OLS	PERFORM OIL SAMPLES	DON	P	N	GARAGE	0.30	\$17.25	\$8.00	\$0.00	\$25.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$61.34	\$0.00	\$118.84
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.60	\$34.50	\$16.99	\$0.00	\$51.49

JOB COUNT: 7	WORK ORDER TOTAL:	5.40	310.50	101.86	0.00	412.36
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	06/12/2017 08:18:00	06/12/2017 08:54:00	0.60	\$34.50
66-PM-PMA	PERFORM OIL CHANGE	11758845	06/12/2017 07:00:00	06/12/2017 08:00:00	1.00	\$57.50
66-PM-OLS	PERFORM OIL SAMPLES	11758845	06/12/2017 08:00:00	06/12/2017 08:18:00	0.30	\$17.25
66-79-002	PERFORM SERVICE CALL	11213180	06/12/2017 07:00:00	06/12/2017 08:00:00	1.00	\$57.50
31-17	ROTATE TIRES, TUBES, LINERS & VALVES	11758845	06/12/2017 08:54:00	06/12/2017 09:24:00	0.50	\$28.75
24-32-001	REPAIR CABLES/WIRING	11213180	06/12/2017 08:00:00	06/12/2017 09:30:00	1.50	\$86.25
03-42-035	REPLACE NEW WATER/DCA FILTER	11758845	06/12/2017 07:00:00	06/12/2017 07:30:00	0.50	\$28.75
03-42-035	REPLACE NEW WATER/DCA FILTER	11758845	06/12/2017 07:00:00	06/12/2017 07:18:00	(0.30)	(\$17.25)
03-42-035	REPLACE NEW WATER/DCA FILTER	11758845	06/12/2017 07:00:00	06/12/2017 07:18:00	0.30	\$17.25
					LABOR	310.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40P	PROTECK DIESEL OIL	9.36	5	\$46.80
24-32-001	REPAIR CABLES/WIRING	MMM06133	ELECTRICAL TAPE	4.38	1	\$4.38
24-32-001	REPAIR CABLES/WIRING	PIC2500C	CONNECTORS	5.39	1	\$5.39
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-42-035	REPLACE NEW WATER/DCA FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
66-PM-OLS	PERFORM OIL SAMPLES	OSB	OIL SAMPLE BOTTLE	8.00	1	\$8.00
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	2.69	1	\$2.69
					PARTS	101.86

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 26454

Work Order Notes

(LISAPATE) DEPT REQUESTED A SERVICE CALL WAIT TO START LIGHT IS ON TUCK WILL NOT CRANK AT ALL BESIDE RUSSELL HALL-DUE FOR PM-PMF AND WATER FILTER

Job Notes

03-42-035 - REPLACE NEW WATER/DCA FILTER

(LISAPATE) REPLACED COOLANT FILTER

24-32-001 - REPAIR CABLES/WIRING

(LISAPATE) FOUND GROUND CONNECTOR @ BATTERY WAS MELTED. REMOVED CONNECTORS AND STRAIGHT WIRED. RECHECKED OK

31-17 - ROTATE TIRES, TUBES, LINERS & VALVES

(LISAPATE) ROTATED TIRES

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) SERVICE CALL COMPLETED.

66-PM-OLS - PERFORM OIL SAMPLES

(LISAPATE) PULLED OIL SAMPLE

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY CS

TOPPED COOLANT OFF WITH DELO ALREADY CHARGED OUT

JACKED UP FRONT END ND GREASED KING PINS AND CHECKED HUBS. TRUCK NEEDS TO COME BACK FOR RF KING PIN TO BE SHIMMED AND AN ALIGNMENT

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

Work Order Charge Detail

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 26846

USING DEPT NO:	504302	OPENED DATE:	07/17/2017 08:09:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/24/2017 15:15:06	METER 1 - M:	51208	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/24/2017 15:15:08	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-074	REPLACE NEW WINDOW SWITCH	DON	O	N	GARAGE	0.50	\$28.75	\$49.09	\$0.00	\$77.84

JOB COUNT: 1	WORK ORDER TOTAL:					0.50	28.75	49.09	0.00	77.84
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-074	REPLACE NEW WINDOW SWITCH	11268671	07/21/2017 07:00:00	07/21/2017 07:30:00	0.50	\$28.75
					LABOR	28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-074	REPLACE NEW WINDOW SWITCH	XL1Z14529CA	WINDOW SWITCH	49.09	1	\$49.09
					PARTS	49.09

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 26846

Work Order Notes

(LISAPATE) PASSENGER WINDOW WONT WORK

Job Notes

03-02-074 - REPLACE NEW WINDOW SWITCH

(LISAPATE) ORDERED NEW PASSENGER WINDOW SWITCH FROM FORD. IF INSTALLED

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 27605

USING DEPT NO:	504302	OPENED DATE:	09/27/2017 10:06:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/28/2017 14:46:34	METER 1 - M:	52326	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/28/2017 14:46:38	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-007	REPLACE NEW COOLANT FILTER	DON	O	N	GARAGE	0.31	\$18.08	\$5.76	\$0.00	\$23.84
16-53	TRANSPORT EXPENDABLE ITEMS	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.02	\$58.70	\$104.26	\$0.00	\$162.96
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.22	\$12.92	\$16.99	\$0.00	\$29.91
PU-53-996	PURCHASED MISC TOOLS	DON	O	N	GARAGE	0.00	\$0.00	\$28.11	\$0.00	\$28.11

JOB COUNT: 5	WORK ORDER TOTAL:	2.56	147.20	155.12	0.00	302.32
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-53	TRANSPORT EXPENDABLE ITEMS	10208562	09/27/2017 16:09:42	09/27/2017 17:09:42	1.00	\$57.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	09/27/2017 13:24:38	09/27/2017 13:38:07	0.22	\$12.92
03-42-007	REPLACE NEW COOLANT FILTER	11074414	09/27/2017 13:05:42	09/27/2017 13:24:34	0.31	\$18.08
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/27/2017 13:00:00	09/27/2017 13:05:40	0.09	\$5.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	09/27/2017 11:04:25	09/27/2017 12:00:00	0.93	\$53.27
					LABOR	147.20

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PROTECK AF	DIESEL ANTIFREEZE 50/50	9.12	1	\$9.12
66-PM-PMA	PERFORM OIL CHANGE	15W40P	PROTECK DIESEL OIL	9.37	4	\$37.48
66-PM-PMA	PERFORM OIL CHANGE	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99
66-PM-PMA	PERFORM OIL CHANGE	BALPF7698	BALDWIN FUEL FILTER	16.99	(1)	(\$16.99)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	45.81	1	\$45.81
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
PU-53-996	PURCHASED MISC TOOLS	1" COLD ROUND	STEEL ROD	28.11	1	\$28.11
					PARTS	155.12

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 27605

Work Order Notes

(LISAPATE) PM-PMF-REPLACE COOLANT FILTER

Job Notes

03-42-007 - REPLACE NEW COOLANT FILTER

(LISAPATE) REPLACED COOLANT FILTER

16-53 - TRANSPORT EXPENDABLE ITEMS

(IFALLS) EK WENT TO CAIN STEEL TO PURCHASE 10 FT STICK OF COLD ROLL STEAL

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY SH-REPLACED AIR FILTER

(LISAPATE) USED 1/2GAL OF OIL ALREADY CHARGED OUT

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

PU-53-996 - PURCHASED MISC TOOLS

(LISAPATE) GERALD REQUESTED A STEEL POLE FOR INSTALLING TENTS. CAIN STEEL ONLY SELLS 10' SECTION PURCHASED ONE POLE IT WAS CUT TO 59" AND 61" GAVE POLES TO ERIC

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 27894

USING DEPT NO:	504302	OPENED DATE:	10/19/2017 14:10:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2017 07:02:09	METER 1 - M:	52594	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2017 07:02:11	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-55-039	REPAIR LIFTGATE ASSY	DON	O	N	GARAGE	0.50	\$28.75	\$2.70	\$0.00	\$31.45

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	2.70	0.00	31.45
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-039	REPAIR LIFTGATE ASSY	11074414	10/24/2017 06:00:00	10/24/2017 06:30:00	0.50	\$28.75
					LABOR	28.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-039	REPAIR LIFTGATE ASSY	TUBE GREASE	TUBE GREASE	2.70	1	\$2.70
					PARTS	2.70

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 27894

Work Order Notes

(LISAPATE) PER DRIVER BOLT IS BROKEN OF THE LIFT GATE

Job Notes

24-55-039 - REPAIR LIFTGATE ASSY

(LISAPATE) SH-GREASED LIFT AND TIGHTENED BOLTS. IF-REPAIRED BROKEN BOLT ON LEFT SIDE OF LIFTGATE
SH-REPLACED RIVET IN LR BACK UP LIGHT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 28444

USING DEPT NO:	504302	OPENED DATE:	12/15/2017 09:41:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2017 06:29:50	METER 1 - M:	53407	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2017 06:29:53	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-78-043	PURCHASED REAR BUMPER GUARDS	DON	O	N	GARAGE	0.30	\$17.25	\$63.36	\$0.00	\$80.61

JOB COUNT: 1	WORK ORDER TOTAL:					0.30	17.25	63.36	0.00	80.61
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-78-043	PURCHASED REAR BUMPER GUARDS	11268671	12/15/2017 10:14:52	12/15/2017 10:32:52	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-78-043	PURCHASED REAR BUMPER GUARDS	3X12BUMPERS	3X12 BUMPERS	15.84	4	\$63.36
					PARTS	63.36

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **28444**

Work Order Notes

(RWINTERS) PURCHASED NEW REAR BUMPERS FOR REAR BUMPER OF TRUCK. PLUS AN ADDITIONAL SET

Job Notes

PU-78-043 - PURCHASED REAR BUMPER GUARDS

(LISAPATE) PUT ONE SET ON AND GAVE GERALD ONE SET OF BUMPERS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 29232

USING DEPT NO:	504302	OPENED DATE:	03/28/2018 11:54:28	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2018 14:18:58	METER 1 - M:	54850	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2018 14:19:00	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650	UNIT SERIAL NO: 3FRNF65Y56V356324						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$780.56	\$780.56
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.00	\$0.00	\$171.15	\$0.00	\$171.15
03-32-010	REPLACE NEW STARTER	DON	O	N	GARAGE	1.50	\$0.00	\$322.61	\$0.00	\$322.61
03-34-001	REPLACE NEW HEADLAMPS	DON	O	N	GARAGE	0.30	\$0.00	\$7.53	\$0.00	\$7.53
03-42-002	REPLACE NEW RADIATOR	DON	O	N	GARAGE	7.00	\$0.00	\$1,463.71	\$0.00	\$1,463.71
03-42-035	REPLACE NEW WATER/DCA FILTER	DON	O	N	GARAGE	0.50	\$0.00	\$5.76	\$0.00	\$5.76
03-44-003	REPLACE NEW FUEL PUMP	DON	O	N	GARAGE	1.00	\$0.00	\$1,480.21	\$0.00	\$1,480.21
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$0.00	\$17.06	\$0.00	\$17.06
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BL	DON	O	N	GARAGE	26.60	\$0.00	\$13,726.59	\$0.00	\$13,726.59
14-27	INSTALL TRANSMISSION - MAIN, AUTO	DON	O	N	GARAGE	3.50	\$0.00	\$51.82	\$0.00	\$51.82
14-52-021	INSTALL GPS SYSTEM	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.67	\$0.00	\$0.00	\$0.00	\$0.00
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	DON	O	N	GARAGE	8.00	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREI	DON	O	N	GARAGE	2.00	\$0.00	\$3.59	\$0.00	\$3.59
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.00	\$0.00	\$145.00	\$0.00	\$145.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$0.00	\$33.79	\$0.00	\$33.79
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	O	N	GARAGE	0.40	\$0.00	\$18.75	\$0.00	\$18.75
CL-41-004	CLEANED INTERCOOLER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$258.75	\$258.75
PU-32-002	PURCHASED BATTERY	DON	O	N	GARAGE	0.00	\$0.00	\$87.76	\$0.00	\$87.76

JOB COUNT: 19	WORK ORDER TOTAL:	57.22	0.00	17,535.33	1,039.31	18,574.64
---------------	-------------------	-------	------	-----------	----------	-----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CL-41-004	CLEANED INTERCOOLER	11277413	45002	0044090	\$258.75

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	\$258.75
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	(\$258.75)
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	\$258.75
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	(\$258.75)
CL-41-004	CLEANED INTERCOOLER	11277413		0044202	(\$100.00)
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	\$258.75
CL-41-004	CLEANED INTERCOOLER	11277413		0044090	(\$258.75)
CL-41-004	CLEANED INTERCOOLER	11277413		0044202	\$100.00
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	2592505	4180007010	0044218	(\$780.56)
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	2592505	4180007010	0044218	\$780.56
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	2592505	4180007010	0044302	\$780.56

COMML 1039.31

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11915538	07/24/2018 14:31:47	07/24/2018 15:11:50	0.67	\$0.00
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11901357	07/18/2018 07:18:00	07/18/2018 07:42:00	0.40	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11758845	07/24/2018 07:00:00	07/24/2018 07:30:00	0.50	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/24/2018 07:00:00	07/24/2018 09:00:00	2.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11170580	07/18/2018 07:00:00	07/18/2018 09:00:00	2.00	\$0.00
35-40	DIAGNOSE ENGINE / MOTOR SYSTEMS	11170580	07/18/2018 07:00:00	07/18/2018 15:00:00	8.00	\$0.00
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11915538	07/18/2018 07:00:00	07/18/2018 08:00:00	1.00	\$0.00
14-52-021	INSTALL GPS SYSTEM	11758845	07/18/2018 07:00:00	07/18/2018 08:00:00	1.00	\$0.00
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	11170580	07/18/2018 19:06:00	07/18/2018 22:36:00	3.50	\$0.00
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	11170580	07/24/2018 07:00:00	07/25/2018 09:36:00	26.60	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11901357	07/24/2018 07:00:00	07/24/2018 07:15:00	0.25	\$0.00
03-44-003	REPLACE NEW FUEL PUMP	11170580	07/18/2018 15:00:00	07/18/2018 16:00:00	1.00	\$0.00
03-42-035	REPLACE NEW WATER/DCA FILTER	11170580	07/24/2018 07:00:00	07/24/2018 07:30:00	0.50	\$0.00
03-42-002	REPLACE NEW RADIATOR	11170580	07/24/2018 09:36:00	07/24/2018 16:36:00	7.00	\$0.00
03-34-001	REPLACE NEW HEADLAMPS	11901357	07/18/2018 07:00:00	07/18/2018 07:18:00	0.30	\$0.00
03-32-010	REPLACE NEW STARTER	11170580	07/18/2018 17:36:00	07/18/2018 19:06:00	1.50	\$0.00
03-32-002	REPLACE NEW BATTERY	11170580	07/23/2018 16:36:00	07/23/2018 17:36:00	1.00	\$0.00

LABOR 0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS SLO491453		T-BOLT CLAMP 83-90 MM	5.74	1	\$5.74
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS SLO491452		T-BOLT CLAMP 76-84 MM	5.26	1	\$5.26
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS SLO491335		T-BOLT CLAMP 70-92 MM	8.19	1	\$8.19
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS SLO491451		T-BOLT CLAMP 67-77 MM	5.17	1	\$5.17
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	2	\$10.46
03-42-002	REPLACE NEW RADIATOR	MAG1ATF	ALLISON TRANS FLUID TES-295	27.74	1	\$27.74
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS 15W40QT		DIESEL OIL QT DELO CK-4	2.99	2	\$5.98
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	(8)	(\$72.96)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	9	\$82.08
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	1817674C1	FUEL STRAINER ELEMENT	16.80	1	\$16.80
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS 5C4Z3C772DA		PUMP ASSY P/S AND FUEL	1480.21	1	\$1,480.21
03-32-002	REPLACE NEW BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	87.76	1	\$87.76
03-32-002	REPLACE NEW BATTERY	BP19C	BATTERY TERMINAL-TOP POST REG	0.99	1	\$0.99
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	(2)	(\$10.46)
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	4	\$20.92
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	(4)	(\$20.92)
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	5	\$26.15
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	(1)	(\$2.11)
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	2	\$4.22
66-42-016	PERFORM FLUSH COOLING SYSTEM	RADIATOR FLUSH	RADIATOR FLUSH	2.99	(2)	(\$5.98)
03-32-010	REPLACE NEW STARTER	4C4Z11002B	STARTER	322.61	1	\$322.61
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	(2)	(\$4.22)
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	3	\$6.33
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS STIPS314		OIL PRESSURE SENDER	26.48	1	\$26.48
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	611942109463	2X2 PVC PIPE	4.82	1	\$4.82
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	611942037643	2" PVC COUPLING	1.14	1	\$1.14
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	034481062301	REDUCER BUSHING 2 1/2/ X 2	7.40	1	\$7.40
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	611942038572	2" PVC CAP SLIP	1.78	1	\$1.78
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS 29546682		TRANS FRONT SEAL	14.48	1	\$14.48
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PTX24240		BLUE LOCTITE 1.22 OZ	19.47	1	\$19.47
03-32-002	REPLACE NEW BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	87.76	(1)	(\$87.76)
03-32-002	REPLACE NEW BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	87.76	1	\$87.76
03-32-010	REPLACE NEW STARTER	4C4Z11002B	STARTER	322.61	(1)	(\$322.61)
03-32-010	REPLACE NEW STARTER	4C4Z11002B	STARTER	322.61	1	\$322.61

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-42-002	REPLACE NEW RADIATOR	MAG1ATF	ALLISON TRANS FLUID TES-295	27.74	(1)	(\$27.74)
03-42-002	REPLACE NEW RADIATOR	MAG1ATF	ALLISON TRANS FLUID TES-295	27.74	2	\$55.48
03-51-038	REPLACE NEW WIPER BLADES	VV324	TRANS FLUID QT	5.23	(5)	(\$26.15)
14-27	INSTALL TRANSMISSION - MAIN, AUTOMATIC	VV324	TRANS FLUID QT	5.24	7	\$36.68
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	(9)	(\$82.08)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	12	\$109.44
03-34-001	REPLACE NEW HEADLAMPS	H6054 LMP	BULB-HEADLIGHT-HALOGEN	7.53	1	\$7.53
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS SLO491451		T-BOLT CLAMP 67-77 MM	5.17	1	\$5.17
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS FHCCB032		HOSE CLAMP	0.58	1	\$0.58
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	(12)	(\$109.44)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS PROTECK AF		DIESEL ANTIFREEZE 50/50	9.12	11	\$100.32
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	17.81	1	\$17.81
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
66-PM-PMT	PERFORM TRANSMISSION SERVICE	WIX57701	TRANSMISSION FILTER	18.75	1	\$18.75
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	1.82	18	\$32.76
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	1.82	20	\$36.40
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	18	\$1.62
03-32-002	REPLACE NEW BATTERY	31S30	BATTERY BCI 31 HD STUD 950 CCA	85.08	2	\$170.16
66-PM-OLS	PERFORM OIL SAMPLES	OSB	OIL SAMPLE BOTTLE	8.00	(1)	(\$8.00)
03-32-002	REPLACE NEW BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	87.76	(1)	(\$87.76)
03-42-002	REPLACE NEW RADIATOR	4C4Z8A365B	HOSE	13.99	(1)	(\$13.99)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS 5C4Z3C772DA		PUMP ASSY P/S AND FUEL	1480.21	(1)	(\$1,480.21)
03-44-003	REPLACE NEW FUEL PUMP	5C4Z3C772DA	PUMP ASSY P/S AND FUEL	1480.21	1	\$1,480.21
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.23	2	\$0.46
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.09	1	\$1.09
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON LB	RECLAIMED FREON LB	1.50	1	\$1.50
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	6	\$0.54
PU-32-002	PURCHASED BATTERY	29HM	HD BATTERY DC 29M/31S 100AH	87.76	1	\$87.76
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS STIPS314		OIL PRESSURE SENDER	26.48	(1)	(\$26.48)
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	(18)	(\$1.62)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	17.81	(1)	(\$17.81)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	16.99	1	\$16.99
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	45.81	1	\$45.81
03-42-035	REPLACE NEW WATER/DCA FILTER	BALB5134	COOLANT FILTER SPIN-ON	5.76	1	\$5.76

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	11.85	1	\$11.85
66-PM-OLS	PERFORM OIL SAMPLES	OSB	OIL SAMPLE BOTTLE	8.00	1	\$8.00
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	2	\$17.06
66-42-016	PERFORM FLUSH COOLING SYSTEM	RADIATOR FLUSH	RADIATOR FLUSH	2.99	1	\$2.99
66-42-016	PERFORM FLUSH COOLING SYSTEM	RADIATOR FLUSH	RADIATOR FLUSH	2.99	2	\$5.98
66-42-016	PERFORM FLUSH COOLING SYSTEM	RADIATOR FLUSH	RADIATOR FLUSH	2.99	(1)	(\$2.99)
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	1	\$2.11
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	1154629339029	ENGINE 6.0L DIESEL F650	13413.00	1	\$13,413.00
03-42-002	REPLACE NEW RADIATOR	3C3Z10884AA	SENDER	26.01	1	\$26.01
03-42-002	REPLACE NEW RADIATOR	4C4Z6C640QA	CONNECTOR	206.77	1	\$206.77
03-42-002	REPLACE NEW RADIATOR	4C4Z6C640RA	CONNECTOR	69.09	1	\$69.09
03-42-002	REPLACE NEW RADIATOR	4C4Z6K769BA	DUCT	60.90	1	\$60.90
03-42-002	REPLACE NEW RADIATOR	4C4Z6K770AA	DUCT	90.70	1	\$90.70
03-42-002	REPLACE NEW RADIATOR	RADIATOR	ALL METAL 12 INTL RADIATOR	775.00	1	\$775.00
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	FWS61125	SAFETY CHAIN QUICK LINK	4.40	5	\$22.00
03-42-002	REPLACE NEW RADIATOR	4C4Z8A365B	HOSE	13.99	1	\$13.99
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	4C4Z12B568AA	WIRE ASSY	65.01	1	\$65.01
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	4C4Z12B568BA	WIRE ASSY	33.79	1	\$33.79
03-42-002	REPLACE NEW RADIATOR	4C4Z8286EA	HOSE	18.03	1	\$18.03
03-42-002	REPLACE NEW RADIATOR	4C4Z8260AA	LOWER RADIATOR HOSE	31.31	1	\$31.31
03-42-002	REPLACE NEW RADIATOR	3C3Z10884AA	SENDER	26.01	(1)	(\$26.01)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	SLO491452	T-BOLT CLAMP 76-84 MM	5.26	1	\$5.26
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	SLO491453	T-BOLT CLAMP 83-90 MM	5.74	1	\$5.74
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	PROTECK AF	DIESEL ANTIFREEZE 50/50	9.12	7	\$63.84
03-42-002	REPLACE NEW RADIATOR	44851241	COOLANT RESERVOIR	156.43	1	\$156.43
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	08001	WEATHERSTRIP/GASKET ADHESIVE	5.83	1	\$5.83
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	PROTECK AF	DIESEL ANTIFREEZE 50/50	9.12	(7)	(\$63.84)
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	PROTECK AF	DIESEL ANTIFREEZE 50/50	9.12	8	\$72.96
04-40-413	REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS	SLO491454	T-BOLT CLAMP 87-98 MM	5.60	1	\$5.60
					PARTS	17535.33

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 29232

Work Order Notes

(LISAPATE) PM-PMF-COOLANT FILTER-FLUSH COOLING SYSTEM
(RWINTERS) approx engine hours 10,770
(RWINTERS) AFTER SECOND ENGINE INSTALL 10,781

Job Notes

Work Order Charge Detail

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LISAPATE) BEST ONE INSTALLED 2 NEW STEER TIRES. PD BY CC

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) INSTALLED 2 NEW BATTERIES

03-32-010 - REPLACE NEW STARTER

(LISAPATE) STARTER BEGAN TO GO OUT. INSTALLED A NEW STARTER

03-34-001 - REPLACE NEW HEADLAMPS

(LISAPATE) REPLACED DRIVER HEADLIGHT

03-42-002 - REPLACE NEW RADIATOR

(LISAPATE) INSTALLED NEW RADIATOR

03-42-035 - REPLACE NEW WATER/DCA FILTER

(LISAPATE) REPLACED COOLANT FILTER

03-44-003 - REPLACE NEW FUEL PUMP

(LISAPATE) FOUND FUEL PUMP WAS SLUGGISH. REMOVED AND INSTALLED NEW FUEL PUMP, STRAINER AND CUP.

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

04-40-413 - REPLACE RBLT ENGINE ASSEMBLY BLOCK & HEADS

(LISAPATE) REMOVED AND REPLACED ENGINE. SEE ATTACHED NOTES VERY DETAILED

(RWINTERS) STOCK # 1154629 PROD # 347866

14-27 - INSTALL TRANSMISSION - MAIN, AUTOMATIC

(RWINTERS) TRANSMISSION WAS REMOVED TO ACCESS ENGINE. THEN WAS REINSTALLED AFTER ENGINE REPLACED.

(RWINTERS) REPLACED FRONT PUMP SEAL.

14-52-021 - INSTALL GPS SYSTEM

(LISAPATE) INSTALLED GPS SYSTEM SERIAL NUMBER 5015922699

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO BEST ONE BY RC

35-40 - DIAGNOSE ENGINE / MOTOR SYSTEMS

Work Order Charge Detail

(RWINTERS) VEHICLE WAS HERE FOR A COOLANT FLUSH. NOTICED BEFORE PERFORMING THE FLUSH THAT THE COOLANT HAD OIL IN IT. RADIATOR DOES NOT HAVE OIL COOLER IN IT. PERFORMED BLOCK TEST. ENGINE FAILED BLOCK TEST. STARTED TEARING ENGINE DOWN TO SEE IF IT HAD BLOWN HEADGASKETS. REMOVED CHARGE AIR COOLER HOSES, EVAC A/C AND REMOVED COMPRESSOR. REMOVED ALTERNATOR, DRIVE BELT TENSIONER, IDLER PULLEY ACCESSORY MOUNTING BRACKET. REMOVED FICM AND MOUNTING BRACKET, INTAKE PLENUM, TURBO ASSY AND EXHAUST PIPING, RADIATOR ASSY. REMOVED VALVE COVER HIGH PRESSURE OIL RAIL ASSY. STAND TUBES, INJECTOR ASSY, PUSHRODS, ROCKER ARMS. REMOVED BOTH HEADS FROM ENGINE. FOUND DRIVER SIDE HEADGASKET WAS LEAKING BETWEEN CYLINDERS AND COOLANT HAD CAME OUT OF ONE OF THE INJECTOR PASSAGES. SENT BOTH HEADS AND INTAKE PLENUM TO HAVE CHECKED AND CLEANED. HEADS CAME BACK OK AND PLENUM WAS CLEANED. RADIATOR WAS SENT OFF TO NABORS TO HAVE IT CLEANED. IT WAS DECIDED TO PUT A REMAN RUNNING ENGINE ASSY IN THE VEHICLE. REMOVED HOOD FROM TRUCK AND TOOK THE TRANSMISSION LOOSE FROM THE ENGINE. BORROWED A FORKLIFT BOOM FROM ENGINEERING TO PULL ENGINE OUT. HAD TO GET 5 QUICK LINKS FOR CHAIN TO LIFT ENGINE. PULLED ENGINE OUT PUT OLD ENGINE BACK TOGETHER FOR JASPER TO COME PICK UP AS A CORE.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) PERFORMED EVAC AND RECHARGE TWICE.

66-42-016 - PERFORM FLUSH COOLING SYSTEM

66-PM-OLS - PERFORM OIL SAMPLES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM BY AG

(LISAPATE) FIRST SERVICE AFTER NEW ENGINE DONE AT 55,174 MILES.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) REPLACED FUEL FILTER

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LISAPATE) REPLACED TRANSMISSION FILTER. TOPPED OFF FLUID. RECHECKED OK

CL-41-004 - CLEANED INTERCOOLER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

(LISAPATE) TOOK TO NABORS AND THEY CLEANED THE INTERCOOLER. PD BY CC

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

PU-32-002 - PURCHASED BATTERY

(LISAPATE) PURCHASED A BATTERY FOR ELECTRIC PALLET JACK AND GAVE TO DEPT.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 30396

USING DEPT NO:	504302	OPENED DATE:	07/27/2018 11:14:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2018 08:20:56	METER 1 - M:	55237	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2018 08:20:58	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-40-409	REPAIR HEAD(S)	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$355.00	\$355.00
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	0.00	0.00	355.00	355.00
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-40-409	REPAIR HEAD(S)	6166005	206	0044837	\$355.00
				COMML	355.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11170580	09/25/2018 07:00:00	09/25/2018 08:00:00	1.00	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	TECQ18001	SHIFT TUBE FORD	30.63	(1)	(\$30.63)
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	TECQ18002	SHIFT TUBE BUSHING	4.00	(2)	(\$8.00)
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	TECQ18001	SHIFT TUBE FORD	30.63	1	\$30.63
03-15-025	REPLACE NEW SHIFT TUBE/BUSHINGS	TECQ18002	SHIFT TUBE BUSHING	4.00	2	\$8.00
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 30396

Work Order Notes

(LISAPATE) Gerald requested a service call to ASB loading dock truck has a dead battery

Job Notes

03-15-025 - REPLACE NEW SHIFT TUBE/BUSHINGS

24-40-409 - REPAIR HEAD(S)

(LISAPATE) Heads were taken to Ron Spori in Bessemer to machine. A portion of the work was covered under warranty by Jasper engine they paid \$1725.00 for disassemble cylinder head, vat and clean cylinder heads, magnaflux cylinder heads, pressure test heads and clean intake.

Additional work was paid for by UA \$839.08- R&R valve guides, valve job, surface cylinder heads, clean & assemble cylinder heads. Parts used 8 valve guides and 32 valve seals

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) AB/AG-Service call completed. Found batteries were good. Moved shifter around and started ok. Shifter was in between gears, Shifter has some slack in it. Driver will bring the truck back when its free for shift tube and bushings to be replaced.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 32095

USING DEPT NO:	504302	OPENED DATE:	02/01/2019 15:08:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2019 06:36:13	METER 1 - M:	58580	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2019 06:36:17	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
07-15	LUBRICATE STEERING	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.30	\$0.00	\$0.00	\$0.00	\$0.00
66-42-035	PERFORM WATER/DCA FILTER	DON	P	N	GARAGE	0.50	\$0.00	\$14.12	\$0.00	\$14.12
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.16	\$0.00	\$47.09	\$0.00	\$47.09
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	1.16	\$0.00	\$18.53	\$0.00	\$18.53

JOB COUNT: 5	WORK ORDER TOTAL:	4.62	0.00	79.74	0.00	79.74
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-42-035	PERFORM WATER/DCA FILTER	11074414	02/19/2019 06:00:00	02/19/2019 06:30:00	0.50	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	02/19/2019 08:22:26	02/19/2019 09:32:05	1.16	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/18/2019 13:33:25	02/18/2019 15:43:00	2.16	\$0.00
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	02/19/2019 06:30:00	02/19/2019 06:48:00	0.30	\$0.00
07-15	LUBRICATE STEERING	11074414	02/19/2019 06:00:00	02/19/2019 06:30:00	0.50	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	1.59	20	\$31.80
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	2.81	1	\$2.81
66-42-035	PERFORM WATER/DCA FILTER	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.06	1	\$8.06
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	12.48	1	\$12.48
66-42-035	PERFORM WATER/DCA FILTER	BALB5134	COOLANT FILTER SPIN-ON	6.06	1	\$6.06
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	18.53	1	\$18.53
					PARTS	79.74

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 32095

Work Order Notes

(LISAPATE) PM-PMF-Coolant filter

Job Notes

07-15 - LUBRICATE STEERING

(LISAPATE) Greased and checked king pins and steering.

07-55-039 - LUBRICATE LIFTGATE ASSY

(LISAPATE) Greased lift gate and replaced wear pad(non-stock part)

66-42-035 - PERFORM WATER/DCA FILTER

(LISAPATE) Removed and replaced coolant filter and topped off coolant

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM by SH

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LISAPATE) Replaced fuel filter

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 33512

USING DEPT NO:	504302	OPENED DATE:	07/24/2019 07:43:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/15/2019 07:02:52	METER 1 - M:	61156	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/15/2019 07:02:54	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-17	REPLACE NEW TIRES, TUBES, LINERS	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,869.64	\$1,869.64
03-42-007	REPLACE NEW COOLANT FILTER	DON	O	N	GARAGE	0.20	\$0.00	\$6.06	\$0.00	\$6.06
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	N	N	GARAGE	2.36	\$0.00	\$0.00	\$0.00	\$0.00
19-01-072	WIRE/REWIRE A/C HIGH PRESSURE SV	DON	O	N	GARAGE	0.25	\$0.00	\$11.47	\$0.00	\$11.47
35-01	DIAGNOSE AIR CONDITIONING, HEAT, '	DON	O	N	GARAGE	1.98	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	3.28	\$0.00	\$96.17	\$0.00	\$96.17
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.16	\$0.00	\$18.53	\$0.00	\$18.53

JOB COUNT: 7	WORK ORDER TOTAL:	8.24	0.00	132.23	1,869.64	2,001.87
--------------	-------------------	------	------	--------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11078579	2090001679		\$1,593.64
03-17	REPLACE NEW TIRES, TUBES, LINERS & VALVES	11078579	2090001680		\$276.00
				COMML	1869.64

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/12/2019 10:45:38	08/12/2019 11:12:56	0.46	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/12/2019 09:42:15	08/12/2019 10:31:08	0.81	\$0.00
03-42-007	REPLACE NEW COOLANT FILTER	11901357	08/12/2019 09:30:00	08/12/2019 09:42:15	0.20	\$0.00
03-42-007	REPLACE NEW COOLANT FILTER	11901357	08/12/2019 09:19:06	08/12/2019 09:19:06	0.00	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11901357	08/12/2019 09:05:34	08/12/2019 09:15:00	0.16	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/12/2019 07:19:09	08/12/2019 09:05:34	1.77	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/12/2019 06:08:44	08/12/2019 06:22:56	0.24	\$0.00
19-01-072	WIRE/REWIRE A/C HIGH PRESSURE SWITCH	11170580	07/25/2019 08:25:31	07/25/2019 08:40:28	0.25	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	07/24/2019 14:34:02	07/24/2019 15:26:29	0.87	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11170580	07/24/2019 13:26:57	07/24/2019 13:45:37	0.31	\$0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11915538	07/24/2019 09:36:28	07/24/2019 11:58:16	2.36	\$0.00
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11268671	07/24/2019 08:59:26	07/24/2019 09:47:14	0.80	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	1.58	20	\$31.60
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.11	1	\$2.11
19-01-072	WIRE/REWIRE A/C HIGH PRESSURE SWITCH	PT5736	PIGTAIL	11.47	1	\$11.47
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	6.06	1	\$6.06
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	18.53	1	\$18.53
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	12.48	1	\$12.48
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	49.98	1	\$49.98
					PARTS	132.23

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **33512**

Work Order Notes

(LISAPATE) PM-PMF-Both outside tires have nails in the rear-check a/c blows hot at times

Job Notes

Work Order Charge Detail

03-17 - REPLACE NEW TIRES, TUBES, LINERS & VALVES

(LISAPATE) Southern Tire Mart Installed 4 new rear tires. PD by CC

03-42-007 - REPLACE NEW COOLANT FILTER

(LISAPATE) Replaced coolant filter

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Taken to Southern Tire Mart by RC

19-01-072 - WIRE/REWIRE A/C HIGH PRESSURE SWITCH

(LISAPATE) Installed a new pigtail. Rechecked ok

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

(LISAPATE) Found A/c not cooling at times. Checked power at cycling switch and it was good. Found cut out switch wire had a couple of strands of copper holding it together.

66-17-030 - PERFORM TIRE PATCH

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM by AG

Replaced air filter

Coolant -27'

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

Bin :

(LISAPATE) Replaced fuel filter

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 34801

USING DEPT NO:	504302	OPENED DATE:	11/11/2019 08:09:58	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	11/25/2019 11:28:18	METER 1 - M:	62345	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/25/2019 11:28:20	IN-SERVICE DATE:	02/07/2006						
TECH SPEC NO:	06TKFORDF650	2006 Ford F650									
				UNIT SERIAL NO:	3FRNF65Y56V356324						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-05-032	REPLACE NEW PCV HOSE	DON	O	N	GARAGE	1.58	\$0.00	\$30.11	\$0.00	\$30.11
03-05-033	REPLACE NEW PCV VALVE	DON	O	N	GARAGE	0.77	\$0.00	\$56.14	\$0.00	\$56.14
03-31-001	REPLACE NEW ALTERNATOR	DON	O	N	GARAGE	0.68	\$0.00	\$125.68	\$0.00	\$125.68
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.00	\$0.00	\$174.18	\$0.00	\$174.18
06-31	INSPECT CHARGING SYSTEM	DON	O	N	GARAGE	2.67	\$0.00	\$0.00	\$0.00	\$0.00
06-40-433	INSPECT OIL LEAK	DON	O	N	GARAGE	0.14	\$0.00	\$8.14	\$0.00	\$8.14
24-55-039	REPAIR LIFTGATE ASSY	DON	O	N	GARAGE	0.50	\$0.00	\$88.90	\$0.00	\$88.90
36-41	FLUSH AIR INTAKE SYSTEM	DON	O	N	GARAGE	0.63	\$0.00	\$69.71	\$0.00	\$69.71
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	2.34	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 9	WORK ORDER TOTAL:	10.31	0.00	552.86	0.00	552.86
--------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	11170580	11/22/2019 07:00:00	11/22/2019 08:00:00	1.00	\$0.00
24-55-039	REPAIR LIFTGATE ASSY	11268671	11/22/2019 07:00:00	11/22/2019 07:30:00	0.50	\$0.00
06-40-433	INSPECT OIL LEAK	11170580	11/19/2019 11:30:27	11/19/2019 11:38:51	0.14	\$0.00
03-05-032	REPLACE NEW PCV HOSE	11170580	11/19/2019 09:55:35	11/19/2019 11:30:27	1.58	\$0.00
03-05-033	REPLACE NEW PCV VALVE	11170580	11/19/2019 08:14:21	11/19/2019 09:00:31	0.77	\$0.00
36-41	FLUSH AIR INTAKE SYSTEM	11170580	11/19/2019 07:36:23	11/19/2019 08:14:21	0.63	\$0.00
03-31-001	REPLACE NEW ALTERNATOR	11170580	11/18/2019 08:20:48	11/18/2019 09:01:23	0.68	\$0.00
66-79-002	PERFORM SERVICE CALL	11170580	11/12/2019 14:50:24	11/12/2019 15:59:00	1.14	\$0.00
66-79-002	PERFORM SERVICE CALL	12052187	11/12/2019 14:47:05	11/12/2019 15:58:52	1.20	\$0.00
06-31	INSPECT CHARGING SYSTEM	11170580	11/18/2019 09:30:00	11/18/2019 11:56:27	2.44	\$0.00
06-31	INSPECT CHARGING SYSTEM	11170580	11/18/2019 09:01:23	11/18/2019 09:15:00	0.23	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-55-039	REPAIR LIFTGATE ASSY	COLLAR, SPRING ADJUSTM	WALTCO LIFTGATE PART	56.02	1	\$56.02
03-31-001	REPLACE NEW ALTERNATOR	DIXA9204	ALTERNATOR HD 130A PRESTOLITE	125.68	1	\$125.68
03-05-033	REPLACE NEW PCV VALVE	4C3Z6A665AC	CRANKCASE BREATHER PCV ASSY	56.14	1	\$56.14
03-05-032	REPLACE NEW PCV HOSE	5C4Z6A664AA	HOSE/ELBOW ASSY CRANKCASE VENT	30.11	1	\$30.11
36-41	FLUSH AIR INTAKE SYSTEM	C111	RED BRAKE CLEANER	2.46	2	\$4.92
36-41	FLUSH AIR INTAKE SYSTEM	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	2	\$16.50
06-40-433	INSPECT OIL LEAK	788106	UV DYE - OIL, ATF, PS, FUEL	4.07	2	\$8.14
36-41	FLUSH AIR INTAKE SYSTEM	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	(2)	(\$16.50)
36-41	FLUSH AIR INTAKE SYSTEM	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	1	\$8.25
03-32-002	REPLACE NEW BATTERY	31S30	BATTERY BCI 31 HD STUD 950 CCA	87.09	2	\$174.18
66-79-002	PERFORM SERVICE CALL	31S30	BATTERY BCI 31 HD STUD 950 CCA	87.09	(2)	(\$174.18)
36-41	FLUSH AIR INTAKE SYSTEM	A/C FLUSH	A/C FLUSH DURA II 32OZ	28.27	2	\$56.54
24-55-039	REPAIR LIFTGATE ASSY	SHIPPING	SHIPPING AND HANDLING	32.88	1	\$32.88
24-55-039	REPAIR LIFTGATE ASSY	SHIPPING	SHIPPING AND HANDLING	32.88	(1)	(\$32.88)
66-79-002	PERFORM SERVICE CALL	31S30	BATTERY BCI 31 HD STUD 950 CCA	87.09	2	\$174.18
24-55-039	REPAIR LIFTGATE ASSY	SHIPPING	SHIPPING AND HANDLING	32.88	1	\$32.88
					PARTS	552.86

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 34801

Work Order Notes

(RTUNAITI) Replace liftgate spring adjusting collar
(LISAPATE) Service call dead battery

Job Notes

03-05-032 - REPLACE NEW PCV HOSE

(LISAPATE) Installed new PCV hose

03-05-033 - REPLACE NEW PCV VALVE

(LISAPATE) Installed new PCV valve

03-31-001 - REPLACE NEW ALTERNATOR

(LISAPATE) Installed new alternator now charging at 14 volts Rechecked ok

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Installed 2 new batteries Checked alt charging at 11.9volts needs an alternator

06-31 - INSPECT CHARGING SYSTEM

(LISAPATE) tested after batteries replaced alt was only charging at 11.9 volts after replaced was upto 14 volts

06-40-433 - INSPECT OIL LEAK

(LISAPATE) Cleaned up oil leak in engine. Added UV dye in oil advised driver to bring back next week to recheck

24-55-039 - REPAIR LIFTGATE ASSY

(LISAPATE) Replaced lift gate tension spring on the liftgate

36-41 - FLUSH AIR INTAKE SYSTEM

(LISAPATE) Cleaned out charge air cooler, ran truck. Topped off coolant

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35278

USING DEPT NO:	504302	OPENED DATE:	01/03/2020 10:54:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/06/2020 08:12:32	METER 1 - M:	62817	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/06/2020 08:12:35	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-52-021	REPLACE NEW GPS SYSTEM	DON	O	N	GARAGE	0.28	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.28	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-021	REPLACE NEW GPS SYSTEM	12052187	01/03/2020 11:00:39	01/03/2020 11:17:36	0.28	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35278

Work Order Notes

(EKIMBREL) Install new 4G GPS

Job Notes

03-52-021 - REPLACE NEW GPS SYSTEM

(EKIMBREL) New GPS#5041375506

Old GPS# 5015922699

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35332

USING DEPT NO:	504302	OPENED DATE:	01/07/2020 14:14:46	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	02/04/2020 07:10:30	METER 1 - M:	63021	METER 2 - H:	0				
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/04/2020 07:10:31	IN-SERVICE DATE:	02/07/2006						
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-006	REPLACE NEW THERMOSTATS	DON	O	N	GARAGE	0.50	\$0.00	\$31.46	\$0.00	\$31.46
03-42-007	REPLACE NEW COOLANT FILTER	DON	P	N	GARAGE	0.12	\$0.00	\$6.30	\$0.00	\$6.30
06-42	INSPECT COOLING SYSTEM	DON	O	N	GARAGE	3.65	\$0.00	\$0.00	\$0.00	\$0.00
14-42-002	INSTALL RADIATOR	DON	O	N	GARAGE	5.19	\$0.00	\$83.93	\$0.00	\$83.93
16-42	TRANSPORT COOLING SYSTEM	DON	O	N	GARAGE	2.00	\$0.00	\$0.00	\$0.00	\$0.00
24-42-002	REPAIR RADIATOR	DON	O	N	GARAGE	0.00	\$0.00	\$20.16	\$172.50	\$192.66
25-42-002	REMOVE RADIATOR	DON	P	N	GARAGE	1.14	\$0.00	\$0.00	\$0.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.00	\$0.00	\$6.26	\$0.00	\$6.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.17	\$0.00	\$106.89	\$0.00	\$106.89
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$0.00	\$19.57	\$0.00	\$19.57

JOB COUNT: 10	WORK ORDER TOTAL:	16.08	0.00	274.57	172.50	447.07
---------------	-------------------	-------	------	--------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-42-002	REPAIR RADIATOR	11277413	50358		\$172.50
					COMML 172.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-007	REPLACE NEW COOLANT FILTER	12052187	01/29/2020 09:30:00	01/29/2020 09:31:18	0.02	\$0.00
03-42-007	REPLACE NEW COOLANT FILTER	12052187	01/29/2020 09:08:59	01/29/2020 09:15:00	0.10	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	12052187	01/29/2020 08:51:10	01/29/2020 09:08:59	0.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/29/2020 07:04:33	01/29/2020 08:51:10	1.78	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	01/28/2020 15:27:51	01/28/2020 15:51:42	0.40	\$0.00
16-42	TRANSPORT COOLING SYSTEM	10208562	01/24/2020 07:00:00	01/24/2020 09:00:00	2.00	\$0.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	11213180	01/23/2020 07:30:00	01/23/2020 08:30:00	1.00	\$0.00
03-42-006	REPLACE NEW THERMOSTATS	11213180	01/23/2020 07:00:00	01/23/2020 07:30:00	0.50	\$0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
06-42	INSPECT COOLING SYSTEM	11213180	01/16/2020 09:30:00	01/16/2020 11:44:01	2.23	\$0.00
06-42	INSPECT COOLING SYSTEM	11213180	01/16/2020 07:49:56	01/16/2020 09:15:00	1.42	\$0.00
14-42-002	INSTALL RADIATOR	11213180	01/15/2020 09:30:00	01/15/2020 11:48:39	2.31	\$0.00
14-42-002	INSTALL RADIATOR	11213180	01/15/2020 06:22:12	01/15/2020 09:15:00	2.88	\$0.00
25-42-002	REMOVE RADIATOR	11213180	01/10/2020 10:45:11	01/10/2020 11:53:50	1.14	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-42-002	REPAIR RADIATOR	PIGMAT	OIL ABSORMENT MAT	0.72	28	\$20.16
25-42-002	REMOVE RADIATOR	PIGMAT	OIL ABSORMENT MAT	0.72	(10)	(\$7.20)
03-42-006	REPLACE NEW THERMOSTATS	4 CLAMP	HOSE CLAMPS	0.35	1	\$0.35
25-42-002	REMOVE RADIATOR	PIGMAT	OIL ABSORMENT MAT	0.72	10	\$7.20
03-42-006	REPLACE NEW THERMOSTATS	4C4Z8575AA	THERMOSTAT	31.11	1	\$31.11
14-42-002	INSTALL RADIATOR	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	6	\$49.50
14-42-002	INSTALL RADIATOR	20 CLAMP	CLAMP 3/4-1 3/4	0.41	1	\$0.41
14-42-002	INSTALL RADIATOR	6 CLAMP	HOSE CLAMP	0.33	1	\$0.33
14-42-002	INSTALL RADIATOR	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	(6)	(\$49.50)
14-42-002	INSTALL RADIATOR	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.25	7	\$57.75
14-42-002	INSTALL RADIATOR	VV324	TRANS FLUID QT	4.24	4	\$16.96
14-42-002	INSTALL RADIATOR	VV324	TRANS FLUID QT	4.24	(4)	(\$16.96)
14-42-002	INSTALL RADIATOR	VV324	TRANS FLUID QT	4.24	6	\$25.44
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.21	19	\$3.99
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	0.74	1	\$0.74
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.09	17	\$1.53
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	19.57	1	\$19.57
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	51.12	1	\$51.12
03-42-007	REPLACE NEW COOLANT FILTER	BALB5134	COOLANT FILTER SPIN-ON	6.30	1	\$6.30
66-PM-PMA	PERFORM OIL CHANGE	BALP7235	OIL FILTER	13.31	1	\$13.31
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.26	1	\$8.26
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	2.80	1	\$2.80
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	1.57	20	\$31.40
					PARTS	274.57

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **35332**

Work Order Notes

(EKIMBREL) Customer said coolant has run down in only couple days. wants to check for coolant leak

Job Notes

Work Order Charge Detail

03-42-006 - REPLACE NEW THERMOSTATS

(LISAPATE) Installed a new thermostat

03-42-007 - REPLACE NEW COOLANT FILTER

(LISAPATE) Replaced coolant filter-Tightened hose clamp on lower radiator hose had slow leak

06-42 - INSPECT COOLING SYSTEM

(LISAPATE) Checked found coolant leaking from the radiator at the top around the neck

14-42-002 - INSTALL RADIATOR

(GARAGE) Job 14-42-002 was added on-the-fly by 11213180 on 01/15/2020 06:23:06.

(LISAPATE) Reinstalled radiator it was still leaking. Removed and sent back to Nabors again. Reinstalled and rechecked ok

16-42 - TRANSPORT COOLING SYSTEM

(LISAPATE) EK Picked up radiator from Nabors

24-42-002 - REPAIR RADIATOR

(LISAPATE) Nabor's repaired radiator twice. Pd by CC

25-42-002 - REMOVE RADIATOR

(LISAPATE) Removed radiator and sent to Nabor's to be repaired.

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(LISAPATE) Evac and recharged system due to had to remove condenser to remove the radiator.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(LISAPATE) PM by JW

Coolant -34'

Replaced air filter

Greased liftgate and all fittings

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

(LISAPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA
Qty : 1
Description : FUEL FILTER
Manufacturer :
Bin :

(LISAPATE) Replaced fuel filter

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35743

USING DEPT NO:	504302	OPENED DATE:	02/24/2020 08:55:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2020 08:36:06	METER 1 - M:	63283	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/27/2020 08:36:07	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-013	REPLACE NEW HOSES, COOLING SYS	DON	O	N	GARAGE	1.43	\$0.00	\$29.12	\$0.00	\$29.12
06-42-013	INSPECT HOSES, COOLING SYSTEM	DON	O	N	GARAGE	0.45	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.89	0.00	29.12	0.00	29.12
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	02/25/2020 09:30:00	02/25/2020 10:41:07	1.19	\$0.00
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	11310047	02/25/2020 09:00:03	02/25/2020 09:15:00	0.25	\$0.00
06-42-013	INSPECT HOSES, COOLING SYSTEM	11310047	02/24/2020 14:30:00	02/24/2020 14:49:37	0.33	\$0.00
06-42-013	INSPECT HOSES, COOLING SYSTEM	11310047	02/24/2020 14:07:26	02/24/2020 14:15:00	0.13	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-42-013	REPAIR HOSES, COOLING SYSTEM	36 CLAMP	CLAMP 1 13/16-2 3/4	0.40	1	\$0.40
24-42-013	REPAIR HOSES, COOLING SYSTEM	36 CLAMP	CLAMP 1 13/16-2 3/4	0.40	(1)	(\$0.40)
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	36 CLAMP	CLAMP 1 13/16-2 3/4	0.40	1	\$0.40
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	8.36	1	\$8.36
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	32 CLAMP	CLAMP 1 9/16-2 1/2	0.36	1	\$0.36
03-42-013	REPLACE NEW HOSES, COOLING SYSTEM	9408	MOLDED RADIATOR HOSE	20.00	1	\$20.00
					PARTS	29.12

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35743

Work Order Notes

(LISAPATE) Per driver hose is leaking fluid behind oil filter looked like red fluid in puddle under truck

Job Notes

03-42-013 - REPLACE NEW HOSES, COOLING SYSTEM

(LISAPATE) Replaced lower radiator hose and refilled cooling system. Pressure tested and inspected for leaks. Performed road test after repairs

06-27-044 - INSPECT TRANS. OIL COOLER LINE(S)

06-42-013 - INSPECT HOSES, COOLING SYSTEM

(LISAPATE) Found coolant leaking at lower radiator hose to thermostat housing

24-42-013 - REPAIR HOSES, COOLING SYSTEM

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 35917

USING DEPT NO:	504302	OPENED DATE:	03/06/2020 08:44:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/06/2020 15:07:28	METER 1 - M:	63429	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	03/12/2020 15:31:56	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-42-013	REPAIR HOSES, COOLING SYSTEM	DON	O	N	GARAGE	0.17	\$0.00	\$0.40	\$0.00	\$0.40
CB-42	COME BACK COOLING SYSTEM	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.17	0.00	0.40	0.00	0.40
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-42-013	REPAIR HOSES, COOLING SYSTEM	11213180	03/06/2020 11:44:16	03/06/2020 11:54:13	0.17	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-42-013	REPAIR HOSES, COOLING SYSTEM	36 CLAMP	CLAMP 1 13/16-2 3/4	0.40	1	\$0.40
					PARTS	0.40

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **35917**

Work Order Notes

(LISAPATE) Truck is leaking coolant again

Job Notes

24-42-013 - REPAIR HOSES, COOLING SYSTEM

(LISAPATE) Tightened existing clamp and added an additional clamp. Rechecked ok

CB-42 - COME BACK COOLING SYSTEM

(LISAPATE) Found coolant leaking form lower radiator hose.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 36322

USING DEPT NO:	504302	OPENED DATE:	05/06/2020 07:58:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/06/2020 15:17:58	METER 1 - M:	63794	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/07/2020 08:33:32	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.05	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-OLS	PERFORM OIL SAMPLES	DON	P	N	GARAGE	0.25	\$0.00	\$9.67	\$0.00	\$9.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.98	\$0.00	\$56.15	\$0.00	\$56.15
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.35	\$0.00	\$31.95	\$0.00	\$31.95

JOB COUNT: 4	WORK ORDER TOTAL:	2.63	0.00	97.77	0.00	97.77
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-OLS	PERFORM OIL SAMPLES	12052187	05/06/2020 15:16:38	05/06/2020 15:31:38	0.25	\$0.00
06-15	INSPECT STEERING	12052187	05/06/2020 14:00:35	05/06/2020 14:03:23	0.05	\$0.00
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	12052187	05/06/2020 11:17:26	05/06/2020 11:38:35	0.35	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/06/2020 09:59:17	05/06/2020 11:17:26	1.30	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	05/06/2020 09:49:23	05/06/2020 10:29:55	0.68	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	7312MP	OIL FILTER ELEMENT W CAP	13.25	1	\$13.25
66-PM-OLS	PERFORM OIL SAMPLES	OSB	OIL SAMPLE BOTTLE	9.67	1	\$9.67
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818MP	FUEL FILTER	18.70	1	\$18.70
66-PM-PMA	PERFORM OIL CHANGE	15W40GAL	OIL 15W40 CAM2 SUPER HD GAL	11.23	5	\$56.15
					PARTS	97.77

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 36322

Work Order Notes

(EKIMBREL) PM

Job Notes

06-15 - INSPECT STEERING

(EKIMBREL) JW/SH checked front end, all good.

66-PM-OLS - PERFORM OIL SAMPLES

(EKIMBREL) JW collected oil sample.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL)

Parts For Job Include:

Part 15W40 OIL GAL BOTTLE (DIESEL) Qty 5 Cost 12.050000

Part P7235 FILTER-OIL Qty 1 Cost 0.000000

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0.000000

(EKIMBREL) JW/AG. Coolant -34

JW found leak at top of radiator from coolant jug hose, tightened clamp and topped off coolant with non-inventory coolant. Greased and inspected lift gate.

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(RTUNAITI)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

Bin :

(EKIMBREL) JW replaced fuel filter.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 37009

USING DEPT NO:	504302	OPENED DATE:	07/02/2020 14:23:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2020 15:35:06	METER 1 - M:	64318	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2020 11:20:18	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	O	N	GARAGE	0.49	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.49	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11074414	07/02/2020 14:43:00	07/02/2020 15:12:09	0.49	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 37009

Work Order Notes

(LISAPATE) Repair rear roll up door rivets came off the hinges

Job Notes

24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP

(LISAPATE) Installed new bolts in bottom panel hinges. Also drilled out rivets on the side grip handle and installed new rivets

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 37432

USING DEPT NO:	504302	OPENED DATE:	08/25/2020 07:52:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/26/2020 11:38:07	METER 1 - M:	64958	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/26/2020 11:58:52	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-029	REPLACE NEW COOLANT HOSE ADAP	DON	O	N	GARAGE	0.39	\$0.00	\$0.00	\$0.00	\$0.00
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	0.12	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.68	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/26/2020 08:45:11	08/26/2020 08:55:06	0.17	\$0.00
35-42	DIAGNOSE COOLING SYSTEM	11170580	08/26/2020 07:28:26	08/26/2020 07:35:29	0.12	\$0.00
03-42-029	REPLACE NEW COOLANT HOSE ADAPTERS	11170580	08/26/2020 07:04:35	08/26/2020 07:28:07	0.39	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-42-029	REPLACE NEW COOLANT HOSE ADAPTERS	SLO491330	CONSTANT TORQUE HOSE CLAMP 3IN	8.95	(1)	(\$8.95)
03-42-029	REPLACE NEW COOLANT HOSE ADAPTERS	SLO491335	T-BOLT CLAMP 70-92 MM	8.95	(1)	(\$8.95)
03-42-029	REPLACE NEW COOLANT HOSE ADAPTERS	SLO491335	T-BOLT CLAMP 70-92 MM	8.95	1	\$8.95
03-42-029	REPLACE NEW COOLANT HOSE ADAPTERS	SLO491330	CONSTANT TORQUE HOSE CLAMP 3IN	8.95	1	\$8.95
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 37432

Work Order Notes

(LISAPATE) PM-Check for leaking coolant-level is low and found a puddle under the truck

Job Notes

03-42-029 - REPLACE NEW COOLANT HOSE ADAPTERS

(ABLACK) AB found lower radiator hose was leaking at the top clamp. Installed a heavier duty hose clamp on hose. Topped off coolant with already charged out coolant. Pressured up system and rechecked ok.

35-42 - DIAGNOSE COOLING SYSTEM

(ABLACK) AB found lower radiator hose was leaking around top clamp.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) unit has only went 100 miles since last pm service. updated sticker aqnd checked all fluids and tires. greased lift gate and suspension. found no issues at this time. JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 38339

USING DEPT NO:	504302	OPENED DATE:	11/10/2020 09:13:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/13/2020 09:37:27	METER 1 - M:	66113	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/13/2020 15:24:59	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	1.11	\$130.82	\$12.57	\$0.00	\$143.39

JOB COUNT: 1	WORK ORDER TOTAL:	1.11	130.82	12.57	0.00	143.39
--------------	-------------------	------	--------	-------	------	--------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	11213180	11/10/2020 09:51:24	11/10/2020 10:57:55	1.11	\$130.82
					LABOR	130.82

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
35-42	DIAGNOSE COOLING SYSTEM	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	12.57	1	\$12.57
					PARTS	12.57

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 38339

Work Order Notes

(LISAPATE) Check coolant level going to Montgomery tomorrow

(LISAPATE) Dept declined repair at this time. Will bring back if it starts leaking again

Job Notes

35-42 - DIAGNOSE COOLING SYSTEM

(MSIDES) Added about 1 quart of coolant to system and checked for leaks. Found radiator to have a very small leak on passenger side tank, recommend replace radiator. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 38572

USING DEPT NO:	504302	OPENED DATE:	12/07/2020 12:34:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2020 14:25:50	METER 1 - M:	66585	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/10/2020 08:48:04	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.09	\$10.49	\$28.84	\$0.00	\$39.33
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.48	\$174.51	\$69.35	\$0.00	\$243.86
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	O	N	GARAGE	0.18	\$21.63	\$28.05	\$0.00	\$49.68

JOB COUNT: 3	WORK ORDER TOTAL:	1.75	206.63	126.24	0.00	332.87
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	12052187	12/09/2020 09:35:00	12/09/2020 09:40:20	0.09	\$10.49
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/09/2020 07:09:29	12/09/2020 07:53:53	0.74	\$87.32
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/08/2020 14:11:40	12/08/2020 14:54:32	0.71	\$84.30
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	12052187	12/08/2020 14:00:29	12/08/2020 14:11:29	0.18	\$21.63
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/08/2020 13:59:01	12/08/2020 14:00:29	0.02	\$2.88
					LABOR	206.62

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818MP	FUEL FILTER	28.05	1	\$28.05
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	4.22	1	\$4.22
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	18.03	1	\$18.03
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	6050	LAMP OVAL LED S/T/TL	25.77	1	\$25.77
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	GRO92420	TAILLIGHT GROMMET	3.07	1	\$3.07
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	2.36	20	\$47.10
					PARTS	126.24

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 38572

Work Order Notes

(EKIMBREL) PM

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(JWRIGHT) Replaced or brake light with new light and grommet. JAW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Greased all fittings. Found the lr brake light needs replaced. Washed truck. Checked front end. Found no other issues. Coolant-34°. JAW/SH

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(JWRIGHT) Replaced fuel filter. Primed system and ran for 5minutes. Found no issues JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 39384

USING DEPT NO:	504302	OPENED DATE:	03/11/2021 14:43:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/12/2021 11:20:37	METER 1 - M:	67594	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/15/2021 08:00:36	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.09	\$129.01	\$4.20	\$0.00	\$133.21

JOB COUNT: 1	WORK ORDER TOTAL:	1.09	129.01	4.20	0.00	133.21
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/12/2021 09:30:00	03/12/2021 10:35:36	1.09	\$129.01
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/12/2021 09:27:49	03/12/2021 09:27:49	0.00	\$0.00
					LABOR	129.01

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	4.20	1	\$4.20
					PARTS	4.20

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 39384

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1009 miles since last service. Updated pm sticker. Checked all fluids and tires. Coolant -34°. JAW
MILEAGE-67594

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 40249

USING DEPT NO:	504302	OPENED DATE:	06/25/2021 08:15:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/09/2021 10:55:04	METER 1 - M:	69202	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/09/2021 13:39:34	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-002	REPLACE NEW RADIATOR	DON	O	N	GARAGE	4.47	\$527.69	\$1,191.75	\$0.00	\$1,719.44
35-42	DIAGNOSE COOLING SYSTEM	DON	O	N	GARAGE	1.40	\$164.77	\$0.00	\$0.00	\$164.77
66-01-058	PERFORM EVAC AND RECHARGE FREON	DON	O	N	GARAGE	1.00	\$118.00	\$23.63	\$0.00	\$141.63
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.09	\$128.19	\$76.52	\$0.00	\$204.71
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	O	N	GARAGE	0.34	\$39.73	\$24.66	\$0.00	\$64.39

JOB COUNT: 5	WORK ORDER TOTAL:	8.29	978.38	1,316.56	0.00	2,294.94
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-42-002	REPLACE NEW RADIATOR	11213180	07/02/2021 09:30:00	07/02/2021 10:56:19	1.44	\$169.76
03-42-002	REPLACE NEW RADIATOR	11213180	07/02/2021 08:44:14	07/02/2021 09:15:00	0.51	\$60.51
03-42-002	REPLACE NEW RADIATOR	11213180	07/01/2021 15:18:56	07/01/2021 15:48:27	0.49	\$58.05
03-42-002	REPLACE NEW RADIATOR	11213180	07/01/2021 13:00:00	07/01/2021 13:56:33	0.94	\$111.22
03-42-002	REPLACE NEW RADIATOR	11213180	07/01/2021 11:59:59	07/01/2021 11:59:59	0.00	\$0.00
03-42-002	REPLACE NEW RADIATOR	11213180	06/29/2021 09:30:00	06/29/2021 09:44:26	0.24	\$28.39
03-42-002	REPLACE NEW RADIATOR	11213180	06/29/2021 08:24:16	06/29/2021 09:15:00	0.85	\$99.78
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11901357	06/28/2021 13:42:25	06/28/2021 14:02:37	0.34	\$39.73
66-01-058	PERFORM EVAC AND RECHARGE FREON	11213180	07/09/2021 07:00:00	07/09/2021 08:00:00	1.00	\$118.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/28/2021 13:15:03	06/28/2021 13:18:07	0.05	\$6.03
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/28/2021 09:38:15	06/28/2021 09:38:32	0.00	\$0.56
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/28/2021 07:01:44	06/28/2021 08:03:34	1.03	\$121.61
35-42	DIAGNOSE COOLING SYSTEM	11213180	06/25/2021 09:16:19	06/25/2021 10:40:06	1.40	\$164.77
					LABOR	978.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-42-002	REPLACE NEW RADIATOR	VV324	TRANS FLUID QT	6.38	12	\$76.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-42-002	REPLACE NEW RADIATOR	VV324	TRANS FLUID QT	6.38	(6)	(\$38.25)
03-42-002	REPLACE NEW RADIATOR	VV324	TRANS FLUID QT	6.38	6	\$38.25
03-42-002	REPLACE NEW RADIATOR	36 CLAMP	CLAMP 1 13/16-2 3/4	0.60	4	\$2.40
03-42-002	REPLACE NEW RADIATOR	ANTIFREEZE DIESEL	HD DIESEL ANTIFREEZE 50/50	16.34	6	\$98.01
03-42-002	REPLACE NEW RADIATOR	4C4Z8005YA	RADIATOR	1014.84	1	\$1,014.84
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	24.66	1	\$24.66
66-01-058	PERFORM EVAC AND RECHARGE FREON	R134AOZ	R134A FREON-OUNCE	0.29	7	\$2.00
66-01-058	PERFORM EVAC AND RECHARGE FREON	ESTER OIL	A/C ESTER OIL OUNCE	1.01	1	\$1.01
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.77	1	\$4.77
66-01-058	PERFORM EVAC AND RECHARGE FREON	RECYCLED FREON OZ	RECLAIMED FREON OZ	0.14	29	\$3.92
66-01-058	PERFORM EVAC AND RECHARGE FREON	FOR26820	A/C SYSTEM SEAL KIT	16.70	1	\$16.70
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	18.03	1	\$18.03
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	2.48	20	\$49.50
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	4.22	1	\$4.22
					PARTS	1316.56

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 40249

Work Order Notes

(LISAPATE) PM-Per driver looks like radiator hose is leaking

Job Notes

03-42-002 - REPLACE NEW RADIATOR

(MSIDES) Replaced radiator and refilled with coolant.MS

35-42 - DIAGNOSE COOLING SYSTEM

(MSIDES) Found radiator to have a small leak from a fitting made onto the tank on the passenger side. Leak is from same spot as checked on 11/10/2020 work order #38339, repairs were declined at that time. If approved vehicle will need radiator replaced. MS

66-01-058 - PERFORM EVAC AND RECHARGE FREON

(MSIDES) Performed evac and recharge to replace radiator. Recharged system to spec of 36oz and added 1.0oz of oil with dye. MS

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 69202 Completed PM top and bottom side, completed checklist. AMG/AMG

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(AGUERRA) Replaced fuel filter and checked for leaks, all good. AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 41560

USING DEPT NO:	504302	OPENED DATE:	11/09/2021 09:40:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/06/2021 09:57:32	METER 1 - M:	70841	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/06/2021 12:59:48	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-71-038	INSPECT REAR DOOR ASSY	DON	O	N	GARAGE	0.21	\$25.11	\$0.00	\$0.00	\$25.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.21	25.11	0.00	2.00	27.11
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-71-038	INSPECT REAR DOOR ASSY	11213180	11/09/2021 13:39:09	11/09/2021 13:51:55	0.21	\$25.11
					LABOR	25.11

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.58	(2)	(\$15.15)
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.58	2	\$15.15
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 41560

Work Order Notes

(LISAPATE) PM-replace wipers-adjust brakes- back door is off track hard to open and close -repair passenger seat
(IFALLS) DETPT TOOK VEHICLE AFTER DOOR REPAIR. PM NOT PERFORMED.

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

06-71-038 - INSPECT REAR DOOR ASSY

(MSIDES) Found rear door to be missing several pieces of hardware and also to have bolts pulled through wood paneling will need overhead door to come out and inspect. MS
(LISAPATE) Overhead door is ordering parts will get truck back in when parts arrive

66-PM-PMA - PERFORM OIL CHANGE

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 42015

USING DEPT NO:	504302	OPENED DATE:	01/07/2022 15:22:26	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	03/11/2022 15:30:24	METER 1 - M:	71808	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/31/2022 00:00:00	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650							
			UNIT SERIAL NO:	3FRNF65Y56V356324					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-42-023	REPLACE NEW COOLANT TEMP SENS	DON	O	N	GARAGE	0.79	\$93.58	\$134.69	\$0.00	\$228.27
03-42-024	REPLACE NEW 90" FITTINGS, COOLING	DON	O	N	GARAGE	1.99	\$234.69	\$71.88	\$80.49	\$387.06
03-44-049	REPLACE NEW ICP SENSOR	DON	O	N	GARAGE	0.59	\$69.26	\$665.22	\$23.00	\$757.48
03-44-057	REPLACE NEW GLOW PLUGS	DON	O	N	GARAGE	1.59	\$188.18	\$212.36	\$0.00	\$400.54
03-44-059	REPLACE NEW INJECTOR DRIVER MOI	DON	O	N	GARAGE	2.74	\$323.84	\$13.56	\$228.28	\$565.68
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$7.05	\$20.37	\$0.00	\$27.42
03-79-009	REPLACE NEW SEAT BELT(S)	DON	O	N	GARAGE	0.38	\$44.64	\$239.52	\$0.00	\$284.16
25-02-027	REMOVE SEAT FRAMES & SPRINGS	DON	O	N	GARAGE	1.22	\$143.70	\$0.00	\$0.00	\$143.70
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.61	\$190.14	\$144.55	\$0.00	\$334.69
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.47	\$27.95	\$0.00	\$33.42
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	0.67	\$78.50	\$0.00	\$0.00	\$78.50

JOB COUNT: 12	WORK ORDER TOTAL:	11.69	1,379.05	1,530.10	331.77	3,240.92
---------------	-------------------	-------	----------	----------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	11074386	100623790		\$80.49
03-44-049	REPLACE NEW ICP SENSOR	11074386	100625482		\$23.00
03-44-059	REPLACE NEW INJECTOR DRIVER MODULE	11074390	03CW308571		\$228.28
CH-SP	CHARGE Shop Supplies	503163	1		(\$2.00)
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					331.77

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-44-057	REPLACE NEW GLOW PLUGS	11213180	01/14/2022 10:06:09	01/14/2022 10:54:56	0.81	\$95.94
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/25/2022 14:42:57	01/25/2022 14:48:10	0.09	\$10.26

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-049	REPLACE NEW ICP SENSOR	11310047	01/25/2022 10:07:55	01/25/2022 10:43:08	0.59	\$69.26
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	11310047	01/24/2022 10:32:34	01/24/2022 11:58:04	1.43	\$168.15
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	11310047	01/21/2022 10:22:06	01/21/2022 10:55:56	0.56	\$66.54
03-44-057	REPLACE NEW GLOW PLUGS	11213180	01/12/2022 15:02:16	01/12/2022 15:49:10	0.78	\$92.24
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	01/11/2022 07:49:07	01/11/2022 07:51:54	0.05	\$5.47
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/11/2022 07:45:17	01/11/2022 07:48:52	0.06	\$7.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/11/2022 07:42:44	01/11/2022 07:45:00	0.04	\$4.46
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/10/2022 14:30:00	01/10/2022 15:36:57	1.12	\$131.67
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/10/2022 13:47:32	01/10/2022 14:15:00	0.46	\$54.02
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	01/25/2022 15:13:23	01/25/2022 15:48:05	0.58	\$68.24
03-44-059	REPLACE NEW INJECTOR DRIVER MODULE	11310047	02/10/2022 13:01:15	02/10/2022 14:15:00	1.23	\$145.04
03-79-009	REPLACE NEW SEAT BELT(S)	11310047	02/14/2022 14:48:01	02/14/2022 15:10:43	0.38	\$44.64
03-44-059	REPLACE NEW INJECTOR DRIVER MODULE	11310047	02/14/2022 13:06:28	02/14/2022 14:11:04	1.08	\$127.05
03-44-059	REPLACE NEW INJECTOR DRIVER MODULE	11310047	02/10/2022 11:27:27	02/10/2022 11:53:46	0.44	\$51.76
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	11310047	02/10/2022 10:58:35	02/10/2022 11:27:27	0.48	\$56.77
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	11310047	02/10/2022 09:31:02	02/10/2022 09:49:45	0.31	\$36.81
03-79-009	REPLACE NEW SEAT BELT(S)	11074414	02/10/2022 09:18:50	02/10/2022 09:18:50	0.00	\$0.00
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	02/10/2022 08:59:03	02/10/2022 09:15:00	0.27	\$31.37
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	02/03/2022 09:30:37	02/03/2022 10:01:04	0.51	\$59.89
25-02-027	REMOVE SEAT FRAMES & SPRINGS	11074414	02/01/2022 13:27:48	02/01/2022 13:54:28	0.44	\$52.44

LABOR 1379.07

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-059	REPLACE NEW INJECTOR DRIVER MODULE	DOR800041	FUEL LINE RETAINER	13.56	1	\$13.56
03-79-009	REPLACE NEW SEAT BELT(S)	2C4Z2561203BAA	SEAT BELT	239.52	1	\$239.52
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	DOR904488	COOLANT SENSOR	35.28	1	\$35.28
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	BALB5134	COOLANT FILTER SPIN-ON	9.05	1	\$9.05
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	4C4Z10884A	COOLANT SENSOR	90.36	1	\$90.36
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	BALB5134	COOLANT FILTER SPIN-ON	9.05	(1)	(\$9.05)
03-44-049	REPLACE NEW ICP SENSOR	ICP101K	ICP SENSOR	121.41	1	\$121.41
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	BALL VALVE	HEATER CONTROL VALVE	31.49	2	\$62.97
03-44-057	REPLACE NEW GLOW PLUGS	4C3Z12A342	GLOW PLUGS	18.20	8	\$145.56

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-44-057	REPLACE NEW GLOW PLUGS	4C4Z12B533AA	GLOW PLUG CONTROL SENSOR	66.80	1	\$66.80
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	2	\$20.37
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	2.51	20	\$50.10
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	20.09	1	\$20.09
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	27.95	1	\$27.95
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	82180	ULTRA BLACK RTV	7.47	1	\$7.47
03-42-024	REPLACE NEW 90" FITTINGS, COOLING SYSTEM	7701755	TEFLON TAPE	1.44	1	\$1.44
66-PM-PMA	PERFORM OIL CHANGE	BALCS5366	AIR FILTER	74.36	1	\$74.36
03-42-023	REPLACE NEW COOLANT TEMP SENSOR	BALB5134	COOLANT FILTER SPIN-ON	9.05	1	\$9.05
03-44-049	REPLACE NEW ICP SENSOR	ONE782004F	ICP SENSOR	543.81	1	\$543.81
03-44-049	REPLACE NEW ICP SENSOR	ONE782004F	ICP SENSOR	543.81	(1)	(\$543.81)
03-44-049	REPLACE NEW ICP SENSOR	ONE782004F	ICP SENSOR	543.81	1	\$543.81
					PARTS	1530.10

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **42015**

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

01-13 - ADJUST BRAKES

03-42-023 - REPLACE NEW COOLANT TEMP SENSOR

(EHOWELL) Replaced engine coolant temperature sensor and pigtail connector. EH

03-42-024 - REPLACE NEW 90" FITTINGS, COOLING SYSTEM

(EHOWELL) Installed 2 new shut off valves for coolant filter. Coolant filter was replaced as well. EH

03-44-049 - REPLACE NEW ICP SENSOR

(EHOWELL) Replaced Injection Control Pressure Sensor. Also, Replaced the pigtail connector for the sensor. Verified sensor operation my viewing the pressure data with the J-Pro scan tool. EH

03-44-057 - REPLACE NEW GLOW PLUGS

(MSIDES) Replaced all 8 glow plugs and glow plug relay. MS

(MSIDES) Had to remove alternator and several other things to replace bill 4.5hrs. MS

03-44-059 - REPLACE NEW INJECTOR DRIVER MODULE

(EHOWELL) Installed the new injector driver module after it was programmed. Performed a road test. The vehicle runs good and the check engine light is no longer illuminated. EH

(EKIMBREL) SOUTHLAND PROGRAMMED IDM

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

03-79-009 - REPLACE NEW SEAT BELT(S)

(SHARBIN) The plug on the seat belt buckle was damaged at the upholstery shop and could not be repaired. Installed a new seat belt buckle. SH

25-02-027 - REMOVE SEAT FRAMES & SPRINGS

(SHARBIN) Removed both seats and carried to the upholstery shop. Reinstalled seats when completed. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/JW Performed PM. Checked steering and king pins greased greased lift gate. SH

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(SHARBIN) Replaced fuel filter. SH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

(EHOWELL) PID 164 FMI 4 Signal is out of range or low for Injection Control Pressure (ICP)

PID 110 ECT Data Erratic

SID 221 Relay voltage is low for Injector Driver Module

SID 254 IDM Fault

(MSIDES) Scanned vehicle out and found several codes stored to the history, PID 110, SID 221, SID 254, SID 1, SID 2, SID 22 and several others. Most codes delt with low voltage to a couple related circuits. After inspection found glow plug relay to be inoperative and show signs of high resistance (distorded/melted plastic). Decided to replace glow plug relay and all glow plugs, vehicle could possibly need further diag after repair. MS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 4215

USING DEPT NO:	504302	OPENED DATE:	08/31/2009 10:19:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2009 08:58:37	METER 1 - M:	14880	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/03/2009 08:58:37	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
01-71	ADJUST BODY	DON	O	N	GARAGE	6.64	\$381.64	\$0.00	\$0.00	\$381.64
03-02-051	REPLACE NEW SEAT COVER	DON	O	N	GARAGE	0.00	\$0.00	\$51.20	\$0.00	\$51.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.74	\$100.03	\$306.55	\$0.00	\$406.58

JOB COUNT: 3	WORK ORDER TOTAL:	8.38	481.67	357.75	0.00	839.42
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
01-71	ADJUST BODY	11268671	09/02/2009 06:00:00	09/02/2009 08:00:00	2.00	\$115.00
01-71	ADJUST BODY	11274660	09/01/2009 09:20:51	09/01/2009 13:59:05	4.64	\$266.64
66-PM-PMA	PERFORM OIL CHANGE	11274660	08/31/2009 14:15:19	08/31/2009 15:59:42	1.74	\$100.03
					LABOR	481.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	FL2016	OIL FILTER KIT	31.32	1	\$31.32
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	16.17	5	\$80.85
66-PM-PMA	PERFORM OIL CHANGE	FA1889	AIR FILTER	172.56	1	\$172.56
03-02-051	REPLACE NEW SEAT COVER	5040617	BUCKET SEAT COVERS	51.20	1	\$51.20
66-PM-PMA	PERFORM OIL CHANGE	F81Z9N184AA	FUEL FILTER	48.95	1	\$48.95
66-PM-PMA	PERFORM OIL CHANGE	FA1889	AIR FILTER	172.56	(1)	(\$172.56)
66-PM-PMA	PERFORM OIL CHANGE	FA1753	AIR FILTER	145.43	1	\$145.43
					PARTS	357.75

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 4215

Work Order Notes

(LPATE) PM-DRIVER REQUESTED SET OF SEAT COVERS-DRIVER BACKED INTO SOMETHING MOVED BED OUT OF PLACE NEED TO SEE IF WE CAN ADJUST

Job Notes

01-71 - ADJUST BODY

(LPATE) TONY AND ISAAC LOOSENEED TRUCK BODY MOUNTS READJUSTED BED THEN TIGHTENED DOWN THE MOUNTS

03-02-051 - REPLACE NEW SEAT COVER

(LPATE) GAVE DRIVER SET OF SEAT COVERS FOR FRONT OF TRUCK HE WILL INSTALL HIMSELF

66-PM-PMA - PERFORM OIL CHANGE

(LPATE) The following parts are included with the standard job:

Part No : 15W40
Qty : 5
Description : OIL BOTTLE (DIESEL)
Manufacturer :

Part No : P7235
Qty : 1
Description : FILTER-OIL
Manufacturer :

Part No : TUBE GREASE
Qty : 1
Description : TUBE GREASE
Manufacturer :

(LPATE) PM BY TF

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 42762

USING DEPT NO:	504302	OPENED DATE:	03/30/2022 09:12:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2022 08:44:54	METER 1 - M:	72303	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/10/2022 14:52:01	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
20-00	TOWING COMPLETE VEHICLE	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$575.00	\$575.00
24-05-034	REPAIR ECM/ENGINE CONTROL MODU	DON	B	N	GARAGE	0.00	\$0.00	\$0.00	\$1,047.88	\$1,047.88
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.71	\$83.49	\$0.00	\$0.00	\$83.49
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.48	\$56.38	\$0.00	\$0.00	\$56.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.19	139.87	0.00	1,624.88	1,764.75
--------------	-------------------	------	--------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
24-05-034	REPAIR ECM/ENGINE CONTROL MODULE	11074390	03CW309000		\$1,047.88
20-00	TOWING COMPLETE VEHICLE	11076249	224135		\$287.50
20-00	TOWING COMPLETE VEHICLE	11076249	223997		\$287.50
COMML					1624.88

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	12052187	04/11/2022 09:45:58	04/11/2022 09:46:26	0.01	\$0.92
03-32-002	REPLACE NEW BATTERY	12052187	04/11/2022 09:45:58	04/11/2022 09:46:26	(0.01)	(\$0.92)
66-PM-PMA	PERFORM OIL CHANGE	12052187	04/11/2022 09:17:08	04/11/2022 09:45:48	0.48	\$56.38
66-79-002	PERFORM SERVICE CALL	11213180	03/30/2022 10:05:23	03/30/2022 10:47:50	0.71	\$83.49
LABOR						139.87

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 42762

Work Order Notes

(LISAPATE) Dead battery at asb

Job Notes

03-32-002 - REPLACE NEW BATTERY

(JWRIGHT) Replaced batteries still will not start. Having unit towed

20-00 - TOWING COMPLETE VEHICLE

(LISAPATE) Bambarger towed from Paul Bryant Dr to the shop. PD by CC
then towed from the shop to Southland. PD by CC

24-05-034 - REPAIR ECM/ENGINE CONTROL MODULE

(LISAPATE) Southland came to the shop found truck and inspected. Found truck wont even turn over, unable to get laptop to hook up going to check starter relay in the morning. Checked starter relay able to spin motor, checked all fuses and power supplies no signal to starter found. Bad wiring in battery box rigged wiring motor and started. Sent P&A for parts to fix wiring. Remove top step and disconnected old battery jumper harness and installed new but spliced heat shrink. It fires right up but was running on 4 cyl found broke ECM plug unbolted ECM so he could access zip ties around ECM and through the plug. tied up so it will stay connected and runs like a top now. Pd by CC

66-79-002 - PERFORM SERVICE CALL

(MSIDES) Performed service call vehicle still not starting and glow plug light isnt coming on will likely need to be towed to shop. MS

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 495 miles since last pm. Updated sticker. Checked fluids and tires coolant -34°. JAW
MILEAGE-72303

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 42946

USING DEPT NO:	504302	OPENED DATE:	04/18/2022 08:45:05	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	07/11/2022 08:22:20	METER 1 - M:	72894	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 09:44:36	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650							
			UNIT SERIAL NO:	3FRNF65Y56V356324					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-01-004	REPLACE NEW BLOWER MOTOR	DON	O	N	GARAGE	0.20	\$23.90	\$66.09	\$0.00	\$89.99
03-01-014	REPLACE NEW RESISTOR	DON	O	N	GARAGE	0.25	\$29.37	\$29.87	\$0.00	\$59.24
03-02-090	REPLACE NEW CUP HOLDER ASSY/BR	DON	O	N	GARAGE	0.39	\$46.28	\$101.19	\$0.00	\$147.47
03-02-103	REPLACE NEW BEZEL	DON	O	N	GARAGE	0.15	\$17.70	\$90.30	\$0.00	\$108.00
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.74	\$10.23	\$0.00	\$13.97
03-52-024	REPLACE NEW BACK UP CAMERA	DON	O	N	GARAGE	2.50	\$295.00	\$960.00	\$23.62	\$1,278.62
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$2,786.45	\$2,786.45
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$118.16	\$49.80	\$0.00	\$167.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 9	WORK ORDER TOTAL:	4.53	534.15	1,307.48	2,812.07	4,653.70
--------------	-------------------	------	--------	----------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-72-004	REPAIR REAR DOOR ASSEMBLY - ROLL-UP	11076414	TCS51311		\$2,786.45
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
03-52-024	REPLACE NEW BACK UP CAMERA	5761126	1988677		\$23.62
03-52-024	REPLACE NEW BACK UP CAMERA	5761126	1988677		(\$23.62)
03-52-024	REPLACE NEW BACK UP CAMERA	5761126	INV2108335		\$23.62
COMML					2812.07

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-52-024	REPLACE NEW BACK UP CAMERA	11213180	07/01/2022 07:00:00	07/01/2022 09:30:00	2.50	\$295.00
03-51-038	REPLACE NEW WIPER BLADES	12052187	06/30/2022 09:45:36	06/30/2022 09:47:30	0.03	\$3.74
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/30/2022 09:30:00	06/30/2022 09:45:25	0.26	\$30.32
66-PM-PMA	PERFORM OIL CHANGE	12052187	06/30/2022 08:30:20	06/30/2022 09:15:00	0.74	\$87.84
24-71-003	REPAIR SIDE WALL ASSEMBLY	12052187	04/21/2022 14:30:00	04/21/2022 14:34:25	0.07	\$8.69
24-71-003	REPAIR SIDE WALL ASSEMBLY	12052187	04/21/2022 13:49:31	04/21/2022 14:15:00	0.42	\$50.12

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-103	REPLACE NEW BEZEL	11074414	06/10/2022 14:14:59	06/10/2022 14:14:59	0.00	\$0.00
03-02-103	REPLACE NEW BEZEL	11074414	06/10/2022 14:14:59	06/10/2022 14:14:59	0.00	\$0.00
03-02-103	REPLACE NEW BEZEL	11074414	06/10/2022 14:14:59	06/10/2022 14:23:59	0.15	\$17.70
03-02-090	REPLACE NEW CUP HOLDER ASSY/BACKET	11074414	06/10/2022 13:51:11	06/10/2022 14:14:43	0.39	\$46.28
24-71-003	REPAIR SIDE WALL ASSEMBLY	12052187	04/21/2022 14:30:00	04/21/2022 14:34:25	(0.07)	(\$8.69)
24-71-003	REPAIR SIDE WALL ASSEMBLY	12052187	04/21/2022 13:49:31	04/21/2022 14:15:00	(0.42)	(\$50.12)
03-01-004	REPLACE NEW BLOWER MOTOR	11310047	06/17/2022 13:17:49	06/17/2022 13:29:58	0.20	\$23.90
03-01-014	REPLACE NEW RESISTOR	11310047	06/17/2022 13:02:53	06/17/2022 13:17:49	0.25	\$29.37
					LABOR	534.15

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-920	SIDE CAMERA	322.50	(1)	(\$322.50)
03-52-024	REPLACE NEW BACK UP CAMERA	IA-RV-505A	7" LCD CAMERA	637.50	(1)	(\$637.50)
03-52-024	REPLACE NEW BACK UP CAMERA	IA-RV-505A	7" LCD CAMERA	637.50	1	\$637.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-RV-505A	7" LCD CAMERA	637.50	1	\$637.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-920	SIDE CAMERA	322.50	1	\$322.50
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	5.12	2	\$10.23
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	2.49	20	\$49.80
03-01-014	REPLACE NEW RESISTOR	FOR 20348	BLOWER MOTOR RESISTOR	29.87	1	\$29.87
03-01-004	REPLACE NEW BLOWER MOTOR	FOR76900	BLOWER MOTOR	66.09	1	\$66.09
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-920	SIDE CAMERA	322.50	1	\$322.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-RV-505A	7" LCD CAMERA	637.50	(1)	(\$637.50)
03-52-024	REPLACE NEW BACK UP CAMERA	IA-RV-505A	7" LCD CAMERA	637.50	1	\$637.50
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-920	SIDE CAMERA	322.50	(1)	(\$322.50)
03-52-024	REPLACE NEW BACK UP CAMERA	IA-DVR-920	SIDE CAMERA	322.50	1	\$322.50
03-02-103	REPLACE NEW BEZEL	F81Z14527AAC	PASSENGER DOOR BEZEL	90.30	1	\$90.30
03-02-090	REPLACE NEW CUP HOLDER ASSY/BACKET	4C4Z2513560CA	CUP HOLDER	101.19	1	\$101.19
					PARTS	1307.48

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 42946

Work Order Notes

(LISAPATE) Rear door cables about to break, 2 panels need to be replaced, box has a hole in the sidewall, back up camera has a short

Job Notes

03-01-004 - REPLACE NEW BLOWER MOTOR

(EHOWELL) Replaced blower motor. EH

03-01-014 - REPLACE NEW RESISTOR

(EHOWELL) Replaced blower motor resistor. The ac is cooling, and all fan speeds are working. EH

03-02-090 - REPLACE NEW CUP HOLDER ASSY/BRACKET

(HHARBIN) Installed a new cup holder per customer request. SH

03-02-103 - REPLACE NEW BEZEL

(HHARBIN) Installed a new bezel for the door lock and window switch on the passenger door per customer request. SH

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wipers

03-52-024 - REPLACE NEW BACK UP CAMERA

(EKIMBREL) Replaced back up camera and monitor . MS

24-52-024 - REPAIR BACK UP CAMERA

(LISAPATE) Replaced back up camera and monitor . MS

24-71-003 - REPAIR SIDE WALL ASSEMBLY

(JWRIGHT) Repaired hole in left wall with an aluminum plate. Sealed it with silicone and riveted in place. Painted patch white.
1/2 hr labor

24-72-004 - REPAIR REAR DOOR ASSEMBLY - ROLL-UP

(LISAPATE) Overhead door to replace rollup door. Will contact us when door comes in.

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-72894

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 44006

USING DEPT NO:	504302	OPENED DATE:	07/18/2022 14:13:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/23/2022 15:16:24	METER 1 - M:	73298	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/27/2022 07:11:02	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-43-004	REPLACE NEW TURBOCHARGER	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$8,093.87	\$8,093.87
03-44-046	REPLACE NEW FUEL PRESSURE REGU	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	1.31	\$154.15	\$0.00	\$0.00	\$154.15
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	O	N	GARAGE	0.23	\$27.24	\$27.95	\$0.00	\$55.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
SO-05	SCAN OUT ELECTRONIC ENGINE EEC	DON	O	N	GARAGE	4.11	\$484.59	\$0.00	\$0.00	\$484.59

JOB COUNT: 6	WORK ORDER TOTAL:	5.64	665.98	27.95	8,098.87	8,792.80
--------------	-------------------	------	--------	-------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-44-046	REPLACE NEW FUEL PRESSURE REGULATOR	11074390	03CW309928		\$691.50
03-44-046	REPLACE NEW FUEL PRESSURE REGULATOR	11074390	03CW309928		(\$691.50)
03-43-004	REPLACE NEW TURBOCHARGER	11074390	03CW309928		\$6,317.12
03-43-004	REPLACE NEW TURBOCHARGER	11074390	03CW309928		\$5,625.63
03-43-004	REPLACE NEW TURBOCHARGER	11074390	03CW309928		(\$5,625.63)
03-43-004	REPLACE NEW TURBOCHARGER	11074390	03CW310276		\$1,776.75
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					8098.87

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-00	TRANSPORT COMPLETE VEHICLE	11915538	08/16/2022 09:30:34	08/16/2022 10:48:57	1.31	\$154.15
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11310047	07/21/2022 15:27:44	07/21/2022 15:41:35	0.23	\$27.24
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	07/19/2022 13:02:18	07/19/2022 15:56:03	2.90	\$341.71
SO-05	SCAN OUT ELECTRONIC ENGINE EEC SYSTEM	11310047	07/18/2022 14:44:06	07/18/2022 15:56:45	1.21	\$142.88
LABOR						665.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	27.95	1	\$27.95

Work Order Charge Detail

PARTS	27.95
-------	-------

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 44006

Work Order Notes

(LISAPATE) Scan out-Per Gerald feels like turbo going out- truck was spitting and sputtering and would only go 15mph driving here.

Job Notes

03-43-004 - REPLACE NEW TURBOCHARGER

(LISAPATE) Per invoice Southland replaced turbo charger. unit was towed back to Southland because clips on ECM were broken. Zip tied back in place for now. PD by CC
Invoices attached

03-44-046 - REPLACE NEW FUEL PRESSURE REGULATOR

(LISAPATE) Per invoice Southland replaced fuel pressure regulator.

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) Truck taken to Southland by RC

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(EHOWELL) Replaced the fuel filter on the engine. Cut the old fuel filter open and examined for debris but found none. EH

CH-SP - CHARGE Shop Supplies

SO-05 - SCAN OUT ELECTRONIC ENGINE EEC SYSTEM

(IFALLS) Performed road test. Used J Pro scan tool in attempt to diagnose the vehicle, but the scan tool offered limited capabilities. Observed fuel pressure reading. The engine was backfiring through the turbo and the vehicle did not have hardly any power. Removed air duct and exhaust pipe from both sides of the turbo and examined turbo vanes. The vanes looked good. Examined for leaks around the charge air cooler. EH 1 HRS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 45293

USING DEPT NO:	504302	OPENED DATE:	11/16/2022 14:43:44	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	12/21/2022 10:56:07	METER 1 - M:	74572	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/04/2023 15:35:51	IN-SERVICE DATE:	02/07/2006						
TECH SPEC NO:	06TKFORDF650	2006 Ford F650			UNIT SERIAL NO:	3FRNF65Y56V356324					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-52-024	INSPECT BACK UP CAMERA	DON	O	N	GARAGE	0.78	\$92.30	\$0.00	\$0.00	\$92.30
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.09	\$10.75	\$0.00	\$0.00	\$10.75
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$17.01	\$97.49	\$0.00	\$114.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.02	120.06	97.49	5.00	222.55
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	11/22/2022 14:30:22	11/22/2022 14:35:50	0.09	\$10.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/22/2022 14:06:21	11/22/2022 14:15:00	0.14	\$17.01
06-52-024	INSPECT BACK UP CAMERA	11074414	11/16/2022 14:53:38	11/16/2022 15:40:34	0.78	\$92.30
LABOR						120.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	3.87	20	\$77.40
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	20.09	1	\$20.09
PARTS						97.49

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 45293

Work Order Notes

(LISAPATE) Back up camera not working at times
(CWIGLEY) PM

Job Notes

06-52-024 - INSPECT BACK UP CAMERA

(SHARBIN) Checked all connections and power possible that the monitor has gone bad. SH
(EKIMBREL) Ethan ordered new monitor.

07-55-039 - LUBRICATE LIFTGATE ASSY

(SHARBIN) Greased lift gate. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH AMG/SH Performed PM. Checked front end found no issues at this time. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 46101

USING DEPT NO:	504302	OPENED DATE:	02/09/2023 08:04:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/27/2023 11:53:18	METER 1 - M:	75516	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/27/2023 13:50:05	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	O	N	GARAGE	3.25	\$383.76	\$920.53	\$0.00	\$1,304.29
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.10	\$11.24	\$21.80	\$0.00	\$33.04
03-52-008	REPLACE NEW MONITOR	DON	O	N	GARAGE	0.10	\$11.80	\$868.50	\$21.06	\$901.36
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.12	\$14.29	\$0.00	\$0.00	\$14.29
14-17	INSTALL TIRES, TUBES, LINERS & VALV	DON	O	N	GARAGE	0.40	\$47.20	\$0.00	\$0.00	\$47.20
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$938.49	\$938.49
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	1.32	\$155.60	\$0.00	\$0.00	\$155.60
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.54	\$63.95	\$0.00	\$0.00	\$63.95
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 10	WORK ORDER TOTAL:	6.33	746.84	1,810.83	964.55	3,522.22
---------------	-------------------	------	--------	----------	--------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-52-008	REPLACE NEW MONITOR	5761126	2113128		\$21.06
03-52-008	REPLACE NEW MONITOR	5761126	2113626		\$19.30
03-52-008	REPLACE NEW MONITOR	5761126	2113626		(\$19.30)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11078579	2090051576		\$938.49
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	964.55

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-52-008	REPLACE NEW MONITOR	11074414	02/27/2023 07:00:00	02/27/2023 07:06:00	0.10	\$11.80
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	11915538	02/27/2023 07:00:00	02/27/2023 07:30:00	0.50	\$59.00
14-17	INSTALL TIRES, TUBES, LINERS & VALVES	11074414	02/27/2023 07:00:00	02/27/2023 07:24:00	0.40	\$47.20
03-52-008	REPLACE NEW MONITOR	11074414	02/21/2023 13:45:29	02/21/2023 13:52:57	0.12	\$14.68
03-52-008	REPLACE NEW MONITOR	11074414	02/21/2023 13:45:29	02/21/2023 13:52:57	(0.12)	(\$14.68)

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11074414	02/21/2023 13:14:43	02/21/2023 13:41:53	0.45	\$53.43
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11074414	02/21/2023 09:30:00	02/21/2023 11:09:28	1.66	\$195.62
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11074414	02/21/2023 09:05:22	02/21/2023 09:15:00	0.16	\$18.95
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	11074414	02/21/2023 07:12:12	02/21/2023 08:11:04	0.98	\$115.77
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/10/2023 07:25:09	02/10/2023 08:44:16	1.32	\$155.60
07-55-039	LUBRICATE LIFTGATE ASSY	11074414	02/10/2023 07:01:58	02/10/2023 07:09:14	0.12	\$14.29
03-51-038	REPLACE NEW WIPER BLADES	11074414	02/09/2023 15:31:00	02/09/2023 15:36:43	0.10	\$11.24
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/09/2023 14:58:18	02/09/2023 15:30:49	0.54	\$63.95
					LABOR	746.85

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	4C4Z2C026A	FRONT ROTORS	235.65	2	\$471.30
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	3080866	OIL SEALS	144.00	2	\$288.00
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWRZ36786	BRAKE PADS	111.92	1	\$111.92
03-52-008	REPLACE NEW MONITOR	IA-RV-805A	7" QUAD MONITOR	868.50	1	\$868.50
03-52-008	REPLACE NEW MONITOR	IA-PM-1980S	7" QUAD MONITOR	846.00	(1)	(\$846.00)
03-52-008	REPLACE NEW MONITOR	IA-PM-1980S	7" QUAD MONITOR	846.00	1	\$846.00
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.41	1	\$4.41
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PTX24240	BLUE LOCTITE 1.22 OZ	35.70	1	\$35.70
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	VV831	HP 80W90 GEAR OIL GL5 QT	9.20	1	\$9.20
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.46	1	\$4.46
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	BRAKE FLUID	BRAKE FLUID DOT 3 12OZ	4.46	(1)	(\$4.46)
03-51-038	REPLACE NEW WIPER BLADES	C111	RED BRAKE CLEANER	6.17	1	\$6.17
					PARTS	1810.83

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 46101

Work Order Notes

(EHANNAH) pm- replace wipers- perform safety inspections

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(SHARBIN) Installed new front brake pads and rotors and installed new cotter pins. SH

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

03-52-008 - REPLACE NEW MONITOR

(EKIMBREL) MONITOR PLUG IS DIFFERENT, HAD TO ORDER NEW CAMERAS. WILL INSTALL ONCE CAMERAS COME IN

(LISAPATE) Camera has not been installed yet. but billing the monitor

07-55-039 - LUBRICATE LIFTGATE ASSY

(SHARBIN) Greased the liftgate. SH

14-17 - INSTALL TIRES, TUBES, LINERS & VALVES

(EKIMBREL) SH INSTALLED 2 FRONT TIRES AFTER STM MOUNTED AND BALANCED TIRES

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Taken to Southern Mart by RC

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) STM MOUNT AND BALANCED 2 TIRES

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found the front pads at 6MM and the rear pads at 8MM. The front tire DOT dates are 1917 on the left and 4416 on the right they will need to be replaced. Found no other issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 944 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. The front tires are out of date(LF 1917 RF 4416) and need to be replaced. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 47021

USING DEPT NO:	504302	OPENED DATE:	05/12/2023 08:01:23	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	05/12/2023 14:23:12	METER 1 - M:	76512	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/12/2023 15:09:53	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650							
			UNIT SERIAL NO:	3FRNF65Y56V356324					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.10	\$11.31	\$0.00	\$0.00	\$11.31
07-55-039	LUBRICATE LIFTGATE ASSY	DON	O	N	GARAGE	0.25	\$29.50	\$0.00	\$0.00	\$29.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$79.95	\$100.26	\$0.00	\$180.21
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.15	\$18.13	\$29.71	\$0.00	\$47.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:					1.18	138.89	129.97	5.00	273.86
--------------	-------------------	--	--	--	--	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
07-55-039	LUBRICATE LIFTGATE ASSY	12052187	05/12/2023 10:07:58	05/12/2023 10:22:58	0.25	\$29.50
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	12052187	05/12/2023 10:14:06	05/12/2023 10:23:19	0.15	\$18.13
06-15	INSPECT STEERING	12052187	05/12/2023 10:08:09	05/12/2023 10:13:54	0.10	\$11.31
66-PM-PMA	PERFORM OIL CHANGE	12052187	05/12/2023 09:27:19	05/12/2023 10:07:58	0.68	\$79.95
LABOR						138.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	29.71	1	\$29.71
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	22.86	1	\$22.86
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	3.87	20	\$77.40
PARTS						129.97

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 47021

Work Order Notes

(EHANNAH) pm- replace wipers- adjust brakes- inspect steering.

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

06-15 - INSPECT STEERING

(JWRIGHT) Checked steering all good. JAW,GC

07-55-039 - LUBRICATE LIFTGATE ASSY

(LISAPATE) Greased liftgate assy. JW

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) performed pm service coolant -34° JAW,GC/JAW
MILEAGE-76512

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(JWRIGHT) Replaced fuel filter.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 47696

USING DEPT NO:	504302	OPENED DATE:	07/21/2023 10:34:34	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/24/2023 14:14:22	METER 1 - M:	77547	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2023 14:08:18	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.96	\$16.65	\$0.00	\$26.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$12.65	\$0.00	\$0.00	\$12.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.19	22.61	16.65	5.00	44.26
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/24/2023 13:00:00	07/24/2023 13:06:26	0.11	\$12.65
66-PM-PMA	PERFORM OIL CHANGE	12201267	07/24/2023 12:41:05	07/24/2023 12:41:05	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	07/24/2023 13:06:26	07/24/2023 13:11:30	0.08	\$9.96
				LABOR		22.61

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
					PARTS	16.65

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 47696

Work Order Notes

(LISAPATE) PM-adjust brakes
(EKIMBREL) truck doesn't get brakes adjusted. isn't a big truck

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC, Fluid check only, vehicle driven 1,035 miles, filter good, tires and tire pressure, greased fittings, updated oil change sticker.
Miles, 77,547

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 48012

USING DEPT NO:	504302	OPENED DATE:	08/28/2023 13:52:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:42:29	METER 1 - M:	78376	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 11:43:16	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-36-004	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.17	\$19.50	\$156.44	\$0.00	\$175.94
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.17	19.50	156.44	5.00	180.94
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-36-004	REPLACE NEW BATTERY	11074414	09/05/2023 13:11:02	09/05/2023 13:20:57	0.17	\$19.50
06-32-002	INSPECT BATTERY	11074414	08/28/2023 14:17:25	08/28/2023 14:17:25	0.00	\$0.00
06-32-002	INSPECT BATTERY	11074414	08/28/2023 14:17:25	08/28/2023 14:17:25	0.00	\$0.00
				LABOR		19.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-36-004	REPLACE NEW BATTERY	DKAETX9	BATTERY	156.44	1	\$156.44
					PARTS	156.44

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 48012

Work Order Notes

(EHANNAH) check battery

Job Notes

03-36-004 - REPLACE NEW BATTERY

(SHARBIN) Installed a new battery per customer request. SH

06-32-002 - INSPECT BATTERY

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 49077

USING DEPT NO:	504302	OPENED DATE:	11/29/2023 08:07:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2024 09:21:18	METER 1 - M:	79905	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 11:07:33	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.16	\$19.04	\$16.65	\$0.00	\$35.69
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.15	\$18.22	\$0.00	\$0.00	\$18.22
14-52-024	INSTALL BACK UP CAMERA	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.83	\$97.78	\$30.11	\$0.00	\$127.89
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.05	\$5.74	\$30.62	\$0.00	\$36.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	1.69	199.78	77.38	5.00	282.16
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-52-024	INSTALL BACK UP CAMERA	11310047	01/24/2024 07:00:00	01/24/2024 07:30:00	0.50	\$59.00
06-15	INSPECT STEERING	11074414	12/01/2023 15:04:09	12/01/2023 15:13:25	0.15	\$18.22
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/01/2023 14:30:00	12/01/2023 14:48:55	0.32	\$37.20
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/01/2023 13:44:12	12/01/2023 14:15:00	0.51	\$60.57
03-51-038	REPLACE NEW WIPER BLADES	11074414	12/01/2023 14:54:17	12/01/2023 15:03:58	0.16	\$19.04
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11074414	12/01/2023 14:50:10	12/01/2023 14:53:05	0.05	\$5.74
				LABOR		199.77

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	22.86	1	\$22.86
66-PM-PMA	PERFORM OIL CHANGE	CMP	MOBILE CM-P TUBE GREASE	7.25	1	\$7.25
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	BALPF7698	BALDWIN FUEL FILTER	30.62	1	\$30.62
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
				PARTS		77.38

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 49077

Work Order Notes

(EHANNAH) pm- adjust brakes- inspect steering. Check on the camera that was ordered for this vehicle.,
(EHOWELL) Inspect passenger window. The customer called after they picked up the vehicle and informed us of this problem. The job was cancelled on this ticket. We will need to address the concern when the vehicle comes back. EH
(EHANNAH) install backup camera

Job Notes

01-13 - ADJUST BRAKES

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

06-15 - INSPECT STEERING

(SHARBIN) Inspected the steering. Found no issues at this time. SH

14-52-024 - INSTALL BACK UP CAMERA

(EHOWELL) The old camera had moisture in it. Installed a new backup camera. The old monitor in the truck is not compatible. The customer will need to bring the vehicle back so we can install the new monitor. We have the monitor here. EH .5 HR

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) performed PM greased lift gate. SH

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(SHARBIN) Replaced the fuel filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 4936

USING DEPT NO:	504302	OPENED DATE:	12/09/2009 13:48:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2009 14:52:14	METER 1 - M:	14880	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2009 14:52:16	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIF	DON	O	N	GARAGE	0.80	\$46.00	\$52.20	\$0.00	\$98.20

JOB COUNT: 1	WORK ORDER TOTAL:	0.80	46.00	52.20	0.00	98.20
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	10041963	12/09/2009 17:00:00	12/09/2009 17:48:00	0.80	\$46.00
					LABOR	46.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	SLM10011	SLIME TIRE REPAIR	13.10	2	\$26.19
24-17-019	REPAIR DOLLY/GOLF CART/UTILITY TIRES	SLM30010	INNER TUBE 4.10/3.50-4	13.01	2	\$26.01
					PARTS	52.20

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **4936**

Work Order Notes

(LPATE) TIM BROUGHT OVER 2 DOLLY'S WITH FLAT TIRES ON THEM SEALS BROKEN ONE TIRE HAD A HOLE IN TUBE, WE REPLACED TUBE AND GAVE THEM EXTRA TIRES TO HAVE ON HAND

Job Notes

24-17-019 - REPAIR DOLLY/GOLF CART/UTILITY TIRES

(LPATE) REPAIRED TIRES ON 2 DOLLY'S FOR MOVING DEPT GAVE TIM EXTRA TUBE AND SLIME TO REPAIR AS NEEDED NEXT TIME ONE GOES FLAT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 49697

USING DEPT NO:	504302	OPENED DATE:	02/05/2024 13:27:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2024 07:53:36	METER 1 - M:	80774	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/21/2024 08:00:02	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-074	REPLACE NEW WINDOW SWITCH	DON	N	N	GARAGE	0.38	\$45.14	\$68.33	\$0.00	\$113.47
06-52-024	INSPECT BACK UP CAMERA	DON	N	N	GARAGE	0.17	\$20.39	\$0.00	\$0.00	\$20.39
24-52-024	REPAIR BACK UP CAMERA	DON	N	N	GARAGE	1.33	\$156.58	\$0.00	\$0.00	\$156.58
35-42	DIAGNOSE COOLING SYSTEM	DON	N	N	GARAGE	1.71	\$201.22	\$41.82	\$0.00	\$243.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	3.59	423.33	110.15	5.00	538.48
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-074	REPLACE NEW WINDOW SWITCH	11310047	02/14/2024 07:19:56	02/14/2024 07:42:53	0.38	\$45.14
06-52-024	INSPECT BACK UP CAMERA	11310047	02/13/2024 15:43:47	02/13/2024 15:54:09	0.17	\$20.39
35-42	DIAGNOSE COOLING SYSTEM	11310047	02/13/2024 07:41:53	02/13/2024 09:20:06	1.64	\$193.16
35-42	DIAGNOSE COOLING SYSTEM	11310047	02/12/2024 08:35:44	02/12/2024 08:39:50	0.07	\$8.06
24-52-024	REPAIR BACK UP CAMERA	11310047	02/12/2024 07:08:36	02/12/2024 08:28:13	1.33	\$156.58
				LABOR		423.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
35-42	DIAGNOSE COOLING SYSTEM	KSLST5501	K-SEAL COOLANT LEAK STOP	20.91	2	\$41.82
03-02-074	REPLACE NEW WINDOW SWITCH	STIDWS110	POWER WINDOW SWITCH	68.33	1	\$68.33
					PARTS	110.15

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 49697

Work Order Notes

(EHANNAH) replace passenger window motor with regulator- repair backup camera

Job Notes

03-02-074 - REPLACE NEW WINDOW SWITCH

(EHOWELL) The passenger window switch would operate the window in the down position, but not the up position. The circuit inside the switch was not closing. Installed a new passenger window switch. EH 1.5 HRS

06-52-024 - INSPECT BACK UP CAMERA

(EHOWELL) The vehicle previously had a rear backup camera installed, but the monitor needed to be installed. EH

24-52-024 - REPAIR BACK UP CAMERA

(EHOWELL) Removed the radio and removed the old monitor from the top of the dash. Installed a new monitor and connected the monitor to the camera cable going to the rear of the vehicle. The cable was not long enough so we had to unwind the excessive cable and reposition the cable along the frame rail. We used mechanic's wire to route the cable up through the frame of the box/body and connect it to the backup camera. The backup camera is now functioning when the gear selector is placed in Reverse. EH/SH/CW 1.5 HR

35-42 - DIAGNOSE COOLING SYSTEM

(EHOWELL) The vehicle was leaking coolant on the ground due to multiple points of failure in the heater hose lines. Added two bottles of stop leak to the cooling system and allowed the vehicle to run so the additive could circulate. Allowed the vehicle to sit with the engine off. Examined beneath the vehicle and did not see a puddle of coolant on the ground. EH .5 HR

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 4978

USING DEPT NO:	504302	OPENED DATE:	12/15/2009 10:05:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/16/2009 08:39:15	METER 1 - M:	14880	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/16/2009 08:39:17	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCI	DON	O	N	GARAGE	0.00	\$0.00	\$12.03	\$0.00	\$12.03

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	12.03	0.00	12.03
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	RADL616	WHITE LITHIUM	6.02	2	\$12.03
					PARTS	12.03

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 4978

Work Order Notes

(LPATE) TIM REQUESTED 2 CANS OF WHITE LITHIUM GREASE

Job Notes

PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LPATE) GAVE TIM 2 CANS OF WHITE LITHIUM GREASE FOR LIFT GATES ON TRUCKS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 50115

USING DEPT NO:	504302	OPENED DATE:	03/08/2024 07:58:18	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2024 15:08:26	METER 1 - M:	81066	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2024 09:36:31	IN-SERVICE DATE:	02/07/2006						
TECH SPEC NO:	06TKFORDF650	2006 Ford F650			UNIT SERIAL NO:	3FRNF65Y56V356324					

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-074	REPLACE NEW WINDOW SWITCH	DON	N	N	GARAGE	0.50	\$59.00	\$190.91	\$0.00	\$249.91
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.02	\$2.26	\$0.00	\$0.00	\$2.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$1.93	\$281.66	\$0.00	\$283.59
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	63.19	472.57	5.00	540.76
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-02-074	REPLACE NEW WINDOW SWITCH	11310047	05/02/2024 07:00:00	05/02/2024 07:30:00	0.50	\$59.00
06-15	INSPECT STEERING	12395904	05/02/2024 08:52:01	05/02/2024 08:53:10	0.02	\$2.26
66-PM-PMA	PERFORM OIL CHANGE	12395904	05/02/2024 08:15:35	05/02/2024 08:16:34	0.02	\$1.93
LABOR						63.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BALCA5366	AIR FILTER ELEMENT	94.40	1	\$94.40
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	22.86	1	\$22.86
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	4.11	20	\$82.20
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	4.11	20	\$82.20
03-02-074	REPLACE NEW WINDOW SWITCH	WL1Z14529CA	POWER WINDOW SWITCH	190.91	1	\$190.91
PARTS						472.57

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 50115

Work Order Notes

(EKIMBREL) replace window switch
(EHANNAH) pm- adjust brakes- inspect steering
(EKIMBREL) cant adjust brakes

Job Notes

01-13 - ADJUST BRAKES

03-02-074 - REPLACE NEW WINDOW SWITCH

(EKIMBREL) eh replace window switch

06-15 - INSPECT STEERING

(FCONTRER) perform inspect FC - SH good

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc -sh
(EKIMBREL) 20qts should have been billed on wo#49077

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 5080

USING DEPT NO:	504302	OPENED DATE:	01/11/2010 13:26:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/12/2010 13:50:33	METER 1 - M:	14880	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/12/2010 13:50:35	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCI	DON	O	N	GARAGE	0.00	\$0.00	\$63.63	\$0.00	\$63.63

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	63.63	0.00	63.63
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PU-53-999	PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&	CRC05432	DIESEL FUEL TREATMENT	10.61	6	\$63.63
					PARTS	63.63

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 5080

Work Order Notes

(LPATE) DUE TO COLD WEATHER BELOW FREEZING DRIVER NEEDS DIESEL FUEL TREATMENT

Job Notes

PU-53-999 - PURCHASED VEHICLE FLUIDS,LUBRCNTS,GASES&

(LPATE) GAVE DRIVER 6 BOTTLES OF DIESEL FUEL TRMT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 51149

USING DEPT NO:	504302	OPENED DATE:	06/11/2024 12:24:45	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	06/12/2024 15:32:21	METER 1 - M:	82031	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2024 08:30:52	IN-SERVICE DATE:	02/07/2006						
TECH SPEC NO:	06TKFORDF650	2006 Ford F650									
		UNIT SERIAL NO:	3FRNF65Y56V356324								

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-52-021	INSTALL GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **51149**

Work Order Notes

(EHANNAH) install GPS- 87U0306400060

Job Notes

14-52-021 - INSTALL GPS SYSTEM

(EHOWELL) Removed GPS# 5041375506.

Installed GPS# 87U030640060. Verified that light on new GPS was blinking. EH

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 5123

USING DEPT NO:	504302	OPENED DATE:	01/20/2010 07:40:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/22/2010 14:54:31	METER 1 - M:	16641	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/22/2010 14:54:33	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	N	N	GARAGE	0.25	\$14.38	\$31.32	\$0.00	\$45.70
03-55-035	REPLACE NEW LIFTGATE STARTER	DON	O	N	GARAGE	3.52	\$202.32	\$650.48	\$0.00	\$852.80
36-42-016	FLUSH FLUSH COOLING SYSTEM	DON	O	N	GARAGE	1.00	\$57.50	\$63.75	\$0.00	\$121.25
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.50	\$102.94	\$0.00	\$160.44
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$0.32	\$66.48	\$0.00	\$66.80
66-PM-PMT	PERFORM TRANSMISSION SERVICE	DON	P	N	GARAGE	2.33	\$133.93	\$271.14	\$0.00	\$405.07

JOB COUNT: 6	WORK ORDER TOTAL:	8.10	465.95	1,186.11	0.00	1,652.06
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
36-42-016	FLUSH FLUSH COOLING SYSTEM	11268671	01/22/2010 06:15:00	01/22/2010 07:15:00	1.00	\$57.50
03-51-038	REPLACE NEW WIPER BLADES	11268671	01/22/2010 06:00:00	01/22/2010 06:15:00	0.25	\$14.38
03-55-035	REPLACE NEW LIFTGATE STARTER	11268671	01/21/2010 09:15:00	01/21/2010 11:58:06	2.72	\$156.30
03-55-035	REPLACE NEW LIFTGATE STARTER	11268671	01/21/2010 08:11:59	01/21/2010 09:00:00	0.80	\$46.02
66-PM-PMA	PERFORM OIL CHANGE	11268671	01/21/2010 08:11:50	01/21/2010 09:11:50	1.00	\$57.50
66-PM-PMA	PERFORM OIL CHANGE	11268671	01/21/2010 08:11:50	01/21/2010 08:11:59	0.00	(\$0.14)
66-PM-PMA	PERFORM OIL CHANGE	11268671	01/21/2010 08:11:50	01/21/2010 08:11:59	0.00	\$0.14
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11268671	01/21/2010 08:11:30	01/21/2010 08:11:50	0.01	\$0.32
66-PM-PMT	PERFORM TRANSMISSION SERVICE	11268671	01/21/2010 05:51:45	01/21/2010 08:11:30	2.33	\$133.93
					LABOR	465.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	16.11	5	\$80.55
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	22.39	1	\$22.39
03-51-038	REPLACE NEW WIPER BLADES	60-2040	WIPER BLADE	15.66	2	\$31.32
03-55-035	REPLACE NEW LIFTGATE STARTER	SHIPPING	SHIPPING AND HANDLING	171.37	1	\$171.37
66-PM-PMT	PERFORM TRANSMISSION SERVICE	C111	RED BRAKE CLEANER	3.43	1	\$3.43

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMT	PERFORM TRANSMISSION SERVICE	CIT632493001004	QUATRASYND TRANS FLUID	247.08	1	\$247.08
36-42-016	FLUSH FLUSH COOLING SYSTEM	ANTIFREEZE CHEVRON	ANTIFREEZE-DIESEL	12.75	5	\$63.75
03-55-035	REPLACE NEW LIFTGATE STARTER	WA70092313	LIFTGATE MOTOR	41.99	1	\$41.99
66-PM-PMT	PERFORM TRANSMISSION SERVICE	WIX57701	TRANSMISSION FILTER	20.63	1	\$20.63
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	MOTFD4596	FILTER-FUEL	66.48	1	\$66.48
03-55-035	REPLACE NEW LIFTGATE STARTER	WA70092313	LIFTGATE MOTOR	41.99	(1)	(\$41.99)
03-55-035	REPLACE NEW LIFTGATE STARTER	WA70092313	LIFTGATE MOTOR	437.12	1	\$437.12
03-55-035	REPLACE NEW LIFTGATE STARTER	WA75089833	LIFTGATE SOLENOID	41.99	1	\$41.99
					PARTS	1186.11

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 5123

Work Order Notes

(LPATE) LIFTGATE IS INOP-PM-REPLACE WIPERS-REPLACE FUEL FILTER-REPLACE TRANS FILTER-FLUSH COOLANT

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

03-55-035 - REPLACE NEW LIFTGATE STARTER

(LPATE) REPLACED LIFTGATE MOTOR AND SOLENOID HAD TO SPECIAL ORDER FROM BOBBY PARK TRUCK AND EQUIP

36-42-016 - FLUSH FLUSH COOLING SYSTEM

(LPATE) DRAINED COOLANT, FLUSHED WITH WATER, REFILLED WITH NEW COOLANT

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 0

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY IF

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE) The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

66-PM-PMT - PERFORM TRANSMISSION SERVICE

(LPATE) DRAINED TRANS FLUID-REPLACED EXTERNAL FILTER-ADDED NEW FLUID

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 51232

USING DEPT NO:	504302	OPENED DATE:	06/18/2024 09:05:57	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/29/2024 14:23:20	METER 1 - M:	82109	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/30/2024 08:17:05	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-34-008	INSPECT DOME LIGHT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-02-016	REPAIR TAIL&LIFT GATE	DON	N	N	GARAGE	0.00	\$0.00	\$0.69	\$0.00	\$0.69
24-02-023	REPAIR HANDLES - INNER & OUTER	DON	N	N	GARAGE	0.00	\$0.00	\$3.06	\$0.00	\$3.06
35-03-015	DIAGNOSE OIL PRESSURE GAUGE	DON	N	N	GARAGE	6.85	\$808.63	\$0.00	\$0.00	\$808.63
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$1,725.00	\$1,725.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	78.17	\$9,223.96	\$0.00	\$0.00	\$9,223.96
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$6.44	\$0.00	\$6.44
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 9	WORK ORDER TOTAL:	85.02	10,032.59	10.19	1,730.00	11,772.78
--------------	-------------------	-------	-----------	-------	----------	-----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11078579	2090076393		\$1,725.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11078579	2090076422		\$1,725.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11078579	2090076422		(\$1,725.00)
COMML					1730.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11310047	06/24/2024 14:30:00	06/24/2024 15:54:31	1.41	\$166.22
66-79-003	PERFORM SAFETY INSPECTION	11310047	06/24/2024 13:00:00	06/24/2024 14:15:00	1.25	\$147.50
66-79-003	PERFORM SAFETY INSPECTION	11310047	06/24/2024 09:30:00	06/24/2024 12:00:00	2.50	\$295.00
66-79-003	PERFORM SAFETY INSPECTION	11310047	06/21/2024 08:14:22	06/24/2024 09:15:00	73.01	\$8,615.25
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	06/21/2024 07:12:17	06/21/2024 08:14:22	1.03	\$122.10
35-01	DIAGNOSE AIR CONDITIONING, HEAT, VENT	11310047	06/21/2024 07:12:17	06/21/2024 08:14:22	(1.03)	(\$122.10)
35-03-015	DIAGNOSE OIL PRESSURE GAUGE	11310047	06/20/2024 14:15:13	06/20/2024 15:52:55	1.63	\$192.14

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
35-03-015	DIAGNOSE OIL PRESSURE GAUGE	11310047	06/20/2024 07:26:54	06/20/2024 12:11:22	4.74	\$559.45
35-03-015	DIAGNOSE OIL PRESSURE GAUGE	11310047	06/18/2024 15:20:22	06/18/2024 15:49:22	0.48	\$57.03
					LABOR	10032.59

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
24-02-023	REPAIR HANDLES - INNER & OUTER	BOLT	BOLT	0.77	4	\$3.06
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	6.44	1	\$6.44
24-02-016	REPAIR TAIL&LIFT GATE	BOLT	BOLT	69.00	1	\$69.00
24-02-016	REPAIR TAIL&LIFT GATE	BOLT	BOLT	69.00	(1)	(\$69.00)
24-02-016	REPAIR TAIL&LIFT GATE	BOLT	BOLT	0.69	1	\$0.69
					PARTS	10.19

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 51232

Work Order Notes

(EHANNAH) pm- inspect oil gage- replace cup holder- repair lift gage, there is a piece hanging- diagnose AC and charge freon- replace wood on both sides on bottom walls- install E- tracks where there is missing and or damaged- replace front headlight- diagnose dash and radio lights.

(EKIMBREL) dept only wanted tires and liftgate fixed at this time

Job Notes

Work Order Charge Detail

06-34-008 - INSPECT DOME LIGHT

(EHOWELL) Removed the light switch for the interior lights inside the box. Crimped two I-lets on the wires and secured them to the toggle switch. Verified operation of the lights after repair.

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(IFALLS) chad and ronnie performed transport to southern tire

24-02-016 - REPAIR TAIL&LIFT GATE

(IFALLS) EH removed broken bolt in liftgate and installed a new bolt

24-02-023 - REPAIR HANDLES - INNER & OUTER

(GARAGE) Removed the rivits from the right rear handle and reinstalled with self driller screws. JAW
.5hr

24-02-090 - REPAIR CUP HOLDER ASSY/BRACKET

24-34-001 - REPAIR HEADLAMPS

24-55-012 - REPAIR CARGO RESTRAINTS

24-71-007 - REPAIR LINING - PLYWOOD

35-01 - DIAGNOSE AIR CONDITIONING, HEAT, VENT

35-03-010 - DIAGNOSE CLUSTER ASSY

35-03-015 - DIAGNOSE OIL PRESSURE GAUGE

(EHOWELL) Removed the oil pressure sending unit for the low pressure oil system. Installed a gauge and verified that the vehicle had proper oil pressure. The oil pressure sending unit appears to be intermittently sending false signals. Reinstalled original sending unit. EH

66-01-058 - PERFORM EVAC AND RECHARGE FREON

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) STM replaced 4 rear tires

66-79-003 - PERFORM SAFETY INSPECTION

(IFALLS) EH performed the safety inspection

66-PM-PMA - PERFORM OIL CHANGE

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

(EHOWELL) The vehicle was driven 1043 miles since the oil was dropped last. (According to M5 records.) It should have gotten a fluid check this visit. No records that the PM was performed.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 51901

USING DEPT NO:	504302	OPENED DATE:	08/21/2024 14:04:45	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/21/2024 15:48:21	METER 1 - M:	82590	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/22/2024 14:27:34	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$1,439.96	\$1,439.96
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	1,444.96	1,444.96
--------------	-------------------	------	------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11078579	2090076393		\$1,439.96
				COMML	1444.96

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 51901

Work Order Notes

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) WRONG INVOICE AND AMOUNT BILLED TO WO#51232. \$1500 WAS BILLED, SHOULD HAVE BEEN \$2752.14. PER ANGEL I WILL BE THE DIFFERENCE AND PUT CORRECT INV#.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		236625	2006 FORD F650				WORK ORDER NO:			52598		
USING DEPT NO:		504302	OPENED DATE:		10/25/2024 08:23:27		LOCATION: GARAGE - University Automotive Services					
WO STATUS:		CLOSED	COMPLETED DATE:		11/01/2024 07:51:51		METER 1 - M:		83459	METER 2 - H: 0		
WO VISIT REASON:		SCHEDULED	CLOSED DATE:		11/01/2024 07:51:51		IN-SERVICE DATE:		02/07/2006			
TECH SPEC NO:		06TKFORDF650	2006 Ford F650				UNIT SERIAL NO:		3FRNF65Y56V356324			
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
24-55-038		REPAIR CARGO DOOR LIFT SPRINGS		DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1				WORK ORDER TOTAL:				0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 52598

Work Order Notes

Job Notes

24-55-038 - REPAIR CARGO DOOR LIFT SPRINGS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 52745

USING DEPT NO:	504302	OPENED DATE:	11/07/2024 09:04:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/12/2024 09:25:46	METER 1 - M:	83459	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/12/2024 14:16:55	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$112.85	\$0.00	\$112.85
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	112.85	5.00	117.85
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	3.87	21	\$81.27
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	3.87	(20)	(\$77.40)
66-PM-PMA	PERFORM OIL CHANGE	BALP7436	OIL FILTER ELEMENT W/ CAP	22.86	1	\$22.86
66-PM-PMA	PERFORM OIL CHANGE	15W40BT	BULK OIL 15W40 THOMAS	3.87	20	\$77.40
66-PM-PMA	PERFORM OIL CHANGE	DOR090177	DRAIN PLUG	8.72	1	\$8.72
					PARTS	112.85

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 52745

Work Order Notes

(EHANNAH) pm- adjust brakes- inspect steering- PLEASE DO NOT CALL CUSTOMER WHEN COMPLETE, MORE REPAIRS ARE NEEDED.

Job Notes

01-13 - ADJUST BRAKES

06-15 - INSPECT STEERING

(GARAGE) Cm- Inspected steering system.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- LOF/PM complete.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 53051

USING DEPT NO:	504302	OPENED DATE:	12/09/2024 12:48:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/09/2024 13:38:08	METER 1 - M:	83876	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/09/2024 13:38:11	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-55-038	REPAIR CARGO DOOR LIFT SPRINGS	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$672.50	\$672.50
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	677.50	677.50
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
24-55-038	REPAIR CARGO DOOR LIFT SPRINGS	11076414	TCS55499		\$672.50
24-55-038	REPAIR CARGO DOOR LIFT SPRINGS	11076414	TCS55499		(\$649.75)
24-55-038	REPAIR CARGO DOOR LIFT SPRINGS	11076414	TCS55499		\$649.75
				COMML	677.50

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 53051

Work Order Notes

(IFALLS) department requested rear roll up door be repaired

Job Notes

24-55-038 - REPAIR CARGO DOOR LIFT SPRINGS

(EKIMBREL) Closed work order at month end for WO#52598. Reopened to bill repairs.

(IFALLS) overhead door came out and repaired rear roll up door.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO:		236625	2006 FORD F650			WORK ORDER NO:			53184			
USING DEPT NO:		504302	OPENED DATE:		12/17/2024 14:43:56	LOCATION: GARAGE - University Automotive Services						
WO STATUS:		CLOSED	COMPLETED DATE:		12/20/2024 12:00:04	METER 1 - M:		83876	METER 2 - H:		0	
WO VISIT REASON:		SCHEDULED	CLOSED DATE:		12/20/2024 14:00:07	IN-SERVICE DATE:		02/07/2006				
TECH SPEC NO:		06TKFORDF650	2006 Ford F650			UNIT SERIAL NO:		3FRNF65Y56V356324				
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021		REMOVE GPS SYSTEM		DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:						0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 53184

Work Order Notes

(EHANNAH) remove GPS install in 246832

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) REMOVED GPS SN: 87U030640060 OUT OF UNT 5975A-GC

(EHOWELL) Visit Reason Changed On 12/20/2024 11:59 AM By EHOWELL

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 53368

USING DEPT NO:	504302	OPENED DATE:	01/14/2025 15:24:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/16/2025 13:23:29	METER 1 - M:	83925	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/16/2025 14:51:49	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$42.30	\$0.00	\$42.30

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	42.30	5.00	47.30
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	WILW747	RAZOR BLADES	0.15	2	\$0.30
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	08984	ADHESIVE REMOVER	42.00	1	\$42.00
					PARTS	42.30

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 53368

Work Order Notes

(EHANNAH) prep for sale

Job Notes

CH-SP - CHARGE Shop Supplies

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) removed wordmarks and tag\RC\CW

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 5708

USING DEPT NO:	504302	OPENED DATE:	04/29/2010 15:31:47	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2010 09:07:09	METER 1 - M:	16641	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2010 09:07:11	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-51-052	PURCHASED WINDOW VENT VISORS/F	DON	O	N	GARAGE	0.00	\$0.00	\$75.23	\$0.00	\$75.23

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	75.23	0.00	75.23
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-51-052	PURCHASED WINDOW VENT VISORS/RAINGUARDS	VEN192503	VENT VISORS	75.23	1	\$75.23
					PARTS	75.23

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **5708**

Work Order Notes

(LPATE) TIM REQUESTED VENT VISORS FOR BOTH FRONT WINDOWS

Job Notes

PU-51-052 - PURCHASED WINDOW VENT VISORS/RAINGUARDS

(LPATE) GAVE TIM VENT VISORS TO INSTALL ON HIS TRUCK

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6434

USING DEPT NO:	504302	OPENED DATE:	08/05/2010 04:00:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2010 06:38:52	METER 1 - M:	18828	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	08/06/2010 06:38:53	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	O	N	GARAGE	0.30	\$17.25	\$1.38	\$0.00	\$18.63

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	1.38	0.00	18.63
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11088858	08/05/2010 04:02:00	08/05/2010 04:20:00	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	3157	BULB-BRAKE/TURN/PARK	1.38	1	\$1.38
					PARTS	1.38

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6434

Work Order Notes

(RWINTERS) LF BULB PARK/BLINKER IS OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(RWINTERS) REPLACED LF BULB

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6445

USING DEPT NO:	504302	OPENED DATE:	08/06/2010 15:41:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2010 07:16:35	METER 1 - M:	18846	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2010 07:16:39	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
24-02-016	REPAIR TAIL&LIFT GATE	DON	O	N	GARAGE	0.50	\$28.75	\$2.40	\$0.00	\$31.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.03	\$59.23	\$101.99	\$0.00	\$161.22
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	1.02	\$58.47	\$23.67	\$0.00	\$82.14

JOB COUNT: 3	WORK ORDER TOTAL:	2.55	146.45	128.06	0.00	274.51
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	11274660	08/09/2010 07:00:00	08/09/2010 07:30:00	0.50	\$28.75
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	10230946	08/07/2010 10:12:27	08/07/2010 11:13:28	1.02	\$58.47
66-PM-PMA	PERFORM OIL CHANGE	10230946	08/07/2010 07:56:06	08/07/2010 08:57:54	1.03	\$59.23
					LABOR	146.45

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
24-02-016	REPAIR TAIL&LIFT GATE	CONNECTOR	CONNECTOR-NYLON	1.20	2	\$2.40
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	23.67	1	\$23.67
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	16.61	5	\$83.03
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	18.96	1	\$18.96
					PARTS	128.06

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6445

Work Order Notes

(LPATE) PM-REPLACE FUEL FITLER-LUBE LIFT GATE-CHECK WIRING OVERHEATS AT TIMES

Job Notes

24-02-016 - REPAIR TAIL&LIFT GATE

(LPATE) REWIRED THERMAL PROTECTOR ON LIFT GATE

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 0

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY JM/IF

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6700

USING DEPT NO:	504302	OPENED DATE:	09/03/2010 14:02:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2010 14:10:39	METER 1 - M:	19155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/03/2010 14:10:41	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-51	PURCHASED GENERAL ACCESSORIES	DON	O	N	GARAGE	0.00	\$0.00	\$18.81	\$0.00	\$18.81

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	18.81	0.00	18.81
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-51	PURCHASED GENERAL ACCESSORIES	BOX66059	RATCHET TIE DOWNS - SET	18.81	1	\$18.81
					PARTS	18.81

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 6700

Work Order Notes

(RWINTERS) NEED TIE DOWNS FOR GAME DAY TENT

Job Notes

PU-51 - PURCHASED GENERAL ACCESSORIES

(RWINTERS) GAVE DRIVER RATCHET TIE DOWNS

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 7055

USING DEPT NO:	504302	OPENED DATE:	10/22/2010 09:50:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2010 06:50:24	METER 1 - M:	19155	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2010 06:50:26	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STO	DON	N	N	GARAGE	0.30	\$17.25	\$7.75	\$0.00	\$25.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	7.75	0.00	25.00
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	11328035	10/22/2010 17:00:00	10/22/2010 17:18:00	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-002	REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC	5060202R3	BULB-MARKER-RED	7.75	1	\$7.75
					PARTS	7.75

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **7055**

Work Order Notes

(LPATE) LEFT REAR BRAKE LIGHT IS OUT

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

(LPATE) REPLACED LEFT REAR BRAKE LIGHT

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 7544

USING DEPT NO:	504302	OPENED DATE:	01/20/2011 14:05:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2011 07:02:20	METER 1 - M:	20542	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2011 07:02:22	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$17.00	\$104.45	\$0.00	\$121.45
66-PM-PMF	PERFORM FUEL FILTER REPLACEMEN	DON	P	N	GARAGE	0.50	\$28.75	\$23.67	\$0.00	\$52.42

JOB COUNT: 2	WORK ORDER TOTAL:	0.80	45.75	128.12	0.00	173.87
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	01/21/2011 07:00:00	01/21/2011 07:30:00	0.50	\$28.75
66-PM-PMA	PERFORM OIL CHANGE	11338644	01/20/2011 15:22:04	01/20/2011 15:39:48	0.30	\$17.00
					LABOR	45.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.22	1	\$17.22
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.22	(2)	(\$34.44)
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	23.67	1	\$23.67
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	17.45	5	\$87.23
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.22	2	\$34.44
					PARTS	128.12

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 7544

Work Order Notes

(LPATE) PM-REPLACE FUEL FILTER

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 0

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY JM/RS/TM-GREASED AND LUBED LIFTGATE AS NEEDED

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 844

USING DEPT NO:	504302	OPENED DATE:	02/14/2008 14:13:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/18/2008 11:32:22	METER 1 - M:	248318	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/18/2008 11:32:23	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-052	REPLACE NEW WINDOW MOTOR	DON	O	N	GARAGE	0.00	\$0.00	\$349.25	\$0.00	\$349.25
03-34-008	REPLACE NEW DOME LIGHT	DON	O	N	GARAGE	0.00	\$0.00	\$1.34	\$0.00	\$1.34

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	350.59	0.00	350.59
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-008	REPLACE NEW DOME LIGHT	212	BULB-DOME 3RD-BRAKE	1.34	1	\$1.34
03-02-052	REPLACE NEW WINDOW MOTOR	14040844	SWITCH ASM	34.53	1	\$34.53
03-02-052	REPLACE NEW WINDOW MOTOR	14051899	CHANNEL ASM	59.33	1	\$59.33
03-02-052	REPLACE NEW WINDOW MOTOR	14049969	SEAL	36.99	1	\$36.99
03-02-052	REPLACE NEW WINDOW MOTOR	5045610	MOTOR ASM	129.26	1	\$129.26
03-02-052	REPLACE NEW WINDOW MOTOR	349896	SEAL ASM	35.55	1	\$35.55
03-02-052	REPLACE NEW WINDOW MOTOR	326162	CHANNEL ASM	53.60	1	\$53.60
					PARTS	350.60

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 844

Work Order Notes

(RWINTERS) REAR TAILGATE WINDOW IS INOP

Job Notes

03-02-052 - REPLACE NEW WINDOW MOTOR

(LOBRIEN) REPLACED THE REAR TAILGATE WINDOW MOTOR, FRONT DASH REAR WINDOW SWITCH, LEFT AND RIGHT CHANNEL RUN AND BELTLINE STRIPPING.

03-34-008 - REPLACE NEW DOME LIGHT

(LOBRIEN) REPLACED BULB.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 8836

USING DEPT NO:	504302	OPENED DATE:	08/01/2011 10:12:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/02/2011 08:50:32	METER 1 - M:	129284	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/02/2011 08:50:34	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-55-025	REPLACE NEW FOLDING LIFT ARM SPI	DON	O	N	GARAGE	0.00	\$0.00	\$67.47	\$0.00	\$67.47

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	67.47	0.00	67.47
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	75089350	"S" HOOK	4.17	4	\$16.68
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	75085003	HEX NUT 5/16	0.15	4	\$0.60
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	20252200	EYE BOLT AND NUT	3.33	4	\$13.32
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	20270400	PARALLEL ARM SPRING	6.08	4	\$24.30
03-55-025	REPLACE NEW FOLDING LIFT ARM SPRING(S)	SHIPPING	SHIPPING AND HANDLING	12.57	1	\$12.57
					PARTS	67.47

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **8836**

Work Order Notes

(LPATE) PER TIM SPRING FOR LIFTGATE ASSY IS BROKEN

Job Notes

03-55-025 - REPLACE NEW FOLDING LIFT ARM SPRING(S)

(LPATE) GAVE TIM 4 SPRINGS AND HARDWARE TO REPLACE ON LIFTGATE DUE TO ONE BROKEN AND OTHERS WORN WILL INSTALL ALL NEW AND KEEP OTHERS FC BACKUP.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 8953

USING DEPT NO:	504302	OPENED DATE:	08/18/2011 07:46:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/19/2011 08:43:55	METER 1 - M:	129284	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/19/2011 08:43:56	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-34-028	REPLACE NEW MARKER/TURN SIGNAL	DON	O	N	GARAGE	0.30	\$17.25	\$16.17	\$0.00	\$33.42
03-55-038	REPLACE NEW CARGO DOOR LIFT SPI	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$607.71	\$607.71
16-55	TRANSPORT CARGO HNDLNG,RESTRN	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.30	74.75	16.17	607.71	698.63
--------------	-------------------	------	-------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-55-038	REPLACE NEW CARGO DOOR LIFT SPRINGS	11076414	TCS30023	0012848	\$607.71
03-55-038	REPLACE NEW CARGO DOOR LIFT SPRINGS	11076414	TCS30023	0012848	\$0.00
03-55-038	REPLACE NEW CARGO DOOR LIFT SPRINGS	11076414	TCS30023	0012848	\$0.00
COMML					607.71

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-55	TRANSPORT CARGO HNDLNG,RESTRNTS&LIFT SYS	11328035	08/18/2011 17:00:00	08/18/2011 18:00:00	1.00	\$57.50
03-34-028	REPLACE NEW MARKER/TURN SIGNAL ASSY	11237753	08/18/2011 17:00:00	08/18/2011 17:18:00	0.30	\$17.25
LABOR						74.75

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-34-028	REPLACE NEW MARKER/TURN SIGNAL ASSY	F1TZ13411A	TURN SIGNAL SOCKET	16.17	1	\$16.17
PARTS						16.17

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 8953

Work Order Notes

(LPATE) LEFT FRONT TURN SIGNAL SOCKET IS BURNT BULB IS GOOD BUT TURN SIGNAL IS NOT WORKING. REAR CARGO DOOR SPRING BROKEN ON LEFT SIDE. OVERHEAD DOOR TO REPLACE.

Job Notes

03-34-028 - REPLACE NEW MARKER/TURN SIGNAL ASSY

(LPATE) REPLACED LEFT FRONT TURN SIGNAL SOCKET.

03-55-038 - REPLACE NEW CARGO DOOR LIFT SPRINGS

(LPATE) OVERHEAD DOOR HAD SPRINGS OVERNIGHTED FROM OHIO. BROKEN SPRING WAS ON THE LEFT SIDE REMOVED AND INSTALLED NEW SPRINGS FOR BOTH SIDES. PD BY CC.

16-55 - TRANSPORT CARGO HANDLING, RESTRAINTS & LIFT SYS

(LPATE) TAKEN TO OVERHEAD DOOR BY TM

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9160

USING DEPT NO:	504302	OPENED DATE:	09/19/2011 07:44:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/20/2011 11:25:51	METER 1 - M:	129284	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/20/2011 11:25:53	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	1.69	\$96.93	\$0.00	\$0.00	\$96.93
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	2.68	\$153.92	\$137.28	\$0.00	\$291.20
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$3.74	\$24.42	\$0.00	\$28.16

JOB COUNT: 3	WORK ORDER TOTAL:	4.43	254.59	161.70	0.00	416.29
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11338644	09/19/2011 13:00:00	09/19/2011 14:15:00	1.25	\$71.88
03-51-038	REPLACE NEW WIPER BLADES	11338644	09/19/2011 11:33:51	09/19/2011 12:00:00	0.44	\$25.06
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	11338644	09/19/2011 11:29:44	09/19/2011 11:33:38	0.07	\$3.74
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/19/2011 09:30:00	09/19/2011 11:28:37	1.98	\$113.67
66-PM-PMA	PERFORM OIL CHANGE	11338644	09/19/2011 08:33:00	09/19/2011 09:15:00	0.70	\$40.25
					LABOR	254.60

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	P7235	FILTER-OIL	17.65	1	\$17.65
66-PM-PMA	PERFORM OIL CHANGE	TUBE GREASE	TUBE GREASE	3.15	1	\$3.15
66-PM-PMA	PERFORM OIL CHANGE	15W40	OIL GAL BOTTLE (DIESEL)	18.08	4	\$72.30
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	4.91	1	\$4.91
66-PM-PMA	PERFORM OIL CHANGE	60-2040	WIPER BLADE	19.64	2	\$39.27
66-PM-PMF	PERFORM FUEL FILTER REPLACEMENT	3818	FUEL FILTER	24.42	1	\$24.42
					PARTS	161.70

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9160

Work Order Notes

(LPATE) PM-REPLACE WIPERS-REPLACE FUEL FILTER-LUBE LIFTGATE

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LPATE) REPLACED WIPERS

66-PM-PMA - PERFORM OIL CHANGE

(LPATE)

Parts For Job Include:

Part 15W40 OIL BOTTLE (DIESEL) Qty 5 Cost 0

Part P7235 FILTER-OIL Qty 1 Cost 0

Part TUBE GREASE TUBE GREASE Qty 1 Cost 0

(LPATE) PM BY SH/RS-LUBED LIFT GATE

66-PM-PMF - PERFORM FUEL FILTER REPLACEMENT

(LPATE)

The following parts are included with the standard job:

Part No : F81Z9N184AA

Qty : 1

Description : FUEL FILTER

Manufacturer :

(LPATE) REPLACED FUEL FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9402

USING DEPT NO:	504302	OPENED DATE:	10/13/2011 07:32:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/13/2011 11:41:09	METER 1 - M:	24523	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2011 11:41:11	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	1.00	\$57.50	\$210.84	\$0.00	\$268.34
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 2	WORK ORDER TOTAL:	2.00	115.00	210.84	0.00	325.84
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-002	PERFORM SERVICE CALL	11074414	10/13/2011 17:00:00	10/13/2011 18:00:00	1.00	\$57.50
03-32-002	REPLACE NEW BATTERY	11074414	10/13/2011 18:00:00	10/13/2011 19:00:00	1.00	\$57.50
					LABOR	115.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-32-002	REPLACE NEW BATTERY	ACD31TS	BATTERY LARGE TRUCKS	105.42	2	\$210.84
					PARTS	210.84

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9402

Work Order Notes

(LPATE) TIM REQUESTED SVC CALL TO REAR OF MORGAN HALL LEFT FLASHERS ON BATTERIES ARE DEAD.

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LPATE) REPLACED BOTH BATTERIES

66-79-002 - PERFORM SERVICE CALL

(LPATE) SVC CALL TO MORGAN HALL JUMPED TRUCK OFF DRIVER BROUGHT TO GARAGE TO HAVE NEW BATTERIES INSTALLED.

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9669

USING DEPT NO:	504302	OPENED DATE:	11/11/2011 11:40:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/11/2011 13:40:02	METER 1 - M:	24833	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/11/2011 13:40:04	IN-SERVICE DATE:	02/07/2006	
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-34-008	REPLACE NEW DOME LIGHT	DON	N	N	GARAGE	0.30	\$17.25	\$1.33	\$0.00	\$18.58

JOB COUNT: 1	WORK ORDER TOTAL:	0.30	17.25	1.33	0.00	18.58
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-008	REPLACE NEW DOME LIGHT	11074414	11/11/2011 17:00:00	11/11/2011 17:18:00	0.30	\$17.25
					LABOR	17.25

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-34-008	REPLACE NEW DOME LIGHT	912	BULB-BRAKE-3RD	1.33	1	\$1.33
					PARTS	1.33

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: **236625** **2006 FORD F650**

WORK ORDER NO: **9669**

Work Order Notes

(LPATE) PER DRIVER DOME LIGHT IS OUT

Job Notes

03-34-008 - REPLACE NEW DOME LIGHT

(LPATE) REPLACED DOME LIGHT BULB

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9912

USING DEPT NO:	504302	OPENED DATE:	12/19/2011 07:21:31	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	01/03/2012 14:01:27	METER 1 - M:	25155	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/03/2012 14:01:29	IN-SERVICE DATE:	02/07/2006				
TECH SPEC NO:	06TKFORDF650	2006 Ford F650		UNIT SERIAL NO:	3FRNF65Y56V356324				

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-016	REPLACE NEW TAIL&LIFT GATE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$11,818.27	\$11,818.27

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	11,818.27	11,818.27
--------------	-------------------	------	------	------	-----------	-----------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
03-02-016	REPLACE NEW TAIL&LIFT GATE	11153069	48310	0014331	\$11,818.27
				COMML	11818.27

Work Order Charge Detail

The University of Alabama

Report Printed: 01/23/2025 11:34:20 By User: GLOBETTI

UNIT NO: 236625 2006 FORD F650

WORK ORDER NO: 9912

Work Order Notes

(LPATE) LYNCOACH TO REMOVE 3,000LB LIFT AND INSTALL 5,000LB LIFT PER UA BID \$10,276.26. P0037629

Job Notes

03-02-016 - REPLACE NEW TAIL&LIFT GATE

(LPATE) LYNCOACH REMOVED WALTCO LIFGATE INSTALLED NEW LIFGATE ON UA OWNED FORD F650 BOX TRUCK PER BID AS QUOTED. P0037629. LYNCOACH PICK UP FROM UA AND DELIVERED AFTER REPLACED.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Jan 23 2025 11:34:20 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '236625') //Q=