

# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 30099

<b>USING DEPT NO:</b>	504241	<b>OPENED DATE:</b>	06/26/2018 08:02:49	<b>LOCATION:</b>	GARAGE - University Automotive Services		
<b>WO STATUS:</b>	CLOSED	<b>COMPLETED DATE:</b>	06/27/2018 10:06:02	<b>METER 1 - M:</b>	15	<b>METER 2 - H:</b>	0
<b>WO VISIT REASON:</b>	SCHEDULED	<b>CLOSED DATE:</b>	06/27/2018 10:06:03	<b>IN-SERVICE DATE:</b>	06/21/2018		
<b>TECH SPEC NO:</b>	18TOYTACOMA	2018 Toyota Tacoma		<b>UNIT SERIAL NO:</b>	5TFAX5GN8JX123939		

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

**JOB COUNT: 1**      **WORK ORDER TOTAL:**      **0.50**      **28.75**      **0.00**      **0.00**      **28.75**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11074414	06/26/2018 08:03:39	06/26/2018 08:33:39	0.50	\$28.75
					<b>LABOR</b>	<b>28.75</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 30099

---

**Work Order Notes**

(LISAPATE) NEW UNIT DO PDI

---

**Job Notes**

**PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION**

(LISAPATE) PDI COMPLETED

---

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 30897

USING DEPT NO:	504241	OPENED DATE:	09/21/2018 08:45:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/25/2018 09:25:38	METER 1 - M:	817	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/25/2018 09:25:39	IN-SERVICE DATE:	06/21/2018	
TECH SPEC NO:	18TOYTACOMA	2018 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8JX123939	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	1.00	\$0.00	\$850.00	\$0.00	\$850.00

<b>JOB COUNT: 1</b>	<b>WORK ORDER TOTAL:</b>					<b>1.00</b>	<b>0.00</b>	<b>850.00</b>	<b>0.00</b>	<b>850.00</b>
---------------------	--------------------------	--	--	--	--	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-044	INSTALL TOOLBOX ASSY	11268671	09/24/2018 07:00:00	09/24/2018 08:00:00	1.00	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-044	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	850.00	1	\$850.00
					<b>PARTS</b>	<b>850.00</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 30897

---

**Work Order Notes**

(LISAPATE) Install tool box per Scott Matherson special ordered from Alabama Ladder- Low tire light on

---

**Job Notes**

**14-78-044 - INSTALL TOOLBOX ASSY**

(LISAPATE) Installed tool box and added air to all tires. Tires hold 32 they were all low 28-29psi

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 33819

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 08/22/2019 13:34:51	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/29/2019 15:06:59	<b>METER 1 - M:</b> 3507 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/29/2019 15:06:59	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA 2018 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
16-52	TRANSPORT ELECTRICAL ACCESSORI	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
17-52-028	RECALL Pre-Collision System (PCS)	DON	R	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.82	\$0.00	\$27.67	\$0.00	\$27.67

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>1.82</b>	<b>0.00</b>	<b>27.67</b>	<b>0.00</b>	<b>27.67</b>
---------------------	--------------------------	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
17-52-028	RECALL Pre-Collision System (PCS)	11076422	6049378		\$0.00
				<b>COMML</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-52	TRANSPORT ELECTRICAL ACCESSORIES	11074414	08/28/2019 06:00:00	08/28/2019 07:00:00	1.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/23/2019 08:17:35	08/23/2019 09:07:04	0.82	\$0.00
					<b>LABOR</b>	<b>0.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	7	\$27.23
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	(7)	(\$27.23)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
					<b>PARTS</b>	<b>27.67</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 33819

---

## Work Order Notes

(LISAPATE) PM

(LISAPATE) Take to Tuscaloosa Toyota for Special Service Campaign-Millimeter Wave Radar Sensor

---

## Job Notes

### **16-52 - TRANSPORT ELECTRICAL ACCESSORIES**

(LISAPATE) Taken to Toyota by SH

### **17-52-028 - RECALL Pre-Collision System (PCS)**

(LISAPATE) Toyota completed recall on pres collision system

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW,EK/AG

Coolant -25'

---

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 35559

USING DEPT NO:	504241	OPENED DATE:	02/03/2020 13:14:47	LOCATION:	GARAGE - University Automotive Services		
WO STATUS:	CLOSED	COMPLETED DATE:	02/07/2020 08:19:32	METER 1 - M:	4254	METER 2 - H:	0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	02/07/2020 08:19:34	IN-SERVICE DATE:	06/21/2018		
TECH SPEC NO:	18TOYTACOMA	2018 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8JX123939		

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.94	\$0.00	\$139.38	\$0.00	\$139.38
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	1.10	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.80	\$0.00	\$27.58	\$0.00	\$27.58
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.30	\$0.00	\$9.06	\$0.00	\$9.06

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>3.14</b>	<b>0.00</b>	<b>176.02</b>	<b>0.00</b>	<b>176.02</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/04/2020 08:06:22	02/04/2020 08:33:58	0.46	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/04/2020 08:11:17	02/04/2020 08:31:54	0.34	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	02/03/2020 14:47:58	02/03/2020 15:44:18	0.94	\$0.00
66-79-002	PERFORM SERVICE CALL	11901357	02/03/2020 13:26:34	02/03/2020 14:32:20	1.10	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	02/04/2020 07:00:00	02/04/2020 07:18:00	0.30	\$0.00

**LABOR 0.00**

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	136.56	1	\$136.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	2.01	1	\$2.01
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.30	2	\$0.60
66-17-028	PERFORM MOUNT AND BALANCE TIRES	22201	VALVE STEM TR413	0.21	1	\$0.21
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	9.06	1	\$9.06
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.24	1	\$4.24

**PARTS 176.02**

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 35559

---

## Work Order Notes

(EKIMBREL) Service call; passenger front tire flat

---

## Job Notes

### **66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(LISAPATE) Replaced RF tire with the spare tire. Removed and installed new tire onto the rim. Aired and torqued to spec. Both tires were balanced

### **66-79-002 - PERFORM SERVICE CALL**

(LISAPATE) Service call completed aired up and drove to the shop

### **66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) PM by JW/SH  
coolant -34'

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(LISAPATE) Replaced cabin filter

---



# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 37542

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 09/09/2020 11:12:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 09/11/2020 14:43:24	<b>METER 1 - M:</b> 5194 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 09/11/2020 14:43:30	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA 2018 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 1** **WORK ORDER TOTAL: 0.33 0.00 0.00 0.00 0.00**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11915538	09/09/2020 14:46:12	09/09/2020 15:06:00	0.33	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11915538	09/09/2020 14:46:12	09/09/2020 14:46:34	(0.01)	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11915538	09/09/2020 14:46:12	09/09/2020 14:46:34	0.01	\$0.00
					<b>LABOR</b>	<b>0.00</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 37542

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**66-PM-PMA - PERFORM OIL CHANGE**

(LISAPATE) Did not drop oil only been 940 miles Checked fluids, battery and tire pressures. all good  
Coolant -34'

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 39067

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 02/10/2021 07:27:15	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/19/2021 11:01:59	<b>METER 1 - M:</b> 5889 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/19/2021 14:15:29	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA 2018 Toyota Tacoma		<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-34-002	INSTALL LAMPS-REAR, TAIL, STOP, TURN	DON	O	N	GARAGE	0.22	\$26.03	\$231.00	\$0.00	\$257.03
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.86	\$33.39	\$0.00	\$67.25

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.51** **59.89** **264.39** **0.00** **324.28**

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 13:00:00	02/10/2021 13:03:17	0.05	\$6.46
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 12:04:41	02/10/2021 12:04:41	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/10/2021 11:39:06	02/10/2021 11:53:02	0.23	\$27.40
14-34-002	INSTALL LAMPS-REAR, TAIL, STOP, TURN, ETC	12052187	02/17/2021 12:15:14	02/17/2021 12:28:28	0.22	\$26.03
					<b>LABOR</b>	<b>59.89</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-34-002	INSTALL LAMPS-REAR, TAIL, STOP, TURN, ETC	SHIPPING	SHIPPING AND HANDLING	15.75	1	\$15.75
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
14-34-002	INSTALL LAMPS-REAR, TAIL, STOP, TURN, ETC	TYC11-6849-70	TAIL LIGHT ASSEMBLY	215.25	1	\$215.25
					<b>PARTS</b>	<b>264.39</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 39067

---

**Work Order Notes**

(LISAPATE) PM

---

**Job Notes**

**14-34-002 - INSTALL LAMPS-REAR,TAIL,STOP,TURN,ETC**

(JWRIGHT) Installed new tail light assy on right rear. JAW

**66-PM-PMA - PERFORM OIL CHANGE**

(AGUERRA) miles: 5889 Performed PM bottom side Josh was topside, completed checklist. vacuumed, washed no fuel needed. AMG JW

---

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 40448

USING DEPT NO:	504241	OPENED DATE:	07/15/2021 13:30:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2021 15:38:24	METER 1 - M:	6574	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/20/2021 13:24:22	IN-SERVICE DATE:	06/21/2018	
TECH SPEC NO:	18TOYTACOMA	2018 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN8JX123939	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.75	\$14.67	\$0.00	\$19.42
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.18	\$21.08	\$0.00	\$0.00	\$21.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$48.68	\$0.00	\$0.00	\$48.68

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.63</b>	<b>74.51</b>	<b>14.67</b>	<b>0.00</b>	<b>89.18</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	07/16/2021 08:56:13	07/16/2021 09:06:56	0.18	\$21.08
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/16/2021 08:14:05	07/16/2021 08:16:30	0.04	\$4.75
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/16/2021 07:34:23	07/16/2021 07:59:08	0.41	\$48.68
					<b>LABOR</b>	<b>74.51</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.34	2	\$14.67
					<b>PARTS</b>	<b>14.67</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 40448

---

## Work Order Notes

(LISAPATE) PM

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

### **66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION**

(SHARBIN) Rotated tires inspected brakes washed and filled with gas. SH

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Mileage 6574. Vehicle has been driven 685 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

---

# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 41833

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 12/09/2021 09:50:14	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 12/10/2021 13:40:50	<b>METER 1 - M:</b> 7248 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 12/13/2021 13:26:12	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA      2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.21	\$15.18	\$0.00	\$18.39
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.53	\$62.34	\$31.49	\$0.00	\$93.83
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.56</b>	<b>65.55</b>	<b>46.67</b>	<b>2.00</b>	<b>114.22</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/09/2021 13:19:53	12/09/2021 13:21:31	0.03	\$3.21
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/09/2021 12:48:02	12/09/2021 13:19:44	0.53	\$62.34
<b>LABOR</b>					<b>65.55</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.58	1	\$4.58
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
<b>PARTS</b>					<b>46.67</b>	

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 41833

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(JWRIGHT) Replaced wiper blades

**66-PM-PMA - PERFORM OIL CHANGE**

(JWRIGHT) Performed pm service. Coolant -34°. JAW,SH/AMG  
MILEAGE-7248

**CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 43261

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 05/16/2022 12:49:29	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 05/18/2022 11:43:24	<b>METER 1 - M:</b> 12000 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 05/18/2022 13:43:41	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.43	\$15.18	\$0.00	\$19.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.33	\$0.00	\$0.00	\$35.33
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.34</b>	<b>39.76</b>	<b>15.18</b>	<b>2.00</b>	<b>56.94</b>
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
<b>COMML</b>					<b>2.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/17/2022 07:34:38	05/17/2022 07:36:53	0.04	\$4.43
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/17/2022 07:16:29	05/17/2022 07:34:27	0.30	\$35.33
<b>LABOR</b>					<b>39.76</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	2	\$15.18
<b>PARTS</b>					<b>15.18</b>	

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 43261

---

**Work Order Notes**

(CWIGLEY) PM-Replace Wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(HHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(HHARBIN) Vehicle has been driven 835 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 45022

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 10/18/2022 08:52:19	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/20/2022 07:55:31	<b>METER 1 - M:</b> 8771 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/20/2022 09:46:46	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.21	\$15.63	\$0.00	\$20.84
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.38	\$40.37	\$0.00	\$78.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.37**      **43.59**      **56.00**      **5.00**      **104.59**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/18/2022 15:26:50	10/18/2022 15:29:29	0.04	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/18/2022 15:07:09	10/18/2022 15:26:40	0.33	\$38.38
<b>LABOR</b>					<b>43.59</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	2	\$15.63
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.72	1	\$5.72
<b>PARTS</b>					<b>56.00</b>	

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 45022

---

**Work Order Notes**

(LISAPATE) PM-replace wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 46414

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 03/08/2023 12:32:32	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 03/09/2023 14:01:46	<b>METER 1 - M:</b> 8927 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 03/09/2023 14:29:23	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$15.64	\$0.00	\$33.34
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.37	\$43.20	\$0.00	\$0.00	\$43.20
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.10	\$11.47	\$0.00	\$0.00	\$11.47
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.48	\$56.84	\$0.00	\$0.00	\$56.84

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>1.10</b>	<b>129.21</b>	<b>15.64</b>	<b>5.00</b>	<b>149.85</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/09/2023 07:00:00	03/09/2023 07:09:00	0.15	\$17.70
WA-00	WASH COMPLETE VEHICLE	11074414	03/08/2023 14:52:13	03/08/2023 15:21:07	0.48	\$56.84
66-79-003	PERFORM SAFETY INSPECTION	11074414	03/08/2023 14:30:00	03/08/2023 14:51:58	0.37	\$43.20
66-79-003	PERFORM SAFETY INSPECTION	11074414	03/08/2023 14:25:35	03/08/2023 14:25:35	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/08/2023 14:23:37	03/08/2023 14:23:37	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/08/2023 14:09:10	03/08/2023 14:15:00	0.10	\$11.47
<b>LABOR</b>					<b>129.21</b>	

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
<b>PARTS</b>					<b>15.64</b>	

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 46414

---

## Work Order Notes

(EHANNAH) pm- replace wipers, preform SI- wash vehicle.

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(SHARBIN) Replaced the wipers. SH

### **66-79-003 - PERFORM SAFETY INSPECTION**

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH  
Front pads measure 10MM.

### **66-PM-PMA - PERFORM OIL CHANGE**

(SHARBIN) Vehicle has been driven 156 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed and vacuumed vehicle. SH

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 47806

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 08/02/2023 09:49:08	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 08/04/2023 08:18:15	<b>METER 1 - M:</b> 9063 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 08/04/2023 09:42:58	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.90	\$16.65	\$0.00	\$20.55
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$34.71	\$43.83	\$0.00	\$78.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.73	\$86.34	\$0.00	\$0.00	\$86.34

<b>JOB COUNT:</b> 4	<b>WORK ORDER TOTAL:</b>	<b>1.06</b>	<b>124.95</b>	<b>60.48</b>	<b>5.00</b>	<b>190.43</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	08/02/2023 13:21:49	08/02/2023 14:05:43	0.73	\$86.34
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/02/2023 13:19:50	08/02/2023 13:21:49	0.03	\$3.90
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/02/2023 13:02:11	08/02/2023 13:19:50	0.29	\$34.71
					<b>LABOR</b>	<b>124.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.21	1	\$6.21
					<b>PARTS</b>	<b>60.48</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 47806

---

**Work Order Notes**

(LISAPATE) PM-replace wipers-wash

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) Replaced the wipers. SH

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM. SH

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed the vehicle. SH

---



# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 49460

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 01/11/2024 15:49:07	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 01/17/2024 09:48:03	<b>METER 1 - M:</b> 9171 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 01/17/2024 14:35:53	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA      2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.09	\$10.23	\$16.66	\$0.00	\$26.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$61.52	\$26.94	\$0.00	\$88.46
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.07	\$11.79	\$0.00	\$13.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.48	\$57.13	\$0.00	\$0.00	\$57.13

<b>JOB COUNT: 5</b>	<b>WORK ORDER TOTAL:</b>	<b>1.11</b>	<b>130.95</b>	<b>55.39</b>	<b>5.00</b>	<b>191.34</b>
---------------------	--------------------------	-------------	---------------	--------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>	
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00	
					<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
WA-00	WASH COMPLETE VEHICLE	11074414	01/12/2024 10:08:18	01/12/2024 10:37:21	0.48	\$57.13
03-51-038	REPLACE NEW WIPER BLADES	12395904	01/12/2024 09:03:08	01/12/2024 09:08:20	0.09	\$10.23
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	01/12/2024 09:01:42	01/12/2024 09:02:45	0.02	\$2.07
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/12/2024 08:29:47	01/12/2024 09:01:04	0.52	\$61.52
					<b>LABOR</b>	<b>130.95</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	1	\$8.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
					<b>PARTS</b>	<b>55.39</b>

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 49460

---

## Work Order Notes

(EHANNAH) pm- wipers- wash

---

## Job Notes

### **03-51-038 - REPLACE NEW WIPER BLADES**

(FCONTRER) Replaced new wipers fc

### **66-PM-PMA - PERFORM OIL CHANGE**

(FCONTRER) Perform fluid check fc

### **66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT**

(FCONTRER) replaced new cabin filter FC

### **CH-SP - CHARGE Shop Supplies**

### **WA-00 - WASH COMPLETE VEHICLE**

(SHARBIN) Washed and filled with gas. SH

---

# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 51088

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 06/07/2024 10:01:24	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 06/10/2024 07:08:11	<b>METER 1 - M:</b> 9331 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 06/10/2024 07:57:19	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.30	\$0.00	\$48.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

**JOB COUNT: 3**      **WORK ORDER TOTAL:**      **0.00**      **0.00**      **48.30**      **5.00**      **53.30**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
<b>PARTS</b>						<b>48.30</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 51088

---

**Work Order Notes**

(EHANNAH) pm- wipers - wash  
(EKIMBREL) did not need wipers

---

**Job Notes**

**03-51-038 - REPLACE NEW WIPER BLADES**

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) Performed PM-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.  
Note: Tires are out of date but not dry rotted and Issac said to let them go one more time.-GC  
Miles, 9,331

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

(GARAGE) Washed vehicle-SH

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 52607

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 10/28/2024 07:23:28	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/28/2024 08:48:20	<b>METER 1 - M:</b> 9438 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/29/2024 07:11:10	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.02	\$1.90	\$0.00	\$0.00	\$1.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$1.90	\$1.90

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.02** **1.90** **0.00** **1.90** **3.80**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$1.90
<b>COMML</b>					<b>1.90</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-79-002	PERFORM SERVICE CALL	11399745	10/28/2024 08:46:30	10/28/2024 08:47:28	0.02	\$1.90
<b>LABOR</b>						<b>1.90</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 52607

---

**Work Order Notes**

(EHOWELL) Service Call for dead battery- pm needed after. See WO# 52611.

(EHOWELL)

(EHOWELL)

---

**Job Notes**

**06-32-002 - INSPECT BATTERY**

**66-79-002 - PERFORM SERVICE CALL**

(GARAGE) Jumped vehicle off an brought it back to the shop. CW/RC

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242716      **2018 TOYOTA TACOMA**      **WORK ORDER NO:** 52611

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 10/28/2024 08:48:45	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 10/28/2024 16:13:35	<b>METER 1 - M:</b> 9438 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 10/29/2024 07:08:11	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA      2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$203.99	\$0.00	\$203.99
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 3</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>203.99</b>	<b>5.00</b>	<b>208.99</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
<b>COMML</b>					<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F-3	BATTERY	203.99	1	\$203.99
<b>PARTS</b>						<b>203.99</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 52611

---

## Work Order Notes

(EHOWELL) FJ- All 4 tires have date codes of 10/18.

---

## Job Notes

### **03-32-002 - REPLACE NEW BATTERY**

(EHOWELL) FJ- Replaced battery. Tested @ 12.38v , and 318 out of 582 CCA.

AFTER replacement: new battery tested at 12.55v, & 753 out of 650 CCA.

(EHOWELL) Charging .15 HR because we performed a service call for a dead battery.

### **66-PM-PMA - PERFORM OIL CHANGE**

(EHOWELL) FJ- Vehicle driven 106 miles since last service.

### **CH-SP - CHARGE Shop Supplies**

---



# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 52657

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 10/31/2024 07:59:33	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 11/07/2024 11:24:52	<b>METER 1 - M:</b> 9438 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 11/07/2024 13:41:57	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$712.80	\$0.00	\$712.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

<b>JOB COUNT: 4</b>	<b>WORK ORDER TOTAL:</b>	<b>0.00</b>	<b>0.00</b>	<b>712.80</b>	<b>5.00</b>	<b>717.80</b>
---------------------	--------------------------	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				<b>COMML</b>	<b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	173.63	4	\$694.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.58	4	\$18.30
					<b>PARTS</b>	<b>712.80</b>

# Work Order Charge Detail

UNIT NO: 242716 2018 TOYOTA TACOMA

WORK ORDER NO: 52657

---

Work Order Notes

Job Notes

**06-15 - INSPECT STEERING**

(GARAGE) INSPECTED STEERING CHECKED OK, CQ

**66-17-013 - PERFORM ALIGNMENT**

(GARAGE) PERFORMED ALIGNMENT EH

**66-17-028 - PERFORM MOUNT AND BALANCE TIRES**

(GARAGE) ghdf

(GARAGE) pulled truck on lift and removed tires. removed tires from rims and installed new tpms kits, installed new tires and inflated to 32 pounds. balanced tires and installed and torqued lug nuts to 83 pounds. CQ

**CH-SP - CHARGE Shop Supplies**

---

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 53651

<b>USING DEPT NO:</b> 504241	<b>OPENED DATE:</b> 02/06/2025 10:15:56	<b>LOCATION:</b> GARAGE - University Automotive Services
<b>WO STATUS:</b> CLOSED	<b>COMPLETED DATE:</b> 02/10/2025 09:17:26	<b>METER 1 - M:</b> 9438 <b>METER 2 - H:</b> 0
<b>WO VISIT REASON:</b> SCHEDULED	<b>CLOSED DATE:</b> 02/10/2025 10:10:39	<b>IN-SERVICE DATE:</b> 06/21/2018
<b>TECH SPEC NO:</b> 18TOYTACOMA	2018 Toyota Tacoma	<b>UNIT SERIAL NO:</b> 5TFAX5GN8JX123939

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.06	\$7.64	\$0.00	\$0.00	\$7.64

**JOB COUNT: 2** **WORK ORDER TOTAL:** **0.06** **7.64** **0.00** **5.00** **12.64**

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
					<b>COMML</b> <b>5.00</b>

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DISPOSAL	11399745	02/10/2025 09:12:08	02/10/2025 09:15:48	0.06	\$7.64
					<b>LABOR</b>	<b>7.64</b>

# Work Order Charge Detail

**UNIT NO:** 242716 2018 TOYOTA TACOMA

**WORK ORDER NO:** 53651

---

**Work Order Notes**

(EHANNAH) prep for sale

---

**Job Notes**

CH-SP - CHARGE Shop Supplies

**PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL**

(GARAGE) Removed wordmarks. Removed tag S1859C. Removed RFID. Removed all paperwork. No GPS. Told Denise to contact Michael S about the contents left in the tool box. CW/RC

---

# Work Order Charge Detail

# Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Sat Feb 15 2025 10:58:09 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

## Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and({view\_udc\_main.unit\_no\_alt} = 'S1859C') //Q=