

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26257

USING DEPT NO:	504241	OPENED DATE:	04/28/2017 14:24:01	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/03/2017 10:03:16	METER 1 - M:	114	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/03/2017 10:03:18	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11792814	04/28/2017 14:29:01	04/28/2017 14:59:01	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26257

Work Order Notes

(LISAPATE) NEW UNIT DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26531

USING DEPT NO:	504241	OPENED DATE:	06/06/2017 07:14:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/16/2017 10:32:08	METER 1 - M:	337	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/16/2017 10:32:16	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-24	WARRANTY DRIVE SHAFTS	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-24	WARRANTY DRIVE SHAFTS	2727147	475549	0038803	\$0.00
COMML					0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26531

Work Order Notes

(LISAPATE) TRUCK IS HESITATING WHEN TAKING OFF. TAKE TO REINHARDT MOTORS, INC. DELIVERING DEALER

Job Notes

15-24 - WARRANTY DRIVE SHAFTS

(LISAPATE) PER REINHARDT MOTORS INVOICE. C/S TRUCK WIL HESITATE WHEN TAKING OFF. DAN IN SALES IN THE LANE SAID JOEY HELPED HIM VERIFY THE CONCERN. CHECK AND ADVISE.

FOUND DRIVE SHAFT CAUSING VIBRATION

TEST DROVE TO VERIFY CONCERN, HARSH VIBRATION ON ACCLERATION FROM A STOP

CONTACT TA# 171350638 WAS ADVISED TO CHANGE DRIVE SHAFT WITH ANOTH VEHICLE. VIBRATION WAS GINE. SWAPPED PARTS BACK AROUND AND ORDERED DRIVE SHAT. INSTALLED NEW DRIVE SSHAFT AND VERIFIED REPAIR NO VIBRATION FELT.

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26813

USING DEPT NO:	504241	OPENED DATE:	07/11/2017 13:45:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2017 13:31:50	METER 1 - M:	875	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2017 13:31:52	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
15-03-010	WARRANTY CLUSTER ASSY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
15-27	WARRANTY TRANSMISSION - MAIN, AL	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-27	TRANSPORT TRANSMISSION - MAIN, A	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50

JOB COUNT: 3	WORK ORDER TOTAL:	1.00	57.50	0.00	0.00	57.50
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
15-27	WARRANTY TRANSMISSION - MAIN, AUTOMATIC	11076422	TOCS770025	0039477	\$0.00
COMML					0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-27	TRANSPORT TRANSMISSION - MAIN, AUTOMATIC	11792814	08/07/2017 07:00:00	08/07/2017 08:00:00	1.00	\$57.50
LABOR						57.50

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 26813

Work Order Notes

(LISAPATE) PER DRIVER TRUCK IS NOT SHIFT RIGHT WHEN COLD GETS BETTER AFTER IT WARMS UP-ALSO SPEEDOMETER STUCK AT 20MPH MOST OF THE TIME

Job Notes

15-03-010 - WARRANTY CLUSTER ASSY

(LISAPATE) TOYOTA REPLACED CLUSTER.

15-27 - WARRANTY TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) TOYOTA OPENED TECH CASE CHECKED FOR CODES AND ADJUSTED FLUID LEVELS. RESET MEMORY

16-27 - TRANSPORT TRANSMISSION - MAIN, AUTOMATIC

(LISAPATE) TAKEN TO TOYOTA BY TB

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 27977

USING DEPT NO:	504241	OPENED DATE:	10/27/2017 15:12:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2017 06:48:22	METER 1 - M:	1715	METER 2 - H: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/30/2017 06:48:24	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$21.18	\$0.00	\$39.01

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	21.18	0.00	39.01
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/30/2017 14:31:42	10/31/2017 07:17:30	(16.76)	(\$963.89)
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/30/2017 14:31:42	10/31/2017 07:17:30	16.76	\$963.89
66-PM-PMA	PERFORM OIL CHANGE	11758845	10/27/2017 15:13:25	10/27/2017 15:32:01	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.50	1	\$4.50
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	6	\$16.68
					PARTS	21.18

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 27977

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 31302

USING DEPT NO:	504241	OPENED DATE:	10/26/2018 10:08:41	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/31/2018 06:54:00	METER 1 - M:	4504	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/31/2018 06:54:01	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.27	\$0.00	\$27.73	\$0.00	\$27.73

JOB COUNT: 1	WORK ORDER TOTAL:					1.27	0.00	27.73	0.00	27.73
---------------------	--------------------------	--	--	--	--	-------------	-------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/26/2018 10:17:26	10/26/2018 11:33:42	1.27	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.39	1	\$4.39
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
					PARTS	27.73

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 31302

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI) PM by SH

Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 31365

USING DEPT NO:	504241	OPENED DATE:	11/01/2018 08:53:38	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/06/2018 06:33:25	METER 1 - M:	4555	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/06/2018 06:33:27	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-01	TRANSPORT AIR CONDITIONING, HEAT	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
17-01-004	RECALL BLOWER MOTOR	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
17-01-004	RECALL BLOWER MOTOR	11076422	6013678	0045721	\$0.00
				COMML	0.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-01	TRANSPORT AIR CONDITIONING, HEAT, VENT	10208562	11/02/2018 07:00:00	11/02/2018 08:00:00	1.00	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: **242286** **2017 TOYOTA TACOMA**

WORK ORDER NO: **31365**

Work Order Notes

(LISAPATE) Recall from Toyota for possibility that the blower motor fan hub may crack

Job Notes

16-01 - TRANSPORT AIR CONDITIONING, HEAT, VENT

(LISAPATE) Taken to Toyota by EK

17-01-004 - RECALL BLOWER MOTOR

(LISAPATE) Toyota completed recall installed new blower motor

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 33811

USING DEPT NO:	504241	OPENED DATE:	08/22/2019 09:32:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/23/2019 13:25:14	METER 1 - M:	6502	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/23/2019 13:25:15	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.52	\$0.00	\$31.88	\$0.00	\$31.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.12	\$0.00	\$9.06	\$0.00	\$9.06

JOB COUNT: 2	WORK ORDER TOTAL:	0.64	0.00	40.94	0.00	40.94
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/22/2019 09:53:15	08/22/2019 10:03:37	0.17	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12052187	08/22/2019 10:03:37	08/22/2019 10:11:05	0.12	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	08/22/2019 10:11:05	08/22/2019 10:31:43	0.34	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800038C	CABIN AIR FILTER REP 4871	9.06	1	\$9.06
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	40.94

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 33811

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW/AG

Coolant -34'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 34023

USING DEPT NO:	504241	OPENED DATE:	09/09/2019 11:30:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/11/2019 10:34:58	METER 1 - M:	6619	METER 2 - H: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	09/11/2019 10:35:00	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
15-32-002	WARRANTY BATTERY	DON	W	J	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
16-32	TRANSPORT CRANKING SYSTEM	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	0.00	0.00	0.00	0.00
---------------------	--------------------------	--	--	--	--	-------------	-------------	-------------	-------------	-------------

<u>Job Code</u>	<u>Job Description</u>	<u>Vendor No.</u>	<u>Invoice No.</u>	<u>Purchase Order No.</u>	<u>Total Cost</u>
15-32-002	WARRANTY BATTERY	11076422	6051333		\$0.00
COMML					0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-32	TRANSPORT CRANKING SYSTEM	11915538	09/10/2019 07:00:00	09/10/2019 08:00:00	1.00	\$0.00
LABOR						0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 34023

Work Order Notes

(LISAPATE) Tyler requested a service call to BPCC truck turns over wont start
(LISAPATE) Tyler got the truck started and brought to us service call was not done

Job Notes

15-32-002 - WARRANTY BATTERY

(LISAPATE) Took to Tuscaloosa Toyota they verified a bad battery removed and installed a new battery

16-32 - TRANSPORT CRANKING SYSTEM

(LISAPATE) Taken to Toyota by RC

66-79-002 - PERFORM SERVICE CALL

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 35576

USING DEPT NO:	504241	OPENED DATE:	02/04/2020 14:14:29	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2020 07:25:11	METER 1 - M:	7283	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/20/2020 07:25:13	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	1.39	\$0.00	\$17.06	\$0.00	\$17.06
14-78-044	INSTALL TOOLBOX ASSY	DON	O	N	GARAGE	1.04	\$0.00	\$899.00	\$0.00	\$899.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$0.00	\$27.58	\$0.00	\$27.58

JOB COUNT: 3	WORK ORDER TOTAL:	2.63	0.00	943.64	0.00	943.64
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	02/05/2020 09:44:17	02/05/2020 11:07:36	1.39	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/05/2020 11:12:44	02/05/2020 11:24:38	0.20	\$0.00
14-78-044	INSTALL TOOLBOX ASSY	11901357	02/13/2020 07:00:00	02/13/2020 07:30:00	0.50	\$0.00
14-78-044	INSTALL TOOLBOX ASSY	11901357	02/18/2020 11:21:21	02/18/2020 11:53:41	0.54	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	4.24	1	\$4.24
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
14-78-044	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	899.00	1	\$899.00
14-78-044	INSTALL TOOLBOX ASSY	131501	SADDLE BOX ALMN 66IN LOPROBLK	899.00	(1)	(\$899.00)
14-78-044	INSTALL TOOLBOX ASSY	131001	LOPRO 66IN ALUM TOOLBOX WG	899.00	1	\$899.00
14-78-044	INSTALL TOOLBOX ASSY	CAMS71LPMBLK	TOOLBOX XOVER LP MN LOWPROFILE	660.00	(1)	(\$660.00)
14-78-044	INSTALL TOOLBOX ASSY	CAMS71LPMBLK	TOOLBOX XOVER LP MN LOWPROFILE	660.00	1	\$660.00
03-51-038	REPLACE NEW WIPER BLADES	WW-2200-PC	WIPER BLADE 22"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2000-PC	WIPER BLADE 20"	8.53	1	\$8.53
					PARTS	943.64

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 35576

Work Order Notes

(LISAPATE) PM-Install a new toolbox

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(EKIMBREL) AG replaced both wiper blades.

14-78-044 - INSTALL TOOLBOX ASSY

(EKIMBREL) AG/AB installed toolbox on bed of truck, checked for proper operation. All good.

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) EK/AG. Coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 37671

USING DEPT NO:	504241	OPENED DATE:	09/21/2020 11:54:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2020 12:21:43	METER 1 - M:	8042	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2020 13:24:56	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.32	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/21/2020 15:20:12	09/21/2020 15:39:41	0.32	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: **242286** **2017 TOYOTA TACOMA**

WORK ORDER NO: **37671**

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Vehicle has only been 759 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist . Scott assisted. AMG SH Coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 39072

USING DEPT NO:	504241	OPENED DATE:	02/10/2021 08:36:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/17/2021 10:11:41	METER 1 - M:	8462	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/17/2021 12:26:08	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.48	\$56.08	\$0.00	\$0.00	\$56.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.87	\$103.09	\$33.39	\$0.00	\$136.48

JOB COUNT: 2 WORK ORDER TOTAL: 1.35 159.17 33.39 0.00 192.56

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/10/2021 13:57:30	02/10/2021 14:15:00	0.29	\$34.42
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/10/2021 14:30:00	02/10/2021 14:32:48	0.05	\$5.51
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 14:01:06	02/10/2021 14:15:00	0.23	\$27.34
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 14:30:00	02/10/2021 14:44:02	0.23	\$27.60
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	02/10/2021 15:00:26	02/10/2021 15:28:57	0.48	\$56.08
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/10/2021 15:29:17	02/10/2021 15:33:28	0.07	\$8.23
					LABOR	159.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.48	1	\$6.48
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
					PARTS	33.39

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 39072

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 8462 Completed PM bottom side, Josh was top side. Completed checklist, vacuumed out vehicle, unable to wash, wash bay under repair, no fuel needed.
AMG JW

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 40183

USING DEPT NO:	504241	OPENED DATE:	06/15/2021 11:28:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/22/2021 07:42:31	METER 1 - M:	8647	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/22/2021 07:42:35	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.09	\$10.42	\$113.55	\$0.00	\$123.97

JOB COUNT: 1	WORK ORDER TOTAL:					0.09	10.42	113.55	0.00	123.97
---------------------	--------------------------	--	--	--	--	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	11170580	06/15/2021 11:49:12	06/15/2021 11:54:30	0.09	\$10.42
					LABOR	10.42

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	113.55	1	\$113.55
					PARTS	113.55

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 40183

Work Order Notes

(LISAPATE) Per driver truck is slow to crank

Job Notes

03-32-002 - REPLACE NEW BATTERY

(ABLACK) AB tested battery and it was bad. Installed a new battery rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 40497

USING DEPT NO:	504241	OPENED DATE:	07/21/2021 10:28:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/27/2021 07:33:13	METER 1 - M:	8826	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/27/2021 15:41:32	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$23.60	\$14.66	\$0.00	\$38.26
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.07	\$8.46	\$0.00	\$0.00	\$8.46

JOB COUNT: 2	WORK ORDER TOTAL:	0.27	32.06	14.66	0.00	46.72
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2021 13:41:59	07/21/2021 13:53:59	0.20	\$23.60
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2021 13:41:59	07/21/2021 13:42:22	0.01	\$0.75
03-51-038	REPLACE NEW WIPER BLADES	11074414	07/21/2021 13:41:59	07/21/2021 13:42:22	(0.01)	(\$0.75)
66-PM-PMA	PERFORM OIL CHANGE	11074414	07/21/2021 13:37:27	07/21/2021 13:41:45	0.07	\$8.46
					LABOR	32.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.33	1	\$7.33
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.33	1	\$7.33
					PARTS	14.66

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 40497

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 8826. Vehicle has been driven 364 miles since last PM. Checked fluids battery tire pressure and updated oil change sticker. SH EH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 41800

USING DEPT NO:	504241	OPENED DATE:	12/06/2021 09:06:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/07/2021 11:18:34	METER 1 - M:	9423	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/07/2021 14:00:20	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.30	\$34.97	\$15.18	\$0.00	\$50.15
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.42	\$49.30	\$35.36	\$0.00	\$84.66
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.71	84.27	50.54	2.00	136.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	12/06/2021 13:51:45	12/06/2021 13:56:36	0.08	\$9.54
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/06/2021 13:34:46	12/06/2021 13:54:59	0.34	\$39.76
03-51-038	REPLACE NEW WIPER BLADES	12052187	12/06/2021 13:33:48	12/06/2021 13:51:35	0.30	\$34.97
				LABOR		84.27

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	FL910S	FILTER-OIL	8.45	1	\$8.45
				PARTS		50.54

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 41800

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(JWRIGHT) Replaced wiper blades

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW,AMG/SH
MILEAGE-9423

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 43285

USING DEPT NO:	504241	OPENED DATE:	05/17/2022 14:38:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2022 15:23:14	METER 1 - M:	9905	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2022 13:59:23	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.13	\$15.18	\$0.00	\$17.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.20	\$23.63	\$0.00	\$0.00	\$23.63
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.22	25.76	15.18	2.00	42.94
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/18/2022 07:58:06	05/18/2022 07:59:11	0.02	\$2.13
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2022 07:45:42	05/18/2022 07:57:43	0.20	\$23.63
					LABOR	25.76

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
					PARTS	15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 43285

Work Order Notes

(CWIGLEY) PM-Replace Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) RC Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 482 miles since the last PM. RC Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 43825

USING DEPT NO:	504241	OPENED DATE:	07/05/2022 09:21:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/07/2022 13:55:29	METER 1 - M:	9999	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/11/2022 10:03:30	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-78-031	INSTALL TONNEAU/BED COVER	DON	O	N	GARAGE	1.15	\$135.80	\$1,087.50	\$0.00	\$1,223.30
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.15	135.80	1,087.50	2.00	1,225.30
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-78-031	INSTALL TONNEAU/BED COVER	12052187	07/05/2022 14:28:16	07/05/2022 15:37:19	1.15	\$135.80
					LABOR	135.80

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-78-031	INSTALL TONNEAU/BED COVER	0001635187	TRI-FOLD TONNEAU RIGID 5FT	1087.50	1	\$1,087.50
					PARTS	1087.50

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 43825

Work Order Notes

(LISAPATE) Dept requested install a tonneau cover

Job Notes

14-78-031 - INSTALL TONNEAU/BED COVER

(JWRIGHT) Removed toolbox and installed tonneau cover. JAW
1 HR labor

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 45009

USING DEPT NO:	504241	OPENED DATE:	10/17/2022 12:50:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/24/2022 15:01:47	METER 1 - M:	10498	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2022 07:53:00	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.06	\$6.79	\$0.00	\$0.00	\$6.79
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	1.34	\$158.55	\$0.00	\$0.00	\$158.55
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.79	\$211.19	\$662.85	\$0.00	\$874.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.43	\$50.28	\$74.59	\$0.00	\$124.87
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.08	\$9.41	\$14.58	\$0.00	\$23.99
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	3.70	436.22	752.02	5.00	1,193.24
--------------	-------------------	------	--------	--------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	10/20/2022 07:06:33	10/20/2022 08:31:57	1.42	\$167.95
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	10/19/2022 15:19:23	10/19/2022 15:41:22	0.37	\$43.23
06-15	INSPECT STEERING	11901357	10/19/2022 14:11:33	10/19/2022 14:15:00	0.06	\$6.79
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/18/2022 08:44:11	10/18/2022 09:09:45	0.43	\$50.28
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/18/2022 09:10:13	10/18/2022 09:15:00	0.08	\$9.41
66-17-013	PERFORM ALIGNMENT	12296277	10/20/2022 10:39:23	10/20/2022 12:00:00	1.34	\$158.55
				LABOR		436.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	14.58	1	\$14.58
66-PM-PMA	PERFORM OIL CHANGE	49155	AIR FILTER	26.39	1	\$26.39
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	5.69	1	\$5.69
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.90	4	\$23.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.32	1	\$0.32
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	1	\$0.57
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58106	1.75 OZ WHEEL WEIGHT	0.81	1	\$0.81
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58107	WHEEL WEIGHT PFE 2.00	0.89	1	\$0.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	163.04	4	\$652.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	163.04	(4)	(\$652.14)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	159.11	4	\$636.42
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	159.11	(4)	(\$636.42)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	002761	TIRE LT245/75R16 FS TRANSF HT2	159.11	4	\$636.42
					PARTS	752.02

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 45009

Work Order Notes

(CWIGLEY) PM

Job Notes

06-15 - INSPECT STEERING

(AGUERRA) Inspected steering, no issues found. AMG

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment no issues present jdm

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(AGUERRA) Replaced and balanced 4 tires. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 10498 Completed PM topside, Chad assisted, Scott was bottomsides. AMG CW/SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Chad replaced cabin filter. CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 46421

USING DEPT NO:	504241	OPENED DATE:	03/09/2023 08:39:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/09/2023 13:49:04	METER 1 - M:	10910	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/09/2023 14:33:12	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.49	\$15.64	\$0.00	\$18.13
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.13	\$14.95	\$0.00	\$0.00	\$14.95
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.14	\$15.93	\$0.00	\$0.00	\$15.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.13	\$15.11	\$0.00	\$0.00	\$15.11

JOB COUNT: 5	WORK ORDER TOTAL:	0.41	48.48	15.64	5.00	69.12
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	12201267	03/09/2023 09:35:15	03/09/2023 09:42:51	0.13	\$14.95
WA-00	WASH COMPLETE VEHICLE	12201267	03/09/2023 09:07:19	03/09/2023 09:15:00	0.13	\$15.11
03-51-038	REPLACE NEW WIPER BLADES	12201267	03/09/2023 09:05:47	03/09/2023 09:07:03	0.02	\$2.49
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/09/2023 08:57:12	03/09/2023 09:05:18	0.14	\$15.93
				LABOR		48.48

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
					PARTS	15.64

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 46421

Work Order Notes

(EHANNAH) pm- replace wipers- preform SI- wash vehicle

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-JW

66-79-003 - PERFORM SAFETY INSPECTION

(GRCOOK) Performed safety inspection-GC, Found no issues at this time

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- GC, Fluid check only, filters good, tires and tire pressure
Miles, 10,910

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Performed wash vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 47799

USING DEPT NO:	504241	OPENED DATE:	08/01/2023 13:42:16	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/04/2023 08:22:26	METER 1 - M:	11849	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/04/2023 09:42:24	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.18	\$20.98	\$16.64	\$0.00	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$39.86	\$43.85	\$0.00	\$83.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.52	60.84	60.49	5.00	126.33
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/02/2023 08:13:57	08/02/2023 08:24:37	0.18	\$20.98
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/02/2023 07:53:41	08/02/2023 08:13:57	0.34	\$39.86
				LABOR		60.84

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	8.33	1	\$8.33
03-51-038	REPLACE NEW WIPER BLADES	21-1	21" WIPER	7.74	(1)	(\$7.74)
03-51-038	REPLACE NEW WIPER BLADES	21-1	21" WIPER	7.74	1	\$7.74
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.31	1	\$8.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.23	1	\$6.23
					PARTS	60.49

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 47799

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers SH

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Wash bay closed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 49437

USING DEPT NO:	504241	OPENED DATE:	01/10/2024 10:01:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/24/2024 15:17:03	METER 1 - M:	13079	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/25/2024 07:05:08	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.05	\$0.00	\$0.00	\$40.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$34.38	\$0.00	\$0.00	\$34.38

JOB COUNT: 3	WORK ORDER TOTAL:	0.63	74.43	0.00	5.00	79.43
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	01/11/2024 08:57:31	01/11/2024 09:15:00	0.29	\$34.38
66-PM-PMA	PERFORM OIL CHANGE	12201267	01/11/2024 08:36:53	01/11/2024 08:57:15	0.34	\$40.05
LABOR						74.43

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 49437

Work Order Notes

(EHANNAH) pm- wipers- wash
(EKIMBREL) did not need wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC, Fluid check only, vehicle driven 1,230 miles, fluids good, filters good, tires and tire pressure, updated oil change sticker.
Miles, 13,079

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 51091

USING DEPT NO:	504241	OPENED DATE:	06/07/2024 10:46:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/07/2024 13:21:57	METER 1 - M:	13902	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/10/2024 08:07:19	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.01	\$1.18	\$22.13	\$0.00	\$23.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.21	\$48.30	\$0.00	\$49.51
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$0.98	\$0.00	\$0.00	\$0.98

JOB COUNT: 4	WORK ORDER TOTAL:	0.03	3.37	70.43	5.00	78.80
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/07/2024 11:10:58	06/07/2024 11:11:35	0.01	\$1.21
03-51-038	REPLACE NEW WIPER BLADES	11074414	06/07/2024 11:11:35	06/07/2024 11:12:11	0.01	\$1.18
WA-00	WASH COMPLETE VEHICLE	11074414	06/07/2024 11:12:11	06/07/2024 11:12:41	0.01	\$0.98
				LABOR		3.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
03-51-038	REPLACE NEW WIPER BLADES	XC22	22" WIPER	11.25	1	\$11.25
					PARTS	70.43

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 51091

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) Replaced the wipers. SH FC

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FC Washed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 52586

USING DEPT NO:	504241	OPENED DATE:	10/24/2024 10:49:59	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2024 09:45:50	METER 1 - M:	15007	METER 2 - H:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2024 11:53:24	IN-SERVICE DATE:	04/27/2017				
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681				

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.39	\$0.00	\$48.39
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$24.18	\$0.00	\$24.18
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	72.57	5.00	77.57
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.99	6	\$41.94
66-PM-PMA	PERFORM OIL CHANGE	BT223	OIL FILTER	6.45	1	\$6.45
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	24.18	1	\$24.18
PARTS						72.57

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 52586

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-79-003 - PERFORM SAFETY INSPECTION

(IFALLS) FJ performed safety inspection

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked fluids, checked tires and tire pressures

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) JR- changed cabin air filter

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 53649

USING DEPT NO:	504241	OPENED DATE:	02/06/2025 10:13:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/13/2025 08:40:10	METER 1 - M:	15759	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/14/2025 12:32:04	IN-SERVICE DATE:	04/27/2017	
TECH SPEC NO:	17TOYTACOMA	2017 Toyota Tacoma		UNIT SERIAL NO:	5TFAX5GN2HX088681	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 02/15/2025 11:11:04 By User: GLOBETTI

UNIT NO: 242286 2017 TOYOTA TACOMA

WORK ORDER NO: 53649

Work Order Notes

(EHANNAH) prep for sale

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(EKIMBREL) RC removed tag and wordmarks. no GPS

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Sat Feb 15 2025 11:11:04 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no_alt} = 'S1077C') //Q=