

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 20852

USING DEPT NO:	224107	OPENED DATE:	07/21/2015 10:29:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2015 10:58:28	METER 1 - M:	60	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2015 10:58:30	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	28.75	0.00	0.00	28.75
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11338644	07/21/2015 10:30:00	07/21/2015 11:00:00	0.50	\$28.75
					LABOR	28.75

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 20852

Work Order Notes

(LPATE) DO PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LPATE) PDI COMPLETED

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 22953

USING DEPT NO:	224107	OPENED DATE:	03/30/2016 13:19:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/31/2016 10:28:27	METER 1 - M:	5816	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/31/2016 10:28:28	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$19.66	\$0.00	\$37.49

JOB COUNT: 1	WORK ORDER TOTAL:					0.31	17.83	19.66	0.00	37.49
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	10260422	03/30/2016 13:20:08	03/30/2016 13:38:44	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	4	\$15.04
					PARTS	19.66

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 22953

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY GM

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 24292

USING DEPT NO:	224107	OPENED DATE:	09/06/2016 08:25:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/08/2016 09:11:23	METER 1 - M:	11309	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/08/2016 09:11:26	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$17.83	\$23.42	\$0.00	\$41.25

JOB COUNT: 1	WORK ORDER TOTAL:	0.31	17.83	23.42	0.00	41.25
---------------------	--------------------------	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11758845	09/07/2016 07:00:00	09/07/2016 07:18:36	0.31	\$17.83
					LABOR	17.83

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	5	\$18.80
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
					PARTS	23.42

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 24292

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS-IF/MS

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 25549

USING DEPT NO:	224107	OPENED DATE:	01/24/2017 10:20:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/25/2017 07:46:42	METER 1 - M:	16210	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	01/25/2017 07:46:44	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.15	\$8.88	\$33.45	\$0.00	\$42.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.15	\$8.77	\$4.89	\$0.00	\$13.66

JOB COUNT: 2	WORK ORDER TOTAL:	0.31	17.65	38.34	0.00	55.99
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	01/24/2017 13:08:39	01/24/2017 13:17:48	0.15	\$8.77
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/24/2017 12:59:20	01/24/2017 13:08:36	0.15	\$8.88
					LABOR	17.65

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
66-PM-PMA	PERFORM OIL CHANGE	0W20S	HAVOLINE OW20 SYNTHETIC OIL QT	3.76	5	\$18.80
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.61	1	\$4.61
					PARTS	38.34

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 25549

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH PERFORMED PM COOLANT IS GOOD TO -35

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(IFALLS) SH REPLACED CABIN FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 26881

USING DEPT NO:	224107	OPENED DATE:	07/20/2017 07:17:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/24/2017 14:27:28	METER 1 - M:	21453	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	07/24/2017 14:27:30	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.35	\$77.39	\$28.56	\$0.00	\$105.95
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$17.25	\$4.89	\$0.00	\$22.14

JOB COUNT: 2	WORK ORDER TOTAL:	1.65	94.64	33.45	0.00	128.09
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11758845	07/21/2017 09:15:00	07/21/2017 09:33:00	0.30	\$17.25
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/21/2017 09:30:00	07/21/2017 10:51:58	1.37	\$78.55
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/21/2017 09:30:00	07/21/2017 10:51:58	(1.37)	(\$78.55)
66-PM-PMA	PERFORM OIL CHANGE	11758845	07/21/2017 07:54:15	07/21/2017 09:15:00	1.35	\$77.39
					LABOR	94.64

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	5	\$13.90
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.62	1	\$4.62
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	C111	RED BRAKE CLEANER	2.12	1	\$2.12
					PARTS	33.45

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 26881

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY CS
REPLACED AIR FILTER

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) REPLACED CABIN FILTER

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 27921

USING DEPT NO:	224107	OPENED DATE:	10/24/2017 07:36:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/25/2017 11:56:13	METER 1 - M:	26440	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/25/2017 11:56:16	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.00	\$57.72	\$15.71	\$0.00	\$73.43

JOB COUNT: 1	WORK ORDER TOTAL:					1.00	57.72	15.71	0.00	73.43
---------------------	--------------------------	--	--	--	--	-------------	--------------	--------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/24/2017 10:05:29	10/24/2017 11:05:43	1.00	\$57.72
					LABOR	57.72

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.78	4	\$11.12
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.59	1	\$4.59
					PARTS	15.71

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 27921

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 10/24/2017 7:36 AM By LISAPATE

(LISAPATE) PM BY EK/SH-USED 1/2QT OF OIL ALREADY CHARGED OUT

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 28994

USING DEPT NO:	224107	OPENED DATE:	02/26/2018 08:26:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/28/2018 09:50:12	METER 1 - M:	31580	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/28/2018 09:50:13	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.63	\$36.15	\$23.35	\$0.00	\$59.50

JOB COUNT: 1	WORK ORDER TOTAL:	0.63	36.15	23.35	0.00	59.50
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/26/2018 08:37:17	02/26/2018 09:15:00	0.63	\$36.15
					LABOR	36.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	2.77	4	\$11.08
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	7.92	1	\$7.92
					PARTS	23.35

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 28994

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY AG
REPLACED AIR FILTER
COOLANT -30'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29123

USING DEPT NO:	224107	OPENED DATE:	03/20/2018 07:45:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/27/2018 15:59:03	METER 1 - M:	32169	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/27/2018 15:59:05	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$14.38	\$17.06	\$0.00	\$31.44
06-13	INSPECT BRAKES	DON	O	N	GARAGE	0.50	\$28.75	\$0.00	\$0.00	\$28.75
09-17	ALIGN TIRES, TUBES, LINERS & VALVE	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$77.61	\$77.61
16-17	TRANSPORT TIRES, TUBES, LINERS &	DON	O	N	GARAGE	1.00	\$57.50	\$0.00	\$0.00	\$57.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$23.00	\$11.97	\$0.00	\$34.97
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$177.91	\$177.91

JOB COUNT: 6	WORK ORDER TOTAL:	2.15	123.63	29.03	255.52	408.18
--------------	-------------------	------	--------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
09-17	ALIGN TIRES, TUBES, LINERS & VALVES	11122732	240770	0042669	\$77.61
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	240739	0042636	\$177.91
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	240739	0042636	(\$177.91)
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	240739	0042636	\$177.91
COMML					255.52

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11901357	03/21/2018 07:15:00	03/21/2018 07:39:00	0.40	\$23.00
16-17	TRANSPORT TIRES, TUBES, LINERS & VALVES	10208562	03/21/2018 07:00:00	03/21/2018 08:00:00	1.00	\$57.50
06-13	INSPECT BRAKES	11901357	03/21/2018 07:00:00	03/21/2018 07:30:00	0.50	\$28.75
03-51-038	REPLACE NEW WIPER BLADES	11901357	03/21/2018 07:00:00	03/21/2018 07:15:00	0.25	\$14.38
LABOR						123.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.25	3	\$0.75
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
66-17-028	PERFORM MOUNT AND BALANCE TIRES	923312	TIRE PRESSURE MONITOR	5.61	2	\$11.22

Work Order Charge Detail

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-028	PERFORM MOUNT AND BALANCE TIRES	923312	TIRE PRESSURE MONITOR	5.61	(2)	(\$11.22)
66-17-028	PERFORM MOUNT AND BALANCE TIRES	923312	TIRE PRESSURE MONITOR	5.61	2	\$11.22
					PARTS	29.03

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29123

Work Order Notes

(LISAPATE) REPLACE WIPERS-NEEDS 2 TIRES

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) REPLACED WIPERS

06-13 - INSPECT BRAKES

(LISAPATE) INSPECTED FRONT AND REAR BRAKES BOTH WERE IN GOOD CONDITION. INSPECTED FRONT END FOR WEAR ALL GOOD.

09-17 - ALIGN TIRES, TUBES, LINERS & VALVES

(LISAPATE) FIRESTONE COMPLETED ALIGNMENT. PD BY CC

16-17 - TRANSPORT TIRES, TUBES, LINERS & VALVES

(LISAPATE) TAKEN TO FIRESTONE BY EK

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNT AND BALANCED 2 NEW TIRES

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 2 TIRES FROM FIRESTONE. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29398

USING DEPT NO:	224107	OPENED DATE:	04/12/2018 10:31:43	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/16/2018 11:46:04	METER 1 - M:	32169	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/16/2018 11:46:06	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PU-78-036	PURCHASED TOUCH UP PAINT	DON	O	N	GARAGE	0.00	\$0.00	\$8.33	\$0.00	\$8.33

JOB COUNT: 1	WORK ORDER TOTAL:	0.00	0.00	8.33	0.00	8.33
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
PU-78-036	PURCHASED TOUCH UP PAINT	002580004021	WHITE TOUCH UP PAINT	8.33	1	\$8.33
					PARTS	8.33

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29398

Work Order Notes

(LISAPATE) KAREN REQUESTED TOUCH UP PAINT FOR THE CAR

Job Notes

PU-78-036 - PURCHASED TOUCH UP PAINT

(LISAPATE) GAVE KAREN A TUBE OF TOUCH UP PAINT

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29547

USING DEPT NO:	224107	OPENED DATE:	04/24/2018 10:37:11	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/02/2018 07:38:37	METER 1 - M:	32963	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2018 07:38:40	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-00	TRANSPORT COMPLETE VEHICLE	DON	O	N	GARAGE	1.50	\$86.39	\$0.00	\$0.00	\$86.39
24-71	REPAIR BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$631.35	\$631.35
AD-78-036	ADDED TOUCH UP PAINT	DON	O	N	GARAGE	0.30	\$17.25	\$0.00	\$0.00	\$17.25

JOB COUNT: 3	WORK ORDER TOTAL:	1.80	103.64	0.00	631.35	734.99
--------------	-------------------	------	--------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	166510	0043171	\$631.35
				COMML	631.35

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/27/2018 09:45:37	04/27/2018 10:28:03	0.71	\$40.67
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 13:00:00	04/26/2018 14:15:00	(1.25)	(\$71.88)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 13:00:00	04/25/2018 14:15:00	(1.25)	(\$71.88)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 10:51:22	04/25/2018 12:00:00	(1.14)	(\$65.77)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 14:30:00	04/27/2018 08:16:04	(17.77)	(\$1,021.65)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 09:30:00	04/26/2018 12:00:00	(2.50)	(\$143.75)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 14:30:00	04/26/2018 09:15:00	(18.75)	(\$1,078.13)
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 14:30:00	04/27/2018 08:16:04	17.77	\$1,021.65
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 13:00:00	04/26/2018 14:15:00	1.25	\$71.88
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/26/2018 09:30:00	04/26/2018 12:00:00	2.50	\$143.75
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 14:30:00	04/26/2018 09:15:00	18.75	\$1,078.13
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 13:00:00	04/25/2018 14:15:00	1.25	\$71.88
16-00	TRANSPORT COMPLETE VEHICLE	11915538	04/25/2018 10:51:22	04/25/2018 12:00:00	1.14	\$65.77
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/25/2018 14:30:00	04/26/2018 08:05:15	(17.59)	(\$1,011.28)
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/25/2018 13:01:39	04/25/2018 14:15:00	(1.22)	(\$70.29)
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/25/2018 14:30:00	04/26/2018 08:05:15	17.59	\$1,011.28

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/25/2018 13:01:39	04/25/2018 14:15:00	1.22	\$70.29
16-00	TRANSPORT COMPLETE VEHICLE	10208562	04/25/2018 10:27:59	04/25/2018 11:15:42	0.80	\$45.73
AD-78-036	ADDED TOUCH UP PAINT	11074414	04/27/2018 06:00:00	04/27/2018 06:18:00	0.30	\$17.25
					LABOR	103.65

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 29547

Work Order Notes

(LISAPATE) ANDREW'S TO REPAIR DINGS AND CHIPS IN PAINT ON THE HOOD PER THE ESTIMATE

Job Notes

16-00 - TRANSPORT COMPLETE VEHICLE

(LISAPATE) TAKEN TO ANDREWS BY EK

24-71 - REPAIR BODY

(LISAPATE) ANDREWS PAINTED AND REPAIRED CHIPS IN HOOD. PD BY CC

AD-78-036 - ADDED TOUCH UP PAINT

(LISAPATE) SH TOUCHED UP ADDITIONAL SPOTS ON THE BODY. PUT EXTRA TOUCH UP PAINT IN THE GLOVE BOX
(IFALLS) Per Lisa touch up paint was billed on a previous work order

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 30342

USING DEPT NO:	224107	OPENED DATE:	07/24/2018 08:29:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/25/2018 18:00:00	METER 1 - M:	35635	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/25/2018 18:00:00	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$0.00	\$5.37	\$0.00	\$5.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$0.00	\$27.76	\$0.00	\$27.76
PU-17	PURCHASED TIRES, TUBES, LINERS &	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$152.70	\$152.70

JOB COUNT: 5	WORK ORDER TOTAL:	2.21	0.00	33.13	152.70	185.83
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
PU-17	PURCHASED TIRES, TUBES, LINERS & VALVES	11122732	246156	0044328	\$152.70
				COMML	152.70

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	07/25/2018 07:00:00	07/25/2018 07:18:36	0.31	\$0.00
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11213180	07/25/2018 07:00:00	07/25/2018 07:30:00	0.50	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11758845	07/25/2018 07:00:00	07/25/2018 07:24:00	0.40	\$0.00
09-15	ALIGN STEERING	11213180	07/25/2018 07:00:00	07/25/2018 08:00:00	1.00	\$0.00
				LABOR		0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.84	5	\$19.20
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.35	1	\$4.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	5	\$1.35
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	2.01	2	\$4.02
				PARTS		33.13

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 30342

Work Order Notes

(LISAPATE) PM-TIRES NOISY AT 25-30 MPG STOPS AT 50MPH

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) CHECKED FOUND NEEDS 2 TIRES

09-15 - ALIGN STEERING

(LISAPATE) MS PERFORMED ALIGNMENT

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) MOUNT AND BALANCED 2 NEW TIRES

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM BY EK/AG

COOLANT -20'

PU-17 - PURCHASED TIRES, TUBES, LINERS & VALVES

(LISAPATE) PURCHASED 2 NEW TIRES FROM FIRESTONE. PD BY CC

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 31177

USING DEPT NO:	224107	OPENED DATE:	10/15/2018 11:09:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2018 14:34:34	METER 1 - M:	39040	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2018 14:34:38	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-17-030	PERFORM TIRE PATCH	DON	O	N	GARAGE	0.70	\$50.45	\$5.08	\$0.00	\$55.53

JOB COUNT: 1	WORK ORDER TOTAL:	0.70	50.45	5.08	0.00	55.53
---------------------	--------------------------	-------------	--------------	-------------	-------------	--------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	11901357	10/15/2018 11:14:57	10/15/2018 11:56:42	0.70	\$50.45
					LABOR	50.45

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	2.20	1	\$2.20
66-17-030	PERFORM TIRE PATCH	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	2.34	1	\$2.34
					PARTS	5.08

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 31177

Work Order Notes

(EKIMBREL) nail in LR tire

Job Notes

66-17-030 - PERFORM TIRE PATCH

(LISAPATE) Removed and patched LR tire

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 31635

USING DEPT NO:	224107	OPENED DATE:	12/04/2018 07:47:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/07/2018 13:01:26	METER 1 - M:	41431	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/07/2018 13:01:28	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.05	\$3.26	\$17.06	\$0.00	\$20.32
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.23	\$89.15	\$33.00	\$0.00	\$122.15

JOB COUNT: 2	WORK ORDER TOTAL:	1.27	92.41	50.06	0.00	142.47
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/04/2018 09:44:05	12/04/2018 10:10:57	0.45	\$32.46
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2018 09:50:21	12/04/2018 10:10:12	0.33	\$23.99
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/04/2018 09:40:59	12/04/2018 09:43:41	0.05	\$3.26
66-PM-PMA	PERFORM OIL CHANGE	11074414	12/04/2018 08:32:56	12/04/2018 09:00:00	0.45	\$32.71
					LABOR	92.42

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	9.27	1	\$9.27
					PARTS	50.06

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 31635

Work Order Notes

(LISAPATE) PM

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by AG,SH/SH

Coolant -35'

Replaced air filter

Cleaned battery cables

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32233

USING DEPT NO:	224107	OPENED DATE:	02/20/2019 15:07:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/25/2019 08:38:03	METER 1 - M:	47414	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/25/2019 08:38:05	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.40	\$29.00	\$163.46	\$0.00	\$192.46
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$37.20	\$0.00	\$59.68

JOB COUNT: 3	WORK ORDER TOTAL:	1.71	123.98	200.66	0.00	324.64
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	02/22/2019 07:00:00	02/22/2019 07:18:36	0.31	\$22.48
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11268671	02/22/2019 07:00:00	02/22/2019 07:24:00	0.40	\$29.00
09-15	ALIGN STEERING	11213180	02/22/2019 07:00:00	02/22/2019 08:00:00	1.00	\$72.50
					LABOR	123.98

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	9.26	1	\$9.26
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	023240	TIRE 205/65R16 F/S CHAMP FF	79.26	2	\$158.52
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.27	2	\$0.54
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.20	2	\$4.40
					PARTS	200.66

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32233

Work Order Notes

(LISAPATE) PM-Tires making a whomping noise and vibrating

Job Notes

09-15 - ALIGN STEERING

(LISAPATE) MS performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) IF mount and balanced 2 new rear tires

66-PM-PMA - PERFORM OIL CHANGE

(RTUNAITI) Visit Reason Changed On 2/20/2019 3:08 PM By RTUNAITI

(LISAPATE) PM by AG,EK/AG

Replaced air filter

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32565

USING DEPT NO:	224107	OPENED DATE:	04/09/2019 08:21:05	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2019 09:30:41	METER 1 - M:	51792	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/15/2019 09:30:43	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.66	\$47.75	\$27.94	\$0.00	\$75.69
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.30	\$21.75	\$4.89	\$0.00	\$26.64

JOB COUNT: 2	WORK ORDER TOTAL:	0.96	69.50	32.83	0.00	102.33
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	04/10/2019 07:00:00	04/10/2019 07:18:00	0.30	\$21.75
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2019 14:30:00	04/09/2019 14:53:38	0.39	\$28.56
66-PM-PMA	PERFORM OIL CHANGE	11901357	04/09/2019 13:59:07	04/09/2019 14:15:00	0.26	\$19.19
					LABOR	69.50

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	800012C	CABIN AIR FILTER REPL 4483	4.89	1	\$4.89
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	4.21	1	\$4.21
					PARTS	32.83

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32565

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 4/9/2019 8:21 AM By LISAPATE

(LISAPATE) PM by AG

Coolant -35'

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(LISAPATE) Replaced cabin filter

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32624

USING DEPT NO:	224107	OPENED DATE:	04/15/2019 10:18:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/24/2019 06:38:23	METER 1 - M:	51792	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/24/2019 06:38:25	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
03-02-010	REPLACE NEW MIRRORS	DON	O	N	GARAGE	0.70	\$50.75	\$137.18	\$0.00	\$187.93

JOB COUNT: 1	WORK ORDER TOTAL:	0.70	50.75	137.18	0.00	187.93
---------------------	--------------------------	-------------	--------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	11170580	04/17/2019 07:00:00	04/17/2019 07:42:00	0.70	\$50.75
					LABOR	50.75

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
03-02-010	REPLACE NEW MIRRORS	8790606040	MIRROR ASSEMBLY, POWER LH	97.60	1	\$97.60
03-02-010	REPLACE NEW MIRRORS	8794506060A0	OUTER MIRROR COVER, S WHITE	39.58	1	\$39.58
					PARTS	137.18

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 32624

Work Order Notes

(LISAPATE) Glass was stolen from left outside mirror clips were broken to install

Job Notes

03-02-010 - REPLACE NEW MIRRORS

(LISAPATE) Removed and installed new mirror assy. Rechecked ok

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 33235

USING DEPT NO:	224107	OPENED DATE:	06/25/2019 08:49:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2019 10:17:37	METER 1 - M:	56802	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2019 10:17:39	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.72	\$52.04	\$0.00	\$0.00	\$52.04
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.96	\$69.28	\$33.97	\$0.00	\$103.25

JOB COUNT: 2	WORK ORDER TOTAL:	1.67	121.32	33.97	0.00	155.29
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	06/27/2019 06:59:08	06/27/2019 07:42:12	0.72	\$52.04
66-PM-PMA	PERFORM OIL CHANGE	11901357	06/26/2019 09:27:03	06/26/2019 10:24:23	0.96	\$69.28
					LABOR	121.32

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	5	\$19.40
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	10.24	1	\$10.24
					PARTS	33.97

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 33235

Work Order Notes

(LISAPATE) PM-Per driver pulling to the Right

Job Notes

09-15 - ALIGN STEERING

(EKIMBREL) EH checked front end. Performed alignment. Alignment wasn't bad, vehicle is ok.

(IFALLS) Per Ethan the tire pressure was off a few pounds

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) Visit Reason Changed On 6/25/2019 8:50 AM By LISAPATE

(EKIMBREL) AG/AG; Coolant -35

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 33841

USING DEPT NO:	224107	OPENED DATE:	08/23/2019 10:01:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/30/2019 08:28:25	METER 1 - M:	59648	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/30/2019 08:28:25	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	O	N	GARAGE	0.21	\$15.45	\$0.00	\$0.00	\$15.45
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	O	N	GARAGE	1.54	\$111.29	\$0.00	\$0.00	\$111.29
09-15	ALIGN STEERING	DON	O	N	GARAGE	0.37	\$27.07	\$0.00	\$0.00	\$27.07
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	1.71	\$124.32	\$370.56	\$0.00	\$494.88

JOB COUNT: 4	WORK ORDER TOTAL:	3.84	278.13	370.56	0.00	648.69
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
09-15	ALIGN STEERING	11310047	08/28/2019 08:52:36	08/28/2019 09:15:00	0.37	\$27.07
06-15	INSPECT STEERING	12052187	08/26/2019 15:41:02	08/26/2019 15:53:49	0.21	\$15.45
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	08/26/2019 14:37:20	08/26/2019 15:45:37	1.14	\$82.51
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	08/26/2019 15:06:26	08/26/2019 15:41:02	0.58	\$41.81
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11170580	08/23/2019 11:28:56	08/23/2019 13:01:02	1.54	\$111.29

LABOR 278.13

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	34654	TIRE P205/65R16 MICH DEFND T+H	90.01	4	\$360.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	2.21	4	\$8.84
66-17-028	PERFORM MOUNT AND BALANCE TIRES	WHEEL WEIGHT	WHEEL WEIGHT KNOCK ON	0.28	6	\$1.68

PARTS 370.56

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 33841

Work Order Notes

(LISAPATE) Per driver rear end is roaring and shaking(vibrating) also pulling right

Job Notes

06-15 - INSPECT STEERING

(LISAPATE) JW Checked front end no issues found at this time

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(LISAPATE) Needs 2 tires. Changing all 4 to a better Michelin tire so driver can get more life out of them

09-15 - ALIGN STEERING

(LISAPATE) EH Performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(LISAPATE) Mounted and balanced 4 new tires

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 34237

USING DEPT NO:	224107	OPENED DATE:	09/25/2019 09:43:28	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/26/2019 11:33:10	METER 1 - M:	61090	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/26/2019 11:33:11	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	O	N	GARAGE	2.12	\$153.70	\$0.00	\$0.00	\$153.70
10-13	SERVICE BRAKES	DON	O	N	GARAGE	1.00	\$72.50	\$0.00	\$0.00	\$72.50
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.31	\$22.48	\$23.62	\$0.00	\$46.10

JOB COUNT: 3	WORK ORDER TOTAL:	3.43	248.68	23.62	0.00	272.30
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
10-13	SERVICE BRAKES	11213180	09/26/2019 08:37:47	09/26/2019 09:37:47	1.00	\$72.50
10-13	SERVICE BRAKES	11213180	09/26/2019 08:37:47	09/26/2019 10:37:47	(2.00)	(\$145.00)
10-13	SERVICE BRAKES	11213180	09/26/2019 08:37:47	09/26/2019 10:37:47	2.00	\$145.00
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/26/2019 07:00:00	09/26/2019 07:18:36	0.31	\$22.48
06-13	INSPECT BRAKES	11213180	09/26/2019 06:30:35	09/26/2019 08:37:47	2.12	\$153.70
					LABOR	248.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.17	1	\$4.17
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
					PARTS	23.62

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 34237

Work Order Notes

(LISAPATE) PM-Check brakes making a rubbing/grinding noise

Job Notes

06-13 - INSPECT BRAKES

(LISAPATE) Found brakes were glazed over.

10-13 - SERVICE BRAKES

(LISAPATE) Removed calipers and roughed brake pad surface on all 4 wheels. test drove no other noises found.

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by JW,EK/JW

Coolant -35'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 35508

USING DEPT NO:	224107	OPENED DATE:	01/28/2020 09:16:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/04/2020 07:22:13	METER 1 - M:	62397	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/04/2020 07:22:15	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-32-002	REPLACE NEW BATTERY	DON	O	N	GARAGE	0.39	\$28.01	\$80.36	\$0.00	\$108.37
03-51-038	REPLACE NEW WIPER BLADES	DON	O	N	GARAGE	0.25	\$18.13	\$17.06	\$0.00	\$35.19
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.70	\$50.49	\$23.78	\$0.00	\$74.27

JOB COUNT: 3	WORK ORDER TOTAL:	1.33	96.63	121.20	0.00	217.83
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	01/29/2020 07:00:00	01/29/2020 07:15:00	0.25	\$18.13
03-32-002	REPLACE NEW BATTERY	11074414	01/29/2020 08:36:49	01/29/2020 09:00:00	0.39	\$28.01
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 08:19:22	01/29/2020 08:36:49	0.29	\$21.09
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/29/2020 07:29:57	01/29/2020 07:54:17	0.41	\$29.40
					LABOR	96.63

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	5	\$19.45
03-32-002	REPLACE NEW BATTERY	728249	BATTERY TERM 8MM STUD STYLE	3.82	1	\$3.82
03-32-002	REPLACE NEW BATTERY	24F2	BATTERY BCI 24F 550CCA	75.70	1	\$75.70
03-32-002	REPLACE NEW BATTERY	740245	BATTERY TERM PROTECTOR WASHER	0.42	2	\$0.84
03-51-038	REPLACE NEW WIPER BLADES	WW-2600-PC	WIPER BLADE 26"	8.53	1	\$8.53
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	8.53	1	\$8.53
					PARTS	121.20

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 35508

Work Order Notes

(LISAPATE) PM

Job Notes

03-32-002 - REPLACE NEW BATTERY

(LISAPATE) Replaced battery and positive battery terminal due to corroded. Added new corrosion washers

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(LISAPATE) PM by SH,EK/AG

Coolant -50'

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 36567

USING DEPT NO:	224107	OPENED DATE:	05/22/2020 09:39:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/22/2020 15:43:18	METER 1 - M:	62588	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/27/2020 11:52:03	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.19	\$13.84	\$0.00	\$0.00	\$13.84

JOB COUNT: 1	WORK ORDER TOTAL:	0.19	13.84	0.00	0.00	13.84
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/22/2020 13:08:49	05/22/2020 13:20:16	0.19	\$13.84
					LABOR	13.84

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	(1)	(\$4.33)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	(4)	(\$15.52)
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.88	4	\$15.52
					PARTS	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 36567

Work Order Notes

(EKIMBREL) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) Vehicle had only been driven 191 miles since last service. SH checked fluids, tire pressures, and updated window sticker.

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 38073

USING DEPT NO:	224107	OPENED DATE:	10/20/2020 08:07:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/23/2020 08:03:30	METER 1 - M:	62724	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/23/2020 10:42:42	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$40.64	\$0.00	\$0.00	\$40.64
AD-71-030	ADDED EXTERIOR PAINT-VEHICLE	DON	O	N	GARAGE	1.17	\$138.06	\$1.82	\$0.00	\$139.88

JOB COUNT: 2	WORK ORDER TOTAL:	1.51	178.70	1.82	0.00	180.52
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
AD-71-030	ADDED EXTERIOR PAINT-VEHICLE	11901357	10/23/2020 07:12:06	10/23/2020 07:17:24	0.09	\$10.42
AD-71-030	ADDED EXTERIOR PAINT-VEHICLE	11901357	10/22/2020 13:10:50	10/22/2020 14:06:49	0.93	\$110.10
AD-71-030	ADDED EXTERIOR PAINT-VEHICLE	11901357	10/22/2020 08:02:06	10/22/2020 08:11:01	0.15	\$17.54
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/20/2020 14:39:35	10/20/2020 14:42:44	0.05	\$6.20
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/20/2020 13:51:06	10/20/2020 14:08:37	0.29	\$34.45
					LABOR	178.71

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
AD-71-030	ADDED EXTERIOR PAINT-VEHICLE	SANDPAPER	VAR GRIT SINGLE SHEET SANDPAPE	1.82	1	\$1.82
					PARTS	1.82

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 38073

Work Order Notes

(LISAPATE) PM-Touch up rust spots on car around passenger door for sure

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Vehicle has been 327 miles. Checked fluids, battery and tires, updated oil change sticker. Completed checklist. AMG

AD-71-030 - ADDED EXTERIOR PAINT-VEHICLE

(AGUERRA) Cleaned and sanded rust spots on hood and passenger door, applied touchup paint to areas. 1.5 Hrs AMG

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 38203

USING DEPT NO:	224107	OPENED DATE:	10/29/2020 08:24:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/07/2020 10:50:12	METER 1 - M:	62724	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/08/2020 08:24:46	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$2,957.69	\$2,957.69

JOB COUNT: 2	WORK ORDER TOTAL:	0.50	59.00	0.00	2,957.69	3,016.69
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	5569647	4983		\$2,957.69
				COMML	2957.69

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	10208562	12/07/2020 07:00:00	12/07/2020 07:30:00	0.50	\$59.00
24-71	REPAIR BODY	10208562	12/07/2020 07:00:00	12/07/2020 07:30:00	(0.50)	(\$59.00)
24-71	REPAIR BODY	10208562	12/07/2020 07:00:00	12/07/2020 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 38203

Work Order Notes

(LISAPATE) Take to Browns Body Shop to paint hood and roof of car per the estimate.

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Browns by RC

24-71 - REPAIR BODY

(LISAPATE) Browns repaired paint damage to the hood and roof per the estimate. Pd by CC

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 39358

USING DEPT NO:	224107	OPENED DATE:	03/10/2021 07:10:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/12/2021 09:49:09	METER 1 - M:	62827	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/15/2021 08:03:10	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	1.06	\$124.82	\$35.00	\$0.00	\$159.82

JOB COUNT: 1	WORK ORDER TOTAL:	1.06	124.82	35.00	0.00	159.82
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2021 08:13:01	03/11/2021 09:03:23	0.84	\$99.05
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/11/2021 07:54:44	03/11/2021 08:07:50	0.22	\$25.76
					LABOR	124.81

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	57047	FILTER-OIL	12.57	1	\$12.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	5	\$22.43
					PARTS	35.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 39358

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 62827. SH Performed PM and vacuumed.

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 40655

USING DEPT NO:	224107	OPENED DATE:	08/06/2021 07:59:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2021 09:35:08	METER 1 - M:	63091	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2021 15:00:33	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.29	\$17.77	\$0.00	\$24.06
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.50	\$58.74	\$0.00	\$0.00	\$58.74
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.63	\$0.00	\$0.00	\$51.63
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	O	N	GARAGE	0.05	\$6.00	\$21.74	\$0.00	\$27.74
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.04	122.66	39.51	2.00	164.17
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11901357	08/07/2021 08:08:54	08/07/2021 08:38:46	0.50	\$58.74
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	08/07/2021 08:02:53	08/07/2021 08:05:56	0.05	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	11901357	08/07/2021 07:36:23	08/07/2021 08:02:38	0.44	\$51.63
03-51-038	REPLACE NEW WIPER BLADES	11901357	08/07/2021 07:29:23	08/07/2021 07:32:35	0.05	\$6.29
					LABOR	122.66

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	21.74	1	\$21.74
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.46	1	\$7.46
					PARTS	39.51

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 40655

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 63091 Vehicle has been driven 264 miles, oil was changed at last PM. Checked fluids, battery and tires. Updated oil change sticker and completed checklist. AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 42054

USING DEPT NO:	224107	OPENED DATE:	01/12/2022 08:01:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/13/2022 10:40:45	METER 1 - M:	65608	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/14/2022 08:07:34	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$5.21	\$17.90	\$0.00	\$23.11
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.66	\$78.27	\$0.00	\$0.00	\$78.27
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.68	\$47.87	\$0.00	\$123.55
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	1.35	159.16	65.77	2.00	226.93
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/13/2022 07:03:42	01/13/2022 07:27:15	0.39	\$46.32
66-79-003	PERFORM SAFETY INSPECTION	11074414	01/12/2022 15:24:33	01/12/2022 15:40:48	0.27	\$31.96
03-51-038	REPLACE NEW WIPER BLADES	11074414	01/12/2022 15:14:15	01/12/2022 15:16:54	0.04	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	11074414	01/12/2022 14:35:34	01/12/2022 15:14:03	0.64	\$75.68
				LABOR		159.17

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.56	1	\$6.56
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	13.56	1	\$13.56
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.25	1	\$5.25
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.50	5	\$22.50
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59
				PARTS		65.77

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 42054

Work Order Notes

(LISAPATE) PM-replace wipers-Do annual SI

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 43293

USING DEPT NO:	224107	OPENED DATE:	05/18/2022 10:09:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/19/2022 15:22:16	METER 1 - M:	67429	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/20/2022 13:59:46	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.66	\$17.90	\$0.00	\$20.56
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.16	\$19.21	\$0.00	\$0.00	\$19.21
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.19	21.87	17.90	2.00	41.77
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/18/2022 10:45:01	05/18/2022 10:46:22	0.02	\$2.66
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/18/2022 10:34:57	05/18/2022 10:44:43	0.16	\$19.21
					LABOR	21.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	26-1	WIPER BLADE	10.31	1	\$10.31
03-51-038	REPLACE NEW WIPER BLADES	18-1	WIPER BLADE 18"	7.59	1	\$7.59
					PARTS	17.90

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 43293

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) Vehicle has been driven 1821 miles since the last PM. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 44946

USING DEPT NO:	224107	OPENED DATE:	10/11/2022 07:56:55	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/12/2022 14:25:44	METER 1 - M:	71218	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/13/2022 07:26:44	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.06	\$6.88	\$23.10	\$0.00	\$29.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.23	\$27.53	\$62.62	\$0.00	\$90.15
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.29	34.41	85.72	5.00	125.13
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/11/2022 12:53:01	10/11/2022 13:07:01	0.23	\$27.53
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/11/2022 12:49:12	10/11/2022 12:52:42	0.06	\$6.88
					LABOR	34.41

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	20.43	1	\$20.43
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	5	\$28.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.85	1	\$7.85
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.38	1	\$10.38
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	12.72	1	\$12.72
					PARTS	85.72

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: **241441** **2015 TOYOTA CAMRY**

WORK ORDER NO: **44946**

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 71218 Completed PM topside, Josh was bottomside. AMG/JW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 45469

USING DEPT NO:	224107	OPENED DATE:	12/07/2022 09:31:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/12/2022 10:22:59	METER 1 - M:	73535	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/12/2022 13:33:36	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
35-32	DIAGNOSE CRANKING SYSTEM	DON	O	N	GARAGE	2.02	\$237.90	\$0.00	\$0.00	\$237.90
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	2.52	296.90	0.00	5.00	301.90
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
35-32	DIAGNOSE CRANKING SYSTEM	11310047	12/09/2022 13:41:41	12/09/2022 15:42:39	2.02	\$237.90
66-79-002	PERFORM SERVICE CALL	11399745	12/12/2022 07:00:00	12/12/2022 07:30:00	0.50	\$59.00
					LABOR	296.90

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 45469

Work Order Notes

(EHANNAH) Karen requested services call to WOW for dead battery. Battery was replaced in 2020

Job Notes

35-32 - DIAGNOSE CRANKING SYSTEM

(EHOWELL) Cranked the vehicle multiple times while the vehicle was hot and cold. The vehicle never failed to start. Left the headlights on for five minutes and then started the vehicle. The vehicle started fine. The battery tested good. No problem found. EH .3 HR

66-79-002 - PERFORM SERVICE CALL

(LISAPATE) Service call completed by RC/CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 46184

USING DEPT NO:	224107	OPENED DATE:	02/17/2023 09:00:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/20/2023 07:43:02	METER 1 - M:	74636	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/20/2023 10:31:23	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.59	\$69.82	\$46.32	\$0.00	\$116.14
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.59	69.82	46.32	5.00	121.14
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	02/17/2023 12:16:04	02/17/2023 12:51:34	0.59	\$69.82
					LABOR	69.82

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	5	\$30.45
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	8.01	1	\$8.01
					PARTS	46.32

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 46184

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW
MILEAGE-74636

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 47142

USING DEPT NO:	224107	OPENED DATE:	05/22/2023 13:45:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/23/2023 12:04:07	METER 1 - M:	74636	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/24/2023 09:26:15	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-51-042	INSTALL KEY FOB BATTERY	DON	O	N	GARAGE	0.15	\$17.70	\$3.41	\$0.00	\$21.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.15	17.70	3.41	5.00	26.11
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-51-042	INSTALL KEY FOB BATTERY	12201267	05/23/2023 07:00:00	05/23/2023 07:09:00	0.15	\$17.70
					LABOR	17.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-51-042	INSTALL KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.41	1	\$3.41
					PARTS	3.41

Work Order Charge Detail

UNIT NO:	241441	2015 TOYOTA CAMRY	WORK ORDER NO:	47142
----------	--------	-------------------	----------------	-------

Work Order Notes

(CWIGLEY) Change key fob battery.

Job Notes

14-51-042 - INSTALL KEY FOB BATTERY

(LISAPATE) Installed new battery. GC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 47988

USING DEPT NO:	224107	OPENED DATE:	08/25/2023 07:39:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/25/2023 11:45:25	METER 1 - M:	79565	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/28/2023 07:28:37	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.87	\$24.05	\$0.00	\$27.92
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.94	\$65.86	\$0.00	\$104.80
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.39	\$45.86	\$0.00	\$0.00	\$45.86

JOB COUNT: 4	WORK ORDER TOTAL:	0.75	88.67	89.91	5.00	183.58
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	08/25/2023 09:32:13	08/25/2023 09:55:32	0.39	\$45.86
03-51-038	REPLACE NEW WIPER BLADES	11074414	08/25/2023 09:30:06	08/25/2023 09:32:04	0.03	\$3.87
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2023 09:16:33	08/25/2023 09:16:33	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2023 09:16:33	08/25/2023 09:16:33	0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/25/2023 09:16:33	08/25/2023 09:36:21	0.33	\$38.94
				LABOR		88.67

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.00	1	\$6.00
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	5	\$31.35
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.82	1	\$10.82
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
				PARTS		89.91

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 47988

Work Order Notes

(CHANNELL) pm replace wipers wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/FC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 49319

USING DEPT NO:	224107	OPENED DATE:	12/21/2023 09:28:20	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/04/2024 08:56:33	METER 1 - M:	83216	METER 2 - N: 0
WO VISIT REASON:	UNSCHEDULED	CLOSED DATE:	01/04/2024 11:57:00	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.39	\$45.79	\$12.05	\$0.00	\$57.84
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.05	\$5.54	\$0.00	\$0.00	\$5.54
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.44	51.33	12.05	5.00	68.38
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	12/21/2023 10:06:42	12/21/2023 10:09:31	0.05	\$5.54
66-17-030	PERFORM TIRE PATCH	11074414	12/21/2023 09:43:11	12/21/2023 10:06:28	0.39	\$45.79
				LABOR		51.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	58103	1.00 OZ WHEEL WEIGHT	0.78	1	\$0.78
66-17-030	PERFORM TIRE PATCH	58102	.75 OZ WHEEL WEIGHT	1.01	1	\$1.01
66-17-030	PERFORM TIRE PATCH	14041	PATCH 1/4 PILOT WIRE	5.46	1	\$5.46
66-17-030	PERFORM TIRE PATCH	21030	TPMS SERVICE KIT 6-116	4.80	1	\$4.80
					PARTS	12.05

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 49319

Work Order Notes

(EKIMBREL) NAIL IN TIRE; TIRE ROTATION

Job Notes

66-17-030 - PERFORM TIRE PATCH

(SHARBIN) Patched the left rear tire. Rechecks good. SH

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Did not rotate the tires at this time due to uneven wear. Front tires were 7/32 across the tire. The rear tires went from 5/23 to 7/32. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 49364

USING DEPT NO:	224107	OPENED DATE:	01/08/2024 07:58:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/09/2024 15:21:29	METER 1 - M:	83415	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/10/2024 07:17:23	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.08	\$9.05	\$24.08	\$0.00	\$33.13
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.29	\$60.96	\$0.00	\$136.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.21	\$24.71	\$0.00	\$0.00	\$24.71

JOB COUNT: 4	WORK ORDER TOTAL:	0.92	109.05	85.04	5.00	199.09
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	01/08/2024 13:00:00	01/08/2024 13:12:34	0.21	\$24.71
WA-00	WASH COMPLETE VEHICLE	12395904	01/08/2024 12:59:07	01/08/2024 12:59:07	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12395904	01/08/2024 11:40:25	01/08/2024 11:45:01	0.08	\$9.05
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/08/2024 11:01:38	01/08/2024 11:39:55	0.64	\$75.29
				LABOR		109.05

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.29	5	\$31.43
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
				PARTS		85.04

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 49364

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) replaced new wipers FC

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc - ah

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 50470

USING DEPT NO:	224107	OPENED DATE:	04/08/2024 09:53:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/17/2024 15:07:26	METER 1 - M:	86991	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2024 07:19:58	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-01	INSPECT AIR CONDITIONING, HEAT, VE	DON	N	N	GARAGE	0.42	\$49.43	\$0.00	\$0.00	\$49.43
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.16	\$18.49	\$0.00	\$0.00	\$18.49
24-02-061	REPAIR WINDSHIELD	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$80.44	\$80.44
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.19	\$22.42	\$192.11	\$0.00	\$214.53
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.39	\$46.02	\$71.53	\$0.00	\$117.55
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.54	\$13.17	\$0.00	\$14.71
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.29	\$34.35	\$0.00	\$0.00	\$34.35

JOB COUNT: 8	WORK ORDER TOTAL:	1.46	172.25	276.81	85.44	534.50
--------------	-------------------	------	--------	--------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	117405		\$80.44
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	85.44

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/08/2024 10:56:02	04/08/2024 11:19:26	0.39	\$46.02
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	12395904	04/08/2024 11:19:53	04/08/2024 11:21:36	0.03	\$3.38
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	04/08/2024 13:31:06	04/08/2024 13:31:53	0.01	\$1.54
WA-00	WASH COMPLETE VEHICLE	12395904	04/08/2024 13:32:18	04/08/2024 13:49:46	0.29	\$34.35
06-01	INSPECT AIR CONDITIONING, HEAT, VENT	11310047	04/09/2024 09:23:21	04/09/2024 09:46:46	0.39	\$46.05
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11310047	04/10/2024 13:07:43	04/10/2024 13:19:07	0.19	\$22.42
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11310047	04/10/2024 13:19:07	04/10/2024 13:28:31	0.16	\$18.49
				LABOR		172.25

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
----------	-----------------	----------	-------------	------------	----------	------------

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	5	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	17.75	1	\$17.75
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	13.17	1	\$13.17
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.78	2	\$1.56
66-17-028	PERFORM MOUNT AND BALANCE TIRES	69099	TIRE 205/65R16 MICH DEFENDER2	185.70	1	\$185.70
66-17-028	PERFORM MOUNT AND BALANCE TIRES	6-111	TPMS SERVICE KIT 6-111	4.85	1	\$4.85
					PARTS	276.81

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 50470

Work Order Notes

(EHANNAH) pm-inspect AC due to whistling noise- wash

(EHANNAH) Tires are making noise and need to be checked possible balanced- Glass Dr. repair chip in windshield.

Job Notes

06-01 - INSPECT AIR CONDITIONING, HEAT, VENT

(FCONTRER) inspect air conditioning heat Ben good fc

(EHOWELL) FC stated that debris around the cabin filter was causing the blower motor to make noise. The customer said that the noise went away after the cabin filter was replaced. EH

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(EHOWELL) The left rear tire is cupped excessively and causing road noise. EH

24-02-061 - REPAIR WINDSHIELD

(LISAPATE) Glass Dr repaired ding in the windshield. PD by CC

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EHOWELL) Mounted and balanced a new tire. Installed it on the left rear of the vehicle. EH

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes FC

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replace new wipers fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) wash fc

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 51564

USING DEPT NO:	224107	OPENED DATE:	07/23/2024 07:17:52	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	08/06/2024 11:23:36	METER 1 - M:	86991	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/06/2024 11:23:41	IN-SERVICE DATE:	07/20/2015						
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY									
				UNIT SERIAL NO:	4T1BF1FK2FU100832						

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
24-02-061	REPAIR WINDSHIELD	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$91.94	\$91.94
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.01	\$1.67	\$0.00	\$0.00	\$1.67
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.25	\$70.14	\$0.00	\$71.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:					0.02	2.92	70.14	96.94	170.00
--------------	-------------------	--	--	--	--	------	------	-------	-------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-02-061	REPAIR WINDSHIELD	11078716	120206		\$91.94
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					96.94

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/23/2024 10:46:44	07/23/2024 10:47:22	0.01	\$1.25
66-79-003	PERFORM SAFETY INSPECTION	12395904	07/23/2024 10:45:21	07/23/2024 10:46:12	0.01	\$1.67
LABOR						2.92

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.57	1	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	5	\$34.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	49223	AIR FILTER REPL 9223	16.04	1	\$16.04
PARTS						70.14

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 51564

Work Order Notes

(EHANNAH) pm-wipers- SI- transport to Glass Dr. for rock chip

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-71 - TRANSPORT BODY

(IFALLS) no transport needed/repared at our shop

24-02-061 - REPAIR WINDSHIELD

(EKIMBREL) glass dr repaired windshield

66-79-003 - PERFORM SAFETY INSPECTION

(FCONTRER) perform safety inspection fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 52045

USING DEPT NO:	224107	OPENED DATE:	09/06/2024 07:58:37	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2024 13:17:21	METER 1 - M:	86991	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2024 13:17:27	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-52-003	INSPECT RADIO	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$103.44	\$103.44
14-52-003	INSTALL RADIO	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$563.49	\$563.49
16-52-003	TRANSPORT RADIO	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	0.00	671.93	671.93
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
14-52-003	INSTALL RADIO	11287280	108086		\$563.49
06-52-003	INSPECT RADIO	11076422	6264784		\$103.44
				COMML	671.93

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 52045

Work Order Notes

(EHANNAH) wipers- radio buttons and steering buttons not working. Hands free phone not working. the dial knobs do work. but nothing on the touch screen works, or on the steering wheel.

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

06-52-003 - INSPECT RADIO

(EKIMBREL) tusc toyota diagnosed internal radio failure

14-52-003 - INSTALL RADIO

(EKIMBREL) Mobile Electronics installed radio

16-52-003 - TRANSPORT RADIO

(EHOWELL) The vehicle was driven to Tuscaloosa Toyota for an estimate/diagnosis.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 52464

USING DEPT NO:	224107	OPENED DATE:	10/14/2024 09:58:10	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/14/2024 13:29:33	METER 1 - M:	86991	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/14/2024 13:29:40	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-52-003	INSTALL RADIO	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$215.05	\$215.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	0.00	220.05	220.05
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
14-52-003	INSTALL RADIO	11287280	108178		(\$212.75)
14-52-003	INSTALL RADIO	11287280	108178		(\$207.00)
14-52-003	INSTALL RADIO	11287280	108178		\$207.00
14-52-003	INSTALL RADIO	11287280	108178		(\$201.25)
14-52-003	INSTALL RADIO	11287280	108178		\$201.25
14-52-003	INSTALL RADIO	11287280	108178		(\$247.25)
14-52-003	INSTALL RADIO	11287280	108178		\$247.25
14-52-003	INSTALL RADIO	11287280	108178		\$212.75
14-52-003	INSTALL RADIO	11287280	108178		(\$224.25)
14-52-003	INSTALL RADIO	11287280	108178		\$224.25
14-52-003	INSTALL RADIO	11287280	108178		\$215.05
COMML					220.05

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: **241441** **2015 TOYOTA CAMRY**

WORK ORDER NO: **52464**

Work Order Notes

(EKIMBREL) upgrade to touch screen radio

Job Notes

14-52-003 - INSTALL RADIO

(EKIMBREL) Mobile Electronics swapper radio to touch screen so back up camera worked

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 53165

USING DEPT NO:	224107	OPENED DATE:	12/17/2024 07:09:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/18/2024 15:44:48	METER 1 - M:	96466	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2024 07:32:10	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	24.08	5.00	29.08
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
					PARTS	24.08

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 53165

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Replaced blades

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Fluid check. Driven 1814 miles since last PM. Checked filters, topped off fluids, set tire pressure, recorded date codes & tread depths.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Washed vehicle

(GARAGE) FJ- Cannot wash vehicle at this time. Wash bay is down as of 8:58 a.m. 12/18/24.

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 53408

USING DEPT NO:	224107	OPENED DATE:	01/17/2025 09:15:13	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/27/2025 11:46:42	METER 1 - M:	96466	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/27/2025 13:19:54	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL'	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-013	PERFORM ALIGNMENT	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.00	\$0.00	\$570.82	\$0.00	\$570.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.00	0.00	570.82	5.00	575.82
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	69099	TIRE 205/65R16 MICH DEFENDER2	185.70	3	\$557.10
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.57	3	\$13.72
					PARTS	570.82

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 53408

Work Order Notes

(CWIGLEY) Driver says that she's hearing a roaring sound coming from the passenger side of the vehicle.

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(IFALLS) test drove and inspected vehicle on rack found roar was dew to tires having knots on tread depths and side walls tire will need replacing, cm .5 labor

06-71 - INSPECT BODY

66-17-013 - PERFORM ALIGNMENT

(GARAGE) performed alignment cm 97401 miles, test drove checked ok,

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) mounted and balanced 3 tires, replaced valve stems cm

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 54615

USING DEPT NO:	224107	OPENED DATE:	04/28/2025 12:06:31	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/28/2025 13:05:43	METER 1 - M:	101553	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/28/2025 13:05:43	IN-SERVICE DATE:	07/20/2015	
TECH SPEC NO:	15TOYOTACAMRY	2015 TOYOTA CAMRY		UNIT SERIAL NO:	4T1BF1FK2FU100832	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/29/2025 08:07:03 By User: GLOBETTI

UNIT NO: 241441 2015 TOYOTA CAMRY

WORK ORDER NO: 54615

Work Order Notes

(EHANNAH) PREP FOR SALE
(IFALLS) 101553 miles

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(IFALLS) IF performed perp for sale

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Tue Apr 29 2025 08:07:03 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '241441') //Q=