

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 43515

USING DEPT NO:	507301	OPENED DATE:	06/03/2022 10:41:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/03/2022 10:42:24	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/03/2022 12:25:52	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00

JOB COUNT: 2	WORK ORDER TOTAL:					1.00	118.00	0.00	2.00	120.00
--------------	-------------------	--	--	--	--	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	11901357	06/03/2022 10:41:57	06/03/2022 11:41:57	1.00	\$118.00
LABOR						118.00

Work Order Charge Detail

UNIT NO:	244673	2022 TOYOTA HIGHLANDER	WORK ORDER NO:	43515
----------	--------	------------------------	----------------	-------

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

CH-SP - CHARGE Shop Supplies

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI completed

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 43975

USING DEPT NO:	507301	OPENED DATE:	07/14/2022 10:56:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/15/2022 10:52:46	METER 1 - M:	3934	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/21/2022 11:57:01	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$30.88	\$39.02	\$0.00	\$69.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.26	30.88	39.02	2.00	71.90
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	07/15/2022 08:03:24	07/15/2022 08:19:06	0.26	\$30.88
LABOR						30.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.21	1	\$5.21
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.90	1	\$6.90
PARTS						39.02

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 43975

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/SH
MILEAGE-3934

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44337

USING DEPT NO:	507301	OPENED DATE:	08/16/2022 12:59:24	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/19/2022 14:09:06	METER 1 - M:	6538	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/22/2022 09:52:12	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$747.50	\$747.50
16-02	TRANSPORT CAB & SHEET METAL	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	752.50	811.50
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2101971		\$747.50
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					752.50

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-02	TRANSPORT CAB & SHEET METAL	11915538	08/22/2022 07:00:00	08/22/2022 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44337

Work Order Notes

(CWIGLEY) Replace windshield. Transport

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed new windshield and recalibrated. PD by CC

16-02 - TRANSPORT CAB & SHEET METAL

(LISAPATE) Taken to Glass DR by RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44617

USING DEPT NO:	507301	OPENED DATE:	09/08/2022 11:22:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/12/2022 10:53:24	METER 1 - M:	8186	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/12/2022 12:49:51	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.30	\$35.89	\$47.75	\$0.00	\$83.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.30	35.89	47.75	5.00	88.64
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	09/09/2022 08:47:21	09/09/2022 09:05:36	0.30	\$35.89
					LABOR	35.89

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.64	1	\$7.64
					PARTS	47.75

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 44617

Work Order Notes

(CHANNELL) pm\ replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 8186 Completed PM topside, Josh was bottomside. AMG/JM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 45358

USING DEPT NO:	507301	OPENED DATE:	11/23/2022 10:31:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/29/2022 14:00:51	METER 1 - M:	12525	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/30/2022 08:09:41	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.32	\$38.12	\$55.98	\$0.00	\$94.10
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.32	38.12	55.98	5.00	99.10
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/28/2022 07:53:54	11/28/2022 08:13:17	0.32	\$38.12
LABOR						38.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	11.58	1	\$11.58
PARTS						55.98

Work Order Charge Detail

UNIT NO:	244673	2022 TOYOTA HIGHLANDER	WORK ORDER NO:	45358
----------	--------	------------------------	----------------	-------

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46380

USING DEPT NO:	507301	OPENED DATE:	03/06/2023 13:57:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/07/2023 11:46:44	METER 1 - M:	17636	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/07/2023 13:13:16	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.26	\$52.17	\$0.00	\$72.43
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.17	20.26	52.17	5.00	77.43
--------------	-------------------	--	--	--	--	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12052187	03/07/2023 08:03:43	03/07/2023 08:14:01	0.17	\$20.26
LABOR						20.26

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
PARTS						52.17

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46380

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Performed pm service. Coolant -34°. JAW/GC
MILEAGE-17636

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46700

USING DEPT NO:	507301	OPENED DATE:	04/12/2023 14:00:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/14/2023 15:24:35	METER 1 - M:	21541	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2023 09:54:16	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	0.12	\$14.13	\$286.44	\$0.00	\$300.57
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.25	\$29.24	\$0.00	\$0.00	\$29.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.37	43.37	286.44	5.00	334.81
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12052187	04/14/2023 09:00:35	04/14/2023 09:07:46	0.12	\$14.13
66-79-002	PERFORM SERVICE CALL	12052187	04/14/2023 08:40:20	04/14/2023 08:55:12	0.25	\$29.24
					LABOR	43.37

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	08008	TIRE 235/65R18 MICHELIN LTX	285.09	1	\$285.09
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.14	10	\$1.35
					PARTS	286.44

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46700

Work Order Notes

(EHANNAH) service call for flat tire

Job Notes

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(EKIMBREL) Replaced RR tire. Aired and balanced to spec. Torqued all lug nuts. JAW
REUSED TPMS KIT, NEW VEHICLE

66-79-002 - PERFORM SERVICE CALL

(JWRIGHT) Went to fleet found a hole in sidewall at the rim, put a plug in it to hold air to get it over to the shop. JAW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46816

USING DEPT NO:	507301	OPENED DATE:	04/24/2023 09:40:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/26/2023 10:08:30	METER 1 - M:	22586	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/27/2023 10:00:42	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$23.66	\$0.00	\$41.36
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.29	\$33.76	\$119.49	\$0.00	\$153.25
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.44	51.46	143.15	5.00	199.61
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/25/2023 07:14:48	04/25/2023 07:31:58	0.29	\$33.76
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/25/2023 12:19:06	04/25/2023 12:19:06	0.00	\$0.00
03-51-038	REPLACE NEW WIPER BLADES	12201267	04/26/2023 07:00:00	04/26/2023 07:09:00	0.15	\$17.70
LABOR						51.46

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	19180	WIPER BLADE BEAM SYLE 18"	10.44	1	\$10.44
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	1562036020	OIL FILTER HOUSING	64.88	1	\$64.88
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.22	1	\$13.22
PARTS						143.15

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 46816

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-SH-GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 22,586

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47338

USING DEPT NO:	507301	OPENED DATE:	06/13/2023 07:42:25	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/13/2023 13:36:10	METER 1 - M:	26720	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/14/2023 09:15:02	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.32	\$38.02	\$0.00	\$0.00	\$38.02
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.18	\$21.31	\$54.70	\$0.00	\$76.01
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.33	54.70	5.00	119.03
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/13/2023 10:00:32	06/13/2023 10:19:52	0.32	\$38.02
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/13/2023 09:48:03	06/13/2023 09:58:53	0.18	\$21.31
				LABOR		59.33

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
					PARTS	54.70

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47338

Work Order Notes

(EHANNAH) pm- replace wipers- wash
(EKIMBREL) cancelled wiper job, just got wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated the tires and inspected the brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47855

USING DEPT NO:	507301	OPENED DATE:	08/08/2023 10:35:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/10/2023 10:51:05	METER 1 - M:	29918	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/10/2023 14:00:47	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$730.25	\$730.25
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	735.25	794.25
--------------	-------------------	------	-------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
03-02-061	REPLACE NEW WINDSHIELD	11078716	2111287		\$730.25
COMML					735.25

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	08/10/2023 07:00:00	08/10/2023 07:30:00	0.50	\$59.00
LABOR						59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 47855

Work Order Notes

(EHANNAH) replace new windshield - Glass Dr.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(LISAPATE) Glass Dr installed new windshield. Pd by CC

04-02-061 - REPLACE RBLT WINDSHIELD

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Glass Dr by CW

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48063

USING DEPT NO:	507301	OPENED DATE:	08/31/2023 10:40:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/05/2023 15:04:37	METER 1 - M:	30341	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/11/2023 11:52:18	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.64	\$75.95	\$57.43	\$0.00	\$133.38
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.64	75.95	57.43	5.00	138.38
--------------	-------------------	--	--	--	--	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	08/31/2023 13:06:47	08/31/2023 13:45:24	0.64	\$75.95
LABOR						75.95

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.80	6	\$40.77
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.90	1	\$5.90
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
PARTS						57.43

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48063

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed by SH

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 48998

USING DEPT NO:	507301	OPENED DATE:	11/17/2023 13:32:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/21/2023 07:30:49	METER 1 - M:	35161	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/21/2023 13:23:26	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.19	\$61.53	\$0.00	\$103.72
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.36	42.19	61.53	5.00	108.72
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/17/2023 14:30:00	11/17/2023 14:51:27	0.36	\$42.19
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/17/2023 14:25:33	11/17/2023 14:25:33	0.00	\$0.00
LABOR						42.19

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	12.96	1	\$12.96
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.77	1	\$10.77
PARTS						61.53

Work Order Charge Detail

UNIT NO:	244673	2022 TOYOTA HIGHLANDER	WORK ORDER NO:	48998
----------	--------	------------------------	----------------	-------

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49721

USING DEPT NO:	507301	OPENED DATE:	02/07/2024 07:13:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/07/2024 12:31:17	METER 1 - M:	39031	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/07/2024 15:19:30	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.51	\$60.31	\$87.62	\$0.00	\$147.93
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.51	60.31	87.62	5.00	152.93
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	02/07/2024 08:01:17	02/07/2024 08:31:57	0.51	\$60.31
					LABOR	60.31

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	ANTIFREEZE PINK	TOYOTA ANTIFREEZE	26.94	1	\$26.94
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.68	1	\$7.68
					PARTS	87.62

Work Order Charge Detail

UNIT NO:

244673

2022 TOYOTA HIGHLANDER

WORK ORDER NO:

49721

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changes fc

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49795

USING DEPT NO:	507301	OPENED DATE:	02/14/2024 08:16:33	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/15/2024 08:21:32	METER 1 - M:	39331	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/16/2024 11:51:46	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-030	PERFORM TIRE PATCH	DON	B	N	GARAGE	0.05	\$5.80	\$3.71	\$0.00	\$9.51
66-79-002	PERFORM SERVICE CALL	DON	B	N	GARAGE	0.02	\$2.92	\$0.00	\$0.00	\$2.92
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.07	8.72	3.71	5.00	17.43
--------------	-------------------	------	------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	12201267	02/14/2024 13:22:30	02/14/2024 13:25:27	0.05	\$5.80
66-79-002	PERFORM SERVICE CALL	11399745	02/14/2024 12:13:26	02/14/2024 12:14:55	0.02	\$2.92
					LABOR	8.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-030	PERFORM TIRE PATCH	63001	1/4 OZ STICK ON TAPE WEIGHT	0.20	5	\$0.98
66-17-030	PERFORM TIRE PATCH	14040	PATCH 1/8 PILOT WIRE	2.73	1	\$2.73
					PARTS	3.71

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 49795

Work Order Notes

(EHANNAH) RR tire is completely flat - it's in the fleet lot

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

66-17-030 - PERFORM TIRE PATCH

(GARAGE) Performed tire patch on unit 6105B, for small leak in tire. patched tire rebalanced and inspected tire and found no issues.-GC

66-79-002 - PERFORM SERVICE CALL

(GARAGE) Aired LR tire up, and brought back to shop to have the tire checked out. CW/RC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 50098

USING DEPT NO:	507301	OPENED DATE:	03/07/2024 08:44:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2024 15:45:22	METER 1 - M:	39725	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/26/2024 07:09:45	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-17	INSPECT TIRES, TUBES, LINERS & VAL	DON	N	N	GARAGE	0.27	\$31.50	\$0.00	\$0.00	\$31.50
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.32	\$38.22	\$307.36	\$0.00	\$345.58
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.59	69.72	307.36	5.00	382.08
--------------	-------------------	------	-------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-17	INSPECT TIRES, TUBES, LINERS & VALVES	11074414	03/07/2024 09:38:56	03/07/2024 09:54:57	0.27	\$31.50
66-17-028	PERFORM MOUNT AND BALANCE TIRES	11074414	03/08/2024 09:54:46	03/08/2024 10:14:12	0.32	\$38.22
				LABOR		69.72

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.80	1	\$4.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	7	\$1.58
66-17-028	PERFORM MOUNT AND BALANCE TIRES	08008	TIRE 235/65R18 MICHELIN LTX	300.98	1	\$300.98
				PARTS		307.36

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 50098

Work Order Notes

(EHANNAH) inspect tires- tire light is on

Job Notes

06-17 - INSPECT TIRES, TUBES, LINERS & VALVES

(SHARBIN) Broke the tire down to inspect. Found the hole in the tire was approximately 3 inches from a previous repair. Tire can not be patched. SH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) Mounted and balanced 1 tire for the left rear. Drove car to reset the tire light. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 50746

USING DEPT NO:	507301	OPENED DATE:	05/06/2024 08:43:00	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/06/2024 12:52:06	METER 1 - M:	44834	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/07/2024 13:44:46	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.28	\$96.26	\$0.00	\$97.54
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.11	\$22.73	\$0.00	\$23.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.02	2.39	118.99	5.00	126.38
--------------	-------------------	------	------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/06/2024 09:12:13	05/06/2024 09:12:47	0.01	\$1.11
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/06/2024 09:11:34	05/06/2024 09:12:13	0.01	\$1.28
LABOR					2.39	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	(1)	(\$6.87)
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
66-PM-PMA	PERFORM OIL CHANGE	WA10859	AIR FILTER CAMRY	35.61	1	\$35.61
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	1	\$6.87
PARTS					118.99	

Work Order Charge Detail

UNIT NO: 244673 2022 TOYOTA HIGHLANDER WORK ORDER NO: 50746

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) SH/FC Performed PM. SH

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 51222

USING DEPT NO:	507301	OPENED DATE:	06/17/2024 10:15:27	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/17/2024 15:36:22	METER 1 - M:	48678	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/20/2024 07:28:07	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.03	\$3.05	\$0.00	\$0.00	\$3.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$0.92	\$53.43	\$0.00	\$54.35
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.03	3.97	53.43	5.00	62.40
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12395904	06/17/2024 15:18:28	06/17/2024 15:20:01	0.03	\$3.05
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/17/2024 15:17:21	06/17/2024 15:17:49	0.01	\$0.92
				LABOR		3.97

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
					PARTS	53.43

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 51222

Work Order Notes

(EHANNAH) pm

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(FCONTRER) Rotate -2 tires and check brakes good fc

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed FC

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52364

USING DEPT NO:	507301	OPENED DATE:	10/03/2024 08:24:04	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/03/2024 14:48:42	METER 1 - M:	52465	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/03/2024 15:36:11	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$54.86	\$0.00	\$54.86
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.00	0.00	54.86	5.00	59.86
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	12.83	1	\$12.83
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	6	\$42.03
PARTS						54.86

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52364

Work Order Notes

(EHANNAH) pm

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) Performed safety inspection, found no issues at this time-GC
Miles, 52,465

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-CM
Miles, 52,465

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52846

USING DEPT NO:	507301	OPENED DATE:	11/18/2024 13:47:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/18/2024 15:49:36	METER 1 - M:	56630	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/19/2024 07:16:22	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.28	\$0.00	\$60.28
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	60.28	5.00	65.28
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	13.93	1	\$13.93
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.45	6	\$38.70
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
PARTS						60.28

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 52846

Work Order Notes

(CWIGLEY) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR- perform PM, changed oil and filter, checked air filters, checked tires and tire pressures
56630 miles

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54031

USING DEPT NO:	507301	OPENED DATE:	03/17/2025 09:10:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/18/2025 10:16:13	METER 1 - M:	60859	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/18/2025 14:39:10	IN-SERVICE DATE:	06/02/2022	
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander		UNIT SERIAL NO:	5TDZZRAH2NS123230	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$60.53	\$0.00	\$60.53
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.00	0.00	60.53	5.00	65.53
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.36	1	\$14.36
PARTS						60.53

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54031

Work Order Notes

(EHANNAH) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) GC- PM bottom side, drained oil and changed oil filter.

FJ- top side, filled with oil and checked fluids, filters , tires and tire pressure.

Miles, 60,859

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54486

USING DEPT NO:	507301	OPENED DATE:	04/15/2025 09:12:55	LOCATION:	GARAGE - University Automotive Services				
WO STATUS:	CLOSED	COMPLETED DATE:	04/15/2025 13:06:29	METER 1 - M:	61487	METER 2 - N:	0		
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/16/2025 09:00:42	IN-SERVICE DATE:	06/02/2022				
TECH SPEC NO:	22TOYHIGHLNDR	2022 Toyota Highlander							
			UNIT SERIAL NO:	5TDZZRAH2NS123230					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	5	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 2						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 04/17/2025 08:08:29 By User: GLOBETTI

UNIT NO: 244673 2022 TOYOTA HIGHLANDER

WORK ORDER NO: 54486

Work Order Notes

(EHANNAH) prep for sale

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(EHOWELL) GPS# 87B011240382 was removed.

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) performed prep for sale cm, 61487 miles

(GARAGE) gpe unit number was 87b011240382

(GARAGE) removed gps cm add job for gps removal

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Thu Apr 17 2025 08:08:29 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '244673') //Q=