

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 39464

USING DEPT NO:	510201	OPENED DATE:	03/22/2021 14:49:48	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/22/2021 14:55:08	METER 1 - M:	10	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2021 08:31:08	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE	DON	C	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.50	59.00	0.00	0.00	59.00
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
PS-00-001	PREP SERVICE NEW UNIT IN-SERVICE INSPECTION	10208562	03/22/2021 14:51:18	03/22/2021 15:21:18	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 39464

Work Order Notes

(LISAPATE) New unit do PDI

Job Notes

PS-00-001 - PREP SERVICE NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) PDI done by EK

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 41472

USING DEPT NO:	510201	OPENED DATE:	11/01/2021 09:45:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/04/2021 08:09:20	METER 1 - M:	2031	METER 2 - N: 0
WO VISIT REASON:	PREVENTIVE MAINT	CLOSED DATE:	11/04/2021 08:09:23	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$73.23	\$33.42	\$0.00	\$106.65
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.62	73.23	33.42	2.00	108.65
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
COMML					2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2021 09:30:00	11/02/2021 09:52:45	0.38	\$44.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/02/2021 09:00:31	11/02/2021 09:15:00	0.24	\$28.48
LABOR					73.22	

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
PARTS					33.42	

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 41472

Work Order Notes

(IFALLS) PM
PICK UP AT asb Building

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH Performed PM. Add 1/2 hour labor for skid plate removal. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 43162

USING DEPT NO:	510201	OPENED DATE:	05/09/2022 09:03:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/11/2022 10:41:39	METER 1 - M:	3909	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/11/2022 14:13:02	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.44	\$22.61	\$0.00	\$28.05
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.68	\$80.80	\$33.42	\$0.00	\$114.22
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.06	\$7.34	\$29.30	\$0.00	\$36.64
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.79	93.58	85.33	2.00	180.91
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	05/10/2022 08:01:39	05/10/2022 08:05:23	0.06	\$7.34
66-PM-PMA	PERFORM OIL CHANGE	11074414	05/10/2022 07:20:23	05/10/2022 08:01:28	0.68	\$80.80
03-51-038	REPLACE NEW WIPER BLADES	11074414	05/09/2022 15:14:54	05/09/2022 15:17:40	0.05	\$5.44
					LABOR	93.58

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
03-51-038	REPLACE NEW WIPER BLADES	19240	WIPER BLADE 24 IN OE BEAM	12.42	1	\$12.42
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.19	1	\$10.19
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24511	CABIN AIR FILTER CARBON	29.30	1	\$29.30
					PARTS	85.33

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 43162

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(HHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(HHARBIN) SH Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(HHARBIN) Replaced cabin air filter. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 45259

USING DEPT NO:	510201	OPENED DATE:	11/14/2022 11:22:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/15/2022 13:43:59	METER 1 - M:	6415	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/17/2022 08:56:15	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.07	\$8.62	\$0.00	\$0.00	\$8.62
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.46	\$54.05	\$0.00	\$0.00	\$54.05
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.53	62.67	0.00	5.00	67.67
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/14/2022 14:17:33	11/14/2022 14:17:33	0.00	\$0.00
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	11/14/2022 14:30:00	11/14/2022 14:34:23	0.07	\$8.62
66-PM-PMA	PERFORM OIL CHANGE	11074414	11/14/2022 13:20:00	11/14/2022 13:47:29	0.46	\$54.05
				LABOR		62.67

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 45259

Work Order Notes

(LISAPATE) PM

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires and inspected brakes. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has 6415 miles on it will go to Toyota at 10,000 miles. Checked fluids battery tire pressure and updated the oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 46490

USING DEPT NO:	510201	OPENED DATE:	03/22/2023 10:17:15	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/24/2023 08:42:16	METER 1 - M:	7310	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/24/2023 13:13:02	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$5.90	\$23.18	\$0.00	\$29.08
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.29	\$34.22	\$0.00	\$0.00	\$34.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.47	\$55.82	\$54.57	\$0.00	\$110.39
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	O	N	GARAGE	0.03	\$3.74	\$0.00	\$0.00	\$3.74

JOB COUNT: 5	WORK ORDER TOTAL:	0.84	99.68	77.75	5.00	182.43
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-79-003	PERFORM SAFETY INSPECTION	11074414	03/23/2023 11:34:55	03/23/2023 11:52:19	0.29	\$34.22
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/23/2023 11:31:44	03/23/2023 11:34:44	0.05	\$5.90
WA-00	WASH COMPLETE VEHICLE	11074414	03/23/2023 11:29:40	03/23/2023 11:31:34	0.03	\$3.74
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/23/2023 11:00:57	03/23/2023 11:29:20	0.47	\$55.82
				LABOR		99.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	6.51	1	\$6.51
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.53	1	\$10.53
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.47	1	\$10.47
03-51-038	REPLACE NEW WIPER BLADES	19240	WIPER BLADE 24 IN OE BEAM	12.71	1	\$12.71
				PARTS		77.75

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 46490

Work Order Notes

(LISAPATE) PM-Do annual Si-Wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) Performed a safety inspection. Found no issues at this time. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Performed PM. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Wash bay is closed. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 48168

USING DEPT NO:	510201	OPENED DATE:	09/12/2023 07:32:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/19/2023 07:57:50	METER 1 - M:	8746	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/19/2023 09:51:45	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$4.03	\$23.86	\$0.00	\$27.89
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.71	\$83.65	\$43.59	\$0.00	\$127.24
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.74	87.68	67.45	5.00	160.13
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12201267	09/12/2023 10:34:07	09/12/2023 10:36:10	0.03	\$4.03
66-PM-PMA	PERFORM OIL CHANGE	12201267	09/12/2023 09:51:13	09/12/2023 10:33:45	0.71	\$83.65
				LABOR		87.68

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	5.97	1	\$5.97
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
03-51-038	REPLACE NEW WIPER BLADES	19240	WIPER BLADE 24 IN OE BEAM	13.01	1	\$13.01
				PARTS		67.45

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 48168

Work Order Notes

(EHANNAH) pm- wash

Job Notes

03-34-002 - REPLACE NEW LAMPS-REAR, TAIL, STOP, TURN, ETC

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-FC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-FC, GC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 8,746

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 49526

USING DEPT NO:	510201	OPENED DATE:	01/23/2024 07:04:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/23/2024 15:41:52	METER 1 - M:	10339	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/24/2024 07:27:24	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.26	\$31.04	\$0.00	\$0.00	\$31.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.58	\$0.00	\$0.00	\$44.58

JOB COUNT: 3	WORK ORDER TOTAL:	0.64	75.62	0.00	5.00	80.62
--------------	-------------------	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12395904	01/23/2024 09:51:51	01/23/2024 10:14:31	0.38	\$44.58
66-PM-PMA	PERFORM OIL CHANGE	12395904	01/23/2024 09:33:18	01/23/2024 09:49:05	0.26	\$31.04
					LABOR	75.62

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 49526

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform fluid check fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(FCONTRER) Was fc

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 51272

USING DEPT NO:	510201	OPENED DATE:	06/24/2024 09:01:40	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/27/2024 08:10:50	METER 1 - M:	13384	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/27/2024 08:37:57	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-15	INSPECT STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
09-15	ALIGN STEERING	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	N	N	GARAGE	0.02	\$2.43	\$1,436.00	\$0.00	\$1,438.43
CH-SP	CHARGE Shop Supplies	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.02	2.43	1,436.00	5.00	1,443.43
--------------	-------------------	------	------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12395904	06/25/2024 11:19:13	06/25/2024 11:20:27	0.02	\$2.43
LABOR						2.43

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	4.57	3	\$13.72
66-17-028	PERFORM MOUNT AND BALANCE TIRES	63001	1/4 OZ STICK ON TAPE WEIGHT	0.23	37	\$8.33
66-17-028	PERFORM MOUNT AND BALANCE TIRES	66255	TIRE LT 265/70R17 BFG A/T KO2	340.50	4	\$1,362.00
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21360	TPMS DUAL FREQ UNIV STEM	51.95	1	\$51.95
PARTS						1436.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 51272

Work Order Notes

(EHANNAH) mount and balance tire from a flat.

Job Notes

06-15 - INSPECT STEERING

(EHOWELL) The front end checked good per FC. EH

09-15 - ALIGN STEERING

(EHOWELL) Performed a front end alignment and reset the steering angle sensor using Code Link. EH

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(FCONTRER) perform mounted 4 tires and balanced fc

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 6/28/2024 8:28 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 51489

USING DEPT NO:	510201	OPENED DATE:	07/16/2024 07:50:58	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/22/2024 09:36:15	METER 1 - M:	13384	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/22/2024 09:36:21	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.08	\$97.74	\$0.00	\$98.82
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.01	1.08	97.74	5.00	103.82
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	07/16/2024 10:26:18	07/16/2024 10:26:51	0.01	\$1.08
					LABOR	1.08

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	49350	AIR FILTER	37.83	1	\$37.83
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA5	FILTER-OIL	10.41	1	\$10.41
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
					PARTS	97.74

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 51489

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 53164

USING DEPT NO:	510201	OPENED DATE:	12/16/2024 15:33:26	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2024 13:31:34	METER 1 - M:	14662	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2024 14:07:08	IN-SERVICE DATE:	03/18/2021	
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4		UNIT SERIAL NO:	JTENU5JR3M5908743	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$24.11	\$0.00	\$24.11
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	24.11	5.00	29.11
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5667	CABIN FILTER	24.11	1	\$24.11
					PARTS	24.11

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 53164

Work Order Notes

(EHANNAH) pm-SI- wash

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) FJ- Performed SI. All tires measure 14/32. Brakes: LF: 6mm, RF: 6mm, RR: 8mm, LR: 8mm. No leaks found at this time.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Fluid check. 1082 miles since PM. Checked filters, set tire pressure, recorded date codes & tread depths, topped off fluids.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) FJ- Replaced cabin filter

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) FJ- Cannot wash vehicle at this time. Wash bay down as of 9:45 a.m. 12/19/24.

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 54638

USING DEPT NO:	510201	OPENED DATE:	04/30/2025 09:48:45	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	04/30/2025 10:50:24	METER 1 - M:	16487	METER 2 - N:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/30/2025 12:53:25	IN-SERVICE DATE:	03/18/2021						
TECH SPEC NO:	21TOY4RUN4X4	2021 Toyota 4Runner 4X4			UNIT SERIAL NO:	JTENU5JR3M5908743					

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
25-52-021	REMOVE GPS SYSTEM	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 54638

Work Order Notes

(EHANNAH) remove GPS -

Job Notes

25-52-021 - REMOVE GPS SYSTEM

(GARAGE) GC- removed GPS SN: 87U030240199 from unit 7401B

Work Order Charge Detail

UNIT NO:		243997		2021 TOYOTA 4RUNNER			WORK ORDER NO:			54640		
USING DEPT NO:		510201		OPENED DATE:		04/30/2025 10:55:11		LOCATION: GARAGE - University Automotive Services				
WO STATUS:		CLOSED		COMPLETED DATE:		04/30/2025 14:35:22		METER 1 - M: 16487		METER 2 - N: 0		
WO VISIT REASON:		SCHEDULED		CLOSED DATE:		05/02/2025 08:51:21		IN-SERVICE DATE:		03/18/2021		
TECH SPEC NO:		21TOY4RUN4X4		2021 Toyota 4Runner 4X4			UNIT SERIAL NO:		JTENU5JR3M5908743			
<u>JOB CODE</u>		<u>JOB DESCRIPTION</u>		<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999		PREP DISPOSE PREPARE UNIT FOR DI		DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1		WORK ORDER TOTAL:						0.00	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 05/14/2025 08:18:25 By User: GLOBETTI

UNIT NO: 243997 2021 TOYOTA 4RUNNER

WORK ORDER NO: 54640

Work Order Notes

(CWIGLEY) Prep For Sale.

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) FJ- Prep for sale. Removed all UA paperwork, no lettering on the vehicle at this time, no gps found, p-card/gas card found in the console (place in work order jacket per EH). Mileage is 16,886

(EKIMBREL) GC removed GPS # put on another work order

(EHOWELL) GC- removed GPS SN: 87U030240199 from unit 7401B.

We had a GPS job added to work order # 54638 and we've already charged .5 HR.

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Wed May 14 2025 08:18:25 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243997') //Q=