

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 45195

USING DEPT NO:	507301	OPENED DATE:	11/07/2022 14:03:59	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/07/2022 14:04:56	METER 1 - M:	9	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/09/2022 13:46:47	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	C	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	5.00	123.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11310047	11/09/2022 07:00:00	11/09/2022 08:00:00	1.00	\$118.00
					LABOR	118.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 45195

## Work Order Notes

(LISAPATE) New unit do PDI

## Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(LISAPATE) EH completed PDI

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 46381

USING DEPT NO:	507301	OPENED DATE:	03/06/2023 14:01:44	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/08/2023 07:47:58	METER 1 - M:	4850	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/08/2023 09:40:35	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.11	\$13.28	\$42.78	\$0.00	\$56.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.11	13.28	42.78	5.00	61.06
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	03/07/2023 08:17:33	03/07/2023 08:24:18	0.11	\$13.28
					LABOR	13.28

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.35	5	\$36.75
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	6.03	1	\$6.03
					PARTS	42.78

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 46381

## Work Order Notes

(EHANNAH) pm- replace wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM- JW-GC, Changed oil and oil filter, checked fluids, tires a d tire pressure, filters are good.  
Miles, 4,850

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 47294

USING DEPT NO:	507301	OPENED DATE:	06/08/2023 10:14:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/08/2023 15:12:04	METER 1 - M:	9886	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/13/2023 10:27:01	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-PM	TRANSPORT PM SERVICE	DON	O	N	GARAGE	0.33	\$38.94	\$0.00	\$0.00	\$38.94
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:					0.33	38.94	0.00	5.00	43.94
--------------	-------------------	--	--	--	--	------	-------	------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
66-PM-PMA	PERFORM OIL CHANGE	11076422	6207486		\$0.00
COMML					5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-PM	TRANSPORT PM SERVICE	11399745	06/13/2023 07:00:00	06/13/2023 07:19:48	0.33	\$38.94
LABOR						38.94

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 47294

## Work Order Notes

(EHANNAH) pm- replace wipers- wash  
(EKIMBREL) TOYOTA PERFORMED PM SERVICE, NO WIPERS OR WASH

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

16-33 - TRANSPORT IGNITION SYSTEM

16-PM - TRANSPORT PM SERVICE

(LISAPATE) Taken to Toyota by RC/CW

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) TOYOTA PERFORMED OIL CHANGE

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 48300

USING DEPT NO:	507301	OPENED DATE:	09/22/2023 07:33:46	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/22/2023 13:45:21	METER 1 - M:	15077	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/22/2023 13:45:25	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.23	\$24.08	\$0.00	\$26.31
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.03	\$2.98	\$51.39	\$0.00	\$54.37
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.04	5.21	75.47	5.00	85.68
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	09/22/2023 08:33:00	09/22/2023 08:34:31	0.03	\$2.98
03-51-038	REPLACE NEW WIPER BLADES	12395904	09/22/2023 08:30:50	09/22/2023 08:31:58	0.02	\$2.23
					LABOR	5.21

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WIX51394	OIL FILTER	7.44	1	\$7.44
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.79	5	\$43.95
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
					PARTS	75.47

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 48300

## Work Order Notes

(EHANNAH) pm- wipers

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) Replaced wipers

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Performed pm

CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 49138

USING DEPT NO:	507301	OPENED DATE:	12/04/2023 08:57:54	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/05/2023 10:04:42	METER 1 - M:	19708	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/05/2023 13:19:49	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.02	\$2.23	\$46.96	\$0.00	\$49.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.02	2.23	46.96	5.00	54.19
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	12/04/2023 13:46:12	12/04/2023 13:47:20	0.02	\$2.23
					LABOR	2.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	7.91	5	\$39.53
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
					PARTS	46.96

# Work Order Charge Detail

UNIT NO:2450802023 TOYOTA CAMRY

WORK ORDER NO:49138

Work Order Notes

(EHANNAH) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) Perform oil changed fc

CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 49211

USING DEPT NO:	507301	OPENED DATE:	12/11/2023 09:51:02	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/05/2024 15:19:53	METER 1 - M:	19708	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/08/2024 07:57:02	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	O	N	GARAGE	0.00	\$0.00	\$0.00	\$1,150.00	\$1,150.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	1,155.00	1,214.00
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	1697888		\$1,150.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					1155.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11399745	01/05/2024 07:00:00	01/05/2024 07:30:00	0.50	\$59.00
LABOR						59.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 49211

## Work Order Notes

(EHANNAH) Going to body shop for repairs.

## Job Notes

### **16-71 - TRANSPORT BODY**

(LISAPATE) Taken to Andrews by RC and CW

### **24-71 - REPAIR BODY**

(LISAPATE) Andrews repaired right rear fender area per State Auto estimate. State Auto paid Check# 1001412504 pd 1/4/24 \$ 1287.62 UA to pay 1000.00 Ded State Auto also paid supplement Check# 1001446834 pd 1/4/24 \$371.50.

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50382

USING DEPT NO:	507301	OPENED DATE:	04/02/2024 08:27:19	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/03/2024 10:46:22	METER 1 - M:	25379	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/03/2024 11:39:59	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.41	\$47.99	\$48.68	\$0.00	\$96.67
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	0.41	47.99	48.68	5.00	101.67
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12395904	04/02/2024 10:40:05	04/02/2024 11:04:29	0.41	\$47.99
					LABOR	47.99

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.43	1	\$7.43
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.25	5	\$41.25
					PARTS	48.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50382

## Work Order Notes

(EHANNAH) pm

## Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changes fc

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50628

USING DEPT NO:	507301	OPENED DATE:	04/19/2024 08:07:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2024 10:55:07	METER 1 - M:	26030	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/29/2024 13:23:14	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	N	N	GARAGE	0.03	\$3.70	\$0.00	\$0.00	\$3.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$3.70	\$3.70

JOB COUNT: 2	WORK ORDER TOTAL:	0.03	3.70	0.00	3.70	7.40
--------------	-------------------	------	------	------	------	------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$3.70
				COMML	3.70

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	12395904	04/19/2024 10:53:41	04/19/2024 10:55:34	0.03	\$3.70
					LABOR	3.70

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50628

## Work Order Notes

(EHANNAH) inspect brakes- customer reports not being able to stop well and jerking when trying to stop.  
(IFALLS) Issac called unit back in for a tech 2 to inspect.

## Job Notes

### 06-13 - INSPECT BRAKES

(FCONTRER) inspect Brakes good F 10-m R 8-m fc

### CH-SP - CHARGE Shop Supplies



# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50697

USING DEPT NO:	507301	OPENED DATE:	04/29/2024 13:20:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	05/01/2024 12:39:40	METER 1 - M:	26556	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	05/02/2024 11:56:33	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
06-13	INSPECT BRAKES	DON	N	N	GARAGE	1.00	\$118.00	\$0.00	\$0.00	\$118.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:	1.00	118.00	0.00	5.00	123.00
--------------	-------------------	------	--------	------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
06-13	INSPECT BRAKES	12052187	05/01/2024 07:00:00	05/01/2024 08:00:00	1.00	\$118.00
					LABOR	118.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 50697

## Work Order Notes

(CWIGLEY) Inspect brakes. the complaint was that they are squeaking.

## Job Notes

### 06-13 - INSPECT BRAKES

(GARAGE) Test drove 3 times across campus and at highway speed and never heard any noise. The last test drive, I felt minor vibration one time while braking but it was not enough to shake the steering wheel and never pulled the steering. Removed tires and cleaned off brake dust, all pads are at 9mm. Scanned unit for any abs codes in history and found no codes. Found no safety issues at this time and released to customer. JAW

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 51348

USING DEPT NO:	507301	OPENED DATE:	06/28/2024 13:50:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/02/2024 07:28:43	METER 1 - M:	29649	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/02/2024 14:40:51	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.29	\$24.08	\$0.00	\$26.37
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.01	\$1.15	\$48.11	\$0.00	\$49.26
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.01	\$1.44	\$22.73	\$0.00	\$24.17
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.04	4.88	94.92	5.00	104.80
--------------	-------------------	------	------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	12395904	06/28/2024 14:56:26	06/28/2024 14:57:36	0.02	\$2.29
66-PM-PMA	PERFORM OIL CHANGE	12395904	06/28/2024 14:55:31	06/28/2024 14:56:06	0.01	\$1.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12395904	06/28/2024 14:54:25	06/28/2024 14:55:09	0.01	\$1.44
					LABOR	4.88

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC99237C	CABIN FILTER 2020 CAMRY	22.73	1	\$22.73
03-51-038	REPLACE NEW WIPER BLADES	XC20	20" WIPER	10.88	1	\$10.88
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	6.86	1	\$6.86
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.25	5	\$41.25
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.20	1	\$13.20
					PARTS	94.92

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 51348

## Work Order Notes

(EHANNAH) pm- wipers

## Job Notes

### 03-51-038 - REPLACE NEW WIPER BLADES

(FCONTRER) reenplaced new wipers fc

### 66-PM-PMA - PERFORM OIL CHANGE

(FCONTRER) perform oil changed fc

### 66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(FCONTRER) replaced new cabin filter fc

### CH-SP - CHARGE Shop Supplies

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 52457

USING DEPT NO:	507301	OPENED DATE:	10/11/2024 10:34:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2024 09:21:49	METER 1 - M:	35171	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/18/2024 10:09:37	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.88	\$0.00	\$50.88
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	50.88	5.00	55.88
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.26	5	\$41.32
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.56	1	\$9.56
					PARTS	50.88

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 52457

## Work Order Notes

(CWIGLEY) PM

## Job Notes

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) performed safety inspection, found no issues at this time-GC  
brake pads are 8mm front and rear  
Miles, 35,172

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) performed pm-CM

### **CH-SP - CHARGE Shop Supplies**

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 52868

USING DEPT NO:	507301	OPENED DATE:	11/21/2024 07:56:53	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/26/2024 11:03:00	METER 1 - M:	39006	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	11/27/2024 07:30:28	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$777.40	\$777.40
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$24.08	\$0.00	\$24.08
16-71-023	TRANSPORT WINDSHIELD REPLACEMI	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$51.60	\$0.00	\$51.60
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 6	WORK ORDER TOTAL:	0.00	0.00	75.68	782.40	858.08
--------------	-------------------	------	------	-------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	2123141		\$777.40
03-02-061	REPLACE NEW WINDSHIELD	11078716	2123141		\$777.40
03-02-061	REPLACE NEW WINDSHIELD	11078716	2123141		(\$777.40)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	782.40

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	9.60	1	\$9.60
03-51-038	REPLACE NEW WIPER BLADES	19200	WIPER BLADE OE BEAM STYLE 20IN	10.85	1	\$10.85
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.40	5	\$42.00
03-51-038	REPLACE NEW WIPER BLADES	19260	WIPER BLADE 26 IN OE BEAM	13.23	1	\$13.23
				PARTS		75.68

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 52868

## Work Order Notes

(EHANNAH) pm- SI- front glass by Glass DR.

## Job Notes

### **03-02-061 - REPLACE NEW WINDSHIELD**

(EHOWELL) Glass Doctor replaced windshield.

(EHOWELL) Visit Reason Changed On 11/26/2024 11:02 AM By EHOWELL

### **03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) FJ- Replaced wiper blades.

### **16-71-023 - TRANSPORT WINDSHIELD REPLACEMENT**

(EHOWELL) CW & RC transported the vehicle to and from Glass Doctor.

### **66-79-003 - PERFORM SAFETY INSPECTION**

(GARAGE) performed si 39006 miles checked ok, cm

(GARAGE) rotated tires

### **66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) FJ- Performed PM service. Topped off fluids, recorded tire build dates & tread depths.

### **CH-SP - CHARGE Shop Supplies**



# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 54539

USING DEPT NO:	507301	OPENED DATE:	04/22/2025 07:32:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/22/2025 09:50:39	METER 1 - M:	44208	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/23/2025 09:29:52	IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$48.90	\$0.00	\$48.90
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	48.90	5.00	53.90
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG4476F	OIL FILTER	7.50	1	\$7.50
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.28	5	\$41.40
					PARTS	48.90

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 54539

## Work Order Notes

(EHANNAH) pm- wipers

## Job Notes

**03-51-038 - REPLACE NEW WIPER BLADES**

(GARAGE) DID NOT NEED WIPERS. CQ

**66-PM-PMA - PERFORM OIL CHANGE**

(GARAGE) DROPPED OIL AND FILTER AND INSTALLED NEW FILTER=CM SET TIRE PRESSURE CHECKED ALL FLUIDS AND FILLED WITH OIL=CQ RECORDED TREAD DEPTH AND BUILD DATES AND INSTALLED STICKER=JR

**CH-SP - CHARGE Shop Supplies**

**WA-00 - WASH COMPLETE VEHICLE**

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 55118

USING DEPT NO:	507301	OPENED DATE:	06/16/2025 14:40:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	06/17/2025 08:27:39	METER 1 - M:	46877	METER 2 - N: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	11/03/2022	
TECH SPEC NO:	23TOYCAMRY	2023 Toyota Camry		UNIT SERIAL NO:	4T1C11AK1PU106018	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	D	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

# Work Order Charge Detail

The University of Alabama

Report Printed: 06/17/2025 09:20:23 By User: GLOBETTI

UNIT NO: 245080 2023 TOYOTA CAMRY

WORK ORDER NO: 55118

## Work Order Notes

(EHANNAH) prep for sale

## Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) PREPPED FOR SALE PER DECOMMISSION SHEET. CQ.

# Work Order Charge Detail

## Work Order Charge Detail

**Report Title:** WODETAIL - Work Order Detail v20.0  
**Report Author:** FleetFocus M5  
**File Path:** E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i  
**Data Extracted:** Tue Jun 17 2025 09:20:23 **Report User:** GLOBETTI  
**TZ:** Central Standard Time  
**DLL Version:** 2021.02.23  
**Report Comments:** 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

### Parameters and Selection Filters

**First Grouping:** VIEW\_WO\_WORKSHEET.WO\_NO  
**Second Grouping:** VIEW\_JOB\_WORKSHEET.JOB  
**Third Grouping:**  
**Sorted By:**  
**From Date:**  
**To Date:**  
**Option 1:**  
**Option 2:**  
**Selection Filters:** isnull({VIEW\_JOB\_WORKSHEET.ORIG\_JOB\_ID}) and {VIEW\_JOB\_WORKSHEET.JOB\_STATUS} <> "CAN" and( {view\_udc\_main.unit\_no} = '245080') //Q=