

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35209

USING DEPT NO:	204906	OPENED DATE:	12/16/2019 14:12:51	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/19/2019 06:47:34	METER 1 - M:	55	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/19/2019 06:47:36	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSP	DON	S	N	GARAGE	0.50	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:					0.50	0.00	0.00	0.00	0.00
--------------	-------------------	--	--	--	--	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-00-001	PERFORM NEW UNIT IN-SERVICE INSPECTION	11310047	12/16/2019 14:16:23	12/16/2019 14:46:23	0.50	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35209

Work Order Notes

(EKIMBREL) PDI

Job Notes

66-00-001 - PERFORM NEW UNIT IN-SERVICE INSPECTION

(EKIMBREL) EH performed PDI

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35240

USING DEPT NO:	204906	OPENED DATE:	12/19/2019 11:20:03	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	01/03/2020 06:41:51	METER 1 - M:	55	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	01/03/2020 06:41:52	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
14-78-031	INSTALL TONNEAU/BED COVER	DON	O	N	GARAGE	1.00	\$0.00	\$650.00	\$0.00	\$650.00

JOB COUNT: 1	WORK ORDER TOTAL:					1.00	0.00	650.00	0.00	650.00
---------------------	--------------------------	--	--	--	--	-------------	-------------	---------------	-------------	---------------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-031	INSTALL TONNEAU/BED COVER	11074414	12/19/2019 15:11:52	12/19/2019 16:11:52	1.00	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
14-78-031	INSTALL TONNEAU/BED COVER	0001635187	TRI-FOLD TONNEAU RIGID 5FT	650.00	1	\$650.00
					PARTS	650.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35240

Work Order Notes

(EKIMBREL) Install bed cover

Job Notes

14-78-031 - INSTALL TONNEAU/BED COVER

(EKIMBREL) IF/SH installed new tonneau cover.

(RWINTERS) reduced price on cover due to a ding.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 35821

USING DEPT NO:	204906	OPENED DATE:	02/28/2020 08:57:35	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/10/2020 09:57:16	METER 1 - M:	80	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/13/2020 07:33:14	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/	DON	O	N	GARAGE	11.61	\$0.00	\$373.39	\$0.00	\$373.39

JOB COUNT: 1	WORK ORDER TOTAL:	11.61	0.00	373.39	0.00	373.39
--------------	-------------------	-------	------	--------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	03/03/2020 06:59:01	03/03/2020 11:38:07	4.65	\$0.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	03/02/2020 14:01:39	03/02/2020 15:49:45	1.80	\$0.00
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	11170580	03/02/2020 06:47:22	03/02/2020 11:56:43	5.16	\$0.00
					LABOR	0.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	WIONF	STROBE ASSY ION AMBER/WHITE	98.60	2	\$197.20
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	VTX3609F	STROBE VERTEX LED AMBER/WHITE	81.70	2	\$163.40
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC0963PT	INLINE FUSE HOLDER ATC 12GA	1.49	1	\$1.49
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	ATO10	FUSE-10 AMP	0.38	1	\$0.38
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	06133	ELECTRICAL TAPE 3M SUPER 33+	4.47	1	\$4.47
14-34-022	INSTALL STROBE LIGHT/BULB/MOTOR/ASSY	PIC8219A	SHRINK TUBING 1/8 IN 4FT	2.15	3	\$6.45
					PARTS	373.39

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: **243614** **2020 TOYOTA TACOMA 4X4**

WORK ORDER NO: **35821**

Work Order Notes

(LISAPATE) Install front and rear strobe lights

Job Notes

14-34-022 - INSTALL STROBE LIGHT/BULB/MOTOR/ASSY

(EKIMBREL) AB installed front and rear strobes.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36101

USING DEPT NO:	204906	OPENED DATE:	04/06/2020 10:14:42	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/06/2020 14:35:26	METER 1 - M:	81	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/06/2020 14:39:34	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.62	\$0.00	\$27.67	\$0.00	\$27.67

JOB COUNT: 1	WORK ORDER TOTAL:	0.62	0.00	27.67	0.00	27.67
--------------	-------------------	------	------	-------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/06/2020 11:20:29	04/06/2020 11:57:40	0.62	\$0.00
					LABOR	0.00

<u>Job Code</u>	<u>Job Description</u>	<u>Part No.</u>	<u>Description</u>	<u>Unit Price</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	3.89	6	\$23.34
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	4.33	1	\$4.33
					PARTS	27.67

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 36101

Work Order Notes

(IFALLS) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(IFALLS) SH performed pm

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 37492

USING DEPT NO:	204906	OPENED DATE:	09/03/2020 07:02:17	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/03/2020 09:52:21	METER 1 - M:	1944	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/04/2020 13:17:30	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.34	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 1	WORK ORDER TOTAL:	0.34	0.00	0.00	0.00	0.00
--------------	-------------------	------	------	------	------	------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	12052187	09/03/2020 07:13:27	09/03/2020 07:33:43	0.34	\$0.00
					LABOR	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 37492

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(JWRIGHT) Unit has only been 1500 miles since pm. Updated pm sticker and checked all fluids and tires. Found no issues. Coolant -34° SH,JAW

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 39140

USING DEPT NO:	204906	OPENED DATE:	02/19/2021 09:58:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	02/22/2021 08:03:24	METER 1 - M:	2378	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	02/22/2021 11:36:53	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	O	N	GARAGE	0.13	\$15.54	\$0.00	\$0.00	\$15.54
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.40	\$46.97	\$0.00	\$0.00	\$46.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.58	\$68.74	\$33.05	\$0.00	\$101.79

JOB COUNT: 3	WORK ORDER TOTAL:	1.11	131.25	33.05	0.00	164.30
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	02/19/2021 15:12:58	02/19/2021 15:20:52	0.13	\$15.54
66-79-003	PERFORM SAFETY INSPECTION	11074414	02/19/2021 14:48:49	02/19/2021 15:12:42	0.40	\$46.97
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2021 14:30:00	02/19/2021 14:35:58	0.10	\$11.73
66-PM-PMA	PERFORM OIL CHANGE	11074414	02/19/2021 13:46:01	02/19/2021 14:15:00	0.48	\$57.00
					LABOR	131.24

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	4.49	6	\$26.91
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.14	1	\$6.14
					PARTS	33.05

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 39140

Work Order Notes

(LISAPATE) PM-Do annual safety inspection

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Rotated tires due to shoulder wear on the front tires. SH

66-79-003 - PERFORM SAFETY INSPECTION

(SHARBIN) SH Performed safety inspection found no issues.

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2378. SH Performed PM.

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40271

USING DEPT NO:	204906	OPENED DATE:	06/28/2021 09:43:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/30/2021 09:59:19	METER 1 - M:	2397	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/06/2021 09:30:32	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.36	\$42.05	\$0.00	\$0.00	\$42.05

JOB COUNT: 1	WORK ORDER TOTAL:	0.36	42.05	0.00	0.00	42.05
--------------	-------------------	------	-------	------	------	-------

<u>Job Code</u>	<u>Job Description</u>	<u>Employee No.</u>	<u>Start</u>	<u>Finish</u>	<u>Quantity</u>	<u>Total Cost</u>
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/29/2021 09:30:00	06/29/2021 09:31:29	0.02	\$2.92
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/29/2021 08:55:06	06/29/2021 09:15:00	0.33	\$39.14
					LABOR	42.06

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 40271

Work Order Notes

(LISAPATE) PM

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2397. Vehicle has been driven 19 miles since last PM. Checked fluids battery tire pressure washed and updated oil change sticker. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 41338

USING DEPT NO:	204906	OPENED DATE:	10/15/2021 09:45:49	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/18/2021 14:28:49	METER 1 - M:	2475	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/19/2021 07:44:38	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.88	\$15.18	\$0.00	\$20.06
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.27	\$31.99	\$49.76	\$0.00	\$81.75
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.31	36.87	64.94	2.00	103.81
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	10/18/2021 07:39:36	10/18/2021 07:42:05	0.04	\$4.88
66-PM-PMA	PERFORM OIL CHANGE	11074414	10/18/2021 07:23:09	10/18/2021 07:39:25	0.27	\$31.99
					LABOR	36.87

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.32	6	\$37.89
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	6.54	1	\$6.54
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.33	1	\$5.33
					PARTS	64.94

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 41338

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Mileage 2475. SH/JW Performed PM

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42717

USING DEPT NO:	204906	OPENED DATE:	03/28/2022 09:52:08	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/29/2022 09:08:12	METER 1 - M:	3215	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/29/2022 15:25:32	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.04	\$4.79	\$15.18	\$0.00	\$19.97
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.25	\$29.27	\$0.00	\$0.00	\$29.27
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.29	34.06	15.18	2.00	51.24
--------------	-------------------	------	-------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11074414	03/28/2022 11:04:21	03/28/2022 11:06:47	0.04	\$4.79
66-PM-PMA	PERFORM OIL CHANGE	11074414	03/28/2022 10:49:16	03/28/2022 11:04:09	0.25	\$29.27
					LABOR	34.06

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.59	1	\$7.59
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.59	1	\$7.59
					PARTS	15.18

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42717

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) Vehicle has been driven 740 miles since the last PM. Checked fluids battery tire pressure and updated oil change sticker. SH

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42754

USING DEPT NO:	204906	OPENED DATE:	03/29/2022 09:08:23	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/18/2022 10:44:13	METER 1 - M:	3162	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/18/2022 13:04:31	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
16-71	TRANSPORT BODY	DON	O	N	GARAGE	0.50	\$59.00	\$0.00	\$0.00	\$59.00
24-71	REPAIR BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$2,369.00	\$2,369.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.50	59.00	0.00	2,371.00	2,430.00
--------------	-------------------	------	-------	------	----------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
24-71	REPAIR BODY	11150605	169068108		(\$2,300.00)
24-71	REPAIR BODY	11150605	169068108		\$2,300.00
24-71	REPAIR BODY	11150605	169068108		\$2,369.00
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
					COMML 2371.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
16-71	TRANSPORT BODY	11915538	04/18/2022 07:00:00	04/18/2022 07:30:00	0.50	\$59.00
					LABOR	59.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 42754

Work Order Notes

(LISAPATE) Take to the Body Shop to repair per the estimate State Auto paid Andrews Body Shop

Job Notes

16-71 - TRANSPORT BODY

(LISAPATE) Taken to Andrews by RC

24-71 - REPAIR BODY

(LISAPATE) Andrews Body Shop repaired per State Auto estimate. State Auto pd Check# 1000974494 on 4-11-22 \$1537.05 UA pd ded of \$2000.00 plus cc sur charge 60.00.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44129

USING DEPT NO:	204906	OPENED DATE:	08/01/2022 08:49:52	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	08/09/2022 09:31:32	METER 1 - M:	3611	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/09/2022 12:52:21	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
14-02-013	INSTALL FLOOR COVERINGS	DON	O	N	GARAGE	0.18	\$20.68	\$336.68	\$0.00	\$357.36
66-17-013	PERFORM ALIGNMENT	DON	O	N	GARAGE	0.46	\$53.89	\$0.00	\$0.00	\$53.89
66-17-028	PERFORM MOUNT AND BALANCE TIRE	DON	O	N	GARAGE	2.23	\$263.66	\$1,110.40	\$0.00	\$1,374.06
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$2.00	\$2.00

JOB COUNT: 4	WORK ORDER TOTAL:	2.87	338.23	1,447.08	2.00	1,787.31
--------------	-------------------	------	--------	----------	------	----------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$2.00
				COMML	2.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
14-02-013	INSTALL FLOOR COVERINGS	11074414	08/02/2022 11:32:36	08/02/2022 11:43:07	0.18	\$20.68
66-17-013	PERFORM ALIGNMENT	11310047	08/02/2022 08:04:05	08/02/2022 08:31:29	0.46	\$53.89
66-17-028	PERFORM MOUNT AND BALANCE TIRES	12296277	08/01/2022 11:21:38	08/01/2022 13:35:42	2.23	\$263.66
				LABOR		338.23

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58105	1.50 OZ WHEEL WEIGHT	0.80	1	\$0.80
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58100	.25 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58101	.50 OZ WHEEL WEIGHT	0.26	1	\$0.26
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58104	1.25 OZ WHEEL WEIGHT	0.63	1	\$0.63
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58103	1.00 OZ WHEEL WEIGHT	0.57	2	\$1.14
66-17-028	PERFORM MOUNT AND BALANCE TIRES	58102	.75 OZ WHEEL WEIGHT	0.43	1	\$0.43
66-17-028	PERFORM MOUNT AND BALANCE TIRES	21030	TPMS SERVICE KIT 6-116	5.52	4	\$22.08
14-02-013	INSTALL FLOOR COVERINGS	4412991	FRONT FLOOR MATS TACOMA	196.64	1	\$196.64
14-02-013	INSTALL FLOOR COVERINGS	448722	REAR FLOOR MATS TACOMA CREW	140.04	1	\$140.04
66-17-028	PERFORM MOUNT AND BALANCE TIRES	15477	TIRE LT245/75R16 BFG A/T KO2	271.20	4	\$1,084.80
				PARTS		1447.08

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44129

Work Order Notes

(EKIMBREL) 4 TIRES AND AN ALIGNMENT
(LISAPATE) Install floor mats

Job Notes

14-02-013 - INSTALL FLOOR COVERINGS

(HHARBIN) Installed front and rear floor mats. SH

66-17-013 - PERFORM ALIGNMENT

(LISAPATE) EH performed alignment

66-17-028 - PERFORM MOUNT AND BALANCE TIRES

(GARAGE) We replaced 4 tires mount and balanced all 4 tires and torqued spec on all tires

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44822

USING DEPT NO:	204906	OPENED DATE:	10/03/2022 09:21:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/06/2022 08:40:11	METER 1 - M:	6481	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2022 09:32:03	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.03	\$3.97	\$15.64	\$0.00	\$19.61
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.44	\$51.85	\$47.88	\$0.00	\$99.73
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.07	\$7.90	\$17.10	\$0.00	\$25.00
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.54	63.72	80.62	5.00	149.34
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
03-51-038	REPLACE NEW WIPER BLADES	11901357	10/03/2022 14:05:53	10/03/2022 14:07:54	0.03	\$3.97
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	10/03/2022 14:08:09	10/03/2022 14:12:10	0.07	\$7.90
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/03/2022 14:12:26	10/03/2022 14:15:00	0.04	\$5.05
66-PM-PMA	PERFORM OIL CHANGE	11901357	10/03/2022 14:30:00	10/03/2022 14:53:48	0.40	\$46.81
				LABOR		63.73

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.77	1	\$7.77
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	5.78	6	\$34.65
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	5.46	1	\$5.46
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	17.10	1	\$17.10
				PARTS		80.62

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 44822

Work Order Notes

(LISAPATE) PM-replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) Miles: 6481 Completed PM top and bottom side. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45625

USING DEPT NO:	204906	OPENED DATE:	12/19/2022 10:04:18	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/20/2022 11:14:53	METER 1 - M:	11989	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/20/2022 14:14:07	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.05	\$6.16	\$15.64	\$0.00	\$21.80
66-17-015	PERFORM TIRE ROTATION	DON	O	N	GARAGE	0.42	\$49.79	\$0.00	\$0.00	\$49.79
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.94	\$111.15	\$107.57	\$0.00	\$218.72
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.08	\$9.90	\$11.78	\$0.00	\$21.68
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 5	WORK ORDER TOTAL:	1.50	177.00	134.99	5.00	316.99
--------------	-------------------	------	--------	--------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	11901357	12/20/2022 07:27:12	12/20/2022 08:23:43	0.94	\$111.15
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11901357	12/20/2022 07:21:48	12/20/2022 07:26:50	0.08	\$9.90
03-51-038	REPLACE NEW WIPER BLADES	11901357	12/20/2022 07:18:23	12/20/2022 07:21:31	0.05	\$6.16
66-17-015	PERFORM TIRE ROTATION	11901357	12/20/2022 08:28:20	12/20/2022 08:53:39	0.42	\$49.79
				LABOR		177.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	WA10085	AIR FILTER	49.88	1	\$49.88
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.86	1	\$7.86
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.09	6	\$36.54
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	7.82	1	\$7.82
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.78	1	\$11.78
03-51-038	REPLACE NEW WIPER BLADES	TWB20-1	WIPER BLADE 20"	7.82	1	\$7.82
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	13.29	1	\$13.29
				PARTS		134.99

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 45625

Work Order Notes

(EHANNAH) pm- replace wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(AGUERRA) Replaced wipers. AMG

66-17-015 - PERFORM TIRE ROTATION

(AGUERRA) Rotated tires and checked brakes, no issues found. AMG

66-PM-PMA - PERFORM OIL CHANGE

(AGUERRA) miles: 11989 Completed PM top and bottom side. Add 1/2 hour for skid plate. AMG/AMG

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(AGUERRA) Replaced cabin filter. AMG

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46658

USING DEPT NO:	204906	OPENED DATE:	04/10/2023 10:17:56	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/12/2023 08:05:51	METER 1 - M:	16725	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/17/2023 10:51:43	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.02	\$2.33	\$16.65	\$0.00	\$18.98
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.22	\$25.83	\$55.01	\$0.00	\$80.84
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.02	\$2.29	\$11.79	\$0.00	\$14.08
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.38	\$44.58	\$0.00	\$0.00	\$44.58

JOB COUNT: 5	WORK ORDER TOTAL:	0.64	75.03	83.45	5.00	163.48
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	04/10/2023 11:14:48	04/10/2023 11:15:58	0.02	\$2.29
WA-00	WASH COMPLETE VEHICLE	11074414	04/10/2023 10:51:57	04/10/2023 11:14:37	0.38	\$44.58
03-51-038	REPLACE NEW WIPER BLADES	11074414	04/10/2023 10:50:32	04/10/2023 10:51:43	0.02	\$2.33
66-PM-PMA	PERFORM OIL CHANGE	11074414	04/10/2023 10:37:10	04/10/2023 10:50:18	0.22	\$25.83
				LABOR		75.03

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.70	1	\$10.70
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.26	6	\$37.53
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.78	1	\$6.78
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
				PARTS		83.45

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 46658

Work Order Notes

(EHANNAH) pm- replace wipers - wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(SHARBIN) Replaced the wipers. SH

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Washed the vehicle. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 47430

USING DEPT NO:	204906	OPENED DATE:	06/26/2023 08:52:06	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/28/2023 07:42:44	METER 1 - M:	21923	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/28/2023 11:42:19	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.21	\$24.22	\$0.00	\$0.00	\$24.22
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.17	\$20.19	\$54.70	\$0.00	\$74.89
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.30	\$35.40	\$11.79	\$0.00	\$47.19
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.01	\$1.34	\$0.00	\$0.00	\$1.34

JOB COUNT: 5	WORK ORDER TOTAL:	0.69	81.15	66.49	5.00	152.64
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	11074414	06/26/2023 09:55:10	06/26/2023 09:55:51	0.01	\$1.34
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/26/2023 09:30:00	06/26/2023 09:42:19	0.21	\$24.22
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	11074414	06/26/2023 09:25:23	06/26/2023 09:25:23	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/26/2023 09:23:42	06/26/2023 09:23:42	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/26/2023 09:23:42	06/26/2023 09:23:42	0.00	\$0.00
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	11074414	06/26/2023 09:23:42	06/26/2023 09:41:42	0.30	\$35.40
66-PM-PMA	PERFORM OIL CHANGE	11074414	06/26/2023 09:04:44	06/26/2023 09:15:00	0.17	\$20.19
				LABOR		81.15

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.76	1	\$10.76
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	6.32	1	\$6.32
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
				PARTS		66.49

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 47430

Work Order Notes

(EHANNAH) pm- replace wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(SHARBIN) Cross rotated the tires and inspected the brakes. Found no issues at this time. SH GC

66-PM-PMA - PERFORM OIL CHANGE

(SHARBIN) SH/GC Performed PM.

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(SHARBIN) Replaced the cabin air filter. SH

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(SHARBIN) Did not wash. SH

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48418

USING DEPT NO:	204906	OPENED DATE:	10/05/2023 10:27:09	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	10/05/2023 14:41:52	METER 1 - M:	26698	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	10/06/2023 07:14:37	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.15	\$17.70	\$16.65	\$0.00	\$34.35
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.24	\$28.48	\$57.33	\$0.00	\$85.81
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 4	WORK ORDER TOTAL:	0.39	46.18	73.98	5.00	125.16
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	12201267	10/05/2023 10:39:14	10/05/2023 10:53:43	0.24	\$28.48
03-51-038	REPLACE NEW WIPER BLADES	12201267	10/05/2023 10:53:43	10/05/2023 11:02:43	0.15	\$17.70
				LABOR		46.18

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	6	\$37.62
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	16.56	1	\$16.56
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.27	(6)	(\$37.62)
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	6.80	6	\$40.77
					PARTS	73.98

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 48418

Work Order Notes

(LRUSHING) pm-wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(LISAPATE) Replaced wipers GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,SH, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 26,698

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(LISAPATE) Washed GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 49054

USING DEPT NO:	204906	OPENED DATE:	11/27/2023 09:22:39	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	11/30/2023 09:33:46	METER 1 - M:	29383	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/01/2023 11:42:46	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-033	PERFORM TIRE ROTATION AND BRAKE	DON	P	N	GARAGE	0.04	\$4.16	\$0.00	\$0.00	\$4.16
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.33	\$38.58	\$61.53	\$0.00	\$100.11
66-PM-PMC	PERFORM CABIN FILTER REPLACEME	DON	P	N	GARAGE	0.01	\$1.05	\$11.79	\$0.00	\$12.84
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.25	\$28.91	\$0.00	\$0.00	\$28.91

JOB COUNT: 5	WORK ORDER TOTAL:	0.62	72.70	73.32	5.00	151.02
--------------	-------------------	------	-------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
66-17-033	PERFORM TIRE ROTATION AND BRAKE INSPECTION	12201267	11/27/2023 10:32:13	11/27/2023 10:34:20	0.04	\$4.16
WA-00	WASH COMPLETE VEHICLE	12201267	11/27/2023 10:17:13	11/27/2023 10:31:55	0.25	\$28.91
66-PM-PMA	PERFORM OIL CHANGE	12201267	11/27/2023 09:57:22	11/27/2023 10:16:59	0.33	\$38.58
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	12201267	11/27/2023 10:34:39	11/27/2023 10:35:11	0.01	\$1.05
				LABOR		72.70

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	10.77	1	\$10.77
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.30	6	\$37.80
66-PM-PMA	PERFORM OIL CHANGE	04152-YZZA1	FILTER-OIL	12.96	1	\$12.96
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	24871	CABIN FILTER-TACOMA	11.79	1	\$11.79
					PARTS	73.32

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 49054

Work Order Notes

(EHANNAH) pm- wash

Job Notes

66-17-033 - PERFORM TIRE ROTATION AND BRAKE INSPECTION

(GRCOOK) Performed tire rotation, and inspected brakes, front brake pads are 6mm and rear drum and shoes are good. -GC
Miles, 29,383

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC;FC, Changed oil and oil filter, checked fluids, air filter good, changed cabin filter, tires and tire pressure.
Miles, 29,383

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GRCOOK) Replaced cabin filter-FC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50364

USING DEPT NO:	204906	OPENED DATE:	04/01/2024 09:27:30	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	04/02/2024 07:35:46	METER 1 - M:	33462	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	04/02/2024 12:37:22	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.20	\$24.16	\$16.65	\$0.00	\$40.81
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.77	\$90.70	\$53.00	\$0.00	\$143.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.12	\$14.26	\$0.00	\$0.00	\$14.26

JOB COUNT: 4	WORK ORDER TOTAL:	1.09	129.12	69.65	5.00	203.77
--------------	-------------------	------	--------	-------	------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Employee No.	Start	Finish	Quantity	Total Cost
WA-00	WASH COMPLETE VEHICLE	12201267	04/01/2024 10:46:47	04/01/2024 10:54:02	0.12	\$14.26
03-51-038	REPLACE NEW WIPER BLADES	12201267	04/01/2024 10:34:09	04/01/2024 10:46:26	0.20	\$24.16
66-PM-PMA	PERFORM OIL CHANGE	12201267	04/01/2024 09:47:49	04/01/2024 10:33:56	0.77	\$90.70
				LABOR		129.12

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.87	6	\$41.22
03-51-038	REPLACE NEW WIPER BLADES	22-1	WIPER BLADE 22" TRICO EXACT	8.33	2	\$16.65
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.78	1	\$11.78
				PARTS		69.65

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 50364

Work Order Notes

(EHANNAH) pm- wipers- wash

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GRCOOK) Replaced wipers-GC

66-PM-PMA - PERFORM OIL CHANGE

(GRCOOK) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, filters good, tires and tire pressure.
Miles, 33,462

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GRCOOK) Washed vehicle-FC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51484

USING DEPT NO:	204906	OPENED DATE:	07/16/2024 07:07:48	LOCATION:	GARAGE - University Automotive Services						
WO STATUS:	CLOSED	COMPLETED DATE:	07/19/2024 12:24:52	METER 1 - M:	33462	METER 2 - H:	0				
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	07/19/2024 12:24:58	IN-SERVICE DATE:	12/16/2019						
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4									
			UNIT SERIAL NO:	3TMCZ5ANXLM307235							

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-17-015	PERFORM TIRE ROTATION	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$76.88	\$0.00	\$76.88
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$11.79	\$0.00	\$11.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	88.67	5.00	93.67
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.58	1	\$11.58
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.98	6	\$41.85
66-PM-PMA	PERFORM OIL CHANGE	WA10085	AIR FILTER	23.45	1	\$23.45
PARTS						88.67

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51484

Work Order Notes

(EHANNAH) pm- tire rotation- wash

Job Notes

66-17-015 - PERFORM TIRE ROTATION

(GARAGE) Rotated tires and inspected brakes-GC, Rear shoes are ok and front brake pads are at 5mm, Showed JW and he spoke with Matt Gage and told him on next PM it would need front pads.

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) Performed PM-GC,FC, Changed oil and oil filter, checked fluids, changed air filter and cabin filter, tires and tire pressure.
Miles, 37,775

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) Replaced cabin filter-GC

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) Wash bay down-GC

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51563

USING DEPT NO:	204906	OPENED DATE:	07/23/2024 07:13:12	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	07/31/2024 16:44:26	METER 1 - M:	33462	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	08/01/2024 08:49:05	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-02-061	REPLACE NEW WINDSHIELD	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$770.26	\$770.26
16-71	TRANSPORT BODY	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
CH-SP	CHARGE Shop Supplies	DON	A	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 3	WORK ORDER TOTAL:	0.00	0.00	0.00	775.26	775.26
--------------	-------------------	------	------	------	--------	--------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
03-02-061	REPLACE NEW WINDSHIELD	11078716	120221		\$770.26
CH-SP	CHARGE Shop Supplies	503163	1		\$5.75
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.75)
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
CH-SP	CHARGE Shop Supplies	503163	1		(\$5.00)
03-02-061	REPLACE NEW WINDSHIELD	11078716	120221		\$770.26
03-02-061	REPLACE NEW WINDSHIELD	11078716	120221		(\$770.26)
COMML					775.26

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 51563

Work Order Notes

(EHANNAH) Transport to Glass Dr for new windshield.

Job Notes

03-02-061 - REPLACE NEW WINDSHIELD

(EKIMBREL) glass dr replaced windshield

(LRUSHING) Visit Reason Changed On 8/21/2024 8:50 AM By LRUSHING

16-71 - TRANSPORT BODY

(EKIMBREL) rc/cw transported vehicle to and from glass dr

(LRUSHING) Visit Reason Changed On 8/21/2024 8:50 AM By LRUSHING

CH-SP - CHARGE Shop Supplies

(LRUSHING) Visit Reason Changed On 8/21/2024 8:50 AM By LRUSHING

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52195

USING DEPT NO:	204906	OPENED DATE:	09/23/2024 11:04:36	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	09/24/2024 08:43:47	METER 1 - M:	43178	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	09/24/2024 08:43:50	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$21.69	\$0.00	\$21.69
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$61.25	\$0.00	\$61.25
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	DON	P	N	GARAGE	0.00	\$0.00	\$11.79	\$0.00	\$11.79
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00

JOB COUNT: 5	WORK ORDER TOTAL:	0.00	0.00	94.73	5.00	99.73
--------------	-------------------	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
				COMML	5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMC	PERFORM CABIN FILTER REPLACEMENT	PC5644	CABIN FILTER	11.79	1	\$11.79
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.57	1	\$11.57
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	7.01	6	\$42.03
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
03-51-038	REPLACE NEW WIPER BLADES	19220	WIPER 22 IN OE BEAM	10.85	2	\$21.69
					PARTS	94.73

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52195

Work Order Notes

(CWIGLEY) PM. Wash. Wipers

Job Notes

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) REPLACED WIPER BLADES CM

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) PERFORMED PM 43178 MILES CM CHANGED MOTOR OIL AND FILTER CHECKED ALL FLUIDS CHECKED OK, TIRES CHECKED OK,

66-PM-PMC - PERFORM CABIN FILTER REPLACEMENT

(GARAGE) REPLACED CABIN AIR FILTER CM

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) WAS VEHICLE CM

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52940

USING DEPT NO:	204906	OPENED DATE:	12/02/2024 10:09:50	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	12/02/2024 15:07:00	METER 1 - M:	48096	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	12/03/2024 10:12:06	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$75.70	\$0.00	\$75.70
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	75.70	5.00	80.70
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	0W20T	0W20 SYN OIL THOMAS CAM2 QT	9.00	6	\$54.00
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.30	(6)	(\$49.77)
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	14.05	1	\$14.05
66-PM-PMA	PERFORM OIL CHANGE	05089	BRAKE CLEAN NON-FLAMMABLE 14OZ	7.65	1	\$7.65
66-PM-PMA	PERFORM OIL CHANGE	0W16T	OIL 0W16 CAM2 LSPI SN4+ QT	8.30	6	\$49.77
PARTS						75.70

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 52940

Work Order Notes

(EHANNAH) pm- SI- wash
(EKIMBREL) dept needed truck, did not do SI

Job Notes

66-79-003 - PERFORM SAFETY INSPECTION

66-PM-PMA - PERFORM OIL CHANGE

(EKIMBREL) JR/FJ performed pm.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54114

USING DEPT NO:	204906	OPENED DATE:	03/24/2025 09:13:07	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	03/25/2025 09:26:00	METER 1 - M:	53224	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	03/25/2025 14:54:30	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
03-13-001	REPLACE NEW FRONT BRAKES & ROT	DON	N	N	GARAGE	0.00	\$0.00	\$57.23	\$0.00	\$57.23
03-51-038	REPLACE NEW WIPER BLADES	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
03-51-042	REPLACE NEW KEY FOB BATTERY	DON	N	N	GARAGE	0.00	\$0.00	\$3.23	\$0.00	\$3.23
66-13-130	PERFORM Burnish Brakes	DON	N	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-79-003	PERFORM SAFETY INSPECTION	DON	Y	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$50.36	\$0.00	\$50.36
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00
WA-00	WASH COMPLETE VEHICLE	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 8		WORK ORDER TOTAL:				0.00	0.00	110.82	5.00	115.82

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
03-13-001	REPLACE NEW FRONT BRAKES & ROTORS	PWR17976	BRAKE PADS	57.23	1	\$57.23
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	11.84	1	\$11.84
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.42	6	\$38.52
03-51-042	REPLACE NEW KEY FOB BATTERY	CR2016	REMOTE BATTERY 3V COIN CELL	3.23	1	\$3.23
PARTS						110.82

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54114

Work Order Notes

(EHANNAH) pm- wipers- wash - SI
(GARAGE) Pending SI & wash.

Job Notes

03-13-001 - REPLACE NEW FRONT BRAKES & ROTORS

(GARAGE) replaced both front brake pads rotors checked ok, cm 1 labor

03-51-038 - REPLACE NEW WIPER BLADES

(GARAGE) FJ- Blades not needed at this time.

03-51-042 - REPLACE NEW KEY FOB BATTERY

(GARAGE) FJ- Replaced key fob battery

66-13-130 - PERFORM Burnish Brakes

(GARAGE) burnish brakes cm

66-79-003 - PERFORM SAFETY INSPECTION

(GARAGE) performed si cm found front brakes were wore down out of spec, everything else checked ok,

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) FJ- Top

JR- Bottom

FJ- Topped off fluids, added engine oil and verified oil level, checked filters, set tire pressure, recorded date codes & tread depths.

JR- Oil change.

CH-SP - CHARGE Shop Supplies

WA-00 - WASH COMPLETE VEHICLE

(GARAGE) washed cm

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54986

USING DEPT NO:	204906	OPENED DATE:	06/04/2025 11:12:14	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	CLOSED	COMPLETED DATE:	06/06/2025 14:48:06	METER 1 - M:	57978	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:	06/09/2025 09:23:08	IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

JOB CODE	JOB DESCRIPTION	STAT	RSN	WRTY	JOB LOC	LABOR HRS	LABOR	MATERIAL	COMMERCIAL	TOTAL COST
66-PM-PMA	PERFORM OIL CHANGE	DON	P	N	GARAGE	0.00	\$0.00	\$49.04	\$0.00	\$49.04
CH-SP	CHARGE Shop Supplies	DON	2	N	GARAGE	0.00	\$0.00	\$0.00	\$5.00	\$5.00

JOB COUNT: 2	WORK ORDER TOTAL:					0.00	0.00	49.04	5.00	54.04
--------------	-------------------	--	--	--	--	------	------	-------	------	-------

Job Code	Job Description	Vendor No.	Invoice No.	Purchase Order No.	Total Cost
CH-SP	CHARGE Shop Supplies	503163	1		\$5.00
COMML					5.00

Job Code	Job Description	Part No.	Description	Unit Price	Quantity	Total Cost
66-PM-PMA	PERFORM OIL CHANGE	PG5608F	OIL FILTER	10.61	1	\$10.61
66-PM-PMA	PERFORM OIL CHANGE	0W20BT	BULK OIL 0W20 FS	6.41	6	\$38.43
PARTS						49.04

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 54986

Work Order Notes

(CHANNELL) pm

Job Notes

66-PM-PMA - PERFORM OIL CHANGE

(GARAGE) JR-topside

GC- pit

perform PM,c hanged oil and filter, checked fluids, checked air filters, checked tires and tire pressures, changed sticker, reset oil light, filled up washer fluid
57978 miles

(EHOWELL) Needs tires. Vehicle is being sold.

CH-SP - CHARGE Shop Supplies

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55113

USING DEPT NO:	204906	OPENED DATE:	06/16/2025 11:16:22	LOCATION:	GARAGE - University Automotive Services	
WO STATUS:	COMPLETED	COMPLETED DATE:	06/16/2025 14:15:52	METER 1 - M:	58403	METER 2 - H: 0
WO VISIT REASON:	SCHEDULED	CLOSED DATE:		IN-SERVICE DATE:	12/16/2019	
TECH SPEC NO:	20TOYTACOM4X4	2020 Toyota Tacoma 4X4		UNIT SERIAL NO:	3TMCZ5ANXLM307235	

<u>JOB CODE</u>	<u>JOB DESCRIPTION</u>	<u>STAT</u>	<u>RSN</u>	<u>WRTY</u>	<u>JOB LOC</u>	<u>LABOR HRS</u>	<u>LABOR</u>	<u>MATERIAL</u>	<u>COMMERCIAL</u>	<u>TOTAL COST</u>
PD-00-999	PREP DISPOSE PREPARE UNIT FOR DI	DON	P	N	GARAGE	0.00	\$0.00	\$0.00	\$0.00	\$0.00
JOB COUNT: 1						WORK ORDER TOTAL:	0.00	0.00	0.00	0.00

Work Order Charge Detail

The University of Alabama

Report Printed: 06/16/2025 14:49:59 By User: GLOBETTI

UNIT NO: 243614 2020 TOYOTA TACOMA 4X4

WORK ORDER NO: 55113

Work Order Notes

(CWIGLEY) Prep for sale.

Job Notes

PD-00-999 - PREP DISPOSE PREPARE UNIT FOR DISPOSAL

(GARAGE) performed prep for sale cm, checked over unit checked ok, 58403 miles

Work Order Charge Detail

Work Order Charge Detail

Report Title: WODETAIL - Work Order Detail v20.0
Report Author: FleetFocus M5
File Path: E:\Program Files (x86)\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\FAFLEETCRYSTAL.AdaptiveJobServer\~i
Data Extracted: Mon Jun 16 2025 14:49:59 **Report User:** GLOBETTI
TZ: Central Standard Time
DLL Version: 2021.02.23
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No 3053 07/02/07 - Focus No. 15696 04/48/08 - Focus No. 19868 11/20/08 - Focus No. 22706 02/02/09 - Focus No. 22842 02/19/09 - Focus No. 23813 12/10/09 - Focus No. 24193 08/25/10 - Focus No. 28649 12/11/10 - Focus No. 31863 07/08/11 - Focus No. 28649 06/18/12 - Focus No. 39905 07/13/12 - Focus No. 39906 08/24/15 - FMV-3590 09/24/15 - FMV-4217 10/07/15 - FMV-4485 06/29/17 - FMV-10050 11/04/19 - FMV-17773

Parameters and Selection Filters

First Grouping: VIEW_WO_WORKSHEET.WO_NO
Second Grouping: VIEW_JOB_WORKSHEET.JOB
Third Grouping:
Sorted By:
From Date:
To Date:
Option 1:
Option 2:
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_udc_main.unit_no} = '243614') //Q=